

Date: February 5/2024

Pilgrim Bros. Ventures Ltd.
 TC Reg: 25-0992; Exp: 2023-11-01
 19267 PDR 9A Road
 Wonowon, B.C. V0C 2N0
 250-772-3082

Client: AquaFlow Trucking Ltd
 Address: PO Box 138
 City: Wonowon, BC
 Postal Code: V0C2N0
 Phone: 250-772-3082

☐ Lined ☐ Insulated ☐ Both lined and insulated
☐ Loaded by vacuum ☐ Corrosive service ☐ Dedicated service: _____

Tank serial number:
 Tank Spec: DOT 407
 Lining Material: SHERGLASS FF
 Date of MFR: 01/13
 CTMV orig. Test date:
 Manufacturer: HEIL
 TCRN: N/A
 MAWP: 30 psi
 Man. Thickness Head: 0.375 in
 Man. Thickness Shell: 0.250 in
 Exposed surface area: 1126 SQ FT

Unit Number: 531A
 VIN: 5HTDL4931D5L26116
 Orig. test date: 01/13
 Comp/Cert date: 01/13
 CTMV Cert Date:
 Assembler:
 MDIN: N/A
 Design Pressure: 45 psi
 Min. Thickness Head: 0.328 in
 Min. Thickness Shell: 0.232 in
 Volumetric Capacity: 12200 G

Visibly corroded or abraded areas are tested 7.2.6.1	Pass X	Repair ☐	Fail ☐	N/A ☐
Areas around lading retaining piping	Pass X	Repair ☐	Fail ☐	N/A ☐
High stress areas of the shell such as the bottom of the tank	Pass X	Repair ☐	Fail ☐	N/A ☐
Areas around openings, weld joints, shell reinforcements, appurtenance attachment points	Pass X	Repair ☐	Fail ☐	N/A ☐
Near the upper coupler, suspension attachments and connecting structures	Pass X	Repair ☐	Fail ☐	N/A ☐
Known thin areas in the tank	Pass ☐	Repair ☐	Fail ☐	N/A X
Structures adjoining self supporting transport units	Pass X	Repair ☐	Fail ☐	N/A ☐

Lowest measured thickness head: 0.342

Shell: 0.238 Baffle: N/A

Tank Disposition

X Pass ☐ Repaired/Re-tested/Returned to service
☐ Fail/removed from service ☐ Removed from facility

Inspector name: Andreas Schneider
 Inspector Signature: _____
 Date signed: Feb 05/2024

Tester name: _____
 Tester Signature: _____
 Markings applied: 02/24 T 992