

Manitoba

Date Inspection Started DAY MONTH YEAR 21 04 25			Station Number C01103			Name Daniel Ready			City [Blank]			A971706		
Date Inspection Completed DAY MONTH YEAR 23 04 25			Stockpile Number M0956			Batch Number [Blank]			Station Phone Number 204-326-3456			[Blank]		
Inspection Expiry Date DAY MONTH YEAR 30 04 26			Vehicle Owner Diamond Ready Mix Concrete Ltd. 308 Hwy 12 North Winnipeg, MB R2G 1V1											
Address [Blank]			Phone (204) 320-3454 FAX (204) 320-3455			Signature [Blank]			Postal Code [Blank]			Phone [Blank]		
☒ Pass Safe Vehicle ☒ Fail Unsafe Vehicle ☐ Fail Hazardous			Licence Number SKL714			Prov. MB			Exp. MB 900642			Collector Number [Blank]		
Vehicle Identification Number 5MAD5333V18C015760			Make Marc			Model [Blank]			Year 2008			Mileage 7022		
☒ Confirmed legal Vehicle Identification Number or vehicle														

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☐ Truck ☐ KQS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus
 List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when Item Rejected "XX" under "R" when Item Hazardous "X" under "P" when Item Corrected or No Defects found in Section																																																																																																															
X		Section 1 - Power Train: Defects (if any)																																																																																																															
X	X	Section 2 Suspension: Defects (if any) <i>shocks worn (S2.7.A)</i>																																																																																																															
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type <i>All brakes lining and drums low on pad spec (S3A.15.C) Right hand left middle and left rear gear chamber spring broken (S3A.14.A) front ABS wiring (S3A.8.B) Park brake cable loose (S3A.18.A)</i>																																																																																																															
		Brake Inspection Type: A B C D E Circle appropriate letter for internal brake component inspection																																																																																																															
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7/8"</td> <td>7/8"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>2</td> <td>7/8"</td> <td>7/8"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>3</td> <td>7/8"</td> <td>7/8"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"	2	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"	3	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"	4							5							Final Measurement																																																														
Axle	Lining			Drum/Rotor		Stroke																																																																																																											
	L	R	L	R	L	R																																																																																																											
1	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"																																																																																																											
2	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"																																																																																																											
3	7/8"	7/8"	16.5"	16.5"	1 1/4"	1 1/4"																																																																																																											
4																																																																																																																	
5																																																																																																																	
Final Measurement																																																																																																																	
		Section 4 - Steering: Defects (if any)																																																																																																															
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																																															
		Section 6 - Lamps: Defects (if any)																																																																																																															
		Section 7 - Electrical System: Defects (if any)																																																																																																															
		Section 8 - Body: Defects (if any)																																																																																																															
X	X	Section 9 - Tire & Wheel: Defects (if any) <i>Tire Pressure (S9.4.A) low tread (S9.2.C)</i>																																																																																																															
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth <i>1/32"</i></th> <th colspan="4">Air Pressure <i>PSI</i></th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3</td> <td>4</td> <td>2</td> <td>3</td> <td>15</td> <td>15</td> <td>15</td> <td>15</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>11</td> <td>10</td> <td>15</td> <td>15</td> <td>11</td> <td>10</td> <td>15</td> <td>15</td> <td>90</td> <td>85</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>6</td> <td>6</td> <td>15</td> <td>15</td> <td>15</td> <td>15</td> <td>15</td> <td>15</td> <td>100</td> <td>100</td> <td>90</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth <i>1/32"</i>				Air Pressure <i>PSI</i>				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	3	4	2	3	15	15	15	15	100	100	100	100	100	100	100	100	2	11	10	15	15	11	10	15	15	90	85	100	100	100	100	100	100	3	6	6	15	15	15	15	15	15	100	100	90	100	100	100	100	100	4																	5																
Axle	Tread Depth <i>1/32"</i>				Air Pressure <i>PSI</i>																																																																																																												
	Initial		Corrected		Initial		Corrected																																																																																																										
	L	R	L	R	L	R	L	R																																																																																																									
1	3	4	2	3	15	15	15	15	100	100	100	100	100	100	100	100																																																																																																	
2	11	10	15	15	11	10	15	15	90	85	100	100	100	100	100	100																																																																																																	
3	6	6	15	15	15	15	15	15	100	100	90	100	100	100	100	100																																																																																																	
4																																																																																																																	
5																																																																																																																	
		Section 10 - Coupling Devices: Defects (if any)																																																																																																															

· THIS INSPECTION IS NOT A WARRANTY ·

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

Ref. A935798

am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and
 7 inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a
 state officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.