

03825716

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-585-0920

Manitoba



Date Inspection Started DAY 14 MO. 11 YR. 24	Station Number C10103	Station Name Diamond Ready Mix	City Steinbach, MB	Province MB	Postal Code R5A 1A1	Phone (204) 326-3456
Date Inspection Completed DAY 15 MO. 11 YR. 24	Mechanic Number M0856	Mechanic Signature [Signature]	Station Phone Number 204-326-3456			
Inspection Expiry Date DAY 30 MO. 11 YR. 25	Vehicle Owner Diamond Ready Mix Concrete					
Address 399 Hwy 12 North Steinbach, MB R5A 1A1						
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous						
Licence Number SPV 1715	Prov. MB	NSC 1000000000	Odometer Reading 100000	Make JAC	Model S2	Year 2008
Vehicle Identification Number 5994105133315K11151261	Confirmed legible Vehicle Identification Number on vehicle					

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 130-16 - Replace all brake pads Tand of SAC																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1 1/4"</td> <td>1 1/4"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>2</td> <td>1 1/4"</td> <td>1 1/4"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>3</td> <td>1 1/4"</td> <td>1 1/4"</td> <td>16.5"</td> <td>16.5"</td> <td>1 1/4"</td> <td>1 1/4"</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"	2	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"	3	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"	4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"																																																																			
2	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"																																																																			
3	1 1/4"	1 1/4"	16.5"	16.5"	1 1/4"	1 1/4"																																																																			
4																																																																									
5																																																																									
Final Measurement																																																																									
		Section 4 - Steering: Defects (if any)																																																																							
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
		Section 6 - Lamps: Defects (if any) 6.1 - Replace Brake Light																																																																							
		Section 7 - Electrical System: Defects (if any)																																																																							
		Section 8 - Body: Defects (if any) 8.21 - Replace Rear Mud Flaps																																																																							
		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth 132"</th> <th colspan="4">Air Pressure 99</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>8</td> <td>8</td> <td>9</td> <td>10</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>10</td> <td>11</td> <td>16</td> <td>16</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>9</td> <td>8</td> <td>10</td> <td>8</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth 132"				Air Pressure 99				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	8	8	9	10	100	100	100	100	2	10	11	16	16	100	100	100	100	3	9	8	10	8	100	100	100	100	4									5								
Axle	Tread Depth 132"				Air Pressure 99																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	8	8	9	10	100	100	100	100																																																																	
2	10	11	16	16	100	100	100	100																																																																	
3	9	8	10	8	100	100	100	100																																																																	
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

SC622-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION