



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY12119
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21369833

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS / N5395
INSPECTOR: SCHROEDER, COLIN LESLIE / 109354
WORK ORDER #:
INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSR. REASON: Semi-annual
INSR. START: 2025-Jun-11 01:30 PM MST
INSR. COMPLETE: 2025-Jun-11 03:00 PM MST

VEHICLE JUR: Alberta
PLATE #: ND9070
LICENCED GVW(kg): 99999
VEHICLE YEAR: 2019
MAKE: KENWORTH
MODEL: TAN
REGI: VIN: 1XKZD40X7KJ957484
UNIT/FLEET#: 29
BODY STYLE: Tractor
ODOMETER: 659871 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
OWNER/LESSEE NAME: RELIANCE VENTURES, INC
ADDRESS: BOX 6242
Fort St John, British Columbia
V1J4H6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WINDSHIELD REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	27	28	18			18	
2	Clamp	30	Automatic	35	37	15	15	15	15	
3	Clamp	30	Automatic	38	38	15	15	15	15	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	56	57	Lining (Shoe)	16	16	Drum		
2	71	74	Lining (Shoe)	14	13	Drum		
3	75	72	Lining (Shoe)	13	14	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: SCHROEDER, COLIN LESLIE
Road Test Date: *Colin Schroeder*
Signature: *Colin Schroeder*
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-13 12:34 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.