

NewGen Projects Ltd.

5301 57th Ave

Grimshaw, AB T0H 1W0

Phone: (780)332-2054

Work Order

DATE

July 25/20

INVOICE #

E203

Completed

Initials

Hours

Parts # & Description

Service requirec/Description of work

Replace Both front Idlers

front Idlers x2

1 Pale Great oil

change oil in finals

Work Order

Phone: (780)332-2054

July 25/20

[illegible]

Keith

NewGen Projects Ltd.

5301 57 Ave

Grimshaw AB, T0H 1W0

P: 780-332-2054

Unit # E203

Machine Hours: 5708

Sept 14/20

Description	Tech	Parts And Discription	Price
- Build Belly Pan		outer air	\$ -
- change engine oil & filter		engine oil filter	\$ -
- change fuel filters & Bleed		Pilot hyd filter	\$ -
- check all air filters		Case drain filter	\$ -
- change hyd pilot filter		Fuel filters	\$ -
- change hyd return filter			\$ -
- * Case drain to be charged at Next service			\$ -
- Change outer air filter			\$ -
			\$ -
			\$ -
			\$ -

10/10

NewGen Projects Ltd.

5301 57 Ave

Grimshaw AB, T0H1W0

P: 780-332-2054

Unit # E203

Machine Hours: 5821 hrs

Oct 21/20

Description	Tech	Parts And Discription	Price
- check all fluid levels		outlet air filter	\$ -
- clean cab			\$ -
- wash			\$ -
- Top up hydraulics			\$ -
- Top up pump drive oil			\$ -
- replace ring on LH side of Boom			\$ -
* cut lines to heater core + flush system			\$ -
replace outlet Air filter			\$ -
			\$ -
			\$ -
			\$ -

NewGen Projects Ltd.

Feb 19/21

NewGen Projects Ltd.

203

APR 11/21

127

NewGen Projects Ltd.

5801 57 Ave

Grimshaw AB, T0H 2W0

P: 780-362-2054

Unit # E-203

Machine Hours: 6069.4

May, 12, 2021

Description	Tech	Parts And Discription	Price
Complete Service		RS 4992 Air outter	\$
Drained & Refilled Finals		RS 5329 air inner	\$
Drained, Flushed & Refilled Swing Drive		B7322 oil	\$
Greased & checked nipples		BF 7949 - D Secondary Fuel	\$
Topped up coolant		BF 7950 - D Primary Fuel	\$
Checked wipers & lights		PT9557 - Hyd Main	\$
checked all oils.		BT 9446 - Hyd	\$
Installed Master Switch		PA5656 - Cab Air	\$
		PA 30174 - Cab Air	\$
		BF46100-0 Fuel/Water Separator	\$
			\$
			\$

NewGen Projects Ltd.

Unit #

E203

Machine Hours:

6462

Sept 28/21

Description	Tech	Parts And Description	Price
New Tails + Pad Swap By Brandt		B7322	\$
New Sockets - Brandt		BF-46100-0	\$
heater Repairs - Brandt		BT9446	\$
changed Eng 3 Filter		BF-7950-1D	\$
changed Hyd Filter		BS-4992	\$
changed all fuel filters		PT-9557	\$
changed gutter Air			\$
checked Gear Pump Oil 3 Swing			\$
Replaced Fire extinguisher			\$
Greased			\$
Topped up all fluids			\$
checked final Drives Oil			\$
Changed			\$

NewGen Projects Ltd.

Unit #

E203

Machine Hours:

6819

Nov 22/21

Description	Tech	Parts And Description	Price
- Install Cage + ROPS			\$
- Change engine oil + filter			\$
- Change fuel & hydraulic filters			\$
- Change cab filter			\$
- engine air filter			\$
- Remount RTH mirror			\$
- wash / clean cab			\$
- stock unit			\$
- check swing + pump drive			\$
			\$
			\$
			\$

NewGen Projects Ltd.

Unit # E 203

12/30/21

Machine Hours: 7164

Description	Tech	Parts And Discription	Price
Service: change oil / Filter primary + secondary	824	(1) B7322 oil	
Fuel filters, hydraulic pilot + main filter		(1) BF46100-0 fuel primary	\$
lights: ✓ horn ✓ first aid ✓		(1) BF7950D sec-fuel	
spill kit ✓ grease + gun ✓ wipers ✓		(1) BF7949-0 sec-fuel	\$
seal ✓ outer cab filter: changed ✓		(1) BF9440 hyd-pilot	\$
washer reservoir + pump: filled ✓ operation ✓		(1) PT9557 hyd-main	\$
heater motor controls + operation: ✓		(1) PA5656	
air intake, clamps + tubes: ✓		(1) R502513 dust seal	\$
exhaust system: ✓		(1) T428818 fan belt	\$
Dust Seal for oil filter		(4) led cab lights	\$
Replaced fan Belt.			\$

NewGen Projects Ltd.

Unit # E203

Machine Hours: 7872

Apr 23/22

Description	Tech	Parts And Discription	Price
Service: Change oil/filter, fuel filters hydraulic filters,		(1) B7322 oil filter-	
cabin air, engine air, install LED cab light, install		(1) BT9440 hydraulic (pilot)	
hard line on stick cylinder, service final drives, service		(1) PT PT9557 hydraulic (full flow)	
swing motor, R/R door seal, R/R wiper blade, straighten		(1) BF7949-D fuel	
inspection covers, coolant leak at surge tank and		(1) BF7950-D fuel	
heater connections repaired, R/R L/H upper function covers,		(1) BF46100-D fuel	
R/R R/H lower vent bezel, R/R female wing coupler,		(1) PA5656 cabin air auto-	
R/R ball valve, R/R hydraulic hoses for male coupler-		(1) PA30134 Cabin air auto-	
return line, Check thumb for cylinder creep;		(1) RS5329 engine air line-	
		(1) RS4992 engine air auto-	
		(2) LLJ4232 LED light	
		(1) Door seal (cab)	

- (1) FF100493 A/C belt (1) 79222 22" wiper blade (1) LH upper function control cover (1) LH lower vent bezel
 (1) 1" valve handle (1) 1" female wing coupler (2) -8 JIC hydraulic hoses (1) mounting block for -8 line

NewGen Projects Ltd.

Unit #

E-203

Machine Hours:

7872 hrs

Apr. 25/22 + Apr. 26/22

Description	Tech	Parts And Description	Price
Remove and replace change piston. Rod gasket. Ingr gasket and turbo gasket.			\$
Checked all collers.			\$
Checked for engine oil leaks and coolant + leaks good.			\$
R+R All 4 carrier collers			\$
Checked A/C to make sure working. GOOD			\$
*Waiting on Turbo Air Inlet tube old one patched with silicone.			\$
			\$
			\$
			\$
			\$
			\$
			\$

Jordan

革命軍の政治綱領

Machine Hours: 8037.8

July 26/77

Description	Tech	Parts And Discription	Price
- R+R EGR cooler RE522589 (x1)		(1) 4450008 power	
- Gaskets R519487 (x2)		supply unit.	
- Diagnose for power backfeed issue, no power supply to all systems; R+I wiring harness + fuse blocks		(1) 3105789 power supply	
power surges found found in all wiring systems, check power supply unit for proper function; power supply unit checked internally and back feeding system R+R + reset system for functionality; OK			


Jordan.

E-203

8069hrs

Aug 11/22

[illegible]



Machine Hours:

8329

Oct 17/22

Description	Tech	Parts & Description	Price
Engine oil + filter change	KC		\$
Fuel filter change			\$
Pilot filter change			\$
hydraulic tank filter change			\$
Outer + inner engine oil filter change			\$
Cabin inner + outer oil filter change			\$
Final drive fluid change			\$
			\$
			\$
			\$
			\$



Nov 11/22

[illegible]



86 1/2

Dec 12/21

[illegible]

JOHN DEERE

Parts Invoice

Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414



Brandt

NEW GEN PROJECTS LTD
BOX 650
*****FM STAT & INVOICE**
GRIMSHAW AB T0H IWO CA

NEW GEN PROJECTS LTD
KIEITH 780-835-8526
WILLYS TO PEACE RIVER

01115

PAGE		1		CASH	CHG.	OTHER
		X				
ACCOUNT NO.			70000820			
INVOICE DATE						

SALESMAN	ORDER NO.	INVOICE NO.	INVOICE DATE	TIME
749	E203		01MAY23	11:18
QUANTITIES		BIN		
ORDERED	SHIPPED	NO	DESCRIPTION	
1	2		MAKE: JD MODEL: 290GLC SERNO: 705865	
PART NUMBER		BIN		
N 4664392	N TH111245	E06022	E0603	
TAPERED SEAL		1722.13 873.02		
Tax ID:		1722.13 3444.26		
PARTS HOURS: MON-FRI 7AM-6PM		SAT 8AM-4PM		
24 HOUR EMERGENCY ON CALL PARTS, SERVICE & SALES		ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE		
ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE		*****		
Attached for audit Posted				
MILLIS		DESCRIPTION		
SHIP VIA		AMOUNT		
TERMS: NET 30 DAYS FROM DATE OF INVOICE		AMOUNT		
NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF RECEIPT OF GOODS.		AMOUNT		
PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUAL MINIMUM CHARGE OF \$1.50)		AMOUNT		
SIGNATURE		DATE		

Brandt

Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414

Parts
Invoice



JOHN DEERE

S
L
O
D
T
O

NEW GEN PROJECTS LTD

BOX 650

*****EM STAT & INVOICE**

GRIMSHAW AB T0H 1W0 CA

PAGE	
CASH	1
CHG.	
OTHER	
ACCOUNT NO.	
700000820	

SALESMAN	ORDER NO.	PHONE	INVOICE DATE	TIME	INVOICE NO.
750	RETURN	01252826	780-332-2054	02MAY23	15:56
QUANTITIES					
ORDERED	SHIPPED	PROD			

MAKE: JD	MODEL:	DESCRIPTION	BIN	LIST	NET	EXTENSIONS	OFFICE USE
TH11245	TAPERED						
REF INVOICE 4763003	Tax ID:						

PARTS HOURS: MON-FRI 7AM-6PM
SAT 8AM-4PM
24 HOUR EMERGENCY ON CALL PARTS, SERVICE & SALES
ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE
ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE

CREDIT MEMO - DO NOT PAY **

GST No. 899544779
TOTAL GST/HST *

172.22-

AMOUNT	ACCOUNT	DESCRIPTION

TAXABLE	PARTS	SALES TAX

PLEASE PAY THIS TOTAL		3616.47-
-----------------------	--	----------

CUSTOMER COPY

LF-1117C

SIGNATURE

DATE

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUAL)
MINIMUM CHARGE OF \$1.50

NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF RECEIPT OF GOODS.

TERMS: NET 30 DAYS FROM DATE OF INVOICE

GST # 122695246

SHIP VIA



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit# E 203

Machine Hours

9226

Description	Tech	Parts & Description	Price
Service Fuel/Air/Hyd/Finals Auger Just did engine			\$
Replace rear window			\$
Preplace wiper			\$
Preplace heater vent			\$
Adjust front window			\$
Preplace 2 hoses on stick			\$
weld cracks on thumb			\$
and weld on stops			\$
Replace over flow bottle			\$
Replace fan belt			\$
Replace mirrors			\$
Repair steps			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

Machine Hours

[illegible]



July 16/23

[illegible]



Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414

Parts
Invoice



JOHN DEERE

S
O
L
D

T
O

NEW GEN PROJECTS LTD
BOX 650
EM STAT & INVOICES
GRIMSHAW AB T0H 1W0 CA

PAGE		
1		
CASH	CHG.	OTHER
	X	
ACCOUNT NO.		
70000820		

S
H
I
P

T
O

NEW GEN PROJECTS LTD
KEITH 780-835-8526
WILLYS TO GRIMSHAW

SALESMAN	ORDER NO.	RO. NO.	PHONE	INVOICE DATE	TIME	INVOICE NO.			
749	E203	01262261	780-332-2054	28AUG23	10:31	07	4770155		
QUANTITIES				PART NUMBER	DESCRIPTION	BIN	PRICES		OFFICE USE
ORDERED	SHIPPED	S/O	✓				LIST	NET	
				MAKE: JD	MODEL: 290GLC	SERNO: 1FF290GX	CDD705865	HRS:	
12				N R519486	CAP SCRE	E08078	26.49	26.49	317.88 PC
12				N R529236	SPACER	H02055	24.79	24.79	297.48 PC
6				N R519488	GASKET	E09093	19.74	19.74	118.44 PC
6				N SE501926	INJECTIO	C08021	808.01	808.01	4848.06 PC
HAS A CORE VALUE OF \$102.00									
1				N R519489	GASKET	8V2A	24.28	24.28	24.28 PC
4				N 14M7296	FLANGE N	8V1C	4.96	4.96	19.84 PC
2				N R519484	CAP SCRE	8V1D	4.04	4.04	8.08 PC
2				N DZ101862	STUD STU	8V1D	16.30	16.30	32.60 PC
1				N DZ120384	GASKET	F13055	14.01	14.01	14.01 PC
2				N 19M8063	SCREW	H01026	5.44	5.44	10.88 PC
Tax ID:									

** PARTS HOURS: MON-FRI 7AM-6PM SAT 8AM-4PM **									
** 24 HOUR EMERGENCY ON CALL PARTS, SERVICE & SALES **									
** ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE **									
** ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE **									

GST No. 899544779									
* TOTAL GST/HST *									
284.55									

Posted

QST # 1226957240

WILLYS

SHIP VIA

TERMS: NET 30 DAYS FROM
DATE OF INVOICE

NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS
RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY
ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO
CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF
RECEIPT OF GOODS.

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM).
MINIMUM CHARGE OF \$1.50

TITLES TO ALL ITEMS
REMAIN WITH BRANDT
TRACTOR LTD. UNTIL PUR-
CHASE PRICE, INTEREST
AND OTHER CHARGES
ARE FULLY PAID.

DESCRIPTION	ACCOUNT	AMOUNT
PARTS TAXABLE		
PARTS NONTAXBLE		5691.55
MISC TAXABLE		
MISC NONTAXABLE		
SALES TAX		
PLEASE PAY THIS TOTAL		5976.10

SIGNATURE _____

DATE _____

CUSTOMER COPY



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

E-203

Machine Hours

9459

Aug/08/23

Description	Tech	Parts & Description	Price
Inner tower engine air charged	EW		\$
Complete fuel filter	EW		\$
Change	EW		\$
Number 2 coolant			\$
level sensor			\$
changed			\$
Number 1 cleaned	EW		\$
out the plug			\$
New Sprocket bolts	EW		\$
RH side with sprockets			\$
In Rear locitite			\$
torque to spec			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Oct 20

20

Unit#

E 203

Machine Hours

9575

[illegible]



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

11-20-23

Machine Hours

4634

Sen 24/0024 Etkan

[illegible]



Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414

Parts
Invoice



JOHN DEERE

S
O
L
D

T
O

NEW GEN PROJECTS LTD
BOX 650
EM STAT & INVOICES
GRIMSHAW AB T0H 1W0

CA

PAGE		
1		
CASH	CHEQ	OTHER
	X	
ACCOUNT NO.		
70000820		

S
H
I
P

T
O

NEW GEN PROJECTS LTD
JORDAN 306-307-4834
WILLYS TO GRIMSHAW

SALESMAN	ORDER NO.	PO NO.	PHONE	INVOICE DATE	TIME	INVOICE NO.						
749	E203	01277546	780-332-2054	01FEB24	14:33	07	4781635					
QUANTITIES				PART NUMBER		DESCRIPTION		BIN	PRICES		OFFICE USE	
ORDERED	SHIPPED	BID	✓						LIST	NET	EXTENSIONS	
	1			MAKE: JD		MODEL: 290GLC		SERNO: 1FF290GX	CDD705865	HRS:		
	1			N 4601384		HYDRAULI		04J16C	1304.33	1304.33	1304.33	PC
	1			N 4629062		HYDRAULI		04J18E	971.04	971.04	971.04	PC
	1			N 4656668		HYDRAULI		04J13G	1188.08	1188.08	1188.08	PC
	2			N T59014		O-RING		12V3E	9.73	9.73	19.46	PC
	1			N 966993		O-RING		5V1C	3.72	3.72	3.72	PC
Tax ID:												
* HOURS: MON-THUR 7AM-10:30PM FRI 7AM-6PM SAT 8AM-4PM *												
***** 24 HOUR ON CALL PARTS & SERVICE *****												
***** ALL OPENED ELECTRICAL IS NON RETURNABLE *****												
* RESTOCKING FEE'S: 25% TO A MAX OF \$5000 PER LINE *												
** AS OF DECEMBER 1ST, 2023 ON ALL SPECIAL ORDERS **												
** ALL FABRICATED HYDRAULIC HOSE SALES ARE FINAL **												

GST No. 899544779												
* TOTAL GST/HST *												
174.33												

Posted

TERMS: NET 30 DAYS FROM
DATE OF INVOICE

NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS
RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY
ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO
CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF
RECEIPT OF GOODS.

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM).
MINIMUM CHARGE OF \$1.50

SIGNATURE

DATE

DESCRIPTION	ACCOUNT	AMOUNT
PARTS TAXABLE		
PARTS NONTAXABLE		3486.63
MISC TAXABLE		
MISC NONTAXABLE		
SALES TAX		
PLEASE PAY THIS TOTAL		3660.96



P.O. Box 650 Grimshaw, AB. T0H 1W0 *Quinten* *march 28/24*

Unit# *E 203* Machine Hours *10200*

Description	Tech	Parts & Description	Price
- Replace 3 hoses from			\$
stick to valve bank			\$
- Replaced 2 lights			\$
- Tighter clamps off			\$
Hyd tank			\$
- Repair valve mount			\$
B.H.S of stick			\$
- Change final drive oil			\$
- Repair rad door	<i>C.S</i>		\$
			\$
			\$
			\$

NUMBER: 199

WORK ORDER

COMPANY New Gen.

DARCY KURIGA 780-835-8090 dkuriga@yahoo.com

DATE	UNIT	SERIAL	HOURS/KILOMETERS
July 16/24			

UNIT/SERIAL	JOB DESCRIPTION	HOURS
	Loon River	

E 203	- Installed new ecms. still had code on for turbo sensor. ordered sensor + pig tail. checked out seat cushion.	2
A312.	changed ignition switch. checked engine v.l. added 2 gallons coolant to engine. Note: * has cracked manifold.	2
M-2102	Drove from PR to Cadott. Checked out Broken track turned out to be Broken pad. changed 2 pads. Note needs 2 more pads.	4
Travel.	Travel from Home to Loon River. and Back.	4
JOB TOTAL		12.

DATE COMPLETED: _____
COMPLETED BY: Darcy Kuriga



P.O. Box 650 Grimsshaw, AB. T0H 1W0

Unit#

E-203

Machine Hours

10345

Edna

June 28 / 2004

Description	Tech	Parts & Description	Price
Engine Oil & Filter Change			\$
Fuel Filters changed			\$
Replace Fan Blade.			\$
Reseal Fan motor New bearing & New Nut as well			\$
New Pilot Hydraulic Filter			\$
Drain hpd oil from tank, stick, friction pump hydraulic cooler			\$
filled with new Oil			\$
New outer engine air filter			\$
Machine harness Replaced			\$
By Brandt & Foster			\$
Shimmed main Stick Pin is tight is tight			\$
Replaced RH hpd pump doors & new paint			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Maxlin Eldridge

Unit# E-203 Machine Hours 10609.7

Description	Tech	Parts & Description	Price
Primary fuel filter		BF7950-D	\$
Secondary fuel filter		BF7949-D	\$
Primer fuel filter		BF46100-0	\$
Hydro filter		BT 9440	\$
Oil filter		B7322	\$
air filters		RS4992	\$
final drives		75-90	\$
			\$
			\$
			\$
			\$
			\$

P.O. Box 650 Grimsshaw, AB. T0H 1W0

Unit #: E-203 Date: Mar 8/25

Machine Hours: 11 317

Technician Signature: 

Description

Parts & Description

- Complete Service	- Put Lockout Clasp with lock + tag in machine above master switch.
- Eng Oil Change	- Re-mounted 2 way radio
- Fuel Filters changed	* Right boom cylinder starting to seep oil out of seal
- Hyd pilot + Return filters replaced	
- Cab filters replaced	
- Eng Air filters replaced Inner + Outer	
- Final drive oil good, Swing drive oil good	
- Coolant, hyd oil + Eng oil good.	
- Lights + Wiper work	
- Hyd lockout works (both the arm bar + the thumb switch on right hand panel)	
- Main works	
- Master Switch swapped out with a Cat style where it can actually be locked out + Key removed.	
- Right rear caps mount was busted, removed mount + got Kyle to weld	
- When Right Mirror mount had 2 broken bolts, extracted bolts + Put New ones in	