10/8/25, 4:34 PM HEM Data Dashboard



2016 Peterbilt 579

	Test Information
Engine	PACCAR MX/MX-13 (12.9)
Engine Serial	PCAR*MX16U15D13*Y089386*00000000
VIN	1XPBDP9X1GD354701
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Oct. 8, 2025, 12:09 p.m.
File Length	49.005 s

Usage					
Label	Value	Units			
Engine Odometer	385,112	mi			
Odometer (Cab Controller - Primary)	723,940	mi			
Engine Total Hours of Operation	12,344.95	h			
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	61	%			

Engine On/Off

Engine running

10/8/25, 4:34 PM **HEM Data Dashboard**

Check Engine Light



MIL - Emissions malfunction



Amber Warning Lamp - Warning, but OK to drive

Emissions Deleted/Tampered

No

Faults						
DM	Controller Name	SPN Name	FMI Name	Count		
Active	Engine #1	Engine Fuel Pump Pressurizing Assembly #1	High-moderate severity	25		
Active	Brakes - System Controller	Wheel Sensor ABS Axle 3 Right	Erratic, Intermittent, or Incorrect	126		
Active	Brakes - System Controller	Wheel Sensor ABS Axle 3 Left	Erratic, Intermittent, or Incorrect	126		
Active	Cab Controller - Primary	Forward Rear Drive Axle Temperature	Voltage Above Normal	126		
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 1 Right	Abnormal Update Rate	1		
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 1 Left	Abnormal Update Rate	1		
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Erratic, Intermittent, or Incorrect	6		
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 3 Left	Abnormal Rate of Change	18		
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 3 Right	Not Responding Properly	15		
Previous	Brakes - System Controller	Brake Light Switch 1	Erratic, Intermittent, or Incorrect	1		
Emissions Active	Engine #1	Engine Fuel Pump Pressurizing Assembly #1	High-moderate severity	25		
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent	Condition Exists	1		
Emissions Previous	Engine #1	Engine Fuel Pump Pressurizing Assembly #1	High-moderate severity	25		
Permanent	Engine #1	Engine Fuel Pump Pressurizing Assembly #1	High-moderate severity	25		