



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY03251
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21307829

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
NS398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407
INSPECTION TYPE: Correction
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual
INSPECTION START: 2025-Apr-08 01:30 PM MST
INSPECTION COMPLETE: 2025-Apr-08 02:30 PM MST

WORK ORDER #:
ORIGINAL INSP. #: 21307623

VEHICLE JUR: British Columbia
PLATE #: 78814K
LICENCED GVW(kg): 0
VEHICLE YEAR: 1994
MAKE: SCION
MODEL:
REGI: 13493944
UNIT/FLEET#:
BODY STYLE: Flat Deck Trailer
ODOMETER: 1 KM
HUB ODOMETER: 1 KM
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2E9F45E36R3000568
OWNER/LESSEE NAME: A.L.R. CONTRACTING LTD.,
ADDRESS: BOX 6836
Fort St John, British Columbia
V1J4J3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Manual	36	37
2	Clamp	30	Manual	38	37
3	Clamp	30	Manual	37	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13	13	7	13	
14	14	12	12	
9	8	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	68	61
2	69	62
3	72	74

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	15	16
Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-10 01:18 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSGVIP at the Commercial Vehicle Safety Enforcement

CVSED014

4/10/2025 1:18:27 PM MST