



# MAINTENANCE HISTORY REPORT

## UNIT # 225977

### LAST 60 MONTHS OF MAINTENANCE ACTIVITY

<b>VIN</b>	2AYNF8JV7K3S14372
<b>Year, Make, Model</b>	2019 HIN 338
<b>Vehicle Description</b>	22FT SAD MEDIUM REEFER
<b>Engine</b>	HIN J08E-VB 260hp
<b>Transmission</b>	ALL 6speed AUTO
<b>Color</b>	WHITE
<b>Odometer</b>	197,988 km

DATE	MILEAGE	DESCRIPTION
11/06/25	196,351 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
08/15/25	195,020 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION
08/15/25	195,020 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
05/17/25	191,965 km	REPLACE FRONT AXLE DISC BRAKE PADS, BOTH LEFT AND RIGHT
05/17/25	191,965 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION
05/17/25	191,965 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
05/17/25	191,965 km	COMPLETE WET - TRUCK / TRACTOR, FLUID CHANGE
02/15/25	191,045 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION
02/15/25	191,045 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
11/16/24	189,963 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
08/26/24	189,077 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION
08/26/24	189,077 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
08/26/24	189,077 km	COMPLETE CS - COOLANT SAMPLE & CHANGE POWER STEERING FILTER IF APPLICABLE
05/25/24	184,951 km	REPLACE REAR AXLE DISC PADS, BOTH LEFT AND RIGHT
05/25/24	184,951 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P. ("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE. PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE'S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.



# MAINTENANCE HISTORY REPORT

## UNIT # 225977

### LAST 60 MONTHS OF MAINTENANCE ACTIVITY

<b>VIN</b>	2AYNF8JV7K3S14372
<b>Year, Make, Model</b>	2019 HIN 338
<b>Vehicle Description</b>	22FT SAD MEDIUM REEFER
<b>Engine</b>	HIN J08E-VB 260hp
<b>Transmission</b>	ALL 6speed AUTO
<b>Color</b>	WHITE
<b>Odometer</b>	197,988 km

DATE	MILEAGE	DESCRIPTION
05/25/24	184,951 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
05/25/24	184,951 km	COMPLETE WET - TRUCK / TRACTOR, FLUID CHANGE
05/25/24	184,951 km	ADJUST VEHICLE ROAD AND CRUISE SPEEDS
03/01/24	178,723 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
12/08/23	172,301 km	COMPLETE DRY - TRUCK / TRACTOR, OPERATIONAL INSPECTION
12/08/23	172,301 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
09/09/23	167,243 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
06/17/23	160,846 km	COMPLETE DRY - TRUCK / TRACTOR OPERATIONAL INSPECTION
06/17/23	160,846 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
06/17/23	160,846 km	TRUCK / TRACTOR, FLUID CHANGE
03/17/23	153,340 km	COMPLETE DRY - TRUCK / TRACTOR OPERATIONAL INSPECTION
03/17/23	153,340 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
01/26/23	149,777 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
01/26/23	149,777 km	COMPLETE CS - COOLANT SAMPLE & CHANGE POWER STEERING FILTER IF APPLICABLE
09/17/22	137,441 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P. ("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE. PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE'S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.



# MAINTENANCE HISTORY REPORT

## UNIT # 225977

### LAST 60 MONTHS OF MAINTENANCE ACTIVITY

<b>VIN</b>	2AYNF8JV7K3S14372
<b>Year, Make, Model</b>	2019 HIN 338
<b>Vehicle Description</b>	22FT SAD MEDIUM REEFER
<b>Engine</b>	HIN J08E-VB 260hp
<b>Transmission</b>	ALL 6speed AUTO
<b>Color</b>	WHITE
<b>Odometer</b>	197,988 km

DATE	MILEAGE	DESCRIPTION
09/17/22	137,441 km	TRUCK / TRACTOR, FLUID CHANGE
03/24/22	122,056 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
03/18/22	121,690 km	REPLACE FRONT AXLE DISC BRAKE PADS, BOTH LEFT AND RIGHT
03/18/22	121,690 km	COMPLETE DRY - TRUCK / TRACTOR OPERATIONAL INSPECTION
03/18/22	121,690 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
03/18/22	121,690 km	TRUCK / TRACTOR, FLUID CHANGE
09/23/21	98,302 km	COMPLETE MR1 - TRUCK REEFER, OPERATIONAL INSPECTION
07/23/21	90,542 km	COMPLETE MR2 - TRUCK REEFER, MAINTENANCE INSPECTION
07/23/21	90,542 km	COMPLETE CS - COOLANT SAMPLE & CHANGE POWER STEERING FILTER IF APPLICABLE
04/10/21	82,835 km	REPLACE REAR AXLE DISC PADS, BOTH LEFT AND RIGHT
04/10/21	82,835 km	COMPLETE DRY - TRUCK / TRACTOR OPERATIONAL INSPECTION
04/10/21	82,835 km	TRUCK / TRACTOR, FLUID CHANGE

THIS MAINTENANCE HISTORY REPORT INCLUDES ONLY CERTAIN MAINTENANCE ACTIVITIES THAT WERE PERFORMED AND RECORDED BY PENSKE TRUCK LEASING CO., L.P. ("PENSKE") DURING THE SIXTY (60) MONTH PERIOD PRIOR TO THE DATE OF THIS REPORT THE MILEAGE AMOUNT SET FORTH ABOVE IS THE AMOUNT LAST RECORDED BY PENSKE WITHOUT VERIFICATION FOR THIS REPORT AND MAY NOT REPRESENT THE ACTUAL MILEAGE OF THE VEHICLE. THE MILEAGE AMOUNT WILL BE VERIFIED UPON SALE. PENSKE DOES NOT REPRESENT OR WARRANT THAT THIS REPORT INCLUDES ALL MAINTENANCE AND/OR REPAIRS PERFORMED BY PENSKE OR PERFORMED BY ANY THIRD PARTY WITH OR WITHOUT PENSKE'S CONSENT. PENSKE SHALL NOT BE LIABLE FOR ANY ERRORS OR OMISSIONS IN THE CONTENT OF THIS REPORT. PENSKE MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE VEHICLE(S) COVERED BY THIS REPORT, AND ANY SUCH WARRANTIES (INCLUDING, BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE) ARE EXPRESSLY DISCLAIMED AND EXCLUDED. ALL VEHICLES ARE SOLD BY PENSKE AS-IS, IN THEIR PRESENT CONDITION. THE PURCHASER OF ANY VEHICLE SHALL RELY SOLELY ON ITS OWN INSPECTION OF THE VEHICLE PRIOR TO PURCHASE. THE PURCHASE OF ANY VEHICLE REFERENCED IN THIS REPORT SHALL BE SUBJECT TO THE TERMS AND CONDITIONS SET FORTH IN THE MOTOR VEHICLE BILL OF SALE.