

Hydrovac Tank Clean and Purge Certification

Date Issued:	Sept 12 / 2025
Location of Issue:	Sherwood park
Tank S/N:	5KKPAVDV8NPG6334
Vehicle VIN:	5KKPAVDV8NPG6334
Previous Cargo:	mud + water
Cleaning Completion & Time:	3:00 pm
Inspection Date & Time:	Friday Sept 12 / 25

1. Cleaning Details:

Cleaning Method: (i.e. Steam/Water/Chemicals/Manual Wash)	water / manual clean
Cleaning Materials Used:	power washer
Ventilation Performed: (Y/N With Duration)	N/A
Slops Disposal Location:	N/A

2. Inspection Results:

Criteria	Result
Tank Structure Condition	passed
Smell/Vapor Presence	N/A
Visual Inspection	small pieces of plastic at top
LOD (Limit of Direction for previous Cargo)	

51475 RANGE ROAD 231 - SHERWOOD PARK, AB - T8B 1K9

780-449-4059

780-467-3322

info@can-traffic.ca



3. Certification:

I hereby certify the above tank(s) were cleaned and inspected according to relevant standards and are suitable for loading cargo.

Inspector Name: John Wood

Designation: Heavy duty mechanic

Company Name: Can - traffic Services

Signature: 

51475 RANGE ROAD 231 - SHERWOOD PARK, AB - T8B 1K9

780-449-4059

780-467-3322

info@can-traffic.ca

Owner Code/Schedule Number(s): FF07-1**RESIDUE LAST CONTAINED**Company: Can-Traffic ServiceConsignor Name: KEENAN BRERETONAddress: 51475 Range Road 231Phone Number: 780-449-4051Transporter: Can-TrafficDescription of tank (including serial number): SN-SKKPAVDV8NPNG6334

Tank emptied:

YES



NO



Please note all tanks must be emptied

Tank purge/steamed:

YES



NO

3rd Party Certificate provided:

YES



NO



Other: _____

Consignor Signature: [Signature] Date: Sept 18/25Consignor Print Name: KEENAN BRERETON**INTERNAL USE ONLY:**
OK'D BY: _____