

Hydrovac Tank Clean and Purge Certification

Date Issued:	Sept 12
Location of Issue:	Sherwood park
Tank S/N:	1FVPG3DV8PHN X 1592
Vehicle VIN:	1FVPG3DV8PHN X 1592
Previous Cargo:	mud / water
Cleaning Completion & Time:	Sept 12 1:00 pm 3:00 pm
Inspection Date & Time:	3:00 pm

1. Cleaning Details:

Cleaning Method: (i.e. Steam/Water/Chemicals/Manual Wash)	water
Cleaning Materials Used:	power washed
Ventilation Performed: (Y/N With Duration)	yes
Slops Disposal Location:	Sherwood park

2. Inspection Results:

Criteria	Result
Tank Structure Condition	PASSED
Smell/Vapor Presence	NONE
Visual Inspection	pass
LOD (Limit of Direction for previous Cargo)	

51475 RANGE ROAD 231 - SHERWOOD PARK, AB - T8B 1K9

780-449-4059

780-467-3322

info@can-traffic.ca



3. Certification:

I hereby certify the above tank(s) were cleaned and inspected according to relevant standards and are suitable for loading cargo.

Inspector Name: John Wood

Designation: Heavy duty mechanic

Company Name: Can - traffic Services

Signature: 

51475 RANGE ROAD 231 - SHERWOOD PARK, AB - T8B 1K9

780-449-4059

780-467-3322

info@can-traffic.ca

HV0002.

Owner Code/Schedule Number(s) FF07-2

RESIDUE LAST CONTAINED

Company: Can-traffic Service

Consignor Name: KEELAN BRERETON

Address: 51475 Range Road 231

Phone Number: 780-449-4059

Transporter: Can-Traffic

Description of tank (including serial number): S/N 1FVPG13DV8 PHNX 1592.

Tank emptied: YES ☒ NO ☐

Please note all tanks must be emptied

Tank purge/steamed: YES ☒ NO ☐

3rd Party Certificate provided: YES ☒ NO ☐

Other: _____

Consignor Signature: [Signature] Date: Sept 18/25

Consignor Print Name: KEELAN BRERETON

INTERNAL USE ONLY:
OK'D BY: _____