

K69-3



TANK WASH AND PURGE TEST

September 13th 2024

Date: _____ Time: _____

Location: 2130 121 ave NE Edmonton _____

Tank Unit# 791175 _____

Meter Used: M4SH495976 _____

Reading: _____
% LEL Level: 0.0 %O2: 20.7 CO: 0.0 H2S: 0.0

Tested Clean? ☒ / N

Comments: Washed and Steamed out _____

CLEAN _____

Printed Name: Aaron Hemmings _____

Signature*: _____

*this signature verifies that this tanker has been washed out and purged

Title: Service Coordinator _____

Contact Phone Number: _____