

K69-9



TANK WASH AND PURGE TEST

Date: OCT 17 2025 Time: 08:30 AM

Location: CALMAR, ALBERTA

Tank Unit# HP5042

Meter Used: MSA ULTAR 4x

Reading:
% LEL Level: 0 %O2: 20.8 CO: 0 H2S: 0

Tested Clean? ☒ Y ☐ N

Comments: _____


Printed Name: Peter Hill

Signature*: [Signature]

*this signature verifies that this tanker has been washed out and purged

Title: SUPERVISOR

Contact Phone Number: 780-868-2721



LAST CONTAINED

Date: OCT 17 2025 Time: 08:30 AMLocation: CALMAR, ALBERTATank Unit# HP5042Comments: RESIDUE DIESELPrinted Name: PETER HILLSignature*: [Signature]Title: SUPERVISORContact Phone Number: 780-868-2721