

K69-11



TANK WASH AND PURGE TEST

Date: Oct 15, 2025 Time: 10:00 AM

Location: Ryley AB

Tank Unit# 791181

Meter Used: _____

Reading:
% LEL Level: 0 %O₂: 20.8 CO: 0 H₂S: 0

Tested Clean? ☒ Y ☐ N

Comments: A bit rusty on the inside from
sitting for a few years.

Printed Name: Wayne Codd

Signature*: Wayne Codd
*this signature verifies that this tanker has been washed out and purged

Title: Operations Manager

Contact Phone Number: 780 603-7561