

Owner Code/Schedule Number(s): 6416-7

RESIDUE LAST CONTAINED

Company: RBS Bulk Systems Inc.

Consignor Name: Rylee Stonehouse

Address: 123-55202 St 825, Sturgeon County, AB, T8L 5C1

Phone Number: 780-720-7906

Transporter: _____

Description of tank (including serial number): Unit 7047

Vin: 2S9BTP5326C031268

Serial: 1268

Tank emptied:

YES



NO



Please note all tanks must be emptied

Tank purge/steamed:

YES



NO



3rd Party Certificate provided:

YES



NO



Other: _____

Consignor Signature: _____

Date:

Oct 19 / 25

Consignor Print Name: _____

Rylee Stonehouse

INTERNAL USE ONLY:

OK'D BY: _____

G416-7



**ADVANCE
TANK CENTRES**

Date: OCT 1/25
 Customer: RBS Unit# 7047
 Work Order No.: ATC 6740000001 Serial No.: 1268
 Employee Name: B. ROWLEY Clock #: 2401

On this date, Advance Tank Centres rendered this tank safe.

It is important to recognize that:

- In order to do so, it may have been necessary to steam or otherwise introduce water in the tank, it's pipeline and other accessories.
- There is a danger of damage to the tank or its equipment through freezing. It is your responsibility to take precautions to avoid such damage. Advance specifically disclaims any liability for damage of this sort.
- As part of the process, pipelines may be left unconnected. Manholes and other devices may also be open and these must be identified and dealt with. This is your responsibility.
- Prior to being placed back into service all piping connections, valves etc. should be checked and the system should be purged to remove moisture or other contaminants introduced during the steaming or repair operations.
- While this tank was rendered safe on this date is no assurance that it will remain so. It is very important to recognize that this tank may re-gas or otherwise become dangerous at any time and without additional hazardous material being added to the tank. This tank must be retested for safety before any operations are carried out on it or before and after it is moved into a hazardous environment. This would include a shop. This retesting is responsibility; Advance specially disclaims any liability for and future dealings with this tank once it has left our control.

Read and understood this _____ day of _____, 20_____.

Signed _____

 (Print Name)

On behalf of _____
 Customer Name

Owner Code/Schedule Number(s): G416-8

RESIDUE LAST CONTAINED

Company: RBS Bulk Systems Inc

Consignor Name: Rylee Stonehouse

Address: 123-55202 St 825, Sturgeon County, AB, T8L5C1

Phone Number: 780-720-7906

Transporter: _____

Description of tank (including serial number): Unit 7048

Vin: 2S9 BTP4236C031269

Serial: 2401

Tank emptied:

YES



NO



Please note all tanks must be emptied

Tank purge/steamed:

YES



NO



3rd Party Certificate provided:

YES



NO



Other: _____

Consignor Signature: _____

Date: Oct 19/25

Consignor Print Name: Rylee Stonehouse

INTERNAL USE ONLY:
OK'D BY: _____

GY16-8


**ADVANCE
TANK CENTRES**

Date: OCT 1/25
 Customer: RBS Unit#: 7048
 Work Order No.: ATC6740010001 Serial No.: 1269
 Employee Name: B. ROWLEY Clock #: 2401

On this date, Advance Tank Centres rendered this tank safe.

It is important to recognize that:

- In order to do so, it may have been necessary to steam or otherwise introduce water in the tank, its pipeline and other accessories.
- There is a danger of damage to the tank or its equipment through freezing. It is your responsibility to take precautions to avoid such damage. Advance specifically disclaims any liability for damage of this sort.
- As part of the process, pipelines may be left unconnected. Manholes and other devices may also be open and these must be identified and dealt with. This is your responsibility.
- Prior to being placed back into service all piping connections, valves etc. should be checked and the system should be purged to remove moisture or other contaminants introduced during the steaming or repair operations.
- While this tank was rendered safe on this date is no assurance that it will remain so. It is very important to recognize that this tank may re-gas or otherwise become dangerous at any time and without additional hazardous material being added to the tank. This tank must be retested for safety before any operations are carried out on it or before and after it is moved into a hazardous environment. This would include a shop. This retesting is responsibility; Advance specially disclaims any liability for and future dealings with this tank once it has left our control.

Read and understood this _____ day of _____, 20_____.

Signed _____

(Print Name)

On behalf of _____

Customer Name