



WABASH MFG. INC.
9312-110A ST
WESTLOCK, AB
T79 2M4
780-349-4282

L 26-6-LEAD
NOV

PURGE REPORT

Warning: Wabash Mfg. Inc. will not be liable in any way regarding our Purge Report.

Company Name: Ricks Oilfield

Work Order #: SV-26254

Customer PO #: _____

Serial #: 10752

Unit #: T167L

Date: 2026 / 06 / 18
YY / MM / DD

Residue

Is there residue of material in tank? Y ☒ N ☐

What is the residue? Oil

Hoses

Are there any hoses with this unit? Y ☒ N ☐

Are the hoses to be with the unit? Y ☒ N ☐

Additional Information

Is the unit "HOT"? Y ☐ N ☒

Is the identification plate(s) legible? Y ☒ N ☐


Is the outside of the unit dirty? Y ☐ N ☒

Internal Wash

Was this unit internally washed? Y ☐ N ☒

By signing my name below, I am stating that I have purged every possible orifice, in, on, or around the above stated unit.

Name: Maury Litke

Signature: 

Position: Inspector

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING



WABASH MFG. INC.
9312-110A ST
WESTLOCK, AB
T79 2M4
780-349-4282

L 21-7-Pur
NOV

PURGE REPORT

Warning: Wabash Mfg. Inc. will not be liable in any way regarding our Purge Report.

Company Name: Ricks Oilfield

Work Order #: SV-26247

Customer PO #: _____

Serial #: 10753

Unit #: T167P

Date: 2026 / 06 / 17
YY / MM / DD

Residue

Is there residue of material in tank? Y ☒ N ☐

What is the residue? Oily

Hoses

Are there any hoses with this unit? Y ☒ N ☐

Are the hoses to be with the unit? Y ☒ N ☐

Additional Information

Is the unit "HOT"? Y ☐ N ☒

Is the identification plate(s) legible? Y ☒ N ☐


Is the outside of the unit dirty? Y ☐ N ☒

Internal Wash

Was this unit internally washed? Y ☐ N ☒

By signing my name below, I am stating that I have purged every possible orifice, in, on, or around the above stated unit.

Name: Maury Litke

Signature: 

Position: Inspector

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING