

K69-27



TANK WASH AND PURGE TEST

Date: Oct 17 / 2025 Time: 08:30 AM

Location: CALMAR, ALBERTA

Tank Unit# 2016

Meter Used: MSA ULTAR 4X

Reading: % LEL Level: 0 %O2: 20.8 CO: 0 H2S: 0

Tested Clean? Y N

Comments: _____

Printed Name: Peter Hill

Signature*: [Signature]

*this signature verifies that this tanker has been washed out and purged

Title: SUPERVISOR

Contact Phone Number: 780-868-2721