

K69-9



TANK WASH AND PURGE TEST

Date: October 10th 2025 Time: 10:00am

Location: 2130-121Ave Edmonton

Tank Unit# 7910775

Meter Used: _____

Reading: _____
% LEL Level: 0.0 %O2: 20.3 CO: 0.0 H2S: 0.0

Tested Clean? / N

Comments: _____

Trailer has been steamed and Flushed

CLEAN

Printed Name: Aaron Hemmings

Signature*: Aaron Hemmings

*this signature verifies that this tanker has been washed out and purged

Title: Service Coordinator

Contact Phone Number: _____