

K69-11



### TANK WASH AND PURGE TEST

Date: Feb 24th 2026 Time: \_\_\_\_\_

Location: 2130-121 ave NW Edmoton AB

Tank Unit# 79463

Meter Used: \_\_\_\_\_

Reading:  
% LEL Level: 0.0 %O2: 20.5 CO: 0.0 H2S: 0.0

Tested Clean?  / N

Comments: \_\_\_\_\_

Unit has been flushed

Printed Name: Aaron Hemmings

Signature\*: Aaron Hemmings

\*this signature verifies that this tanker has been washed out and purged

Title: Service coordinator

Contact Phone Number: \_\_\_\_\_