



K69-10
SEP

WABASH MFG. INC.
9312-110A ST
WESTLOCK, AB
T79 2M4
780-349-4282

PURGE REPORT

Warning: Wabash Mfg. Inc. will not be liable in any way regarding our Purge Report.

Company Name: Clean Harbors

Work Order #: SV-25792

Customer PO #: _____

Serial #: E000196

Unit #: 791221

Date: 2025 / 9 / 24
YY / MM / DD

Residue

Is there residue of material in tank? Y ☐ N ☒

What is the residue? _____

Hoses

Are there any hoses with this unit? Y ☐ N ☒

Are the hoses to be with the unit? Y ☐ N ☐

Additional Information

Is the unit "HOT"? Y ☐ N ☒


Is the identification plate(s) legible? Y ☒ N ☐

Is the outside of the unit dirty? Y ☐ N ☒

Internal Wash

Was this unit internally washed? Y ☒ N ☐

By signing my name below, I am stating that I have purged every possible orifice, in, on, or around the above stated unit.

Name: Maury Litke Signature:  Position: Inspector

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING