

K69-2  
NOV



## TANK WASH AND PURGE TEST

Date: October 6, 2026 Time: 11:00 AM

Location: Edm, AB 2130-121 Ave NE

Tank Unit# 781104

Meter Used: MSA 4 head monitor

Reading:  
% LEL Level: 0 %O<sub>2</sub>: 20.8 CO: 0 H<sub>2</sub>S: 0

Tested Clean? ☒ / N

Comments: Tanks have been pressure washed out.

Printed Name: Ahlen Poetz

Signature\*: 

\*this signature verifies that this tanker has been washed out and purged

Title: Supervisor

Contact Phone Number: 587-596-5343