



WABASH MFG. INC.
9312-110A ST
WESTLOCK, AB
T79 2M4
780-349-4282

F60-5
NOV

PURGE REPORT

Warning: Wabash Mfg. Inc. will not be liable in any way regarding our Purge Report.

Company Name: Peter Kiewit

Work Order #: SV-26396

Customer PO #: _____

Serial #: 5155232010

Unit #: _____

Date: 2026 / 09 / 15
YY / MM / DD

Residue

Is there residue of material in tank? Y ☒ N ☐
What is the residue? WATER

Hoses

Are there any hoses with this unit? Y ☒ N ☐
Are the hoses to be with the unit? Y ☐ N ☒

Additional Information

Is the unit "HOT"? Y ☐ N ☒
Is the identification plate(s) legible? Y ☒ N ☐
Is the outside of the unit dirty? Y ☐ N ☒

Internal Wash

Was this unit internally washed? Y ☐ N ☒

By signing my name below, I am stating that I have purged every possible orifice, in, on, or around the above stated unit.

Name: MAURY LITKE Signature: *Maury Litke* Position: INSPECTOR

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING

F60-5
NOV

Wabash Mfg. Inc.

9312-110A Street
Westlock, AB T7P 2M4
780-349-4282

Sniffer Test Report

Company Name: 15702 KIEWIT

Work Order #: SL-26395

Unit #: 143018

Serial #:

Date: 2026109115
YY / MM / DD

WARNING: WABASH MFG. INC. WILL NOT BE LIABLE IN ANY WAY REGARDING OUR SNIFF REPORT

RESIDUE

Is there a residue of any material in tank? ☐ Yes ☒ No

Is it over two inches at any given spot? ☐ Yes ☒ No

What is the residue? _____

Who is to remove it? _____

Date of Removal: ____ / ____ / ____
YY / MM / DD

Time of Removal: ____ : ____
☐ am ☐ pm

HOSES

Are there any hoses with this tank or tractor? ☐ Yes ☒ No

If yes, how many? _____

Are the hoses hot? [I yes, see reverse side for details] ☐ Yes ☒ No

Do the hoses need to be steamed? ☐ Yes ☒ No

Do the hoses need to be vented? ☐ Yes ☒ No

Are the hoses to be left on tank or truck? ☐ Yes ☒ No

If not, where will they be left? _____

ADDITIONAL INFORMATION

Is this tank or truck tractor "HOT"? (See reverse side for details) ☐ Yes ☒ No

Is the identification plate(s) legible? ☐ Yes ☒ No

Is the outside of this tank or tractor dirty? ☐ Yes ☒ No

Are there any toolboxes or cabinets? ☐ Yes ☒ No

COMMENTS:

First Sniff

Time: 7:20
☒ am ☐ pm

By signing my name below, I am stating that I have sniffed every possible orifice in, on or around the above stated tank or tractor and I have accurately written in the reading and/or I have checked off the N/A box (s) on the reverse side of this report.

Name: FREDIE Signature: _____ Position: TOSSER

Second Sniff

Time: ____ : ____
☐ am ☐ pm

By signing my name below, I am stating that I have sniffed every possible orifice in, on or around the above stated tank or tractor and I have accurately written in the reading and/or I have checked off the N/A box (s) on the reverse side of this report.

Name: _____ Signature: _____ Position: _____

Third Sniff

Time: ____ : ____
☐ am ☐ pm

By signing my name below, I am stating that I have sniffed every possible orifice in, on or around the above stated tank or tractor and I have accurately written in the reading and/or I have checked off the N/A box (s) on the reverse side of this report.

Name: _____ Signature: _____ Position: _____

Fourth Sniff

Time: ____ : ____
☐ am ☐ pm

By signing my name below, I am stating that I have sniffed every possible orifice in, on or around the above stated tank or tractor and I have accurately written in the reading and/or I have checked off the N/A box (s) on the reverse side of this report.

Name: _____ Signature: _____ Position: _____

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING.

IMPORTANT

Failing to ensure that all orifices sniff clean prior to issuing a green tag can result in hot work being done on a hot tank causing explosions, bodily injury and/or death.

Failing to ensure that all orifices sniff clean prior to issuing a green tag can result in hot work being done on a hot tank causing explosions, bodily injury and/or death.

[illegible]