A11-1
DEC

CDR WELDING & INSPECTIONS LTD.

PURGED

THIS VEHICLE OR TANK HAS BEEN STEAM PURGED TO THE REQUIREMENTS OF THE FIRE CODE AND HAS BEEN FOUND TO BE SAFE ACCORDING TO STANDARD TESTING PROCEDURES.

EVEN THOUGH THIS TANK OR CONTAINER TESTS SAFE AT THE TIME OF COMPLETION OF STEAMING, IT IS POSSIBLE FOR EXPLOSIVE VAPOURS TO BUILD UP THEREAFTER AND FOR THAT REASON IT MUST BE **RE-TESTED** WITH AN EXPLOSIMETER BEFORE WORK IS COMMENCED ON THE VEHICLE OR TANK.

HAZARDOUS VAPOUR & OXYGEN TEST RECORD

Strause unit# 1212
VIN# 2H9AEBHG3DT002173

EMPLOYEE	DATE	TIME	UNIT SAFE			
			OXYGEN		EXPLOSIVE	
			YES	NO	YES	NO
Brad Sinclair	[redacted]	8:30 a.m.	✓		✓	
	Nov 2/26.					