K69-3
DEC

Clean Harbors

TANK WASH AND PURGE TEST

Date: Nov 17/26 Time: 3:00 AM

Location: Prosco+

Tank Unit#: 717706

Meter Used: GasClip

Reading:
% LEL Level: ϕ %02: 19.5 CO: ϕ H2S: ϕ

Tested Clean: (Y) / N

Comments: Washed + purged

Printed Name: Craig Polk

Signature*:

*(this signature verifies that this tanker has been washed out and purged

Title: Area Manager

Contact Phone Number: 780-205-9979