K69-7
DEC

WABASH MFG. INC.
9312-110A ST
WESTLOCK, AB
T79 2M4
780-349-4282

PURGE REPORT

Warning: Wabash Mfg. Inc. will not be liable in any way regarding our Purge Report.

Company Name: Clean Harbors

Work Order # : SV-26502

Customer PO #: _____

Serial # : 1NPTX4EX7GD284082

Unit #: 790374

Date: 2026 / 11 / 24
YY / MM / DD

Residue
Is there residue of material in tank? Y ☐ N ☑
What is the residue? _____

Hoses
Are there any hoses with this unit? Y ☐ N ☑
Are the hoses to be with the unit? Y ☐ N ☐

Additional Information
Is the unit "HOT" Y ☐ N ☑
Is the identification plate(s) legible? Y ☐ N ☑ - missing
Is the outside of the unit dirty? Y ☐ N ☑

Internal Wash
Was this unit internally washed? Y ☑ N ☐

By signing my name below, I am stating that I have purged every possible orifice, in, on, or around the above stated unit.

Name: MAURY LITKE Signature: _____ Position: INSPECTOR

YOU ARE REQUIRED TO ASK IF YOU ARE NOT SURE ABOUT ANYTHING