

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



RO2-

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 6C7
1-204-945-0020

Manitoba 
A867002

Date Inspection Started 31 DAY 07 MO. 24 YR.			Station Number A621713			Station Name DAYZ'S TIRE & REPAIR			City 204 523 2202			Province 204 523 2202			Postal Code 204 523 2202			Phone 204 523 2202								
Date Inspection Completed 01 DAY 08 MO. 24 YR.			Mechanic Number 109710			Mechanic Signature [Signature]			Vehicle Owner PACIFIC AIRWAYS LTD.			Address [Address]			City [City]			Province [Province]			Postal Code [Postal Code]			Phone [Phone]		
Inspection Expiry Date 31 DAY 08 MO. 25 YR.			Vehicle Identification Number 1U4U433311271370			Make [Make]			Model [Model]			Year 2004			Unit # R 302			Pass/Safe Vehicle ☒			Fail/Unsafe Vehicle ☐			Fail/Hazardous ☐		
Licence Number TR116410			Prov. MB			NSC # [NSC #]			Odometer Reading [Odometer Reading]			Odom. Type ☐ km ☐ mi			Confirmed legible Vehicle Identification Number on vehicle ☒			THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED								

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

_____ Truck 363019 QWYR KGS _____ Truck Tractor _____ Trailer ☒ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus
 List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when Item Rejected "XX" under "R" when Item Hazardous "X" under "P" when Item Corrected or No Defects found in Section																																																																																											
X		Section 1 - Power Train: Defects (if any)																																																																																											
X		Section 2 Suspension: Defects (if any)																																																																																											
X		— X 5 (15) Two AIRBAG R/R																																																																																											
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																																											
X		— X 15 (50) front both 11x16 brake and drum no w.																																																																																											
X		Section 4 - Steering: Defects (if any)																																																																																											
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																											
X		Section 6 - Lamps: Defects (if any)																																																																																											
X		Section 7 - Electrical System: Defects (if any)																																																																																											
X		— X 10 both tail light wiring.																																																																																											
X		Section 8 - Body: Defects (if any)																																																																																											
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																											
X		— X 4 (A) Adjusted air pressure.																																																																																											
X		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11</td> <td>11</td> <td>14</td> <td>14</td> <td>90</td> <td>90</td> <td>92</td> <td>95</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>20</td> <td>20</td> <td>20</td> <td>20</td> <td>100</td> <td>90</td> <td>92</td> <td>92</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>11</td> <td>11</td> <td>11</td> <td>11</td> <td>95</td> <td>88</td> <td>85</td> <td>80</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	11	11	14	14	90	90	92	95	100	100	100	100	2	20	20	20	20	100	90	92	92	100	100	100	100	3	11	11	11	11	95	88	85	80	100	100	100	100	4													5												
Axle	Tread Depth				Air Pressure																																																																																								
	Initial		Corrected		Initial		Corrected																																																																																						
	L	R	L	R	L	R	L	R																																																																																					
1	11	11	14	14	90	90	92	95	100	100	100	100																																																																																	
2	20	20	20	20	100	90	92	92	100	100	100	100																																																																																	
3	11	11	11	11	95	88	85	80	100	100	100	100																																																																																	
4																																																																																													
5																																																																																													
X		Section 10 - Coupling Devices: Defects (if any)																																																																																											

THIS INSPECTION IS NOT A WARRANTY.
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection, a complete inspection will be required.