

04051192

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba
R02-1Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
A982838

Date Inspection Started 3 9 11 25 DAY MO. YR.	Station Number A61007	Station Name Northline Service	City St. James
Date Inspection Completed 03 11 25 DAY MO. YR.	Mechanic Number M75911	Mechanic Signature [Signature]	Station Phone Number 2043243535
Inspection Expiry Date 3 0 11 26 DAY MO. YR.	Vehicle Owner Canehek Tilt Deck Services Ltd.		
Address City Province Postal Code Phone			
☐ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CSIF4109	Prov. MB	NSC # 1406881
Vehicle Identification Number 11X1510U9XX6N2954819		Make Pele	Model 379
☐ Confirmed legible Vehicle Identification Number on vehicle		Year 06	Unit # 108
Odometer Reading 398391		Odom. Type km	mi

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR 24500 KGS ☒ Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	Section 1 - Power Train: Defects (if any) R Rear Fuel Tank Strap Loose
✓		Section 2 Suspension: Defects (if any) Advise Steer Shackle Pin / Bushing Play
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type R Steer Shoe Oil/Grease contamination LFD Brake Adjustment Advise RFD Shoes
✓		Section 4 - Steering: Defects (if any)
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) Windshield Wipers inoperable
X	X	Section 6 - Lamps: Defects (if any) Plate Light out Clearance Light out
X	X	Section 7 - Electrical System: Defects (if any) Front batt hold down bolt loose
X	X	Section 8 - Body: Defects (if any) Rear Crossmembers 2 bolts broken Advise L/Hood Hinge
X	X	Section 9 - Tire & Wheel: Defects (if any) Advise Steer tread depth Steer Pressures out >10% 10% Drive Pressures out
✓		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	6	10			95	120		
2	21	19	20	20	95	105	95	100
3	17	19	20	18	95	0	90	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature