



Commercial Vehicle Inspection Report

Decal Number: GL20941
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21662693

R03-1
Inspection Result:
PASS

FACILITY:	LIGHTHOUSE MECHANICAL / S6863	INSP. TYPE:	Complete	INSP. START:	2026-Feb-09 03:45 PM PST
INSPECTOR:	DYCK, ALLAN TRENT / 113057	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Feb-10 11:15 AM PST
WORK ORDER #:	533V248	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	00307731	VIN:	5V8VA53B57M708869
PLATE #:	83455B	UNIT/FLEET#:	533V248	OWNER/LESSEE NAME:	Comox Valley, Distribution Ltd.
LICENCED GVW(kg):	999999	BODY STYLE:	Van Trailer	ADDRESS:	11398 Bridgeview Drive, 11398 Bridgeview Drive Surrey, British Columbia V3R0C2, Canada
VEHICLE YEAR:	2007	ODOMETER:			
MAKE:	VANGUARD	HUB ODOMETER:	27494 KM		
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day)
Section 3A - Air Brakes	Repaired (same day)
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day)
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	42	40	8	9	9	9	
2	Clamp	30	Automatic	43	45	12	12	12	12	
3	Clamp	30	Automatic	43	43	6	6	5	7	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	62	53	Lining (Shoe)	17	18	Drum		
2	40	53	Lining (Shoe)	18	18	Drum		
3	42	42	Lining (Shoe)	19	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: DYCK, ALLAN TRENT

Road Test Date:
Signature:

Allan Dyck

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-12 10:55 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the vehicle inspection program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

2/12/2026 10:55:59 AM PST