



Internal Visual Inspections - 5361 - 2021-01-14

Authoring Information

Created By Chris Gilley
7808317055

TC Registration 25-1030 (Expires: 2024-10-01)

Company **Keystone Mechanical**
9421 141 ave
Grande prairie, AB
T8V8E1

Created 2021-01-14 15:01:26

Updated 2021-01-14 15:03:14

Client

Company **Dynamic Energy group.**
Box 730
Grande Prairie, AB
T8v 7n9

Contact 780-876-8249

Tank Data

Ser. No. 5361

Unit Number 409

TC Spec. DOT 407

Date of mfr. 2006-06-00

Cert. date 2006-06-00

VIN 1FVHA6AV37LX29748

Tank mfr. TREMCAR

CTMV Orig. Test Date 2006-06-00

CTMV Cert Date 2006-06-00

MAWP 35 psi

Test P. 52.5 psi

Min. head thick .14 in

Min. shell thick .129 in

Exposed Surface 430 ft²

Cap. 17500 litres

Internal Visual Inspection

Inspection Date 2021-01-14

Inspection Expiry Date 2026-01-31

Inspection **Lining test completed if lined as per 7.2.2.1(c)**
Not Applicable

Enter the tank and inspect for: dents, gouges, cracks, corrosion, abrasions or signs of leakage in the shell or heads including bulkheads as per 7.2.2.1(a)
Pass

Inspect piping, valves and gaskets for damage as per 7.2.2.1(a)
Pass

Inspect every weld for cracks, defects or signs of leakage as per 7.2.2.1(b)
Pass

Corroded areas are thickness tested if found as per 7.2.2.1(d)
Not Applicable

Defects No defects found.

Tank Disposition

Current Disposition Passed / No Defects Found

Approval

A handwritten signature in blue ink, consisting of a stylized 'A' followed by a cursive 'e'.

Inspector

Chris Gilley

Service provided by eStandard Solutions.