



Commercial Vehicle Inspection Report

Decal Number: GP54979
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21905551

R04-1
Inspection Result:
PASS

ACILITY:	NIXON BROS. TRUCK REPAIR LTD. / S16280	INSP. TYPE:	Complete	INSP. START:	2026-Sep-02 09:00 AM PDT
INSPECTOR:	METTERS, DEVON / 301613	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Sep-02 12:00 PM PDT
WORK ORDER #:	83253	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	13669465	VIN:	1FVXTEDB51DH09345
LATE #:	XT6208	UNIT/FLEET#:		OWNER/LESSEE NAME:	VIC CITY CRANE LTD.,
PERMITTED GVW(kg):	42200	BODY STYLE:	Truck Tractor	ADDRESS:	2406 SNOWDEN PL
VEHICLE YEAR:	2001	ODOMETER:	43259 Miles		Sooke, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			V9Z1J9, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) Replace exhaust elbow at bottom of muffler
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Replace license plate lights
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Replace passenger side hood latch, replace missing reflector tape
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	28.6	28.6	6.4			7.9	✓
2	Clamp	30	Automatic	41.3	44.5	11.9	11.1	11.9	11.1	
3	Clamp	30	Automatic	22.2	38.1	11.1	11.9	11.1	11.1	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	22	25	Lining (Shoe)	19	19	Drum		
2	34	36	Lining (Shoe)	19	19	Drum		
3	39	50	Lining (Shoe)	18	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: METTERS, DEVON

Signature:

This Inspection Report was submitted to CVSE on 2026-Sep-02 12:11 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE014

2/2026 12:11:17 PM PDT