

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GF47085 2026-Mar-31 21277905

Inspection Result:

FACILITY: JOHNSON RADIATOR SERVICES /

GILOWSKI, TRAVIS GORDON /

200472

INSP. CLASS:

Complete

INSP. START:

INSP. COMPLETE:

WORK ORDER #:

INSP. REASON:

Annual

Class 2 - Heavy Vehicle with LGVW

5501 kg or more

2025-Mar-20 06:00 AM -07 2025-Mar-20 09:00 AM -07

VEHICLE JUR:

INSPECTOR:

207546

British Columbia

REGI:

12441721 PVI-23

VIN:

3C7WRNFL1JG113437

PLATE # ME4063 LICENCED GVW(kg): 11790 VEHICLE YEAR:

Vehicle Identification (VIN)

Section 1 - Power Train

Section 2 - Suspension

2018

DODGE/RAM

UNIT/FLEET#: BODY STYLE: ODOMETER: HUB ODOMETER:

Utility Truck 120623 KM

Hydraulic

Diesel

OWNER/LESSEE NAME: ADDRESS:

PEACE VALLEY INDUSTRIES, PVI

PO BOX 1510

Chetwynd, British Columbia V0C1J0, Canada

MAKE: MODEL:

Passed

Passed Repaired (same day) Passed with Caution

BRAKE TYPE:

FUEL TYPE:

REPLACED REAR SHOCKS RF ROTOR GETTING THIN

Section 3 - Brake System Section 3H - Hydraulic Brakes Passed Section 4 - Steering Passed Section 5 - Instruments and Auxiliary Passed Equipment Section 6 - Lamps Passed Section 7 - Electrical System Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Passed

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	12			12	V	Pad	12	12	Rotor	38.62	37.55
2	13	15	14	14		Pad	12	12	Rotor	38.33	38.36
Comme	nt:					Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? Inspector: GILOWSKI, TRAVIS GORDON Road Test Date: Before Inspection

Signature:

This Inspection Report was submitted to CVSE on 2025-Mar-20 09:24 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations