



Commercial Vehicle Inspection Report

Decal Number: GH69998
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21298336

1206-1
Inspection Result:
PASS

FACILITY:	RJAMES WESTERN STAR / S7341	INSP. TYPE:	Complete	INSP. START:	2025-Mar-24 08:04 AM PDT
INSPECTOR:	HINGER, FRANK JULIUS / 109527	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Apr-03 09:55 AM PDT
WORK ORDER #:	KEL015836	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	14191730	VIN:	5KKHALDR8EPFL3093
PLATE #:	SR7557	UNIT/FLEET#:	559	OWNER/LESSEE NAME:	PITURA ENT LTD, PITURA
LICENCED GVW(kg):	55600	BODY STYLE:	Dump Truck	ADDRESS:	3139 APPALOOSA RD
VEHICLE YEAR:	2014	ODOMETER:	320577 KM		Kelowna, British Columbia
MAKE:	WESTERN ST	HUB ODOMETER:			V1V2G9, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed with Caution #2 AXLE L/R SIDE SLACK ADJUSTER YOKE/ PIN.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	32	8			10	✓
2	Clamp	30L	Automatic	38	38	10	10	11	10	
3	Clamp	30L	Automatic	35	41	12	13	12	12	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	35
2	60	75
3	70	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	19
Lining (Shoe)	17	17
Lining (Shoe)	16	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: HINGER, FRANK JULIUS
Road Test Date: 4/3/2025
Signature: [Signature]
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-03 09:57 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/3/2025 9:57:11 AM PDT