

Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number: GK61143 2026-Mar-31 21483444

Inspection Result:

FACILITY:

CHADD PETERS HEAVY

EQUIPMENT REPAIR LIMITED / S20120

INSP. CLASS:

INSP. TYPE:

Complete Class 3 - Trailer and Semi-Trailer

INSP. START: INSP. COMPLETE:

2025-Sep-03 11:55 AM PDT 2025-Sep-03 12:55 PM PDT

INSPECTOR: **WORK ORDER #:** PETERS, CHADD / 300480

VIN:

2MFB2R6F76R003800

VEHICLE JUR:

British Columbia 60131K

LICENCED GVW(kg): 0

UNIT/FL FFT# BODY STYLE:

INSP. REASON:

14336619 tr-39 **Dump Trailer**

Semi-annual

OWNER/LESSEE NAME: ADDRESS:

ray peters trucking, ray 9375 trans canada hwy Chemainus, British Columbia

VEHICLE YEAR: MAKE: MODEL:

PLATE #:

2006 MIDLAND ODOMETER: **HUB ODOMETER:**

BRAKE TYPE:

FUEL TYPE:

v0r1k4, Canada

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Passed Not Applicable

Not Applicable

Not Applicable

REGI:

Section 3 - Brake System

Repaired (same day)

repair brake pots and slack as required

Section 3A - Air Brakes

Section 3H - Hydraulic Brakes

Not Applicable

Passed

Passed

Section 4 - Steering

Section 5 - Instruments and Auxiliary

Equipment

Section 6 - Lamps

Section 7 - Electrical System

Section 8 - Frame and Body Section 9A - Tires

Passed

Passed with Caution #2 inner tire to be replaced by customer

Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components

Passed Passed Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34.9	31.8	9	14	5.5	7.5	
2	Clamp	30	Automatic	31.8	34.9	6	16	2	14	
3	Clamp	30	Automatic	31.8	31.8	6	9	9	10	
4	Clamp	30	Automatic	31.8	31.8	11	6	10	4	
Comment:						Comment:				



Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GK61143 2026-Mar-31 21483444 Inspection Result:

ir Brake Camshaf	t Rotation (degr	ees)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	40	40	Lining (Shoe)	19	19	Drum			
2	65	40	Lining (Shoe)	18	19	Drum			
3	60	45	Lining (Shoe)	15	16	Drum			
4	55	40	Lining (Shoe)	18	17	Drum			
Comment: Comment:						Comment: Air Brake Camshaft Rotation performed, Rot Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested?
Inspector: PETERS, CHADD

No Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-03 01:01 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.