

Marchese Excavations And Bin Hire - Work Order Summary

Asset:
35 - Caterpillar D6T LGP Bulldozer (Unit 35)

Location:
42 BURNSIDE ROAD, ORMEAU QLD 4208

Current Tracker Hours:
17063

Current Tracker Kms:
1

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
527	Replaced Left Hand Final Drive	28/04/2025	16800	0	17/04/2025	High Priority	Closed	
496	500 hours service (16800 Hrs Service)	07/11/2024	16753	0	04/07/2025	Routine Service	Closed	
476	16528 hours service	06/09/2024	16531	0	28/04/2025	Routine Service	Closed	
447	Replaced Chains & Bolts	05/06/2024	0	0	05/06/2024	High Priority	Closed	
368	Serviced at 16224.2	24/02/2024			26/02/2024	Routine Service	Closed	
364	Need new aircon filter and cabin filter	19/02/2024	16172	0	21/02/2024	High Priority	Closed	
361	New Cutting edges	15/02/2024	16149	0	16/02/2024	High Priority	Closed	
306	16000 hours service	21/12/2023	15944	0	22/12/2023	Routine Service	Closed	
295	Serviced at 15870 final drives and engine	07/12/2023			08/12/2023	Routine Service	Closed	
275	Multiple Prestart Defects Multiple Prestart Multiple	08/11/2023			10/11/2023	High Priority	Closed	
267	NEW C9 Engine put in machine	27/10/2023	15649	0	30/10/2023	High Priority	Closed	
263	Hemisphere gps	23/10/2023			28/10/2023	High Priority	Closed	
261	Hydraulic filter housing leaking again	20/10/2023			23/10/2023	High Priority	Closed	
256	Heater control valve and tinted windows	10/10/2023			12/10/2023	High Priority	Closed	
253	Mssing track plate bolts	27/09/2023			03/10/2023	High Priority	Closed	
243	15500 hours service	22/09/2023	15449	0	25/09/2023	Routine Service	Closed	
244	Prestart Defect - 2. Visibility, Windscreen, Prestart	22/09/2023			25/09/2023	High Priority	Closed	
241	Due for service in 85hrs at 15500	16/09/2023	15411	0	18/09/2023	High Priority	Closed	
239	Hydraulic filter leaking needs oil top up and transmission oil	15/09/2023			18/09/2023	Medium Priority	Closed	
236	Needs tint on the window s	12/09/2023			13/09/2023	High Priority	Closed	
233	Isolator needs replacing	06/09/2023			04/10/2023	High Priority	Closed	
226	Rh Carrier roller needs replacing	28/08/2023			30/08/2023	High Priority	Closed	
225	Lhs rollers need to changed asap asap	28/08/2023			31/08/2023	High Priority	Closed	
222	Aircon Replaced	24/08/2023	15307	0	30/08/2023	High Priority	Closed	
216	Hydraulic filter housing leaking	16/08/2023			17/08/2023	Medium Priority	Closed	
205	Isolator needs replacing	01/08/2023			02/08/2023	High Priority	Closed	
204	Service tracks lh ram collapsed bearing	31/07/2023			01/08/2023	High Priority	Closed	
199	Prestart Defect - 9. Engine: Oil, Water, Noise, Grease, Smoke	20/07/2023			01/08/2023	Medium Priority	Closed	
196	Sprockets chains rollers idler wheel Replaced	13/07/2023	15019	0	01/08/2023	High Priority	Closed	
192	Left hand rear idler wheel noisy	11/07/2023			01/08/2023	High Priority	Closed	
188	15000 hours service	05/07/2023	14956	0	06/07/2023	Routine Service	Closed	

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
173	Leaking cannon rhs	09/06/2023			10/06/2024	Medium Priority	Closed	
142	Due for service rhf windscreen wiper blade needs replacing	27/03/2023			28/03/2023	High Priority	Closed	
134	14500 hours service	18/03/2023	14450	0	20/03/2023	Routine Service	Closed	
127	Cutting edges and track plate put back on asap	04/03/2023			06/03/2023	High Priority	Closed	
97	Cutting edge on blade	08/02/2023			09/02/2023	Medium Priority	Closed	
95	Over heating - Changed Over Faulty Thermostat	08/02/2023	0	0	18/10/2023	Routine Service	Closed	
70	Previous Maintenance History	06/01/2023	14087	0	06/01/2023		Closed	
69	Previous Maintenance History	06/01/2023	14087	0	06/01/2023		Closed	
44	Previous Maintenance History	05/01/2023	14087	0	06/01/2023		Closed	
35	Prestart Defect - 6. Hydraulics: Rams, Hoses, Leaks, Wear, et	30/11/2022			30/11/2022	Routine Service	Closed	
1	14000hr service and track repair	21/10/2022	0	0	14/10/2022		Closed	Nicholas Mcneilly