

Veh#	Date	W/O#	Description	Notes	Odometer
8235	#####	1343264	Service	Completed document email to Sue	1332873
8235	#####	1343963	Mechanic entered - Wheels	Decommissioned the bus for SALE	1332873
8235	#####	1343264		Secured all wiring and put all the panels back. Organised all consat MDVR and bus minders into boxes. Completed	1332873
8235	#####	1343066	Mechanic entered - Elec anc	Company informed bus is being sold as is and no further repairs to be conducted.	1332873
8235	#####	1343065	Mechanic entered - Body Bc	Company informed bus is being sold as is and no further repairs to be conducted.	1332873
8235	#####	1342420		Company informed bus is being sold as is. No further repairs to be conducted.	1332873
8235	#####	1343071	Mechanic entered - Body Re	Company informed bus is being sold as is and no further repairs to be conducted.	1332873
8235	#####	1343264		Removed the number plate rivets and put riv nuts screwed down number plate. Removed bus minder and cradle including all source. Removed MDVR Unit wires and time stamp unit. Removed consat unit with audio amplifiers and fuse box. Removed E tag, C/O	1332873
8235	#####	1343264	Decommission bus for SALE	removed number plate rivet and put riv nut and screw then pulled out MDDVR consat busminder and etag with Aahil C/o.	1332873
8235	#####	1343069	Mechanic entered - Warnin	Company informed bus is being sold as is and no further repairs to be conducted.	1332873
8235	#####	1342480		Fit second hand exhaust flexy hose from scrap bus 8227 sent one from 8235 to be repaired by pakenham exhausts.	1332873
8235	#####	1342402		Helped Matt test the brakes and fitted all rear tyres with Matt. Torqued to 600 nm. Completed	1332873
8235	#####	1342402		Repaired air leaks from the brake lines to N/S/R Booster had both wheels off to check for leaks. Once o-rings replaced and fittings cleaned checked for leaks no more foot brake leak. Fit back all rear tyres with Ahill and tensioned to 600nm.	1332873
8235	#####	1342480		Removed broken flexy - Flange from muffler to turbo.	1332873
8235	#####	1342480	Mechanic entered - Engine I	removed flexi tube connecting turbo housing and muffler	1332873
8235	#####	1342479	Mechanic entered - Elec anc	replaced globe works good	1332873
8235	#####	1342491	HANDLE GRAB GREY STRAP BRV001		1332873
8235	#####	1342491	HANDLE GRAB GREY STRAP BRV001		1332873
8235	#####	1342491	Mechanic entered - Body OI	Replaced 2 x passenger overhead grab handles as the handle rope had frayed beyond repair	1332873
8235	#####	1342485	Mechanic entered - Body OI	Lower bolt on modesty panel was broken and missing nut replaced bolt and nut	1332873
8235	#####	1342485		Secured rear modesty pole panel with new nut & bolt.	1332873
8235	#####	1342420	Mechanic entered - Body Fr	***Found front L/H edge damaged at the top section torn off ***Order form in 21/5/2026 @ 10:20am***	1332873
8235	#####	1342402		Helped take off wheels and practiced putting them back on with silil	1332873
8235	#####	1342402	O-RING KIT LARGE VOSS A6739970145		1332873
8235	#####	1342402	Mechanic entered - Brakes I	Set the bus up on the hoists and lowered onto stands then prepped for rear wheel removal Ahill removed the rear wheels for practice found the air leak from the union feeding into the N/S/R booster removed union and cleaned it up.	1332873
8235	#####	1340986		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Ben to 600nm	1332873
8235	#####	1340986		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist reported all found defects.	1332873
8235	#####	1328688		Fire Extinguisher Test & Tag - Completed by ATS - February 2026	1331737
8235	#####	1322723	Mechanic entered - CCTV	Hard Drive Hard drive out of date	1330949
8235	#####	1322723		supervised and guided Aahil to change hard drive.Complete.	1330949
8235	#####	1322723	HARD DRIVE SOLID STATE 1TB (17128E-P01)		1330949
8235	#####	1322725		Assisted in carrying out CCTV A service as per check list. Completed.	1330949
8235	#####	1322725		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Carried out CCTV A service as per check list. Completed.	1330949
8235	#####	1322725		Carry out CCTV A Service as per check list Complete.	1330949
8235	#####	1321624		completed	1330949
8235	#####	1321624		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS carried out safety inspection as per checked list	1330949
8235	#####	1321624		VEHICLE SAFETY INSPECTION	1330949
8235	#####	1321820	Consumables		1330949
8235	#####	1321656	Consumables		1330949
8235	#####	1321820		Assisted	1330949
8235	#####	1321820	Mechanic entered - Wheels	Retensioned O/S/R wheel nuts.	1330949
8235	#####	1321656		removed and replaced N/S rear pos 5.6 all wheel nuts retension with silil NM650	1330949
8235	#####	1321656		changed O/R tyres tensioned wheel nut 650nm with Silil	1330949
8235	#####	1321656	Mechanic entered - Wheels	Justin changed O/R tyres tensioned wheel nut tensioned wheel nut 650nm. (used run out)	1330949
8235	#####	1321735	Mechanic entered - Fluid Le	replaced new clamp top up coolant ok	1330949
8235	#####	1321754	Consumables		1330949
8235	#####	1321754	Mechanic entered - Body OI	repaired the broken spring	1330949
8235	#####	1321235	Consumables		1330833
8235	#####	1321235	PTI Tablet Entered -Elec and	replaced globe.	1330833
8235	#####	1313918	PUMP WIPER WASHER 24 VOLT		1330445
8235	2/4/2026	1318234	Consumables		1330368
8235	2/4/2026	1318234		check and foud damage wire next stop switch next to rear door repaired wire	1330368
8235	2/3/2026	1318234	Workshop Tablet Entered -E	door operation ok found door bell keep comingremove and checked all bel switches door bell keep coming C/O	1330368
8235	2/3/2026	1318234	Workshop Tablet Entered -Body - Rear_Door	Operation Faulty	1330368
8235	#####	1317005		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed transmission service	1330368
8235	#####	1317005		carry out checkover justin and aaron work	1330368
8235	#####	1317005	FILTER ZF ECOMAT GEARBOX (4139-298-038)(3098081)		1330368
8235	#####	1317005		Carry out Transmission service as per checklist with Justin	1330368
8235	#####	1317005	OIL ZF GEARBOX SYNTHETIC ECOFLUID A PLUS		1330368
8235	#####	1313918	Mechanic entered - Wipers	replaced faulty washer motor. operation checked - serviceable.	1329638
8235	#####	1313918	PUMP WIPER WASHER 24 VOLT		1329638
8235	#####	1309879	Engine steam Clean radiator	Completed Intercooler clean and cleaned engine bay	1328662
8235	#####	1307186	Engine (None) oil filter hou	replaced both oil filters and orings test run and checked not leaking at the time that checked monitor	1327960
8235	#####	1307186	FILTER OIL MERC BENZ 0500LE E5 OH1830 ES		1327960
8235	#####	1306297	Mechanic entered - Fluid Le	remove and clean oil filter cap. run up engine check not leaking at time of checking	1327378
8235	#####	1305833		Assisted Abraham and retensioned wheel nuts to 600Nm.	1327378
8235	#####	1305833		VEHICLE SAFETY INSPECTION Completed VSI.	1327378
8235	#####	1305833		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Retensioned wheel nuts w/ Guri to 600Nm.	1327378
8235	#####	1299276		CARRY OUT C SERVICE AS PER CHECK LIST C service completed and retensioned wheel nuts w/ Aaron to 600Nm.	1327378
8235	#####	1299276		Assist Abraham with C service as per checklist and Retensioned wheelnuts to 600Nm	1327378
8235	#####	1299276	FILTER AIR MERC BENZ 0500LE E3 - E5 A0040941704		1327378
8235	#####	1299276	BREATHER OIL MIST MERC BENZ 0500LE		1327378
8235	#####	1299276	FILTER FUEL/WATER SEPARATOR MERC 0500LE >E5		1327378
8235	#####	1299276	OIL SAMPLE TEST KIT		1327378
8235	#####	1299276	FILTER FUEL MERC BENZ 0500LE E5		1327378
8235	#####	1299276	FILTER OIL MERC BENZ 0500LE E5 OH1830 ES		1327378
8235	#####	1299276	FILTER POWER STEER SCANIA ALL MODELS		1327378
8235	#####	1299276	OIL FAN DRIVE MERC BENZ 0500LE E3 to E5 75W-90		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276		CARRY OUT B SERVICE AS PER CHECK LIST B service completed.	1327378
8235	#####	1299276	OIL ENGINE ALL FLEET PLUS E900 15W-40		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378

8235	#####	1299276		CARRY OUT A SERVICE AS PER CHECK LIST A service completed.	1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1299276	Consumables		1327378
8235	#####	1297417		Retensioned wheel nuts w/ Aaron pos3456 to 600Nm.	1326488
8235	#####	1297417	Mechanic entered - Wheels	Retensioned all rear wheelnuts with Abraham to 600nm	1326488
8235	#####	1297417	Consumables		1326488
8235	#####	1285350		removed and replaced rear sway bar bushes tensioned bolts to 210nm seating nicely all good and tensioned rear wheel nuts with aaron	1326355
8235	#####	1285350	BUSH REAR SWAY BAR MER	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G394487RET Receiving #:419625 Date :2025-09-12	1326355
8235	#####	1285350	BUSH SWAY BAY 60MM ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394415RET1 Receiving #:419626 Date :2025-09-12	1326355
8235	#####	1287915	ROAD WORTHINESS INSPEC	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G394564 Receiving #:419786 Date :2025-09-16	1326355
8235	#####	1285350	Mechanic entered - Suspens	reemove bushes c/o.	1326355
8235	9/5/2025	1285350	BUSH SWAY BAR REAR MER	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394349RET Receiving #:419099 Date :2025-09-05	1326355
8235	9/5/2025	1285350	BUSH SWAY BAY 60MM ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394415RET Receiving #:419103 Date :2025-09-05	1326355
8235	9/5/2025	1285350	BUSH SWAY BAY 60MM ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394415 Receiving #:419152 Date :2025-09-05 wrong need to return	1326355
8235	9/5/2025	1285350	BUSH SWAY BAR REAR MER	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394415 Receiving #:419154 Date :2025-09-05 replacement - Richard Singapore	1326355
8235	9/5/2025	1285350	BUSH SWAY BAR REAR MER	stock usage correction	1326355
8235	9/3/2025	1287915		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1326355
8235	9/3/2025	1287915		VEHICLE SAFETY INSPECTION completed.	1326355
8235	9/3/2025	1287915		ANNUAL SAFETY INSPECTION SERIAL # RSI 072472 - 03.09.2025 - PASSED	1326355
8235	9/3/2025	1285350	BUSH FRT & RR SWAY BAR	WRONG SIZED BUSHES over booked	1326355
8235	9/3/2025	1285350	BUSH SWAY BAY 60MM ME	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394415 Receiving #:419004 Date :2025-09-03 wrong need to return	1326355
8235	9/2/2025	1285350	BUSH SWAY BAR REAR MER	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G394349 Receiving #:418757 Date :2025-09-02	1326175
8235	9/2/2025	1285350	BUSH REAR SWAY BAR MER	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G394487 Receiving #:419002 Date :2025-09-03	1326175
8235	9/1/2025	1285350	Mechanic entered - Suspension	Other rear sway bar bushes nee	1326175
8235	9/1/2025	1285350	BUSH FRT & RR SWAY BAR	WRONG SIZED BUSHES PUTTING INTO STOCK	1326175
8235	9/1/2025	1285350		removed all rear tyre removed bushes and found out new ones are wrong refitted old parts and rear tyres and tensioned wheel nuts with satheesh and ordered new parts	1326175
8235	9/1/2025	1287368	Mechanic entered - Elec anc	removed snd replaced indicator housing tested all working	1326175
8235	9/1/2025	1287414	Mechanic entered - Elec anc	removed and replaced high beam housing tested all working	1326175
8235	9/1/2025	1287414	HEADLAMP INSERT HELLA 90MM L/FLOOR	0500 9314365038525	1326175
8235	9/1/2025	1287427	Mechanic entered - Elec anc	removed second hand light from scrap bus and fitted tested all working	1326175
8235	9/1/2025	1287368	LIGHT INDICATOR SIDE L/H		1326175
8235	9/1/2025	1287368	Consumables		1326175
8235	9/1/2025	1287414	Consumables		1326175
8235	9/1/2025	1287427	Consumables		1326175
8235	9/1/2025	1287435	DECAL WHEELCHAIR ACCESS RAMP	LOAD RATED 300KG	1326175
8235	9/1/2025	1287435	Mechanic entered - Body OI	fitted new decal	1326175
8235	9/1/2025	1287444	Mechanic entered - Body Fr	adjusted front door rear leaf now clearing prefectly and opening and closing okay	1326175
8235	9/1/2025	1287367		assisted with final inspection	1326175
8235	9/1/2025	1287367		Accidently opened	1326175
8235	9/1/2025	1287367	Carryout final inspection for	RSI	1326175
8235	9/1/2025	1287367		completed. Steam cleaned Assisted jimmy to fix the door decal and head light jobs.	1326175
8235	9/1/2025	1287367	Consumables		1326175
8235	9/1/2025	1287367	Consumables		1326175
8235	9/1/2025	1287367	Consumables		1326175
8235	9/1/2025	1287435	Consumables		1326175
8235	9/1/2025	1287435	Consumables		1326175
8235	9/1/2025	1287444	Consumables		1326175
8235	9/1/2025	1287444	Consumables		1326175
8235	#####	1287026		FIRE EXTINGUISHER TEST & TAG - COMPLETED BY ATS FIRE	1326175
8235	#####	1285350	BUSH FRT & RR SWAY BAR	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G393989 Receiving #:418367 Date :2025-08-27	1326175
8235	#####	1285329		replaced the valve.	1326175
8235	#####	1285328	RUBBER BRAKE PEDAL PAD	FROM STOCK	1326175
8235	#####	1285328		replaced the rubber.	1326175
8235	#####	1285329	TEST NIPPLE 3/8 16MM AIR		1326175
8235	#####	1285315		PRE ANNUAL SAFETY INSPECTION CHECK completed as per check list.	1326175
8235	#####	1285315		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST done	1326175
8235	#####	1285342	Mechanic entered - Wipers	check and found that fuse was blownreplaced the fuse then wiper motor got power but wipers was still not working check and found that wiper linkage connecting bolt to the motor was loose. tighten the bolt and check after wipers working all ok.	1326175
8235	#####	1285350	Mechanic entered - Suspens	ordered the parts. c/o	1326175
8235	#####	1285349	Mechanic entered - Engine	steam clean done.	1326175
8235	#####	1285340	Mechanic entered - Fluid Le	fixed the leaking heater hose and replaced the o-ring on coolant sensor on header tank . topped up the coolant steam cleaned and checked after road test all ok.	1326175
8235	#####	1285341	Mechanic entered - Body Pa	replaced the torn seat bases from scrap bus 8227.	1326175
8235	#####	1285341	Consumables		1326175
8235	#####	1285328	Mechanic entered - Brakes	ordered the parts.c/o	1326175
8235	#####	1285329	Mechanic entered - Air Syst	ordered the part. c/o removed the air tank valve from scrap bus 8227 and fitted fixed the air leak.	1326175
8235	#####	1284110		VEHICLE SAFETY INSPECTION	1326175
8235	#####	1284110		Assisted Guri.	1326175
8235	#####	1284110		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1326175
8235	8/7/2025	1281164		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1325542
8235	8/7/2025	1281164	MIZU A/C FOAM CLEANER SPRAY		1325542
8235	#####	1278839	Mechanic entered - Fluid Le	carried out removed and replaced and still leaking carried out removing againa nd re sealing with abit of silicon carried out road tested got up to temp check for leaks no leaks ok	1324990
8235	#####	1278839	THERMOSTAT 83 DEG 0500LE	- A004203837501 MAN S1.06402.0063	1324990
8235	#####	1278499		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Starter motor trigger wire secured with conduit. Carried out fire safety inspection as per checklist. Complete	1324990
8235	6/3/2025	1268239	Mechanic entered - Wheels	Retensioned wheel nuts pos 5 and 6.	1324495
8235	6/3/2025	1268239		Assisted	1324495
8235	6/3/2025	1268239	Consumables		1324495
8235	#####	1266779		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Retensioned wheel nuts w/ Guri to 700Nm.	1324495
8235	#####	1266779		VEHICLE SAFETY INSPECTION Completed VSI.	1324495
8235	#####	1266779		Assisted Abraham.	1324495
8235	#####	1266803	Mechanic entered - Wheels	Fitted runout tyes pos.56 and tensioned wheel nuts w/ Guri to 700Nm	1324495
8235	#####	1266803		Assisted Abraham Tensioned wheel nuts pos.56 to 700Nm.	1324495
8235	#####	1266803	Consumables		1324495
8235	#####	1265038		Replaced air hose holding tube re-connect all wiring harnessess to different computers. Complete	1324478
8235	#####	1265038		Put the demister back into the bus tight the screws put the wiring into the nodes and secured it with cable ties put the demister air ducted into the right position checked everything is secured Complete.	1324478
8235	#####	1265038		Put a new demister inside the bus connecting other units which was disconnected when taking the demister out still working on the bus to connect the units and wiring	1324428
8235	#####	1265038		assist Zakir to put Demister and then tried put other parts in too.C/O.	1324428
8235	#####	1265038		checked all hoses clamp and tighten clamps	1324395
8235	#####	1265038			1324395

8235	#####	1265038	DEMISTER HEATER UNIT	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G387807 Receiving #:411212 Date :2025-05-22	1324395
8235	#####	1265038	Driver Tablet Entered -A/C †	removed and replaced hose job not completed	1324378
8235	#####	1265038	BALL VALVE 3/4 S/S 304 HEATER 20MM		1324378
8235	#####	1265038		Removed and replaced new engine side gate valve drain coolant . removed gate valve hose and replaced new hoses. removed and replaced new 2mm hose	1324378
8235	#####	1265038	Driver Tablet Entered -A/C †	removed the heater core and ordered the parts C/O	1324378
8235	#####	1265038	Drv entered - A/C Heating N	Replaced demister valve run unit up found the gate valve has failed parts have been ordered	1324361
8235	#####	1265038	VALVE HEATER DEMISTER MERC 0500LE(DH4008)(37V3305)		1324361
8235	#####	1265038	VALVE GATE A/C 3/4" BRASS	Transferring from Pakenham KW	1324361
8235	5/8/2025	1263153	Deinstall smart track and fit	Completed by smart track Joe	1324178
8235	5/8/2025	1263153	Consumables		1324178
8235	#####	1260643	Ops Entered - Fault - Body R	Replaced pressure switch. PTI done.	1321943
8235	#####	1260643	SWITCH AIR BRAKE PRESSURE ROLL AWAY 4.0 BAR MERC BENZ 0500LE		1321943
8235	#####	1260643		Assisted in replacing switch and cleaning	1321943
8235	#####	1260643	Consumables		1321943
8235	#####	1259768	Elec and Light	Warning Ligh carried out checking bus for warning lights on dash no warning lights carried out road testing to see if any faults come on the dash no faults bus ok.	1321794
8235	#####	1259768	Consumables		1321794
8235	#####	1259523	Elec and Light	Warning Ligh Checked found no warning light on dash. Drive tested all ok.	1321794
8235	#####	1255924	SBIWA - SIDE ARROW WHITE	Creditor #:EA-TRA013 TRANSCAL P/O #:EA385567 Receiving #:409198 Date :2025-04-22	1321794
8235	#####	1255924	FREIGHT	Creditor #:EA-TRA013 TRANSCAL P/O #:EA385567 Receiving #:409198 Date :2025-04-22	1321794
8235	4/9/2025	1257737	Consumables		1320685
8235	4/9/2025	1257737	Elec and Light	Check and re; checked speaker and find speaker is damage and wire broken from inside. take a good speaker out of bus 8227 and fit it and cked ok. Complete.	1320685
8235	4/9/2025	1255923	Accident # 58673 - NEARSID	East coast completed repair and refer w/o 1255924 and 1255923	1320685
8235	4/9/2025	1255923	Accident # 58673 - NEARSID	As above	1320685
8235	4/9/2025	1255923	Accident # 58673 - NEARSID	As above	1320685
8235	4/8/2025	1255924	D/S LOWER ORANGE STRIPES - SMART BUS		1320685
8235	4/8/2025	1255924	D/S LOWER BLACK STRIPES - SMART BUS		1320685
8235	4/8/2025	1255924	SAUSAGE WHITE BOSTIK		1320685
8235	4/8/2025	1255924	EDGE STEP INSERT YELLOW	tristan booked this for luke as TIMS was down.	1320685
8235	4/8/2025	1255924		glue down w/chair surround and put on stickers	1320685
8235	4/8/2025	1255924	GLASS WINDSCREEN CR228	Creditor #:EA-0BR001 O'BRIENS GLASS INDUSTRIES P/O #:EA385339 Receiving #:408744 Date :2025-04-14	1321001
8235	4/7/2025	1255924	LIGHT INDICATOR SIDE R/H		1320685
8235	4/7/2025	1255924	PANEL SIDE SUPPORT STAYS TELESCOPIC		1320685
8235	4/7/2025	1255924		finished repair on w/chair surround and fitted panel	1320685
8235	4/7/2025	1255924	DOOR PILLAR RUBBER		1320685
8235	4/7/2025	1255924	WHEEL ARCH RUBBER BACKING P/LENGTH		1320685
8235	4/4/2025	1255924		perp and paint	1320685
8235	4/4/2025	1255924	PAINT DEBEER LIGHTNING STRIKE SILVER 4LTR		1320685
8235	4/4/2025	1255924		fibreglassed w/chair surround	1320685
8235	4/3/2025	1255924		drilled hinge and nstalled	1320685
8235	4/2/2025	1255924		finished off panel and took to pants shop removed w/chair ramp surround	1320685
8235	4/1/2025	1255924	HINGE WHEEL ARCH C2 UPPER 3MT		1320685
8235	4/1/2025	1255924	C2 LOWER WHEEL ARCH HINGE 6MT		1320685
8235	4/1/2025	1255924	HINGE RUBBER FOR COBALT 2		1320685
8235	4/1/2025	1255924	SHEET ALUM 5050 240cm x120cm x 3mm		1320685
8235	4/1/2025	1255924	Piano Hinge - # 12422 - 63r	Creditor #:EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:EA384858 Receiving #:407981 Date :2025-04-02	1320685
8235	4/1/2025	1255924		continued making panel and fixed doors not closing properly	1320685
8235	#####	1255923	Accident # 58673 - NEARSID	Bus at east coast and repairing	1320685
8235	#####	1255924	TPAF - N/S/F Damage - Accident# 58673		1320685
8235	#####	1249781		rechrgre battries done battery lord test batteries serviceble	1317891
8235	#####	1249781	Consumables		1317891
8235	#####	1249782		replaced 3 faulty air drain plugs	1317891
8235	3/5/2025	1238009	Workshop Tablet Entered -A/C Heating - Not Cooling		1317181
8235	3/5/2025	1238009	Driver Tablet Entered -A/C †	Compressor is noisy will replaced when compressor failses	1316851
8235	3/5/2025	1249574	TANK COOLANT HEADER MI	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G382812-1 Receiving #:405838 Date :2025-03-05	1316851
8235	3/4/2025	1249782	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1316575
8235	3/3/2025	1249748	VEHICLE SAFETY INSPECTION	Assist guri carry out safety inspection as per checklist.	1316556
8235	3/3/2025	1249748	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	Tension all wheel nuts with Guri	1316556
8235	3/3/2025	1249748		completed safety inspection as per check list and tensioned the wheel nuts with Louchlan	1316556
8235	3/3/2025	1249574	PTI Tablet Entered -Coolant leak		1316556
8235	3/3/2025	1249574		removed and replaced header tank topped up the coolant steam clean the engine bay . Done road test and check the level after road test all ok	1316556
8235	3/3/2025	1249574		Assist Guri replace header tank	1316556
8235	3/3/2025	1249781	Mechanic entered - Elec anc	ordered the parts. c/o	1316556
8235	3/3/2025	1249782	Mechanic entered - Air Syst	ordered the parts.c/o	1316556
8235	#####	1248774		COMPLETED BY ATS 23/2/2025	1315992
8235	#####	1248180		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	1315992
8235	#####	1244141	Mechanic entered - Engine †	replaced idler pulley and belt.	1314826
8235	#####	1345289	PERFORM CAMPAIGN 02/21	DONE 13/02/2025	1314325
8235	#####	1244141	PULLEY ADJUSTER IDLER PULLEY 0500 - UPPER		1313705
8235	#####	1244141	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696		1313705
8235	#####	1244141	PULLEY IDLER/ ADJUSTER M	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G381585 Receiving #:404438 Date :2025-02-12	1313705
8235	#####	1244141	Mechanic entered - Engine †	Requested parts C/Over.	1313594
8235	#####	1244133	Driver Tablet Entered -Elec †	check all the stop buttom all ok and working.	1313594
8235	#####	1244133	Consumables		1313594
8235	#####	1244129		Assisted Abraham with king pin check and tensioned the wheel nuts.	1313594
8235	#####	1244129		CARRY OUT A SERVICE AS PER CHECK LIST Completed	1313594
8235	#####	1244129	Consumables		1313594
8235	#####	1244129	Consumables		1313594
8235	#####	1244129	Consumables		1313594
8235	2/6/2025	1243160	Driver Tablet Entered -Susp	Measured kneeling height ok.	1312842
8235	#####	1241981		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST carried out air system service as per check list. removed the pipe and inspected all ok so have not replace the pipes.	1312024
8235	#####	1241981	AIR DRYER ASSY MERC 0500LE A0004302915		1312024
8235	#####	1241981	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1312024
8235	#####	1241981	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1312024
8235	#####	1238009	Workshop Tablet Entered -†	Run commission test found unit low on refrigerant traced back too pressure switch seal and tested ok charge system and run up compressor failed pump down and is very noisy will fit a second hand compressor from a decommissioned bus job not completed carry over	1309129
8235	1/4/2025	1236806	Driver Tablet Entered -Engir	checked no engine light or waring lights road tested ok	1308482
8235	1/3/2025	1236604	Driver Tablet Entered -Elec †	There was a broken behind the panel at front of the bus fixed the broken wire and secured the wiring with tape Complete.	1308482
8235	1/3/2025	1236604	Driver Tablet Entered -Elec and Light - Next Stop Button		1308482

8235	1/3/2025	1236604	Driver Tablet Entered -Elec and Light - Next Stop ButtonM	1308482
8235	1/3/2025	1236604	Consumables	1308482
8235	#####	1236215	Driver Tablet Entered -Air S ₁ Repaired air leaks from hose connector to tank.	1307933
8235	#####	1235913	Workshop Tablet Entered -v Right at the back the hammer emergency hammer bracket was broken replaced with new. Complete	1307933
8235	#####	1235471	PTI Tablet Entered -Elec and replaced globe.	1307690
8235	#####	1235471	Consumables	1307690
8235	#####	1234721	VEHICLE SAFETY INSPECTION completed as per check list.	1307411
8235	#####	1234721	OIL ENGINE ALL FLEET PLUS E900 15W-40	1307411
8235	#####	1234721	completed safety inspection as per check list and tensioned all wheel nuts with gurdarshan topped up 2l of engine oil	1307411
8235	#####	1234721	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with jimmy	1307411
8235	#####	1234740	Consumables	1307411
8235	#####	1234734	BRUSH WHEELARCH 75mm 2.5M PER WHEEL	1307411
8235	#####	1234734	Mechanic entered - Body OI fitted new wheel arch brush	1307411
8235	#####	1234740	MUDFLAP 605MM X 330MM	1307411
8235	#####	1234740	Mechanic entered - Body OI Assisted Jimmy with fitting mud flap.	1307411
8235	#####	1234740	removed and replaced n/s/f mudflap	1307411
8235	#####	1234734	Consumables	1307411
8235	#####	1232640	FAN CONDENSOR A/C CITI-RT	1305720
8235	#####	1232640	Workshop Tablet Entered -f Replaced right number 1 and center condenser fan motor assemblies replaced return air filter medium check refrigerant levels tested heat and cool modes tested ok	1305720
8235	#####	1231924	Driver Tablet Entered -spae: checked and find Consat speaker was a bit loud adjusted it from amplifier and checked ok.Complete.	1305270
8235	#####	1231924	Consumables	1305270
8235	#####	1230400	Driver Tablet Entered -Speal The interior voice speaker is set at (DEFAULT 003 percents) should be at 060 (sixty) percents still figuring out how to set the volume at 060. under process The volume is all set accordingly and speakers are working aswell. Complete	1303935
8235	#####	1230400	Consumables	1303935
8235	#####	1229991	PTI Tablet Entered -Right ha retight bolts.	1303647
8235	#####	1229991	Consumables	1303647
8235	#####	1226771	PTI Tablet Entered -Body -Rj Already replaced and refer w/o 1226215	1300279
8235	#####	1226245	Drv entered - Body Mirrors I Defect made twice.	1300279
8235	#####	1226153	Driver Tablet Entered - - Spe checked bus consat sound was all ok but did not find what the issue is with smart track we can not check that.Complete.	1300279
8235	#####	1226153	Consumables	1300279
8235	#####	1226215	Accident O/S MIRROR Broi Replaced O/S morror.	1300279
8235	#####	1226215	MIRROR R/H 380MM SHORT UES1411D	1300279
8235	#####	1223831	Mechanic entered - Wheels Assisted Abraham	1298160
8235	#####	1223831	Tensioned wheel nuts w/ Nick pos.34	1298160
8235	#####	1223831	Consumables	1298160
8235	#####	1223468	VEHICLE SAFETY INSPECTION	1298160
8235	#####	1223468	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS carried out safety inspection as per check list tension all wheel nuts with Lachlan	1298160
8235	#####	1223468	Carried out safety inspection as per checklist Tensioned all wheel nuts with indi	1298160
8235	#####	1223491	Mechanic entered - Wheels R/R pos 3 and 4 tyres (used new recap 2x tyres for pos 3 and 4 - 295/80R22.5)	1298160
8235	#####	1223491	Removed and replaced worn tyre used new recap for tyre pos 3 and 4 Tensioned wheel nuts with indi	1298160
8235	#####	1223491	Consumables	1298160
8235	#####	1222652	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Carroed out tune up service as [per check list.	1297765
8235	#####	1222651	CAP RADIATOR 70KPA MERC 0500LE A0005014615	1297765
8235	#####	1222651	CARRY OUT A SERVICE AS PER CHECK LIST carried out A service as per check list Tension all wheel nuts with Zubz Replaced Radiator capTighten Radiator bottom hose. it was leaking. replaced air tank maual air drain valve.	1297765
8235	#####	1222651	Consumables	1297765
8235	#####	1222651	Consumables	1297765
8235	#####	1222651	Consumables	1297765
8235	#####	1219501	PERFORM CAMPAIGN 11/2/ DONE	1294820
8235	#####	1215640	Ops Entered - Fault - Gearbc Checked transmission oil level ok. Checked transmission wiring harnessok. Drive tested found transmission temperature gauge up and down. Fitted temperature gauge from bus 8239 bus ok. (order parts BUS 8239)	1293766
8235	#####	1217799	Consumables	1293070
8235	#####	1217799	Mechanic entered - Wheels Retensioned pos 5 and 6 wheel nuts	1293070
8235	#####	1217799	Assisted	1293070
8235	#####	1217198	Driver Tablet Entered -A/C † Repair completed and refer w/o 1217104	1293070
8235	#####	1217104	Consumables	1293070
8235	#####	1217104	Drv entered - Dash Switches Replaced second hand demister switch the demister switvh and demister working fine. Complete	1293070
8235	#####	1217022	Consumables	1293070
8235	#####	1217022	PTI Tablet Entered -Wheels : Fitted Runout tyre @ pos. 3 and Tensioned wheel nuts with Zubair.	1293070
8235	#####	1217022	Tensioned wheel nuts with Satheesh	1293070
8235	#####	1216959	Consumables	1293070
8235	#####	1216959	GLOBE 24V 70W H1 HLC2470	1293070
8235	#####	1216959	PTI Tablet Entered -Elec and Light - Exterior Lightleft hea	1293070
8235	#####	1216726	Driver Tablet Entered -Wipe Removed and replaced broken wiper blade	1292858
8235	#####	1216726	WIPER BLADE ASSEMBLY 39037 5/S FROM TX1000	1292858
8235	#####	1215640	GAGUE OIL TEMP VDO 24V Creditor #:GB-ASH001 NAPA AUTO PARTS P/O #:G372894 Receiving #:395228 Date :2024-09-25	1292858
8235	#####	1215640	BRACKET 52MM VDO GALUC Creditor #:GB-ASH001 NAPA AUTO PARTS P/O #:G372894 Receiving #:395228 Date :2024-09-25	1292858
8235	#####	1212389	road safety inspection Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G371731 Receiving #:394262 Date :2024-09-11	1290474
8235	9/6/2024	1212850	Workshop Tablet Entered -E check brakes all ok done brake test all pass. road tested bus serviceble	1289501
8235	9/4/2024	1212389	VEHICLE SAFETY INSPECTION	1289501
8235	9/4/2024	1212389	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1289501
8235	9/4/2024	1212389	ANNUAL SAFETY INSPECTION SERIAL #RSI 063202. PASS. 4/9/2024. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 completed.	1289501
8235	9/2/2024	1211806	Consumables	1289077
8235	9/2/2024	1211808	Consumables	1289077
8235	9/2/2024	1211794	Consumables	1289077
8235	9/2/2024	1211800	Consumables	1289077
8235	9/2/2024	1211834	Consumables	1289077
8235	9/2/2024	1211794	SEAT CUSH SINGLE CEN CVR CI	1289077
8235	9/2/2024	1211794	Mechanic entered - Body Pa removed and replaced with new and returned damaged cushion to store	1289077
8235	9/2/2024	1211800	Mechanic entered - Body OI drilled out worn rivets and fitted new rivets	1289077
8235	9/2/2024	1211806	Mechanic entered - Body OI installed new mudflap	1289077
8235	9/2/2024	1211806	MUDFLAP 605MM X 330MM	1289077
8235	9/2/2024	1211808	Workshop Tablet Entered -E replaced seat.	1289077
8235	9/2/2024	1211808	SEAT DRIVER RECO	1289077
8235	9/2/2024	1211834	Carry out final inspection fo completed	1289077
8235	9/2/2024	1211834	completed with zubair and steam cleaned bus	1289077
8235	#####	1211095	COMPLETED BY ATS 20/8/2024	1288613
8235	#####	1209980	Consumables	1287996

8235	#####	1209980	Drv entered - Body Drivers	replaced seat cushion.	1287936
8235	#####	1209980	SEAT CUSH 6008 DRIVER RE FIRB CVR PAD		1287936
8235	#####	1208523	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	Service as per list	1286486
8235	#####	1208523	FILTER DRYER AIR COND THERMO KING 2750300 DML305R		1286486
8235	#####	1208523	OIL AC COMPRESSOR		1286486
8235	#####	1208523	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	Service as per list	1286486
8235	#####	1208150	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	Service as per list	1286486
8235	8/9/2024	1206490	WIPER BLADE ASSEMBLY 39037 S/S FROM TX1000		1285402
8235	8/9/2024	1206490	Mechanic entered - Wipers	Fitted new wiper blade on driver side. pti done and parked in the line.	1285402
8235	8/9/2024	1206493	Consumables		1285402
8235	8/9/2024	1206498	Consumables		1285402
8235	8/9/2024	1206493	Mechanic entered - Elec anc	Fitted new globe.	1285402
8235	8/9/2024	1206498	Mechanic entered - Elec anc	Secured the indicator and brake lights with new set of Screws.	1285402
8235	8/9/2024	1204981	Consumables		1285402
8235	8/9/2024	1204981		fitted new gas struts on bothside disabled seats.	1285402
8235	8/8/2024	1204948	BOLT PROP - DIFF FLANGE 150MM MERC BENZ 0500LE		1285213
8235	8/8/2024	1204948	NUT PROPSHAFT BOLT MER Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370088	Receiving #:391931 Date :2024-08-08	1285402
8235	8/6/2024	1205608	Consumables		1285213
8235	8/6/2024	1204981		removed all the gas struts	1285213
8235	8/6/2024	1205608	Mechanic entered - Body OI	cleaned the rust spots treated and painted the under body coating	1285213
8235	8/6/2024	1205608	UNDERBODY SHUTZ BLACK L250 AEROSOL 500ML		1285213
8235	8/6/2024	1205299		repaired the air leaks	1285213
8235	8/5/2024	1205299	O-RING KIT LARGE VOSS A6739970145		1285213
8235	8/5/2024	1205299	Mechanic entered - Air Syst	r/ 3 out of 4 o-ring kit c/o	1285213
8235	8/2/2024	1204860	PRE ANNUAL SAFETY INSPECTION CHECK	Carried out pre RSI as per checklist reported all found defects. Tensioned all wheel nuts with Guri. Spent some time finding all the airleaks that need fixing.	1285213
8235	8/2/2024	1204860	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	CCTV service complete.	1285213
8235	8/2/2024	1204860		done wheel nut retensioned with matt	1285213
8235	8/2/2024	1204948	Mechanic entered - Gearbo	***Parts order form in 2/8/2024 @ 10:20am*** Fit second hand bolt from 8239 while it is off the road getting its engine rebuilt.	1285213
8235	8/2/2024	1204999	Mechanic entered - Engine	Removed the bolt that was loose and letting oil weep past cleaned area and put thread tape on the bolt then tighten up to 30nm.	1285213
8235	8/2/2024	1205007	Mechanic entered - Fluid Le	Fit new hose clamp to the headertank hose underneath sealing well now.	1285213
8235	8/2/2024	1205003	Consumables		1285213
8235	8/2/2024	1205006	Consumables		1285213
8235	8/2/2024	1205028	Consumables		1285213
8235	8/2/2024	1205006	Mechanic entered - Elec anc	Replaced light	1285213
8235	8/2/2024	1205006	LAMP LED NUMBER PLATE EXIT LIGHT 250120 27771		1285213
8235	8/2/2024	1205003	Mechanic entered - Elec anc	checked and find head light lense dirty.cleaned and find globe also worn.re-placed and checked ok.Complete.	1285213
8235	8/2/2024	1205003	GLOBE 24V 70W H1 HLC2470		1285213
8235	8/2/2024	1205028	Mechanic entered - Elec anc	removed and replaced the n/s/f high beam light assy from old stock.	1285213
8235	8/2/2024	1204981	Mechanic entered - Body OI	***Parts order form in 2/8/2024 @ 11:40AM	1285213
8235	8/2/2024	1204982	Consumables		1285213
8235	8/2/2024	1205000	Consumables		1285213
8235	8/2/2024	1205000	Mechanic entered - Body OI	Removed old sticker and cleaned surface fit new give way sticker.	1285213
8235	8/2/2024	1205000	DECAL GIVE WAY 240MM X 225MM		1285213
8235	8/2/2024	1204982	Mechanic entered - Body OI	Fit new ventura sticker to the O/S of the bus.	1285213
8235	8/2/2024	1204982	DECAL VENTURA ROUTE SV PART TRANSERED FROM ECTB		1285213
8235	8/1/2024	1204981	KS40-18-235 STRUTTS	Creditor #:GB-MCN001 MCNNAUGHTANS P/O #:G370072 Receiving #:391925 Date :2024-08-08	1285402
8235	#####	1203483	Mechanic entered - A/C Hea	Replaced torn belt with a new one made sure its been fitted correctly and bolt has been tightened properly new belt is working fine. Completed	1284521
8235	#####	1203483	BELT FAN DRIVE MERC BENZ 0500LE A0139971992		1284521
8235	#####	1203473		Performed fire safety inspection found torn drive belt and replaced with new one checked the new one is working fine. Completed	1284521
8235	#####	1203473	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	Completed fire safety inspection with Mehdi replaced drive belt as it was torn checked new one is working fine. completed	1284521
8235	#####	1203473		assisted Mehdi to fre safety inspection as per check list.Complete.	1284521
8235	#####	1201605	CARRY OUT B SERVICE AS PER CHECK LIST	Completed	1282890
8235	#####	1201605	OIL ENGINE ALL FLEET PLUS E900 15W-40		1282890
8235	#####	1201605	OIL SAMPLE TEST KIT		1282890
8235	#####	1201605	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1282890
8235	#####	1201605	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1282890
8235	#####	1201605	Consumables		1282890
8235	#####	1201605	Consumables		1282890
8235	#####	1201605		CARRY OUT A SERVICE AS PER CHECK LIST Completed	1282890
8235	#####	1201605	Consumables		1282890
8235	#####	1201605	Consumables		1282890
8235	#####	1200869	PERFORM CAMPAIGN 08/2/ DONE		1282407
8235	#####	1200097	PTI Tablet Entered -Wheels	Removed metal object & checked tyres are ok.	1281907
8235	#####	1200097	Consumables		1281907
8235	7/9/2024	1199491		VEHICLE SAFETY INSPECTION Completed check list.	1281559
8235	7/9/2024	1199491		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Abraham.	1281559
8235	7/9/2024	1199491		Assisted Rene.	1281559
8235	7/9/2024	1199509	Mechanic entered - Suspens	Removed and replace air bag.	1281559
8235	7/9/2024	1199509	AIRBAG FRT/RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200		1281559
8235	7/9/2024	1199514	Mechanic entered - Brakes	Removed and replace o ring air line fittings Tightened all fittings and secured test run engine build up air check ok no leak.	1281559
8235	7/9/2024	1199514	O-RING KIT LARGE VOSS A6739970145		1281559
8235	7/5/2024	1198711		checked and find blown globe.re-placed and checked ok.Complete.	1281034
8235	7/5/2024	1198711	Consumables		1281034
8235	7/2/2024	1197832	Vandalism. REPLACE ANTI G	COMPLETED BY GLASSPROTECH 1/7/24	1280810
8235	7/2/2024	1197832	REPLACE ANTI GRAFFITI FIL	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G365249 Receiving #:389357 Date :2024-07-02	1280810
8235	7/2/2024	1197182		conect workshop air gauges check all air system adjusted park brake air pressure secure os rear wear sensor wire road tested bus ok. stop all bus stop with park brake on. park brake holding ok.	1280810
8235	7/1/2024	1197182	Workshop Tablet Entered -E	check brake air system can't find anything wrong. i will check with driver c/o	1277531
8235	#####	1194289	Driver Tablet Entered -Braki	Checked for air leaks ok. Drive the bus and operate park brake it's holding. Performed brake test passed.	1277822
8235	#####	1194004	Mechanic entered - Wheels	Retensioned wheel nuts pos 1 and 2.	1277531
8235	#####	1194004		Assisted	1277531
8235	#####	1194004	Consumables		1277531
8235	#####	1192838		Fitted new f/n/s brake caliper/brake pads and adjusted front brakes. Tensioned caliper bolts ans wheel nuts to spec. Drive/brake tested and checked warning light on dash ok.	1277405
8235	6/8/2024	1192839			1277405
8235	6/8/2024	1192839	DECAL EMERGENCY EXIT PRESS BUTTON UNDER BUMPER		1277405
8235	6/8/2024	1192839	DOOR PILLAR RUBBER		1277405
8235	6/8/2024	1192839		remove and refit n/s front corner bar ands door rubber and refit decals	1277405
8235	6/7/2024	1192838	A0044208783 caliper	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G366196 Receiving #:387802 Date :2024-06-07	1277405

8235	6/7/2024	1192839	perp and paint	1277405
8235	6/7/2024	1192839	BUMPER FRONT N/SIDE CNR VOLGREN CR228	1277405
8235	6/5/2024	1192489	carried out complete job yesterdays.	1277405
8235	6/5/2024	1192489	Consumables	1277405
8235	6/5/2024	1192838	Removed both side calipers Discs and Hub. Cleaned Hub Bearingsand Re-Greased. Fitted Back New Discs Tensioned bolts to spec.Mounted Hub and Tensioned to Spec. O/s Calipers Mounted and Secured. Ordered N/s Front calipers c/o	1277405
8235	6/5/2024	1192838	Mechanic entered - Brakes \ Lifted up front of bus put on stands and removed front wheels removed brake pads and boosters. Removed Calipers Job is being taken over by Nick to finish off.	1277405
8235	6/5/2024	1192838	BOLT FRT BRAKE DISC MERC BENZ 0500LE A910105014019	1277405
8235	6/5/2024	1192838	Assisted Matt. Removed front wheels and brake pads. removed calipers	1277405
8235	6/5/2024	1192838	BRAKE DISC FRT / RR MERC BENZ 0500LE E3>E6 50F3339	1277405
8235	6/5/2024	1192838	Assisted	1277405
8235	6/5/2024	1192839	*** PHOTOS TAKEN BY GERALD *** - TPAF - R/2024/56771/MR - A	1277405
8235	6/4/2024	1192489	LAMP INDICATOR DURALED L.E.D 177 X 100	1277405
8235	6/4/2024	1192489	rear indicator not working carried out removing and replacing whole led light	1277405
8235	6/4/2024	1192489	BRAKE PADS FRT / RR MERC 0500LE E3>E5 49G7501BERAL	1277405
8235	6/4/2024	1192489	Workshop Tablet Entered -E carried out diagnosing found front pads low and took off wheels and found rotors also worn 37mm put wheels back on and park in bay.	1277405
8235	6/4/2024	1192489	Workshop Tablet Entered -Brakes - Warning Light On	1277405
8235	#####	1190071	Workshop Tablet Entered -Brakes - Park Brake Not Holding	1275600
8235	#####	1190071	VALVE RR MODULATOR MERC BENZ 0500LE A0004292124	1275600
8235	#####	1190071	Workshop Tablet Entered -E Checked faulty rear brake modulator replaced road tested ok.	1275600
8235	#####	1190071	O-RING KIT SMALL VOSS A0309971748	1275600
8235	#####	1190071	O-RING KIT LARGE VOSS A6739970145	1275600
8235	#####	1189478	PTI Tablet Entered -front rig replaced globe.	1275284
8235	#####	1189478	GLOBE 24V 70W H1 HLC2470	1275284
8235	#####	1189478	Consumables	1275284
8235	5/9/2024	1187208	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST carried out diff service as per check list.	1273580
8235	5/9/2024	1187208	OIL DIFFERENTIAL SYNGEAR 75W-140 CALTEX	1273580
8235	5/6/2024	1186542	Mechanic entered -Wheels Retension pos 3-4 wheel nuts.	1273027
8235	5/6/2024	1186542	Mechanic entered -Wheels Assisting	1273027
8235	5/6/2024	1186542	Consumables	1273027
8235	5/3/2024	1185892	Removed the N/s Rear park Brake Air Fittings. Changed Washer and Oring.connected Air lines and Fitted Wheels Back.Tensioned wheel nuts with Abraham.Re-filled diff oil and Road tested. Checked ok no leaks.	1272982
8235	5/2/2024	1185892	Mechanic entered - Brakes \ Fitted new Bearing runner Hub seal and Dust seal.Mounted hub and disc bolts Tensioned to spec and SecuredTensioned Axle nuts and caliper bolts to spec. Adjusted Brake. found Air leaking at brake Booster fittings c/o.	1272982
8235	5/2/2024	1185892	SEAL KIT REAR HUB MERC BENZ 0500LE E3 - ES 1F1304	1272982
8235	5/2/2024	1185892	Assisted	1272982
8235	#####	1185336	VEHICLE SAFETY INSPECTION Completed check list.	1272538
8235	#####	1185336	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Satheesh.	1272538
8235	#####	1185358	Mechanic entered - Engine \ Assisted.	1272538
8235	#####	1185358	Mechanic entered - Engine \ Removed and replaced exhaust muffler. Ex. muffler parted-out from bus 8228	1272538
8235	#####	1183420	Workshop Tablet Entered -E driver side indicator not working,find blown globe globe re-placed and checked ok.Complete.	1271113
8235	#####	1183420	Consumables	1271113
8235	#####	1182915	**SEND EMAIL TO PLANIN Planning team reduce volume	1270533
8235	#####	1182672	Ops Entered - Fault - Elec an Checked no warning light on dash.	1270332
8235	#####	1182672	Consumables	1270332
8235	4/3/2024	1178629	Checked by Rene seal fixed by him.	1269137
8235	4/1/2024	1178629	PTI Tablet Entered -the air p Checked found out rear middle tank drain plug keep on leaking Check for parts no available order parts. Temporary fix fit plug to seal. Test ok.	1269137
8235	#####	1177445	CARRY OUT A SERVICE AS PER CHECK LIST Completed checklist as per work order. Tensioned Wheelnuts to OEM specs with Kumar. washed down engine and rear door due to previous mess	1267366
8235	#####	1177445	Assisting	1267366
8235	#####	1177445	Consumables	1267366
8235	#####	1177445	Consumables	1267366
8235	#####	1177445	Consumables	1267366
8235	#####	1176320	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE	1266625
8235	#####	1176320	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401	1266625
8235	#####	1176320	O-RING KIT SMALL VOSS A0309971748	1266625
8235	#####	1176320	O-RING KIT LARGE VOSS A6739970145	1266625
8235	#####	1176320	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list	1266625
8235	#####	1176320	AIR DRYER ASSY MERC 0500LE A0004302915	1266625
8235	3/6/2024	1174861	PASS	1265327
8235	#####	1172569	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	1263461
8235	#####	1172369	VEHICLE SAFETY INSPECTION Carried out safety inspection as per check list. Tension all wheel nuts with Zubr.	1263461
8235	#####	1172369	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1263461
8235	#####	1172196	Driver Tablet Entered -Air System - Air_Leak losing air pres	1263461
8235	#####	1172196	O-RING KIT LARGE VOSS A6739970145	1263461
8235	#####	1172196	VALVE MANUAL DRAIN 22MM VOLVO B7RL E 49G7901	1263461
8235	#####	1171382	PERFORM CAMPAIGN 01/2/ complete	1262881
8235	#####	1170260	Drv entered - Body Front_D_ adjusted front door.	1262136
8235	#####	1170261	Drv entered - Body Drivers \ Defect entered twice.	1262136
8235	#####	1170256	Mechanic entered - Body Or Removed and replace seatbelt buckle.	1262136
8235	#####	1170256	BUCKLE SEAT BELT TWIN WIRE GREY SOB2123GY 340446	1262136
8235	#####	1170256	Consumables	1262136
8235	#####	1170260	Consumables	1262136
8235	#####	1170261	Consumables	1262136
8235	1/4/2024	1161230	PERFORM CAMPAIGN 10/2: COMPLETED	1254546
8235	1/2/2024	1160759	Ops Entered - Fault - Body F Checked found out front right hand door lock stucked to open. Turn door lock close and operate ok. Bus can be use.	1254928
8235	#####	1159910	Service VEHICLE SAFETY INSPECTION Complete	1254928
8235	#####	1159910	Service VEHICLE SAFETY INSPECTION Complete	1254928
8235	#####	1159910	Service TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1254928
8235	#####	1153526	RUBBER W/ARCH EXTRUSIO	1254552
8235	#####	1153526	WHEEL ARCH RUBBER 2.5M PER WHEEL	1254552
8235	#####	1157675	Workshop Tablet Entered -v Clean rariater checked ok.	1252879
8235	#####	1157674	Workshop Tablet Entered -E Retight L/H mirror.	1252879
8235	#####	1157005	ALTERNATOR 24V 140AMP MERC 0500LE VOLVO B12B	1252879
8235	#####	1157005	BELT MICRO V SERPENT BELT 6 RIB 1308mm LNG	1252879
8235	#####	1157005	change the faulty alternator repair the cable and connections change the alternator belt	1252879
8235	#####	1157005	Fault#:39003 - Ops Entered Attended breakdown found the battery light was on hence door brakes locked on and the bus unable to move turned off the RPD bus can move again driven back to depot to have it's alternator looked out.	1252879
8235	#####	1155009	Service Eastcoast completed bus accident #5539 WO# 1153526	1252879
8235	#####	1153526	REFLECTOR AMBER HELLA 94 X 44MM	1252879
8235	#####	1153526	RUBBER W/ARCH EXTRUSION (040021)	1252879
8235	#####	1153526	LEVER LATCH ADJ FLUSH	1252879

8235	#####	1153526	REFLECTOR RED 94MM X 4MM NR84052BL		1252879
8235	#####	1153526			1252879
8235	#####	1153526	assembly parts and fitted wheel arch ruber and brush		1252879
8235	#####	1153526	BRUSH WHEELARCH 75mm 2.5M PER WHEEL		1252879
8235	#####	1153526	supply & install pvt decal	Creditor #EA-TRA013 TRANSICAL P/O #EA354854 Receiving #:376026 Date :2023-12-20	1254552
8235	#####	1153526	CATCH CLAW PLASMA ENGINE HATCH DOOR 2132-001-2		1252879
8235	#####	1153526		Fit osr wheel arch and plastic insert. Fit 2x panel claws. Removed 1x catch.	1252879
8235	#####	1153526		perp fine fill perp maskup and paint	1252879
8235	#####	1153526	SHEET ALUMIN 2400x1200x2mm		1252879
8235	#####	1153526	SHEET ALUM 5050 240cm x120cm x 3mm		1252879
8235	#####	1153526	PAINT SPRAYCAN BLACK MATT 400ml		1252879
8235	#####	1153526		Completed wheelarch panel fab inc etch black on rear of panel.	1252879
8235	#####	1153526		unmasked the bus and moved bus to body shop area c/o	1252879
8235	#####	1153526	Service - 3rd Accident	Time correction	1252879
8235	#####	1153526		Completed toggle panel fabrication x3 inc stiffeners cutting fuel hose bolt holes. Prep & etch primed rear of toggle panels. Removed damaged osr w/arch panel and began fabrication.	1252879
8235	#####	1153526		clean glue from decals perp o/s for paint fine fill	1252879
8235	#####	1153526	Service - 3rd Accident	Did not clock off	1252879
8235	#####	1153526	Service - 3rd Accident	time correction	1252879
8235	#####	1153526	Service - 3rd Accident	Did not clock off	1252879
8235	#####	1155009	Only booking for east coast		1252879
8235	#####	1155009	Only booking for east coast	Bus send to east coast for accident repair	1252879
8235	#####	1155009	Consumables		1252879
8235	#####	1153526		strip o/s and remove decals	1252879
8235	#####	1153526		Moved vehicles for bodyshop and paintshop. Assisted Abi with bumper fit-up (Yutong bus). Removed and fabricated 3x toggle panels.	1252879
8235	#####	1153526	ERAZER WHEEL VINYL ZAPPER		1252879
8235	#####	1153526	ERAZER WHEEL VINYL ZAPPER		1252879
8235	#####	1154064	Service	CARRY OUT A SERVICE AS PER CHECK LIST	1251913
8235	#####	1154064		Assisted	1251913
8235	#####	1154064	Consumables		1251913
8235	#####	1154064	Consumables		1251913
8235	#####	1154064	Consumables		1251913
8235	#####	1153526	*** DECALS ON ORDER FROM TRANSICAL. NEED TO REBOOK BUS ***		1251399
8235	#####	1152941	Driver Tablet Entered -Elec ;	Work shop cannot access to consat volume and send email to Opp 18/11/2023.	1250821
8235	#####	1152941	Consumables		1250821
8235	#####	1152928	Driver Tablet Entered -CCTV	Rectify fault check found out gss box off not secured causing for noise. Secured.	1250821
8235	#####	1149169		Retensioned all rear wheel nuts.	1246518
8235	#####	1149169		Assisted	1246518
8235	#####	1149032		VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts by jimmy and feda.	1246518
8235	#####	1149032		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1246518
8235	#####	1149032		completed safety inspection as per check list with zubair secured loose panels and added top up before you travel decal on front stanchion pole	1246518
8235	#####	1149114	Consumables		1246518
8235	#####	1149114	Mechanic entered - Elec anc	removed reverse light made new connector for new light drilled bumper bar to fit new light with bolt and nut and tested light all working	1246518
8235	#####	1149056	Consumables		1246518
8235	#####	1149057	Consumables		1246518
8235	#####	1149112	Consumables		1246518
8235	#####	1149056	Mechanic entered - Body OI	tighten loose hex nut bolt now seat can stay up	1246518
8235	#####	1149057	Mechanic entered - Body OI	tighten loose screws	1246518
8235	#####	1149057	LAMP LED REVERSE RECTANGULAR		1246518
8235	#####	1149112	Mechanic entered - Body OI	tighten loose screw now secured	1246518
8235	#####	1149077	Mechanic entered - Air Syst;	carried out removing and replacing rear brake boosters and carried out checking for leaks no leaks feda and jimmy tensioned all rear wheel nuts.	1246518
8235	#####	1149077		assist Zubair to change both rear brake boosters and checked ok. put tyres abck and tension all wheel nuts with Jimmy. Complete.	1246518
8235	#####	1149077	BOOSTER BRAKE LHR MERC		1246518
8235	#####	1149077	BOOSTER BRAKE RHR MERC BENZ 0500LE E6 20/24		1246518
8235	#####	1148681	Consumables		1246230
8235	#####	1148681	PTI Tablet Entered -Elec and	Fitted second hand LED tail/stop light.	1246230
8235	#####	1132393	PIN SIDE BIN LOCK DRIVERS PART NOT IN STOCK		1244411
8235	#####	1143701	SOLENOID STARTER (SLAVE) 24V RELAY MERC 0500LE		1242376
8235	#####	1143701		assist Csaba to checked the bus and checked for fuses and relays and find out starter motor relay/Solenoid is faulty re-placed and checked working ok. put number plate back together. Complete.	1242376
8235	#####	1143701		checked the system fuses relays MR unit and change the starter motor solenoid	1242376
8235	#####	1143701	PTI Tablet Entered -Engine -	Engine could'nt start. Towed the bus from fuel bay. (require further investigation.)	1242088
8235	#####	1143701	PTI Tablet Entered -Engine -	Assisting	1242088
8235	#####	1143197	Warning Lights Doors/Loud	check and fixed rear door ramp and fixed air leak from next to air drayer assy road tested bus ok.	1241843
8235	#####	1138802	CARRYOUT ANNUAL INSPEC	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G350289 Receiving #:369156 Date :2023-09-12	1239132
8235	9/6/2023	1138802		VEHICLE SAFETY INSPECTION completed	1237925
8235	9/6/2023	1138802		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1237925
8235	9/6/2023	1138802	Service	ANNUAL SAFETY INSPECTION SERIAL # RSI 057611 PASS 6/9/2023 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1237925
8235	9/6/2023	1138802		Assisting	1237925
8235	9/6/2023	1131653	STONEGUARD BLACK AEROSOL 500ML		1237925
8235	9/4/2023	1138192	Carry out final inspection fo	completed also changed torn PS- seat	1237924
8235	9/4/2023	1138192	SEAT CUSH SINGLE CEN CVR CI		1237924
8235	9/4/2023	1138192		final inspection done.	1237924
8235	9/4/2023	1138192		Assisted and steam cleaned Engine bay and under carriage.	1237924
8235	#####	1136376		CARRY OUT A/JC - A SERVICE AS PER CHECK LIST service as per list	1237856
8235	#####	1134913	Consumables		1237856
8235	#####	1134913	Mechanic entered - Body OI	Repair completed by east coast	1237856
8235	#####	1135019	Consumables		1237856
8235	#####	1135019	SAUSAGE BLACK SIKA		1237856
8235	#####	1135019	Service	Assisted Abi	1237856
8235	#####	1135019		resealed floor tile and sealed inside wheelarch panel on exterior fit vinyl and sealed	1237856
8235	#####	1135019		refit angle rear seat and screw locks and rivert angles and cut 50 x 50 angles and drill and bolts	1237856
8235	#####	1135019		removed old side wall rust treated made new wall welded and sealed	1237856
8235	#####	1135019	Secure floor vinyl. Secure re	remove rear seats and locks and angle and remove vinyl and drill all 3\16 riverts and drill and put mono riverts and cut new vinyl and glue	1237856
8235	#####	1135019	removed bubbled vinyl and began rust repair		1237856
8235	#####	1134913	Mechanic entered - Body OI	Bus at east coast and repairing	1237856
8235	#####	1134913	Mechanic entered - Body OI	As above	1237856
8235	#####	1134913	Mechanic entered - Body OI	Repair completed by east coast	1237856
8235	#####	1136957	Service	CARRY OUT FIRE EXTINGUISHER TEST & TAG Completedby ATS	1237238

8235	#####	1136957	Assisting	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	CARRY OUT C SERVICE AS PER CHECK LIST Complete	1237238
8235	#####	1134443	completed c service as per check list with neven	1237238
8235	#####	1134443	BREATHER OIL MIST MERC BENZ 0500LE A5410100163	1237238
8235	#####	1134443	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151	1237238
8235	#####	1134443	FILTER FUEL/WATER SEPARATOR MERC 0500LE >E5 A0004771302	1237238
8235	#####	1134443	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709	1237238
8235	#####	1134443	FILTER P/STRG MERC SCANIA VOLVO 0153468 349619	1237238
8235	#####	1134443	OIL SAMPLE TEST KIT	1237238
8235	#####	1134443	OIL FAN DRIVE MERC BENZ 0500LE E3 to E5	1237238
8235	#####	1134443	FILTER AIR MERC BENZ 0500LE E3 - E5 A0040941704	1237238
8235	#####	1134443	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	CARRY OUT B SERVICE AS PER CHECK LIST	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	Consumables	1237238
8235	#####	1134443	CARRY OUT A SERVICE AS PER CHECK LIST	1237238
8235	#####	1134154	PERFORM CAMPAIGN 05/2: Done by Refuelers	1237005
8235	#####	1132393	Fault#:38824 - Ops Entered Attended breakdown drivers door had gone passed the lock latch and was jammed up unable to un-jum it removed the hinges holding the door on and removed the door that wya. Bus went back out on its run without drivers door when it returns back to depot we can repair the latch and door properly.	1235521
8235	#####	1132393	PIN SIDE BIN LOCK (UES 600-0487)	1235521
8235	#####	1132393	CHECK STRAP DRIVERS DOOR HINGE	1235521
8235	#####	1132393	Refitted realign drivers door and replaced side bin lock.	1235521
8235	#####	1132517	Consumables	1235521
8235	#####	1132517	Ops Entered - Fault - Body F Cleaned and lub door guide/roller.	1235521
8235	8/8/2023	1131567	Assisted Matt. Removed sway bar link on front off side and replaced with new	1235208
8235	8/8/2023	1131567	Removed and replaced the N/S/F sway bar link with Ben road tested no more knocking	1235208
8235	8/8/2023	1131838	Consumables	1235208
8235	8/8/2023	1131838	Mechanic entered - Body OI Finished off job from yesterday with fresh coat of gray paint.	1235208
8235	8/7/2023	1131525	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST CCTV service completed with Ben.	1235208
8235	8/7/2023	1131525	PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre RSI inspection as per checklist with Ben reported / repaired any found defects.	1235208
8235	8/7/2023	1131525	Assisted Matt. completed checklist as per work order. removed some seat bases and matched colours. hoisted up bus and removed rust and repayed.	1235208
8235	8/7/2023	1131567	Mechanic entered - Suspens ***Parts ordered with Lee 7/8/2023***	1235208
8235	8/7/2023	1131567	LINK SWAY BAR OSF MERC I Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G348441 Receiving #:366473 Date :2023-08-07	1235208
8235	8/7/2023	1131584	Mechanic entered - Engine I Steam cleaned engine body axles and chassis for RSI	1235208
8235	8/7/2023	1131592	Consumables	1235208
8235	8/7/2023	1131653	Consumables	1237925
8235	8/7/2023	1131654	Consumables	1235208
8235	8/7/2023	1131592	DECAL EMERGENCY EXIT PUSH BUTTON UNDER PANEL	1235208
8235	8/7/2023	1131653	STONEGUARD BLACK AEROSOL 500ML	1235208
8235	8/7/2023	1131592	Mechanic entered - Body OI Fit sticker from Eastcoast Lee to fix up stock.	1235208
8235	8/7/2023	1131654	Mechanic entered - Body OI Created an aluminium plate for the rear door plastic bolted on with lock nuts large body washes and bolts. Sanded plate back and painted dark gray. Panel is holding much better now.	1235208
8235	8/7/2023	1131653	Mechanic entered - Body OI Assisted Ben checked over work looks good.	1235208
8235	8/7/2023	1131653	Scraped and cleaned down rust and used rust eater and then used underbody spray to reseal	1234236
8235	#####	1130085	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Ben	1234236
8235	#####	1130085	Assisted Matt. Completed checklist as per work order. Tensioned all wheelnuts to OEM specs with Matt.	1234236
8235	#####	1130085	VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist with Ben.	1234236
8235	#####	1129948	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safety inspection as per checklist	1234236
8235	#####	1128670	Drv entered - Body Mirrors I replaced cracked (nsf) exterior mirror.	1232985
8235	#####	1128670	MIRROR L/H 380MM SHORT(UES1411E)	1232985
8235	#####	1128670	Consumables	1232985
8235	#####	1128458	BELT MICRO V SERPENT BELT 6 RIB 1308mm LNG	1232985
8235	#####	1128458	Alternator not charging check and replaced alternator belt check all belt bus serviceble.	1232985
8235	#####	1128458	Consumables	1232985
8235	#####	1127418	Retensioned ALL rear wheel nuts.	1232237
8235	#####	1127418	Assisted	1232237
8235	#####	1126992	Removed and replace N/S/R brake pads.	1232178
8235	#####	1126992	BRAKE PADS FT / RR MERC 0500LE E6 49G7501-4550	1232178
8235	#####	1126992	Fitted new rear brake pads passed brake test road tested OK. No warning lights OK.	1232178
8235	#####	1126992	Driver Tablet Entered -Braks carried out checking bus bring over pit check brakges visually rear brakes low.	1232178
8235	7/7/2023	1125056	PERFORM CAMPAIGN 02/2: Completed	1230467
8235	7/5/2023	1124214	PERFORM CAMPAIGN 13/2: completed by Volgren	1230129
8235	7/4/2023	1124054	Elec and Light Myki 4G ante completed by AMTEK.	1230129
8235	7/4/2023	1124054	Elec and Light Myki 4G antenna install	1230129
8235	7/4/2023	1124054	Consumables	1230129
8235	#####	1122005	Mechanic entered - Wheels Checked for damaged or puncture All tyre ok no problem. Air pressure ok.	1228193
8235	#####	1122005	Consumables	1228193
8235	#####	1120477	Modify pipe work to suit new water valve install water valve tested ok	1227974
8235	#####	1120477	Workshop Tablet Entered -f as above	1227974
8235	#####	1120477	Workshop Tablet Entered -f as above	1227974
8235	#####	1120477	Driver Tablet Entered -A/C f as above	1227974
8235	#####	1120477	Drv entered - A/C Heating V as above	1227974
8235	#####	1120476	3/4 H/TAIL X 3/4 BSPT BARB	1227974
8235	#####	1120476	Modify pipe work to suit water valve replace water valve tested ok	1227974
8235	#####	1121752	Drv entered - Warning Light Checked brake pads ok. (need bild up air pressur befoe release park brake)	1227252
8235	#####	1120477	BOOST PUMP A/C COACH 90LTR 24V CM90P7	1227464
8235	#####	1120477	VALVE WATER AC THERMOI Creditor #:GB-QTX001 QTK GROUP P/O #:G345053 Receiving #:362781 Date :2023-06-16	1227252
8235	#####	1120477	Workshop Tablet Entered -f Remove and check strainer remove and replaced boost pump (open circuit) check system for alarms no lodged alarms in system water valve needs to be replaced parts ordered carry over	1227252
8235	#####	1120476	Drv entered - A/C Heating N Replaced water valve modify pipe work to match new water valve	1227252
8235	#####	1117491	MOUNT EXHAUST MERC 0500LE(A0004910285)	1226866
8235	6/9/2023	1117491	Mechanic entered - Engine I Ordered parts from 29/5/23 Removed muffler flexible pipe and replace exhaust brake air cylinder. Putted back flexible pipe and replace a muffler mount bush for front.	1226866
8235	6/9/2023	1119825	Ops Entered - Fault - Elec an HLC2470 Replaced globe.	1226866

8235	6/9/2023	1119826	Mechanic entered - Elec anc Defect entered twice.	1226866
8235	6/9/2023	1119825	Consumables	1226866
8235	6/9/2023	1119826	Consumables	1226866
8235	#####	1117783	Assisted.	1225088
8235	#####	1117783	Tensioned wheel nuts position 125 and 6 with Nick.	1225088
8235	#####	1117491	SOCKET EXH BRAKE CYL MEI Creditor #-GB-MUL001 MULTISPARES LTD P/O #:G344092 Receiving #:361662 Date :2023-05-30	1225088
8235	#####	1117491	CYLINDER EXHAUST BRAKE Creditor #-GB-MUL001 MULTISPARES LTD P/O #:G344092 Receiving #:361662 Date :2023-05-30	1225088
8235	#####	1117467	VEHICLE SAFETY INSPECTION Completed safety service.	1224967
8235	#####	1117467	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1224967
8235	#####	1117490	Mechanic entered - Wheels Assisted.	1224967
8235	#####	1117490	TYRE 295/80R22.5 RECAP	1224967
8235	#####	1117490	TYRE 295/80R22.5 NEW	1224967
8235	#####	1117490	Mechanic entered - Wheels Removed and replace 2 new tyres for front and keep P1 tyre for runout. Replaced 2 recap tyres for P5+6 and tension wheel nuts. Need bookback wheel nuts retension.	1224967
8235	#####	1117490	Consumables	1224967
8235	#####	1117491	Mechanic entered - Engine f Ordered part.	1224967
8235	#####	1117492	Mechanic entered - Body Pa Removed and replace 2 passenger seats cushions.	1224967
8235	#####	1117492	SEAT CUSH SINGLE CEN CVR CI	1224967
8235	#####	1117492	Consumables	1224967
8235	#####	1111087	FILTER DRYER AIR COND THERMO KING 2750300 DML305R	1223697
8235	#####	1111087	Finish off B service Replaced drier and compressor oil check system for refrigerant leaks tested ok	1223697
8235	#####	1111087	FAN CONDENSOR A/C CITI-RT	1223697
8235	#####	1111087	Service	1223697
8235	#####	1111087	O-RING VIBRASORBER DISCHARGE SCREW TYPE	1223172
8235	#####	1111087	AIR CON REFRIDGERANT	1223172
8235	#####	1111087	VIBRASORBER DISCHARGE SCREW TYPE (33-1777 O RING)	1223172
8235	#####	1111087	NITROGEN DRY E SIZE	1223172
8235	#####	1114898	. Assisted and Re-tensioned wheel nuts with indica.	1223172
8235	#####	1114898	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A service as per check list.	1223172
8235	#####	1114898	Consumables	1223172
8235	#####	1114898	Consumables	1223172
8235	#####	1114898	Consumables	1223172
8235	#####	1114898	Consumables	1223172
8235	5/4/2023	1111087	ADAPTOR A/C SUCTION #2C Creditor #-GB-QTK001 QTK GROUP P/O #:G342443 Receiving #:360455 Date :2023-05-11	1222748
8235	5/4/2023	1111087	ADAPTOR A/C #16 R407C SC Creditor #-GB-QTK001 QTK GROUP P/O #:G342443 Receiving #:360455 Date :2023-05-11	1222748
8235	5/4/2023	1111087	ADAPTOR A/C DISCHARGE F Creditor #-GB-QTK001 QTK GROUP P/O #:G342443 Receiving #:360455 Date :2023-05-11	1222748
8235	5/3/2023	1111087	Fitted hoses found unit had lost refrigerant check unit and compressor area for dry trace no dye trace was found due to excess oil from engine presse tested again with nitrogen with trace gas in it found discharge vibra sorber pipe has ahair line crack on the under side of pipe due to vibrasorber beeing too rigidit will have to	1221767
8235	#####	1111087	Workshop Tablet Entered -# Tested found unit had lost its charge pressure tested at 300psi for 1 hour unit lost no pressure released pressure and did a vac test unheld ok vac system and charge with trace dye will check a later date	1221115
8235	#####	1111087	Workshop Tablet Entered -# Remove and modify pipe work to suit screw on hoses fitted new discharge hose pressure test at 300 psi vac and charge system .	1221115
8235	#####	1111158	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed	1221115
8235	#####	1111158	DRYER AIR ASSY MERC 0500LE(A0004302915)	1221115
8235	#####	1111158	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)	1221115
8235	#####	1111158	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE	1221115
8235	#####	1111158	Assisted.	1221115
8235	#####	1105787	Retensioned wheel nuts pos 1 with Ben.	1216097
8235	#####	1105787	Service	1216097
8235	#####	1105455	VEHICLE SAFETY INSPECTION Completed check list.	1216097
8235	#####	1105455	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ben.	1216097
8235	#####	1105455	Assisted Rene. Completed checklist as per work order. Tensioned all wheelnuts to OEM specs with Rene.	1216097
8235	#####	1105474	Mechanic entered - Wheels Removed tyre position 1 replaced with a runout of new tyre that matched the size of position 2. W/Nuts Retension with Rene.	1216097
8235	#####	1105474	Consumables	1216097
8235	#####	1105473	Mechanic entered - Air Syst. Removed modulator valve to get access to removed fitting replace o ring seal and test after fit. Ok no leak.	1216097
8235	#####	1105473	O-RING KIT LARGE VOSS(A6739970145)	1216097
8235	#####	1105178	Workshop Tablet Entered -- From day one two way was right hand side and we cannot move to left hand side due to wiring	1216097
8235	#####	1105178	Consumables	1216097
8235	#####	1104160	Accident#54706 REAR-Scra No damage only need cut and polish job completed.	1215426
8235	#####	1099918	Assisting	1212038
8235	#####	1099918	CARRY OUT FIRE EXTINGUISHER TEST & TAG Competed by ATS	1212038
8235	#####	1099861	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Service Complete as per Check list. Complete.	1212038
8235	#####	1097192	Service	1210120
8235	#####	1097192	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST carried out service as per check list	1209983
8235	#####	1097192	FILTER ZF ECOMAT GEARBOX 1139-298-038 1193281	1209983
8235	#####	1097192	OIL ZF GEARBOX SYNTHETIC ECOFLUID A PLUS	1209983
8235	2/7/2023	1095269	Consumables	1208236
8235	2/7/2023	1095269	Consumables	1208236
8235	2/7/2023	1095269	Consumables	1208236
8235	2/7/2023	1095269	Consumables	1208236
8235	2/2/2023	1089889	NITROGEN DRY E SIZE	1207596
8235	2/2/2023	1094403	REF NEGATIVE STOCK	1207596
8235	2/2/2023	1094403	VEHICLE SAFETY INSPECTION Completed	1207596
8235	2/2/2023	1094403	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Satheesh	1207596
8235	2/2/2023	1094403		1207596
8235	#####	1093307	LINK ROD ANGLE DRIVE - STRG BOX MERC BENZ 0500LE 50L2288	1207076
8235	#####	1093307	Workshop Tablet Entered -S assisted stuart with holding steering wheel straight	1207076
8235	#####	1093307	Workshop Tablet Entered -S fitted replacment spline shaft between angle drive and power steering box. tested steering all ok	1207076
8235	#####	1093307	Workshop Tablet Entered -S Greased king pin on both sides and drive tested.Found faulty universal joint between steering angle drive and steering gear box.removed and order parts.Carry over.	1207076
8235	#####	1093307	Workshop Tablet Entered -S assisted	1207076
8235	#####	1092977	Driver Tablet Entered -Steer road tested with stuart checked king pins and front bearings all good found no faults	1206954
8235	#####	1092977	Driver Tablet Entered -Steer test drive checked wheel bearings kingpins and balljoints. checked steering wheel for condition. no fault found	1206954
8235	#####	1090463	Drv entered - A/C Heating N Job done under wo#1089889.	1204270
8235	1/9/2023	1089889	NITROGEN DRY E SIZE	1203910
8235	1/9/2023	1089889	AIR CON REFRIDGERANT	1203910
8235	1/9/2023	1089889	A/C Heating Air Conditionir Locate and repair crack in refrigerant pipe pressure tested vac and charge system commission tested ok	1203910
8235	#####	1088757	Consumables	1203008
8235	#####	1088757	Mechanic entered - Elec anc Replaced globe.	1203008
8235	#####	1088757	GLOBE 24V 70W H1	1203008
8235	#####	1087464	Retensioned wheel nuts pos 3 and 4.	1201789
8235	#####	1087464	Assisted Re-tensioned with nick.	1201789
8235	#####	1087250	Consumables	1201500

8235	9/6/2022	1067936	Consumables		1189507
8235	9/2/2022	1066760	PARTS ORDERED - Suspensic replaced both lower Torque rod & bolts.		1189484
8235	9/2/2022	1066760	PARTS ORDERED - Suspensic replaced both lower Torque rod & bolts.		1189484
8235	#####	1066760	BOLT RR LWR TORQUE ROD Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G328017 Receiving #:344760 Date :2022-09-02		1189484
8235	#####	1066760	BOLT RR LWR TORQUE ROD Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G328017 Receiving #:344760 Date :2022-09-02		1189484
8235	#####	1066760	NUT RR LWR TORQUE ROD Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G328017 Receiving #:344760 Date :2022-09-02		1189484
8235	#####	1066741	PARTS ORDERED - Wipers ai repaced wiper arm.		1189032
8235	#####	1066741	WIPER ARM TRICO CONVEN Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G328035 Receiving #:344741 Date :2022-09-02		1189484
8235	#####	1066760	PARTS ORDERED - Suspensic ordered parts		1189032
8235	#####	1066760	PARTS ORDERED - Suspensic parts on order.		1189032
8235	#####	1066760	TORQUE ROD RR LWR MERI Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G328016 Receiving #:344572 Date :2022-08-31		1189322
8235	#####	1066673	Mechanic entered - Fluid Leaks Other Transmission coolant ho		1189032
8235	#####	1066673	Mechanic entered - Fluid Le Drained coolant to replaced coolant hose. Filled up coolant drive tested and checked coolant leaks and level ok.		1189032
8235	#####	1066673	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G		1189032
8235	#####	1066591	Consumables		1189032
8235	#####	1066599	Consumables		1189032
8235	#####	1066591	Mechanic entered - Elec anc replaced both head light insertes and adjusted lights		1189032
8235	#####	1066591	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204		1189032
8235	#####	1066599	Mechanic entered - Elec anc replaced both corner indecator light assy		1189032
8235	#####	1066599	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1189032
8235	#####	1066599	Mechanic entered - Elec and Light Exterior Lights Front n/s		1189032
8235	#####	1066647	Consumables		1189032
8235	#####	1066648	Consumables		1189032
8235	#####	1066658	Consumables		1189032
8235	#####	1066766	Consumables		1189032
8235	#####	1066668	Consumables		1189032
8235	#####	1066647	Mechanic entered - Body Oi removed and replaced both front wheel arch brushes with new ones		1189032
8235	#####	1066647	WHEEL ARCH BRUSH 12065		1189032
8235	#####	1066648	Mechanic entered - Body Oi removed old cover and replaced wit new one		1189032
8235	#####	1066648	COVER EMERGENCY EXIT BUTTON 16906		1189032
8235	#####	1066766	Mechanic entered - Body Oi Completed		1189032
8235	#####	1066668	Mechanic entered - Body Oi Repair done by east coast w/o 1066459		1189032
8235	#####	1066658	Mechanic entered - Body Oi checked all hand straps for damage no damage what so ever but tighten all hand strap bolts due to being loose		1189032
8235	#####	1066527	PRE ANNUAL SAFETY INSPECTION CHECK Completed		1189032
8235	#####	1066527	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1189032
8235	#####	1066346	Mechanic entered - A/C Hea Secure pipe work across engine bay		1189032
8235	#####	1066459	Accident#53951-nearside m Bus at east coast and repairing		1189032
8235	#####	1066459	Accident#53951-nearside m completed by ECB.		1189032
8235	#####	1066309	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list		1189032
8235	8/4/2022	1060984	VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts with jimmy carried out removing and replacing a clamp off the gearbox cooler pipe hose clamp unable to tighten just spinning so replacing with new one checked for leaks no leaks carried out securing all panels and can		1189436
8235	8/4/2022	1060984	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1189436
8235	#####	1060511	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection complete.		1184562
8235	#####	1059713	Consumables		1184306
8235	#####	1059713	Driver compartment door is jammed		1184306
8235	#####	1059713	PADDLE LATCH DRIVER COMPARTMENT DOOR 430047		1184306
8235	#####	1059713	Driver compartment door is Replaced door mechanism.		1184306
8235	#####	1059713	PIN SIDE BIN LOCK (UES 600-0487)		1184306
8235	#####	1030357	CARRY OUT FIRE EXTINGUISHER TEST & TAG 21/2/22 changed to 21/7/22 to post wo		1183112
8235	#####	1057550	Front door not closing Adjust sensitive edge and checked ok.		1182320
8235	#####	1057550	Consumables		1182320
8235	7/8/2022	1055859	Drv entered - Body Window fixed faulty driver window lock		1181093
8235	7/8/2022	1055859	Consumables		1181093
8235	7/8/2022	1056166	Side glass cut to size LAM(2i Creditor #:GB-OBRO10 O'BRIENS GLASS INDUSTRIES P/O #:G324632 Receiving #:340933 Date :2022-07-11		1181319
8235	7/8/2022	1056166	Accident#53773-nearside- r job completed under w/o;1055859.		1181093
8235	7/7/2022	1055859	Drv entered - Body Window Replaced passenger side broken window by Obrien		1181093
8235	#####	1054037	Ops Entered - Fault - Body F Checked front door found sensitive edge is too sensitive and one door leaf closing too quick. Adjusted and checked ok.		1178985
8235	#####	1053198	Near side front indicator is Replaced N/S/F lower indicator globe.		1178448
8235	#####	1053198	Consumables		1178448
8235	6/9/2022	1051148	All Vehicle track need bus t Completed		1176924
8235	6/3/2022	1049358	Mechanic entered - Engine f refitted panels. road tested ok.		1176113
8235	6/3/2022	1049358	Mechanic entered - Engine f fitted new fan angle drive new radiator with old intercooler. topped up coolant		1176113
8235	6/3/2022	1048956	CLEAN AIR SYSTEM PIPES Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G322521 Receiving #:338618 Date :2022-06-03		1176113
8235	6/2/2022	1049358	BUSH RUBBER SLEEVE RADIATOR 0500LE(A0009872143)		1176113
8235	6/2/2022	1049358	HOSE RADIATOR LOWER MERC BENZ 0500LE		1176113
8235	6/2/2022	1049358	Mechanic entered - Engine f fitted new fan drive unit. fitted new radiator and old intercooler.		1176113
8235	6/2/2022	1049358	Mechanic entered - Engine f assisted		1176113
8235	6/2/2022	1049358	FAN ANGLE DRIVE ASSY MEI Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G322531 Receiving #:338459 Date :2022-06-02		1176113
8235	6/1/2022	1049358	Mechanic entered - Engine f waiting for angle fan drive C/O assembled the radiator		1176113
8235	6/1/2022	1049358	Mechanic entered - Engine f removed radiator and intercooler.		1176113
8235	6/1/2022	1049358	RADIATOR MERC BENZ 050 Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G322531 Receiving #:338368 Date :2022-06-01		1176113
8235	6/1/2022	1049358	RADIATOR TOP MOUNT ME Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G322531 Receiving #:338369 Date :2022-06-01		1176113
8235	#####	1049030	Mechanic entered - Engine f new drive shaft fitted.		1176113
8235	#####	1049031	Mechanic entered - Engine f new hose fitted.		1176113
8235	#####	1049358	Mechanic entered - Engine Other coolant leak from engine rad		1176113
8235	#####	1049358	Mechanic entered - Engine Other coolant leak from engine rad		1176113
8235	#####	1049034	Mechanic entered - Elec anc new light unit fitted.		1176113
8235	#####	1049024	Consumables		1176113
8235	#####	1049034	Consumables		1176113
8235	#####	1049024	Mechanic entered - Elec anc completed		1176113
8235	#####	1049353	Mechanic entered - Air Syst: fitted new tank drain valve.		1176113
8235	#####	1049353	VALVE MANUAL DRAIN 22MM VOLVO B7RL 49G7901		1176113
8235	#####	1048956	HOSE COMP - UNLOADER MERC BENZ 0500 A0014292135 A0014292735		1176113
8235	#####	1048956	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)		1176113
8235	#####	1048956	DRYER AIR ASSY MERC 0500LE(A0004302915)		1176113
8235	#####	1048956	COUPLING AIR HOSE - COMP MERC BENZ 0500LE A0089970889		1176113
8235	#####	1048956	completed.		1176113
8235	#####	1048956	completed as per check list		1176113

8235	#####	1048956	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE	1176113
8235	#####	1048955	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1175898
8235	#####	1048955	VEHICLE SAFETY INSPECTION completed.	1175898
8235	#####	1048955	assisted	1176113
8235	#####	1049029	Mechanic entered - Engine (secured hoses and clips.	1175898
8235	#####	1049031	Mechanic entered - Engine (new cooler hose fitted.	1175898
8235	#####	1049029	Mechanic entered - Engine (checked ok	1175898
8235	#####	1049033	Mechanic entered - Engine (checked ok	1175898
8235	#####	1049030	Mechanic entered - Engine Other fan drive shaft worn.	1175898
8235	#####	1049031	Mechanic entered - Engine Other coolant leak from trans cool	1175898
8235	#####	1049033	Mechanic entered - Engine (secured hoses.	1175898
8235	#####	1049030	Mechanic entered - Engine (new drive shaft fitted.	1175898
8235	#####	1049031	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G	1175898
8235	#####	1049030	SHAFT FAN DRIVE MERC BEI Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G322386 Receiving #:338203 Date :2022-05-30	1176113
8235	#####	1049024	Mechanic entered - Elec anc Fitted new led lamp checked ok	1175898
8235	#####	1049034	Mechanic entered - Elec and Light Other reverse lights not w	1175898
8235	#####	1049024	LAMP LED REVERSE RECTANGULAR	1175898
8235	#####	1049021	VALVE PARK BRAKE MERC BENZ 0500LE A0034307581	1175898
8235	#####	1049021	Mechanic entered - Air Syst: new park brake valve fitted.	1175898
8235	#####	1049021	Mechanic entered - Air Syst: assisted	1175898
8235	#####	1048956	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1175898
8235	#####	1049066	Consumables	1176113
8235	#####	1049066	Consumables	1176113
8235	#####	1049066	Consumables	1176113
8235	#####	1049066	Consumables	1176113
8235	#####	1049066	CARRY OUT A SERVICE AS PER CHECK LIST completed.	1175898
8235	#####	1049066	completed	1176113
8235	#####	1048389	Consumables	1175423
8235	#####	1048389	Mechanic entered - Elec anc Fitted new low beam bulb and secured wire.	1175423
8235	#####	1048389	GLOBE 24V 70W H1	1175423
8235	5/5/2022	1044285	Mechanic entered - Body OI checked perspex security frame detached from top of cab door - needs re-welding by east coast. repaired by east coast.	1171782
8235	5/5/2022	1044304	REMOVE AND WELD SECUR removed door to remove security screen cleaned old weld area rewelded screen refit screen and door	1171782
8235	5/3/2022	1043963	Ops Entered - Fault - Body F adjusted font door.	1171699
8235	5/3/2022	1043863	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM	1171699
8235	#####	1042262	Tablet Entered - Body - Driv already checked refer w/o. 1042263	1170525
8235	#####	1042263	Tablet Entered - Body - Driv cushioning and seat controls checked - could not fault.	1170525
8235	#####	1042264	Tablet Entered - Body - Driv already checked refer w/o. 1042263.	1170525
8235	#####	1042265	Tablet Entered - Body - Driv already checked refer w/o. 1042263.	1170525
8235	#####	1042266	Tablet Entered - Body - Driv already checked refer w/o. 1042263.	1170525
8235	#####	1042267	Tablet Entered - Body - Driv already checked refer w/o. 1042263.	1170525
8235	#####	1038340	completed checklist	1167354
8235	#####	1038340	VEHICLE SAFETY INSPECTION Completed VSI.	1167354
8235	#####	1038340	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Jess.	1167354
8235	#####	1038344	AIRBAG FRONT/RR MERC 0405 0500LE RR	1167354
8235	#####	1038344	Mechanic entered - Suspens Fitted new airbag.	1167354
8235	#####	1038346	Consumables	1167354
8235	#####	1038346	Mechanic entered - Elec anc fitted new light	1167354
8235	#####	1038346	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)	1167354
8235	#####	1038341	Mechanic entered - Body OI fitted new pedal pad	1167354
8235	#####	1038341	PAD BRAKE PEDAL RUBBER FLAT MERC 500LE(A110291018201)	1167354
8235	#####	1038359	Mechanic entered - Body OI Secured side panels and rear bumper w/ bolts and screws.	1167354
8235	#####	1035298	Ops Entered - Fault - Body F Checked bus front floor operation and safety edges with mark james. all good	1166235
8235	#####	1035298	Ops Entered - Fault - Body F Bus needs to be booked back so that sensitive edge can be calibrated and tested as sika was still wet when it was fitted to bus.	1166235
8235	#####	1035298	Ops Entered - Fault - Body F Received new sensitive edge and rubber. Constructed new sensitive edge with kit supplied. Needed to use sika so waited for drying. Still wasn't dry but needed bus to go on the road so will need it back to calibrate and test.	1166235
8235	#####	1036868	*EMAILED CAROLYNE 20/1C replaced.	1166235
8235	#####	1035298	DOOR RUBBER SENS /EDGE Creditor #:GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:G317938 Receiving #:333489 Date :2022-03-18	1165756
8235	#####	1035298	KIT SENSITIVE EDGE KIT SMI Creditor #:GB-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O #:G317938 Receiving #:333489 Date :2022-03-18	1165756
8235	#####	1035298	SWITCH SENSITIVE EDGE (RED)	1165058
8235	#####	1035298	Ops Entered - Fault - Body F Bus doors weren't closing. Moved bus to workshop with door override switch. When bus was in workshop doors started working and closing. Readjusted sensitive edges because doors were opening automatically after contact with each other. Faulty front leaf sensitive edge. Awaiting parts.	1165058
8235	#####	1035298	Ops Entered - Fault - Body F Check door operation air pressure set to low and sensitive edges needed re adjustment. Front leaf has a faulty sensitive edge but none in stock or available from Volgren. Reset RPD. All doors working correctly. Complete.	1165058
8235	#####	1035298	Ops Entered - Fault - Body F brought bus to the workshop. bus doors were not closing . then checked doors operation air pressure set to low and sensitive edges needs adjustment. front leaf has a faulty sensitive edge but none in stock is available in volgren.	1165058
8235	3/2/2022	1032776	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Inspection Complete.	1163774
8235	3/2/2022	1032776	Complete.	1163774
8235	#####	1030468	No suspension in driver seat seat checked could not fault. manual adjustment only. controls checked - o.k. replaced broken seat belt buckle and missing lumbar buttons.	1161829
8235	#####	1030468	BUCKLE SEAT BELT TWIN WIRE GREY SDB2123GY 340446	1161829
8235	#####	1030468	L/H LOWER SEAT LUMBAR BUTTONS	1161829
8235	#####	1030468	L/H UPPER SEAT LUMBAR BUTTONS	1161829
8235	#####	1030357	Completed by ATS	1161829
8235	#####	1030222	REMOVE OLD 2020 DECAL / REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS STATED IN DOT INSTRUCTIONS	1161829
8235	#####	1029906	Ops Entered - Fault - Cool & A/C cooling OK.	1161715
8235	#####	1029893	CARRY OUT A SERVICE AS PER CHECK LIST Completed A service and tensioned all wheel nuts w/ Ben.	1161715
8235	#####	1029893	Consumables	1161715
8235	#####	1029893	Consumables	1161715
8235	#####	1029893	Consumables	1161715
8235	2/9/2022	1027635	Mechanic entered - ERROR - Checked front doors working fine could not get to fault.	1160223
8235	2/8/2022	1027453	Bumper bar loose tightened loose rear bumper bar bolts.	1160223
8235	2/4/2022	1026716	Mechanic entered - Wheels carried out checking all wheel arch panels for security and if loose or coming out. all secure.	1159820
8235	2/4/2022	1026716	Consumables	1159820
8235	#####	1025071	VEHICLE SAFETY INSPECTION Completed VSI.	1158624
8235	#####	1025071	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Ben.	1158624
8235	#####	1025071	completed safety inspection as per checklist and done minor repairs	1158624
8235	#####	1025085	Mechanic entered - Elec anc Removed and replaced reverse light with LED light	1158624
8235	#####	1025084	Mechanic entered - Elec anc removed and fitted new park light globe ok	1158624
8235	#####	1025085	LAMP LED REVERSE RECTANGULAR	1158624
8235	#####	1025084	Consumables	1158624
8235	#####	1025085	Consumables	1158624
8235	#####	1023325	Driv entered - A/C Heating -1 As below	1157442

8235	9/3/2021	996977	PERFORM CAMPAIGN 17/2: completed.	1140895
8235	#####	996187	Mechanic entered - Elec anc checked all park lights working	1139935
8235	#####	996187	Consumables	1139935
8235	#####	994217	Mechanic entered - Body Oi replaced reflector	1139071
8235	#####	994218	Mechanic entered - Body Oi replaced decal	1139071
8235	#####	994217	Consumables	1139071
8235	#####	994218	Consumables	1139071
8235	#####	991024	DIRECT PURCHASE ACCIDEN Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G304534 Receiving #:320146 Date :2021-08-26	1139108
8235	#####	994214	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1138786
8235	#####	994214	completed checklist	1138786
8235	#####	994214	PRE ANNUAL SAFETY INSPECTION CHECK completed.	1138786
8235	#####	994233	MOUNT EXHAUST RUBBER VOLVO B7RLE 6850149 70305823	1138786
8235	#####	994233	Mechanic entered - Engine t fitted new rubber mount.	1138786
8235	#####	994236	Mechanic entered - Engine t replaced transmission oil cooler coolant hose and clamps clean and road tested with Alan. all good	1138786
8235	#####	994236	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G	1138786
8235	#####	994236	Mechanic entered - Engine t new hose fitted topped up coolant road tested ok.	1138786
8235	#####	994218	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS	1138786
8235	#####	994217	REFLECTOR AMBER HELLA 94x44mm	1138786
8235	#####	994234	Mechanic entered - Body Other secure side panels.	1138786
8235	#####	994242	Mechanic entered - Body Oi fitted new valve.	1138786
8235	#####	994232	Mechanic entered - Body Oi fitted new door switches and adjusted.	1138786
8235	#####	994242	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON	1138786
8235	#####	994217	Mechanic entered - Body Oi replaced reflector	1138786
8235	#####	994218	Mechanic entered - Body Oi replaced decal	1138786
8235	#####	994234	Mechanic entered - Body Oi secured panels	1138786
8235	#####	994239	Mechanic entered - Body Oi new decal fitted.	1138786
8235	#####	994241	Mechanic entered - Body Oi fitted new bolts and secured.	1138786
8235	#####	994237	Mechanic entered - Body Oi secured seat back and changed grab handle	1138786
8235	#####	994232	Mechanic entered - Body Oi replaced 2 sensitive edge diaphragms tested works okay	1138786
8235	#####	994232	SWITCH SENSITIVE EDGE (RED)	1138786
8235	#####	994232	SWITCH SENSITIVE EDGE (RED)	1138786
8235	#####	994238	Mechanic entered - Body Oi new reflector fitted.	1138786
8235	#####	994240	Mechanic entered - Body Oi secured base bolts.	1138786
8235	#####	994240	Mechanic entered - Body Oi secured base	1138786
8235	#####	994241	Mechanic entered - Body Oi secured bumper	1138786
8235	#####	994237	Mechanic entered - Body Oi secured back rest.	1138786
8235	#####	994237	PASS SEAT HANDGRIP CENTRA MK 2	1138786
8235	#####	994235	Mechanic entered - Body Oi new decal fitted.	1138786
8235	#####	994235	Mechanic entered - Body Oi replaced decal	1138786
8235	#####	994232	Consumables	1138786
8235	#####	994234	Consumables	1138786
8235	#####	994235	Consumables	1138786
8235	#####	994227	Consumables	1138786
8235	#####	994238	Consumables	1138786
8235	#####	994239	Consumables	1138786
8235	#####	994240	Consumables	1138786
8235	#####	994241	Consumables	1138786
8235	#####	994242	Consumables	1138786
8235	#####	993036	SEAT CUSH 6008 DRIVER RE FIRB CVR PAD	1138035
8235	#####	993036	Seat Bottoming Out No Cusi/ checked and replaced seat cushion and fixed back rest adjuster	1138035
8235	#####	993036	Consumables	1138035
8235	#####	993010	Air System Air_Leak Front L Replaced door switch and repair air hose.	1138035
8235	#####	993010	BUTTON CLIPPARD DOOR VALVE 11916-2	1138035
8235	#####	993010	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON	1138035
8235	#####	991024	Accident #52375 - Big dent t Completed by east coast	1137393
8235	#####	991813	Fire safety inspection complete.	1137198
8235	#####	991813	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection complete.	1137198
8235	#####	991024	Accident #52375 - Big dent t ECTB Taken measurements	1136820
8235	8/4/2021	989889	VEHICLE SAFETY INSPECTION Completed VSI.	1136026
8235	8/4/2021	989889	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Satheesh.	1136026
8235	8/4/2021	989889	Assisted Abraham to complete inspection.Tentioned Wheel nuts with Abraham.	1136026
8235	8/4/2021	989890	Mechanic entered - Fluid Le Assisted Satheesh in replacing transmission coolant hose road tested checked for coolant leak and level OK.	1136026
8235	8/4/2021	989890	HOSE ENG TO G/BOX COOLER MERC 0500LE 50N0547G	1136026
8235	8/4/2021	989890	Mechanic entered - Body - F Fitted decal.	1136026
8235	8/4/2021	989921	DECAL EMERGENCY EXIT PRESS BUTTON UNDER BUMPER	1136026
8235	8/4/2021	989921	Consumables	1136026
8235	8/3/2021	989730	Replaced by ATS CARRY OUT FIRE EXTINGUISHER TEST & TAG	1136026
8235	#####	985965	Tensioned wheel nuts pos 5 and 6.	1132669
8235	#####	985965	Assisted	1132669
8235	#####	985435	Mechanic entered - Wheels changed tyres 5 and 6 (worn). nuts tensioned with zubair. nut squirrel replaced (too loose). odo. 132487.	1132373
8235	#####	985435	TYRE 295/80R22.5 NEW	1132373
8235	#####	985435	WHEEL NUT SQUIRREL TUL-10STD-UK	1132373
8235	#####	985435	Consumables	1132373
8235	7/8/2021	984544	Mechanic entered - Fluid Le Fitted new cap.	1131632
8235	7/8/2021	984544	MOUNT RADIATOR LWR MERC BENZ 0500LE 50N0106	1131632
8235	7/8/2021	983421	CLEAN AIR SYSTEM PIPES Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G302359 Receiving #:316571 Date :2021-07-09	1131855
8235	7/6/2021	983978	Mechanic entered - Suspens Removed and replace air bag.	1131623
8235	7/6/2021	983978	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR	1131623
8235	7/6/2021	983978	Mechanic entered - Fluid Le Removed air compressor coolant pipe fitted new pipe Banjo bolts and washers. Top-up coolant. Run engine check for leak ok no leak. Steam cleaned under carriage and engine Plus radiator and intercooler. Roadtest check operation ok Re check coolant level ok.	1131623
8235	7/6/2021	983978	Mechanic entered - Fluid Le Removed and replace sensor. Run engine check for leak ok no leak.	1131623
8235	7/6/2021	983978	WASHER VOITH COMP COOLING PIPE MERC 0500LE	1131623
8235	7/6/2021	983978	SENSOR OIL PRESSURE 457954 ENG MERC 0500LE 50V2812	1131623
8235	7/6/2021	983978	PIPE COOLANT VOITH AIR COMPRESSOR MERC BENZ 0500LE	1131623
8235	7/6/2021	983978	BANJO UNION VOITH COMP COOLING PIPE MERC 0500LE	1131623
8235	7/6/2021	983990	Mechanic entered - Air Syst Removed and fitted new air line pipe and fitting. Test ok no leak. Replace air line fittings o-ring kit found out leaking	1131623
8235	7/2/2021	983447	Mechanic entered - Air Syst Removed air tank to get access to removed fittings. Replace o-ring and re fit fittings. Replace o-ring kit from air line fittings.	1131623
8235	7/2/2021	983421	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)	1131623

8235	#####	954664	Leave old poster in and fit y	Fitted by Refuellers	1114388
8235	2/4/2021	951030	Replaced by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1112485
8235	#####	949122	Ops Entered - Wipers and W	Assist.	1111726
8235	#####	949122	Ops Entered - Wipers and W	Repaired wiper arm clamp.	1111726
8235	#####	946383	Please fit A3 poster over CO	Completed by Refuellers	1109478
8235	1/8/2021	945535		Re-tensioned all wheel nuts w/ Rene	1108799
8235	1/8/2021	945535		Done with Abraham.	1108799
8235	1/7/2021	945149	Consumables		1108799
8235	1/7/2021	945149	Mechanic entered - Wheels	Fitted new tyre to P.O 3-4 as one was worn and one was punctured Tensioned to OEM spec with Abraham	1108799
8235	1/7/2021	945149	Mechanic entered - Wheels	Removed and replaced tyres pos 3 and 4 and tensioned wheel nuts w/ Tayla.	1108799
8235	1/7/2021	945149	TYRE 295/80R22.5 NEW		1108799
8235	1/7/2021	945150	Mechanic entered - Suspens	O/S air bag found to be leaking Removed and fitted new airbag	1108799
8235	1/7/2021	945150	Mechanic entered - Suspens	Removed and replaced front n/s and o/s airbag.	1108799
8235	1/7/2021	945150	AIRBAG FRONT+REAR MERC	0405/0500 REAR/VOLVO B10M/B7R REAR	1108799
8235	1/7/2021	944891	Mechanic entered - Gearbo:	Fitted new transmission coolant hose. Road tested and checked for leaks and fluid level OK.	1108799
8235	1/7/2021	944891	HOSE ENG TO G/BOX COOLER	MERC 0500LE 50N0547G	1108799
8235	1/7/2021	944891	SET DISC PAD SET SCANIA /	MERCEDES 0500	1108799
8235	1/7/2021	945148	STUD WHEEL FRT / RR	MERC BENZ 0500LE A9484010271	1108799
8235	1/7/2021	945148	Mechanic entered - Brakes	Removed and fitted new brake pads to front and rear tensioned wheels with Abraham Brake test was performed and roatest was carried out Okay	1108799
8235	1/7/2021	945148	Mechanic entered - Brakes	Removed and replaced front and rear brake pads and tensioned all wheel nuts w/ Tayla. Road tested OK.	1108799
8235	1/7/2021	945148	SET DISC PAD SET SCANIA /	MERCEDES 0500	1108799
8235	1/6/2021	944865		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Tayla.	1108799
8235	1/6/2021	944865		VEHICLE SAFETY INSPECTION Completed VSI.	1108799
8235	1/6/2021	944891	Mechanic entered - Gearbo:	Drain coolant and removed transmission oil cooler hose. Carry/over.	1108799
8235	1/6/2021	944872	Removed N/S/F window	CO complete.	1108799
8235	1/5/2021	944633	Ops Entered - Fault - Wipers	Secured rivets on wiper arm o/s.	1108708
8235	#####	939881	Mechanic entered - Elec anc	Fitted new stop light lamp.	1103280
8235	#####	939881	LAMP STOP/TAIL LED HELLA		1103280
8235	#####	939881	Consumables		1103570
8235	#####	937481	PERFORM CAMPAIGN 27/2l	Completed	1101224
8235	#####	937434		completed	1101224
8235	#####	937434		CARRY OUT B SERVICE AS PER CHECK LIST	1101224
8235	#####	937434	OIL ENGINE DELO 400 MGX	SAE 15W-40 (MIN)	1101224
8235	#####	937434	OIL ANALYSIS KIT DETECTA	AZ-DET25 3350-601 23448457	1101224
8235	#####	937434	FILTER OIL FILTER	MERCEDES A0001801709	1101224
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	937434	Consumables		1101383
8235	#####	933867	REPLACE ANTI GRAFFITI FILI	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G287760 Receiving #:300566 Date :2020-11-24 REPLACE L 3	1100351
8235	#####	935113		carried out tensioning all wheel nuts with indika.	1099146
8235	#####	934599	SINGLE SEAT BASE		1099146
8235	#####	934599	Consumables		1099146
8235	#####	934564		VEHICLE SAFETY INSPECTION Completed VSI.	1099139
8235	#####	934564		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Sadid.	1099139
8235	#####	934564		Assisted.	1099139
8235	#####	934577	Mechanic entered - Wheels	Removed and fitted run-out tyre for position 4. Tensioned wheel nuts with Abraham.	1099139
8235	#####	934577	Mechanic entered - Wheels	Assisted. Assisted Sadid.	1099139
8235	#####	934577	Consumables		1099146
8235	#####	934579	Mechanic entered - Suspens	Assisted	1099139
8235	#####	934579	Mechanic entered - Suspens	Removed and replaced airbag rear of rear n/s.	1099139
8235	#####	934579	AIRBAG FRONT+REAR MERC	0405/0500 REAR/VOLVO B10M/B7R REAR	1099139
8235	#####	934599	Mechanic entered - Body Ps	Fitted 2 new passenger seat base.	1099139
8235	#####	934611	PERFORM CAMPAIGN 26/2l	Completed.	1099139
8235	#####	933867	Mechanic entered - Vandali	completed by Glassprotech	1098850
8235	#####	933991	Mechanic entered - Elec anc	Fitted new park light globe.	1098850
8235	#####	933991	Consumables		1099139
8235	#####	933560		Assisting - retension pos 1 wheel nuts with Kuma.	1098562
8235	#####	933560		retension pos 1 wheel nuts with Rene.	1098562
8235	#####	933022		completed and road tested ok	1098130
8235	#####	933022		CARRY OUT TUNE UP SERVICE AS PER CHECK LIST adjusted the valve clearance with Sisil	1098130
8235	#####	932292	Mechanic entered - Steering	fitted back new kin pin tensioned wheel nut with Haysun N/F	1098130
8235	#####	932292	*WAITING FOR KING PIN TO	fitted back new king pin tensioned wheel nuts with sisil N/F	1098130
8235	#####	932985	Remove old poster and fit y	Replaced by Refuellers	1098130
8235	#####	932292	KING PIN KIT LH MERC	BENZ 0500LE	1098130
8235	#####	932292	SPACER WASHER 2.30mm	KINGPIN MERC BENZ 0500LE	1098130
8235	#####	932292	SEAL RING KINGPIN	MERC BENZ 0500LE	1098130
8235	#####	932292	SEAL RING KINGPIN	MERC BENZ 0500LE	1098130
8235	#####	932292	Mechanic entered - Steering	removed the kin pin	1098130
8235	#####	932292	*WAITING FOR KING PIN TO	removed king pin	1098130
8235	#####	929545	Fit new Myki Decals & refit	completed.	1096215
8235	#####	929545	Fit new Myki Decals & refit	Assist Mark	1096215
8235	#####	918707	Mechanic entered - Body - C	Completed some has changed	1095344
8235	#####	918707	Consumables		1095633
8235	#####	924065	Vandalism - Slight graffiti	or found no evidence of graffiti.	1092220
8235	#####	924317	PERFORM CAMPAIGN 20/2l	Completed	1092220
8235	#####	922695	Ops Entered - Fault - Elec an	Checked Ok	1090831
8235	#####	922695	Consumables		1091293
8235	#####	921645	REMOVE VINYL AND STEP E	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G284241 Receiving #:296583 Date :2020-09-24	1090540
8235	#####	919231	DIRECT PURCHASE ACCIDEN	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G284241 Receiving #:296582 Date :2020-09-24	1090540
8235	#####	921384	Ops Entered - Fluid Leaks Re	check fixed leak topup coolant bus okl.	1090157
8235	#####	921094	Ops Entered - Warning Light	Fixed coolant leak and replaced radiator cap.	1090157

8235	#####	921094	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615	1090157
8235	#####	918706	Mechanic entered - Body - \ applied new decal to front modesty panel.	1089957
8235	#####	918704	Mechanic entered - Brakes - Door brake u/s	1089957
8235	#####	918704	Mechanic entered - Brakes - Door brake u/s	1089957
8235	#####	918704	Mechanic entered - Brakes - checked node found pink wire came loose.Re crimped wire and put back in rpd plug and checked and still no good.Hooked up lapt top found rpd is getting no pbrake signal so interlock is not working/rpd.Put bus on the pit found broken wires at n/s booster.Repaired checked and ok.	1089957
8235	#####	920994	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST completed inspection.	1089957
8235	#####	920848	CARRY OUT A/C - B SERVICE AS PER CHECK LIST No drivers in stock	1089957
8235	#####	920848	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1089957
8235	#####	920329	DIRECT PURCHASE - BUS IN: Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G283797 Receiving #:296584 Date :2020-09-24	1090831
8235	#####	920329	VEHICLE SAFETY INSPECTION	1089957
8235	#####	920329	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1089957
8235	#####	920329	ANNUAL SAFETY INSPECTION - RWC 034926 - PASSED - 16/09/2020WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1089957
8235	#####	920329	Assisting	1089957
8235	#####	919231	Accident #51007 - Rear left bumper bar - TPAF	1089778
8235	#####	919231	Accident #51007 - Rear left: Refitted rear n/s bumper and lights. Checked the operation of all the lights all ok.	1089778
8235	#####	919231	Accident #51007 - Rear left: Bus at ECBT for repairs	1089778
8235	9/9/2020	919072	Mechanic entered - Wheels fitted new wheel arch brush	1089778
8235	9/9/2020	919072	WHEEL ARCH BRUSH 12065	1089778
8235	9/9/2020	919072	Consumables	1089778
8235	9/9/2020	918709	Mechanic entered - Body - F fitted 2 revet and fixed	1089778
8235	9/9/2020	918953	Mechanic entered - Body - S completed	1089778
8235	9/9/2020	918992	Mechanic entered - Body - F replaced top plastick cover	1089778
8235	9/9/2020	918992	Mechanic entered - Body - F Sisil replaced rear door plastic cover and assisted Sisil	1089778
8235	9/9/2020	918953	Mechanic entered - Body O1 steam cleaned the bus completed	1089778
8235	9/9/2020	918992	COVER REAR DOOR ROOF C Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G283360 Receiving #:295551 Date :2020-09-09	1089778
8235	9/9/2020	921645	Body - INSPECT FOR RUST D Assisting - Repaired by ECBT	1089778
8235	9/9/2020	921645	Body - INSPECT FOR RUST D Repaired by ECBT	1089778
8235	9/8/2020	918705	Mechanic entered - Steering removed the wheel and strated	1089778
8235	9/8/2020	918710	Mechanic entered - Engine - Hasun changed 1 was help him	1089778
8235	9/8/2020	918710	Mechanic entered - Engine - replaced 2 new oil cooler pipe and checked for leaks no leaks	1089778
8235	9/8/2020	918710	SEAL OIL PIPE FILTER HSG - OIL COOLER MERC BENZ 0500LE	1089778
8235	9/8/2020	918710	HOSE OIL FILT HSG - OIL COOLER M/ BENZ 0500LE A4571801620	1089778
8235	9/8/2020	918710	HOSE OIL FILT HSG - OIL COOLER M/ BENZ 0500LE A4571801720	1089778
8235	9/8/2020	918682	Mechanic entered - Elec anc replaced the globe	1089778
8235	9/8/2020	918682	Mechanic entered - Elec anc replaced the light	1089778
8235	9/8/2020	918682	LIGHT SIDE INDICATOR L/H	1089778
8235	9/8/2020	918682	Consumables	1089778
8235	9/8/2020	918708	Mechanic entered - Body - b replaced the sticker	1089778
8235	9/8/2020	918703	Mechanic entered - Brakes - replaced the rubber	1089778
8235	9/8/2020	918703	PAD BRAKE PEDAL RUBBER MERC BENZ 500LE A1072910182	1089778
8235	9/8/2020	918703	Mechanic entered - Brakes - fitted new brake padde rubber	1089778
8235	9/8/2020	918704	Mechanic entered - Brakes - swap the door brake sensor & rpd from bus 201 still the same	1089778
8235	9/8/2020	918682	Mechanic entered - Air Syst repaired leak air pipe inside driver seat	1089778
8235	9/8/2020	918682	Mechanic entered - Air Syst connected the air lines together and secured the air line and secured the driver seat base	1089778
8235	9/7/2020	918534	PRE ANNUAL SAFETY INSPECTION CHECK completed pre annual safety inspection check with Sisil	1089778
8235	9/7/2020	918534	completed. Bus bought from Knox	1089778
8235	9/7/2020	918534	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST PAS checked and did a speedo check with Sisil	1089778
8235	9/7/2020	912998	Mechanic entered - Gearbo: refit torque converter bolts refit sensor plugs and accessories refit air line and to accumulator. replaced rubbed through coolant hose. top up coolant and road test bus found coolant leak at trans cooler tightened hose clamps. topped up coolant. recheck oil level hot. all okay	1089778
8235	9/7/2020	912175	Engine - Stalling when stop 1 Repaired gear box fitted to bus by Knox Tom	1089778
8235	9/4/2020	912998	Mechanic entered - Gearbo: refit transmission to engine refit crossmember refit engine mounts. one bolt hole damaged removed mount and repaired refit mount. refit tailshaft and coolant pipes fill with coolant. found small coolant leak	1089778
8235	9/4/2020	918706	DECAL YOU ARE TRAVELLIN Creditor #:GB-TRA013 TRANSCAL P/O #:G283057 Receiving #:295950 Date :2020-09-15	1089778
8235	9/1/2020	912175	REPAIR OVERHAUL GEARBO Creditor #:GB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:G281666 Receiving #:295322 Date :2020-09-04 PART NO = 4149 004 064 SERIAL NO = 0006774	1089778
8235	#####	912998	Mechanic entered - Gearbo: drain coolant remove coolant pipes and torque converter bolts. remove engine mounts jack up engine and secure with chain and C channel. remove cross member. support transmission on stand and remove bellhousing bolts. remove trnsmission from bus.	1089778
8235	#####	912998	Mechanic entered - Gearbo: clean sump gasket area on transmission housing. clean sump and gasket area refit sump. tension all bolts to zf specs. lower engine and transmission down and refit rear engine mounts. refit intercooler piping. clean filter and refit fill transmission with oil start and top up. road test bus to operating temperature. engine still	1089778
8235	#####	912998	Gasket sump Ecomat	1089778
8235	#####	912998	Mechanic entered - Gearbo: drain and save oil remove rear engine mounts put jack stand under engine and lift. remove sump disconnect all electrical connections remove valvebody. strip valvebody down and inspect. wash all valvebody parts. general wear for kms done. could not find any sticky spool valves. re assemble valvebody using old gaskets ;	1089778
8235	#####	912461		1089778
8235	#####	912175	ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR	1089778
8235	#####	912175	Engine stalling when stop th completed trans service. road tested bus still stalling sent to knox depot.	1089778
8235	8/7/2020	912175	FILTER ZF TRANS ECOMAT (1193281-1) 4139 298 038 01	1089778
8235	8/7/2020	912175	Engine stalling when stop th Road test with Alan (9:20 to 9:25 am)	1089778
8235	8/6/2020	912009	Ops Entered - BusMinder Nc checked ok.busminder charging.	1089778
8235	8/6/2020	912009	Consumables	1089778
8235	8/6/2020	913237	Completed by ATS CARRY OUT FIRE EXTINGUISHER TEST & TAG	1089778
8235	8/5/2020	911373	retension pos 3-4 wheel nuts with nic	1089490
8235	8/5/2020	911373	Assisting	1089490
8235	8/5/2020	911372	Tensioned wheel nuts tyre pos 3 and 4 with Nick.	1089490
8235	8/5/2020	911372	Assisted.	1089490
8235	8/4/2020	911031	Mechanic entered - Wheels Remove pos. 3 tyre and fitted second hand tyre(run out) cleaned rim. Tensioned wheel nuts Assisted by Nick.	1089199
8235	8/4/2020	911031	Consumables	1089490
8235	#####	910216	Remove old A3 Poster and f Completed by Refuellers	1088619
8235	#####	908130	Mechanic entered - Elec anc Fitted new headlight globe.	1086029
8235	#####	908130	GLOBE 24V 70W H1	1086029
8235	#####	908131	Mechanic entered - Elec anc DVR entered twice.	1086029
8235	#####	908130	Consumables	1086303
8235	#####	908131	Consumables	1086303
8235	#####	907790	retension pos 1-2 wheel nuts with Abraham.	1086029
8235	#####	907790	Assisting	1086029
8235	#####	907635	Safety Inspection completedtensioned all wheel nuts with Zubair and tightened fuel filter bowl	1086029
8235	#####	907635	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1086029
8235	#####	907677	Mechanic entered - Air Syst Replaced air fittings o-rings and 1 drain valve	1086029
8235	#####	907677	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 49G7901	1086029
8235	#####	907677	KIT O-RING LARGE VOSS (A6739970145)	1086029
8235	#####	907339	Mechanic entered - Wheels Replaced tyres position 1 and 2 and tensioned all wheel nuts with Alan	1086029
8235	#####	907339	TYRE 295/80R22.5 NEW	1086029
8235	#####	907339	Consumables	1086029
8235	#####	907457	Drv entered - Body Drivers † Check Ok	1086029

8235	#####	907351	KIT O-RING SMALL VOSS (A0309971748)		1086029
8235	#####	907351	Replaced air dryer assemblywater seperator and fixed air leak		1086029
8235	#####	907351	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1086029
8235	#####	907351	AIR DRYER ASSY MERC BENZ 0500LE A0004302915		1086029
8235	#####	907351	SEAL RING AIR DRYER - FOUR WAY VALVE MERC BENZ 0500LE		1086029
8235	#####	907319	CARRY OUT A SERVICE AS PER CHECK LIST A Service completed and tensioned all wheel nuts with Alan		1086029
8235	#####	907319	Consumables		1086029
8235	#####	907319	Consumables		1086029
8235	#####	907319	Consumables		1086029
8235	7/2/2020	904012	PAINT BACK OF SEATS Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G278553 Receiving #:290593 Date :2020-07-03		1083975
8235	7/1/2020	904012	Vandalism - Paint back of se Repaired by ECTB		1083721
8235	7/1/2020	904012	Vandalism - Paint back of se Assisting		1083721
8235	#####	903852	Fault - Elec and Light Interio checked swapped out bulbs and still no good so removed panel and found plugged into innocent socket		1083040
8235	#####	903852	Consumables		1083721
8235	#####	902577	PERFORM CAMPAIGN 06/11 Completed by ECTB		1082460
8235	#####	902577	PERFORM CAMPAIGN 06/11 Sent to ECTB		1082349
8235	#####	900540	Fix A3 Poster in poster fram Completed		1080911
8235	#####	896189	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1077008
8235	#####	896189	VEHICLE SAFETY INSPECTION Completed.		1077008
8235	#####	896189	Safety check completedas per check sheet done with Indika		1077008
8235	#####	896227	Mechanic entered - Elec anc Fitted 3 new saloon lights checkedokay		1077008
8235	#####	896227	LIGHT INTERIOR LED ORION		1077008
8235	#####	896229	Mechanic entered - Dash Ot fitted new globes to dash switches		1077008
8235	#####	896227	Consumables		1077232
8235	#####	896229	Consumables		1077232
8235	#####	896228	Mechanic entered - Body Oi Cleaned back of phone and fitted new magnet		1077008
8235	#####	896185	Mechanic entered - Body Oi Lined up and adjusted drivers door lock.		1077008
8235	5/7/2020	893123	Mechanic entered - Elec anc R/R indicator switch.		1074523
8235	5/7/2020	893123	COMBINATION SWITCH MERC BENZ 0500LE A0085450124		1074523
8235	5/7/2020	893137	Mechanic entered - Elec anc R/R globe.		1074523
8235	5/7/2020	893137	GLOBE 24W 70W H1		1074523
8235	5/7/2020	893123	Consumables		1074812
8235	5/7/2020	893137	Consumables		1074812
8235	5/5/2020	892437	Drv entered - BusMinder Da Checked bus minder and did not found any damage or fault		1073957
8235	5/5/2020	892437	Consumables		1074236
8235	#####	888238	DIRECT PURCHASE ACCIDEN Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G273242 Receiving #:285386 Date :2020-04-28 REPAIR AS REQUIRED		1072737
8235	#####	888238	Accident #48826 - Small scr Repaired by ECTB		1071784
8235	#####	889665	CARRY OUT A SERVICE AS PER CHECK LIST Completed a service and tensioned all wheel nuts w/ Sadik		1071672
8235	#####	889665	Consumables		1071784
8235	#####	889665	Consumables		1071784
8235	#####	889665	Consumables		1071784
8235	#####	889665	Consumables		1071784
8235	#####	888238	Accident #48826 - Small scr Wade took measurement to make panel when he done nedd to book bus		1070230
8235	#####	888220	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST did the service.		1070230
8235	#####	883838	Tape off front Seats of All Ri Done		1067835
8235	#####	882615	VEHICLE SAFETY INSPECTION Completed with Nick.		1067356
8235	#####	882615	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Nick.		1067356
8235	#####	882615	Completed with Rene.		1067356
8235	#####	881841	Service CARRY OUT FIRE EXTINGUISHER TEST & TAG		1066992
8235	#####	881841	Service Has completd		1066992
8235	#####	881448	Ops Entered - Dash Guages I Checked 3 to 4 times works ok. (Note: on going fault could'nt get new fuel sender gauge.)		1066992
8235	#####	881448	Ops Entered - Left hand Mir mirror fixed put new plastic part in and fitted		1066992
8235	#####	881448	Consumables		1066992
8235	#####	881448	Consumables		1066992
8235	#####	881818	Remove old poster and fit R Completed by Refuellers		1066992
8235	3/4/2020	878613	Mechanic entered - Wheels Replace wheel nut squirrel.		1064409
8235	3/4/2020	878613	WHEEL NUT SQUIRREL		1064409
8235	3/4/2020	878613	Consumables		1064699
8235	3/4/2020	878613	Consumables		1064699
8235	3/2/2020	878116	Drv entered - Wipers and W Checked and adjust wiper ok.		1063990
8235	#####	874557	Drv entered - A/C Heating Not Cooling		1061296
8235	#####	874557	Ops Entered - A/C Heating Not Cooling - Route: 2275 - Dep		1061296
8235	#####	874557	Drv entered - A/C Heating Not Cooling		1061296
8235	#####	874557	Ops Entered - A/C Heating Not Cooling Remove failed vibrasorber modify pipe work to suit new style vibrasorber pressure tested vac and recharge unit tested ok		1061296
8235	#####	874557	CLAMP STORF 7/8		1061296
8235	#####	874557	AIR CON REFRIDGERANT		1061296
8235	#####	874557	3/8 O/D x 7/8 I/D BUSH Creditor #:GB-ACT002 ACTROL PARTS P/O #:G269443 Receiving #:280286 Date :2020-02-24		1062003
8235	#####	874557	1/8 I/D UNION Creditor #:GB-ACT002 ACTROL PARTS P/O #:G269443 Receiving #:280286 Date :2020-02-24		1062003
8235	#####	874892	Ops Entered - Fault - BusMir fixed bus minder wire conector bus ok.		1060759
8235	#####	874892	Consumables		1060985
8235	#####	875146	Ops Entered - Fault - Air Sys Repaired and secured drivers seat air hose.		1060759
8235	#####	874557	Drv entered - A/C Heating N Commission tested found that the discharge vibrasorber has failed parts ordered Job not completed carry over		1060727
8235	#####	874557	N0660107 DISCHARGE VIBRO Creditor #:GB-QTK001 QTK GROUP P/O #:G269033 Receiving #:280040 Date :2020-02-20 662-092L		1061296
8235	#####	874598	Ops Entered - Air System Air Fixed Air leak.		1060727
8235	2/1/2020	871021	VEHICLE SAFETY INSPECTION		1057961
8235	2/1/2020	871021	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1057961
8235	2/1/2020	871089	Ops Entered - A/C Heating h Repaired broken a/c clutch wire		1057961
8235	#####	867710	Ops Entered - Fault - A/C Heating Not Cooling - Route: 900		1057013
8235	#####	867710	A/C Heating - Not Cooling		1057013
8235	#####	867710	Ops Entered - A/C Heating h Replaced failed h/p switch modify manifold too suit new style switch		1057013
8235	#####	867710	AIR CON REFRIDGERANT		1057013
8235	#####	869092	PERFORM CAMPAIGN 01/2l completed.		1057013
8235	#####	867710	Drv entered - A/C Heating N Pump unit down removed failed switch went too fit new found switch not the same chasing correct switch job not completed carry over		1056755
8235	#####	867710	SWITCH HIGH PRESSURE R407C		1056755
8235	#####	867710	SWITCH HIGH PRESSURE R407C		1056755
8235	#####	868380	FILTER P/STEER FILTER RETAINER MERCEDES 0500		1056678
8235	#####	868380	completed		1056678

8235	#####	868380	CARRY OUT C SERVICE AS PER CHECK LIST	1056678
8235	#####	868380	FILTER OIL FILTER MERCEDES A0001801709	1056678
8235	#####	868380	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)	1056678
8235	#####	868380	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)	1056678
8235	#####	868380	FILTER FUEL MERCEDES (A5410900151)	1056678
8235	#####	868380	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)	1056678
8235	#####	868380	FILTER AIR FILTER MERCEDES BENZ	1056678
8235	#####	868380	OIL FAN DRIVE OIL MERCEDES 0500LE	1056678
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	CARRY OUT B SERVICE AS PER CHECK LIST	1056678
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	CARRY OUT A SERVICE AS PER CHECK LIST	1056678
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	868380	Consumables	1056755
8235	#####	867710	Ops Entered - Fault - A/C He Tested found H/P switch has failed parts ordered job not completed carry over	1056033
8235	#####	867710	SWITCH HIGH PRESSURE R4 Creditor #:GB-QTK001 QTK GROUP P/O #:G266747 Receiving #:277281 Date :2020-01-17	1056242
8235	#####	867007	Ops Entered - Body Wheel C check tighten all wheel chair ramp high boltes removed	1055815
8235	#####	866673	Ops Entered - Fault - Air Sys check and fixed air leak from driver seat	1055615
8235	#####	866673	AIRLINE FERRAL LARGE	1055615
8235	#####	1/1/2020	844636 REPLACE ANTI GRAFFITI FIL Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G258858 Receiving #:277174 Date :2020-01-17 REPLACE L2 R2	1056242
8235	#####	859269	VEHICLE SAFETY INSPECTION Fixed	1048560
8235	#####	859269	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1048560
8235	#####	859269		1048560
8235	#####	859274	Mechanic entered - Body Oi Fitted new wheel arch brushes.	1048560
8235	#####	859274	WHEEL ARCH BRUSH 12065	1048560
8235	#####	859278	PLASTIC TRIANGLE HANDSTRAP GREY	1048560
8235	#####	859278	Mechanic entered - Body Oi Removed and fitted new hand rail strap.	1048560
8235	#####	859287	Mechanic entered - Body Pa Fitted new seat bases.	1048560
8235	#####	859277	VALVE MANUAL DRAIN VALVE	1048560
8235	#####	859277	Mechanic entered - Air Syst Repair air leaks	1048560
8235	#####	858824	A3 Poster Frame Adhesive L Completed by ECB	1048252
8235	#####	852594	Mechanic entered - Air Syst Fit new o-rings on hose fittings	1042524
8235	#####	852594	KIT O-RING LARGE VOSS (A6739970145)	1042524
8235	#####	852565	CARRY OUT A SERVICE AS PER CHECK LIST Completed a service as per checklist fixed air leaks and tensioned wheel nuts w/ ryan	1042524
8235	#####	852565	A Service completed with Abraham and tensioned all wheel nuts	1042524
8235	#####	852565	Consumables	1042735
8235	#####	852565	Consumables	1042735
8235	#####	852565	Consumables	1042735
8235	#####	852565	Consumables	1042735
8235	#####	852565	Consumables	1042735
8235	#####	851223	KIT O-RING SMALL VOSS (A0309971748)	1041392
8235	#####	851223	KIT O-RING LARGE VOSS (A6739970145)	1041392
8235	#####	851223	AIR DRYER ASSY MERC BENZ 0500LE A0004302915	1041392
8235	#####	851223	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE	1041392
8235	#####	851223	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Checked ping tank abd air pipes Ok.	1041392
8235	#####	850435	Consumables	1040898
8235	#####	850435	Ops Entered - Fault - BusMir remove old wire conector and replaced with new conector bus ok.	1040699
8235	#####	849783	Consumables	1040409
8235	#####	849538	Consumables	1040409
8235	#####	849783	Ops Entered - Fault - BusMir Sent Ron email to rectify	1040124
8235	#####	849538	Elec and Light Engine stop c Completed buy Dulkith	1040124
8235	#####	849578	Fault#:37000 - Ops Entered attened to B/D check and fixed faulty electrical system temprally and bus send to depot replaced main solonide bus ok.	1039972
8235	#####	849538	Elec and Light Engine stop control salonoid U/S	1039972
8235	#####	849538	STARTER RELAY 24V-300AMP 0500LE	1039972
8235	#####	849417	Consumables	1039972
8235	#####	849417	GLOBE 24V 70W H1	1039573
8235	#####	849417	Mechanic entered - Elec anc R/R globe.	1039573
8235	#####	848950	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1039573
8235	#####	846102	Consumables	1039573
8235	#####	846102	Mechanic entered - Elec anc checked all working o.k.	1039373
8235	#####	848048	CARRY OUT ANNUAL INSPE Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G260100 Receiving #:270769 Date :2019-10-24	1040409
8235	#####	848048	Service TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1038988
8235	#####	848048	Service VEHICLE SAFETY INSPECTION	1038988
8235	#####	848048	Assisting completed.	1038988
8235	#####	848048	Service ANNUAL SAFETY INSPECTION SERIAL # K015424 PASS 15/10/19 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1038988
8235	#####	847843	Final chek for RSI	1038823
8235	#####	847418	Consumables	1038823
8235	#####	846102	Mechanic entered - Elec anc Reffer 843021	1038513
8235	#####	847418	Drv entered - Elec and Light replaced os park light globe and fixed holder	1038513
8235	#####	846107	Mechanic entered - Engine steam clean engine and transmission. remove floor hatches and clean top of both.	1037880
8235	#####	845984	REPAIR SINGLE SEAT BASE Creditor #:GB-AUTO05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G259397 Receiving #:269048 Date :2019-10-07	1037880
8235	#####	845984	REPAIR DBLE SEAT BACK Creditor #:GB-AUTO05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G259397 Receiving #:269048 Date :2019-10-07	1037880
8235	#####	845984	REPAIR DISABLED SEAT BASI Creditor #:GB-AUTO05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G259397 Receiving #:269048 Date :2019-10-07	1037880
8235	#####	845984	Mechanic entered - Body Pa re-fitted and secured disabled seat base cushions following repairs.	1037880
8235	#####	846021	Consumables	1037880
8235	#####	846101	Consumables	1037880
8235	#####	846101	Mechanic entered - Elec anc fitted back with new fitting	1037880
8235	#####	846021	Mechanic entered - Elec anc replaced	1037880
8235	#####	846021	LED INT LIGHT ORION	1037880

8235	#####	779754	REAR SEATS NOT CLIPPED IN	Secure rear seat	982501
8235	#####	779309	Consumables		982501
8235	#####	779309	LAMP LED SIDE LAMP RED/AMBER PERE	[52-98002]	982013
8235	#####	779309	Mechanic entered - Elec anc	replaced smashed [osr] clearance light.	982013
8235	#####	775618	CLEAN GRAFFITI INSIDE	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:#G233581 Receiving #:241415 Date :2018-11-07	980800
8235	#####	776808	Ops Entered - Fault - Wipers	clean water pickup washer ok.	979610
8235	#####	776838	Ops Entered - Fault - A/C He	Locate and repair electrical fault in run time circuit	979610
8235	#####	776810	Consumables		979695
8235	#####	776809	Consumables		979695
8235	#####	776810	Ops Entered - Fault - Elec an	Locate and repair electrical fault to a/c	979610
8235	#####	776810	Ops Entered - Fault - Elec an	as below	979610
8235	#####	776809	UHF ANTENNA 500-520MHZ		979610
8235	#####	776809	Ops Entered - Fault - Elec an	check 2 way and replaced antenna radio ok.	979610
8235	#####	775618	CLEAN GRAFFITI FROM BUS	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:#G232810 Receiving #:240600 Date :2018-10-26 CLEAN AS REQUIRED	978496
8235	#####	775618	Vandalism - Clean graffiti fo	Cleaned by ECTB	978208
8235	#####	775058	FILTER DRYER AIR COND THE	RMO KING	977567
8235	#####	775058		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	977567
8235	#####	775058		CARRY OUT A/C - A SERVICE AS PER CHECK LIST service as per list	977567
8235	#####	772065	DIRECT PURCHASE - BUS INI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:#G231452 Receiving #:239588 Date :2018-10-15 ANNUAL INSPECTION	975855
8235	#####	772546	Mechanic entered - Body OI	done.	973475
8235	#####	772299	Mechanic entered - Brakes I	reseal n/s rear brake booster air line	973475
8235	#####	772065		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	973475
8235	#####	772065		VEHICLE SAFETY INSPECTION	973475
8235	#####	772065		ANNUAL SAFETY INSPECTION SERIAL - RWC 015744 - PASSED - 09/10/18WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	973475
8235	#####	772065		Assisting	973475
8235	#####	771661	Check over bus for RSI	completed.	973475
8235	#####	769996	Mechanic entered - Body W	reseal rubber gap	973475
8235	#####	769925	Mechanic entered - Air Syst	fit new suspension control valve.	973475
8235	#####	769925	KIT O-RING LARGE VOSS	[A6739970145]	973475
8235	#####	770411	Drv entered - Brakes Park_B	Road tested buschecked rear brakes on the pit - ok.	973475
8235	#####	769926	CRANK DRIVE BELT 0500LE	MERC	973058
8235	#####	769926	Mechanic entered - Engine t	new drive belt fitted.	973058
8235	#####	769996	Mechanic entered - Body OI	complete steam clean engine bay under engine chassis .	973058
8235	#####	769926	HINGE DRIVERS DOOR S/S	60mmX60mm [12205][802505]	973058
8235	#####	769994	Mechanic entered - Body OI	fit new struts.	973058
8235	#####	769994	Mechanic entered - Body OI	fit new struts.	973058
8235	#####	769994	STRUT GAS STAY 600Nm	54	973058
8235	#####	769994	STRUT GAS STAY 500Nm	330mm LONG	973058
8235	#####	769907	Check bus for RSI	completed.	973058
8235	#####	769926	Mechanic entered - Body OI	new decals fitted.	973058
8235	#####	769926	Mechanic entered - Body OI	secure panels.	973058
8235	#####	769926	Mechanic entered - Body OI	refit hinge pin.	973058
8235	#####	769926	Mechanic entered - Body OI	refit strips.	973058
8235	#####	769926	Mechanic entered - Body OI	refit seat backs to wall.	973058
8235	#####	769926	Mechanic entered - Body OI	fit new decals.	973058
8235	#####	769926	Mechanic entered - Body Pa	fitted new decals.	973058
8235	#####	769926	Mechanic entered - Body OI	fit new hinge.	973058
8235	#####	769925	SOLENOID VALVE LEVELLINI	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:#G230794 Receiving #:238755 Date :2018-10-03	973475
8235	#####	769769	REMOVE AND REPLACE A3 I	Replaced by Refuellers	973058
8235	#####	769957	Vandalism - needs painting	Clean by east coast	973473
8235	#####	767378	Consumables		972362
8235	#####	767378	Headlight out	check and adjusted head lights bus ok.	971743
8235	#####	767345	Consumables		972075
8235	#####	767344	Consumables		972075
8235	#####	767345	GLOBE 24V 70W H1		971743
8235	#####	767345	Ops Entered - Fault - Elec an	R/R globe.	971743
8235	#####	767344	NUT BRASS BATTERY TERMINAL	NEGATIVE (-)	971743
8235	#####	767344	NUT BRASS BATTERY TERMINAL	POSITIVE (+)	971743
8235	#####	767344	Mechanic entered - Elec anc	removed and replaced battery bridge cable.	971743
8235	#####	767343		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Drove on underchassis wash and did fire inspection.	971743
8235	#####	766322		PRE ANNUAL SAFETY INSPECTION CHECK carried out pre annual safety check	970530
8235	#####	765385	Mechanic entered - Wheels	retensioned wheel nuts	970530
8235	#####	765385	Mechanic entered - Wheels and Tyres	Wheel Nut Retension	969280
8235	#####	763211	PERFORM CAMPAIGN 26/1I	Completed under body wash	969280
8235	9/7/2018	764859	cleaned vandalism as requir	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:#G229090 Receiving #:236598 Date :2018-09-07	969280
8235	9/7/2018	764859	Vandalism Vandalism/ Graf	done by eastcoast	969280
8235	9/5/2018	763050	Mechanic entered - Suspens	fit new sway bar link.	968820
8235	9/5/2018	762934	DRAGLINK ASSY MERC 0500	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:#G228818 Receiving #:236402 Date :2018-09-05	968820
8235	9/5/2018	762934	Steering box oil leak	refit reconditioned steering box.	968820
8235	9/5/2018	762934	Steering box oil leak	re fit reconditioned steering box changed tie rod and drag link aswell.	968820
8235	9/5/2018	762934	NUT DRAG LINK BALL JOINT	MERC 0500LE 50L0003	968820
8235	9/5/2018	762933	Brakes Steering wheel shack	road tested fit new front wheels. road testedsteering still shaking. wheel alignment done by contractor. tested ok.	968820
8235	9/5/2018	762933	Service	Whell alignment carry out by air anywhere	968820
8235	9/1/2018	762934	Steering box oil leak	remove steering box. 30/08/18	968820
8235	9/1/2018	762934	Steering box oil leak	remove steering box sent for repair. 31/08/18	968820
8235	9/1/2018	762934	REPAIR LEAKING STEERING I	Creditor #:GB-HYD001 HYDROSTEER PTY LTD P/O #:#G228483 Receiving #:236303 Date :2018-09-04	968820
8235	9/1/2018	762933	Brakes Steering wheel shack		968820
8235	9/1/2018	763211	PERFORM CAMPAIGN 26/1I	Replaced rear brakes pads and brake booster. Brake tested and road tested. Replaced tie rod and steering box sent for repair. 31/08/18	968820
8235	#####	763051	Mechanic entered - Steering	fitted new track rod.	968820
8235	#####	763050	SWAY BAR DROP ARM R/H	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:#G228434 Receiving #:235894 Date :2018-08-30	968820
8235	#####	762947	Suspension O/S/R front air t	Wrong bus number must be bus 203	968820
8235	#####	762944	Suspension R/H/rear top to	Wrong bus number must be bus 203	968820
8235	#####	763051	Tie Rod Mercedes Benz 050	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:#G228434 Receiving #:235894 Date :2018-08-30	968820
8235	#####	763051	Mechanic entered - Steering	Shakes/ Wobbles tie rod ball joi	968820
8235	#####	762935	Brakes rear R/H pads worn t	fit new r/h rear callper and brake pads.	968820
8235	#####	762741	Brakes Rear brake pads low	fit new rear brake pads.	968820
8235	#####	762741	SET DISC PAD SET SCANIA /	MERCEDES 0500	968820

8/30/2018

8235	#####	762948	Brakes Front ?l modulator v wrong bus number must be bus 203	968820
8235	#####	762942	Brakes L/H rear brake boost Worn bus number must be bus 203	968820
8235	#####	762717	Assisting completed and tensioned wheel nut with Newan	968820
8235	#####	762717	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	968820
8235	#####	762717	VEHICLE SAFETY INSPECTION	968820
8235	#####	762741	REAR BRAKE CALIPER RH 05 Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G228289 Receiving #:235804 Date :2018-08-29	968820
8235	#####	762741	Brakes Rear brake pads low Assisting	968820
8235	#####	762741	Brakes Rear brake pads low	968820
8235	#####	760131	re-tensioned all wheel nuts with kumar.	967012
8235	#####	760129	re-tensioned all drive wheel nuts with kumar.	967012
8235	#####	760182	Mechanic entered - Fluid Le added coolant - low.	967012
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	FILTER BOWL TYPE FUEL CHASS/MOUNTED MERCEDES 0500LE	967012
8235	#####	759798	Consumables	967121
8235	#####	759846	Wheels and Tyres Flat or Le Remove and replace position 5 & 6 tyre fitted two (2) new tyre. Position 6 return to rack. Tensioned wheel nuts with Shalen.	967012
8235	#####	759846	TYRE 295/80R22.5 NEW	967012
8235	#####	759846	Consumables	967121
8235	#####	759798	CARRY OUT C SERVICE AS PER CHECK LIST Complete	967012
8235	#####	759798	FILTER FUEL FILTER MERCEDES BENZ (a0004771302)	967012
8235	#####	759798	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)	967012
8235	#####	759798	FILTER FUEL MERCEDES (A5410900151)	967012
8235	#####	759798	FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)	967012
8235	#####	759798	FILTER AIR FILTER MERCEDES BENZ	967012
8235	#####	759798	OIL FAN DRIVE OIL MERCEDES 0500LE	967012
8235	#####	759798	FILTER OIL FILTER MERCEDES A0001801709	967012
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	CARRY OUT B SERVICE AS PER CHECK LIST Complete	967012
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	Consumables	967121
8235	#####	759798	CARRY OUT A SERVICE AS PER CHECK LIST Complete	967012
8235	#####	759798	Consumables	967121
8235	#####	8/9/2018	758466 Mechanic entered - Wheels Top up tyre pressure.	965493
8235	#####	756175	PERFORM CAMPAIGN 17/1i Checked by Refuellers and this job has been done	964782
8235	#####	753585	CLEAN AIR SYSTEM PIPES Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G225329 Receiving #:233320 Date :2018-07-31	963367
8235	#####	753585	ELBOW COUPLING 90 DEGREES	962540
8235	#####	753585	NUT VOSS 232 22mm MERK	962540
8235	#####	753585	VALVE OVERFLOW VALVE N	962540
8235	#####	753585	KIT O-RING LARGE VOSS (A6	962540
8235	#####	753585	KIT O-RING SMALL VOSS (A6	962540
8235	#####	755151	REMOVE OLD POSTER AND Replaced by refuellers	962540
8235	#####	753585	Mechanic entered - Engine Other Air compressor coolant pipe	962540
8235	#####	753585	Mechanic entered - Engine (R/R overflow valvenylon tubings and fittings.R/R all voss fittings.Checked - ok.Steam cleaned engine and inside bus.Road tested - ok.	962540
8235	#####	753585	KIT O-RING LARGE VOSS (A6739970145)	962540
8235	#####	753585	SEAL RING A/DRYER	962540
8235	#####	753585	PIPE COOLANT VOITH COM	962540
8235	#####	753585	VALVE 4 WAY CIRCUIT PROT	962540
8235	#####	753585	WASHER FUEL PIPE	962540
8235	#####	753585	BANJO UNION 0500LE	962540
8235	#####	753585	KIT O-RING SMALL VOSS (A6	962540
8235	#####	753585	NYLON TUBING 8MM X 1MM	962540
8235	#####	753585	O RING P/STRG PUMP MERC 0500LE (A0159974845)	962540
8235	#####	753585	GASKET AIR COMPRESSOR (962540
8235	#####	753585	Mechanic entered - Engine (Remove 6 way valve replace o-ring air line voss fitting o-ring kit for five(5) fittings. Fitted new 6 way valve and re-fit all fittings. Remove All air line pipe and fitted new repair clean pipe and secured fitted p clamp to secured. Replace nylon tubing found brittle remove air line and replace with new nylon tubing. Replace o-ring	962540
8235	#####	753585	Mechanic entered - Engine (Remove air compressor coolant hose remove steering pump and remove air compressor assembly. Clean top of engine and remove Air compressor fittings and re-fit fittings to new Air compressor and re-fit Steering pump. Fitted new Air compressor fitted new Air compressor coolant pipe. Re-fit steering pipe and re-fit cor	962540
8235	#####	753585	COMPRESSOR AIR VOITH M Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G225096 Receiving #:232597 Date :2018-07-23	962540
8235	#####	753663	Gearbox Driveline - Steam c Steam clean Engine and under of the Bus.	962540
8235	#####	753585	Mechanic entered - Engine (Rectify found air compressor coolant pipe worn. check for parts availableparts wrong parts.Road tested bus - found 6 way leakingair gauges playing.C/O.	962540
8235	#####	753565	Mechanic entered - Body OI Fitted new wheel arch rubber and brush.	962540
8235	#####	753555	SILENCER AIR DRYER MERC 0500LE	962540
8235	#####	753555	HALDEX COIL BASE OIL SEPERATOR (49G0031)	962540
8235	#####	753555	VALVE DRAIN VALVE CONDI	962540
8235	#####	753555	KIT O-RING LARGE VOSS (A6739970145)	962540
8235	#####	753555	KIT O-RING SMALL VOSS (A0309971748)	962540
8235	#####	753555	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Remove Air dryer filter found full of dirt pipes and fitting blocked. Remove water separator assembly. Remove all pipes found blocked clean. Fitted new water separator and replace voss fittings o- ring with o-ring kit. fitted new air dryer assembly and fitted new voss o-rin	962540
8235	#####	753555	AIR DRYER ASSY A0004302915	962540
8235	#####	752726	PERFORM CAMPAIGN 11/1i complete	961846
8235	#####	752726	FUSE BLADE 10 AMP (NRS2810)	961846
8235	#####	751811	Breakdown#:35209 - Ops Er replaced door air regulator assy	961846
8235	#####	751811	FILTER PNEUMATIC REGULATOR DOOR RAM (AW20-02H-C)	961846
8235	#####	751811	Found door regulator drainplug brokn Blocked line off and send to depot	961846
8235	#####	751811	Breakdown#:35209 - Ops Er Shalen - Arranged Jarek to attend.	961506
8235	#####	7/3/2018	749834 PERFORM CAMPAIGN 13/1i completed.	960416
8235	#####	7/2/2018	749614 Breakdown#:35147 - Ops Er did not attend to brake down call to driver bus bring back to depot	960295
8235	#####	748005	KIT O-RING LARGE VOSS (A6739970145)	959189
8235	#####	748005	Air System leaks on air dry repaired	959189
8235	#####	747098	Body rear door seal is peelir remove and refitted rear passanger door rubber bus ok.	958744
8235	#####	747310	PERFORM CAMPAIGN 16/1i REPLACED	958744
8235	#####	747051		958744
8235	#####	747051	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Craig;	958744
8235	#####	747051	VEHICLE SAFETY INSPECTION Complete with Craig.	958744

8235	#####	747060	BUSH RUBBER SLEEVE RADIATOR - 0500LE A0009872143	958744
8235	#####	747060	Mechanic entered - Engine (Remove and replace radiator mount.	958744
8235	#####	745392	DIRECT PURCHASE - VANDA Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G222231 Receiving #:230058 Date :2018-06-20 CLEAN	958438
8235	#####	745374	DIRECT PURCHASE - VANDA Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G222228 Receiving #:230056 Date :2018-06-20 CLEAN	958438
8235	#####	745392	Vandalism - Clean graffiti as CLEANED BY ECTB 26/05/18	957362
8235	#####	745374	Vandalism - Clean graffiti as CLEANED BY ECTB 25/05/18	957362
8235	#####	744456	KIT SWITCH OVERRIDE RPD	957160
8235	6/8/2018	744456	PERFORM CAMPAIGN 07/18 did the campaign and check sheet.	957160
8235	#####	739960	PERFORM CAMPAIGN 15/18 Completed	952300
8235	#####	739663	Consumables	952300
8235	#####	739663	Consumables	952300
8235	#####	739663	Consumables	952300
8235	#####	739663	Consumables	952300
8235	#####	739663	CARRY OUT A SERVICE AS PER CHECK LIST Complete with Nick.	952300
8235	5/4/2018	736683	Consumables	952300
8235	5/4/2018	736683	GLOBE 24V 70W H1	949880
8235	5/4/2018	736683	Mechanic entered - Elec anc changed blown globe (ns) low beam headlight.	949414
8235	5/2/2018	736195	Ops Entered - Fault - Brakes check and fixed front door road tested bus serviceble.	949414
8235	5/2/2018	736195	SILENCER DOOR VALVE SILENCER	949414
8235	#####	735531	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)	949098
8235	#####	735531	ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTR	949098
8235	#####	735531	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	949098
8235	#####	735680	CARRY OUT FIRE EXTINGUISHER TEST & TAG	949098
8235	#####	735680	COMPLETED ON 15/02/18	949098
8235	#####	735238	Mechanic entered - Engine (Fit lower intake pipe clamp and road test	949098
8235	#####	735238	PLASTIC TRIANGLE HANDSTRAP GREY	949098
8235	#####	735238	NUT HAND RAIL CLAMP (28	949098
8235	#####	735238	Body - Grab rail handle miss Fit grab handle	949098
8235	#####	735157		949098
8235	#####	735157	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	948912
8235	#####	735157	VEHICLE SAFETY INSPECTION	948912
8235	#####	733303	PERFORM CAMPAIGN 06/18 Checked been done already	947290
8235	#####	733303	DECAL PARK BRAKE/NO WINDOW ACCES NEW	947290
8235	4/9/2018	731657	Mechanic entered - Acciden Job has been completed	945651
8235	#####	726410	CLEAN GRAFFITI Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G216231 Receiving #:224349 Date :2018-04-04	945651
8235	#####	726410	Rectify Vandalism damage r Completed by east coast	941001
8235	3/9/2018	725774	Consumables	940467
8235	3/9/2018	725774	Mechanic entered - Elec anc replaced faulty (nsf) top indicator light.	939992
8235	3/9/2018	725774	INDICATOR LED FRONT TURN LOW FLOOR SQUARE (32983)	939992
8235	#####	723486		938032
8235	#####	723486	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	938032
8235	#####	723486	VEHICLE SAFETY INSPECTION assisted with saftey	938032
8235	#####	722946	Please remove any old post Fitted by Refuellers	938032
8235	#####	722384	FITTING STRAIGHT JOINER 6mm (11060600)	938032
8235	#####	722384	Body (None) / Driver seat is fit reconditioned seat.	938032
8235	#####	722384	SEAT SEAT ASSY ISRI A6008	938032
8235	#####	721939	Mechanic entered - Body O1 Fitted new screw.	937418
8235	#####	721920	Consumables	937730
8235	#####	721920	Consumables	937730
8235	#####	721920	Consumables	937730
8235	#####	721920	Consumables	937730
8235	#####	721920	Consumables	937730
8235	#####	721920	Complete with Mark.	937418
8235	#####	721920	CARRY OUT A SERVICE AS PER CHECK LIST	937418
8235	#####	720239	Assisting	935305
8235	#####	720239	Tensioned all rear tyres.	935305
8235	#####	719984	Drv entered - Suspension Kr check air bags air system bus serviceble.	935305
8235	#####	719791	Consumables	935695
8235	#####	719791	TYRE 295/80R22.5 NEW	935305
8235	#####	719791	Wheels and Tyres - Tyres 3 { changed tyres 3; (worn); 4 and 5 (rack) and 6 (worn). 295's fitted. all drive wheel nuts tensioned with sisil.	935305
8235	#####	719802	BOLT BUMPER BAR BOLT SPECIAL	935305
8235	#####	719802	PLASTIC WASHER	935305
8235	#####	719802	Mechanic entered - Body O1 replaced missing bumper bar bolts (nsr).	935305
8235	#####	718948	Body Front_Door Operatio check and adjusted front passenger doors	934953
8235	2/6/2018	717619	FILTER DRYER SCANIA / VOLVO (1375997) (4968704W)	933603
8235	2/5/2018	717619	Breakdown - Sandown Park Checked air leak clean air dryer replaced air dryer canister bus serviceble	933603
8235	#####	713365	Consumables	929345
8235	#####	713365	Consumables	929345
8235	#####	713365	PLASTIC TRIANGLE HANDSTRAP GREY	928807
8235	#####	713360	Assisting	928807
8235	#####	713360	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	928807
8235	#####	713360	VEHICLE SAFETY INSPECTION	928807
8235	#####	713365	Body replace two passenger Replaced	928807
8235	#####	713306	Consumables	929006
8235	#####	713306	Consumables	929006
8235	#####	713306	Consumables	929006
8235	#####	713306	Dash - When you go over a l went trough and removed o/s pax buzzrs at rear of bus foun one with slight rub trough tapped and put back.Checked and all ok now.	928807
8235	#####	713323	Perform Campaign 27/17 Pt fitted decal	928807
8235	#####	710600	Mechanic entered - Fluid Le added coolant - low.	924828
8235	#####	709306	Vandalism - Replace DOT fil Replaced	923332
8235	#####	705261	Consumables	922112
8235	#####	705261	TYRE 295/80R22.5 NEW	921457
8235	#####	707938	Consumables	922112
8235	#####	707938	Consumables	922112
8235	#####	707938	Consumables	922112
8235	#####	707938	Consumables	922112
8235	#####	707938	CARRY OUT B SERVICE AS PER CHECK LIST	921457
8235	#####	707938	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)	921457
8235	#####	707938	FILTER OIL FILTER MERCEDE	921457

8235	#####	668011	Mechanic entered - Vandali: i cleaned graffiti in side this bus	908377
8235	#####	689603	PERFORM CAMPAIGN 09/1: complete	907876
8235	#####	689603	DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE	907876
8235	#####	689872	Remove old A3 Posters with Replaced by Fleet Support	907876
8235	#####	688231	Consumables	906729
8235	#####	688231	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)	906465
8235	#####	688231	Mechanic entered - Elec anc Replaced o/s bottom park light.	906465
8235	#####	688212	Assisting completed and tensioned wheel nuts with nick	906465
8235	#####	688212	CARRY OUT A SERVICE AS PER CHECK LIST	906465
8235	#####	688212	Consumables	906729
8235	#####	688212	Consumables	906729
8235	#####	688212	Consumables	906729
8235	#####	688212	Consumables	906729
8235	#####	688212	Consumables	906729
8235	#####	685518	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete	902851
8235	#####	685518	Tensioned pos 1 and 34 tyres.	906636
8235	#####	682151	DIRECT PURCHASE - VANDA Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201036A Receiving #:209151 Date :2017-09-05 Vandalism Vandalism/ Graffiti Interior rear floors have graffiti and build up of grime and sticky substances.	902136
8235	#####	682151	DIRECT PURCHASE - VANDA Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201036B Receiving #:209148 Date :2017-09-05 Vandalism Vandalism/ Graffiti Interior rear floors have graffiti and build up of grime and sticky substances.	902136
8235	#####	682151	Complete graffiti work Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G201036 Receiving #:208842 Date :2017-09-01	900833
8235	#####	683129	Consumables	900636
8235	#####	683129	Wheels and Tyres - Tyres 13 Replaced position 1 and 3 tyres with run outs.	900467
8235	#####	682151	Vandalism Vandalism/ Graf Completed EASTCOAST	899398
8235	#####	681335	Carried out Tune up service with Ryan and washed engine.	899102
8235	#####	681335	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Tune up service completed with Matt S	899102
8235	#####	680613	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	898280
8235	#####	680613	VEHICLE SAFETY INSPECTION	898280
8235	#####	680613	Assisting	898280
8235	#####	680613	HAMMER EMERGENCY HAMMER	898280
8235	#####	680613	Assisting	898280
8235	#####	680739	Consumables	898752
8235	#####	680739	Wheels and Tyres - Tyre 3 w Has been replaced	898280
8235	#####	680739	Consumables	898752
8235	#####	680739	Dash Guages Not Working (Checked working OK	898280
8235	#####	680739	Ops Entered - Fault - Elec an Checked OK	898280
8235	#####	680739	DECAL EMERGENCY EXIT 600x80mm	898280
8235	#####	680739	EMERGENCY EXIT (HAMMER)	898280
8235	#####	680739	Ops Entered - Fault - Body D Check seat control working OK	898280
8235	#####	680739	Body - Front door top plasti Secured	898280
8235	#####	680817	PERFORM CAMPAIGN 17/1: complete	898280
8235	#####	679280	Drv entered - Vandalism Van removed graffiti from engine hatch.	896137
8235	8/3/2017	677914	Please remove old posters a Done by refuellers	894493
8235	#####	675844	VALVE OVERFLOW VALVE MERCEDES 0500LE	892961
8235	#####	675844	Air System - Air valve leak n replaced suspension tank non return valve.	891754
8235	#####	675590	Consumables	892017
8235	#####	675590	Consumables	892017
8235	#####	675590	Consumables	892017
8235	#####	675590	CARRY OUT A SERVICE AS PER CHECK LIST completed with kuma	891754
8235	7/7/2017	672541	MOUNT RUBBER EXHAUST MOUNT VOLVO (6850149-3) (30T0001)	888149
8235	7/7/2017	672541	PLASTIC TRIANGLE HANDST	888149
8235	7/7/2017	672541	VEHICLE SAFETY INSPECTION	888149
8235	7/7/2017	672541	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	888149
8235	7/7/2017	672541	VEHICLE SAFETY INSPECTION	888149
8235	7/7/2017	672496	Ops Entered - Fault - Passen Ref to w/o # 672497	888149
8235	7/7/2017	672742	Engine - Muffler mount broi removed	888149
8235	7/7/2017	672742	Consumables	888357
8235	7/7/2017	672742	Elec and Light - OSR indicat: replaced new taping screws	888149
8235	7/7/2017	672742	Body - Pax hand strap torn removed	888149
8235	7/7/2017	672497	Body Rear_Door Operation Replaced solenoid valve	888149
8235	7/5/2017	672040	Vandalism Vandalism/ Graf Ref to defect # 649524	887709
8235	#####	670483	VALVE DOOR SOLENOID VALVE WITH VOLTAGE SUPPRESSOR	887128
8235	#####	670483	CONTACT BLOCK DOOR PUSH SWITCH (M22-K10)	885879
8235	#####	670483	Body Rear_Door Operation Replaced door switch assy & cleaned solenoid	885879
8235	#####	670719	PERFORM CAMPAIGN 05/1: UPDATED	885879
8235	#####	669883	Ops Entered - Fault - Body R adjusted rear door sestive edge bus ok.	885636
8235	#####	669252	Remove old Green 2016/17 Replaced	885119
8235	#####	668011	SILENCER DOOR VALVE SILENCER	883989
8235	#####	668011	Ops Entered - Fault - Body R Rectified problem	883989
8235	#####	667864	Ops Entered - Fault - Passen check and fixed front and rear passanger doors	883989
8235	#####	667891	Engine Bolt missing on cool remove floor hatch and fit new nut	883989
8235	#####	667253	Breakdown#:33452 - Ops Er removed broken a/c bottom idler pulley and replaced. assisted ranjith in fitting new belts and adjusted. road test - o.k. work overseen by ranjith.	883773
8235	#####	667253	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG	883773
8235	#####	667253	BELT MICRO V SERPENTINE	883773
8235	#####	667253	PULLEY ADJUSTER IDLER PU	883773
8235	#####	667253	BOLT TENSIONER PULLEY	883773
8235	#####	667253	Body / driver seat has no su seat operation checked. could not fault.	883773
8235	#####	667251	Body / driver seat has no su seat checked - could not fault.	883773
8235	#####	666203	REPLACE /FIT ANTI GRAFFITI Creditor #:GB-GLAD10 GLASSPROTECH MELBOURNE P/O #:G195370 Receiving #:202554 Date :2017-06-14 L1 R14	883773
8235	6/7/2017	666203	Vandalism - Fit & Replace ar REPLACED	882114
8235	6/5/2017	665660	Consumables	882114
8235	6/5/2017	665660	Elec and Light - Interior flurc: changed blown fluro tube - saloon light.	881295
8235	6/1/2017	665192	retension pos 3/4. with nick.	881032
8235	6/1/2017	665192	Assisting	881032
8235	#####	664752	Wheels and Tyres - Tyre 3 w changed tyre 3 (worn). nuts tensioned with sisil.	880103
8235	#####	664752	Wheels and Tyres - Tyre 3 w changed tyre 3 (worn). nuts tensioned with sisil.	880103
8235	#####	664752	Consumables	881032
8235	#####	663011	FIT A3 Poster/Hangers Fitted	878886

8235	#####	651761	A/C Heating - Replace A/C fi complete	869060
8235	#####	651761	A/C Heating - Replace A/C filter	869060
8235	#####	651761	A/C Heating (None): demist fitted new dail	869060
8235	#####	651761	A/C Heating (None): demister not working	869060
8235	#####	651761	A/C Heating (None) / Demister not working	869060
8235	#####	651761	DEMISTER CONTROL UNIT	869060
8235	#####	651378	Consumables	868531
8235	#####	651378	Consumables	868531
8235	#####	651378	GLOBE 24V 70W H1	867996
8235	#####	651378	Elec and Light Head light ou Replace globes	867996
8235	#####	650989	Carried out safety inspection with sisil and matt	867440
8235	#####	650989	Carried out safety inspection with sisil and zub.	867440
8235	#####	650989	SINGLE SEAT BASE	867440
8235	#####	650989	GLOBE 24V 21W SINGLE CONTACT (HLR2421)	867440
8235	#####	650989	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Matt	867440
8235	#####	650989	VEHICLE SAFETY INSPECTION completed	867440
8235	#####	605747	CARRY OUT ROLLAWAY SYS Rcvg# 194471 (Refer kerrie's email 7/3)	856246
8235	#####	647815	Consumables	862616
8235	#####	647815	LED INTERIOR ROOF LIGHT (Use P/No. NR87676G)	862264
8235	#####	647815	Elec and Light - OSF LED salc fitted new led light now working	862264
8235	#####	646339	SINGLE SEAT BASE	861394
8235	#####	646339	Body Passenger Seat Torn - replaced damaged pax. seat bases.	861394
8235	#####	645735	PERFORM CAMPAIGN 01/1: NOT ON CAMPAIGN LIST	861078
8235	2/2/2017	642259	VALVE BALL 1/2 HEATER	857895
8235	2/2/2017	642258	KIT AIR LINE FITTING VOSS 22MM (5020114)	857895
8235	2/1/2017	642221		857076
8235	2/1/2017	642221	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	857076
8235	2/1/2017	642221	VEHICLE SAFETY INSPECTION	857076
8235	2/1/2017	642259	Fluid Leaks - coolant leaks fi R/R heater taprefilled coolantroad tested - ok.	857076
8235	2/1/2017	642084	Consumables	857895
8235	2/1/2017	642084	LED FRONT POSITION MARKER LIGHT	857076
8235	2/1/2017	642084	Elec and Light - NSF & rear c replaced both.	857076
8235	2/1/2017	642258	Air System - Air Ireak from r Fitted air line kit - ok.	857076
8235	2/1/2017	642077	Fit New 2107 Large and 5m: completed	857076
8235	2/1/2017	642220	Consumables	857895
8235	2/1/2017	642220	Consumables	857895
8235	2/1/2017	642220	Consumables	857895
8235	2/1/2017	642220	Consumables	857895
8235	2/1/2017	642220	Consumables	857895
8235	2/1/2017	642220	Consumables	857076
8235	2/1/2017	642220	Consumables	857076
8235	#####	639617	Service Road rsted ok	857076
8235	#####	639688	Replace 2x N/S side window Creditor #:GB-A1W001 A-1 Windscreens P/O #:G185732 Receiving #:192534 Date :2017-01-30	857076
8235	#####	639688	Accident damage - Vandalism Acc # DAN 44825 - 2 N/S windows.	856246
8235	#####	639617	HAMMER EMERGENCY HAMMER	856246
8235	#####	639617	Brakes Park_Brake Not Hol: R/R park brake valve and emergency hammer. (required road test)	856246
8235	#####	639617	VALVE PARK BRAKE VALVE I	856246
8235	1/9/2017	637600	Ops Entered - Fault - Fluid Lu checked and fixed coolant leak bus ok.	853391
8235	1/4/2017	636621	Retensioned pos 56 & 34 with Nick	852768
8235	1/3/2017	636269	Consumables	852768
8235	1/3/2017	636269	TYRE 11R22.5N NEW	852032
8235	1/3/2017	636269	Mechanic entered - Wheels removed tyres 5 and 6. checked pressure in 5. inflated to specs. found valve stem leaking. replaced tyre 5. nuts tensioned with dulkith.	852032
8235	1/1/2017	605747	Consumables	852032
8235	1/1/2017	605747	CARRY OUT ROLLAWAY SYS Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G178986 Receiving #:192126 Date :2017-01-23	856246
8235	#####	636001	Brakes (None) hand brake r Checked hand brake and working properly could not find any fault	852032
8235	#####	632412	VEHICLE SAFETY INSPECTION	847167
8235	#####	632412	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	847167
8235	#####	632412	VEHICLE SAFETY INSPECTION	847167
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	628738	Consumables	842768
8235	#####	621294	Vandalism - Replace O/S/R Creditor #:GB-A1W001 A-1 Windscreens P/O #:G179023 Receiving #:187522 Date :2016-11-15	842571
8235	#####	624407	COMPRESSOR OIL AIR CON	841989
8235	#####	624407	FILTER DRYER AIR COND THERMO KING	840710
8235	#####	625534	Fit A3 poster to holder eithe Replaced by Fleet Support	840410
8235	#####	621294	Vandalism - Replace O/S/R x 4 N/S/R x 3 windows including	835363
8235	#####	624407	CARRY OUT A/C - B SERVICE AS PER CHECK LIST	838527
8235	#####	624407	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list found the compressor cradle was loose tension and tested ok road tetsted ok	838527
8235	#####	624308	KIT AIR LINE FITTING VOSS 2	838527
8235	#####	624308	VALVE 4 WAY CIRCUIT PROT	838527
8235	#####	624308	SWITCH LOW AIR 0500LE (A0045455514)	838527
8235	#####	624308	Drv entered - Warning Light Checked and found forway protection valve and low air pressure sender. Replaced for way valeand low air pressure sender also tested all O/k	838527
8235	#####	624308	SEAL RING A/DRYER	838527
8235	#####	624308	SEALS 4 WAY PROTECTION \	838527
8235	#####	622783	Consumables	837254
8235	#####	622783	Elec and Light - FR3130 codi look for defect fault FR 3031 changed coolant tank sensor fault gone sensor warranty	836963
8235	#####	622590	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	836963
8235	#####	622590	VEHICLE SAFETY INSPECTION	836963
8235	#####	622590	Mechanic entered - A/C Hea removed the headed tank fitted 2 clamp	836963
8235	#####	622525	Brakes (None) / DOOR BRA no rollaway feature working. Tested pins and ok. Traced further found broken wire at booster for buzzer repaierd. Checked and repaired and ok. Swapped the old over ride switch with new one as well.	836963
8235	#####	620867	Replace broken N/S/F side v Creditor #:GB-A1W001 A-1 Windscreens P/O #:G179022 Receiving #:185173 Date :2016-10-12	835865
8235	#####	620867	DECAL EMERGENCY EXIT 600x80mm	835363
8235	#####	620867	DECAL NO SMOKING	835363
8235	#####	620867	EMERGENCY EXIT (HAMMER)	835363
8235	#####	620867	DECAL WHEELCHAIR	835363

8235	9/7/2016	614459	KIT DRAIN VALVE KIT BOTTOM		827535
8235	9/7/2016	614459	KIT CYCLONE CONDENSER VALVE KIT		827535
8235	9/7/2016	614459			827535
8235	9/7/2016	614459	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air System Check Completed		827535
8235	9/7/2016	614460	Consumables		830870
8235	9/7/2016	614460	Consumables		830870
8235	9/7/2016	614460	Consumables		830870
8235	9/7/2016	614460	Consumables		830870
8235	9/7/2016	614460	CARRY OUT A SERVICE AS PER CHECK LIST B Service Completed		827535
8235	9/6/2016	611584	Consumables		830870
8235	9/6/2016	611584	Body (None): sunvisor has f secured back		827535
8235	9/6/2016	611584	BLIND ROD CLIP		827535
8235	9/6/2016	611584	DRIVERS BLIND PULL KNOB		827535
8235	9/6/2016	611584	Ops Entered - Fault - Body V fixed door brake and sun blind both.		827535
8235	9/5/2016	611584	Engine - Compressor pumpi rebooked		827535
8235	#####	611523	check charging system and i refit alterntator. working ok.		827535
8235	#####	611523	Consumables		827616
8235	#####	611584	Gearbox Driveline (None): t Replaced alternator - working ok.		827535
8235	#####	611584	Gearbox Driveline (None): t fitted axle back jump started moved the bus to work shop		827535
8235	#####	611523	check charging system and i checked batteries low. checked charge rate. alternator not charging. moved bus to workshop removed alternator. carry over.		827535
8235	#####	611523	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE		827535
8235	#####	611519	DIRECT PURCHASE - TOWIN Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G175380 Receiving #:181805 Date :2016-08-29 PRINCES HWY TO DEPOT		828307
8235	#####	611519	Consumables		827535
8235	#####	611519	Elec and Light - Princes Hwy Jump started bus but drives and drops gears tried a few times and arranged tow: CHECK CHARGE RATE		827535
8235	#####	610473	Consumables		826630
8235	#####	610472	Consumables		826630
8235	#####	610472	PLASTIC WASHER		826254
8235	#####	610472	BUMPER BOLT SPECIAL		826254
8235	#####	610473	GAS STAY 350NM X 600MM		826254
8235	#####	610454			826254
8235	#####	610454	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		826254
8235	#####	610454	VEHICLE SAFETY INSPECTION		826254
8235	#####	594661	AIR COMPRESSOR 0500 EURO 3 A4571302915		826254
8235	#####	594661	POWER STEERING PUMP O		826254
8235	#####	594661	GASKET COMPRESSOR 0500		826254
8235	#####	610451	Consumables		826630
8235	#####	610264	Consumables		826630
8235	#####	610451	Fit diode to rollaway system fitted diode to rollaway circuit		826254
8235	#####	610264	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)		826254
8235	#####	610264	Mechanic entered - Elec anc changed blown globe (osf) bottom park light.		826254
8235	#####	610474	Body (None)lts mirror loos Secured bracket.		826254
8235	#####	610473	Body Replace o/s/r hatch sb R/R strut		826254
8235	#####	610472	Body Rear bumper bolts mi Fitted new bolts		826254
8235	#####	610474	Consumables		826630
8235	#####	609407	Vandalism -CLEAN GRAFFITI CLEANED		824656
8235	#####	609358	Consumables		824656
8235	#####	609358	Elec and Light - Destination Completed		824220
8235	8/6/2016	608579	MERCEDES REAR ENGINE DOOR SWITCH		823003
8235	8/6/2016	608579	Engine (None) wont restart changed rear engine hatch safty switch assy		823003
8235	8/4/2016	608139	Air System Air_Leak Front fixed air leak - driver's seat.		822931
8235	8/2/2016	607695	CARY OUT CCTV RETRO FIT Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G173840 Receiving #:182106 Date :2016-09-01		829216
8235	8/2/2016	607695	-Replace Drivers Camera wi Completed by Bwereelectrical Jhonny		822237
8235	8/2/2016	607572	Consumables		822611
8235	8/2/2016	607572	Body Drivers seat faulty.(C. removed old seat and replaced with new job completed		822237
8235	#####	607572	SEAT ASSY ISRI A6008 AIR LI Creditor #:GB-RP AUTO UPHOLSTERY PTY LTD P/O #:G173148 Receiving #:179942 Date :2016-08-03		822931
8235	#####	606021	Wipers and Washers Wiper checked. tightened loose linkage connection. working ok		820462
8235	#####	606021	CCTV Timestamp Incorrect checked time correct.		820462
8235	#####	606034	Body - Remove till tray completed. (removed silicone and cleaned top of cab door).		820462
8235	#####	605747	Consumables		820462
8235	#####	605747	PERFORM CAMPAIGN 08/1i did the roll away fitment		820462
8235	#####	605185	Accident damage - N/S/M - Solvent cleaned marks from O/S/M		819485
8235	#####	603907	Consumables		818355
8235	#####	603907	INDICATOR LOOSE WHEEL NUT 32MM		817702
8235	#####	603907	Mechanic entered - Wheels re-tensioned nuts on wheel 2. replaced missing nut pointer on same wheel.		817702
8235	#####	603663	PLEASE REMOVE ANY OLD Fleet Support		817702
8235	#####	602957	CLEANER GRAFFITI REMOVER AMERASE PER LITRE		817124
8235	#####	602957	HARDENER DELFLEET GRAFFITI RESISTANT PER LITRE		817124
8235	#####	602957	ANTI GRAFFITI PAINT DARK GREY		817124
8235	#####	602957	ANTI GRAFFITI PAINT LIGHT GREY		817124
8235	#####	594661	Engine - Compressor pumpi Rebooked		807878
8235	7/9/2016	602957	Vandalism Vandalism/ Graffiti Interior		817124
8235	7/9/2016	602957	Vandalism Vandalism/ Graf Graffiti cleaned whole bus		817124
8235	7/7/2016	602702	Body Two Passenger Seat Tr replaced.		816940
8235	7/7/2016	602690	Consumables		817124
8235	7/7/2016	602690	Consumables		817124
8235	7/7/2016	602690	Consumables		817124
8235	7/7/2016	602690	Consumables		817124
8235	7/7/2016	602690	Consumables		816940
8235	7/7/2016	602690	CARRY OUT A SERVICE AS PER CHECK LIST		816940
8235	7/4/2016	601591			815992
8235	7/4/2016	601591	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Phil		815992
8235	7/4/2016	601591	VEHICLE SAFETY INSPECTION Complete with Phil		815992
8235	7/4/2016	601705	Drv entered - Wipers and W checked ok		815992
8235	#####	594648	Body - Back of drivers seat e C/O with new defect number		807878
8235	#####	594648	Air System Air_Leak Interio Swapped parts from old valve to new and fitted new h/brake valve to the bus.		807878
8235	#####	594661	Consumables		813364
8235	#####	594661	GLOBE WEDGE INSTRUMENT 24V SW (17197)		812551

8235	#####	594661	Drv entered - Elec and Light	Replaced park light globe	812551
8235	#####	597428	Please remove any old post	done by fleet support	811827
8235	#####	594661	GASKET SUIT 0500LE COMP		807878
8235	#####	594661	POWER STEERING PUMP O RING 0500LE		807878
8235	#####	594661	AIR COMPRESSOR 0500 EUF	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G169225 Receiving #:175050 Date :2016-05-31	808012
8235	#####	594648	Fluid Leaks - Header tank le	Tighten sender drive tested. ok	807878
8235	#####	594648	Body - Mirror arm loose	Tighten n/s side mirror bracket.	807878
8235	#####	594648	Brakes - Handbrake leaking	Removed and replaced hand brake.	807878
8235	#####	594093	Wipers and Washers Wiper	lubricate wiper link rod ok.	807236
8235	#####	593948		re tensioned wheel nuts position 3 and 4	807236
8235	#####	593567	Consumables		807236
8235	#####	593567	TYRE NEW 11R22.5N		806543
8235	#####	593567	Mechanic entered - Wheels	changed tyres 3 (worn) and 4 (rack). wheel nuts tensioned.	806543
8235	#####	593403	PERFORM CAMPAIGN 04/1t	Already location there for wallet	806543
8235	#####	592158			804986
8235	#####	592158		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	804986
8235	#####	592158		VEHICLE SAFETY INSPECTION	804986
8235	#####	591417	Ops Entered - Fault - Brakes	checked OK	804986
8235	#####	591416	0500 COOLANT LOW LEVEL SENDER		804225
8235	#####	591416	Engine low coolant light on.	replace coolant low level sender.	804154
8235	#####	591417	Brakes calibrate rear brake.	done	804154
8235	#####	590754	Ops Entered - Fault - Air Sys	check air leak and changed dorr air regulator bus ok.	803216
8235	#####	590754	BRACKET FILTER REGULATOR		803216
8235	#####	590754	FILTER REGULATOR DOOR F		803216
8235	5/5/2016	589974	SEAT BELT BUCKLE TWIN WIRE GREY (Use 340446)		801728
8235	5/5/2016	589974	Body Drivers Seat Belt	replaced broken seat belt stork - driver's cab.	801728
8235	#####	588931	KIT AIR LINE FITTING VOSS 22MM	5020114	800873
8235	#####	588851	CCTV Timestamp Incorrect	time changed	800873
8235	#####	588851	CCTV Timestamp Incorrect	time changed by apprentice	800873
8235	#####	588931	Air System Air_Leak Rear n	Cut and removed suspension line from air dryerfitted new kitreplaced new nut and fittedchecked air line ok.	800873
8235	#####	588891	Consumables		800873
8235	#####	588891	Consumables		800873
8235	#####	588891	Consumables		800873
8235	#####	588891	Consumables		800873
8235	#####	588891	Consumables		800873
8235	#####	588891		CARRY OUT A SERVICE AS PER CHECK LIST Did A service and checked air leaks torqued wheel nuts.	800873
8235	#####	588891		CARRY OUT A SERVICE AS PER CHECK LIST Did A service and checked air leaks torqued wheel nuts.	800873
8235	#####	588154	Consumables		800545
8235	#####	588154	Mechanic entered - Elec anc	replaced (osf) top indicator light - u/s.	799560
8235	#####	588154	LED FRONT TURN INDICATOR LOW FLOOR SQUARE(32983)		799560
8235	#####	587916	Consumables		799560
8235	#####	587916	Wheels and Tyres - Pos 12 a	inflated both steer tyres to specs.	799560
8235	#####	587627	Body (None): drivers blind	fixed driver blind.	799028
8235	#####	587307	FILTER TRANSMISSION ZF	4139-298-038/4139 298 038 01	799028
8235	#####	587308			798423
8235	#####	587308		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	798423
8235	#####	587307			798423
8235	#####	587307		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST	798423
8235	#####	586890	Consumables		798961
8235	#####	586890	GLOBE H1 24V 70W HLC2470		798423
8235	#####	586890	Ops Entered - Fault - Elec an	changed blown globe (os) low beam headlight.	798423
8235	#####	586756	Consumables		798423
8235	#####	586756	0500 COOLANT LOW LEVEL SENDER		798423
8235	#####	586756	cooling warning on dash	Checked fault code changed coolant level sender r/tested bus OK	798423
8235	#####	582246	Brakes (None): ramp is misi	adjusted rear leaf of front door. removed debris from ramp. extricated a foreign screw from near hinge. ramp still lifts but not on sensor side. roadtested working perfectly. parked on fuel bay.	795131
8235	#####	581475	Brakes Park_Brake Not Reli	check park brake air pressure and value ok. bus serviceable.	794651
8235	#####	581602			794651
8235	#####	581602		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	794651
8235	#####	581602		VEHICLE SAFETY INSPECTION	794651
8235	#####	580737		Changed Diff oil	793889
8235	#####	580737	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	793889
8235	#####	577628	OUTER LEVER ISRI SEAT A60	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G162874 Receiving #:168805 Date :2016-02-26	789972
8235	#####	577628	KIT PIVOT & BUSH ISRI	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G162874 Receiving #:168805 Date :2016-02-26	789972
8235	#####	578100	Mechanic entered - Body OI	re-fitted used brush strip to (osf) wheel arch. - failen off.	789972
8235	#####	577628	CUSHION FOAM ISRI D/SEAT A6008		789969
8235	#####	577628	Body Drivers Seat Controls	checked over seat and replaced damage parts	789969
8235	#####	576002	Engine - Warning sound not off		788914
8235	#####	576252	Mechanic entered - Air Syst	check and fixed air fault road test bus serviceable.	788914
8235	#####	576002	Consumables		788914
8235	#####	576002	0500 COOLANT LOW LEVEL SENDER		788914
8235	#####	576002	Dash (None) High pitched a	Replace coolant level sender	788914
8235	#####	575337	Consumables		788378
8235	#####	575337	Warning Lights (None) / W	checked bus. roadtested. intermittant fault that did not occur during testing.	788205
8235	#####	575337	Body - Both front w/arch br	fitted new brush and rubber.	788205
8235	#####	575337	WHEEL ARCH BRUSH RUBBER (Sold P/M)		788205
8235	#####	575337	WHEEL ARCH BRUSH 2.5MT		788205
8235	#####	575417	The Campaign requires all B	MOBITEC - MOBITEC ICU400 - 16 X 140 - N/A - N/A	788205
8235	#####	575050	Consumables		788205
8235	#####	575050	GLOBE WEDGE INSTRUMENT 24V SW 17197		787287
8235	#####	575050	Mechanic entered - Elec anc	changed blown globe (nsf) bottom park light.	787287
8235	2/5/2016	573826	Body - Bench seat cushion d	replaced seat cushions and re-fuelled and parked the bus for service	786860
8235	2/4/2016	573826	Consumables		786860
8235	2/4/2016	571721	Consumables		786860
8235	2/4/2016	573826	Ops Entered - Fault - Elec an	refit repaired 2-way to bus. working ok.	786860
8235	2/4/2016	573826	Ops Entered - Fault - Elec and Light	Two Way Radio - Route:	786860
8235	2/4/2016	571721	Ops Entered - Fault - Elec an	REF TO W/O 571721	785092
8235	2/4/2016	573826	Drv entered - Comm Equip		786860

8235	2/4/2016	573826	REPAIR BENCH SEAT	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G161577 Receiving #:167928 Date :2016-02-16	788914
8235	2/4/2016	573826	Body - Bench seat cushion damaged on engine OSF 1st row		788660
8235	2/3/2016	571721	REPAIR TWO WAY RADIO	Creditor #:GB-AAR001 AA RADIO SERVICES PTY LTD P/O #:G160988 Receiving #:167342 Date :2016-02-04	788660
8235	2/3/2016	573826	FLOOR HATCH SCREWS 13405 + 30628		788660
8235	2/3/2016	573826	OVERFLOW VALVE 0500LE		788660
8235	2/3/2016	573826	KIT AIR LINE FITTING VOSS 2		788660
8235	2/3/2016	573826	SEALS 4 WAY PROTECTION VALVE BARREL (MB 0500LE)		788660
8235	2/3/2016	573826	Air System - 4 way valve la fit new 4 way valve cup washers/fit new suspension overflow valve/fit new pipe union seals		788660
8235	2/2/2016	573698	25mm BLACK NO 6		788660
8235	2/2/2016	573698	25mm BLACK NO 7		788660
8235	2/2/2016	573698	Body decal		788660
8235	2/1/2016	573348	HALDEX CONDENSER KIT TOP(CYCLONE)		786683
8235	2/1/2016	573348	CYCLONE CONDENSER VALVE KIT		786683
8235	2/1/2016	573348			786683
8235	2/1/2016	573348	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed		786683
8235	2/1/2016	573348	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		786683
8235	#####	572505	Consumables		786362
8235	#####	572505	Consumables		786362
8235	#####	572505	Consumables		786362
8235	#####	572505	Consumables		786362
8235	#####	572505	PWR STRG FILTER		785092
8235	#####	572505	FUEL FILTER 0500LE		785092
8235	#####	572505	AIR FILTER MERC 0500LE E		785092
8235	#####	572505	ENGINE OIL BREATHER KIT C		785092
8235	#####	572505	OIL FILTER 1725+0500LE		785092
8235	#####	572505	CARRY OUT C SERVICE AS PER CHECK LIST		786031
8235	#####	572505	CARRY OUT C SERVICE AS PER CHECK LIST		786031
8235	#####	572505	CARRY OUT B SERVICE AS PER CHECK LIST		786031
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	CARRY OUT B SERVICE AS PER CHECK LIST		786031
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	Consumables		786042
8235	#####	572505	Service	CARRY OUT A SERVICE AS PER CHECK LIST	786031
8235	#####	572505	Service	CARRY OUT A SERVICE AS PER CHECK LIST	786031
8235	#####	569951	AIR FILTER MERC 0500LE E491L		785092
8235	#####	571721	Consumables		785370
8235	#####	571721	Ops Entered - Fault - Elec an removed radio and sent to cmi concepts		785092
8235	#####	570877	Consumables		784982
8235	#####	570877	GLOBE H1 24V 70W HLC2470		784365
8235	#####	570877	Mechanic entered - Elec anc change os head light globe.		784365
8235	#####	570964	DECAL PTV METRO MYKI DECAL LARGE 450x330mm		784365
8235	#####	570964	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS		784365
8235	#####	570788	VEHICLE SAFETY INSPECTION		784365
8235	#####	570788	VEHICLE SAFETY INSPECTION		784365
8235	#####	570788	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		784365
8235	#####	569895	Elec and Light Bus mooving checked. front and rear door brakes working correctly. also checked door ramp brake which is working correctly.		783350
8235	#####	569829	GLOBE WEDGE INSTRUMENT 24V SW 17197		783350
8235	#####	569829	Mechanic entered - Elec anc changed blown globe (osf) bottom park light.		783350
8235	#####	569895	Consumables		783689
8235	#####	569829	Consumables		783689
8235	#####	569951	BUMPER BOLT SPECIAL		783350
8235	#####	569951	PLASTIC WASHER		783350
8235	#####	569951	Mechanic entered - Body Ot replace missing bolts on (osr) cornerbumper bar. tighten all loose bolts on rear bumper bar.		783350
8235	#####	569401	already been done.		782900
8235	#####	569400	re-tensioned nuts on wheels 1 and 2.		782900
8235	#####	568604	EVAPORATOR FAN MOTOR		782707
8235	1/8/2016	568708	WIPER REFILL SUIT TX800+TX900		781397
8235	1/8/2016	568987	Drv entered - Wipers and W Changed both wiper blades		781397
8235	1/8/2016	568987	Drv entered - Wipers and W replaced wiper blade		781397
8235	1/8/2016	568708	Steering Shakes/ Wobbles / Adjust brakes put wheels on torque nuts and road test.		781397
8235	1/8/2016	568708	Steering Shakes/ Wobbles / put the wheel back and tensioned road tested ok		781397
8235	1/8/2016	568708	Mechanic entered - Engine t replaced air compressor coolant hose		781397
8235	1/8/2016	568987	Fluid Leaks - Oil sitting in va Washed engine and changed coolant pipe		781397
8235	1/8/2016	568987	Fluid Leaks - Oil sitting in va tightened power steering pump pipe and steam cleaned		781397
8235	1/8/2016	568987	Warning Lights (None) road tested all the warning light gone		781397
8235	1/8/2016	568987	Warning Lights (None) check warning lights no problem found. Test private call line and radio working fine.		781397
8235	1/8/2016	568987	Consumables		782091
8235	1/8/2016	568987	Ops Entered - Fault - Comm Tested was all good		781397
8235	1/8/2016	568987	Ops Entered - Fault - Comm Equip - Route: 900 - Caulfield 5		781397
8235	1/7/2016	568708	Steering Shakes/ Wobbles / replaced front both side brake calipers and rotors		781397
8235	1/7/2016	568708	Steering Shakes/ Wobbles / Assist Sisiil with changing both front sides discs & calipers		781397
8235	1/7/2016	568604	A/C Heating Not Cooling Replaced all failed evap fan motors		781397
8235	1/7/2016	568708	MERCEDES BENZ 0500 LE R ₁ Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G160310 Receiving #:165980 Date :2016-01-07		782091
8235	1/7/2016	568708	MERC BENZ 0500LE BRAKE I Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G160310 Receiving #:165956 Date :2016-01-07		782091
8235	1/7/2016	568708	DISC PAD SET SCANIA MB0500		781397
8235	1/7/2016	568708	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		781397
8235	1/6/2016	568534	TYRE NEW 11R22.5N		781397
8235	1/6/2016	568534	Mechanic entered - Wheels assist neven in changing tyres 1 and 2. vibration in steering still occurring. allsteer nuts tensioned with neven.		781397
8235	1/6/2016	568534	Consumables		782091
8235	1/6/2016	568708	Steering Shakes/ Wobbles / Adjusted all the brakes & r/tested still the same c/o		781397
8235	1/6/2016	568393	Ops Entered - Fault - Steerin road test and change front 2 balanced wheels road test bus serviceable.		781397
8235	1/6/2016	568393	Steering Shakes/ Wobbles / check oOk.		781397

8235	#####	547528	Accident damage - N/S/R - f repaired nsr wheel arch panel repaired os lower panels and CANTA rail sanded and masked up ns os and rear wheel arch panels	762591
8235	#####	547537	Accident damage - O/S/F - R Repairs	762591
8235	#####	547528	Service - AccidentAccident Started repairs	762218
8235	#####	547528	Accident damage - N/S/R - f Started repairs	762218
8235	#####	547537	Accident damage - O/S/F - R Started repairs	762218
8235	9/7/2015	541281	Ops Entered - Fault - Passen Check door operation all doora working O/K	755750
8235	9/7/2015	541281	RAD CAP MERC BENZ SIGHT GLASS SIDE 50N0701 A0005014615	755750
8235	9/7/2015	541281	Fluid Leaks Rear of bus leal fixed coolant leak topup coolant change header tank cap.bus ok.	755750
8235	9/4/2015	545295	Steering (None) / Low fluid Top up power steering oil	755750
8235	9/1/2015	544961	Consumables	759501
8235	9/1/2015	544961	Complete task as instructed Checked OK	759501
8235	9/1/2015	544618	Consumables	759501
8235	9/1/2015	544618	Consumables	759501
8235	9/1/2015	544618	Consumables	759501
8235	9/1/2015	544618	Consumables	759501
8235	9/1/2015	544618	Consumables	759501
8235	9/1/2015	544618	CARRY OUT A SERVICE AS PER CHECK LIST	759409
8235	#####	542774	A3 Poster Change on Route Replaced	759409
8235	#####	541303	Body Front door U/S Repaired and adjusted	757268
8235	#####	540518	Consumables	755750
8235	#####	540518	BELL PUSH FOR WHEEL CHAIR PASS	755750
8235	#####	540517	BRAKE+ CLUTCH PEDAL PAD 0500LE	755750
8235	#####	540944	as per Campaign 08/15Fit H Completed	755750
8235	#####	540458		755301
8235	#####	540458	CLEAN A/C FILTERS	755301
8235	#####	540458	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	755301
8235	#####	540458	VEHICLE SAFETY INSPECTION	755301
8235	#####	540518	Elec and Light Pax bell switc R/R disablen pax bell switch	755301
8235	#####	540517	Brakes pedal rubber is u/s R/R pedal pad	755301
8235	#####	540117	Consumables	755301
8235	#####	540117	AMBER REFLECTOR	755301
8235	#####	540117	Elec and Light - Reflector mi replaced 2 n/s rear reflectors and o/s rear reflector.	755301
8235	#####	540135	CCTV (None) Check CCTV tc checked time and date.Time was out by 20 min adjusted it date was ok checked play back and all good.	755301
8235	8/3/2015	538974	L.E.D SIDE MARKER PERE RED/AMBER LLX30131	753303
8235	8/3/2015	538974	Accident - Broken clearance replaced smashed (nsr) clearance light.	753303
8235	#####	537971	Complete Campaign 6/15 A Replaced	752078
8235	#####	536661	Consumables	751189
8235	#####	536661	LED FRONT POSITION MARKER LIGHT	751137
8235	#####	536661	Elec and Light - OSF exit ligh replaced dull exit lights (osf) and at centre door.	751137
8235	#####	536015	re-tensioned nuts on wheels 5 and 6.	749750
8235	#####	535943	re-tensioned nuts on wheels 5 and 6.	749750
8235	#####	536016	Consumables	750128
8235	#####	536016	GLOBE H1 24V 70W	749750
8235	#####	536016	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500	749750
8235	#####	536016	Elec and Light Exterior Ligh replaced (os) low beam headlight insert. removed (ns) low beam headlight insert and replaced. drilled out two seized mounting screws and blind nuts. replaced with new ones. adjusted both beams.	749750
8235	#####	535800	TYRE NEW 11R22.5N	749750
8235	#####	535800	CLAMP SUIT TYRE VALE EXTENSION T18 & T19	749750
8235	#####	535800	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG	749750
8235	#####	535800	Wheels and Tyres - Tyre 5 ni changed tyres 5 (worn) and 6 (to rack). nuts tensioned with ryan.	749750
8235	#####	535839	Mechanic entered - Steering added power steering fluid - low.	749750
8235	#####	535530	KIT AIR LINE FITTING VOSS 22MM 5020114	749362
8235	#####	535530	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115	749362
8235	#####	535530	SEAL RING A/DRYER	749362
8235	#####	535530	AIR DRYER MERCEDES 0500 (49G8505W)	749362
8235	#####	535530	Ops Entered - Fault - Air Sys check air leak steam clean air dryer assy change air dryer assy and air fitting o ring kit adjust air dryer pressure cut off value road test bus ok. engine oil pumping from air compresor.	749362
8235	7/7/2015	534557	NO 5 WHITE 25MM	747954
8235	7/7/2015	534557	NO 7 WHITE 25MM	747954
8235	7/7/2015	534557	EMERGENCY PROCEDURE DECAL	747954
8235	7/7/2015	534557	DECAL MAX SAFE CARRY WHITE ON CLEAR	747954
8235	7/7/2015	534557	DECAL VIDEO AND AUDIO SURVEILLANCE	747954
8235	7/7/2015	534557	Audit Route buses for correct Decals and positions. Replace	747954
8235	#####	533227	Body Front_Door Operatio fixed front passanger door ramp arm.	746997
8235	#####	532105	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	744930
8235	#####	532105	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	744930
8235	#####	532105	CLEAN A/C FILTERS	744930
8235	#####	532105	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	744930
8235	#####	532105	VEHICLE SAFETY INSPECTION Completed	744930
8235	#####	532225	Consumables	744930
8235	#####	532225	Mechanic entered - Wheels Replaced tyres position 1 & 2	744930
8235	#####	532104	Consumables	744930
8235	#####	532104	OIL ENGINE MINERAL 15W40 (LU18)	744930
8235	#####	532104	Replace Engine Oil Breather Kit	744930
8235	#####	532104	Grease AC Compressor Clutch Bearing	744930
8235	#####	532104	Tension Wheel Nuts to Spec	744930
8235	#####	532104	A Service & Bus Safety Inspection	744930
8235	#####	532104	D-Service & Bus Safety Inspection	744930
8235	#####	532104	Consumables	744930
8235	#####	532104	Consumables	744930
8235	#####	532104	Consumables	744930
8235	#####	532104	ENGINE OIL BREATHER KIT 0500LE (EASS00M05)	744930
8235	#####	532104	AIR FILTER MERC 0500LE E491L	744930
8235	#####	532104	OIL FILTER 1.725+0500LE	744930
8235	#####	532118	Consumables	744930
8235	#####	532118	Consumables	744930
8235	#####	532118	Consumables	744930
8235	#####	532118	Consumables	744930
8235	#####	532118	Consumables	744930
8235	#####	532118	CARRY OUT B SERVICE AS PER CHECK LIST	744930

8235	#####	532103	Consumables		744930
8235	#####	532103	Consumables		744930
8235	#####	532103	Consumables		744930
8235	#####	532103	Consumables		744930
8235	#####	532104		CARRY OUT A SERVICE AS PER CHECK LIST Completed	744930
8235	#####	532103		CARRY OUT A SERVICE AS PER CHECK LIST Completed	744930
8235	#####	532104	Consumables		744930
8235	#####	532118	Consumables		744930
8235	#####	532118	Consumables		744930
8235	#####	532118	Consumables		744930
8235	#####	532118	Consumables		744930
8235	#####	532104	Consumables		744930
8235	#####	532104	Consumables		744930
8235	#####	532104	Consumables		744930
8235	#####	532118		CARRY OUT A SERVICE AS PER CHECK LIST Completed	744930
8235	#####	530742	Consumables		742987
8235	#####	530742	Elec and Light Exterior Ligh	checked - already been changed.	742534
8235	#####	530362	Mechanic entered - Fluid Le	added coolant - low.	742018
8235	#####	530383		Re-kit Air Cyclone Separator	742018
8235	#####	530383			742018
8235	#####	530383	HALDEX COIL BASE OIL SEPE	Base	742018
8235	#####	530383	CYCLONE CONDENSER VAL	Condenser Valve Kit.	742018
8235	#####	530383	HALDEX CONDENSER KIT TOP	(CYCLONE)	742018
8235	#####	530383		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	742018
8235	#####	530383	HALDEX COIL KIT 0500LE 49	Coil Kit	742018
8235	#####	530383	DRAIN VALVE KIT BOTTOM	Valve Kit	742018
8235	#####	527686	Ops Entered - Fault - Body D	replaced damage in seat with new job completed	738858
8235	#####	527686	SPRING RECLINE D/SEAT		738858
8235	#####	525579	Consumables		736172
8235	#####	525579	Ops Entered - Fault - Dash G	remove dash clean conecter fixed same as road test bus ok.	734947
8235	#####	525360	Consumables		735701
8235	#####	525360	Ops Entered - Fault - Elec an	all lights checked. all working o.k.	734947
8235	5/8/2015	525192		Perform & Complete PTSV Bus Safety Inspection completed	734947
8235	5/8/2015	525192		Tension Wheel Nuts done with Alex	734947
8235	5/8/2015	525192		Perform & Complete PTSV Bus Safety Inspection completed	734947
8235	#####	523467	Consumables		732690
8235	#####	523467	BATTERY 12V 200AMP 1100CCA + LHS		732387
8235	#####	523467	Chech chraging system	checked batteries found one collaped not holding and loadremoved and replaced and checked amps at alternator amps with in specs.Checked voltage at batteryes batterys charging at 27.78 volts.road tested and checked again and all ok.	732387
8235	#####	523352	Mechanic entered - Breakd	out 8.00ppm in 9.45pm .fault flat battery. stad park jump start.	732387
8235	#####	523129	Consumables		732155
8235	#####	523129	Mechanic entered - Elec anc	Jumpstart	732155
8235	#####	523072	Engine coolant leak.	replaced botom coolnt hose.tpped up coolant road tested.	732155
8235	#####	521947	Consumables		731858
8235	#####	521947	Body Front_Door Operatio	steam cleaned front door ramp. assisted by ranjith.	731858
8235	#####	521950	Brakes Foot_Brakes Noisy	checked. brakes working o.k. no vibrations felt. assisted by ranjith.	731858
8235	#####	521947	Brakes Foot_Brakes Noisy	checked. both door brakes working. checked foot brakes - working o.k. not noisy. assisted by ranjith.	731858
8235	#####	521946	Brakes Warning Light On	checked no warning light showing. assisted by ranjith.	731858
8235	#####	521212	Consumables		730804
8235	#####	521212	Elec and Light Exterior Ligh	check ok serviceble.	730131
8235	#####	520955	Consumables		730131
8235	#####	520955	Mechanic entered - Elec anc	jump started - battery flat.	730131
8235	#####	520957	Gearbox Driveline Steam cl	Steam cleaned gearbox and road tested - ok.	729942
8235	#####	520972	Engine (None) coolant leak	repair coolant leak (heater hose)	729942
8235	#####	521045	Consumables		730131
8235	#####	521045	Body - Replace seat cushion	Replaced	730131
8235	#####	518815	Accident damage - O/S/R - f	Picked up vehicle from KNOX depot	729942
8235	#####	520955	Consumables		730131
8235	#####	520955	Consumables		730131
8235	#####	520955	LED NO PLATE+EXIT LIGHT		729942
8235	#####	520955		done.	729942
8235	#####	520955		Grease AC Compressor Clutch Bearing	729942
8235	#####	520955		Tension Wheel Nuts To OEM Specification	729942
8235	#####	520955		A Service	729942
8235	#####	520955		Clean A/C filter	729942
8235	4/9/2015	518815	Accident damage - O/S/R - f	Repairs completed at KNOX April 2015 - Units Repair Order 191489	729942
8235	4/1/2015	519366	Replace See Something Say	n/a	729942
8235	#####	517720	Ops Entered - Accident - Vel	Breakdown at 2.00 bus 8235 accident at wellington rd mgravetave van to job rear of bus damaged and diesel leaking from fuel filter . remove damaged panels and clean up broken glass and wait for tow truck return to depot at 4.40	729942
8235	#####	516378	Suspension - OSF airbag leal	Replaced front o/s air bag	728516
8235	#####	516378	0405 ANSAIR FRONT AND REAR AIR BAG	B10M/B7R REAR	728516
8235	3/6/2015	514853		re-tensioned nuts on wheels 3 and 4.	726305
8235	3/5/2015	514712	TYRE NEW 11R22.5N		726305
8235	3/4/2015	514534		Safety Inspection Completed	725406
8235	3/4/2015	514534		Tension Wheel Nuts Alex and Matt done	725406
8235	3/4/2015	514534		Perform & Complete PTSV Bus Safety Inspection complete	725406
8235	3/4/2015	514712	Whls & Tyres - Replace tyre	Replaced & tensioned w/nuts	726305
8235	3/4/2015	514712	Whls & Tyres - Replace tyre	Replaced & tensioned w/nuts	726305
8235	3/4/2015	514400	Passenger Doors (None) re	adjust both doors sensitive edge and inner lock doors ok.	725406
8235	#####	513155	Mechanic entered - Air Syst	- ok.	723852
8235	#####	513155	Exhaust Brake Cylinder Mer	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G148742 Receiving #:151317 Date :2015-02-25	723582
8235	#####	513155	Road tested and checked fo	- ok.	723582
8235	#####	513155	R/R exhaust brake valve and	tig weld line to valve.	723582
8235	#####	512869	Consumables		723695
8235	#####	512869	Ops Entered - Fault - Elec &	check all fault code cant find any fault. bus serviceble.	723582
8235	#####	513153	Ops Entered - Fault - Eng Co	check leak. changed 2 coolant hose steam clenod road tested ok	723582
8235	#####	513155	Mechanic entered - Air Syst	check for leak. exhaust brake leak order part	723582
8235	#####	512468	Consumables		723351
8235	#####	512468	Ops Entered - Fault - Elec &	added coolant and power steering fluid - both low.	723132

8235	#####	494731	Tension Wheel Nuts	700330
8235	#####	494731	Perform & Complete PTSV Bus Safety Inspection	700330
8235	#####	494775	Consumables	0
8235	#####	494775	Consumables	0
8235	#####	494775	Consumables	0
8235	#####	494775	Replace Engine Oil Breather Kit	700330
8235	#####	494775	A Service & Bus Safety Inspection	700330
8235	#####	494775	D-Service & Bus Safety Inspection complete	700330
8235	#####	494775	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)	700330
8235	#####	494775	Consumables	0
8235	#####	494775	AIR FILTER MERC 0500LE E491L	700330
8235	#####	494775	OIL FILTER 1725+0500LE	700330
8235	#####	494775	Grease AC Compressor Clutch Bearing	700330
8235	#####	494775	ENGINE OIL DELO 400LE 15W40 (LU18)	700330
8235	#####	494775	Tension Wheel Nuts to Spec done with Ryan	700330
8235	#####	494776	FILTER TRANSMISSION ZF 4: ZF Transmission Filter	700330
8235	#####	494776	ZF SYNTHETIC GEARBOX OIL ZF Ecofluid A Plus Synthetic Transmission Oil	700330
8235	#####	494776	Service T - Replace Transmission Oil & Filter complete	700330
8235	#####	494775	Consumables	0
8235	#####	494775	Consumables	0
8235	#####	494772	Consumables	0
8235	#####	494772	Consumables	0
8235	#####	494772	Consumables	0
8235	#####	494772	Consumables	0
8235	#####	494775	Consumables	700330
8235	#####	494772	A Service complete	700330
8235	#####	494772	Clean A/C filter	700330
8235	#####	494772	Grease AC Compressor Clutch Bearing	700330
8235	#####	494772	Tension Wheel Nuts To OEM Specification done with ryan	700330
8235	#####	494775	Consumables	0
8235	#####	494775	Consumables	0
8235	#####	494775	A Service	700330
8235	#####	494775	Clean A/C filter	700330
8235	#####	494775	Grease AC Compressor Clutch Bearing	700330
8235	#####	494234	WIPER REFILL SUIT TX800+TX900	699712
8235	#####	494234	Wipers & Washers (None) \ change wiper blade lubricate wiper link rod.	699712
8235	#####	494374	B Service	699712
8235	#####	494374	Replace filter drier	699712
8235	#####	494374	Replace compressor oil	699712
8235	#####	494374	Bottom unloader u/s R&R u	699712
8235	#####	494374	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	699712
8235	#####	494374	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	699712
8235	#####	494374	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	699712
8235	#####	494374	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	699712
8235	#####	494374	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	699712
8235	#####	494374	compressor shows signs of r	699712
8235	#####	494374	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	699712
8235	#####	494374	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	699712
8235	#####	494374	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	699712
8235	#####	494374	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	699712
8235	#####	494374	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	699712
8235	#####	494374	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	699712
8235	#####	493326	Consumables	0
8235	#####	493326	Remove Legacy Poster and i	698927
8235	#####	492108	Removed and replaced by refuellers	697317
8235	#####	492108	FILTER DRIER THERMO KING	697317
8235	#####	492108	COMPRESSOR OIL AIR CON	697317
8235	#####	492108	O RING THERMO KING COMPRESSOR	697317
8235	#####	492108	UNLOADER COIL LS391 THERMOKING	697317
8235	#####	492069	Consumables	0
8235	#####	492069	Complete AM/FM radio sal; did radio camping	697317
8235	#####	492102	Check boost pump condition	697317
8235	#####	492102	Check & replace electric motor brushes	697317
8235	#####	492102	Replace compressor oil	697317
8235	#####	492102	Replace filter drier	697317
8235	#####	492102	D Service	697317
8235	#####	492108	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	697317
8235	#####	492108	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	697317
8235	#####	492108	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	697317
8235	#####	492108	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	697317
8235	#####	492108	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	697317
8235	#####	492108	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	697317
8235	#####	492108	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	697317
8235	#####	492108	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	697317
8235	#####	492108	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	697317
8235	#####	492108	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	697317
8235	#####	492108	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	697317
8235	#####	492102	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	697317
8235	#####	492102	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	697317
8235	#####	492102	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	697317
8235	#####	492102	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	697317
8235	#####	492102	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	697317
8235	#####	492102	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	697317
8235	#####	492102	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	697317
8235	#####	492102	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	697317
8235	#####	492102	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	697317
8235	#####	492102	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	697317
8235	#####	492102		697317
8235	#####	491747	Ops Entered - Fault - Passen adjust rear passenger door sensitive edge bus ok.	696299
8235	#####	491663	Service Completed	696299

8235	#####	491466	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals complete	696299
8235	#####	491466	Check oil level in transmission - top up if required complete	696299
8235	#####	491466	Check air cleaner	696299
8235	#####	491466	Replace angle drive oil complete	696299
8235	#####	491466	Inspect radiator and charge air cooler for dirt - clean complete	696299
8235	#####	491666	Passenger Doors - Adjust rei: complete	696299
8235	#####	491666	Engine - Steamclean the bus complete	696299
8235	#####	491557	DISC PAD SET SCANIA MB0500	696299
8235	#####	491466	R/R rear brake pads and tensioned wheel nuts with Shalen.	696299
8235	#####	491466	Replace pre and main fuel filters complete	696299
8235	#####	491466	Replace air dryer canister clean silence and drain reservoir complete	696299
8235	#####	491466	Test coolant level - top up if required to equate to 37C frost protection	696299
8235	#####	491466	Replace power steering filter and check level (Replace oil if required) complete	696299
8235	#####	491466	FUEL FILTER MERC 0500LE	696299
8235	#####	491466	FUEL FILTER 0500LE	696299
8235	#####	491466	AIR DRYER CANISTER VOLVO+ NL202	696299
8235	#####	491466	POWER STEERING FILTER VOLVO	696299
8235	#####	491557	Brakes - Replace rear brake Replaced & tensioned w/nuts with Shalen	696299
8235	#####	489012	Consumables	696343
8235	#####	489012	TOP ALT BELT 0500LE Creditor #:GB-BUR001 BURSON AUTO PARTS P/O #:G144247 Receiving #:146078 Date :2014-10-04	0
8235	#####	489012	WEDGE GLOBE INSTRUMENT 24V SW	693276
8235	#####	489012	Mechanic entered - Elec & L change os indicater globe and parking light globe.	692925
8235	#####	489012	GLOBE 24V 21W SINGLE CONTACT	692925
8235	#####	488500	Perform & Complete PTSV Bus Safety Inspection	692664
8235	#####	488500	Tension Wheel Nuts	692664
8235	#####	488500	GLOBE H1 24V 70W	692664
8235	#####	488500	Tension Wheel Nuts	692664
8235	#####	488500	Perform & Complete PTSV Bus Safety Inspection	692664
8235	#####	488374	BRAKE BOOSTER REAR N/S MB0500LE 50G2546K	692664
8235	#####	488374	Air System Leaking - air boi Checked air leak removed & replaced rear OS brake chamber repair 1 air hose connector checked for leak OK/r/tested all OK	692664
8235	#####	487418	Mechanic entered - Elec & L changed blown globe.	691197
8235	#####	487418	GLOBE INST 24V 2W (17063)	691197
8235	#####	485621	Service Re-tensioned	688264
8235	#####	485621	Re-tensioned	688264
8235	#####	485480	VALVE EXTENSION-130mm Metal type	688264
8235	#####	485376	AIR FILTER MERC 0500LE E491L	688264
8235	#####	485480	Whls & Tyres - Replace tyre: Replaced	688264
8235	#####	485480	Whls & Tyres - Replace tyre: Replaced	688264
8235	#####	485480	Fit Tyre Valve Extensions To Fitted	688264
8235	#####	485151	Mechanic entered - Body & replace missing rubbish bin.	687679
8235	#####	485151	15LTR RUBBISH BINS	687679
8235	#####	485480	Air System - Replace air flite Replaced	688264
8235	#####	485376	Tension Wheel Nuts To OEM Specification	687679
8235	#####	485376	Complete top nick done bottom	687679
8235	#####	485376	A Service	687679
8235	#####	485376	Clean A/C filter	687679
8235	#####	485376	Grease AC Compressor Clutch Bearing	687679
8235	#####	485376	Tension Wheel Nuts To OEM Specification	687679
8235	9/9/2014	484270	DECAL AUTHORISED OFFICER	687359
8235	9/5/2014	484270	Remove old decal and fit ne Replaced	686753
8235	9/4/2014	483811	BRAIDED COMPRESSOR PIPE 0500LE	686366
8235	9/4/2014	483811	Mechanic entered - Air Syst: check air leak damage air compresure flaxi hose change flaxi hose.bus ok.	686366
8235	#####	482503	Ops Entered - Fault - Elec & Check ok	684802
8235	#####	482499	Ops Entered - Fault - Fuel Er Check Ok	684802
8235	#####	482600	Ops Entered - Fault - Fuel Er Take fuel to Stud Park checked tank and still 1/2 full fuel gauge playing up	684802
8235	#####	481207	inspected bus as per safety inspection	683792
8235	#####	481207	Tension Wheel Nuts	683792
8235	#####	481207	Perform & Complete PTSV Bus Safety Inspection	683792
8235	8/9/2014	479106	GLOBE 24V 21W SINGLE CONTACT	681064
8235	8/9/2014	479106	Mechanic entered - Elec & L changed blown globe - (nsf) side indicator.	681064
8235	8/7/2014	478598	15LTR RUBBISH BINS	680734
8235	8/6/2014	478598	Gearbox software replace Replaced by east cost Knocks - bring bus to depot	680522
8235	8/5/2014	478264	GEARBOX MECH Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G142021 Receiving #:143933 Date :2014-08-07 going into panic mode	680734
8235	8/5/2014	478264	Gearbox - Gearbox goes intr: Repaired by Volgren 05/08/14	680522
8235	#####	477175	Ops Entered - Fault - Passen Checked all doors working O/K	680366
8235	#####	476155	Service Checked all doors working O/K	679407
8235	#####	476155	Service Completed	679407
8235	#####	475827	Gearbox No Retarder	679226
8235	#####	475827	Ops Entered - Fault - Body & Checked OK	679226
8235	#####	475827	Mechanic entered - Brakes (road test and check retarder with Ranjith it's ok.check front suspension by shaker all ok change front brake pades balance new front tyre road test bus ok.	679226
8235	#####	475827	road test and check retarder with Ranjith it's ok.check front suspension by shaker all ok change front brake pades balance new front tyre road test bus ok.	679226
8235	#####	475827	DISC PAD SET SCANIA MB0500	679226
8235	#####	474550	Ops Entered - Fault - Brakes Test drove bus and found retarder n/w.Switched retarder on Accelerator mode.Test drove and checked ok.Need to rebook bus to check normal retarder function.	678884
8235	#####	473561	Mechanic entered - Steering added power steering fluid - low.	677613
8235	7/9/2014	473222	Mechanic entered - Elec & L Replace indicator light globe	676949
8235	7/9/2014	473222	GLOBE 24V 21W SINGLE CONTACT	676949
8235	7/4/2014	472529	Ops Entered - Fault - Brakes check front and rear brake road test bus ok.	676021
8235	#####	471724	Ops Entered - Fault - Brakes R/tested checked OK fuelled & parked	676021
8235	#####	470192	Fit Wheel Nut Pointers to al Fitted	674811
8235	#####	470192	MERC RADIATOR MOUNT BUSHING	674811
8235	#####	470192	Body & Acc Mirrors Exterio Secured	674811
8235	#####	470192	Brakes Foot brake valve leal Replaced	674811
8235	#####	470192	FOOT BRAKE VALVE Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G140425 Receiving #:142281 Date :2014-06-24	674811
8235	#####	470192	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	674811
8235	#####	470192	Steering wheel cover loose repaired	674811
8235	#####	470192	Radiator mount broken replaced	674811
8235	#####	469944		674557

8235	#####	469944	Tension Wheel Nuts	674557
8235	#####	469944	Perform & Complete PTSV Bus Safety Inspection	674557
8235	#####	469944	Tension Wheel Nuts	674557
8235	#####	469077	FRONT RELAY PROPORTIONAL VALVE 0500LE	673654
8235	#####	469077	Air Leaking from valve next change front brake propotional value adjust driver compartment door opener.road test bus ok.	673654
8235	#####	468830	BELT BOTTOM ALTERNATOI	673654
8235	#####	468830	A/C BELT 0500 BENZ	673654
8235	#####	468830	ADJUSTER IDLER PULLEY	673654
8235	#####	468830	Elec & Light - Replace main readjusted levelling valve r/tested bus OK	673375
8235	#####	468830	Elec & Light - Replace main Changed belts 2 idler pulleys adjust belt adjust all levelling valve height need to r/test & readjust c/o	673375
8235	6/5/2014	467367	CYCLONE CONDENSER VAL Condenser Valve Kit.	673375
8235	6/5/2014	467367		673375
8235	6/5/2014	467367	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	673375
8235	6/5/2014	467367	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	673375
8235	6/5/2014	467367	HALDEX COIL KIT 0500LE	673375
8235	6/5/2014	467367	DRAIN VALVE KIT BOTTOM	673375
8235	6/5/2014	467367	HALDEX COIL BASE OIL SEPE Base	673375
8235	6/4/2014	466798	MERC - WORN - POS 34 - 11 Creditor #:GB-TYR002 TYRES4U P/O #:G139685 Receiving #:141561 Date :2014-06-05 REPLACE WITH NEW 35867RT606	673375
8235	6/3/2014	466798	Whls & Tyres - Replace tyre Replaced	672924
8235	6/3/2014	466657	A/C BELT 0500 BENZ	672924
8235	6/3/2014	466657	BELT BOTTOM ALTERNATOI	672924
8235	6/3/2014	466657	OIL PIPE FILTER TO BLOCK 0	672924
8235	6/2/2014	466662	Whls & Tyres - Tyre 3 needs replacing	672924
8235	6/2/2014	466662	Whls & Tyres Worn pos 3 & Replaced pos 3 & 4 tyres and tensioned wheels	672924
8235	6/2/2014	466657	Engine Belt came off and br Found A/C roller tensioner looserremoved alternator belt/fan drive belt and replaced new belt.Adjusted belts.Replaced broken oil pipe with new one.	672910
8235	6/2/2014	466609	A Service	672910
8235	6/2/2014	466609	Clean A/C filter	672910
8235	6/2/2014	466609	Grease AC Compressor Clutch Bearing	672910
8235	6/2/2014	466609	A Service	672910
8235	6/2/2014	466609	Tension Wheel Nuts To OEM Specification - done with Nick	672910
8235	#####	465978	Brakes Shuddering or jurkir check front brake road test bus ok.	672049
8235	#####	465157		671256
8235	#####	465157	SYNTHETIC GEAR LUBRICANT FM 75W-140 (LU6)	671256
8235	#####	465157	Service	671256
8235	#####	463192	Wipers & Washers Worn	669467
8235	#####	463192	MANUAL DRAIN VALVE	669467
8235	#####	463192	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	669467
8235	#####	463192	Ops Entered - Fault - Suspen road test ok. change suspension control valve road test bus ok.	669467
8235	#####	463192	WHEEL ARCH BRUSH 2.5MTR	669467
8235	#####	463192	WHEEL ARCH BRUSH RUBBER (Sold P/M)	669467
8235	#####	463192	Brakes RETARDER NOT WDO road test retader ok.	669467
8235	#####	463192	Brakes Severe sticky ok	669467
8235	#####	463192	ECAS LEVELLING VALVE COP Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G138933 Receiving #:140756 Date :2014-05-16	669467
8235	#####	463192	Ops Entered - Fault - Suspen check air suspension electrical system remove suspension control valve air leak from exhaust order parts c/o	669467
8235	#####	463192	Body & Acc Drivers Seat Mt Repaired drivers seat and replaced O/S/F wheel arch rubber and brush	669467
8235	#####	463348	Remove Fair Evasion A3 Pos Replaced Myki Poster	669467
8235	#####	463192	OVERFLOW VALVE 0500LE	669467
8235	#####	463192	Ops Entered - Fault - Suspen checking out suspensionfound no air in one tank	669467
8235	#####	462434	FUSE BLADE 10AMP	668540
8235	#####	462434	GLOBE DASH B7L	668540
8235	#####	462434	Mechanic entered - Elec & L Done	668540
8235	#####	462434	Elec & Light FM RADIO NO traced problem to missing fuse replaced and working	665303
8235	#####	459499	Body & Acc Drivers Seat Be replaced lap seat belt and seat belt stork - damaged.	665303
8235	#####	459499	SEAT BELT BUCKLE TWIN WIRE GREY	665303
8235	#####	459499	SEAT BELT R/H	665303
8235	#####	459434	Tension Wheel Nuts	665303
8235	#####	459434	Perform & Complete PTSV Bus Safety Inspection	665303
8235	#####	459499	Body & Acc Drivers Seat Be Ordered seat belt	662235
8235	4/9/2014	457109	Ops Entered - Breakdown - f fixed exhaust brake and adjust throtel road test bus ok	662175
8235	4/8/2014	456900	Perform Campaign 1_14 Scd N/A	662175
8235	4/8/2014	456970	Ops Entered - Breakdown - f Test drove and fopund retarder n/w.Turned on to accelerator mode.Test drove ok.	662175
8235	4/7/2014	456847	Remove A3 Marketing Postr replaced	659228
8235	#####	455010	Passenger Doors - Secure frn Tightened & secured	658596
8235	#####	454443	Passenger Doors rear Doo fixed door brake and fixed osr wheel speed sensor road test bus ok.	658596
8235	#####	454602	Mechanic entered - Elec & L replace headlight globe	657776
8235	#####	453712	ENGINE OIL DELO 400LE 15W40	657776
8235	#####	453712	Tension Wheel Nuts to Spec	657776
8235	#####	453712	A Service & Bus Safety Inspection	657776
8235	#####	453712	D-Service & Bus Safety Inspection	657776
8235	#####	453712	Grease AC Compressor Clutch Bearing	657776
8235	#####	453712	Replace Engine Oil Breather Kit	657776
8235	#####	453712	ENGINE OIL BREATHER KIT 0500LE [EAS500M05]	657776
8235	#####	453712	AIR FILTER MERC 0500LE	657776
8235	#####	453712	OIL FILTER 1725+0500LE	657776
8235	#####	453712	Tension Wheel Nuts To OEM Specification	657776
8235	#####	453712	A Service	657776
8235	#####	453712	Clean A/C filter	657776
8235	#####	453712	Grease AC Compressor Clutch Bearing	657776
8235	#####	452413	UNREPORTED - NSR corner Refit h/light surround fleet # vent NSR top & mopped floor of bus	656890
8235	#####	452840	Perform & Complete PTSV Bus Safety Inspection	656890
8235	#####	452840	Tension Wheel Nuts	656890
8235	#####	452840	Perform & Complete PTSV Bus Safety Inspection	656890
8235	#####	452937	Vandalism - Clean graffiti - f cleaned	656890
8235	#####	452937	Body & Acc - Secure all loww cleaned	656890
8235	#####	452413	UNREPORTED - NSR corner Painted OS front headlight surround panel & pod vents	656890
8235	#####	452413	UNREPORTED - NSR corner Removed OSF h/light surround repaired primed prep make color Sharma to paint	656890
8235	#####	452413	BODY SHOP SUPPLIES	656890

8235	#####	437767	HALDEX COIL BASE OIL SEPE Base	636001
8235	#####	437767	CYCLONE CONDENSER VALV Condenser Valve Kit.	636001
8235	#####	437767	HALDEX COIL KIT 0500LE Coil Kit	636001
8235	#####	437485	FUEL FILTER 0500LE	636001
8235	#####	437485	AIR DRYER CANISTER VOLVO+ NL202	636001
8235	#####	437485	POWER STEERING FILTER VOLVO	636001
8235	#####	437485	RSI Inspection	636001
8235	#####	437485	Replace air dryer cansiter clean silence and drain reservoir	636001
8235	#####	437485	Test coolant level - top up if required to equate to 37C frost protection	636001
8235	#####	437485	Replace power steering filter and check level (Replace oil if required)	636001
8235	#####	437485	Replace pre and main fuel filters	636001
8235	#####	437485	FUEL FILTER MERC 0500LE	636001
8235	#####	437565	Mechanic entered - Annual done	636001
8235	#####	437565	Annual Licencc	636001
8235	#####	436121	SIDEWALL Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G132202 Receiving #:134049 Date :2013-12-02 SCRAPPED	636388
8235	#####	435467	BRAZILLIAN MIRROR RH	634766
8235	#####	436554	Perform Campaign as per In Completed.	634766
8235	#####	426121	Whls & Tyres - SCRAP TYRES SIDEWALL DAMAGED SCRAPPED	634424
8235	#####	435467	o/s/ mirror missing and arm starighten arm and fit new mirror	632804
8235	#####	434782	Tension Wheel Nuts done	631445
8235	#####	434782	Perform & Complete PTSV Bus Safety Inspection don e	631445
8235	#####	434354	Fit New Myki Decal as Per P Fit New Myki Decal as Per TV fitting instructions	630792
8235	#####	433751	Ops Entered - Breakdown - I ??? change over	628895
8235	#####	433294	Mechanic entered - Steering topup power steering oil check leak ok	628895
8235	#####	433079	WORN - POS 456 - 11 R22.5 Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G131445 Receiving #:133013 Date :2013-11-06 REPLACE WITH NEW	628895
8235	#####	433079	Whls & Tyres - Replace tyre Replaced	628895
8235	#####	433001	Whls & Tyres - Tyre pos 4 lo ANDREW NIKOLZEV changed pos 4 5 6 tyres.	628895
8235	#####	433002	A Service complete	628895
8235	#####	433002	Clean A/C filter done	628895
8235	#####	433002	Grease AC Compressor Clutch Bearing	628895
8235	#####	433002	ANDREW NIKOLZEV A Service complete	628895
8235	#####	433002	Tension Wheel Nuts To OEM Specification done with Andrew	628895
8235	#####	430986	AIR CON REFRIDGERANT	626964
8235	#####	430986	COMPRESSOR OIL AIR CON	626964
8235	#####	430986	FILTER DRIER THERMO KING	626964
8235	#####	431427	BY LAW PICKUP/SET DOWN DECAL	626215
8235	#####	431427	CUSTOMER ENQUIRY DECAL	626215
8235	#####	431427	PLEASE ASSIST DRIVER DECAL	626215
8235	#####	431427	PASSENGERS REQUIRED BY LAW DECAL	626215
8235	#####	431427	DRIVERS NO DEFECT CHECKLIST DECAL	626215
8235	#####	431427	WARNING MAXIMUM HEIGHT DECAL	626215
8235	#####	431427	EMERGENCY PROCEDURE DECAL	626215
8235	#####	431427	LICENSED TO CARRY DECAL	626215
8235	#####	431427	NO SMOKING DECAL	626215
8235	#####	431427	CCTV SURVEILLANCE DECAL	626215
8235	#####	431427	Perform sticker audit on vel Removed & replaced	626215
8235	#####	430679	Remove A3 Poster 15/8Fit F Completed by operations	625215
8235	#####	430918	CONTACT BLOCK DOOR PUSH SWITCH	625215
8235	#####	430986	C Service	625215
8235	#####	430986	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	625215
8235	#####	430986	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	625215
8235	#####	430986	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clay; check mounting brackets; check electrical connections; check condensor fan grills	625215
8235	#####	430986	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	625215
8235	#####	430986	Topped up refrigernat REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	625215
8235	#####	430986	Topped up compressor oil COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	625215
8235	#####	430986	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	625215
8235	#####	430986	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	625215
8235	#####	430986	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	625215
8235	#####	430986	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	625215
8235	#####	430986	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	625215
8235	#####	430918	Body & Acc - Replace door f Replaced	625215
8235	#####	430769	Body & Acc - front doors stit assist	625215
8235	#####	430769	Body & Acc - front doors stit replace door switch	625215
8235	#####	429945	GLOBE H1 24V 70W	624829
8235	#####	429945	Diff & Hubs Replace oil done	624829
8235	#####	429930	Ops Entered - Breakdown - I Repair & adjusted front door	624470
8235	#####	429930	Elec & Light - Replace NS he replaced	624470
8235	#####	429725	Mechanic entered - Eng Coc added coolant.	624130
8235	#####	428241	Perform & Complete PTSV Bus Safety Inspection	622758
8235	#####	428241	Tension Wheel Nuts	622758
8235	#####	428241	Perform & Complete PTSV Bus Safety Inspection	622758
8235	#####	427030	BELT BOTTOM ALTERNATOR MERC 0500LE	621442
8235	#####	427030	Elec & Light - Replace altern Replaced	621442
8235	#####	426509	BELT BOTTOM ALTERNATOR MERC 0500LE	621442
8235	#####	426509	Mechanic entered - Allison I replaced bottom aluternater belt.	621442
8235	#####	426509	Mechanic entered - Brakes r adjusted 6 way valve. r/tested.	621442
8235	#####	426509	Mechanic entered - Brakes r checked brake pads	621442
8235	#####	424508	Brake Interlock Re-install to Completed	619055
8235	9/9/2013	424296	Ops Entered - Fault - Brakes Checked all brakes r/tested OK	618822
8235	9/7/2013	423483	Remove A3 Marketing Posti Completed	617335
8235	9/7/2013	424256	Elec & Light - OSF top park I Checked OK	618822
8235	9/7/2013	424256	Body & Acc Passenger Seat Replaced seat cushion	618822
8235	#####	422773	Organise Mbenz Recall SM9 completed	617212
8235	#####	422523	Headlights very dim hard to Checked OK	616731
8235	#####	417242	Accident# 37777 - OSR dam Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G127600 Receiving #:129923 Date :2013-08-22	615939
8235	#####	420332	Perform & Complete PTSV Bus Safety Inspection	614174
8235	#####	420332	Tension Wheel Nuts	614174

8235	#####	420332	Perform & Complete PTSV Bus Safety Inspection	614174
8235	#####	419883	Body & Acc - Fit passenger s Replace seat	612738
8235	8/9/2013	418890	FLAT - POS 3 - 11 R22.5 - NE Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G127985 Receiving #:129383 Date :2013-08-09 REPAIR OR REPLACE WITH NEW	612738
8235	8/9/2013	419325	DASH GLOBE 24V 1.2W WEDGE GLOBE	612738
8235	8/8/2013	419325	Elec & Light - Replace globe: Replaced	612738
8235	8/7/2013	419085	Whls & Tyres - Replace pos : Replaced wheel	612738
8235	8/7/2013	418890	Whls & Tyres - Replace tyre Replaced	612738
8235	8/7/2013	418929	WEDGE GLOBE INSTRUMENT 24V SW	612738
8235	8/6/2013	418781	Gearbox No Retarder rand working ok	612729
8235	8/6/2013	418929	Elec & Light - Replace NSF p Replaced	612738
8235	8/6/2013	418782	Replace Engine Oil Breather Kit	612729
8235	8/6/2013	418782	ENGINE OIL BREATHER KIT 0500LE	612729
8235	8/6/2013	418782	Grease AC Compressor Clutch Bearing	612729
8235	8/6/2013	418782	AIR FILTER MERC 0500LE	612729
8235	8/6/2013	418782	ENGINE OIL DELO 400LE 15W40	612729
8235	8/6/2013	418782	Tension Wheel Nuts to Spec	612729
8235	8/6/2013	418782	OIL FILTER 1725+0500LE	612729
8235	8/6/2013	418782	A Service & Bus Safety Inspection	612729
8235	8/6/2013	418782	D-Service & Bus Safety Inspection	612729
8235	8/6/2013	418782	A Service	612729
8235	8/6/2013	418782	Clean A/C filter	612729
8235	8/6/2013	418782	Grease AC Compressor Clutch Bearing	612729
8235	8/6/2013	418782	Tension Wheel Nuts To OEM Specification	612729
8235	#####	417242	Accident# 37777 - OSR dam ECTB	612729
8235	7/1/2013	412643	Perform & Complete PTSV Bus Safety Inspection	604787
8235	7/1/2013	412643	Tension Wheel Nuts	604787
8235	7/1/2013	412643	Perform & Complete PTSV Bus Safety Inspection	604787
8235	#####	410501	ALTERNATER MOUNT BUSH	600764
8235	#####	410501	CRANK DRIVE BELT 0500LE MERC	600764
8235	#####	410325	ROCKER COVER GASKET OS Rocker Cover Gasket	600293
8235	#####	410325	Adjust Tappets	600293
8235	#####	410501	Elec & Light - Alternator low Fitted new bushes OK and replaced fan belt	600453
8235	#####	410501	Elec & Light - Alternator low Fitted new bushes OK and replaced fan belt	600453
8235	#####	410310	Bus Safety Inspection	600293
8235	#####	410310	FILTER TRANSMISSION ZF 4: ZF Transmission Filter	600293
8235	#####	410310	ZF SYNTHETIC GEARBOX OIL ZF Ecofluid A Plus Synthetic Transmission Oil	600293
8235	#####	410310	Service T - Replace Transmission Oil & Filter	600293
8235	#####	410326	A Service	600293
8235	#####	410326	A Service	600293
8235	#####	410326	Clean A/C filter	600293
8235	#####	410326	Grease AC Compressor Clutch Bearing	600293
8235	#####	410326	Tension Wheel Nuts To OEM Specification	600293
8235	6/3/2013	408539	GLOBE S/CONTACT 24V-10W	596766
8235	6/1/2013	408333	Perform & Complete PTSV Bus Safety Inspection	596252
8235	6/1/2013	408333	Tension Wheel Nuts	596252
8235	6/1/2013	408333	Perform & Complete PTSV Bus Safety Inspection	596252
8235	6/1/2013	408539	Elec & Light - Replace bus st Replaced	596766
8235	6/1/2013	408539	Body & Acc - fit yellow floor Fitted	596766
8235	6/1/2013	408536	Body & Acc - Battery box ha Replaced	596766
8235	#####	407950	PUNCTURE - POS 1 - 11 R22 Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G125059 Receiving #:126110 Date :2013-06-03 REPAIR OR REPLACE WITH NEW	596766
8235	#####	407950	Whls & Tyres - Replace tyre Replaced	595643
8235	#####	408041	Whls & Tyres - Replace tyre Replaced	595788
8235	#####	408041	Whls & Tyres - Replace tyre Replaced	595788
8235	#####	408077	Passenger Doors Door Brak Checked OK	595643
8235	#####	407854	GLOBE H1 24V 70W	595643
8235	#####	408077	Brakes Shudderingneeds to Checked brake pads and rotor r/tested	595643
8235	#####	407770	Re-kit Air Cyclone Separator	595643
8235	#####	407770	HALDEX COIL KIT 0500LE Coil Kit	595643
8235	#####	407770	DRAIN VALVE KIT BOTTOM Valve Kit	595643
8235	#####	407770	HALDEX COIL BASE OIL SEPE Base	595643
8235	#####	407770	CYCLONE CONDENSER VAL Condenser Valve Kit.	595643
8235	#####	407770	Re-kit Air Cyclone Separator	595643
8235	#####	407757	Perform Campaign 01_13 C AUDITED	595643
8235	#####	407854	Drv entered - Elec & Light H- Fred replaced	595643
8235	#####	405126	Wipers & Washers - Replace Replaced	588885
8235	#####	404911	L.E.D SIDE MARKER PERE REJ/AMBER	588885
8235	5/9/2013	404756	WEDGE GLOBE INSTRUMENT 24V SW	588731
8235	5/9/2013	404911	Elec & Light - Replace clear Replaced	588885
8235	5/9/2013	404690	L.E.D.GLOBE FOR SWF SWITCH	588731
8235	5/9/2013	404690	GLOBE INST 24V 2W	588731
8235	5/8/2013	404543	Perform & Complete PTSV Bus Safety Inspection	588145
8235	5/8/2013	404543	Tension Wheel Nuts	588145
8235	5/8/2013	404543	Perform & Complete PTSV Bus Safety Inspection	588145
8235	5/8/2013	404690	Elec & Light - REPLACE DAS Replaced	588731
8235	5/8/2013	404756	Elec & Light - Replace OSF p Replaced	588731
8235	5/8/2013	404542	Drv entered - Brakes Shudd Checked r/tested & checked OK	588145
8235	5/5/2013	404055	Complete Campaign 16/12 : Completed	587347
8235	#####	403327	Body & Acc - Replace missin Replaced	586114
8235	#####	403080	Elec & Light - Replace fluro 1 Replaced	585026
8235	#####	402387	RELAY VALVE	583397
8235	#####	402387	Brakes - Replace rear brake Replaced relay valve & parked	583397
8235	#####	402175	Body & Acc - Adjust to OS re Replaced clamping plate bolt adjusted claw catches	583397
8235	#####	402133	A Service	583397
8235	#####	402133	A Service	583397
8235	#####	402133	Clean A/C filter	583397
8235	#####	402133	Grease AC Compressor Clutch Bearing	583397
8235	#####	402133	Tension Wheel Nuts To OEM Specification	583397

8235	#####	400795	Brakes front grabbing	Checked all Ok no fault found	580938
8235	4/4/2013	399670		Perform & Complete PTSV Bus Safety Inspection	579384
8235	4/4/2013	399670		Tension Wheel Nuts	579384
8235	4/4/2013	399670		Perform & Complete PTSV Bus Safety Inspection	579384
8235	4/4/2013	399911	Eng Cool - radiator fan noise	Checked OK servicable checked angle drive oil	579527
8235	4/2/2013	399651	Elec & Light - Bus wont start	Tulla jump started 25/03/13	579023
8235	#####	396085	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE		571197
8235	3/8/2013	396320		Perform & Complete PTSV Bus Safety Inspection	570925
8235	3/8/2013	396320		Tension Wheel Nuts	570925
8235	3/8/2013	396320		Perform & Complete PTSV Bus Safety Inspection	570925
8235	3/8/2013	396581	Steering drag link U/S	Replaced	571076
8235	3/8/2013	396581	Steering drag link U/S	Replaced	571076
8235	3/8/2013	396629	Air Cond - A/C belt cracked	OK	571076
8235	3/8/2013	396629	Passenger Doors - Adjust re: OK		571076
8235	3/8/2013	396629	Rear Door not closing bus st	OK	571076
8235	3/7/2013	396085	DRAGLINK	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G121263 Receiving #:121997 Date :2013-03-07	570617
8235	3/7/2013	396085	SHUTTLE VALVE	Creditor #:MUL001 MULTISPARES LTD P/O #:G121269 Receiving #:122000 Date :2013-03-07	570617
8235	3/6/2013	396085	Brakes - check brakes	R/tested wobbling when braking sometime c/o	570617
8235	3/6/2013	396085	Brakes - check brakes	R/tested & assisted Subu to check brakes & steering	570617
8235	#####	394552	PARK BRAKE VALVE 0500LE		568111
8235	#####	394552	MANUAL DRAIN VALVE		568111
8235	#####	394814		Tension Wheel Nuts to Spec	568111
8235	#####	394814		D-Service & Bus Safety Inspection	568111
8235	#####	394814		A Service & Bus Safety Inspection	568111
8235	#####	394814	ENGINE OIL DELO 400LE 15W40		568111
8235	#####	394814	AIR FILTER MERC 0500LE		568111
8235	#####	394814	OIL FILTER 1725+0500LE		568111
8235	#####	394814		Grease AC Compressor Clutch Bearing	568111
8235	#####	394814	ENGINE OIL BREATHER KIT 0500LE		568111
8235	#####	394814		Replace Engine Oil Breather Kit	568111
8235	#####	394814		Tension Wheel Nuts To OEM Specification	568111
8235	#####	394814		Grease AC Compressor Clutch Bearing	568111
8235	#####	394814		Clean A/C filter	568111
8235	#####	394814		A Service	568111
8235	#####	394825	Passenger Doors - Front doc	Tulla found hinge loose and door stuck released air to doors took hinge offrefitted lubed track and built air up again 18/02/13	568071
8235	#####	394552	Ops Entered - Fault - Brakes	R/tested checked rear brake chambers OK checked all brakes OK fitted new air tank drain valve leaking fitted new park brake valve leaking r/tested OK bus back in service	568071
8235	#####	394674	Breakdown - Cnr Springvale	Van 619. Jacked up bus released h/brake & checked wheel spinning freely OK escort bus back to w/ship no issues on way back (replaced park brake valve)	568071
8235	#####	393768	WORN - POS 23456 - 11 R2	Creditor #:BEA001 BEAUREPARES P/O #:K120525 Receiving #:121273 Date :2013-02-21 REPLACE WITH NEW	566865
8235	#####	393768	Whls & Tyres - Replace tyre	replaced	566440
8235	#####	393874	Whls & Tyres - Replace tyre	Replaced & torqued w/nuts	566440
8235	#####	392728	BLADE WIPER 1MTR		564221
8235	#####	392728	WIPER WASHER HOSE+JET ASSY		564221
8235	#####	392728	Wipers & Washers - OS wiper	Replaced OS wiper blade & washer jet assembly reprivetted blade assembly clip to wiper arm	564221
8235	#####	392749	Vandalism - Remove graffiti	removed	564221
8235	#####	392549	AMBER REFLECTOR		563931
8235	2/8/2013	392549	Elec & Light - Replace OS mi	Replaced	563657
8235	2/6/2013	391968	NARVA 24V REVERSING BUZZER		562726
8235	2/6/2013	391968	GLOBE INST 24V 2W		562726
8235	2/6/2013	391968	DASH GLOBE 24V 1.2W WEDGE GLOBE		562726
8235	2/6/2013	392148	Body & Acc - Refit OSR b/ba	Refitted	563113
8235	2/5/2013	391968	Elec & Light - Replace rever:	Replaced	562726
8235	2/5/2013	391968	Elec & Light - replace globes	Replaced	562726
8235	2/4/2013	390452	90* ELBOW	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G119416 Receiving #:120421 Date :2013-02-04	562442
8235	2/1/2013	390452	Brakes - Rear left wheel bral	Removed NS rear brake caliper overhauled fitted back caliper & disc brakepads adjusted brakes fitted wheels & torqued w/nuts. Fitted OS rear discpads adjusted brakes fitted new elbow for brake light switch fitted wheels & torqued w/nuts. ALAN checked my work and confirmed all is good put all tools in there designated p	562281
8235	2/1/2013	390452	DISC PAD SET SCANIA MB0500		562281
8235	#####	390452	L/H BRAKE CALIPER	Creditor #:MUL001 MULTISPARES LTD P/O #:G119548 Receiving #:120303 Date :2013-01-30	562281
8235	#####	390452	BRAKE BOOSTER REAR O/S MB0500LE		562281
8235	#####	390452	BRAKE BOOSTER REAR N/S MB0500LE		562281
8235	#####	390452	Brakes - Rear left wheel bral	Removed NS & OS rear tyres brake boosters removed air fittings from old brake boosters & fitted on to new brake boosters fitted back rear brake boostersremoved NS & OS rear brake pads NS rear caliper too tight very little movement NS rear piston dust cover damaged ALAN checked & confirmed that NS rear caliper nee	562281
8235	#####	389689		Perform & Complete PTSV Bus Safety Inspection	562281
8235	#####	389689		Tension Wheel Nuts	562281
8235	#####	389689		Perform & Complete PTSV Bus Safety Inspection	562281
8235	#####	389320	GAS STAY 450N 710MM EXT LENGTH		561890
8235	#####	389320	Body & Acc - Replace rear h	Replaced	561890
8235	1/3/2013	386943	WHEEL ARCH BRUSH 2.5MTR		555473
8235	1/3/2013	386943	GIVE WAY SIGN (SMALL)		555473
8235	1/3/2013	386943	NO SMOKING GOV REG DECAL		555473
8235	1/3/2013	386943	HINGE DRIVERS COMPARTMENT		555473
8235	1/2/2013	386943	Body & Acc - Secure drivers	replaced with new	555204
8235	1/2/2013	386943	Body & Acc - Replace interic	completed	555204
8235	1/2/2013	386943	Body & Acc - Replace w/arcl	replaced both n/s o/s with new	555204
8235	1/2/2013	386943	Body & Acc - Rear step edge	completed	555204
8235	1/2/2013	386943	Body & Acc - Replace Give v	completed	555204
8235	1/2/2013	386943	Body & Acc - Polish exterior	completed	555204
8235	1/2/2013	386943	Body & Acc - Secure rear b/l	completed	555204
8235	1/2/2013	386943	Body & Acc - Clean w/chair	completed	555204
8235	1/2/2013	386943	Body & Acc - Replace safety	replaced	555204
8235	1/2/2013	386943	Body & Acc - Clean air condi	completed	555204
8235	1/2/2013	386943	Body & Acc - Secure all low	tighten and replaced all missing bolts	555204
8235	1/2/2013	386943	Body & Acc - Replace front c	replaced with new	555204
8235	1/1/2013	387025	Engine - S/clean engine	Cleaned	555204
8235	#####	386981	Breakdown - Chelsea Station	C/O bus 8623. return to depot fix oil leak from p/steering pump pressure line s/cleaned engine r/tested checked leak bus OK	553560
8235	#####	386210		Tension Wheel Nuts done done	553560
8235	#####	386210		Perform & Complete PTSV Bus Safety Inspection done done	553560
8235	#####	386210		Perform & Complete PTSV Bus Safety Inspection done done	553560
8235	#####	386409	drivers fan barely working,	Checked OK	553570
8235	#####	386406	Passenger Doors - Adjust re:	Adjusted	553570

8235	#####	386406	Passenger Doors - Adjust re:	Adjusted	553570
8235	#####	386406	Eng Cool - Clean radiator	Cleaned	553570
8235	#####	386406	Eng Cool - Clean radiator	Cleaned	553570
8235	#####	386409	Drv entered - Brakes Shuddi	Checked OK	553570
8235	#####	386409	Drv entered - Brakes [See pr	Checked OK	553570
8235	#####	386409	Drv entered - Brakes Other	Checked OK	553570
8235	#####	386209		Tension Wheel Nuts To OEM Specification	553560
8235	#####	386209		Grease AC Compressor Clutch Bearing	553560
8235	#####	386209		Clean A/C filter	553560
8235	#####	386209		A Service done	553560
8235	#####	386209		A Service done	553560
8235	#####	385812	Engine - Check oil leak	Checked topped up p/steering oil s/clean r/tested check oil leak fuelled and parked	552445
8235	#####	381640	Scrap	Creditor #:BEA001 BEAUREPAIRES P/O #:G116771 Receiving #:118600 Date :2012-12-18	552445
8235	#####	385472	CAMPAIGN - Inspect front cl	checked ok - 12/12/12	552097
8235	#####	385222	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		552097
8235	#####	385222	VALVE 4 WAY CIRCUIT PROTECTION VALVE		551810
8235	#####	385222	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		551810
8235	#####	385011	AIR DRYER CANISTER VOLVO+ NL202		551810
8235	#####	385011	FUEL FILTER 0500LE		551357
8235	#####	385011	Assisted		551357
8235	#####	385011	POWER STEERING FILTER VOLVO		551357
8235	#####	385011	FUEL FILTER MERC 0500LE		551357
8235	#####	385011		Replace power steering filter and check level (Replace oil if required) Done	551357
8235	#####	385011		Test coolant level - top up if required to equate to 37C frost protection Done	551357
8235	#####	385011		Replace angle drive oil Oil changed.	551357
8235	#####	385011		Replace air dryer cansiter clean silence and drain reservoir Changed.	551357
8235	#####	385011		Replace pre and main fuel filters Changed.	551357
8235	#####	385011		Check and clean cartridge in dry type air cleaner	551357
8235	#####	385011		Check oil level in transmission - top up if required ok	551357
8235	#####	385011		Inspect radiator and charge air cooler for dirt - clean Steam cleaned.	551357
8235	#####	385011		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals Checked ok.	551357
8235	#####	385011		Replace final drive oil Done	551357
8235	#####	385011	RPM BORATE EP LUBE 220	Rear Axle Lube	551357
8235	#####	385100	Annual Body Inspection	completed	551357
8235	#####	385222	Air System - Replace 6way v	Replaced	551365
8235	#####		0 Imported Service History	Imported Service History	551357
8235	#####	385102	Replaced	Re-kit Air Cyclone Separator Air separator changed.	551357
8235	#####	385102	CYCLONE CONDENSER VALV	Condenser Valve Kit.	551357
8235	#####	385102	HALDEX COIL BASE OIL SEPE	Base	551357
8235	#####	385102	DRAIN VALVE KIT BOTTOM	Valve Kit	551357
8235	#####	385102	HALDEX COIL KIT 0500LE	Coil Kit	551357
8235	#####	383937	Annual Licence	- RWC 817916 - Passed	550834
8235	#####	384850	Air Cond Cooling Fault Ligh	clean relay contacts	550834
8235	#####	382152	LED FRONT PARK LAMP WHITE		549455
8235	#####	382156	LED FRONT POSITION MARKER LIGHT		549455
8235	#####	382152	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		549455
8235	#####	383101	Air System - Check for air le	Checked could not find	549604
8235	#####	382844	Mechanic entered - Air Syst	fix air leak from safety valve adjust air regulating pressure and road test bus ok.	549370
8235	#####	382844	Mechanic entered - Air Syst	Assisted Dulmith with air leak	549370
8235	#####	382759	Steering - Add p/steering flu	Added	549370
8235	#####	381640	Whls & Tyres - Side wall dar	Scrap	547545
8235	#####	382535	Elec & Light - Bus wont start	Jump started	548601
8235	#####	382533	Eng Cool - Add coolant	Added	548601
8235	#####	382347	Breakdown - Ringwood Stat	C/O bus 8389. Repaired air leak at air tank with new O rings	548320
8235	#####	382152	Elec & Light N/S/top park li	g Replaced	548073
8235	#####	382156	Elec & Light N/S plate light	Replaced	548073
8235	#####	381447	Elec & Light Indicators U/S	checked out flashers found fuse missing taken out by the two way radio people	547424
8235	#####	381447	Elec & Light Indicators U/S	checked out flashers found fuse missing taken out by the two way radio people	547424
8235	#####	381021	Brakes brakes not respondi	Attended by Dysons NO fault found	546254
8235	#####	368906	STUD MOUNT TURBOCHARGER	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	NUT LOCK TUBROCHARGER	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	NUT	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	GASKET	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	SEAL RING VLRUB	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	SEAL RING VLRUB	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	368906	WASHER COOLANT PIPE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112630 Receiving #:116903 Date :2012-11-12	545241
8235	#####	380205	BLADE FUSE HOLDER		545241
8235	#####	380205	15AMP BLADE FUSE		545241
8235	#####	380548	Eng Cool - Add coolant	Added	545241
8235	#####	380280		Perform & Complete PTSV Bus Safety Inspection	544497
8235	#####	380280		Tension Wheel Nuts	544497
8235	#####	380205		B Service	544497
8235	#####	380205		Replace compressor oil	544497
8235	#####	380205		Replace filter drier	544497
8235	#####	380205		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	544497
8235	#####	380205		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	544497
8235	#####	380205		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	544497
8235	#####	380205		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	544497
8235	#####	380205		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	544497
8235	#####	380205		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	544497
8235	#####	380205		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	544497
8235	#####	380205		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	544497
8235	#####	380205		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	544497
8235	#####	380205		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	544497
8235	#####	380205		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	544497
8235	#####	379214	Eng Cool - Add coolant	added	541765
8235	#####	377980	Security - Test and repair security camera system		540242

8235	#####	378071	SIDEWALL - POS 1 - 11 R22.1 Creditor #:BEA001 BEAUREPAIRES P/O #:G115586 Receiving #:116278 Date :2012-10-26 REPLACE WITH NEW	541279
8235	#####	378276	Whls & Tyres - Replace tyre Replaced & torqued w/nuts	540602
8235	#####	378071	Whls & Tyres - Replace tyre Replaced	540242
8235	#####	377285	Security - Test and repair se Repaired	540242
8235	#####	377116	Suspension - N/S/F and N/S/ Changed front OS sway bar link rod	540242
8235	#####	377116	Suspension - N/S/F and N/S/ Assist Dulkhith	540242
8235	#####	377116	Suspension - N/S/F and N/S/ Changed rear both side sway bar link rod	540242
8235	#####	377980	Direct Purchase - ELECTRIC/ Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115560 Receiving #:116075 Date :2012-10-23	540270
8235	#####	378045	Brakes Shuddering when str Ref to w/o 377116	540242
8235	#####	377116	Suspension - N/S/F and N/S/ Fix n/s front swaybar link rod c/o	540242
8235	#####	377116	REAR DROP ARM Creditor #:MUL001 MULTISPARES LTD P/O #:G115429 Receiving #:115929 Date :2012-10-19	540242
8235	#####	377116	FRONT SWAY BAR LINK RIGHT	540242
8235	#####	377116	SOV3521ZF SWAY BAR DROI Creditor #:MUL001 MULTISPARES LTD P/O #:G115429 Receiving #:115929 Date :2012-10-19	540242
8235	#####	377285	Test and repair security syst Creditor #:LON001 LONSDALE ST ELECTRICS P/O #:G115360 Receiving #:115928 Date :2012-10-19	540242
8235	#####	377226	Elec & Light Battery saver li Found broken wires on alternator repaired complete	540242
8235	#####	376834	Elec & Light Bus wont start Jump started	540240
8235	#####	376557	Air Cond - Clean a/c filters Cleaned	540240
8235	#####	374824	REPLACE 8MM SAFETY FILA Creditor #:GLA003 GLASSPRO MELBOURNE PTY.LTD. P/O #:G114591 Receiving #:115546 Date :2012-10-12 REPLACED	540045
8235	#####	375380	BRAKE+ CLUTCH PEDAL PAD 0500LE	538406
8235	#####	375381	Steering - Add p/steering flu Added	538406
8235	#####	375389	Eng Cool - Add coolant Added	538406
8235	#####	375101	SEAT BELT R/H	538164
8235	#####	375380	Brakes - Replace brake peda Replaced	538406
8235	#####	375243	Tension Wheel Nuts To OEM Specification	538164
8235	#####	375243	Grease AC Compressor Clutch Bearing	538164
8235	#####	375243	Clean A/C filter	538164
8235	#####	375243	A Service	538164
8235	#####	375011	Drv entered - Ticket Equip V Checked OK	537507
8235	#####	375101	Body & Acc Drivers Seat Bel replaced by Tulla - 04/10/2012	537507
8235	#####	374834	Body & Acc - Replace 8mm : Replaced	537507
8235	#####	374685	Vandalism - Remove graffiti Removed	536569
8235	#####	374529	L.E.D SIDE MARKER PERE RED/AMBER	536283
8235	#####	374685	Elec & Light - NS rear cleara Repaired broken wire	536569
8235	#####	374374	Perform & Complete PTSV Bus Safety Inspection	536238
8235	#####	374374	Tension Wheel Nuts	536238
8235	#####	374374	Perform & Complete PTSV Bus Safety Inspection	536238
8235	#####	374529	Elec & Light - Replace LED li Replaced	536283
8235	9/7/2012	371941	Wipers & Washers - Fill wat Filled and adjusted washer jets	529888
8235	#####	370436	Perform & Complete PTSV Bus Safety Inspection	527689
8235	#####	370436	Tension Wheel Nuts	527689
8235	#####	370435	Random Vehicle Audit Inspected	527689
8235	#####	369610	GLOBE H1 24V 70W	526108
8235	#####	369610	GLOBE 24V 21W SINGLE CONTACT	526108
8235	#####	369158	APPLY TINT TO DOOR Creditor #:GLA003 GLASSPRO MELBOURNE PTY.LTD. P/O #:G112715 Receiving #:113261 Date :2012-08-24 APPLIED	526108
8235	#####	369513	Perform & Complete PTSV Bus Safety Inspection	
8235	#####	369513	Tension Wheel Nuts	
8235	#####	369513	Random Vehicle Audit Inspected	
8235	#####	368906	turbo o ring Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G112733 Receiving #:113199 Date :2012-08-23	
8235	#####	369610	Elec & Light - Replace front Replaced	526108
8235	#####	369610	Elec & Light - Replace both s Replaced	526108
8235	#####	369610	Air System - Replace 6way v Replaced	526108
8235	#####	368906	Engine - turbo passing oil exhaust flange removed from old turbo and fitted into new turbo. New turbo fitted & connection given s/cleaned	
8235	#####	368906	TURBOCHARGER Creditor #:MUL001 MULTISPARES LTD P/O #:G112661 Receiving #:113082 Date :2012-08-22	525953
8235	#####	369158	Body & Acc - Apply tint to di Applied	
8235	#####	367062	Rebuild: A0004302915 AIR DRYER MERCEDES 0500	
8235	#####	368906	Engine - turbo passing oil Remove turbo parts ordered	
8235	#####	368906	Engine - turbo passing oil Assisted Subu to remove turbo	
8235	#####	368463	Body & Acc - Refit headlight Made new hinge to fit refit headlight surround	
8235	8/7/2012	367062	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER	
8235	8/3/2012	247867	SUB - A/C duct cracked above rear door (VG) (Checked on 10/0	
8235	8/1/2012	366104	CONTACT BLOCK DOOR PUSH SWITCH	525953
8235	#####	366104	Passenger Doors Faulty Cor Door switch changed & checked OK	
8235	#####	365950	Mechanic entered - Eng Coc fit new head tank cap	525776
8235	#####	365950	RAD CAP MERC BENZ SIGHT GLASS SIDE	525776
8235	#####	365296	INDICATOR ARM 0500LE	525080
8235	#####	365296	Indicator Stalk broken Replaced	525080
8235	#####	364944	Elec & Light - Secure rear dc Secured	524454
8235	#####	364705	WEDGE GLOBE INSTRUMENT 24V 3W	524116
8235	#####	364929	Eng Cool - Check for coolant Rectified s/cleaned engine topped up coolant	524454
8235	#####	364683	Mechanic entered - Brakes f reset fault cord.	524116
8235	#####	364705	Elec & Light Park light out Replace globe	524116
8235	#####	364537	AMBER REFLECTOR SIDE MOUNT	523776
8235	#####	364537	Body & Acc Replace side ref Replaced	523776
8235	#####	364538	Body & Acc Replaced	523776
8235	#####	355813	AIR COMPRESSOR 0500LE	523454
8235	#####	361847	Passenger Doors - Front anc Fix under bumper bar switch	523446
8235	#####	359640	Heat & Demist - Drivers fan checked ok.	523446
8235	#####	361847	Engine - Main belt needs re; Replace belt - adjust A/C compressor adjuster	523446
8235	#####	361847	Engine - Main belt needs re; Checked OK	523446
8235	#####	361847	Eng Cool - Radiator leaking Fit radiator to bus complite job	523446
8235	#####	364412	Body & Acc Wheel arch rub; Replace O/S? wheel arch rubber and brush and N/S/R rubber and brush and N/S/F brush and O/S/R panel nm.1 lach	523454
8235	#####	361847	Mechanic entered - Air Syst Change air drayer seperator - adjust pressure - road test OK	523446
8235	#####	361847	AIR DRYER MERCEDES 0500	523446
8235	#####	361847	SNAP ON SILENCER A/DRYER	523446
8235	#####	361847	Eng Cool - Radiator leaking Fit radiator to bus c/o job	523446
8235	#####	361463	Mechanic entered - Elec & L no problem with rear switch	523446
8235	#####	361847	CLIPPARD VALVE DOOR OPEN/CLOSE	523446

8235	7/8/2012	362451	Whls & Tyres - Side Wall dai Scraped	523446
8235	7/5/2012	361847	A/C BELT 0500 BENZ	523446
8235	7/2/2012	361847	Eng Cool - Radiator leaking Start to remove radiator	523446
8235	7/2/2012	361847	Eng Cool - Radiator leaking remove radiator and send to repair	523446
8235	#####	359640	24V DRIVERS FAN (USE FASCO ONLY)	523446
8235	#####	361463	Mechanic entered - Elec & L no problem with rear switch	523446
8235	#####	360126	Air System Low Air Pressur Fit blow off valve to compressor s/clean bus & clean bus inside	523446
8235	#####	360126	AIR COMPRESSOR 0500LE Creditor #:MUL001 MULTISPARES LTD P/O #:G110118 Receiving #:110769 Date :2012-06-29	523446
8235	#####	360413	A Service & Bus Safety Inspection	523446
8235	#####	360413	Tension Wheel Nuts to Spec	523446
8235	#####	360413	D-Service & Bus Safety Inspection	523446
8235	#####	360413	Grease AC Compressor Clutch Bearing	523446
8235	#####	360413	Replace Engine Oil Breather Kit	523446
8235	#####	360413	Tension Wheel Nuts To OEM Specification	523446
8235	#####	360413	Grease AC Compressor Clutch Bearing	523446
8235	#####	360413	Clean A/C filter	523446
8235	#####	360413	A Service	523446
8235	#####	359640	Heat & Demist - Drivers fan same job	523446
8235	#####	359480	Tow bus to GBS Creditor #:ASS001 ASSOCIATED TOWING P/O #:G109641 Receiving #:110625 Date :2012-06-28	523446
8235	#####	360126	Air System Low Air Pressur Clean safety valve on compressor & made up pipe to water separator & fit c/o	523446
8235	#####	359640	Body & Acc - Paint exterior Painted	523446
8235	#####	359640	Body & Acc - Polish exterior Polished	523446
8235	#####	359640	Body & Acc - Replace rear door seals (Checked on 23/04/12 se	523446
8235	#####	359640	Body & Acc - Secure all low Secured	523446
8235	#####	359640	Body & Acc - Replace rear d Replaced	523446
8235	#####	360126	BRAIDED COMPRESSOR PIPE 0500LE	523446
8235	#####	360126	Air System Low Air Pressur Cleaned air pipes with prepsol remove & fit air dryer hose also broken remove to make up hose topped up p/steering fluid	523446
8235	#####	360126	Air System Low Air Pressur Checked air system	523446
8235	#####	360126	Air System Low Air Pressur Fit pump on compressor & fit new brass washers	523446
8235	#####	359640	Body & Acc - Clean air condi Cleaned	523446
8235	#####	360126	Air System Low Air Pressur Fit compressor & fitting c/o	523446
8235	#####	360413	ENGINE OIL DELO 400LE 15W40	523446
8235	#####	360413	OIL FILTER 1725+0500LE	523446
8235	#####	360413	AIR FILTER MERC 0500LE	523446
8235	#####	360413	ENGINE OIL BREATHER KIT 0500LE	523446
8235	#####	360456	Elec & Light - Bus wont start Jump started wont stay on lights on found fuse missing	523446
8235	#####	360126	Air System Low Air Pressur Remove compressor	523446
8235	#####	360053	DRAIN VALVE KIT BOTTOM Valve Kit	523446
8235	#####	360053	HALDEX COIL KIT 0500LE Coil Kit	523446
8235	#####	360053	Rebitted & fitted oneway va Re-Kit Air Cyclone Separator	523446
8235	#####	360053	CYCLONE CONDENSER VALL Condenser Valve Kit.	523446
8235	#####	360053	HALDEX COIL BASE OIL SEPE Base	523446
8235	#####	359640	Vandalism - Clean graffiti - f Cleaned	523446
8235	#####	359997	Eng Cool - Leaking water ar; Tullamarine replaced cap with spare attached to side of radiator 12/06/12 = \$20.00 ex GST	523446
8235	#####	359640	Body & Acc - Replace Do No Replaced	523446
8235	#####	360126	Air System Low Air Pressur Needs a new air compressor air being pumped through cooling system	523446
8235	#####	359640	Heat & Demist - Drivers fan bearing required (Checked on 22	523446
8235	#####	359640	Body & Acc - Destination frc Secured	523446
8235	#####	359640	Body & Acc - Paint till stand Painted	523446
8235	#####	359640	Body & Acc - Tint strip above windscreen has been removed ne	523446
8235	#####	359640	Body & Acc - Replace interic Replaced	523446
8235	#####	359640	Body & Acc - Drivers seat Reset weight dial checked air supply	523446
8235	#####	359640	Body & Acc - Replace rear si Replaced	523446
8235	#####	359640	Body & Acc - Replace a/c ducting above rear door (Checked on	523446
8235	#####	359480	Breakdown - Springvale Rd C/O bus 8297. Compressor blown towed back to depot	523446
8235	#####	359515	Engine - Replace radiator ca Replaced	523446
8235	#####	359508	Elec & Light - Thers is no RH Replaced Globe	523446
8235	#####	359309	Eng Cool - Add coolant Added	522989
8235	6/7/2012	358728	Passenger Doors - Check res Went to check but bus gone	521495
8235	6/7/2012	354717	AIR REGULATOR	521495
8235	6/1/2012	357471	BRAIDED COMPRESSOR PIPE 0500LE	520107
8235	6/1/2012	357649	Eng Cool - Add coolant Added	520107
8235	#####	357414	Eng Cool - Add coolant Added	520107
8235	#####	357471	Eng Cool - Check for coolant Found air leak and replaced compressor cool/air hose	520107
8235	#####	355852	BALD - New - 11.00R 22.5 - i Creditor #:BEA001 BEAUREPAIRES P/O #:G108521 Receiving #:109215 Date :2012-05-30 Replace with new	519156
8235	#####	356699	Perform & Complete PTSV Bus Safety Inspection	518665
8235	#####	356699	Tension Wheel Nuts	518665
8235	#####	356699	Perform & Complete PTSV Bus Safety Inspection	518665
8235	#####	356901	Gearbox - Gears rough betw Checked OK	518838
8235	#####	356897	Air System - Air leak Repaired by Tullamarine 09/05/12	518838
8235	#####	355813	FRONT-REAR DISC ROTOR 0500LE (A942421112)	516293
8235	#####	355813	AIR COMPRESSOR 0500LE	516293
8235	#####	355852	Whls & Tyres Replace tyres Replaced	516293
8235	#####	355813	Mechanic entered - Brakes f	516293
8235	#####	355813	Front brake disks worn C/O Replace O/S front brake pads	516293
8235	#####	355813	Front brake disks worn C/O Replace front brake disks and pads	516293
8235	#####	355813	Mechanic entered - Brakes f Replaced rear brake pads and all rear tyres	516293
8235	#####	355813	DISC PAD SET SCANIA MB0500	516293
8235	#####	355813	Front brake disks worn C/O	516293
8235	#####	355704	Air System Leaking repaired by Tulla - 09/05/2012	516293
8235	#####	354157	LED FRONT POSITION MARKER LIGHT	514880
8235	#####	354717	Air System Air leak front eni Fit dooe regulator and adjust pressure	514570
8235	#####	354636	Elec & Light Head light globi Replace globe	514570
8235	#####	354308	Tension Wheel Nuts To OEM Specification	513907
8235	#####	354308	A Service	513907
8235	#####	354308	Grease AC Compressor Clutch Bearing	513907
8235	#####	354308	Clean A/C filter	513907

8235	#####	354308	A Service	513907
8235	5/8/2012	354157	Elec & Light Change O/S LEE Replaced	513836
8235	5/6/2012	352588	Ventura decals to be supplie Fitted	510085
8235	#####	352567	Passenger Doors - Both fron Adjusted doors	510085
8235	#####	351658		509387
8235	#####	351658	Perform & Complete PTSV Bus Safety Inspection	509387
8235	#####	351658	Tension Wheel Nuts	509387
8235	#####	350226	Passenger Doors - Check re Adjusted	506550
8235	#####	341835	Replace decals - n/s Creditor #-ATT001 ATTITUDE SIGNS P/O #:G104427 Receiving #:106760 Date :2012-03-30	503307
8235	#####	348665	Passenger Doors - Door will Checked OK	502958
8235	#####	347499	Tension Wheel Nuts	500336
8235	#####	347499	Perform & Complete PTSV Bus Safety Inspection	500336
8235	#####	347499	Perform & Complete PTSV Bus Safety Inspection	500336
8235	#####	347347	Elec & Light - Check wiring c Checked battery & alt OK	499465
8235	#####	346620	Adjust Tappets	499420
8235	#####	346620	ROCKER COVER GASKET 05C Rocker Cover Gasket	499420
8235	#####	346620		499420
8235	#####	346620	MERCEDES REAR ENGINE DOOR SWITCH	499420
8235	#####	346824	Passenger Doors - Back doo Adjusted & replaced micro switch	499420
8235	#####	346755	Service T - Replace Transmission Oil & Filter	499420
8235	#####	346755	ZF SYNTHETIC GEARBOX OIL ZF Ecofluid A Plus Synthetic Transmission Oil	499420
8235	#####	346755	FILTER TRANSMISSION ZF 4: ZF Transmission Filter	499420
8235	#####	346755	Bus Safety Inspection	499420
8235	#####	346755	Service T - Replace Transmission Oil & Filter	499420
8235	#####	346328	Passenger Doors - Rear doo Adjusted	497995
8235	#####	346328	Elec & Light - NS clearance l Checked OK	497995
8235	#####	345810	Grease AC Compressor Clutch Bearing	497829
8235	#####	345810	A Service	497829
8235	#####	345810	Clean A/C filter	497829
8235	#####	345810	Tension Wheel Nuts To OEM Specification	497829
8235	3/9/2012	343092	Side wall damage Creditor #-BEAD01 BEAUREPARES P/O #:G104661 Receiving #:105841 Date :2012-03-09	497502
8235	3/9/2012	346027	Air Cond - Clean a/c filters Cleaned	497829
8235	#####	343092	Whls & Tyres - Sidewall darr Disposed	491153
8235	#####	343714	Passenger Doors - Adjust frc Adjusted	492601
8235	#####	343228	Perform & Complete PTSV Bus Safety Inspection	491153
8235	#####	343228	Tension Wheel Nuts	491153
8235	#####	343228	Perform & Complete PTSV Bus Safety Inspection	491153
8235	#####	342837	Service schedule changed	490773
8235	#####	341835	UNREPORTED - Repair & paint NS 45 panels & decals	490773
8235	#####	341835	UNREPORTED - Repair & paint NS 45 panels & decals	490773
8235	#####	342073	UNREPORTED - Repair & pa All painted completed	490773
8235	#####	342073	UNREPORTED - Repair & pa Assisted to prepare and paint n/s panel nos.4567 & Rear B/bar & Rear Lower Panelwork completeddecals to be done by Attitude Signs	490773
8235	#####	341748	PARK BRAKE VALVE 0500LE	490773
8235	#####	341748	Mechanic entered - Brakes l Resealed park brake hose under electrical panel r/tested	490773
8235	#####	341835	UNREPORTED - Repair & pa Assisted to make panels & sand fit to the bus	490773
8235	#####	341835	UNREPORTED - Repair & paint NS 45 panels & decals	490773
8235	#####	341835	SCREW TORX 8 X 15MM SIL Assisted to make panels & sand fit to the bus	490773
8235	#####	341748	Brakes - No handbrake Cut dash panel removed park brake valve make plate for new park brake valve and fitted new valve c/o	490773
8235	#####	341835	UNREPORTED - Repair & pa Cont work on Panel 7 NS fitted alum extrusion to panel painted etch primer & black for the rear of panel sanded panel for paint work. Fitted new alum plate for the air brake valve to secure	490773
8235	#####	341748	Mechanic entered - Brakes l Rekit park brake relay valve	490773
8235	#####	341748	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE	490773
8235	#####	341835	UNREPORTED - Repair & pa Started repairs on 6 started making 7 make new panel no.6 n/s C/O	490773
8235	#####	341835	UNREPORTED - Repair & pa Manufactured panels 47 and assistance given to repair panels 56	490773
8235	#####	341835	UNREPORTED - Repair & pa Make No 4 panel Repair No 5 panel	490773
8235	2/9/2012	339679	ROAD SAFETY INSPECTIONS Creditor #-ROA001 Road Safety Inspections P/O #:G103643 Receiving #:104705 Date :2012-02-09	490267
8235	2/9/2012	341236	Eng Cool - Add coolant Added	490267
8235	2/8/2012	341038	Air Cond - Replace a/c filter: Cleaned	489985
8235	2/5/2012	339679	Annual Licence RWC 233252 - Passed	486877
8235	#####	337603	MERC 0500LE RELAY VALVE+ FRONT EBS MOD B12BLE	483490
8235	#####	337256	Test coolant level - top up if required to equate to 37C frost protection	483390
8235	#####	337256	Replace angle drive oil	483390
8235	#####	337256	Replace air dryer cansiter clean silence and drain reservoir	483390
8235	#####	337256	Replace pre and main fuel filters	483390
8235	#####	337256	Check and clean cartridge in dry type air cleaner	483390
8235	#####	337256	Check oil level in transmission - top up if required	483390
8235	#####	337256	Inspect radiator and charge air cooler for dirt - clean	483390
8235	#####	337256	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	483390
8235	#####	337256	Replace final drive oil	483390
8235	#####	337256	Done at Roadworthy inspection - Doc 136755	483390
8235	#####	337256	Inspect vehicle as per RSI Checklist	483390
8235	#####	337603	Body & Acc - Air to seat nee Seat air pressure OK adjusted seat	483490
8235	#####	337603	Brakes Hand Brake - not rel Removed and cleaned both chamber shuttle valves overhaul rear brake valve secured park brake hand valve	483490
8235	#####	337153	Annual Body Inspection Inspected	479983
8235	#####	327186	Gearbox - Air leak from g/box retarder valve	479983
8235	#####	337153	CENTRA SEAT END CAPS	479983
8235	#####	336612	Whls & Tyres - Replace tyre Replaced	482711
8235	1/6/2012	336607	Whls & Tyres - Replace NS fi Replaced	482711
8235	#####	327186	RETARDER SOLENOID VALV Creditor #-WHT001 WHITEHORSE TRUCKS P/O #:G102091 Receiving #:103193 Date :2011-12-29 8235	480593
8235	#####	327186	AIR LINE FITTING KIT 0500LE AIR DRYER	480025
8235	#####	327186	Air System - Check air syste Valve faulty on suspension system valve changed air line kit changed	479983
8235	#####	327186	50g2809w 6 WAY VALVE Creditor #-MUL001 MULTISPARES LTD P/O #:G102129 Receiving #:102924 Date :2011-12-21 8235	479983
8235	#####	327186	Air System - Check air syste Checked no air supply to air tank	479983
8235	#####	327186	Air System - Check air syste Checked not coming up suspension wasn't working left it with Subu	479983
8235	#####	333927	AIR LINE FITTING KIT 0500LE AIR DRYER	479983
8235	#####	334161	Elec & Light - Check rear bu; Fixed buzzer	479555
8235	#####	327186	Elec & Light Check ABS ligt c Checked & ordered retarder solenoid valve	466522
8235	#####	333926	ENGINE OIL BREATHER KIT 0500LE	479428

8235	#####	333926	D-Service & Bus Safety Inspection	479428
8235	#####	333926	A Service & Bus Safety Inspection	479428
8235	#####	333926	Tension Wheel Nuts to Spec	479428
8235	#####	333926	ENGINE OIL DELO 400LE 15W40	479428
8235	#####	333926	OIL FILTER 1725+0500LE	479428
8235	#####	333926	AIR FILTER MERC 0500LE	479428
8235	#####	333926	Grease AC Compressor Clutch Bearing	479428
8235	#####	333926	Replace Engine Oil Breather Kit	479428
8235	#####	333927	Re-kit Air Cyclone Separator	479428
8235	#####	333927	WATER SEPARATOR SCANIA Water Separator Kit	479428
8235	#####	333927	HALDEX COIL BASE OIL SEPP Base	479428
8235	#####	333927	DRAIN VALVE KIT BOTTOM Valve Kit	479428
8235	#####	333927	HALDEX COIL KIT 0500LE Coil Kit	479428
8235	#####	333926	A Service	479428
8235	#####	333926	Tension Wheel Nuts To OEM Specification	479428
8235	#####	333926	Grease AC Compressor Clutch Bearing	479428
8235	#####	333926	Clean A/C filter	479428
8235	#####	333470	Perform & Complete PTSV Bus Safety Inspection	478494
8235	#####	333470	Tension Wheel Nuts	478494
8235	#####	333470	Perform & Complete PTSV Bus Safety Inspection	478494
8235	#####	333471	Random Vehicle Audit Inspected	478494
8235	#####	333471	Random Vehicle Audit Inspected	478494
8235	#####	333518	Eng Cool - Add coolant Added	478757
8235	#####	330836	Wipers & Washers - Clean n Cleaned	473043
8235	#####	330180	WATER SEPARATOR SCANIA+VOLVO+MB (HAL90364)	471677
8235	#####	330180	HALDEX COIL BASE OIL SEPARATOR	471677
8235	#####	330180	DRAIN VALVE KIT BOTTOM	471677
8235	#####	330180	HALDEX CONDENSER KIT TOP(CYCLONE)	471677
8235	#####	330180	HALDEX COIL KIT 0500LE	471677
8235	#####	330180	Air System - Rebuild ACS Rebuilt	471677
8235	#####	329185	Eng Cool - Add coolant Added	469919
8235	#####	323688	EXH BRAKE SOLENOID Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G99133 Receiving #:100918 Date :2011-11-04 8235	467077
8235	#####	327186	Elec & Light Check ABS lgt c Checked bus wont go did not fix	466522
8235	#####	325712	FILTER DRIER THERMO KING	466522
8235	#####	327171	Air Cond - Clean a/c filters Cleaned	464488
8235	#####	325712	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	464488
8235	#####	325712	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	464488
8235	#####	325712	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	464488
8235	#####	325712	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	464488
8235	#####	325712	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	464488
8235	#####	325712	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	464488
8235	#####	325712	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	464488
8235	#####	325712	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	464488
8235	#####	325712	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	464488
8235	#####	325712	CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	464488
8235	#####	325712	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	464488
8235	#####	326843	Body & Acc - Secure coolant Secured	465975
8235	#####	326921	CAMPAIGN - Install retro - n Installed by Attitude signs	466359
8235	#####	326692	Eng Cool - Add coolant Added	465975
8235	#####	326461	Eng Cool - Add coolant Added	465636
8235	#####	326062	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)	464577
8235	#####	326062	Air System - Exhaust brake s Solenoid valve removed fittings transferred to new valve & fitted 6way valve changed seal fuelled & parked	464577
8235	#####	324469	Body & Acc - Body washed & Cleaned	462823
8235	#####	323688	COOL - vibration noise comi Checked OK	462198
8235	#####	323688	Brakes - rear brakes locking Both side brakes checked OK left side wheel removed disc checked OK wheels fitted nut tensioned f/code 4344 floor cover removed left speed sensor checked faulty removed new sensor fitted. f/code cleared r/tested OK floor cover fitted fuelled & parked jump started	462198
8235	#####	323688	49g0026w abs sensor rear Creditor #:MUL001 MULTISPARES LTD P/O #:G98941 Receiving #:99678 Date :2011-10-10 8235	462198
8235	#####	323943	CAMPAIGN - Fit covers on ri Fitted	462198
8235	#####	322361	Breakdown - Knox - OUT 7.c C/O bus 8381. Air full released handbrake and bus moved	462198
8235	#####	321765	Eng Cool - Coolant leaking in Tightened hose clamps & topped up coolant	461084
8235	#####	321744	Eng Cool - Add coolant Added	461084
8235	#####	321765	Body & Acc - The fold up see Fitted bolt	461084
8235	#####	321171	BALD POS 3-4-5-6 11R NEW Creditor #:BEA001 BEAUREPARES P/O #:G98235 Receiving #:99044 Date :2011-09-23	460156
8235	#####	321087	FIRE EXTINGUISHER 2.5KG Replaced	460156
8235	#####	321171	Whis & Tyres Worn POS 3-4 Replaced	459710
8235	#####	320974	Perform & Complete PTSV Bus Safety Inspection	459689
8235	#####	320974	Tension Wheel Nuts	459689
8235	#####	320974	Perform & Complete PTSV Bus Safety Inspection	459689
8235	#####	321086	Wipers & Washers Adjust w Adjusted	459710
8235	#####	320977	Whis & Tyres - NSR low trea Replace all rear tyres	459689
8235	#####	320977	Whis & Tyres - NSR low trea Replace all rear tyres	459689
8235	#####	320976	Random Vehicle Audit Inspected with service	459689
8235	#####	321087	Body & Acc Replace fire exti Replaced	459710
8235	#####	320975	Tension Wheel Nuts To OEM Specification	459689
8235	#####	320975	Grease AC Compressor Clutch Bearing	459689
8235	#####	320975	Clean A/C filter	459689
8235	#####	320626	Elec & Light/Replace head lig Replaced	458968
8235	#####	320626	GLOBE HIGH BEAM 24V70W H1	458968
8235	#####	320627	Passenger Doors door brush Secured	458968
8235	#####	320629	Body & Acc Cash rox loose Secured	458968
8235	#####	319334	Air Cond - A/c n/w Commission tested unable to fault remove and clean air filter and prefilters (blocked) unit has not had vibra sorber up grades TX warranty	456344
8235	9/6/2011	304904	scrap Creditor #:BEA001 BEAUREPARES P/O #:G97433 Receiving #:98355 Date :2011-09-06	454943
8235	9/1/2011	317860	Wipers & Washers - Clean w Cleaned	453771
8235	#####	316874	BRAZILLIAN MIRROR RH	453056
8235	#####	316874	Body & Acc - Driver side mir Replaced mirror	452723
8235	#####	313859	DOWN LIGHT Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G95661 Receiving #:97714 Date :2011-08-19 Book to bus 8227 8228 8229 8230 8231 and 8235	449608
8235	#####	315097	L/H WIPER ARM (BOSCH) SHORT	449148
8235	#####	315029	Wipers & Washers - drivers Fitted new wiper arm & adjusted wipers	449148

8235	#####	315097	Wipers & Washers - Check v	Checked NO fault found had been fixed	449148
8235	#####	313906	Brakes - rear discs worn	Right side hub fitted both side bearing hub tensioned play adjusted caliper dust boot changed caliper fitted booster drive shaft fitted. wear sensor wires connected ned brake pads fitted & adjusted wheels fitted & nut tensioned diff oil topped up	448832
8235	#####	313906	DISC PADS SCANIA L94+050		448832
8235	#####	313906	FRONT+REAR DISC ROTOR C		448832
8235	#####	313906	REAR HUB SEAL KIT 0500LE		448832
8235	#####	313906	Brakes - rear discs worn	Both side booster caliper hub removed. rotor removed & hub cleaned. new seal ABS wheel fitted LH side hub fitted	448832
8235	#####	313906	Brakes - rear discs worn	Removed rear hub assy changed hub oil seal both side need to change rear NS brake caliper	448832
8235	#####	313843	POS 2 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G96493 Receiving #:97430 Date :2011-08-12	448832
8235	#####	314084	Whls & Tyres - Replace No 2	Moved bus to w/shop replaced tyre & tensioned w/nuts	448832
8235	#####	313843	replace worn tyre pos 2	replaced	448832
8235	#####	314010	Elec & Light - Replace interir	Replaced fluro & ends	448832
8235	#####	313859	Replace down light on driv	Fitted down light	448832
8235	#####	313906	Brakes - rear discs worn	Checked fault code on dash removed rear wheel found rotor & disc pads worn	448832
8235	#####	313906	Brakes - rear discs worn	Bought bus in removed both side wheels & put on stand	448832
8235	8/4/2011	312721	DOWN LIGHT LED		446780
8235	8/3/2011	312721	Elec & Light - Replace front	Replaced	446780
8235	8/1/2011	312355	Eng Cool - add coolant	Added	445830
8235	#####	311969	COOLANT PIPE EXP TANK MERC 0500LE		444835
8235	#####	311969	Body & Acc - Repair water l	Repaired	444835
8235	#####	311724		A Service	444835
8235	#####	311724		Clean A/C filter	444835
8235	#####	311724		Grease AC Compressor Clutch Bearing	444835
8235	#####	311724		Tension Wheel Nuts To OEM Specification	444835
8235	#####	311724		A Service	444835
8235	#####	311647	Wipers & Washers - Repair	Assisted sealan with wipers	444835
8235	#####	311647	Wipers & Washers - Wipers	Fixed wipers & adjusted	444835
8235	#####	298687	decal for bus	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G91863 Receiving #:96480 Date :2011-07-22	444835
8235	#####	301174	Replace Grenda decals x 4	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G92531 Receiving #:96484 Date :2011-07-22	444835
8235	#####	310825	Eng Cool - Add coolant	Added	444835
8235	#####	310531	Wipers & Washers - Wiper r	Checked wiper found RH wiper arm worn checked in store no stock	444835
8235	#####	310531	Wipers & Washers - Wiper r	tried to adjust wiper link need take off all line assy and need to readjust	444835
8235	#####	310531	Wipers & Washers - Wiper r	Wiper shaft on wiper motor and LH side wiper rod bent removed & new rod fitted and aligned checked OK fuelled & parked	444835
8235	#####	310531	Wipers & Washers - Wiper	milling hub slips	444835
8235	#####	308835		Perform & Complete PTSV Bus Safety Inspection	438402
8235	#####	308835		Tension wheel nuts	438402
8235	#####	308835		Perform & Complete PTSV Bus Safety Inspection	438402
8235	#####	309158	Air Cond - Clean a/c filters	Cleaned	439633
8235	#####	309146	Eng Cool - Add coolant	Added	439633
8235	7/1/2011	307793	Add coolant	Added	436366
8235	#####	307643	Clean a/c filters	Cleaned	436086
8235	#####	306612	GLOBE HIGH BEAM 24V70W H1		434002
8235	#####	306612	WEDGE GLOBE INSTRUMENT 24V 3W		434002
8235	#####	306612	Replace globes	Replaced low beam & park globes	434002
8235	#####	304904	POS 1 11R NEW FLAT	Creditor #:BEA001 BEAUREPARES P/O #:G93780 Receiving #:95070 Date :2011-06-22	432185
8235	#####	306172	Add coolant	Added	432725
8235	#####	306033	Add coolant	Added	432725
8235	#####	305282	AMBER REFLECTOR SIDE MOUNT		431497
8235	#####	304904	fix flat tyre pos 1	fixed	430711
8235	#####	305121	Add coolant	Added	431096
8235	#####	304833	AIR LINE FITTING KIT 0500LE AIR DRYER		430711
8235	#####	304813		Tension wheel nuts	430004
8235	#####	304813		Perform & Complete PTSV Bus Safety Inspection	430004
8235	#####	304951	Change tyre pos 1	Replaced	430004
8235	#####	304951	Change tyre pos 1	Replaced	430004
8235	#####	305282	Replace reflectors	Replaced	430004
8235	#####	304833	CYCLONE PACK (SEPARATO	Water Sperator Kit	430004
8235	#####	304833		Re-kit Air Cyclone Separator	430004
8235	#####	304792	GB - Transmission coolant p	Removed replaced coolant pipe	430004
8235	#####	304792	COOL - Coolant pipe needs t	Changed coolant pipe to transmission and r/tested	430004
8235	#####	304792	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		430004
8235	6/9/2011	304674	Clean battery	S/clean battery	430004
8235	6/9/2011	304473	DOWN LIGHT LED		430004
8235	6/9/2011	304617	ENGINE OIL DELO 400LE 15W40		430004
8235	6/9/2011	304617		Tension Wheel Nuts to Spec	430004
8235	6/9/2011	304617		A Service & Bus Safety Inspection	430004
8235	6/9/2011	304617		D-Service & Bus Safety Inspection	430004
8235	6/9/2011	304617	AIR FILTER MERC 0500LE		430004
8235	6/9/2011	304617		Grease AC Compressor Clutch Bearing	430004
8235	6/9/2011	304617	ENGINE OIL BREATHER KIT 0500LE		430004
8235	6/9/2011	304617		Replace engine oil breather kit	430004
8235	6/9/2011	304617		Tension Wheel Nuts To OEM Specification	430004
8235	6/9/2011	304617		Grease AC Compressor Clutch Bearing	430004
8235	6/9/2011	304617		Clean A/C filter	430004
8235	6/9/2011	304617		A Service	430004
8235	6/8/2011	304478	Wipers u/s	Fixed wipers and adjusted wiper blades	430004
8235	6/8/2011	304473	EL - Drivers light n/w	Fitted new interior down light	430004
8235	6/8/2011	304478	Coolant leak	Checked brass coolant pipe is cracked needs to be replaced	430004
8235	6/7/2011	304277	Clean a/c filters	Cleaned	429592
8235	6/7/2011	304282	Add coolant	Added	429592
8235	6/6/2011	304085	Add coolant	Added	429161
8235	6/6/2011	304114	Breakdown - Stud Park - OU	Could not find bus returned	429161
8235	6/3/2011	303863	Add coolant	Added	428024
8235	6/2/2011	303490	PD - Delay for back door	Adjusted	427078
8235	6/1/2011	303490	PD - Delay for back door	Adjusted rear door speed	427078
8235	6/1/2011	303386	WEDGE GLOBE INSTRUMENT 24V 3W		427049
8235	6/1/2011	303386	Replace park light globe	Replaced	427049

8235	6/1/2011	303400	Add coolant	Added	427049
8235	6/1/2011	303490	Straighten mirror arm	Straightened	427078
8235	#####	302486	Add coolant	Added	424238
8235	#####	301174	Replace Grenda decals x 4	Replaced	421691
8235	#####	300240	WIPER ARM LH		421321
8235	#####	300240	BLADE WIPER 1MTR		421321
8235	#####	300991	Noise from back of the engi	Checked air leak in air dryer OK fixed air dryer exhaust silencer	421321
8235	#####	300378	Add coolant	Added	420717
8235	#####	300240	Wipers n/w	Disconnected arms	420207
8235	#####	300240	Wipers n/w	Repaired wipers	420207
8235	#####	300240	Wipers n/w	Repaired wiper linkages	420207
8235	#####	300019	Clean a/c filters	Cleaned	419723
8235	5/9/2011	299889	Add coolant	Added	419723
8235	5/6/2011	299665	Add coolant	Added	419441
8235	5/6/2011	299394	ACC - #33049 - os panels 12	Repair & paint panels	418690
8235	5/4/2011	299276	O/S/F indicator U/S	Rewiring	418690
8235	5/4/2011	298687	GLOBE INDICATOR 24V-18W SINGLE CONTACT		418690
8235	5/4/2011	298687	AMBER REFLECTOR SIDE MOUNT		418690
8235	5/4/2011	298687	ACC - #33049 - os panels 12	Completed	418690
8235	5/3/2011	298687	ACC - #33049 - os panels 12	Paint panels silver	418690
8235	#####	290701	REPLACE DECALS N/S 4-5-6	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G89039 Receiving #:92599 Date :2011-04-29	418690
8235	#####	298687	ACC - #33049 - os panels 12	3567 & 8 - manfr. and paint	418690
8235	#####	294436	POS 3-4-5-6 11R NEW	Creditor #:BEA001 BEAUREPARES P/O #:G90005 Receiving #:92350 Date :2011-04-21	417353
8235	#####	297501	Add coolant	Added	415405
8235	#####	297255	Check rear doors	Checked doors OK	413045
8235	4/8/2011	296604	remove graffiti	Removed	412440
8235	4/8/2011	296606	Add coolant	Added	412440
8235	4/4/2011	295975	GLOBE HIGH BEAM 24V70W H1		411166
8235	4/3/2011	295975	Replace OS headlight globe	Replaced	411166
8235	4/2/2011	298687	ACC - #33049 - os panels 12	Fit panels repaired and mask	418690
8235	4/2/2011	298687	ACC - #33049 - os panels 12	Fit panels repaired and mask	418690
8235	4/2/2011	298687	ACC - #33049 - os panels 12	Fit panels repaired and mask	418690
8235	4/1/2011	295959	Check coolant leak	Checked leaking from header tank to bottom cooling line	411166
8235	4/1/2011	295953	Add coolant	Added 6 ltrs	411166
8235	#####	295672	Add coolant	Added	410402
8235	#####	295235	WING NUT BRASS BATTERY TERMINAL POSITIVE		408011
8235	#####	295235	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		408011
8235	#####	294858	Bus has no broom	Replaced broom	408270
8235	#####	294858	BROOM HEAD (09803211)		408270
8235	#####	294858	BROOM HANDLE (8232715)		408270
8235	#####	294436	replace worn tyre pos 3-4-5-6	replace worn tyre pos 3-4-5-6	407796
8235	#####	295235	Replace battery terminal	Replaced	408011
8235	#####	295235	Replace 4 way seal	Replaced	408011
8235	#####	294465	Overhaul protection valve	R/tested bus OK after overhaul	408011
8235	#####	294465	Overhaul protection valve	Assisted with valve & coolant leak	408011
8235	#####	294484		A Service & Bus Safety Inspection	407796
8235	#####	294484		Clean A/C filter	407796
8235	#####	294484		Grease AC Compressor Clutch Bearing	407796
8235	#####	294484		Tension Wheel Nuts To OEM Specification	407796
8235	#####	294484		A Service & Bus Safety Inspection	407796
8235	#####	294350	WHL - All rear tyres low tref	Completed	407796
8235	#####	294465	COOL - Coolant leak from pi Temp repair pipe (new part ordered) 4 way protection valve leaking (new part ordered)		407796
8235	#####	294045	Breakdown - Springvale Rd - Van 619. Fixed temporarily & returned to depot (Need to replace 4way valve)		407796
8235	#####	293585	AIR S - check for air leak wh	Check air bags road tested ok.	403874
8235	#####	293421	Losing air pressure when bri	Checked OK	403831
8235	#####	291809	ROAD SAFETY INSPECTIONS Creditor #:ROA001 Road Safety Inspections P/O #:G89151 Receiving #:90545 Date :2011-03-10		402557
8235	3/7/2011	292342	SENSITIVE EDGE DOOR SWITCH		402557
8235	3/6/2011	291809	Annual License -	RWC 331102 passed	402557
8235	3/2/2011	292342	WIPER REFILL SUIT TX800+T	replaced wipers	402557
8235	3/2/2011	292342	Check doors	Replaced sensitive edge	402557
8235	3/1/2011	291685	AMBER REFLECTOR SIDE MOUNT		402098
8235	#####	290701	VAN - Clean graffiti - floor si	Needed cleaning again	399567
8235	#####	291633	ST - Steering wheel cover lo	Checked OK	402098
8235	#####	291447	EN - Steamclean bus	Cleaned	401985
8235	#####	291685	Replace reflector	Replaced	402098
8235	#####	291633	COOL - Coolant leak from w	Checked OK	402098
8235	#####	290701	BOD - Polish exterior panels	Polished & touched up	399567
8235	#####	290701	UNREPORTED Acc Dam - Re	Replaced No 3 NS panel makeup & fit clean graffiti	399567
8235	#####	290701	UNREPORTED Acc Dam - Re	Polished needs decals	399567
8235	#####	290701	2MM X 1200MM X 2400MM FLAT ALUMINIUM		399567
8235	#####	290701	UNREPORTED Acc Dam - Re	Prep & painted NS 3 refit polished & touched up 456 & 7	399567
8235	#####	290708	Direct Purchase - ELECTRICAL		400101
8235	#####	289599		Inspect radiator and charge air cooler for dirt - clean	397919
8235	#####	289599		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	397919
8235	#####	289599		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	397919
8235	#####	290701	VAN - Clean graffiti - floor si	Cleaned	399567
8235	#####	290661	Clean a/c filters	Cleaned	399446
8235	#####	290701	PD - Adjust rear door	Adjusted	399567
8235	#####	290708	GB - Mounting clamp missir	Replaced	399567
8235	#####	290708	EL - LHF lower marker light	Replaced	399567
8235	#####	290701	BOD - Clean air condition fil	Cleaned	399567
8235	#####	290701	BOD - Replace rear door sei	Repaired with sikaflex	399567
8235	#####	290701	UNREPORTED Acc Dam - Re	Repair only need to polish	399567
8235	#####	290621		Service T - Replace Transmission Oil & Filter	399446
8235	#####	290621	FILTER TRANSMISSION ZF 4: ZF	Transmission Filter	399446
8235	#####	290621		Bus Safety Inspection	399446
8235	#####	290621	ZF SYNTHETIC GEARBOX OIL ZF Ecofluid A Plus Synthetic Transmission Oil		399446

8235	#####	282271	SINGLE WABCO AIR DRYER KIT 0500LE		378162
8235	#####	289599	Replace final drive oil		397919
8235	#####	289599	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals		397919
8235	#####	289599	Check oil level in transmission - top up if required		397919
8235	#####	289599	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks		397919
8235	#####	289599	Check and clean cartridge in dry tyre air cleaner		397919
8235	#####	289599	Replace pre and main fuel filters		397919
8235	#####	289599	Overhauled air dryer unit	Replace air dryer canister clean silence and drain reservoir	397919
8235	#####	289599		Replace angle drive oil	397919
8235	#####	289599		Test coolant level - top up if required to equate to 37C frost protection	397919
8235	#####	289599		Replace power steering filter and check level (Replace oil if required)	397919
8235	#####	289599	FUEL FILTER MERC 0500LE		397919
8235	#####	289599	FUEL FILTER 0500LE		397919
8235	#####	289599	AIR DRYER CANISTER VOLVO+ NL202		397919
8235	#####	289599	POWER STEER FILTER B10M		397919
8235	#####	289718	Repair windscreen washer p	Repaired	398040
8235	#####	274507	SUS - left airbag weak	Checked OK	361781
8235	#####	289551	WEDGE GLOBE INSTRUMENT 24V 2W		397555
8235	#####	274507	COMM - No radio - has disa	Checked OK	361781
8235	#####	289604	Replace seat squabs - OS 9	Replaced	398040
8235	#####	289604	BOD - Drivers seat - replace	Replaced	398040
8235	#####	289604	BOD - Paint till stand	Painted	398040
8235	#####	289604	BOD - Remove Grendas nan	Removed & polished	398040
8235	#####	289604	Replace & paint NS mirror	Replaced & painted	398040
8235	#####	289604	BOD - Secure rear modesty	Secured front & rear	398040
8235	#####	289604	BOD - Replace emer exit pu	Checked OK	398040
8235	#####	289604	BOD - secure all lower skit p	Secured	398040
8235	#####	289604	BOD - Replace interior deca	Checked OK	398040
8235	#####	289604	BOD - replace mud flaps - N	Checked OK	398040
8235	#####	289718	Replace main air pipe	Replaced new compressor main air pipe	398040
8235	#####	282271	HALDEX COIL KIT 0500LE	Coil Kit	378162
8235	#####	282271	DRAIN VALVE KIT BOTTTOM	Valve Kit	378162
8235	#####	282271	HALDEX COIL BASE OIL SEPE	Base	378162
8235	#####	282271	WATER SEPERATOR SCANIA	Water Seperator Kit	378162
8235	#####	289598		Clean A/C filter	397919
8235	#####	289598		Grease AC Compressor Clutch Bearing	397919
8235	#####	289598		Tension Wheel Nuts To OEM Specification	397919
8235	#####	289598		A Service & Bus Safety Inspection	397919
8235	#####	289551	Replace parking light globe	Replaced parker & indicator globes	397555
8235	#####	289428	Add coolant	Added	397555
8235	#####	289150	Clean a/c filter	Cleaned	396780
8235	#####	289236	PD- adjust rear doors	fixed	397316
8235	#####	289137	Reattach w/arch strip	Reattached	396780
8235	2/9/2011	288931	ANN - Annual Body Inspecti	Inspected	396397
8235	2/9/2011	289056	door wont close	Rectified	396780
8235	2/9/2011	289056	door wont close	Adjusted checked OK	396780
8235	2/9/2011	288874	CUSHION EXHAUST PIPE		396397
8235	2/8/2011	288885	PD - Rear door sensitive edg	Adjusted	396397
8235	2/8/2011	288874	EXH - 2 muffler mounts brol	Replaced 3 mounts.	396397
8235	2/8/2011	288874	EXH - 2 muffler mounts brol	Fixed	396397
8235	2/8/2011	288874	EL - NS front parker top 2 LE	Fixed	396397
8235	2/8/2011	288885	COOI - Pin hole in trans cool	Repaired	396397
8235	2/8/2011	288885	COMM - Head of the CD pla	Checked ok	396397
8235	2/8/2011	288359	BRK - brakes need checking	Fixed	394541
8235	2/8/2011	288359	BRK - brakes need checking	Replaced brake (o/s rear) boost checked and adjust brake road tested.	394541
8235	2/8/2011	288359	rear rhs brake booster	Creditor #-:WHT001 WHITEHORSE TRUCKS P/O #:G88183 Receiving #:89320 Date :2011-02-08 8235	394541
8235	2/7/2011	288359	BRK - brakes need checking	Remove wheels inspect rear brakes cleaned hard grey substance of OSrear brake rotor	394541
8235	2/7/2011	288359	BRK - brakes need checking	Checked and found OS rear booster u/s	394541
8235	2/4/2011	279780	O/S REAR DECALS	Creditor #-:ATT001 ATTITUDE SIGNS P/O #:G85734 Receiving #:89237 Date :2011-02-04	394541
8235	#####	287188	Clean a/c filters	Cleaned	393312
8235	#####	279780	L/H MIRROR ARM LONG (PM8844-1)		371057
8235	#####	279780	BOD - ns mirror arm broken	fixed	392314
8235	#####	279780	BOD - ns mirror arm damag	replaced	392314
8235	#####	286704	BOD - ns mirror broken	fixed	392314
8235	#####	286636	check ABS for possible fault	checked linings and sensors and road tested but could not fault	391184
8235	#####	286636	Breakdown - Chadstone SC - road tested but could not fault		391184
8235	1/7/2011	284510	GLOBE INST 24V 2W		386177
8235	1/6/2011	284510	Replace dash light globes	Replaced	385643
8235	1/4/2011	284046	GB - check erratic shift patt	R/tested bus g/box changing OK	385019
8235	#####	282319	POS 1-5 11R NEW	Creditor #-:BEA001 BEAUREPARES P/O #:G86247 Receiving #:87772 Date :2010-12-29	382433
8235	#####	283504	Replace dash light globe	Replaced	382433
8235	#####	283504	GLOBE INST 24V 2W		382433
8235	#####	282319	replace worn tyre pos 1-5	replace worn tyre pos 1-5	378417
8235	#####	282418	Replace NS front & OS rear	Replaced	378417
8235	#####	282270		Replace engine oil breather kit	378162
8235	#####	282270	ENGINE OIL BREATHER KIT 0500LE		378162
8235	#####	282270		Grease AC Compressor Clutch Bearing	378162
8235	#####	282270	AIR FILTER MERC 0500LE		378162
8235	#####	282270	OIL FILTER 1725+0500LE		378162
8235	#####	282270	ENGINE OIL DELO 400LE 15W40		378162
8235	#####	282270		Tension Wheel Nuts to Spec	378162
8235	#####	282270		A Service & Bus Safety Inspection	378162
8235	#####	282270		D-Service & Bus Safety Inspection	378162
8235	#####	282271	Done in RSI	Re-kit Air Cyclone Separator	378162
8235	#####	282270		Clean A/C filter	378162
8235	#####	282270		Grease AC Compressor Clutch Bearing	378162
8235	#####	282270		Tension Wheel Nuts To OEM Specification	378162

8235	#####	265444	Add coolant	Added		344015
8235	#####	265444	Add coolant	Added		344015
8235	#####	262454	K003800	Creditor #:TRA004 TRADE BRAKE-CLUTCH CO. P/O #:G80172 Receiving #:81550 Date :2010-07-31	8235	343573
8235	#####	262454	K003799	Creditor #:TRA004 TRADE BRAKE-CLUTCH CO. P/O #:G80172 Receiving #:81550 Date :2010-07-31	8235	343573
8235	#####	262454	COMPRESSOR HOSE	Creditor #:ENZ001 Enzed Dandenong P/O #:G79761 Receiving #:81203 Date :2010-07-23	8235	343573
8235	#####	262454	rear rotors	Creditor #:MUL001 MULTISPARES LTD P/O #:G79727 Receiving #:81079 Date :2010-07-23	8235	343573
8235	#####	262454	Check rear brake	Removed nsr brake one way valve ordered parts. Removed one way valve from bus 251 fitted to 8235 road tested. Fitted new one way valve to bus 251 fitted wheels back. Replaced broken dip stick and radiator cap.	8235	343573
8235	#####	262454	Check rear brakes	Fit t piece on nsr brake booster and road test.		343573
8235	#####	262454	50G2536W lrs rear b/boost	Creditor #:MUL001 MULTISPARES LTD P/O #:G80327 Receiving #:81865 Date :2010-08-10	8235	343573
8235	#####	262454	50G2808W SHUTTLE VALVE	Creditor #:MUL001 MULTISPARES LTD P/O #:G80674 Receiving #:81850 Date :2010-08-10	8235	343573
8235	#####	262454	L/TAB	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G80275 Receiving #:81660 Date :2010-08-04	8235	343573
8235	#####	264520	RED REFLECTOR 94X44MM			343573
8235	#####	264520	AMBER REFLECTOR SIDE MOUNT			343573
8235	8/9/2010	262454	Check rear brakes	Started the bus and found NS booster air fitting T joint snapped hoist bus up		343573
8235	8/9/2010	262454	Check rear brakes	Removed rear callipers and fitted new ones adjusted brakes & fitted wheels		343573
8235	8/9/2010	262454	Check rear brakes	fit new caliper pads & wheels		343573
8235	8/9/2010	264520	Accident Damaged # 31218	Fitted new NS - OS rear bumper corner to bus		343573
8235	8/9/2010	264520	Accident damage no 31202	Fitted panels to bus		343573
8235	8/9/2010	264520	Accident Damaged # 31218	Prep & paint & clean up		343573
8235	8/9/2010	264520	Accident damage no 31202	Paint black inside sand outside mask and paint silver		343573
8235	8/9/2010	264520	ACC - Body damage			343573
8235	8/6/2010	264520	F/GLASS REAR N/S BUMPER CORNER			343573
8235	8/5/2010	262454	Check rear brakes	Remove rear caliper		343573
8235	8/4/2010	262454	Check rear brakes	Fitted rear hubs adjusted bearings found wrong caliper fitted to rear axle		343573
8235	8/4/2010	262454	Check rear brakes	Begin to remove rear caliper		343573
8235	8/4/2010	262454	Check rear brakes	Adjusted compressor head relief valve 3 flats on the nut		343573
8235	8/3/2010	262454	Check rear brakes	Fit o/s rear caliper		343573
8235	8/3/2010	264279	FITTING MERCEDES COMPRESSOR			343573
8235	8/3/2010	264279	VALVE SAFETY BLOW OFF 1.3MP			343573
8235	8/2/2010	262454	Check rear brakes	Prep new calipers with old caliper anchor and fit to bus		343573
8235	8/2/2010	262454	Check rear brakes	Fitted both rear brake rotors and hub		343573
8235	8/2/2010	264279	AIR - fit compressor head sa	Removed plug in head of compressor and fit relief valve		343573
8235	#####	263430	HALDEX CONDENSER KIT TOP			343573
8235	#####	262454	Check rear brakes	Removed NS caliper & hub		343573
8235	#####	263430	HALDEX COIL KIT OIL SEPARATOR			343573
8235	#####	263430	WATER SEPARATOR SCANIA+VOLVO			343573
8235	#####	263430	HALDEX COIL BASE OIL SEPARATOR			343573
8235	#####	263430	Rekit oil separator	Cleaned up rekit and fitted back to bus		343573
8235	#####	262454	Check rear brakes	Cont to remove rear hubs		343573
8235	#####	262454	Check rear brakes	Removed rear wheels hubs & calipers		343573
8235	#####	262454	CALIPER SHEAR ADAPTOR			343573
8235	#####	259742	WEDGE GLOBE INSTRUMENT 24V 3W			343573
8235	#####	259742	CLEAR FRONT INDICATOR WRAP-AROUND			343573
8235	#####	262454	Check rear brakes	Removed rear wheel - need to replace rotors		343573
8235	#####	259742	COOL - radiator leak	Fitted front axle air fitting OS front indicator lamp & adjusted front door		343573
8235	#####	259742	WATER SEPARATOR SCANIA+VOLVO			343573
8235	#####	259742	COOL - radiator leak	Fitted radiator intercooler & rekit water separator topped up coolant		343573
8235	#####	259742	COOL - radiator leak	SACHIN - Assisted Kumar to fix radiator intercooler on bus		343573
8235	#####	261773	AIR DRYER CANISTER VOLVO+ NL202			343573
8235	#####	259742	COOL - radiator leak	Assembled radiator		343573
8235	#####	259742	COOL - radiator leak	Fit radiator shroud & cut bracket NS rear to allow easy fit		343573
8235	#####	261773	AIR S - fit air line	Ref to w/order 259742		343573
8235	#####	261773	AIR S - fit air line	fitted air line fitting to union wrong one supplied order new one		343573
8235	7/9/2010	259742	WATER SEPARATOR SCANIA+VOLVO			343573
8235	7/8/2010	259742	COOL - radiator leak	Clean oil separator parts		343573
8235	7/7/2010	259742	COOL - radiator leak	Re kit air dryer		343573
8235	7/6/2010	259742	COOL - radiator leak	Clean air dryer housing.		343573
8235	7/6/2010	259742	COOL - radiator leak	Rekit separator (not complete) Remove air dryer and separator.		343573
8235	7/1/2010	259742	COOL - radiator leak	Removed & replaced air compressor removed radiator		343573
8235	7/1/2010	259742	COOL - radiator leak	Removed intercooler		343573
8235	#####	259742	COOL - radiator leak	diagnose compressor		343573
8235	#####	259050	HOSE ENG TO G/BOX COOLER MERC 0500LE			343573
8235	#####	259127	BD - coolant leak @ Knox Ci	Ref down from tow truck use workshop air line		343573
8235	#####	259127	BDY - damage need to be	Assembled new (painted) o/s rear b/bar corner drilled all holes replaced reflector. Painted n/s front corner and n/s panel 5 & 6. Repaired n/s front b/bar corner applied fibre glass and then body filler sanded and painted grey primer and painted final coat of orange two pack		343573
8235	#####	259050	Breakdown. Knox City s/c.	Took 619 van to deliver parts for bus 8235 and assisted with brake down work. Brought mechanic back to workshop. Departed 6:42pm returned 8:30pm. Assistance only and delivery of the relevant parts.		343573
8235	#####	259050	Breakdown. Knox City s/c.	No coolant. Take 8297 for changover. Changed coolant hose found radiator split. Tow truck called. Air seems to be blowing into coolant system when bus is running.		343573
8235	#####	258556	AD0015428418 SPEED SENS	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G78568 Receiving #:79981 Date :2010-06-21	8235	343573
8235	#####	258556	AD0004292124 AXLE MOD	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G78568 Receiving #:79981 Date :2010-06-21	8235	343573
8235	#####	258556	AD0554927644 POPORTION	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G78568 Receiving #:79981 Date :2010-06-21	8235	343573
8235	#####	258470	32MM LOOSE WHEEL NUT INDICATOR			342698
8235	#####	258556	AIR - Air leak at front	Replaced front proportional relay valve replaced rear modulator valve r/tested		342698
8235	#####	258556	AIR - Air leak at front	Investigate air leak - coming from proportional relay valve - no parts		342698
8235	#####	258479	Breakdown - Endeavour Hill	C/O bus 202. Checked oil coolant engine light staying on. R/tested found air leak		342698
8235	#####	258470	Replace speed sensor	Installed new sensor to rear side rear brake torqued wheels. New sensor had to have harness mounted in different location r/tested and checked codes		342698
8235	#####	247867	WATER SEPARATOR SCANIA+VOLVO			342649
8235	#####	247867	MAKE UP COOL OFF PIPE	Creditor #:PND001 P & N Diesels Pty Ltd P/O #:G78363 Receiving #:79737 Date :2010-06-10	8235	342649
8235	#####	247867	HALDEX COIL KIT 0500LE			342649
8235	6/9/2010	247867	EN - Compressor head gaski	Rekit pipes from air comp ass Dulkith		342649
8235	6/9/2010	247867	EN - Compressor head gaski	Fixed air pipe line compressor to air dryer and rekit water separator		342649
8235	6/9/2010	257800	Replace coolant sensor	Replaced sensortightened loose axle nuts s/clean motor fit floor back mopped r/tested fuelled & parked		342649
8235	6/9/2010	257781	Replace NS & OS rear & fro	Replaced brushes & refitted yellow inserts inside to rear steps		342649
8235	6/8/2010	247867	CARBON CLEAN PIPE	Creditor #:PND001 P & N Diesels Pty Ltd P/O #:G77936 Receiving #:79645 Date :2010-06-08	8235	342649
8235	#####	247867	EN - Compressor head gaski	fixed air compressor but still air pumping to coolant disconnect air outlet line. compressor ok. compressor to air dryer air line block. removed all air pipe cant clean.		342649
8235	#####	247867	EN - Compressor head gaski	fit air compressor remove blocked air line		342649
8235	#####	247867	49A9446 COMP GASKET	Creditor #:MUL001 MULTISPARES LTD P/O #:G77581 Receiving #:79196 Date :2010-05-26	8235	342649
8235	#####	247867	compressor wabco 911553	Creditor #:MUL001 MULTISPARES LTD P/O #:G77581 Receiving #:79196 Date :2010-05-26	8235	342649

8235	#####	247867	EN - Compressor head gaski remove compressor	342649
8235	#####	247867	EN - Compressor head gaski Check to find fault with laptop	342649
8235	#####	247867	EN - Compressor head gaski Make a plug to block coolant go to compressor and check found compressor head faulty need replace air compressor	342649
8235	#####	247867	EN - Compressor head gaski Fit new compressor head gasket kit	342649
8235	#####	247867	a0011302315 gasket Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G77448 Receiving #:78783 Date :2010-05-13 8235	342649
8235	#####	247867	abs9115539252 gasket kit Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G77448 Receiving #:78783 Date :2010-05-13 8235	342649
8235	#####	252645	TOW BUS TO DEPOT Creditor #:ASS001 ASSOCIATED TOWING P/O #:G76937 Receiving #:78689 Date :2010-05-12	342649
8235	#####	247867	EN - Compressor head gaski Removed compressor head replaced gaskets & valves system still faulty (needs another gasket). Removed compressor head again	342649
8235	5/6/2010	247867	EN - Compressor head gaski Towed to red sq by fork lift	342649
8235	5/6/2010	247867	EN - Compressor head gaski Towed to red sq by fork lift	342649
8235	5/4/2010	247867	EN - Compressor head gaski Remove compressor head	342649
8235	5/3/2010	249246	ROAD SAFETY INSPECTIONS Creditor #:ROA001 Road Safety Inspections P/O #:G76117 Receiving #:78426 Date :2010-05-03	342649
8235	#####	252787	Replace compressor coolan Replaced	342649
8235	#####	252645	Breakdown - Hallbury - OUT C/O bus 8297. Picked up by Ranjith. Compressor head gasket failed towed bus back. (Need to repair compressor cylinder head gasket)	342649
8235	#####	251918	ACC - Paint rear bumper bar Temp repaired to get bus back on road	340543
8235	#####	251918	ACC - Paint rear bumper bar Start to fix bumper then left it for Ray	340543
8235	#####	251191	CALIPER SHEAR ADAPTOR	338532
8235	#####	251191	DISC PADS SCANIA L94+0500 MERC	338532
8235	#####	251191	BR - Need to change rear br: Changed rear pads	338532
8235	#####	251191	BR - Need to change rear br: Changed rear pads	338532
8235	#####	250925	A Service & Bus Safety Inspection	338051
8235	#####	250925	Clean A/C filter	338051
8235	#####	250925	Grease AC Compressor Clutch Bearing	338051
8235	#####	250925	Tension Wheel Nuts To OEM Specification	338051
8235	#####	250925	A Service & Bus Safety Inspection	338051
8235	#####	250967	Clean a/c filter	338051
8235	#####	250886	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC	337515
8235	#####	250886	BREAKDOWN - Nunawading c/o bus 8380 replaced belt drove back to depot	337515
8235	4/8/2010	250015	Clean a/c filter	335798
8235	4/1/2010	249575	Adjust sensitive edge at rear Adjusted	334561
8235	#####	249246	RSI -annual inspection BC 117756	333947
8235	#####	248459	N/S REAR TOP DECALS Creditor #:ATT001 ATTITUDE SIGNS P/O #:G75124 Receiving #:77577 Date :2010-03-30	333947
8235	#####	247867	PASS SEAT HANDGRIP CENTRA MK 2	331238
8235	#####	248459	Accident Damaged #30665 training on metallic spray painting painted some paint coats and clear coats to practice on bus 235.	332486
8235	#####	248459	Accident Damaged #30665 repaired n/s/f bar and painted orange prep & paint n/s 45 o/s/r corner silver COB completed.	332486
8235	#####	248459	Accident Damaged #30665 removed all maskings refitted clearance lights. Refitted NSR wheel arch rubber and brush cleaned the dust around the bus body	332486
8235	#####	246756	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	329198
8235	#####	248480	Clean a/c filter	332486
8235	#####	248146	ENG - Steam clean all bus	331677
8235	#####	248146	COOL - Coolant leak from b Retighten hose clamps	331677
8235	#####	248146	FU - Diesel leak from under Retighten hose clamps s/clean	331677
8235	#####	248146	BRA - Air leak from front lef Checked air leak front relay valve air leaking	331677
8235	#####	248146	AIR - Oil pumping through a Serviced air dryer	331677
8235	#####	248459	Accident Damaged #30665 Cont work on rear corner o/s b/bar corner n/s panels (wheel arch) sanded & applied body filler for pinholes & masked up	332486
8235	#####	248459	Accident Damaged #30665 Filler work mask & prime n/s 45 filler work mask & prime	332486
8235	#####	248146	WHL - Need to match front: Checked OK	331677
8235	#####	247867	Drv entered - Vandalism Gri: Cleaned	331238
8235	#####	248146	50g1405w proportional vas Creditor #:MUL001 MULTISPARES LTD P/O #:G75451 Receiving #:77262 Date :2010-03-22 235	331677
8235	#####	248146	A/C BELT 0500 BENZ	331677
8235	#####	248146	ENG - Need to replace main Replaced	331677
8235	#####	247867	BOD - Clean graffiti - floor si Cleaned	331238
8235	#####	247867	BOD - Clean back seat - rubt Cleaned	331238
8235	#####	247867	BOD - Replace emergency e Replaced	331238
8235	#####	247867	BOD - Paint exterior mirrors Painted	331238
8235	#####	247867	BOD - Secure all lower skit ꝑ Secured	331238
8235	#####	247867	BOD - Polish exterior panels Polished n/s front/rear headers	331238
8235	#####	247867	BOD - Paint door handles fr: Touched up	331238
8235	#####	247867	BOD - Need to replace rear: 2 hand grips 2 cushion catches 1 squab & repair 1 cushion	331238
8235	#####	247867	BOD - Adjust front doors	331238
8235	#####	247867	PLASTIC TRIANGLE HANDSTRAP GREY	342649
8235	#####	247867	BOD - Paint till stand	331238
8235	#####	248452	Replace osr hang grip - roof	332486
8235	#####	247867	BOD - Clean air condition fil	331238
8235	#####	248459	Accident Damaged #30665 Refit o/s corner b/bar rear corner panels applied body filler	332486
8235	#####	248459	Accident Damaged #30170 Remove corner bar straighten scuff bar	332486
8235	#####	248143	Clean a/c filter	331677
8235	#####	248167	Add coolant	331677
8235	#####	247867	MUD FLAPS GRENDA S MF60X30GRE RED	342649
8235	#####	246756	Replace angle drive oil	329198
8235	#####	246756	Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST SONMTORQUE AFTER ENG HAS COOLED FOR 30 MIN.	329198
8235	#####	246756	Inspect radiator and charge air cooler for dirt - clean	329198
8235	#####	246756	Check and clean cartridge in dry tyre air cleaner	329198
8235	#####	246756	Replace angle drive oil	329198
8235	#####	246756	Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST SONMTORQUE AFTER ENG HAS COOLED FOR 30 MIN.	329198
8235	#####	246756	Check and clean cartridge in dry tyre air cleaner	329198
8235	#####	246756	Inspect radiator and charge air cooler for dirt - clean	329198
8235	#####	247899	G/BOX PIPE Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G75486 Receiving #:77183 Date :2010-03-18 235	331638
8235	#####	247899	COOL - Coolant leak near tr: Replaced pipe	331638
8235	#####	247867	BOD - N/S rear mud flap dai Replaced by Michael	331238
8235	#####	247867	BOD - A/C duct cracked above rear door (VG)	342649
8235	#####	247867	A/S - Air leak from top of tr: Replaced pipe	331238
8235	#####	247475	EL - red warning light & alar Replaced coolant level sender filled coolant r/tested OK	330890
8235	#####	247185	Clean a/c filter	329307
8235	#####	247171	Air leak at accumalator fitti same as below	329198
8235	#####	247171	BR - Retarder faulty bus sha same	329198
8235	#####	246813	Drv entered - Brakes Noisy repaired faulty proportioning valve	329198
8235	#####	247171	AIR S - Air leak front relay v: Ref to w/order # 246813	329198

8235	#####	241489	Ops Entered - Fault - Wipers	Fixed wiper blade arm and replaced 1 wiper blade	315199
8235	#####	241489	Add coolant	Added	314839
8235	#####	241342	Add coolant	Added	314045
8235	#####	240789	clean a/c filters	cleaned filters	312325
8235	1/6/2010	240150	REPLACE W/SCREEN	Creditor #-ELI001 ELITE WINDSCREENS P/O #:G73681 Receiving #:75153 Date :2010-01-06	311032
8235	1/5/2010	240150	Accident damage#30179#	V replaced by elite	311032
8235	#####	238511	BOSCH REGULATOR	Creditor #-PJL001 PJL DIESEL ELECTRIC P/O #:G73207 Receiving #:75039 Date :2009-12-31	310131
8235	#####	239792	Change O/S wiper blade	Changed	309911
8235	#####	239776	RF wheel bag has slight play	Checked OK	309911
8235	#####	239792	Clean radiator	S/cleaned	309911
8235	#####	239708	WEDGE GLOBE INSTRUMENT 24V 3W		309911
8235	#####	239708	WIPER REFILL SUIT TX800+TX900		309911
8235	#####	239708		Clean A/C filter	309911
8235	#####	239708		Grease AC Compressor Clutch Bearing	309911
8235	#####	239708		Tension Wheel Nuts To OEM Specification	309911
8235	#####	239708		A Service & Bus Safety Inspection	309911
8235	#####	239708		A Service & Bus Safety Inspection	309911
8235	#####	238962	Clean a/c filter	Cleaned	306184
8235	#####	238511	O.Haule alternators	completed alternator job	306184
8235	#####	238511	Brake pedal pad worn out	Refitted	305675
8235	#####	237792	POS 3	Creditor #-BEA001 BEAUREPARES P/O #:G72923 Receiving #:74737 Date :2009-12-15	305675
8235	#####	238511	CRANK DRIVE BELT 0500LE MERC		305675
8235	#####	238511	O.Haule alternators	Completed ait rebuild began fitting to bus	305675
8235	#####	238511	BEARING ALT MAN 16-240		305675
8235	#####	238511	BRAKE+ CLUTCH PEDAL PAD 0500LE		305675
8235	#####	238511	O.Haule alternators	Removed alternators and began rebuild	305675
8235	#####	238417	Battery light staying on	Checked battery light on	305675
8235	#####	238417	Battery light staying on	Battery light not on charging OK 27.7 all belts OK	305675
8235	#####	237792	Replace tyre pos 3 - punctur	replaced	303719
8235	#####	237762	Change pos 3 tyre	Changed	303181
8235	#####	237336	Add coolant	Added	301931
8235	#####	237179	Clean graffitti	Cleaned	301527
8235	#####	237146	Clean a/c filter	Cleaned	301527
8235	#####	236941	Drv entered - Vandalism Gr:	Cleaned	301120
8235	#####	236892	Clean radiator	S/cleaned	301048
8235	#####	236797	FILTER TRANSMISSION ZF 4: ZF	Transmission Filter	301048
8235	#####	236797	ZF SYNTHETIC GEARBOX OIL ZF	Ecofluid A Plus Synthetic Transmission Oil	301048
8235	#####	236797		Service T - Replace Transmission Oil & Filter	301048
8235	#####	236797		Bus Safety Inspection	301048
8235	#####	236797		A Service & Bus Safety Inspection	301048
8235	#####	236797		Clean A/C filter	301048
8235	#####	236797		Tension Wheel Nuts To OEM Specification	301048
8235	#####	236797		Grease AC Compressor Clutch Bearing	301048
8235	#####	236466	clean graffitti	cleaned graffitti	299820
8235	#####	236042	Add coolant	Added	297918
8235	#####	235336	Check for air leak	Found at seperator	296720
8235	#####	234179	Windscreen beading lock cc	Fitted back	292965
8235	#####	234179	Windscreen beading lock cc	Fitted back	292702
8235	#####	234179	Windscreen beading lock cc	Fitted back	292702
8235	#####	233247	Service	A Service & Bus Safety Inspection. completed.	290750
8235	#####	233247		Clean A/C filter	289998
8235	#####	233247		Grease AC Compressor Clutch Bearing	289998
8235	#####	233247		Tension Wheel Nuts To OEM Specification	289998
8235	#####	233247	Service	A Service & Bus Safety Inspection. completed.	289998
8235	#####	233043	Drv entered - Brakes Losing	Fit silencer on air drayer exhaust	289749
8235	#####	233159	clean a/c filter	cleaned filter	289503
8235	#####	232454	bus leaking air while travelli	check no fault found only silencer missing ordered	288633
8235	#####	232454	bus leaking air while travelli	Fit silencer	288310
8235	#####	232421		C Service	288310
8235	#####	232421		B Service	288310
8235	#####	232421		Replace filter drier	288310
8235	#####	232421		Replace compressor oil	288310
8235	#####	232421		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	288310
8235	#####	232421		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	288310
8235	#####	232421		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	288310
8235	#####	232421		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	288310
8235	#####	232421		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	288310
8235	#####	232421		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	288310
8235	#####	232421		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	288310
8235	#####	232421		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	288310
8235	#####	232421		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	288310
8235	#####	232421		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	288310
8235	#####	232421		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	288310
8235	#####	232421	FILTER DRIER THERMO KING		288633
8235	#####	232330	coolant top up	topped up coolant	287898
8235	#####	232339	keeps releasing air every ser	checked - no fault found	287491
8235	#####	231690	SINGLE AIR DRYER KIT 0500LE		287209
8235	#####	231688	right hand exterior mirror o	Fit mirror	286202
8235	#####	231690	Air leak at air dryer	Fit kit	286202
8235	#####	230441	Adjust rear door sensor	Adjusted	281235
8235	#####	230441	Ops Entered - Fault - Elec &	Checked OK	281235
8235	#####	230311		Grease AC Compressor Clutch Bearing	281235
8235	#####	230311		Tension Wheel Nuts To OEM Specification	281235
8235	#####	230311		A Service & Bus Safety Inspection	281435
8235	#####	230311		A Service & Bus Safety Inspection	281235
8235	#####	230311		Clean A/C filter	281235
8235	#####	230125	Air leaking low gauge readir	Fixed accumulator air pipe	280508

8235	#####	229893	Breakdown - Cauffield - OU1 used van 619 cleaned ramp out and returned to depot.		279912
8235	#####	228900	Drivers side convex mirror v Mirror was not cracked but found it to be loose - tightened		276709
8235	#####	227246	Grease AC Compressor Clutch Bearing		272166
8235	#####	227246	AIR FILTER MERC 0500LE		272166
8235	#####	227246	OIL FILTER 1725+0500LE		272166
8235	#####	227246	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		272166
8235	#####	227246	Tension Wheel Nuts to Spec		272166
8235	#####	227246	A Service & Bus Safety Inspection		272166
8235	#####	227246	D-Service & Bus Safety Inspection		272166
8235	#####	227246	Clean A/C filter		272166
8235	#####	227246	Grease AC Compressor Clutch Bearing		272166
8235	#####	227246	Tension Wheel Nuts To OEM Specification		272166
8235	#####	227246	A Service & Bus Safety Inspection		272166
8235	#####	226979	Overhead stop light in the b Checked OK		271165
8235	#####	226772	GLOBE 5/CONTACT 24V-10W		270762
8235	#####	226772	Overhead light stop is not w Fit stop globe in desto		270435
8235	#####	226773	R/H headlight not working Fitted headlight globe		270435
8235	#####	226257	Bus stopping warning light r Checked working		269181
8235	#####	225985	GLOBE HIGH BEAM 24V70W H1		268373
8235	#####	225985	Change halogen globe L/H/S Replaced		268373
8235	#####	223219	BOLTS AS REQUIRED Creditor #:ECO001 ECONOMY BOLT CO. P/L P/O #:G68839 Receiving #:71049 Date :2009-08-10 235		267265
8235	#####	8/7/2009	225575 Clean graffiti	Cleaned	266864
8235	#####	224703	Random vehicle audit	Completed at service	264488
8235	#####	224703	Random vehicle audit	Completed at service	264488
8235	#####	224618	I need a light on top of the t Interior lights are designed like this and we cannot do extra		264488
8235	#####	224683	Replace fleet number and tr Replaced by Attitude signs		264488
8235	#####	224616	A Service & Bus Safety Inspection		264488
8235	#####	224616	Tension Wheel Nuts To OEM Specification		264488
8235	#####	224616	Grease AC Compressor Clutch Bearing		264488
8235	#####	224616	A Service & Bus Safety Inspection		264488
8235	#####	224616	Clean A/C filter		264488
8235	#####	223538	A/C compressor mount broi Repaired mount hole on compressor fit to cradle top up comp oil fitted compressor into position and secure fitted clutch belts & wiring harness vac system & check for leaks vac again and charge align comp to crank secure all mount bolts r/tested OK		261659
8235	#####	223538	5AMP BLADE FUSE		261672
8235	#####	223538	Repair compressor harness Repair compressor harness fitted shield tested OK		261672
8235	#####	223538	A/C compressor mount broi Removed compressor removed a/c bracket		261659
8235	#####	223219	Drv entered - Air Cond Cooli Checked a/c mounts broken		261659
8235	#####	223219	Drv entered - Air Cond Cooli Problem is known		261659
8235	#####	222863	CONSUMABLE DELIVERY CH Creditor #:SMC001 SMC PNEUMATICS (AUSTRALIA) P/L P/O #:G68533 Receiving #:70408 Date :2009-07-20		261659
8235	#####	222863	VT307-5G-02 SOLENOID VA Creditor #:SMC001 SMC PNEUMATICS (AUSTRALIA) P/L P/O #:G68533 Receiving #:70408 Date :2009-07-20		261659
8235	#####	223538	AIR CON REFRIGERANT		261672
8235	#####	223538	O RING AIR CON		261672
8235	#####	223538	COMPRESSOR OIL AIR CON		261672
8235	#####	223219	A/C fault light is on Pressure tested system found unloader end cap O rings had failed had none in stock so I fitted seconds with new end caps. On inspection found left frontweld has totally broken and right front weld has started to crack believe this should be covered under warranty bus has been put off road. Did not chargeunit due to compr		261659
8235	#####	223034	REPLACE W/SCREEN Creditor #:ELI001 ELITE WINDSCREENS P/O #:G68659 Receiving #:70365 Date :2009-07-17		261252
8235	#####	223219	A/C fault light is on Checked a/c needs Bruce to look at		261143
8235	#####	223034	Large crack on side of winds Repaired by Elite		261143
8235	#####	223034	Brocken windsscrin - accident number 21505.		261143
8235	#####	222863	DOOR LIFT SOLENOID 24V 200AMP		261143
8235	#####	222863	CLIPPARD VALVE DOOR OPEN/CLOSE		260696
8235	#####	222863	Front door salinoid valve Uj Replaced door salinoid and bumper switch		260696
8235	#####	222863	Coolant leak from boost pui Checked boost pump OK		260696
8235	#####	221203	POS 5-6 11R225 REAR CAP Creditor #:BEA001 BEAUREPARES P/O #:G68071 Receiving #:70165 Date :2009-07-10		260696
8235	#####	222758	Drv entered - Passenger Doc Need to replace solenoid valve		260696
8235	#####	221796	230016 FRONT HEATER TAP Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G68173 Receiving #:70182 Date :2009-07-10 235		260696
8235	#####	222758	Breakdown - Stud Park Shoq C/O bus 264. Returned to depot and ordered parts for repair		260696
8235	7/3/2009	221995	Ops Entered - Fault - Vandal Fitted new hammer		257981
8235	7/3/2009	221995	EMERGENCY HAMMERS		257981
8235	7/3/2009	221995	Hammer knocked off Fitted new safety hammer in rear of bus		257981
8235	7/3/2009	221995	Back window hammer is mi Fitted new hammer		257981
8235	#####	221796	Ops Entered - Fault - Eng Co Returned from b/down & replaced tap		256994
8235	#####	221795	Breakdown - Monash Unive C/O bus 239. Returned to depot (replaced tap)		256994
8235	#####	221203	Replace tyre pos 56 - worn	Replaced	255369
8235	#####	221284	Add coolant	Added	255369
8235	#####	221219	BLADE WIPER 32INS		255369
8235	#####	221219	Replace windshield wipers Fit wiper inserts		255369
8235	#####	221219	Replace windshield wipers Replaced		255034
8235	#####	221084	BLADE WIPER 1MTR		255034
8235	#####	221084	Replace wiper blade	Replace blade	254696
8235	#####	221236	Change O/S/R both tyres	Changed	255369
8235	#####	221236	Change O/S/R both tyres	Changed	255034
8235	#####	221142	A Service & Bus Safety Inspection		255369
8235	#####	221142	Clean A/C filter		255034
8235	#####	221142	Grease AC Compressor Clutch Bearing		255034
8235	#####	221142	Tension Wheel Nuts To OEM Specification		255034
8235	#####	221142	A Service & Bus Safety Inspection		255034
8235	#####	220729	Add coolant	Added	253408
8235	#####	220350	WATER SEPERATOR SCANIA+VOLVO		252187
8235	#####	220350	HALDEX COIL KIT 0500LE		252187
8235	#####	220350	Rekit oil separator	Rekitted	251871
8235	#####	219863	Add coolant	Added	249955
8235	6/4/2009	219520	Left side mirror top glass bn Took from bus 260 as none in stock		248272
8235	#####	218834	A/C pulley noisy	Checked OK	246921
8235	#####	218834	DEMISTER CONTROL UNIT		246921
8235	#####	218834	Front demister heater tap le Checked OK put new demister knob in place		246921
8235	#####	218750	Add coolant	Added	246780
8235	#####	218820	Breakdown - Ringwood Stat C/O bus 228. Used strap to secure leak. (fitted air dryer canister & secured joiner with hoses)		246780
8235	#####	218711	Air leak on air drayer canist Fitted air dryer canister & secured joiner with hoses		246780

8235	#####	218711	AIR DRYER CANISTER VOLVO+ NL202		246780
8235	#####	218351	Clean A/C filter		245839
8235	#####	218351	Grease AC Compressor Clutch Bearing		245839
8235	#####	218351	Tension Wheel Nuts To OEM Specification		245839
8235	#####	218351	A Service & Bus Safety Inspection		246092
8235	#####	218351	A Service & Bus Safety Inspection		245839
8235	#####	218202	GLOBE HIGH BEAM		244982
8235	#####	218202	Replace headlight globe low	Replaced	244982
8235	#####	217676	reset rear door sensor	Set	243248
8235	#####	216486	POS 3-4 11R225 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G66569 Receiving #:68467 Date :2009-05-11	241647
8235	5/6/2009	216452	Air leaking at back	Rekit air dryer and 6way valve lower valve & r/tested	239766
8235	5/6/2009	216452	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		240128
8235	5/6/2009	216452	AIR DRYER KIT		240128
8235	5/5/2009	216486	Replace tyre pos 34 - bald	Replaced	239766
8235	5/4/2009	216452	Tyre worn No 3	Replaced 34 tyres with new	239449
8235	5/4/2009	216452	Air leaking at back	Checked air leaking from air dryer need to be rekit	239766
8235	5/2/2009	216380	Inside the bus needs a mop	Mopped the bus	239449
8235	#####	215610	Possible leak in hand brake	Check for air leak is OK	237240
8235	#####	215314	POS 5-6 11R225 NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G66215 Receiving #:67959 Date :2009-04-24	236951
8235	#####	215508	Add coolant	Added	236951
8235	#####	215314	Replace tyre pos 5 - worn	Replaced	236465
8235	#####	215394	Add coolant	Added	236465
8235	#####	215320	Change tyre # 5	Changed	236465
8235	#####	215233	A Service & Bus Safety Inspection		236465
8235	#####	215233	Clean A/C filter		236465
8235	#####	215233	Grease AC Compressor Clutch Bearing		236465
8235	#####	215233	Tension Wheel Nuts To OEM Specification		236465
8235	#####	215233	A Service & Bus Safety Inspection		236465
8235	4/9/2009	213256	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G65628 Receiving #:67674 Date :2009-04-09	232138
8235	4/8/2009	212673	DECALS AS REQUIRED	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G65792 Receiving #:67588 Date :2009-04-08	231874
8235	4/7/2009	212927	Air leak from overflow valve	Replaced overflow valve	230817
8235	4/7/2009	212673	supply and fit decals	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G65117 Receiving #:67543 Date :2009-04-07	231634
8235	4/5/2009	213256	Annual Inspection - BC 1187	Annual Inspection - BC 118728	230817
8235	4/3/2009	213633	Add coolant	Added	230822
8235	4/2/2009	212991	POS 1 11R FRONT NEW	Creditor #:BEA001 BEAUREPAIRES P/O #:G65538 Receiving #:67431 Date :2009-04-02	230817
8235	4/2/2009	212673	Accident damage no 18169	All paintwork complete	230817
8235	4/2/2009	212673	Accident Damaged No 1975	All paintwork complete	230817
8235	4/2/2009	212673	Accident damage no 18169	Assembled painted panels refitted wheel arch and cleaned	230822
8235	4/2/2009	212610	Repair & paint front bumper	Refitted all bumpers and panels as req after paint work was completed	230817
8235	4/1/2009	212277	300532 ROOF VENT 5 BLAD	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G65222 Receiving #:67389 Date :2009-04-01	230817
8235	4/1/2009	212673	Accident damage no 18169	Prepared & masked only	230817
8235	4/1/2009	212673	Accident Damaged No 1975	Prepared and masked	230817
8235	#####	212927	3197585 AIR VALVE	Creditor #:CMV001 CMV TRUCK AND BUS P/L P/O #:G65496 Receiving #:67329 Date :2009-03-31 235	230817
8235	#####	212673	Accident damage no 18169	Sanded and prepped bumper bar	230817
8235	#####	212673	Accident Damaged No 1975	Sanded and prepped w/arch and panels as req	230817
8235	#####	212991	Replace tyre pos 1 - flat	Replaced	230817
8235	#####	212928	Needs central light fitted ov	Bus was manufactured like that	230817
8235	#####	212927	50G4602 OVERFLOW VALV	Creditor #:MUL001 MULTISPARES LTD P/O #:G65501 Receiving #:67271 Date :2009-03-30	230817
8235	#####	212673	Accident Damaged No 1975	Primed only	230817
8235	#####	212673	Accident damage no 18169	Primed only	230817
8235	#####	212610	Repair & paint N/S front ma	Primed only	230817
8235	#####	212610	Repair & paint N/S rear corr	Primed only	230817
8235	#####	212610	Accident Damaged -No 180:	Primed	230817
8235	#####	212567	Inspect radiator and charge air cooler for dirt - clean		230817
8235	#####	212747	Replace O/S wiper blade	Replaced	230817
8235	#####	212747	Rear o/s two tyres need cha	Checked OK	230817
8235	#####	212747	BRAKE+ CLUTCH PEDAL PAD 0500LE		230817
8235	#####	212747	WIPER REFILL SUIT TX800+TX900		230817
8235	#####	212747	DISC PADS SCANIA L94+0500 MERC		230817
8235	#####	212747	O/S rear rear air bag cracke	Checked OK	230817
8235	#####	212747	Steamclean bus	Cleaned	230817
8235	#####	212747	Repair oil leak from oil filler	Repaired	230817
8235	#####	212747	Replace brake pedal rubber	Replaced	230817
8235	#####	212747	Need to check/replace front	Replaced	230817
8235	#####	212673	Accident Damaged No 1975	Repaired panels 24 N/S both bottom corners had damage body filled and sanded 90% ready for paint. Also made new N/S panel No 5 filled new panel and sanded ready for paint	230817
8235	#####	212673	Accident Damaged No 1975	Make up wheel arch rubber	230817
8235	#####	212788	Repair & paint N/S/R roof fi	Completed with acc dam jobs	230817
8235	#####	212610	Accident Damaged -No 180: N/S rear corner repaired & applied body filler and prepared for final paint		230817
8235	#####	212610	3MM X 1200MM X 2400MM FLAT ALUMINIUM		230817
8235	#####	212567	Replace angle drive oil		230817
8235	#####	212567	Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.		230817
8235	#####	212610	Repair & paint front bumper	Applied body filler and sanded	230817
8235	#####	212610	Accident Damaged -No 180:	Applied body filler & sanded	230817
8235	#####	212610	Repair & paint N/S front ma	Removed decals and body filled dent on N/S front main rail also sanded just about ready for paint	230817
8235	#####	212567	R.S. Inspection		230817
8235	#####	212567	WATER SEPERATOR SCANIA+VOLVO		230817
8235	#####	212567	Replace final drive oil		230817
8235	#####	212567	Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals		230817
8235	#####	212567	Check oil level in transmission - top up if required		230817
8235	#####	212567	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks		230817
8235	#####	212567	Check and clean cartridge in dry tyre air cleaner		230817
8235	#####	212567	Replace pre and main fuel filters		230817
8235	#####	212567	Replace air dryer cansiter clean silence and drain reservoir		230817
8235	#####	212567	Test coolant level - top up if required to equate to 37C frost protection		230817
8235	#####	212567	Replace power steering filter and check level (Replace oil if required)		230817
8235	#####	212567	FUEL FILTER MERC 0500LE		230817
8235	#####	212567	FUEL FILTER 0500LE		230817

8235	#####	212567	AIR DRYER CANISTER VOLVO+ NL202		230817
8235	#####	212567	POWER STEER FILTER B10M		230817
8235	#####	212610	Replace A/C plastic duct insi Replaced damaged fibreglass duct with new one just about ready for paint		230817
8235	#####	212610	Repair & paint N/S rear corr Repaired fibreglass		230817
8235	#####	212610	Accident Damaged -No 180: Repair n/s/r		230817
8235	#####	212610	Repair & paint front bumper Repaired fibreglass sanded		230817
8235	#####	212277	DOOR COVER VENT Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G65222 Receiving #:67164 Date :2009-03-24 235		230318
8235	#####	212277	Adjust front doors Adjusted		230208
8235	#####	212277	Clean air condition filter sec Cleaned		230208
8235	#####	212277	Paint door handles - front Painted		230208
8235	#####	212277	Paint till stand Painted		230208
8235	#####	212277	Safety triangles and decals - Rplaced		230208
8235	#####	212277	Paint exterior mirrors and a Checked OK		230208
8235	#####	212277	Polish N/S No 1 panel Polished		230208
8235	#####	212277	Polish exterior panels/head Polished		230208
8235	#####	212277	Replace wheel arch brush - 1 Replaced		230208
8235	#####	212277	Secure all lower skit panels Secured		230208
8235	#####	212277	Emer/exit door side window Checked OK		230208
8235	#####	212277	Replace emergency exit pus Replaced		230208
8235	#####	212277	Replace Exit Only on rear dc Replaced		230208
8235	#####	212277	Replace Licensed to carry (N Replaced		230208
8235	#####	212277	Replace safety triangle deca Replaced		230208
8235	#####	212277	Clean graffiti - floor seats s/r Cleaned		230208
8235	#####	212277	Polish N/S rear side window Checked OK		230208
8235	#####	212277	Replace emergency exit dec Replaced		230208
8235	#####	212296	Ops Entered - Fault - Engine Checked OK		230208
8235	#####	212075	Recall for fuel line upgrade ! Repaired by W/horse		229822
8235	#####	211744	Annual RSI inspection Inspected		229145
8235	#####	211709	Add coolant Added		228735
8235	#####	211159	WEDGE GLOBE INSTRUMENT 24V 3W		227195
8235	#####	211159	CLEAR FRONT INDICATOR WRAP-AROUND		227195
8235	#####	211159	Park light lens need replace Replace len		227028
8235	#####	211164	REPLACE INDICATOR PARK l Replace indicator and park light globe		227028
8235	#####	211064	A/C BELT 0500 BENZ		227028
8235	#####	211064	Breakdown - Carrum Downs C/O bus 264 Replace belts on site		226760
8235	#####	210991	AIR FILTER MERC 0500LE		227028
8235	#####	210991	OIL FILTER 1725+0500LE		227028
8235	#####	210991	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		227028
8235	#####	210991	Grease AC Compressor Clutch Bearing		227028
8235	#####	210991	Tension Wheel Nuts To Spec		227028
8235	#####	210991	A Service		227028
8235	#####	210991	D Service		227195
8235	#####	210991	A Service		227195
8235	#####	210991	D Service		227028
8235	#####	210991	Grease AC Compressor Clutch Bearing		227028
8235	#####	210991	Tension Wheel Nuts To OEM Specification		227028
8235	#####	210991	A Service		227028
8235	#####	210991	A Service		227195
8235	3/9/2009	210911	Indicator u/s Replace light		226760
8235	3/9/2009	210910	Loose mirror Secure mirror		226760
8235	#####	209763	A/C boost pump fitting cool SECURED HOSES - CHECKED O/K.		223200
8235	#####	209763	Oil in intercooler pipe under REPLACED PARTS TO BREATHER CORRECTLYR/TESTED O/K.		223200
8235	#####	209763	Coolant pipe hose clamp bn REPAIRED		223200
8235	#####	209434	Accident damage - no numb: Repair wheel arch panel polish and replace wheel arch brush		222231
8235	#####	208917	Add coolant Added		220600
8235	#####	204181	SUPPLY AND FIT DECALS Creditor #:ATT001 ATTITUDE SIGNS P/O #:G63209 Receiving #:66081 Date :2009-02-13		199819
8235	#####	208464	Grease AC Compressor Clutch Bearing		192003
8235	#####	208464	A Service		19413
8235	#####	208464	Tension Wheel Nuts To OEM Specification		192003
8235	#####	208464	A Service		192003
8235	#####	208398	Change belts Changed belts & replaced missing bolt		192003
8235	#####	208398	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		18842
8235	#####	208398	Change belts Assist to change belt		18842
8235	2/5/2009	207967	Add oil Added		216892
8235	2/3/2009	181747	WARRANTY REPAIR Creditor #:SOU005 SOUTHERN STATES THERMO KING P/O #:G61263 Receiving #:65665 Date :2009-02-03		216609
8235	2/3/2009	207682	HEAD LIGHT GLOBE 24V 70/75W		216609
8235	2/3/2009	207682	Replace headlight globe Replaced		216609
8235	#####	206654	AIR DRIER REPAIR KIT Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G63233 Receiving #:65526 Date :2009-01-28 BUS 235		214311
8235	#####	206688	Broken rear door glass Repaired		212268
8235	#####	206654	Repair air leaks on front dox Replaced gway valve seal		212268
8235	#####	206654	Repair air leaks on front dox Checked need mechanic to repair		212268
8235	#####	206654	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		212229
8235	#####	206654	Repair air leaks on front dox Checked out door and adjusted alt belt		212229
8235	#####	206524	Refill coolant Refilled		211772
8235	#####	205947	POS 5 11R225 NEW Creditor #:BEA001 BEAUREPARES P/O #:G63372 Receiving #:65275 Date :2009-01-16		211639
8235	#####	206355	L wiper goes to far left Ass Greg with wipers		211888
8235	#####	206355	L wiper goes to far left Repaired wipers N/S shaft broken and adjusted		210829
8235	#####	206278	Refill coolant Refilled		210829
8235	#####	205863	POLISH WINDSCREEN Creditor #:KNI001 KNIGHTS WINDSCREEN REPAIRS P/O #:G63353 Receiving #:65248 Date :2009-01-15		211188
8235	#####	205947	Replace tyre pos 5 - worn Replaced		210013
8235	#####	205968	Change pos 5 tyre Changed		210013
8235	#####	205968	Change pos 5 tyre Changed		209691
8235	#####	205968	Ops Entered - Engine Checked OK		209691
8235	#####	205328	AIR DRIER KIT Creditor #:PSS001 PARTS SUPPLY SOLUTIONS P/O #:G63184 Receiving #:65090 Date :2009-01-12 235		209691
8235	#####	205897	A Service		210013
8235	#####	205897	Grease AC Compressor Clutch Bearing		209691
8235	#####	205897	Tension Wheel Nuts To OEM Specification		209691

8235	#####	205897		A Service	209691
8235	#####	205863	N/S w/screen need to polish	Polished by Knights	209691
8235	1/6/2009	205328	Check air dryer	Pulled out airdryer from 220 and fitted it to 235 fuelled & parked	208493
8235	1/5/2009	205224	Add coolant	Added	208269
8235	1/5/2009	205327	Breakdown - Dandenong Fr	Used van 619. Returned to depot for repairs. (remove air dryer & replaced)	208269
8235	1/5/2009	205328	Check air dryer	Remove air dryer	208269
8235	#####	204181	Accident Damage No19047	Completed repairs	204676
8235	#####	204181	Accident Damage No19047	Cont repairs on panels 4 & 5	204676
8235	#####	204181	AMBER REFLECTOR SIDE MOUNT		204676
8235	#####	204181	Accident Damage No19047	Cont repairs on panels	204676
8235	#####	204181	3MM X 1200MM X 2400MM FLAT ALUMINIUM		204676
8235	#####	204181	Accident Damage No19047	Began repairs on panels	204676
8235	#####	203568	Refill coolant	Refilled	204676
8235	#####	203665	Breakdown - Northland Sho	C/O bus 262. Removed panel driven to depot off road for repairs	204676
8235	#####	203384	DISC PADS SCANIA L94+0500 MERC		204000
8235	#####	203384	Rear brake pads low	RYAN - Changing rear brake pads	204309
8235	#####	203384	Rear brake pads low	Changed pads	204000
8235	#####	203312	Adjust rear door sensors	Adjusted	204000
8235	#####	202397	WIPER REFILL SUIT TX800+TX900		201105
8235	#####	202397	Drv entered - Wipers & Was	Replaced wiper blades	201105
8235	#####	202397	Need wire for emergency hammer		201105
8235	#####	202333	FILTER TRANSMISSION ZF 4: ZF	Transmission Filter	200699
8235	#####	202333	ZF SYNTHETIC GEARBOX OIL ZF	Ecofluid A Plus Synthetic Transmission Oil	200699
8235	#####	202333		Service T - Replace Transmission Oil & Filter	200699
8235	#####	202333		Tension Wheel Nuts To OEM Specification	200699
8235	#####	202333	RYAN & MEC	A Service	200699
8235	#####	182465	BLADE WIPER 1MTR		192144
8235	#####	182465	Annual Random Audit	Completed	192144
8235	#####	182449		A Service	192144
8235	#####	182449		Tension Wheel Nuts To OEM Specification	192144
8235	#####	182449		A Service	192398
8235	#####	182449	RYAN	A Service	192398
8235	#####	181747	Drv entered - Air Cond Air C	Repaired by Thermoking	189759
8235	#####	181747	Air conditioning blowing ho	Checked out A/C not cooling	189759
8235	#####	181265	LED CLEARANCE LIGHT (RED AMBER)		188646
8235	#####	181265	Replace red/amber LED	Replaced	188646
8235	#####	180321	Bus wont start	Jump started	185255
8235	#####	180236	Bus wont start	Jump started	184967
8235	#####	180236	Bus wont start	Jump started	185255
8235	#####	180222		B Service	184967
8235	#####	180222		Replace filter drier	184967
8235	#####	180222		Replace compressor oil	184967
8235	#####	180222	FILTER DRIER THERMO KING		185255
8235	#####	180222	Service as per list- tension c	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	184967
8235	#####	180222		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	184967
8235	#####	180222		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	184967
8235	#####	180222		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	184967
8235	#####	180222		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	184967
8235	#####	180222		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	184967
8235	#####	180222		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	184967
8235	#####	180222		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	184967
8235	#####	180222		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	184967
8235	#####	180222		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	184967
8235	#####	180222		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	184967
8235	#####	179661	Interior light not working	Checked OK	183132
8235	#####	179644	Emergency hammer stolen	Replaced hammer	183132
8235	#####	179527	Replace alt mounting bolt	Replaced	182369
8235	#####	179457	Direct Purchase - MECHANICAL		182369
8235	#####	179457	ENGINE OIL DELO 400 15W-40	MULTIGRADE/ NEW OIL	182369
8235	#####	179457		Tension Wheel Nuts to Spec	182369
8235	#####	179457		A Service	182369
8235	#####	179457		D-Service	182369
8235	#####	179457		Tension Wheel Nuts To OEM Specification	182369
8235	#####	179457		A Service	182369
8235	#####	179360	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		182369
8235	#####	179360	Alternator belt cracked	Replaced belt	181979
8235	#####	179360	Alternator belt cracked	Replaced belt	181979
8235	#####	178247	N/S REAR PARKER U/S.	replaced n/s/r. clearance light	178148
8235	#####	178247	LED CLEARANCE LIGHT (RED AMBER)		178148
8235	#####	178035	Retarder light on dash stays	Reset switch to correct position	176981
8235	#####	176906	Inspect for driveline warran	Checked for driveline no faults found	173334
8235	#####	176778	Service	Checked Ok	173334
8235	#####	176838	Remove rear tyres and chec	Removed checked OK	173085
8235	#####	176702		A Service	173085
8235	#####	176702		Tension Wheel Nuts To OEM Specification	173085
8235	#####	176702		A Service	173085
8235	#####	176702	AIR FILTER MERC 0500LE		173085
8235	#####	176041	GLOBE HIGH BEAM		170306
8235	#####	176041	O/S. Headlight U/S.	Replaced headlight globe	169921
8235	#####	176041	Front drivers side headlight n/w		169921
8235	#####	175806	Front door not shutting pro	Adjusted front door	169600
8235	#####	174444	Remove graffiti	Removed	164617
8235	#####	174343		A Service	164122
8235	#####	174343		Tension Wheel Nuts To OEM Specification	164122
8235	#####	174343		A Service	164122
8235	#####	172008	POS 4	Creditor #:BEA001 BEAUREPAIRES P/O #:GS8000 Receiving #:60592 Date :2008-07-29 REAR CAP 11R	164122
8235	#####	173238	Pin to small could not fit in	Make up & fit new till pin	159840

8235	#####	165141		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	133195
8235	#####	165141	Service	Replace power steering filter and check level (Replace oil if required)	133195
8235	#####	165141	FUEL FILTER MERC 0500LE		133195
8235	#####	165141	FUEL FILTER 0500LE		133195
8235	#####	165141	AIR DRYER CANISTER MAN NL202+VOLVO		133195
8235	#####	165141	POWER STEER FILTER B10M		133195
8235	4/5/2008	164739	BRAZILLIAN MIRROR RH		131956
8235	4/5/2008	164739	R/H mirror needs to be repli	Replaced	131800
8235	4/4/2008	160778	POS 6	Creditor #:BEAD01 BEAUREPAIRES P/O #:G52956 Receiving #:48348 Date :2008-04-04 NEW	131800
8235	4/2/2008	164291	COMP BELT MERC 12.5X1015		130912
8235	4/2/2008	164291	Air con not working	repaired by t/xing WARRANTY REPAIRS	130912
8235	#####	164211	Check alternator belt adjust	Replaced belts ordered new top alt belts and replaced alt mounting bolts	130818
8235	#####	164211	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		130912
8235	#####	164211	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		130912
8235	#####	164211	A/C BELT 0500 BENZ		130912
8235	#####	164211	Check alternator belt adjust	Checked adjuster and replaced top alternator belt with A 40 belt (was A41) for test	130818
8235	#####	163438	Clean A/C filters	Cleaned	127996
8235	#####	163438	Remove graffiti	Removed	127996
8235	#####	163432	Service	A Service	127996
8235	#####	163432		Tension Wheel Nuts To OEM Specification	127996
8235	#####	163432	Service	A Service	127996
8235	#####	163360	Front tyres flat spotted stee	Replaced tyres & polished rims	127681
8235	#####	163340	Drv entered - Whls & Tyres'1	rep. tyre pos.1 & 2 viberate	127681
8235	3/8/2008	162821	Replaced alternator belt.	Rep. alternator belt.	125441
8235	3/4/2008	160161	POS 4+5 CAPS FITTED WROI	Creditor #:BEA001 BEAUREPAIRES P/O #:G52690 Receiving #:47626 Date :2008-03-04 FIT NEW STEER	123893
8235	#####	161714	Short in air dryer - fault cod	Repaired by Whitehorse	121602
8235	#####	160778	Replaced tyre pos. 6 - Bald.	rep. tyre pos. 6 Bald.	118521
8235	2/8/2008	160662	Change rear tyres	Changed	118285
8235	2/8/2008	160662	Clean graffitti	Cleaned	118285
8235	2/8/2008	160590	Service	A Service	118285
8235	2/8/2008	160590		Tension Wheel Nuts To OEM Specification	118285
8235	2/8/2008	160590	Service	A Service	118285
8235	2/4/2008	160161	Replaced tyre pos.4 & 5 - ba	rep. tyres pos.4 & 5 bald.	117209
8235	2/2/2008	160157	Replaced all rear tyres.	Rep. all rear tyres.	117209
8235	2/1/2008	151605	24 VOLT RELAY PANEL		117209
8235	#####	159424	Drivers fan U.S	Checked OK	116041
8235	#####	159424	A/C not working	Repaired by Volgren	116041
8235	#####	159424	A/C not working	A/C not working replace solinoide still not working	116041
8235	#####	159424	A/C not working	Replaced A/C power solinoide checked battery saver light	116041
8235	#####	159424	DOOR LIFT SOLENOID 24V 200AMP		116041
8235	#####	158592	Graffiti on inside bus rear le	removed graffitti	112869
8235	1/4/2008	157841	Service	removed graffitti	109565
8235	1/4/2008	157841	Service	A Service	109565
8235	1/4/2008	157841		Tension Wheel Nuts To OEM Specification	109565
8235	1/4/2008	157841	Service	A Service	109565
8235	#####	157152	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		107146
8235	#####	157152	REP. TOP ALTERNATOR BEL'1	rep. top alternator belt	106272
8235	#####	157111	Breakdown - Moanash UniC	Breakdown - Monash Uni alt. belt off returned to depotbus off road	106272
8235	#####	156431	Drivers till tray is cracked	repaired o/k.	104931
8235	#####	156087	GLOBE HIGH BEAM		103709
8235	#####	156087	rep. head lamp globe	rep. globe	103709
8235	#####	155305	No bin	Replaced bin	101010
8235	#####	155247	FILTER TRANSMISSION ZF 4: ZF	Transmission Filter	101010
8235	#####	155247		Service T - Replace Transmission Oil & Filter	101010
8235	#####	155247		Tension Wheel Nuts To OEM Specification	101010
8235	#####	155247		A Service	101010
8235	#####	153359	Graffiti in bus	Clean	94476
8235	#####	150329	H/LIGHT HOUSING	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G49484 Receiving #:44733 Date :2007-11-01	93974
8235	#####	152588	Partition above front door li	Secured panel screws	91503
8235	#####	152524	MOVE SCREEN	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G50188 Receiving #:44512 Date :2007-10-24	91503
8235	#####	152524	Move driverscreen		91503
8235	#####	152424	Annual random audit	Completed	91503
8235	#####	152502	Replace alt belt	Replaced	91503
8235	#####	152422	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		91503
8235	#####	152422	AIR FILTER MERC 0500LE		91503
8235	#####	152422	AIR FILTER MERC 0500LE		91503
8235	#####	152422	OIL FILTER 1.725+0500LE		91503
8235	#####	152422	ENGINE OIL DELO 400 15W-40	MULTIGRADE/ NEW OIL	91503
8235	#####	152422		Tension Wheel Nuts to Spec	91503
8235	#####	152422		A Service	91503
8235	#####	152422		D-Service	91503
8235	#####	152422		A Service	91503
8235	#####	152422		Tension Wheel Nuts To OEM Specification	91503
8235	#####	152148	LED CLEARANCE LIGHT (RED AMBER)		89939
8235	#####	152148	Rear L/H/S clearance light s	Replaced light	89576
8235	#####	151605	Service as per list	Unit requires water valve kit & L/P switch	88187
8235	#####	151605	RELAY 24V 10-20AMP(0332209204)		88610
8235	#####	151605		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	88187
8235	#####	151605		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	88187
8235	#####	151605		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blowmer motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grill	88187
8235	#####	151605		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	88187
8235	#####	151605		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	88187
8235	#####	151605		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	88187
8235	#####	151605		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	88187
8235	#####	151605		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	88187
8235	#####	151605		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	88187
8235	#####	151605		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	88187
8235	#####	151605		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	88187

8235	#####	151026	Windscreen rubber seal pop	Fit rubber back on	86514
8235	#####	151026	Left mirror loose	Fit new hut on mirror	86514
8235	#####	151025	Left mirror loose		86514
8235	#####	151025	Windscreen rubber seal popped out	leftside	86514
8235	#####	150877	Drv entered - Vandalism Gri	Checked OK	85983
8235	#####	150329	R/hand headlight not workin	Replaced headlight - Took off 217 had no parts in stock	84634
8235	#####	149814	Replace reverse buzzer	Replaced	82322
8235	#####	149746	Road test for service	A Service	82359
8235	#####	149746		A Service	82322
8235	#####	149746	NARVA 24V REVERSING BUZZER		82322
8235	#####	149746		Tension Wheel Nuts To OEM Specification	82322
8235	#####	149746		A Service	82322
8235	9/5/2007	148749	GLOBE HIGH BEAM		78756
8235	9/5/2007	148749	N/S headlight blown out	Changed headlight globe	78756
8235	9/4/2007	148666	FAN BELT A/C ARTIC		78433
8235	9/4/2007	148666	Replace alternator belts	Replaced	78433
8235	#####	146547	BRIDGESTONE R192 11.225 TYRE		72608
8235	#####	146547	One or both front tyres has	replaced tyres	72608
8235	#####	146502	Drv entered - Heat & Demis	checked o/k.	72608
8235	#####	146547	Ticket light wont adjust or n	checked o/k.	72608
8235	#####	146501	CLEANED AIR FILTER MERC 0500LE		72608
8235	#####	146501		Tension Wheel Nuts To OEM Specification	72608
8235	#####	146501		A Service	72608
8235	#####	144944	Graffiti on L/H side of bus	Removed graffiti from exterior	67003
8235	#####	144458	Front doors rattle & closing	Adjusted door & secured it - o/k.	65559
8235	7/3/2007	143505		A Service	63755
8235	7/3/2007	143505		Tension Wheel Nuts To OEM Specification	63755
8235	7/3/2007	143505		A Service	63755
8235	#####	143411	Replace main drive belt.	Replaced main serpentine belt.	63394
8235	#####	140972		A Service	54713
8235	#####	140972		Tension Wheel Nuts To OEM Specification	54713
8235	#####	140972		A Service	54713
8235	5/9/2007	138694	ROAD SAFETY INSPECTIONS	Creditor #-:ROAD001 Road Safety Inspections P/O #-:G43345 Receiving #:40540 Date :2007-05-09	46787
8235	5/7/2007	139175	Oil in intercooler pipe and b	Repaired by Whitehorse	46333
8235	5/6/2007	138694	Annual Inspection - BC 1045	Annual Inspection - BC 104972	45612
8235	5/4/2007	138511	Drv entered - Vandalism Gri	Checked ok	45430
8235	5/4/2007	138511	FAN BELT A/C ARTIC		46333
8235	5/4/2007	138511	Steam clean	Clean	45430
8235	5/4/2007	138511	Coolant leaks	Repair coolant leak at water pump replace top alternator belt remove intercooler pipe and found oil for warranty repairs clean bus and road test	45430
8235	5/2/2007	138788	Clean air condition filter	Cleaned	45745
8235	5/2/2007	138788	Repair or replace O/S No 4	Repaired & polished	45745
8235	5/2/2007	138788	Polish exterior panels/heads	Polished & touched up	45745
8235	5/2/2007	138788	Polish rear bumper bar	Polished	45745
8235	5/2/2007	138788	Secure all lower skit panels	Secured	45745
8235	5/2/2007	138788	Polish front bumper bar	Polished	45745
8235	5/2/2007	138788	Fit air supply decal	Fitted	45745
8235	5/2/2007	138788	Secure seat capsules O/S 1	Secured	45745
8235	5/2/2007	138788	Paint till stand	Painted	45745
8235	5/2/2007	138788	Accident damaged - n/s/r. corner & n/s/r. clearance light.		45745
8235	5/2/2007	138788	Accident damage no 13107 - Replace n/s panel 4 reflectorr		45745
8235	5/1/2007	138512	Annual body inspection		45430
8235	#####	138510	Drv entered - Vandalism Graffiti		45430
8235	#####	138510	Steam clean bus for RS1		45430
8235	#####	138437		D-Service	45430
8235	#####	138437		A Service	45430
8235	#####	138437		Tension Wheel Nuts to Spec	45430
8235	#####	138437	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		45430
8235	#####	138437	OIL FILTER 1725+0500LE		45430
8235	#####	138437	AIR FILTER MERC 0500LE		45430
8235	#####	138437		D Service	45430
8235	#####	138437		Tension Wheel Nuts To OEM Specification	45430
8235	#####	137932		Top-up coolant level (must equate to -37C frost protection)	44541
8235	#####	137932		Change oil in fan angle drive	44541
8235	#####	137932		Change air drier cannister; clean silencer & drain air reservoir	44541
8235	#####	137932		Change pre and main fuel filter	44541
8235	#####	137932		Check power steering oil level	44541
8235	#####	137932		Check & clean filter cartridge in dry-type air cleaner	44541
8235	#####	137932		Remove disassemble & clean cyclone separator (apply water repellent grease to electrical connections) check drainage function for leaks	44541
8235	#####	137932		Check oil level in transmission & top-up if required	44541
8235	#####	137932		Inspect radiator & charge-air cooler for dirt - clean if required	44541
8235	#####	137932		Electrical - BATTERIES: check fluid level (leave air gap when topping up) CABLES: check cable connections are firm with good contact on ALL battery terminals	44541
8235	#####	137932		Adjust Engine Valve Clearance	44541
8235	#####	137999	Repair exhaust mounts	Repaired	44541
8235	#####	137999	Tighten top alt mount & adj	Tightened up	44541
8235	#####	136459		A Service	38497
8235	#####	136459		Tension Wheel Nuts To OEM Specification	38497
8235	#####	136459		A Service	38497
8235	#####	135104	Warranty	Creditor #-:SOU005 SOUTHERN STATES THERMO KING P/O #-:G40559 Receiving #:39354 Date :2007-03-27 A/C not working	37831
8235	#####	135370	Fuel gauge reads half when	rep. by whitehorse under warranty	36315
8235	#####	135103	Replace top alternator bolts	Replaced	35906
8235	#####	135104	Air con blower not working	Repaired by ThermoKing	35906
8235	#####	135104	Drv entered - Air Cond Air C	Removed solinoid for A/C unable to fit new one wires burnt	35906
8235	#####	135104	Drv entered - Air Cond Air C	Repaired by Volgren	35906
8235	3/4/2007	134434	Hard to extend seat belt.	adjusted belt mounting	33337
8235	#####	133096	Seat belt has knots	Un tied knots. Checked seat belt is operational OK	29105
8235	2/9/2007	132601		A Service	28220
8235	2/9/2007	132601		Tension Wheel Nuts To OEM Specification	28220

8235	2/9/2007	132601	A Service		28220
8235	2/8/2007	132540	Air conditioner not working	Repaired by Thermo King	28220
8235	#####	131475	A/C.Not working at all .	REPAIRED BY SOUTHERN STATES THERMOKING	24984
8235	#####	131459	REPLACED LOWER ALTERNATOR	rep. lower alt. belt	24984
8235	#####	131440	Breakdown - No airconditioner	c/o. bus & returned to depot repaired by Thermo king under warranty.	24984
8235	#####	131440	FAN-HUB BELT SCANIA 12.5X1330MM	& Lower OSO0 Benz	24984
8235	1/7/2007	130249	Replaced top alternator belt	rep. top alternator belt	19989
8235	1/7/2007	130249	FAN BELT A/C ARTIC		20669
8235	1/4/2007	130104	Tighten alt plate boot	Tightened	19879
8235	1/4/2007	129921		A Service	19879
8235	1/4/2007	129921		Tension Wheel Nuts To OEM Specification	19645
8235	1/4/2007	129921		A Service	19645
8235	#####	129592	Breakdown - Monash Uni -	C/O bus 228. Nothing wrong with levels on arrival	16820
8235	#####	128471	A/C compressor leaking oil	Repaired by ThermoKing	12888
8235	#####	128471	Air con still U/S	Repaired by ThermoKing	12888
8235	#####	127978	Water hammer check and n	Repaired by Thermo King	11264
8235	#####	127978	Drv entered - Cool & AC Sys	Repaired by Thermo King	11264
8235	#####	127978	Drv entered - Air Cond Air C	Repaired by Thermo King	11264
8235	#####	128110	Drv entered - Elec & Light Al	Adjusted top alternator belt & secured alternator loom	11264
8235	#####	128116	Breakdown - Stud Park Shor	C/O bus 229 returned to depot. Topped up coolant & roadtested.	11264
8235	#####	127651	32MM LOOSE WHEEL NUT INDICATOR		10877
8235	#####	127651	Fit wheel nut indicators	Fitted	10877
8235	#####	127267	New Registration - DN 1009	New Registration - DN 1009922	9319
8235	#####	127142	FIRE EXTINGUISHER DECAL		9460
8235	#####	127142	SAFETY TRIANGLE DECAL		9460
8235	#####	127142	DO NOT OVERTAKE TURNIN		9460
8235	#####	127142	GIVE WAY SIGN (SMALL)		9460
8235	#####	127142	BROOM HEAD (09803211)		9460
8235	#####	127142	BROOM HANDLE (8232715)		9460
8235	#####	127142	POWDER COATED NOTICE E		9460
8235	#####	127142	Fit all regulation & safety de	Finished fitting decals	9319
8235	#####	127152	Replace wiper washer pump	Replaced	9210
8235	#####	127150	Fuel & park bus	Fuelled and parked bus	9210
8235	#####	127158	Check cameras	Checked OK	9210
8235	#####	127077		A Service	9319
8235	#####	127077		Tension Wheel Nuts To OEM Specification	9210
8235	#####	127077		A Service	9210
8235	#####	126995	Breakdown - Wellington Rd	C/O bus 227 Adjusted front door sensitive edge	9018
8235	#####	126657	Alternator belt broken	Replace belt	8142
8235	#####	126573	Door wont shut	Adjusted sensitive edge	8142
8235	#####	126205	MIRROR TOP BRAZILLIAN GLASS		7319
8235	#####	126205	Service		7319
8235	#####	126085	Front doors will not close	(v checked all o/k.	6899
8235	#####	126049	LED CLEARANCE LIGHT (RED AMBER)		6584
8235	#####	126049	L/H/S clearance light lense 1	Replace light	6319
8235	#####	125727	Warranty Service - 5000 km	Done by Whitehorse	5853
8235	#####	125728	Fit till pin as required.	Fitted	5853
8235	#####	125757	Low Coolant	Fit hose clamp to coolant hose steamclean & roadtest	5853
8235	#####	125754	Breakdown - Monash Uni -	C Low coolant took bus off road	5853
8235	#####	125637	Coolant leak near g/box.	secured hoses	5520
8235	#####	125637	Coolant leak near g/box.	secured hoses	5853
8235	#####	125298	BRAZILLIAN MIRROR L/H		4495
8235	#####	125298	Breakdown - Monash - OUT	Took bus 227 and replaced mirror	4115
8235	#####	124557	New Registration - DN 1009	New Registration - DN 100992	2315
8235	#####	124447	Front doors close and open	Call out for breakdown - adjust front door sensors	1332
8235	#####	124337	Breakdown - Wellington Rd	C/O bus 227 Returned to depot. Adjusted front door	1041
8235	#####	124028	Breakdown - Jones Rd & We	C/O bus 230 Return to depot & adjust front door sensitive edge	355
8235	#####	0	Imported Service History	Imported Service History	10
8235	#####	0	Imported Service History	Imported Service History	10
8235	#####	0	Imported Service History	Imported Service History	0
8235	#####	0	Imported Service History	Imported Service History	0
8235	#####	0	Imported Service History	Imported Service History	0
8235	#####	0	Imported Service History	Imported Service History	0
8235	#####	0	Imported Service History	Imported Service History	10
8235	5/9/2006	0	Imported Service History	Imported Service History	0