

Veh#	Date	W/O#	Description	Notes	Odometer
8231	#####	1343847	Decommission bus for SALE	Completed document email to Sue	1283789
8231	#####	1343847		Gave all bus minders and cradles to sue. Completed	1283789
8231	#####	1343962	Driver Tablet Entered -Rear_Door Operation Faulty	Decommissioned the bus for SALE	1283789
8231	#####	1343960	Mechanic entered -Body Other Fuse box hatch and battery ha	Decommissioned the bus for SALE	1283789
8231	#####	1343847	Decommission bus for SALE	Assisting	1283789
8231	#####	1343961	Mechanic entered - Air System Other Replace hose joiner (sq	Decommissioned the bus for SALE	1283789
8231	#####	1343847		Took out constat unit mdrv bus minder e tag and secured the wiring. Took out the rivets holding the number plates and put rivet nuts and screws instead. Completed	1283789
8231	#####	1343847	Mechanic entered - Elec and Light Other decomission	Took the constat unit out mdrv busminder brainbox and secured the wiring.	1283789
8231	#####	1342795	Workshop Tablet Entered -Body - Rear_Door Operation Faulty	Checked door is operating fine operated both sides and opened the panel on top to see anything wrong. Lubricate it and checked door function is fine Complete.	1283789
8231	#####	1342795		checked door and started operating and then fink squeaky noise then lubricated it and then checked ok.Complete.	1283789
8231	#####	1342795		Assisted Zakir test and lubricate the doors. Completed	1283789
8231	#####	1341922	Mechanic entered - Body Other front door sensitive edge not	adjusted front and rear both sensitive edges	1283495
8231	#####	1341553		VEHICLE SAFETY INSPECTION Completed	1283495
8231	#####	1341553		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Roshan	1283495
8231	#####	1341553		VEHICLE SAFETY INSPECTION Completed	1283495
8231	#####	1341591	Driver Tablet Entered -CCTV - Server Connectionloud beeping		1282409
8231	#####	1334569	REPLACEWINDOW	Creditor # :GB-0BR010 O'BRIENS GLASS INDUSTRIES P/O #:G408508 Receiving #:434584 Date :2026-04-17	1282409
8231	#####	1334569	PTI Tablet Entered -Body - Windows Side. os rear windows is	Replaced window by O Briens	1282409
8231	#####	1334569	Consumables		1282409
8231	#####	1329375	Consumables		1282250
8231	#####	1329375	FITTING REDUCER 4MM X 6MM METAL SMC		1282250
8231	#####	1329373	Driver Tablet Entered -Suspension - Kneeel/ Raise	secure front lavel sensor Kneeel/Raise ok.	1281587
8231	#####	1329375	Driver Tablet Entered -Body - Front_Door Operation Faulty	adjusted front door ramps doors working ok.	1281587
8231	#####	1328687		Fire Extinguisher Test & Tag - Completed by ATS - February 2026	1281587
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	OIL SAMPLE TEST KIT		1281019
8231	#####	1326844	FILTER OIL MERC BENZ 0500LE ES OH1830 ES		1281019
8231	#####	1326844	BREATHER OIL MIST MERC BENZ 0500LE		1281019
8231	#####	1326844	OIL ENGINE ALL FLEET PLUS E900 15W-40		1281019
8231	#####	1326844		CARRY OUT B SERVICE AS PER CHECK LIST completed b service as per check list tensioned wheel nuts with satheesh road tested by sisil checked for leaks no leaks found and oil level good	1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1326844	Consumables		1281019
8231	#####	1322707	Mechanic entered - CCTV Hard Drive hard drive out of date.	CARRY OUT A SERVICE AS PER CHECK LIST while doing service for CCTV find out hard drive is out of date.re-plate and checked ok.Complete.	1280222
8231	#####	1322707	HARD DRIVE SOLID STATE 1TB (17128E-P01)		1280222
8231	#####	1322705		Helped Feda carry out CCTV A service as per check list. Completed.	1280222
8231	#####	1322705		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Completed CCTV A Service as per check list.	1280222
8231	#####	1322043		VEHICLE SAFETY INSPECTION completed as per check list.	1279861
8231	#####	1322043		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Abraham	1279861
8231	#####	1310340	Consumables		1277884
8231	#####	1310340	BRUSH WHEELARCH LENGTH 75mm (2.5M PER WHEEL)		1277884
8231	#####	1310340	Driver Tablet Entered -Body - Body Damage. Not really. The r	replaced damaged brush (ostf) wheel arch rubber.	1277884
8231	#####	1300859	Engine steam Clean radiator assy	Completed Intercooler clean and cleaned engine bay	1277531
8231	#####	1306073		Assisted Guri with Saftey inspection	1277004
8231	#####	1306073		VEHICLE SAFETY INSPECTION completed as per check list.	1277004
8231	#####	1306073		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Nick	1277004
8231	#####	1306077	Consumables		1277004
8231	#####	1306077	BRUSH WHEELARCH LENGTH 75mm (2.5M PER WHEEL)		1277004
8231	#####	1306077	BRUSH WHEELARCH LENGTH 75mm (2.5M PER WHEEL)		1277004
8231	#####	1306077	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1277004
8231	#####	1306077	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1277004
8231	#####	1306077	Mechanic entered - Body Other Missing both front wheel arch	Replaced Wheel arch brushes	1277004
8231	#####	1301147	Driver Tablet Entered -A/C Heating - Not Cooling	Commission tested check heat and cool functions check refrigerant level check all fans and fan modes unable to fault	1276810
8231	#####	1299974	Consumables		1276810
8231	#####	1299974	TERMINAL ECU CONN PLUG MERC BENZ 0500LE		1276810
8231	#####	1299974	Mechanic entered - Elec and Light Other brocken connector	chane the connector pins	1276810
8231	#####	1298823	replace anti Graffitti film - Audit - # 1257	Assisting	1276810
8231	#####	1298823	replace anti Graffitti film -	Creditor # :GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G397761 Receiving #:422422 Date :2025-10-27	1276810
8231	#####	1287917	ROAD WORTHINESS INSPECTIONS -	Creditor # :GB-ROAD01 ROAD SAFETY INSPECTIONS P/O #:G394564 Receiving #:419786 Date :2025-09-16	1275093
8231	9/3/2025	1287917		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1275093
8231	9/3/2025	1287917		VEHICLE SAFETY INSPECTION completed.	1275093
8231	9/3/2025	1287917		ANNUAL SAFETY INSPECTION SERIAL # RSI 072471 - 03.09.2025 - PASSED	1275093
8231	9/3/2025	1287666	REPLACE O/S LAST WINDOW	Creditor # :GB-0BR010 O'BRIENS GLASS INDUSTRIES P/O #:G394506 Receiving #:418924 Date :2025-09-03	1275093
8231	9/2/2025	1287706		CHECKED and found the Faulty Leveling Sensor.Replaced with new one ok.	1275093
8231	9/2/2025	1287706	SENSOR LEVELLING VALVE ECAS MERC BENZ 0500LE A0015420018		1275093
8231	9/2/2025	1287706	Mechanic entered - Suspension Kneeel/ Raise Front of bus rais	Assist Satheesh by replacing leveling sensor	1275093
8231	9/2/2025	1287666	Consumables		1275093
8231	9/2/2025	1287666	Consumables		1275093
8231	9/2/2025	1287666	O/S last window cracked	Replaced o/s last window by O briens	1275093
8231	9/1/2025	1287469	Consumables		1275093
8231	9/1/2025	1287469	HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525	NOT USED	1275093
8231	9/1/2025	1287469	GLOBE HEADLAMP 24V 70W H7		1275093
8231	9/1/2025	1287469	HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525		1275093
8231	9/1/2025	1287469	Mechanic entered - Elec and Light Exterior Lights both high	checked and find only 1 light in stock and re-placed it and then took 1 good one out of 8227 scrap bus and checked it ok.Complete.	1275093
8231	9/1/2025	1287457	Consumables		1275093
8231	9/1/2025	1287457	Consumables		1275093
8231	9/1/2025	1286480	Consumables		1275093
8231	9/1/2025	1286480	Consumables		1275093
8231	9/1/2025	1287275	Consumables		1275093
8231	9/1/2025	1287457	Carryout final inspection for RSI	Minor Air leaks in the Air connecting junction in the middle of the bus and in the Air dryer Area.Temporarily fixed.Front leveling valve control Arm Replaced with Scrap bus. completed.	1275093
8231	9/1/2025	1287275		Repair crack at rear engine frame and rewelded the cracks and cleaned it up and painted it black	1275093
8231	9/1/2025	1286480	Mechanic entered - Body Body Damage Crack in frame N/S/R th	East completed repair and refer w/o 1287275	1275093
8231	#####	1286717		FIRE EXTINGUISHER TEST & TAG - COMPLETED BY ATS	1275093
8231	#####	1286480	Consumables		1275093
8231	#####	1286480	Mechanic entered - Body Body Damage Crack in frame N/S/R th	Bus at east coast and repairing	1275093
8231	#####	1285181	Mechanic entered - Engine Other Steam clean engine gearbox	Gave extensive clean of engine bay gearbox and the axles so all clean for RSI.	1274883
8231	#####	1285266	Consumables		1274883
8231	#####	1285128	Consumables		1274883
8231	#####	1285266	Mechanic entered - Elec and Light Flat Batteries x1 Dead bat	Checked how old batteries are they were installed 30/8/2024 less than a year old performed a load test and they came up decent this time. Cranking is good. Bus is in rail fleet now so might get used enough all the time to keep a healthy state.	1274883
8231	#####	1285128	Mechanic entered - Elec and Light Desto Fault N/W stuck on	Checked desto sign is stuck on bus is full checked for constat unit and restarted it but still stuck. Changed the sign to manual but still stuck pressed the information icon and found bus is full option is activated. Pressed it again to go into normal mode and checked desto sign is working fine Complete.	1274883
8231	#####	1285128		Checked with Zach was able to get it all fixed.	1274883



8231	#####	1248069	Driver Tablet Entered -Body - Drivers Seat Belt	replaced seat belt buckle Ref: W/O# 1248067	1261689
8231	#####	1248069	Driver Tablet Entered -Body - Drivers Seat Belt	as above.	1261689
8231	#####	1248069	Driver Tablet Entered -Body - Drivers Seat Belt	as above.	1261689
8231	#####	1248067	Driver Tablet Entered -Body - Drivers Seat Belt	Replaced drivers seat belt buckle.	1261689
8231	#####	1245730		Fill up coolant and oil clean the bus thoroughly underneath and engine bay went for road test checked for leaks no leaks all good.	1261193
8231	#####	1245730		Zip tied all wires topped up coolant and added 34L of 15W-40 engine oil Connected batteries started bus up and checked for leaks all good moved bus to wash bay gave engine final wash and road tested bus checked over on pit after roady no oil leaks all sealed. Checked inside bus and washed outside then parked bus.	1261193
8231	#####	1245730	OIL ENGINE ALL FLEET PLUS E900 15W-40		1261193
8231	#####	1245730	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1261193
8231	#####	1245730	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1261193
8231	#####	1245730		Continued finishing off cleaning installed the sump with new gasket tensioned all sump bolts to 35nm with a drop of locktite. Fit back oil breather sensor and dipstick tube. Fit new engine oil filters installed alternator / wiring and fan belt. Fit back coolant and oil pipes.	1261193
8231	#####	1245730		Fitted spare sump with new gasket and tensioned all sump bolts to 35Nm. Refit breather sensor and dipstick tube. Installed alternator and wiring Fitted oil filters and coolant pipes	1261193
8231	#####	1245730		Removed alternator mounting bracket and found oil coiming from the mounting bolt. Removed dipstick oil filler neck and oil sensor. Removed the sump from the engine we have a spare 0500LE sump in storage will replace this hairline cracked sump with our spare Commenced cleaning block and all removed parts.	1261193
8231	#####	1245730		Removed sump. Sump has hairline fracture. will be replacing with spare sump found upstairs. Cleaned block and spare sump.	1261193
8231	#####	1245730	SCREW OIL SUMP 457954 MERC BEN	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G381923 Receiving #:404815 Date :2025-02-18	1261193
8231	#####	1245730	GASKET OIL FILLER NECK MERC BE	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G381923 Receiving #:404815 Date :2025-02-18	1261193
8231	#####	1245730	TUBE DIPSTICK MERC BENZ 0500LE	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G381923 Receiving #:404815 Date :2025-02-18	1261193
8231	#####	1245730	GASKET OIL PICK UP 0.5MM MERC	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G381923 Receiving #:404815 Date :2025-02-18	1261193
8231	#####	1245730	GASKET OIL SUMP 457942 MERC BE	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G381923 Receiving #:404815 Date :2025-02-18	1261193
8231	#####	1245730	Mechanic entered - Engine Other engine sump leaking	Lift bus up using stands. Drained oil and Coolant. Removed coolant pipe. RemovedAlternator.	1261193
8231	#####	1245730			1261193
8231	#####	1245730		Assisting Lachlan with removing alternator and fan belt was also doing a safet inspection on 610 and breakdown for 1605.	1261193
8231	#####	1245830	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL REPLACEMENT	DONE 17/02/2025	1261193
8231	2/7/2025	1243247		Assist Seal doing the safety check ensure wheel nuts are torqued to oem spec	1259553
8231	2/7/2025	1243247		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Aaron	1259553
8231	2/7/2025	1243247		VEHICLE SAFETY INSPECTION completed	1259553
8231	2/7/2025	1243247		Fix drivers side front parker headlights	1259553
8231	2/7/2025	1243308	Mechanic entered - Elec and Light Exterior Lights drivers si		1259553
8231	2/7/2025	1243308	GLOBE 24V 70W H1 HLC2470		1259553
8231	2/7/2025	1243312	Mechanic entered - Elec and Light Indicators Not Working Dri	Fix drivers side head light	1259553
8231	2/7/2025	1243312	GLOBE HEADLAMP 24V 70W H7		1259553
8231	2/7/2025	1243308	Consumables		1259553
8231	2/7/2025	1243312	Consumables		1259553
8231	2/7/2025	1243294	O-RING KIT LARGE VOSS A6739070145		1259553
8231	2/7/2025	1243294	Mechanic entered - Brakes Park_Brake Leaking Air Brake pads	fixed foot brake air leak by replacing the o rings	1259553
8231	2/7/2025	1243294		not the park brake valve leaking from foot brake air line fitting. replaced oring kit	1259553
8231	#####	1242003	PTI Tablet Entered -COOLANT LEAK	retight hose clamps toped up coolant.	1258400
8231	#####	1242003	PTI Tablet Entered -COOLANT LEAK	As above	1258400
8231	#####	1242003	PTI Tablet Entered -COOLANT LEAK	As above	1258400
8231	#####	1239543	Driver Tablet Entered -Consat - Speakers smart bus voice ove	checked the system contacted the Consat helpdesk to adjust the volume 20% lower. I think better now.	1256459
8231	#####	1239543	Consumables		1256459
8231	1/2/2025	1236423	Ops Entered - Fault - Air System Air_Leak Front - Route: 90	replaced park brake valve	1254441
8231	1/2/2025	1236423	VALVE PARK BRAKE MERC 0500LE E3 E4 E5 A0034307581		1254441
8231	#####	1233795	PTI Tablet Entered -air leak		1252252
8231	#####	1233795	Drv entered - Air System Air_Not Building_Up	check and fixed air leak from driver seat air line	1252252
8231	#####	1233495	REPLACE ANTI GRAFFITI FILM. AU	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G377761 Receiving #:400699 Date :2024-12-16	1251919
8231	#####	1233495	Vandalism. REPLACE ANTI GRAFFITI FILM - AUDIT 1135	COMPLETED BY GLASSPROTECH 12/12/2024	1251071
8231	#####	1232400	Mechanic entered - Body Other Wheel arch rubber and Brush m	Replaced New brush and rubber.	1251071
8231	#####	1232400	BRUSH WHEELARCH 75mm 2.5M PER WHEEL		1251071
8231	#####	1232400	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1251071
8231	#####	1232400	Consumables		1251071
8231	#####	1232389		CARRY OUT A SERVICE AS PER CHECK LIST Carried out A service as per check list Tension all wheel nuts with Lachlan	1251071
8231	#####	1232389		assisted indika carry out a servce as per checklist	1251071
8231	#####	1232389	Consumables		1251071
8231	#####	1232389	Consumables		1251071
8231	#####	1232389	Consumables		1251071
8231	#####	1232389	Consumables		1251071
8231	#####	1231926	Driver Tablet Entered - - Speakers smart bus voice over way	checked consat speaker was ok not loud at all and find have issue with smart track sound which we do not have enough about Ranji is going to email operations.Complete.	1250799
8231	#####	1231926	Ops Entered - Fault - Consat Speakers - Route: 900v - Caulf	checked consat speaker was ok not loud at all and find have issue with smart track sound which we do not have enough about Ranji is going to email operations.Complete.	1250799
8231	#####	1231926	Consumables		1250799
8231	#####	1231379		VEHICLE SAFETY INSPECTION completed as per check list	1250495
8231	#####	1231379		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS tensioned the wheel nuts with Ben	1250495
8231	#####	1231379		Assisted Haysun. Completed checklist as per work order. Tensioned wheelnuts to OEM specs with Haysun	1250495
8231	#####	1231449	Mechanic entered - Wheels and Tyres Worn position 3and 4 tyr	Removed wheels and got recaps gunned on Tensioned wheelnuts to OEM specs with Haysun	1250495
8231	#####	1231449	TYRE 295/80R22.5 RECAP		1250495
8231	#####	1231598		retensioned the wheel nuts with Abraham	1250495
8231	#####	1231598	Mechanic entered - Wheels and Tyres Wheel Nut Retension Posi	Retensioned wheel nuts w/ Gurdashan po.34.	1250495
8231	#####	1231449	Consumables		1250495
8231	#####	1231598	Consumables		1250495
8231	#####	1231451	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Gr	Scrubbed down with remover chemicals and removed seat rear cushions and replaced with new	1250495
8231	#####	1231451	SEAT SINGLE BACK CEN CVR CI		1250495
8231	#####	1231453	Mechanic entered - Engine Belts_Loose Noisy Missing fan driv	r/r the fan belt and adjusted	1250495
8231	#####	1231453	BELT FAN DRIVE MERC BENZ 0500LE A0139971992		1250495
8231	#####	1231450	Mechanic entered - Elec and Light Interior Lights OSR dome l	removed blown globe and replaced with new	1250495
8231	#####	1231450	Consumables		1250495
8231	#####	1231452	Mechanic entered - Body Other wheel arch brush and rubber mi	fitted new wheel arch brush	1250495
8231	#####	1231452	BRUSH WHEELARCH 75mm 2.5M PER WHEEL		1250495
8231	#####	1231452	WHEEL ARCH RUBBER 2.5M PER WHEEL P/M		1250495
8231	#####	1231452	Consumables		1250495
8231	#####	1231466		Carried out air system service with Haysun	1250495
8231	#####	1231466		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed as per check list and replaced parts as required compressor and air line done on 04/11/24 W/O 1216905	1250495
8231	#####	1231466	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1250495
8231	#####	1231466	AIR DRYER ASSY MERC 0500LE A004302915		1250495
8231	#####	1231466	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1250495
8231	#####	1231466	VALVE AIR FILTER CHECK 22mm CYCLONE		1250495
8231	#####	1231293	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1250495
8231	#####	1231293	PTI Tablet Entered -Right hand side front park light not wor	Replaced indicator/park light assembly.	1250495
8231	#####	1231293	Consumables		1250495
8231	#####	1230973	PTI Tablet Entered -Elec and Light - Exterior LightsRight p	replaced globe	1250300
8231	#####	1230973	Consumables		1250300
8231	#####	1203286	DIRECT PURCHASE - TYRES	GB-8EA001 G369411 REC V 396031	1250300
8231	#####	1227966	PTI Tablet Entered -right hand side parklight not working	Replaced park/indicator lftg assembly.	1247948
8231	#####	1227966	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1247948
8231	#####	1227967	PTI Tablet Entered -right hand side parklight not working	Defect entered twice.	1247948
8231	#####	1227967	Consumables		1247948
8231	#####	1227966	Consumables		1247948
8231	#####	1227065	SILENCER AIR DRYER MERC BENZ 0500LE		1247450
8231	#####	1227065	Driver Tablet Entered -Air System - Air_Leak Rear	checked can not hear any air leak too noisy air dryer silencer replaced the silencer. also tightened exhaust muffler clamp	1247450

8231	#####	1216905	fitting canning plug properly checked over and started bus ran bus and went in gear to check much less vibrations carried out road test and come back check everything, checked with ranjith and dulkitb bus normal. carried out mopping inside.	1246028
8231	#####	1216905 Service	Dates change 1/11/2024. for not posting Lines 40 50 60709010012013016017018019020021020230140260	1246028
8231	#####	1216905	carried iout torquing flywheel and fitting transmission and carried out fitting accessories and 6 converter bolts carry over.	1246028
8231	#####	1216905	carried out removing transmission from other smart bus with no engine and get ready to fit to 8231 bolted up flywheel need to torque.	1246028
8231	#####	1216905	removed all air lines fit new air lines and fitted compressor with new gasket need to fit all fitting s and p/s pump carry over.	1246028
8231	#####	1216905	test transmission using zf test rig all pressures seem to be okay.	1246028
8231	#####	1216905 HOSE RADIATOR UPPER / LWR MERC BENZ 0500LE		1246028
8231	#####	1216905	carried out fitting cross member coolant trans cooler pipe and fitting gearbox under support 2	1246028
8231	#####	1216905	carried on fitting remaining bolts for cross member fitted cooler piping and tail shaft and mmodulator and carried out filling coolant start bus but no gears possible cannon plug not in properly.	1246028
8231	#####	1216905	carried out removal of compressor and order parts and carry out start removal of all air lines.	1246028
8231	#####	1216905	assist Zubz for tasking the gear box out.C/O.	1246028
8231	#####	1216905	Assisted Gurdashan pulled down gearbox.	1246028
8231	#####	1216905		1246028
8231	#####	1216905	carried out diagnosing suspected coming from compressor started removal of compressor. carry over.	1246028
8231	#####	1216905	Assisted Guri	1246028
8231	#####	1216905	carried out fitting back all air lines new new power steering pump o ring new air dryer canister fit back all fittings carried out refilling coolant and bleed p/s still have vibration. carried out removing fan belt with ranjith and run bus still the same carried out started removal of torque converter bolts 3 removed. c/o	1246028
8231	#####	1216905	carried out removing coolant pipes and tail shaft and started removal of gearbox	1246028
8231	#####	1216905	secure the bus on stands removed the torque converter bolts . removed the o/s gearbox mount bolts and crossmember bolts just left one bolt on o/s. Removed the N/s gear box mount bolts and still one bolt left half way out. Secure the gear box and cross member on jack stands. c/o	1246028
8231	#####	1216905	Set up the transmission stand strapped the gearbox to the stand removed all bellhousing bolt. Secure the gear box with chain from inside the bus . removed the gearbox and putted on the pallet.	1246028
8231	#####	1216905	carried out removing gearbox mounts and cross member carried out setting up bus to get box out carry over	1246028
8231	#####	1216905	removed flywheel inspected flex plate with ranjith and rear main seal	1246028
8231	#####	1216905	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G375284 Receiving #:397604 Date :2024-10-30	1246028
8231	#####	1216905	fitting new one had in stock.	1246028
8231	#####	1216905		1246028
8231	#####	1216905	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G373939 Receiving #:396144 Date :2024-10-09	1246028
8231	#####	1216905	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G373852 Receiving #:396101 Date :2024-10-09	1246028
8231	#####	1216905	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G373852 Receiving #:396101 Date :2024-10-09	1246028
8231	#####	1216905	Creditor #:GB-BEA001 BEAU REPAIRS(GOODYEAR) P/O #:G369411 Receiving #:396031 Date :2024-10-08	1246028
8231	#####	1216905	DONE	1246028
8231	#####	1216905	carried out road test no noise for front left wheel area noise coming from engine side.	1246028
8231	#####	1216905	carried out testing bus rattles when air is low and compressor is loading vibrates but when compressor unloads idles fine as per normal checked all torque converter bolts for slack no looseness carry over.	1246028
8231	#####	1216905	assist Zubair to take starter motor out and then checked all torque converter bolts as we suspected that could be cause for engine vibration but all were ok.put back starter and start again and put bus on red square.C/O.	1246028
8231	#####	1216728 Consumables		1245735
8231	#####	1216728 Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	Retension pos 1 wheel nuts.	1245735
8231	#####	1216728 Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	Assisting	1245735
8231	#####	1216441 Consumables		1245716
8231	#####	1216441 Ops Entered - Fault - Wheels and Tyres Noisy - Route: 850 -	Replaced with new tyre pos #1 & assisted fit sway bar bush.	1245716
8231	#####	1216441 TYRE 295/80R22.5 NEW		1245716
8231	#####	1216441 Ops Entered - Fault - Wheels and Tyres Noisy - Route: 850 -	Remove N/S front sway bar bush luricated fitted back.	1245716
8231	#####	1215180 Consumables		1244480
8231	#####	1215180 PTI Tablet Entered -left hand side front park light not wor	check and found that l/s/r indicator broken from behind removed and replaced	1244480
8231	#####	1215180 LAMP CLEAR FRT INDICATOR WRAP-AROUND		1244480
8231	#####	1213921 RSI INSPECTION 2024	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G372171 Receiving #:394808 Date :2024-09-19	1244935
8231	#####	1213921	VEHICLE SAFETY INSPECTION	1243646
8231	#####	1213921	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1243646
8231	#####	1213921	ANNUAL SAFETY INSPECTION SERIAL # _____ WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25 carried out rsi	1243646
8231	#####	1213921		1243646
8231	#####	1213921	Assisted.	1243540
8231	#####	1213526 Workshop Tablet Entered -A/C Heating - Demister Not Heating	Tested ok	1243540
8231	#####	1213526 Workshop Tablet Entered -A/C Heating - Demister Not Heating	Run bus up too operating temperature tested demisters at 41C unable too fault	1243540
8231	#####	1213526 Mechanic entered - A/C Heating Other System will require dri	Replace refrigerant charge compressor oil and drier as per burnout clean	1243540
8231	#####	1213526 Workshop Tablet Entered -A/C Heating - Demister Not Heating	Tested ok	1243540
8231	#####	1213526 FILTER DRYER AIR COND THERMO KING 2750300 DML305R		1243540
8231	#####	1213526 OIL AC COMPRESSOR		1243540
8231	#####	1213526 AIR CON REFRIDGERANT		1243540
8231	9/6/2024	1213005 Consumables		1243540
8231	9/6/2024	1213005 Carry out final inspection for RSI	carried out final inspection for rsi.	1243540
8231	9/6/2024	1213005	completed with zubair and replaced 1 seat cushion and returned torn one to store	1243540
8231	9/6/2024	1213005 SEAT CUSH SINGLE CEN CVR CI		1243540
8231	9/3/2024	1207120 VALVE ECAS MERC BENZ 0500LE -> 000507 A0013271725	PART TRANSFERED	1242594
8231	9/2/2024	1211848 WIPER BLADE ASSEMBLY 39037 5/S FROM TX1000		1242450
8231	9/2/2024	1211848 Drv entered - Wipers and Washers Wipers Loose	replaced damaged (ns) wiper blade. adjusted both arms and tightened.	1242450
8231	#####	1211355 Consumables		1242342
8231	#####	1211355 Elec and Light battery need to replace	re-placed battery and checked ok.Complete.	1242342
8231	#####	1211355 BATTERY 1450CCA POS ON RHS EMFN200R		1242342
8231	#####	1211355	Replaced battery and checked new one is working fine. Complete.	1242342
8231	#####	1211205 Drv entered - Brakes Park_Brake Not Holding	check and found that n/s/r next to booster air line comes off swap the hose from bus 8239 start the bus check for air leak and done brake test and road test . its all ok now bus can go on the road .	1242168
8231	#####	1211041	COMPLETED BY ATS 20/8/2024	1242168
8231	#####	1210383 Consumables		1241778
8231	#####	1210383 Mechanic entered - Elec and Light Flat Batteries	jump started.	1241778
8231	#####	1210336 Consumables		1241778
8231	#####	1210336	Retensioned wheel nuts pos 1 and 2.	1241778
8231	#####	1210336	Completed with Nick.	1241778
8231	#####	1207684	Tested A/C all ok will need oil and drier change in 2 weeks	1241778
8231	#####	1209821 Consumables		1241778
8231	#####	1210197 Consumables		1241778
8231	#####	1209821	fitted new sticker	1241778
8231	#####	1210197 Mechanic entered - Body Other seat adjust button missing	fitted second hand one	1241778
8231	#####	1208888	removed the wheels and removed the booster disassemble the booster and replaced the diaphragm wheels fitted and tensioned the wheel nuts with Locdan	1241778
8231	#####	1208888	Assisted maung soon.	1241778
8231	#####	1207684 OIL AC COMPRESSOR		1241778
8231	#####	1207684 AIR CON REFRIDGERANT		1241778
8231	#####	1209429	Fitted new mount and Secured.	1241778
8231	#####	1209429	assisted	1241778
8231	#####	1208890 Consumables		1242068
8231	#####	1208893 Consumables		1241778
8231	#####	1209821 Mechanic entered - Body Other rear door please hold on stick		1241778
8231	#####	1208821 DECAL PLEASE HOLD ON BLACK ON YELLOW	parts received and booked to bus	1241778
8231	#####	1208890	r/r the front door over head penal	1241778
8231	#####	1208893	fitted new strut.	1241778
8231	#####	1208893 STRUT GAS STAY LIFT UP SEAT		1241778
8231	#####	1208893	r/r the strut	1241778
8231	#####	1208888 DIAPHRAGM T-20 D SHAPE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G371102 Receiving #:393052 Date :2024-08-27	1242068
8231	#####	1209210	drained the coolant and r/r the coolant hose used the used parts	1241778

8231	#####	1208891		completed.		1241778
8231	#####	1209429	Mechanic entered - Engine Other radiator rubber mount broken	assisted		1241778
8231	#####	1209429	MOUNT RADIATOR TOP MERC BENZ O	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G371007 Receiving #:392949 Date :2024-08-23		1242068
8231	#####	1209400	Consumables			1241778
8231	#####	1209400	Workshop Tablet Entered -Elec and Light - Indicators doesnt	checked indictaor stork take it and ckcked if faulty.find oput it is self cutting and works find a loose bolt which could be the cause.re-placed with new ones and put lock tite and put and checked ok.Complete.		1241778
8231	#####	1208883		r/r the brake hose		1241778
8231	#####	1209076	Mechanic entered - Wipers and Washers Wipers Loose N/F	Assisted.		1241778
8231	#####	1209076		adjusted the wiper arm link		1241778
8231	#####	1207684		assisted brace		1241778
8231	#####	1207684	BEARING A/C CLUTCH I/D 50MM O/D 90MM W 30MM 3210 6210 RSR			1241778
8231	#####	1209210	Mechanic entered - Fluid Leaks Rear of bus Transmission coolen	Assisted.		1241778
8231	#####	1209210				1241778
8231	#####	1208891		assisted satheesh		1241778
8231	#####	1208891		Assisted.		1241778
8231	#####	1208890	COVER FRT DOOR ROOF CONTROLS	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G370917 Receiving #:392958 Date :2024-08-23		1242068
8231	#####	1208883	repair brake hose	Creditor #:GB-ENZ001 ENZED DANDENONG P/O #:G370916 Receiving #:392835 Date :2024-08-22		1242068
8231	#####	1208818		PRE ANNUAL SAFETY INSPECTION CHECK completed		1241778
8231	#####	1208818		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST		1241778
8231	#####	1208818		completed as per check list and tensioned wheel nuts with ssiil		1241778
8231	#####	1208900	Mechanic entered - Steering Other bottom cover screw missing	Removed all steering covers as all bolts and the cover were broken used new long bolts from economy bolt with washers to secure both covers for the steering link.		1241778
8231	#####	1208891	Mechanic entered - Engine Other power steering reservoir hos	parts ordered on Z1-08-2024		1241778
8231	#####	1208881	LAMP LED DOWNLIGHT ROUND ENT DOOR			1241778
8231	#####	1208881	Mechanic entered - Elec and Light Interior Lights Rear door	Rear door light assembly replaced due to fault internal to circuit board. Complete		1241778
8231	#####	1208882	Mechanic entered - Elec and Light Interior Lights stop sign	x2 globes replaced everything works now. Complete		1241778
8231	#####	1208880	Consumables			1241778
8231	#####	1208881	Consumables			1241778
8231	#####	1208882	Consumables			1241778
8231	#####	1208880	Mechanic entered - Elec and Light Interior Lights O/R saloon	Replaced rear interior lights O/R saloon. Complete		1241778
8231	#####	1208925	Mechanic entered - Body Passenger Seat Torn 3	removed and replaced with new returned damaged cushion to store		1241778
8231	#####	1208925	SEAT CUSH SINGLE CEN CVR CI			1241778
8231	#####	1208869	Consumables			1241778
8231	#####	1208925	Consumables			1241778
8231	#####	1208932	Consumables			1241778
8231	#####	1208936	Consumables			1241778
8231	#####	1208945	Consumables			1241778
8231	#####	1208890	Mechanic entered - Body Other Front door top plastick cover	parts ordered		1241778
8231	#####	1208893	Mechanic entered - Body Other O/S double fold up seat strut	parts ordered		1241778
8231	#####	1208869	Mechanic entered - Body Other Rust under wheel chair ramp	cleaned and painted		1241778
8231	#####	1208869	UNDERBODY SHUJTZ BLACK 1250 AEROSOL 500ML			1241778
8231	#####	1208932	Mechanic entered -Body Other secure rear modesty panal	secured		1241778
8231	#####	1208936	Mechanic entered -Body Other O/R one of the poll top nut mi	fitted new nut		1241778
8231	#####	1208945	Mechanic entered -Body Other Engine hatch door duct tape ca	repaired wit tape		1241778
8231	#####	1208888	Mechanic entered - Brakes Foot_Brakes Leaking Air O/F	parts ordered		1241778
8231	#####	1208883	Mechanic entered - Air System Air_Leak Rear N/R brake hose I	parts ordered		1241778
8231	#####	1208459	Consumables			1241140
8231	#####	1208459	Workshop Tablet Entered -Body - Front_Door Operation Faulty	check and could not fault anything wrong with front door operation . All ok		1241140
8231	#####	1207120	O-RING KIT LARGE VOSS A6739970145			1241100
8231	#####	1207120		removed the fittings and fitted o-ring kits and fitted tread tape and tightened the fittings start the bus build up air and checked no leak found from the fittings.		1241100
8231	#####	1207120	Mechanic entered - A/C Heating Not Cooling Failed compressor	road tested checked no air leak.		1241100
8231	#####	1207684	ac compressor X430	Compressor oil full off metal new compressor ordered 15/8/24		1241100
8231	#####	1207576		Creditor #:GB-QTK001 QTK GROUP P/O #:G370524 Receiving #:392654 Date :2024-08-20		1241778
8231	#####	1207576	FILTER DRYER AIR COND THERMO KING 2750300 DML30SR	CARRY OUT A/C - B SERVICE AS PER CHECK LIST		1241100
8231	#####	1207576				1241100
8231	#####	1207120	VOSS NUT 232 22MM MERC BENZ 0500LE A000997483401	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list Service as per note comprrsor has failed parts ordered		1241100
8231	#####	1207120		Refitted air line to suspension control valve. Checked leaks ok. Bus still leaning on the o/s rear. C/O		1241100
8231	#####	1207120		r/r the e-class valve and fitted all the fittings still have leaks C/O		1241100
8231	#####	1207120		observed Nic		1241100
8231	#####	1206648		Assisted Haysun. Replace air line junction o ring test ok no leak.		1241100
8231	#####	1207120	Mechanic entered - Suspension Other leaning one side	found suspension valve leaking and assisted Rene r/r the air bag line fitting c/o		1241100
8231	#####	1207120	O-RING KIT LARGE VOSS A6739970145			1241100
8231	#####	1206648		Removed and replace rear off side rear of rear air bag fitting found out leaking. Fitted new o ring kit Replace air line pipe from air bag to suspension valve. Fitted new pipe Replace air line o ring kit for suspension valve fitting. Test run build up air found out air suspension valve rear leaking from body need new suspensi		1241100
8231	#####	1206465	VALVE MANUAL DRAIN 22MM VOLVO	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G370244 Receiving #:392093 Date :2024-08-12		1241100
8231	#####	1206648	O-RING KIT LARGE VOSS A6739970145			1241100
8231	#####	1206648	ELBOW COUPLING 90 DEGREES MERC BENZ 0500LE			1241100
8231	#####	1206648	NUT VOSS 232 22mm MERC BENZ 0500LE 49G4527WABCO			1241100
8231	#####	1206648		Fitted new o ring to air line junction Checked no leak. Fitted new drain cock to rear center tank. Checked found out leaking from air tank fitting removed and fitted new o ring secured test ok no leak. Leaking from circuit protection valve fitting replace air line o ring fittings. Test ok. Air bag off side not build up air replace		1241100
8231	8/9/2024	1206465	Mechanic entered - Suspension Other N/S both drive axel air	r/r the air bags		1241100
8231	8/9/2024	1206465	AIRBAG FRT/RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200			1241100
8231	8/9/2024	1206465	AIRBAG FRT/RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200			1241100
8231	8/9/2024	1206465	A0004322107 airtake	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370202 Receiving #:393056 Date :2024-08-27		1242068
8231	8/9/2024	1206648	Mechanic entered - Air System Other air line junction leakin	rectified leak found air tank drain valve leaking air line junction leaking remove the tank drain valve and air line junction		1241100
8231	8/9/2024	1206648	o ring kit	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G370202 Receiving #:393056 Date :2024-08-27		1242068
8231	8/8/2024	1206067	Mechanic entered - Fluid Leaks Rear of bus COOLANT LEAK REAR			1241100
8231	8/8/2024	1206067		r/r the thermostat seals		1241100
8231	8/8/2024	1206067	O RING THERMOSTAT MERC BENZ 0500LE 50A3504			1241100
8231	8/8/2024	1206243	Consumables			1241100
8231	8/8/2024	1206243	Mechanic entered - Body Other BOTH REAR MUD FLAPS WORN.	r/r the mud flaps		1241100
8231	8/8/2024	1206243	MUDFLAP 605MM X 330MM			1241100
8231	8/8/2024	1206243		Assisted haysun		1241100
8231	8/8/2024	1206211		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Started service not completed carry over Service as per list refer W/O 1207576		1241100
8231	8/7/2024	1205822		carried out safety inspection as per check list and tensioned all wheel nuts with guri.		1241100
8231	8/7/2024	1205822		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		1241100
8231	8/7/2024	1205822		Assisted Zubair with safety inspection and tensioned the wheel nuts.		1241100
8231	8/7/2024	1205887	Mechanic entered - Air System Air_Leak Rear FROM ONE OF THE	carried out removing and replacing 5 air line o ring over haul. and check for leaks no leaks. from the suspension valve.		1241100
8231	8/7/2024	1205887	O-RING KIT LARGE VOSS A6739970145			1241100
8231	8/2/2024	1204980		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Carried out fire safety inspection as per checklist. Complete. Secured stator motor wire with cable tie		1240329
8231	#####	1203236	Fault#:39246 - Ops Entered - Fault - Breakdown Tyre Fault -	Defect entered twice Ref:W/O # 1200939.		1239024
8231	#####	1201339	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	Assisted Nick.		1236972
8231	#####	1201339		Tensioned wheel nuts w/ Abraham pos.2		1236972
8231	#####	1201339	Consumables			1236972
8231	#####	1200939	Off side front tyre is flat	Goody year replaced pos 2 tyre. retension wheel nuts with Abraham.		1236720
8231	#####	1200939	Consumables			1236720
8231	#####	1200870	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC	DONE		1236720
8231	#####	1199584		CARRY OUT C SERVICE AS PER CHECK LIST completed as per check list tensioned the wheel nuts with indika steam cleaned the bus ssiil road tested the bus and check oil lvl all ok		1235921



8231 2/7/2024 1167485	fabricated panel stainless steel splash plate repair filler on bumper primed	1215554
8231 2/6/2024 1167485 HATCH PLAIN COOLANT SURROUND 165 x194MM(WHITE)		1215554
8231 2/6/2024 1167485 *** PHOTOS TAKEN BY GERALD *** - Accident #56163 - Off Side		1215554
8231 2/6/2024 1167485 PANEL LIGHT COWL REAR N/SIDE CRN		1215554
8231 2/6/2024 1167485 FILLER CAMS FINE		1215554
8231 2/6/2024 1167485	remove damage bumper corner o/sdo repairsremove o/s rear tail light panel and replays with new	1215554
8231 2/6/2024 1167485 FILLER & PLATINIUM		1215554
8231 2/6/2024 1167485 *** PHOTOS TAKEN BY RANJITH AND EMAIL TO GERALD ***Accident		1215554
8231 2/6/2024 1167485	started to strip damage bumper sanded back filled cut out coolant hatch and fitted to new bumper	1215554
8231 2/2/2024 1166790	VEHICLE SAFETY INSPECTION carried out safety inspection as per check list and tensioned all wheel nuts with feda and carried out 3 seat backing pins and adjust wipers.	1214826
8231 2/2/2024 1166790		1214826
8231 2/2/2024 1166916 Mechanic entered - Fluid Leaks Other coolant leak rear therm	carried out diagnosing of und not leaking from there leaking higher from coolant hose secured and road tested and check for leaks no leaks.	1214826
8231 ##### 1166161 Fault#:39060 - Ops Entered - Fault - Breakdown Making a Str	Accidentally entered to bus 8231 and bus was 8909 and refer defect no 1020718	1214262
8231 1/6/2024 1161953 BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1211455
8231 1/6/2024 1161953 OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		1211455
8231 1/6/2024 1161953	CARRY OUT B SERVICE AS PER CHECK LIST	1211455
8231 1/6/2024 1161953 FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1211455
8231 1/6/2024 1161953 OIL SAMPLE TEST KIT		1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/6/2024 1161953 Consumables	CARRY OUT A SERVICE AS PER CHECK LIST completed b service as per check list and check over and tensioned all wheel nuts with sisil	1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/6/2024 1161953 Consumables		1211455
8231 1/4/2024 1161238 PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	COMPLETED	1211455
8231 1/2/2024 1160561 Mechanic entered - Elec and Light Flat Batteries	JUMP STARTED.	1211156
8231 1/2/2024 1160561 Consumables		1211156
8231 ##### 1158615 Consumables		1210167
8231 ##### 1158722 Consumables		1210167
8231 ##### 1158735 Consumables		1210167
8231 ##### 1158615 Ops Entered - Fault - Elec and Light Exterior Lights - Rout	Replaced head lamp switch.	1210167
8231 ##### 1158615 SWITCH HEADLIGHT MERC BENZ 0500LE E3 50V2220		1210167
8231 ##### 1158615 KNOB HDLIGHT SWITCH MERC BENZ 0500LE E3		1210167
8231 ##### 1158722 PTI Tablet Entered -front lights switch not working	Defect enterd twice.	1210167
8231 ##### 1158735 PTI Tablet Entered -Exterior Lights switch not working	Ref: W/O #1158615.	1210167
8231 ##### 1157952 Workshop Tablet Entered -Body - Front_Door Operation Faulty	Replaced contact switch.	1209288
8231 ##### 1157952 SWITCH DR CONTACT NORMALLY OPEN M22-K10		1209288
8231 ##### 1156067 SIDE GLASS BUS & COACH AE	Creditor #:GB-0BR010 O'BRIENS GLASS INDUSTRIES P/O #:G355696 Receiving #:374993 Date :2023-12-06	1208246
8231 ##### 1156067 Accident #56218 NEARSIDE - Rear	replaced smashed (nr) clearance light - used one used.	1208089
8231 ##### 1156067 Accident #56218 NEARSIDE - Rear	Side window replaced by O briens	1208089
8231 ##### 1154329 Ops Entered - Fault - BusMinder Unable To Log In - Route: 9	Send email opp to check and repair	1207181
8231 ##### 1154329 Consumables		1207181
8231 ##### 1154329 Ops Entered - Fault - BusMinder Unable To Log In - Route: 9	checked busminder and tried to log in but does log in. re-start bus couple times and tried again to log but does not worked. needs to get checked by operation and fixed by busminder guys. Complete.	1207181
8231 ##### 1153658	Assisted retensioned pos 12 with nick	1206291
8231 ##### 1153658 Mechanic entered - Elec and Light Flat Batteries	Assisting Retensioned wheel nuts pos 1 and 2.	1206291
8231 ##### 1153592 Consumables	jump started.	1206291
8231 ##### 1152931	Finished refitting boosters and sensors. fitted pads and adjusted in. Tensioned all bolts to Manufacturer specs. Put wheels back on and gunned all wheelnuts on. lowered bus and Tensioned all wheelnuts to OEM specs with Matt.	1206291
8231 ##### 1152931	Fit back all remaining parts fit the wheels back and tensioned wheel nuts with Ben took the bus for long road test to warm up brakes all working feels nice and strong. Unable to do brake test as machine is out of order.	1206291
8231 ##### 1153164 Mechanic entered - Body Other Rear engine panel trimming bro	engine hatch panel fixed and put back down. Refitted rear seats as well	1206291
8231 ##### 1153099 Mechanic entered - Body Other rea door modesty panel need to	Installed new screw to hold the pole for the modesty panel up the top near the roof.	1206291
8231 ##### 1153100 Mechanic entered - Body Front_Door Operation Faulty from do	Used sika flex to seal up the top of the front doors waited till dry to test the edges all working now.	1206291
8231 ##### 1153099 Consumables		1206291
8231 ##### 1153100 Consumables		1206291
8231 ##### 1153164 Consumables		1206291
8231 ##### 1152931		1206291
8231 ##### 1152931	Cleaned off all hubs and stub axles installed the new rotors to the front hubs and tensioned holding bolts to 170nm. Installed the hubs back to the bus followed mercedes paperwork for 0500LE. Installed both calipers tensioned holding bolts to 265nm. Installed new brake pads and boosters tensioned to 180nm.	1206291
8231 ##### 1152931	Assisting Jimmy remove air front brakes calipers rotors and hubs.	1206291
8231 ##### 1152931	Assisted Matt. refit brakes and boosters	1206291
8231 ##### 1152931 GASKET FRT HUB CAP MERC 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G354641 Receiving #:373925 Date :2023-11-20	1206291
8231 ##### 1152931 BOLT FRT BRAKE DISC MERC BENZ 0500LE A910105014019		1206291
8231 ##### 1152931 BRAKE DISC FRT / RR MERC BENZ 0500LE E3>E6 50F3339		1206291
8231 ##### 1152931 BRAKE PADS FRT / RR MERC 0500LE E3>E5 49G7501BERAL		1206291
8231 ##### 1153098 Mechanic entered - Air System Air_Leak Rear air leak from ac	Repaired airleak yesterday with new solenoid valve.	1206291
8231 ##### 1153098 VALVE SOLENOID G/BOX ACCUMULATOR ZF 0501 318 457		1206291
8231 ##### 1152931 Mechanic entered - Brakes Other front rotors worn down to 36	removed tyres POS 12 removed front axle brake booster caliper hub and rotors on both sides C/O	1206291
8231 ##### 1152247	assisted with safety inspection and tensioned all wheel nuts with matt	1206291
8231 ##### 1146303 CLAMP P G/BOX COOLING PIPES MERC BENZ 0500LE		1206291
8231 ##### 1146303	Installed all the gearbox coolant lines installed tailshaft and tensioned all nuts to 105nm and paint marked Fit all electrical fittings to the gearbox topped up coolant started bus and checked gearbox oil all good took bus for long road test and inspected on pit on return No leaks all sealed up and gearbox shifting smoo	1206291
8231 ##### 1152247	VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist with Jimmy reported all found defects.	1206291
8231 ##### 1146303	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Jimmy	1206291
8231 ##### 1146303 HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G	With the subframe sitting in place managed to get all bolts to line up for gearbox mounts and chassis tighten up all mounting bolts for this gearbox set up and paint marked all bolts. Now engine / gearbox can support itself removed stands and crane inside everything holding nicely. Installed wiring under the bellhousing	1206291
8231 ##### 1146303	lined up subframe and fitted the bolts need to tighten the bolt	1206291
8231 ##### 1146303	Repaired gearbox returned from ZF removed and replaced rear main seal for the engine as the old one was leaking. Fit the flywheel and flexplates back at 200nm plus 90 degrees. Used the crane to lift the gearbox onto the transmission jack installed the gearbox back to 8231 installed all the torque converter bolts. Start	1206291
8231 ##### 1146303 SEAL RR CRANKSHAFT 447.971 MER	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G353002RET Receiving #:373351 Date :2023-11-13 INCORRECT SEAL	1206291
8231 ##### 1146303	refitted gearbox with Matt lined up the subframe and fitted the bolts need to be tighten	1206291
8231 ##### 1146303 SEAL RR CRANKSHAFT 457942 MERC	Creditor #:GB-DAI001 DAIMLER TRUCKS LAVERTON P/O #:G354133 Receiving #:373296 Date :2023-11-10	1206291
8231 ##### 1146303 REPAIR / OVERHAUL TRANSMISSION	Creditor #:GB-ZF0001 ZF SERVICES AUSTRALIA PTY LTD P/O #:G353097 Receiving #:373195 Date :2023-11-08	1206291
8231 ##### 1146303 SEAL RR CRANKSHAFT 447.971 MER	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G353002 Receiving #:373990 Date :2023-10-23	1206291
8231 ##### 1146303	Gearbox ready to remove found that the bellhousing was really difficult to pop from the engine eventually got it out and removed the gearbox. Lifted the gearbox off the jack and onto a pallet then steam cleaned the box. Removed the fly wheel and cleaned inside the bellhousing ready for new rear main seal.	1206291
8231 ##### 1146303	secured gearbox with strap removed bell housing bolts used heat gun around bell housing and gear box mating point due to be stuck sprayed crc and removed gear box and placed onto a pallet and washed gear box removed flywheel due to remain leaking and cleaned oil/dirt build up on bell housing with brake clean	1206291
8231 ##### 1146303 Service	Gear box send to ZF for repair	1206291
8231 ##### 1146303	Removed gearbox mounts and support arms removed the lower crossmember bar from underneath the gearbox Set up jackstands to support engine.	1206291
8231 ##### 1146303	removed transmission mount and bracket with matt and removed crossmember and supported transmission with jack and engine with a stand	1206291
8231 ##### 1146303	Set up stands to hold the body and one stand with a block of wood to hold the engine loosen off crossmember and engine mont bolts at the gearbox removed one more long coolant line as well.	1206291
8231 ##### 1146303	removed remaining coolant pipes and lowered bus onto jack stand	1206291
8231 ##### 1146303	carried out draining coolant and removing coolant pipes from transmission disconnected wiring removed accumulator from transmission and removed all torque converter bolts and removed all wiring brackets bolted onto transmission housing	1206291
8231 ##### 1146303	Towed the bus into the workshop lifted up on hoist and drained coolant disconnect batteries removed starter motor removed coolant and electrical lines from the gearbox removed all torque converter bolts.	1206291
8231 ##### 1146589 Mechanic entered - Gearbox Driveline Other No Drive	Travel from Knox to dandenong to diagnose VBL bus 8231 for no drive traced fault with turbine speed not working suspect broken turbine shaft reported to Ranjith need changeover transmission	1206291
8231 ##### 1146303 As above		1206291
8231 ##### 1146303 Fault#:38913 - Ops Entered - Fault - Breakdown Gearbox Fault	refitted o/s/r axle with ranji and tensioned bolts to 420nm with ranji Diagnosed trans fault by Beuford found oil level loutopped up and rechecked found okay Connect ZF testman found no turbine speed checked with pin out box resistance is all good on output and input sensor during running there no turbine speed su	1206291
8231 ##### 1146303 TOW BUS FROM STUD PARK SHOPPIN	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G353383 Receiving #:372486 Date :2023-10-27	1206291
8231 ##### 1139949 Consumables		1204116
8231 ##### 1139949 HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525	PART NOT FITTED	1204116



8231	7/7/2023	1125054	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	Completed	1191515
8231	7/3/2023	1123791	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGR		1190557
8231	7/3/2023	1123791	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGR	completed by Volgren	1190557
8231	#####	1115959		VEHICLE SAFETY INSPECTION Carried out safety inspection as per checklist with Ben reported / repaired any found defects Steam cleaned with wheel hatches off as well.	1184175
8231	#####	1115959		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts with Ben	1184175
8231	#####	1115959	FILTER AIR MERC 0500LE(A0040941704)		1184175
8231	#####	1115959		Assisted Matt. completed checklist as per work order. Tensioned wheelnuts to OEM specs with Matt	1184175
8231	#####	1116011	WHEEL ARCH BRUSH 12065		1184175
8231	#####	1116011	RUBBER WHEEL ARCH 41294		1184175
8231	#####	1116011	Mechanic entered - Body Other OSF wheel arch brush and rubbe	Got new rubber and brush and fitted	1184175
8231	#####	1116116	Mechanic entered - Body Other Yellow floor strip at rear of	Fit yellow floor strip	1184175
8231	#####	1116117	Mechanic entered - Body Other OSF seat base loose	Tighten down O/S/F seatbase	1184175
8231	#####	1116118	Mechanic entered - Body Other Authorised officers sticker to	Fit new sticker to front of bus next to drivers area	1184175
8231	#####	1116011	Consumables		1184175
8231	#####	1116116	Consumables		1184175
8231	#####	1116117	Consumables		1184175
8231	#####	1116118	Consumables		1184175
8231	5/9/2023	1113327	TPAF - PAINT SILVER - R/2023/54825/MR - Prepare paint and	Made by accident. Job completed. Refer to W/O# 1105998	1182345
8231	5/5/2023	1112832		Retensioned wheel nuts pos 5 and 6.	1181792
8231	5/5/2023	1112832		Assisted	1181792
8231	5/4/2023	1112532	Mechanic entered - Wheels and Tyres Worn Pos 5/6 worn O/S/R	Removed and replaced tyre pos 5/6 tensioned all wheel nuts with Kuma	1181682
8231	5/4/2023	1112532	TYRE 295/80R22.5 NEW		1181682
8231	5/4/2023	1112532	Consumables		1181682
8231	5/4/2023	1112478	Service	Assisted.	1181682
8231	5/4/2023	1112478		CARRY OUT A SERVICE AS PER CHECK LIST	1181682
8231	5/4/2023	1112478	Consumables		1181682
8231	5/4/2023	1112478	Consumables		1181682
8231	5/4/2023	1112478	Consumables		1181682
8231	5/4/2023	1112478	Consumables		1181682
8231	5/4/2023	1112478	Consumables		1181682
8231	5/2/2023	1111972	LAMP CLEAR FRNT INDICATOR WRAP-AROUND		1181304
8231	5/2/2023	1111972	Mechanic entered - Elec and Light Exterior Lights Front R/H	Replaced o/s indicator/park light assembly.	1181304
8231	5/2/2023	1111972	Consumables		1181304
8231	#####	1110051	Mechanic entered - Elec and Light Exterior Lights	r/r the globe	1179733
8231	#####	1110051	Consumables		1179733
8231	4/6/2023	1105115		Assisted Rene.	1177820
8231	4/6/2023	1105115		Removed and replace sway bar bush with Haysun.	1177820
8231	4/6/2023	1105109		Removed air compressor assembly and fitted new air compressor gasket. Need for me to clean top of engine too much oil spill and dirt. Top-up steering oil and coolant with Haysun. Roadtest check operation air build ok and re check for leak ok no leak.	1177820
8231	4/6/2023	1105109		assisted	1177820
8231	4/1/2023	1105115	Mechanic entered - Suspension Noisy Front suspension noise s	C/O	1176649
8231	4/1/2023	1105109	Mechanic entered - Fluid Leaks Rear of bus Engine oil leak a	Accidentally log on to job.	1176649
8231	4/1/2023	1102574	Accident # 54825 damage rear TPAF	east coast completed and refer w/o 1105998	1176649
8231	4/1/2023	1105998	REFLECTOR RED 94MM X 4MM NR840528L		1176649
8231	4/1/2023	1105998	LAMP LED REVERSE RECTANGULAR		1176649
8231	4/1/2023	1105998	LAMP LED REVERSE RECTANGULAR		1176649
8231	4/1/2023	1105998		remove part and fit up new parts rewire lights	1176649
8231	#####	1105998	PAINT DEBEER CLEAR COAT MS SLTR		1176649
8231	#####	1105998		repainted 4 panels correct colour had to bake and sand all (crow feet) cracks out due to basecoat reaction with clear coat even though was baked twice primed baked sanded and repainted again. Stayed onto 11.30 pm.	1176649
8231	#####	1105998	BUMPER REAR CENTRE VOLGREN FUTURE BUS		1176078
8231	#####	1105998	BUMPER REAR N/SIDE CNR VOLGREN CR228		1176078
8231	#####	1105998	Prepare paint and Fit up bumpers		1176078
8231	#####	1105998	Prepare paint and Fit up bumpers	Assisting prep parts	1176078
8231	#####	1105115	BUSH FRNT & RR SWAY BAR MERC BE	Creditor #:GB-MUL001 MULTISAPRES LTD P/O #:G344004 Receiving #:357250 Date :2023-03-24	1175530
8231	#####	1105109	GASKET AIR COMPRESSOR MT MERC BENZ 0500LE 49A9446		1175530
8231	#####	1105080		VEHICLE SAFETY INSPECTION assisted	1175345
8231	#####	1105080		VEHICLE SAFETY INSPECTION Completed check list.	1175345
8231	#####	1105080		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ben.	1175345
8231	#####	1103769		CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS	1174387
8231	#####	1102574	Accident # 54825 damage rear TPAF	replaced broken (osr) clearance light.	1173623
8231	#####	1102574	LAMP LED SIDE RED/AMBER PERE(S2-98002)		1173623
8231	3/7/2023	1101557	Consumables		1172770
8231	3/7/2023	1101557	Drv entered - Body Front_Door Operation Faulty	Checked front and rear door operation OK.	1172770
8231	3/7/2023	1101393		CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Completed Diff service	1172770
8231	3/7/2023	1101393	OIL DIFFERENTIAL OIL SYNTHETIC FM 75W-140		1172770
8231	3/7/2023	1101369		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Service Complete as per Check list. Complete.	1170447
8231	#####	1097673	Consumables		1170447
8231	#####	1097673	Service	As above	1170447
8231	#####	1097673	Body Front_Door Operation FaultyDriver reported faulty f	Checked lubricate door shaft	1169537
8231	#####	1096480	Consumables		1168557
8231	#####	1096480	Mechanic entered - Elec and Light Exterior Lights Front R/H	Replaced indicator/park light assembly.	1168557
8231	#####	1096480	LAMP CLEAR FRNT INDICATOR WRAP-AROUND		1168557
8231	2/7/2023	1094703	STARTERMOTOR 457942 MERC BENZ	Creditor #:GB-MUL001 MULTISAPRES LTD P/O #:G336906 Receiving #:354076 Date :2023-02-07	1167808
8231	2/7/2023	1094703	Mechanic entered - Engine Will Not Start in Neutral unable	Replaced starter motor	1167808
8231	2/7/2023	1095277	Consumables		1167808
8231	2/7/2023	1095277	Mechanic entered - Elec and Light Other starter motor	faulty starter assist Csaba to take it out and put the new one in and checked bus started and then find out the cover behind alternator not in and tried to put it in and find out couple wires insulation is not good put insulation and put the cover back. Complete.	1167808
8231	2/3/2023	1094703	Mechanic entered - Engine Will Not Start in Neutral unable	Assisting.	1167516
8231	2/3/2023	1094703	Mechanic entered - Engine Will Not Start in Neutral unable	Conect jump starter found starter motor only clicking could not direct start. Tow to Red Sqaur.	1167516
8231	2/3/2023	1094703	Mechanic entered - Engine Will Not Start in Neutral unable	Assisting	1167516
8231	#####	1091024	Mechanic entered - Suspension Noisy N/S/R lower torque rod b	Job completed yesterday.	1166632
8231	#####	1093625		Re-tensioned wheel pos. 345&6 with rene.	1166632
8231	#####	1093625		Assisted.	1166632
8231	#####	1090583	VALVE RR MODULATOR MERC BENZ 0500LE A004292124	PART NO LONGER REQUIRED	1166632
8231	#####	1091024	Mechanic entered - Suspension Noisy N/S/R lower torque rod b	Installed 4 new torque rod bolts tensioned them all to standard 10.9 M18 bolt torque all at 350nm.	1166632
8231	#####	1090583	Drv entered - Suspension Soft	Rene booked air leak job for brake modulator nothing to do with suspension. I (Matt) already repaired that airleak replacing all the o-rings for the airlines that go to the brake modulator.	1166632
8231	#####	1091024	Mechanic entered - Suspension Noisy N/S/R lower torque rod b		1166632
8231	#####	1091298	Mechanic entered - Engine Other Sump bolts loose weeping eng	Topped up engine oil 36L topped up coolant checked over everything and started the bus engine has oil pressure running well took bus for long road test return to depot and checked on pit no oil or coolant leaks.	1166632
8231	#####	1091294	Consumables		1166632
8231	#####	1091294	Mechanic entered - Body Other Gearbox floor hatch seized bol	Removed the sized bolt from the body and repaired the gearbox floor hatch fit floor hatch back used anti-sieze on all floor hatch bolts to prevent what happen here.	1166632
8231	#####	1093276		Service now complete now that W/O: 1091298 sump gasket is fixed. Extra oil added to due draining out the whole system.	1166632
8231	#####	1093276	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1093276	Consumables		1166632
8231	#####	1091024	Mechanic entered - Suspension Noisy N/S/R lower torque rod b	Used air hacksaw to remove the N/S/R lower sized bolts I can't install the new bolts without removing the torque rod went to remove the other side they were also sized up badly got the nuts off but they stripped the threads ordered new axle side bolts. torque rod still good to reuse.	1166632
8231	#####	1091024	Mechanic entered - Suspension Noisy N/S/R lower torque rod b	Assisting Matty with removing torque rod bolts	1166632







8231	3/8/2022	1033918	Complete.		1121421
8231	3/8/2022	1033918	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	Inspection Complete	1121421
8231	#####	1031797	BUSH RUBBER SLEEVE RADIATOR 0500LE(A0009872143)		1119686
8231	#####	1031797	Fluid Leaks	Rear of bus check radiator	1119686
8231	#####	1031797	Fluid Leaks	Rear of bus check radiator	1119686
8231	#####	1031797	BOLT HEX HEAD M8 X 40MM FAN DR		1119686
8231	#####	1031797	Fluid Leaks	Rear of bus check radiator	1119686
8231	#####	1031797	Fluid Leaks	Rear of bus check radiator	1119686
8231	#####	1031797	RADIATOR	MERC BENZ 0500LE A00	1119686
8231	#####	1031243	Mechanic entered - Fluid Leaks	Rear of bus coolant leak from	1119322
8231	#####	1030758	Mechanic entered - Engine	Other Sump gasket weep possible t	1119230
8231	#####	1030761	Mechanic entered - Fluid Leaks	Rear of bus coolant hose leak	1119230
8231	#####	1030740	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS S		1119230
8231	#####	1030356			1119115
8231	#####	1030356			1119115
8231	#####	1029929	Mechanic entered - Fluid Leaks	Rear of bus coolant leak	1118823
8231	#####	1029929	CAP RADIATOR 70KPA MERC 0500LE(A0005014615)		1118823
8231	2/2/2022	1023232	L/H LOWER SEAT LUMBAR BUTTONS		1115695
8231	#####	1025708			1115150
8231	#####	1025708	Consumables		1115150
8231	#####	1025708	Consumables		1115150
8231	#####	1025708	Consumables		1115150
8231	#####	1025708	Consumables		1115150
8231	#####	1025353	Mechanic entered - Elec and Light	Exterior Lights n/s front	1114832
8231	#####	1025353	Consumables		1114832
8231	#####	1024821			1114385
8231	#####	1024821			1114385
8231	#####	1024821	DRYER AIR ASSY MERC 0500LE(A0004302915)		1114385
8231	#####	1024821	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)		1114385
8231	#####	1024821	O-RING KIT SMALL VOSS(A0309971748)		1114385
8231	#####	1023494	Ops Entered - Fault - A/C	Heating Not Cooling - Route: 858	1113253
8231	#####	1023170			1113253
8231	#####	1023170	Service		1113253
8231	#####	1023231	Mechanic entered - Elec and Light	Other 4 dash switch globes	1113253
8231	#####	1023231	Consumables		1113253
8231	#####	1023232	Mechanic entered - Body Drivers	Seat Controls missing a butt	1113253
8231	#####	1023232	L/H LOWER SEAT LUMBAR BUTTONS		1113253
8231	#####	1023229	Mechanic entered - Body Rear_	Door Operation Faulty sensitive	1113253
8231	#####	1023204	Mechanic entered - Body	Other outside window both front emer	1113253
8231	#####	1023204	DECAL EMERGENCY EXIT ROCK RED / SILVER	600 x 80MM	1113253
8231	#####	1023230	Mechanic entered - Body	Other wheel arch brush off side from	1113253
8231	#####	1022701	Tablet Entered - Body - Drivers	Seat Controls forward backwa	1112926
8231	#####	1020036	Tablet Entered - Gearbox	Driveline - Rough Gear Change 2nd t	1110637
8231	#####	1013690	BusMinder - Not showing	route not able to select southern d	1105531
8231	#####	1013690	BusMinder - Not showing	route not able to select southern d	1105531
8231	#####	1013690	BusMinder		1105531
8231	#####	1013525	Mechanic entered - BusMinder -	Unable To Log In error in sc	1105277
8231	#####	1013525	Consumables		1105277
8231	#####	1012327	Mechanic entered - Suspension -	Faulty airbag front o/s	1105161
8231	#####	1012327	Mechanic entered - Suspension -	Faulty airbag front o/s	1105161
8231	#####	1012877	Mechanic entered - Body - Front	o/s wheel arc and rubber mis	1105161
8231	#####	1012879	Mechanic entered - Body - Front	Door Operation Faulty Front	1105161
8231	#####	1012877	RUBBER WHEEL ARCH 41294		1105161
8231	#####	1012877	WHEEL ARCH BRUSH 12065		1105161
8231	#####	1012877	Consumables		1105161
8231	#####	1012879	Consumables		1105161
8231	#####	1012880	Mechanic entered - Air System -	Air Leak Rear Air tank charg	1105161
8231	#####	1012880	TEST NIPPLE M22 X 1.5 VOLVO	RAU623777	1105161
8231	#####	1012327	Mechanic entered - Suspension -	Faulty airbag front o/s	1105161
8231	#####	1012326	MOUNT ENGINE REAR MERC BENZ 05		1105161
8231	#####	1012326	Mechanic entered - Gearbox	Driveline - Faulty transmissi	1105161
8231	#####	1012876	Mechanic entered - Elec and Light -	Interior Lights Bus stop	1105161
8231	#####	1012876	Consumables		1105161
8231	#####	1012875	Mechanic entered - Body - Secre	rear n/s bumper.	1105161
8231	#####	1012878	MOUNT EXHAUST MERC 0500LE(A0004910285)		1105161
8231	#####	1012878	Mechanic entered - Body - Faulty	exhaust mount.	1105161
8231	#####	1012875	Consumables		1105161
8231	#####	1012878	Consumables		1105161
8231	#####	1012880	Mechanic entered - Air System -	Air Leak Rear Air tank charg	1105161
8231	#####	1012327	AIRBAG FRONT/RR MERC 0405	0500LE VOLVO B10BLE RR	1105161
8231	#####	1012398	Mechanic entered - Elec and Light -	Next Stop Button Disabled	1105161
8231	#####	1012398	BELL PUSH FOR WHEEL CHAIR PASS (40792)		1105161
8231	#####	1012398	Mechanic entered - Elec and Light	Next Stop Button Disabled	1105161
8231	#####	1012398	Consumables		1105161
8231	#####	1012265			1105161
8231	#####	1012265			1105161
8231	#####	1012265			1105161
8231	#####	1012283	PERFORM CAMPAIGN 20/20 PRE	SUMMER PREVENTATIVE MAINTENANCE C	1105161
8231	#####	1012283	PERFORM CAMPAIGN 20/20 PRE	SUMMER PREVENTATIVE MAINTENANCE C	1105161
8231	#####	1010240	HOSE COOLANT TAPERED 60/70	MER	1104500
8231	#####	1010240	HOSE ENG - G/BOX OIL COOLER	ME	1104500
8231	#####	1010240	HOSE RADIATOR UPPER /LOWER	MER	1104500
8231	#####	1010240	HOSE ENG - G/BOX OIL COOLER	ME	1104500
8231	#####	1010240	Engine - Check all coolant	hoses and replace if required	1104129
8231	#####	1010240	Engine - Check all coolant	hoses and replace if required	1104129
8231	#####	1010240	HOSE RADIATOR UPPER /LOWER	MER	1104129
8231	#####	1010240	HOSE COOLANT 90 DEG TAPERED	60	1104129
8231	#####	1010240	HOSE ELBOW RADIATOR MERC	BENZ	1104129
8231	#####	1000213	Mechanic entered - Body	Other struts for rear hatch need rep	1103232
8231	#####	1000213	STRUT GAS STAY 450Nm 700mm	LONG	1103232
8231	#####	1000213	Consumables		1103232
8231	#####	999675	DIRECT PURCHASE - BUS	INSPECTI	1105277
8231	#####	1006745	Drv entered - A/C	Heating - Not Cooling	1101540
8231	#####	1005867			1100710
8231	#####	1005867			1100710





8231	3/9/2021	959155	Mechanic entered - Body - Seat worn	replaced new seat cushion..	1070986
8231	3/9/2021	959221	Mechanic entered - Body - Disable stop buttons missing	was told to take buttons from bus 592 and Matt fitted them onto 8231..	1070986
8231	3/9/2021	959220	Mechanic entered - Body - Floor hatch bolt missing	replaced floor hatch bolt..	1070986
8231	3/9/2021	959220	FLOOR HATCH SCREWS 13405 + 30628		1070986
8231	3/2/2021	951792	Engine - Blowing white smoke while driving.	completed tune up removed exhaust pipe and checked exhaust brake butterfly as requested by Pine checked exhaust brake air regulator with dulki disconect exhaust brake and road test with Dulki found fault is still there back to workshop remove ecu plug cleaned and refitted will continue tomorrow..	1070986
8231	3/1/2021	957500	Mechanic entered - A/C Heating - Noisy loose pipes in engine	Replaced mount fasteners for discharge pipe	1070985
8231	#####	951792	Engine - Blowing white smoke while driving.	Replaced accelerator pedal and need road test to check over	1070986
8231	#####	951792	ACCELERATOR PEDAL ASSY MERC B	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G293949 Receiving #:307073 Date :2021-02-26	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	c/o	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.		1070986
8231	#####	951792	Engine - Blowing white smoke while driving.		1070986
8231	#####	951792	Engine - Blowing white smoke while driving.		1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	remove intake pipesand check ok rplaced engine breather filter inform Ranjith and suspect transmission problem..	1070986
8231	#####	951792	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)	assisted Howard to remove parts	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	c/o	1070986
8231	#####	951792	N00000005892 AIR FILTER CLAMP	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G292911 Receiving #:306675 Date :2021-02-22	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	c/o for tomorrow	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	fit air filter intake cleaned with prep checked d/or blockage in filter and tighten all clamps when put back in. one clamp broken requested from lee will complete tomorrow	1070986
8231	#####	951792	CLEAN / FLUSH INTERCOOLER	Creditor #:GB-DAN013 DANDENONG RADIATORS PTY LTD P/O #:G292757 Receiving #:306171 Date :2021-02-16	1070986
8231	#####	954663	Leave old poster in and fit you must wear a maskover the	Fitted by Refuellers	1070986
8231	#####	951792	GASKET AIR PIPE - MANIFOLD M	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G292829 Receiving #:305756 Date :2021-02-11	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	Deassembled top and lower intake pipes Cleaned out all oil from pipes. Reassembled intake pipes. Have fitted lower intake pipe to bus. C/O	1070986
8231	#####	951792	Engine - Blowing white smoke while driving.	c/o	1070986
8231	2/9/2021	951792	Engine - Blowing white smoke while driving.	refit turbo pipes and refit muffler checked intercooler and full of oil removed intercooler and send for cleaning..	1070986
8231	2/9/2021	951792	Engine - Blowing white smoke while driving.	Refitted turbo pipes and muffler. Checked intercooler found oil inside Intercooler has been sent to be cleaned C/O	1070986
8231	2/9/2021	951792	M8 X 90 SOCKET HEAD INTERCOOLE	Creditor #:GB-EC0001 ECONOMY BOLT COMPANY PTY LTD P/O #:G292758 Receiving #:305586 Date :2021-02-09	1070986
8231	2/8/2021	951792	NUT TURBO MOUNT 457942 MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G292635 Receiving #:305485 Date :2021-02-08	1070986
8231	2/8/2021	951792	TURBOCHARGER 457954 MERC BENZ	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G292634 Receiving #:305486 Date :2021-02-08	1070986
8231	2/8/2021	951792	Engine - Blowing white smoke while driving.	Leaking seal on turbo removed and replaced	1070986
8231	2/8/2021	951792	STUD TURBO MOUNT 457942 MERC	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G292635 Receiving #:305485 Date :2021-02-08	1070986
8231	2/8/2021	951792	HOSE EXHAUST BRAKE CYL	Creditor #:GB-ENZ001 ENZED DANDENONG P/O #:G292681 Receiving #:305566 Date :2021-02-09	1070985
8231	2/4/2021	951312	Ops Entered - Fault - Breakdown - Route: 900 - Chadstone	defect entered twice.	1070986
8231	2/4/2021	951310	Ops Entered - Fault - Breakdown - Route: 900 - Chadstone	discus with the driver towed bus to depot. (blowing white smoke)	1070986
8231	2/4/2021	951310	DIRECT PURCHASE - TOWING	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G292525 Receiving #:306205 Date :2021-02-17 TOW BUS CHADSTONE TO DANDENONG DEPOT.	1070986
8231	2/4/2021	951029	Replaced by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1070986
8231	#####	949507	Mechanic entered - Air System Air_Leak Rear Air leak coming	repaired	1069983
8231	#####	949507	KIT O-RING LARGE VOSS (A6739970145)		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	949430	Consumables		1069983
8231	#####	947390	CLEAN AIR SYSTEM PIPES	CARRY OUT A SERVICE AS PER CHECK LIST Completed check list.	1069628
8231	#####	947390		Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G291447 Receiving #:304390 Date :2021-01-21	1069365
8231	#####	947390		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air System check completed. Road test to check leak. No leak found	1069365
8231	#####	947390	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1069365
8231	#####	947390	AIR DRYER ASSY MERC BENZ 0500LE A0004302915		1069365
8231	#####	947390	COUPLING AIR HOSE - CONIP MERC BENZ 0500LE A0009970889		1069365
8231	#####	947390	HOSE COMPRESSOR TO UNLOADER MERCEDES A0014292135		1069365
8231	#####	947390	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE A00544327401		1069365
8231	#####	947390			1069365
8231	#####	946646	Removed N/S/F window COVID-19 & MYKI decals and reposition o	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Removed air dryer assemblywater separator and air pipesfit cleaned air pipes C/O	1068898
8231	#####	946382	Please fit A3 poster over COVID-19 poster and hangers to be	Performed campaign.	1068898
8231	1/2/2021	944039	Consumables	Completed by Refuellers	1067122
8231	1/2/2021	944039	Mechanic entered - Elec and Light Exterior Lights R/H headl	Replace globe	1067122
8231	1/2/2021	944039	GLOBE 24V 70W H1		1067122
8231	#####	939284	Mechanic entered - Engine Noisy or Rattling	Muffler mounting completed.	1062696
8231	#####	939284	Mechanic entered - Engine Noisy or Rattling	Tried to fit exhaust pipes. Carry/over	1062696
8231	#####	939830		VEHICLE SAFETY INSPECTION Completed VSI.	1062696
8231	#####	939830		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Rene.	1062696
8231	#####	939830		Assisted.	1062696
8231	#####	939851	Mechanic entered - Wipers and Washers - Wiper blades needs r	Fitted new wiper blades ns and os.	1062696
8231	#####	939851	ASSY WIPER BLADE ASSY 1000mm N102 (TRP1000 is Refill)		1062696
8231	#####	939284	EXHAUST MOUNT MERC BENZ 0500LE A0004910285	Mounted exhaust muffler. Carry/over	1062696
8231	#####	939284	Mechanic entered - Engine Noisy or Rattling	Creditor #:GB-DA001 DAALDER EXHAUSTS P/O #:G289110 Receiving #:301817 Date :2020-12-08	1062696
8231	#####	939284	Repairs to Exhaust pipe	Removed muffler mount and broken portion of exhaust pipe. Carry/over	1062696
8231	#####	939284	Mechanic entered - Engine Noisy or Rattling	Assisted to pull down muffler	1062365
8231	#####	939284	Mechanic entered - Engine Noisy or Rattling	Pull down exhaust muffler and removed broken flexible pipe.	1062365
8231	#####	937843	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	Assisting - Completed	1060746
8231	#####	937843	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	Completed	1060746
8231	#####	935822	Mechanic entered - Vandalism - Graffiti Exterior	completed	1060118
8231	#####	93866	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G287760 Receiving #:300566 Date :2020-11-24 REPLACE L 23 & R 23	1059162
8231	#####	93866	Vandalism - Graffiti Exterior - White Texta Graffiti at rea	completed by Glassprotech	1059162
8231	#####	933725	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed.	1059162
8231	#####	939284	Remove old poster and fit you must wear a face mask when t	Replaced by Refuellers	1058250
8231	#####	930031		Tensioned all front wheel nuts with Nick.	1055505
8231	#####	930031		Assisted.	1055505
8231	#####	929493	Mechanic entered - Suspension Other l/h front sway bar link	remove old and fit new swaybar link.	1055273
8231	#####	929493	LINK SWAY BAR NSF MERC BENZ 0500LE A6283201089		1055273
8231	#####	929493	Mechanic entered - Suspension Other l/h front sway bar link	remove old and fit new swaybar link.	1055273
8231	#####	929544	Fit new Myki Decals & refit COVID-19 decals new position fo	completed.	1055273
8231	#####	929544	Fit new Myki Decals & refit COVID-19 decals new position fo	Assist Mark	1055273
8231	#####	929388		CARRY OUT C SERVICE AS PER CHECK LIST completed.	1055273
8231	#####	929388	FILTER AIR FILTER MERCEDES BENZ (C27-1170)		1055273
8231	#####	929388	FILTER STEERING FILTER (1S3468) (01S3468)349619		1055273
8231	#####	929388	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)		1055273
8231	#####	929388	OIL FAN DRIVE OIL MERC BENZ 0500LE		1055273
8231	#####	929388	FILTER FUEL MERCEDES (AS410900151)		1055273
8231	#####	929388	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)		1055273
8231	#####	929388	OIL ENGINE DELO 400 MGX SAE 15W-40 (MIN)		1055273
8231	#####	929388	FILTER OIL FILTER MERCEDES A0001801709		1055273
8231	#####	929388	OIL ANALYSIS KIT DETECTA AZ-DET25 3350-601 23448457		1055273
8231	#####	929388	Consumables		1055505
8231	#####	929388	Consumables		1055505
8231	#####	929388	Consumables		1055505



8231	8/4/2020	910722	SEAT FOAM CUSHION PAN DRIVERS SEAT ISRI A6008BA5E		1044087
8231	8/4/2020	910722	RECLINE SPRING SUIT ISRI 6008/5/17 L/H		1044087
8231	#####	910215	Remove old A3 Poster and fit with You can no longer top up	Completed by Refuellers	1043801
8231	#####	906658	Consumables		1040718
8231	#####	906650	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1040714
8231	#####	906658	Consumables		1040718
8231	#####	906658	Consumables		1040718
8231	#####	905697	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G279146 Receiving #:291108 Date :2020-07-13 REPLACE R1	1040428
8231	7/9/2020	905697	Vandalism - Replace Anti Graffiti Film - R1	Assisting - Replaced by Glassprotech	1039716
8231	7/9/2020	905697	Vandalism - Replace Anti Graffiti Film - R1	Replaced by Glassprotech	1039716
8231	#####	901305	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	Completed by ECTB	1037123
8231	#####	901251	CCTV CCTV not recording Driver's Compartment Camera N/W (	Fixed Driver Camera.	1036501
8231	#####	901305	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	Bus send to east coast for driver screen fit	1036501
8231	#####	900533	Fit A3 Poster in poster frame and fit decals as requested I	Completed	1036041
8231	6/9/2020	899263		completed.	1035281
8231	6/9/2020	899263		VEHICLE SAFETY INSPECTION Safety Inspectin completed replaced park light light globereplaced 1 interior light globefit 1 reflector. fixed air leak and tensioned all wheel nuts with Darcy	1035281
8231	6/9/2020	899263		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1035281
8231	6/4/2020	898542	Up load new desto file	Updated	1034787
8231	6/3/2020	898327	Driver fan is hanging by the electrical wiring	removed and fitted secondhand fan checked and ok.	1034265
8231	#####	894288	Ops Entered - Fault - Body Drivers Seat Controls - drivers	secure drivers fan mount.	1030495
8231	#####	893442	Body Rear_Door Operation Faulty	Adjust rear door	1030080
8231	#####	893448	Mechanic entered - Body Rear_Door Operation Faulty Rear Door	Fixed.	1030080
8231	5/6/2020	892601	Mechanic entered - Five LED saloon lights out	Replaced broken saloon lights Tested Okay	1029714
8231	5/6/2020	892601	LIGHT INTERIOR LED ORION		1029714
8231	5/6/2020	892601	BOLT BELT TENSIONER BOTTOM ALTERNATOR MERC BENZ 0500LE		1029714
8231	5/6/2020	892601	Consumables		1029714
8231	5/6/2020	892329	ENGINE HATCH MICRO SWITCH BRAC	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G274653 Receiving #:286257 Date :2020-05-07 WELD AS REQUIRED	1029714
8231	5/6/2020	892722		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed cctv service.	1029714
8231	5/5/2020	892329	Body - Engine hatch micro switch bracket welding broken.	Repaired by ECTB	1029612
8231	5/5/2020	892329	Body - Engine hatch micro switch bracket welding broken.	sent bus to ECTB	1029612
8231	5/1/2020	891451	REPAIR DBLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G274437 Receiving #:285934 Date :2020-05-04	1029612
8231	#####	891451	Mechanic entered - Body Passenger Seat Torn N/S/F passenger	fitted new N/S/F passenger seat base	1029250
8231	#####	888315	Engine - Belts Loose Noisy Missing	Replaced hub clutch assembly repaired nose cone so collar would slide into position check super heat @ 8c check compressor functions check epr pressure @ 60 psi tested ok	1029250
8231	#####	888315	Engine - Belts Loose Noisy Missing	Job not completed carry over	1029250
8231	#####	888315	Engine - Belts Loose Noisy Missing	Started om clutch assembly found it wont seat job not completed carry over	1029250
8231	#####	888315	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		1029250
8231	#####	888315	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG		1029250
8231	#####	888889	Mechanic entered - Elec and Light Exterior Lights (ns) rever	replaced.	1029250
8231	#####	888889	LAMP LED REVERSE LAMP RECTANGULAR		1029250
8231	#####	888889	Consumables		1029250
8231	#####	888315	CLUTCH COIL 6PK/9PK PULLEY ASS	Creditor #:GB-QTK001 QTK GROUP P/O #:G273547 Receiving #:285027 Date :2020-04-22	1029250
8231	#####	888315	AIR CONDITIONING REPAIR	Creditor #:GB-22C001 22 CELSIUS P/O #:G273234 Receiving #:285062 Date :2020-04-23	1029250
8231	#####	887962	Mechanic entered - Elec and Light Exterior Lights (os) rever	replaced.	1029250
8231	#####	887962	LAMP LED REVERSE LAMP RECTANGULAR		1029250
8231	#####	887962	Consumables		1029250
8231	#####	885362		Retension pos 3-4 & 5-6 wheel nuts with Abraham.	1027777
8231	#####	885134	Mechanic entered - Wheels and Tyres Worn tyre no 5 low tread	Defect entered wrong. Position 5 and 6 tyres all okay. Removed and fitted new tyres for position 3 and 4. Tensioned wheel nuts with Abraham.	1027206
8231	#####	885134	TYRE 295/80R22.5 NEW		1027206
8231	#####	885134	Consumables		1027206
8231	#####	885134	Consumables		1027206
8231	#####	884791	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	check and fixed front and rear passenger doores bus ok.	1027206
8231	#####	884723	Fault#:37496 - Ops Entered - Fault - Breakdown Air System Fa	Attended break down at Caulfield Station. Checked for fault found out rear door Drivers manual lock accidentally locked. Unlock and isolate the system check operation ok. Bus can be use.	1027206
8231	#####	883837	Tape off front Seats of All Route and Rail Buses with spec	Done	1026609
8231	#####	882056		VEHICLE SAFETY INSPECTION Completed Safety inspection.	1025521
8231	#####	882056		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1025521
8231	#####	882057	ELBOW COUPLING 90 DEGREES		1025521
8231	#####	882057	EXHAUST MOUNT MERC BENZ 0500LE A0004910285		1025521
8231	#####	882057		CARRY OUT A SERVICE AS PER CHECK LIST Completed A service Replaced 2x Exhaust mounts and Fixed air leak.	1025521
8231	#####	882057	NUT VOSS 232 22mm MERCEDES (49G4527WABCO)		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	882057	Consumables		1025876
8231	#####	881817	Remove old poster and fit Reduce Your Risk of Coronavirus	Completed by Refuellers	1025521
8231	#####	880094	CLEAN AIR SYSTEM PIPES	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G271274 Receiving #:282324 Date :2020-03-19	1025156
8231	#####	880127	Mechanic entered - Air System Air_Leak Rear Air bag control	Put stand and secure bus body. Remove and replace suspension solinoid valve. Replace air line fittings and air line pipe. Start bus build-up air check suspension operation ok.	1024820
8231	#####	880127	VOSS NUT 232 22MM (A000997483401)		1024820
8231	#####	880127	AIR DRYER FITTING ELBOW 16MM MERC BENZ 0500LE		1024820
8231	#####	880094	replace air system pipe lines.	replace all air system pipes.	1024820
8231	#####	880094	replace air system pipe lines.		1024820
8231	#####	880094	KIT O-RING LARGE VOSS (A6739970145)		1024820
8231	#####	880127	SOLENOID VALVE LEVELLING CNT	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G270945 Receiving #:282037 Date :2020-03-16	1024820
8231	#####	880127	Mechanic entered - Air System Air_Leak Rear Air bag control	Remove circuit valve assembly replace al o-ring kit Remove suspension solinoid valve fitting fitted new o-ring. Found stll leaking from suspension solinoid valve body need new solinoid valve. Carry over.	1024820
8231	#####	880094		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed check list. Air line pipe to do.	1024820
8231	#####	880094	AIR DRYER ASSY MERC BENZ 0500LE A0004302915		1024820
8231	#####	880094	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1024820
8231	#####	880094	KIT O-RING LARGE VOSS (A6739970145)		1024820
8231	#####	880094	KIT O-RING SMALL VOSS (A0309971748)		1024820
8231	#####	880094	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1024820
8231	#####	880094	SILENCER AIR DRYER MERC 0500LE		1024820
8231	3/4/2020	878558		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Completed check list.	1023455
8231	3/4/2020	878558	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221		1023455
8231	3/4/2020	878575	Mechanic entered - Engine Other Alternator belt worn.	replaced belt	1023455
8231	3/4/2020	878575	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		1023455
8231	3/4/2020	878575	Mechanic entered - Engine Other Engine oil leak from oil sen	Remove sensor and fitted new o-ring. Steam clean engine and radiator plus roadtested re check for leak all ok.	1023455
8231	#####	876691	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1019621
8231	#####	869751		re-tensioned nuts on wheels 3 and 4 with indika.	1016351
8231	#####	869483	Mechanic entered - Suspension Noisy L/R	replace N/R swaybar link and tension the wheel nut position 3 and 4 with Sisl	1016351
8231	#####	869483	Mechanic entered - Suspension Noisy L/R	replaced N/R sway bar link tensioned wheel nut pos34 with Darsi	1016351
8231	#####	869483	BOLT ALTERNATOR ADJ MERC 0500LE		1016351
8231	#####	869483	LINK RR SWAY BAR MERC BENZ D	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G267312 Receiving #:277974 Date :2020-01-24	1016351



8231	#####	849424	Mechanic entered - Engine Other Muffler flexi pipe leaking.	Fitted flexi pipe to muffler and fitted flexi pipe to turbo mount align Re fit muffler assembly to mount. Tension all muffler and flexi clamp.	1005100
8231	#####	850583	Consumables		1005100
8231	#####	850583	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1005100
8231	#####	850583	Mechanic entered - Elec and Light Other Emergency exit light	Remove light assembly to remove needed to remove over head panel. Fitted new light assembly joint wiring test works ok. Re fit over head panel.	1005100
8231	#####	849436	Mechanic entered - Brakes Other Rear rotor need change.	Brake test and roadtest check brake operation ok.	1005100
8231	#####	850595	KIT O-RING LARGE VOSS (A6739970145)		1005100
8231	#####	850595	Mechanic entered - Air System Air_Leak Rear Top air line air	Remove and replace all voss nut o ring air line kit all. Fitted 8 o ring kit. Start bus build - up air check for leak no leak from air line fix.	1005100
8231	#####	849436	Mechanic entered - Brakes Other Rear rotor need change.	c/o	1005000
8231	#####	850278	Brakes replace both rear brake rotors.	Dis assemble n/s old caliper fitted new caliper to brake carrier. Fitted new caliper n/s and tension all bolts according to specification. Fitted new brake pads n/s and adjust brake. Re fit caliper o/s and tension all bolts according to specification. Fitted new brake pads and adjust brakes. Remove rear ABS sensor both side c	1005100
8231	#####	849436	CALIPER RR BRAKE LH MERC BEN		1005100
8231	#####	849436	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)		1005000
8231	#####	849436	ROTOR FRONT & REAR MERC 0500LE A9424230112		1005000
8231	#####	849436	SET DISC PAD SET SCANIA / MERCEDES 0500		1005000
8231	#####	849436	SENSOR ABS RWR 4000MM MERC B	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G260941 Receiving #:270932 Date :2019-10-24	1005100
8231	#####	849436	SENSOR ABS LHR 2800MM MERC B	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G260941 Receiving #:270932 Date :2019-10-24	1005100
8231	#####	849436	Mechanic entered - Brakes Other Rear rotor need change.	Remove o/s caliper pads and hub assembly clean both hub. Remove o/s and n/s seal runner fitted new and Re fit hub bearing and fitted new seal inner and outer abs ring sensor new o/s and n/s. Re fit hub assembly and tension hub nut according to specification both side o/s and n/s rear. Adjust bearing free play tens	1005000
8231	#####	850604	TORQUE ROD RR LWR MERC BENZ	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G260778 Receiving #:271070 Date :2019-10-28	1005100
8231	#####	849388	REPAIR SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G260754 Receiving #:270685 Date :2019-10-23	1005100
8231	#####	849436	Mechanic entered - Brakes Other Rear rotor need change.	Remove brake pads caliper hub assembly and rotor n/s rear. Carry over.	1005000
8231	#####	849357		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed check list.	1005000
8231	#####	849357		PRE ANNUAL SAFETY INSPECTION CHECK Completed check list.	1005000
8231	#####	849413	Consumables		1005100
8231	#####	849413	Mechanic entered - Wheels and Tyres Worn Tyre position 3 wor	Remove position 3 and fitted second hand tyre.	1005000
8231	#####	849416	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		1005000
8231	#####	849416	Mechanic entered - Suspension Other Air bag rear of rearlea	Remove and fitted new air bag.	1005000
8231	#####	849424	Mechanic entered - Engine Other Muffler flexi pipe leaking.	Remove muffler assembly and flexi pipe. Flexi pipe for repair or change. Separate flexi pipe from muffler assembly - Kumar give assist to remove flexi pipe.	1005000
8231	#####	849399	MUFFLER MOUNTING (A0004910285)		1005000
8231	#####	849399	Mechanic entered - Engine Other Muffler mounting worn.	Remove and fitted two new rubber mounting.	1005000
8231	#####	849401	Mechanic entered - Body Other N/s rear bumper panel missing	Secured panel fitted new screw panel.	1005000
8231	#####	849388	SINGLE SEAT BASE		1005000
8231	#####	849388	Mechanic entered - Body Passenger Seat Torn 7x passenger sea	Removed and fitted new seat bases.	1005000
8231	#####	849438	Mechanic entered - Body Other Passenger seat cushion torn ne	replaced	1005000
8231	#####	849411	Mechanic entered - Body Other Passenger rear door sensitive	Adjust sensitive edge.	1005000
8231	#####	849436	Mechanic entered - Brakes Other Rear rotor need change.	Remove rear wheel n/s and start to remove brakes Job to continue carry over.	1005000
8231	#####	849404	SUMP RING 24MM VOLVO B12BLE 20579690		1005000
8231	#####	849404	VALVE MANUAL DRAIN VALVE		1005000
8231	#####	849404	Mechanic entered - Air System Other Rear air tank drain tap	Remove three air tank drain tap fitted new.	1005000
8231	#####	844455	AIR CDN REFRIDGERANT		1004489
8231	#####	844455	Mechanic entered - A/C Heating Not Cooling	Repair refrigerant leak in corner pillar tested ok	1004489
8231	#####	844455	Mechanic entered - A/C Heating Not Cooling		1004185
8231	#####	846708		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST washed under bus and engine.did the inspection	1003475
8231	#####	845666	Consumables		1003115
8231	#####	845666	Mechanic entered - Elec and Light Exterior Lights o/s front	fit globe.	1002672
8231	#####	839562	SP-RALEXT100314 SEAT BEAM	Creditor #:GB-MCC001 MCCONNELL SEATS AUSTRALIA P/O #:G256773 Receiving #:269116 Date :2019-10-07	1003475
8231	#####	844455	Mechanic entered - A/C Heating Not Cooling	Refrigerant leak in right pillar engine bay Job not completed carry over	1002129
8231	#####	844455	AIR CDN REFRIDGERANT		1002129
8231	#####	844397	Mechanic entered - A/C Heating Not Cooling	Locate and repair refrigerant leak pipe was crushed at condenser liquide out let pipe	1002129
8231	#####	844453		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1002129
8231	#####	843358	Consumables		1000492
8231	#####	843358	STALK INDICATOR MERCEDES 0500 LE A0085450124		1000468
8231	#####	843358	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	check LH indicator n/w replaced indicator switch assy	1000468
8231	#####	843141	Consumables		1000468
8231	#####	843141	GLOBE 24V 75/70W H4		1000365
8231	#####	843141	Mechanic entered - Elec and Light Exterior Lights L/H side h	replaced.	1000365
8231	#####	839563	Consumables		999496
8231	#####	839563	Mechanic entered - Elec and Light Other l/h passenger stop b	fit new stop button.	999496
8231	#####	839563	BELL PLUSH FOR WHEEL CHAIR PASS		999496
8231	#####	839562	CAP END CAP CENTRA SEAT END CAP		999496
8231	#####	839562	Mechanic entered - Body Other l/h folding seat frame base br	fit new deat frame base.	999496
8231	9/2/2019	839561	SHOCK ABSORBER RR MERC BENZ 0	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G256900 Receiving #:266291 Date :2019-09-02	997286
8231	9/2/2019	839561	Mechanic entered - Suspension Other r/h/r shock absorbers le	fit new shock absorbers 2.	996370
8231	9/2/2019	839565	MUFFLER MOUNTING (A0004910285)		996370
8231	9/2/2019	839565	Mechanic entered - Engine Other muffler rubber mount torn.	fit new muffler mount.	996370
8231	9/2/2019	839764	Consumables		997310
8231	9/2/2019	839764	GLOBE 24V 70W H1		996370
8231	9/2/2019	839764	Mechanic entered - Elec and Light Exterior Lights headli	R/R o/s head light globe and f/o/s bottom park light globe.	996370
8231	9/2/2019	839560	Mechanic entered - Body Other fit step tred at rear seats.	fit new step tred.	996370
8231	9/2/2019	839559	Mechanic entered - Body Other secure r/h r 1/4 bumper.	fit new bumper bolts and secure.	996370
8231	9/2/2019	839525	Mechanic entered - Body Other secure l/h/r rear 1/4 bumper .	fit new bumper bolts and secure.	996370
8231	9/2/2019	839557	WHEEL ARCH BRUSH 12065		996370
8231	9/2/2019	839557	Mechanic entered - Body Other fit new front wheel arch brus	Assisting	996370
8231	9/2/2019	839557	Mechanic entered - Body Other fit new front wheel arch brus	wheel arch brushes fitted.	996370
8231	9/2/2019	839564	Mechanic entered - Body Other drivers door hinges worn.	fit new door hinges.	996370
8231	9/2/2019	839564	HINGE DRIVERS COMPARTMENT 12205 49080		996370
8231	#####	838952	Consumables		996681
8231	#####	838950	Consumables		996681
8231	#####	838949	Consumables		996681
8231	#####	838952	DECAL EMERGENCY EXIT ROCK RED / SILVER 600 x 80MM		996370
8231	#####	838950	DECAL DISABLED WHITE ON BLUE S/SIDED 150MM X 150MM		996370
8231	#####	838949	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		996370
8231	#####	838920		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	996272
8231	#####	838920		VEHICLE SAFETY INSPECTION completed.	996272
8231	#####	838951	Consumables		996370
8231	#####	838948	Consumables		996370
8231	#####	838952	Mechanic entered - Body Other fit new rear emergency exit dec	fitted new decal.	996272
8231	#####	838951	Mechanic entered - Body Other fit max capacity numbers (75)	fit new numbers.	996272
8231	#####	838950	Mechanic entered - Body Other fit new wheelchair decal at fro	fitted new decal.	996272
8231	#####	838949	Mechanic entered - Body Other fit new rear door decal.	fit new decal.	996272
8231	#####	838948	Mechanic entered - Body Other fit new invalid decal.	fitted new decal.	996272
8231	#####	837174	Mechanic entered - Air System Other Air tank drain valve fau	Replaced 2 air tank drain valve	995043
8231	#####	837174	WASHER OIL PLUG		995043
8231	#####	837174	VALVE MANUAL DRAIN VALVE		995043
8231	#####	837152	Consumables		995160
8231	#####	837152	Consumables		995160
8231	#####	837152	Consumables		995160





8231	#####	774023	KIT O-RING LARGE VOSS (A6739970145)			944070
8231	#####	774322	Wipers and Washers - Clean wiper jets	completed		944070
8231	#####	774322	Wipers and Washers - Clean wiper jets	cleaned		944070
8231	#####	774324	Consumables			944476
8231	#####	774324	GLOBE 24V LOW SINGLE CONTACT			944070
8231	#####	774319	Body - replace front sunblind and secure side blind	replaced the blind		944070
8231	#####	774321	Body - Secure hand rail grabs	completed secured all hand rail grabs		944070
8231	#####	774321	Body - Secure hand rail grabs	fixed		944070
8231	#####	774023	Brakes - Replace rear brake EBS modulator valve	replaced valve and air fitting oring kit		944070
8231	#####	774272	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR			944070
8231	#####	774272	Suspension - Replace both NSR airbags	replaced both air bags		944070
8231	#####	774318	HEATER VALVE DEMISTER MERC 0500LE			944070
8231	#####	774318	Engine - Repair coolant leak in demister area	replaced leaked demister tap		944070
8231	#####	774271	Engine - Remove floor hatches and s/clean	completed		944070
8231	#####	774325	Consumables			944476
8231	#####	774323	Consumables			944476
8231	#####	774324	Elec and Light - Replace NSF park light globe	replaced		944070
8231	#####	774324	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)			944070
8231	#####	774325	Elec and Light - Replace interior lamp globe	replaced		944070
8231	#####	774323	Elec and Light - Replace next stop sign globe	replaced		944070
8231	#####	774319	BLIND DRIVERS VOLGREN 3800mm	Creditor #:GB-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:G232254 Receiving #:239938 Date :2018-10-18		944476
8231	#####	774059	PLASTIC WASHER			944070
8231	#####	774059	BOLT BUMPER BAR BOLT SPECIAL			944070
8231	#####	774406	Mechanic entered - Body Passenger Seat Torn 5	removed 4 desable seats and one normal seat sent for repair		944070
8231	#####	774320	Body - Repair OS mirror arm	repaired		944070
8231	#####	774023	MODULATOR VALVE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G232093 Receiving #:239930 Date :2018-10-18		944476
8231	#####	773939	KIT O-RING SMALL VOSS (A0309971748)			944070
8231	#####	773939		PRE ANNUAL SAFETY INSPECTION CHECK carried RSI check as per check list.		944070
8231	#####	774059	Body - Replace rear bumper bolt	replaced.		944070
8231	#####	774031	Body - Secure all lower skirt panels	retight		944070
8231	#####	773997	Mechanic entered - Air System Air_Leak Rear replace rear rel	done replaced		944070
8231	#####	773859		Assisting		944070
8231	#####	773859		Tensioned all rear tyres.		944070
8231	#####	773437	MUFFLER MOUNTING (A0004910285)			944069
8231	#####	773437	Mechanic entered - Engine Other exhaust mount u/s	found broken mount. remove and replaced mount		944069
8231	#####	773525	Mechanic entered - Body Rear_Door Operation Faulty sensitive	adjusted rear door sensitive edge		944069
8231	#####	773462	SINGLE SEAT BASE			944069
8231	#####	773462	Mechanic entered - Body Passenger Seat Torn	replaced rear passenger seat		944069
8231	#####	773350	KIT O-RING SMALL VOSS (A0309971748)			944069
8231	#####	773350	KIT O-RING LARGE VOSS (A6739970145)			944069
8231	#####	773350	FITTING JOINER 8MM / 5/16			944069
8231	#####	773350	Mechanic entered - Air System Air_Leak Rear air leak at tran	replaced air line from accumulator solenoid back to joiner and replaced joiner. found 3 fittings leaking at relay valve replaced 3 voos kits. found air tank fitting leaking replaced voss fitting. found drain valve on tank leaking		944069
8231	#####	773350	VALVE MANUAL DRAIN VALVE			944069
8231	#####	772976	GLOBE LED FOR SWF SWITCH (17040) (SWFLED) (47706)			944069
8231	#####	772976	BOSCH TWIN WINDSCREEN WASHER JET			944069
8231	#####	772976		road tested and checked light only.		944069
8231	#####	772976		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS carried out inspection as required		944069
8231	#####	772976		VEHICLE SAFETY INSPECTION		944069
8231	#####	773056	Mechanic entered - Wipers and Washers Washers Not Working	blow out both washer jets amd replace R/H side jets		944069
8231	#####	773058	Mechanic entered - Body Other	rear modesty panel loose. secured with screws.		944069
8231	#####	773004	SET DISC PAD SET SCANIA / MERCEDES 0500			944069
8231	#####	773004	Mechanic entered - Brakes Other rear brakes low	replaced rear brake pads. tensioned wheels to spec 700Nm		944069
8231	#####	770865	FIRE SAFETY INSPECTION	Creditor #:GB-CAR020 CARDINIA P/O #:G231093 Receiving #:239156 Date :2018-10-09 SERVICE AS REQUIRED		942942
8231	#####	771033	SINGLE SEAT BASE			942350
8231	#####	771033	Mechanic entered - Body Passenger Seat Torn	replaced.		942350
8231	#####	770865	Completed by Graeme from Cardinia Auto Elec	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST		942350
8231	#####	770036	COMPRESSOR OIL AIR CON			941460
8231	#####	770036	FILTER DRYER AIR COND THERMO KING			941460
8231	#####	770036		CARRY OUT A/C - B SERVICE AS PER CHECK LIST		941460
8231	#####	770036		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced return air filter medium serviced as per list		941460
8231	#####	769770	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers		941460
8231	#####	766400	CABLE CAMERA EXTENSION DIN JACK 5M			938193
8231	#####	766400	CCTV (None) Camera Opposite Rear Passenger Door	removed all ducts and ran cctv cabling.hook all up set up checked and ok.		938193
8231	#####	767595	Consumables			938981
8231	#####	767607	Consumables			939881
8231	#####	767607	Mechanic entered - Elec and Light Exterior Lights R/H headli	replaced globe		938193
8231	#####	767595	Mechanic entered - Elec and Light Exterior Lights O/F head I	replaced globe		938193
8231	#####	767595	GLOBE 24V 70W H1			938193
8231	#####	767606	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	completed		938193
8231	#####	766400	CABLE CAMERA EXTENSION DIN JACK 5M			938193
8231	#####	765924	Consumables			938418
8231	#####	765924	Mechanic entered - Elec and Light Exterior Lights o/s revers	secured.		938193
8231	#####	766400	CCTV (None) Camera Opposite Rear Passenger Door	found no camera fitted fitted spare thoreb one and spare adapter.still not workin found that specific line had been terminated.Need to order 5-6 meter thoreb cable to run from unit to camera.		938193
8231	#####	766146	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG		938193
8231	9/8/2018	764969		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST		937500
8231	9/8/2018	764970	Consumables			937617
8231	9/8/2018	764970	Consumables			937617
8231	9/8/2018	764970	Consumables			937617
8231	9/8/2018	764970	Consumables			937617
8231	9/8/2018	764970	Consumables			937500
8231	9/8/2018	764970	Consumables			937500
8231	9/7/2018	764853	cleaned vandalism as required			937500
8231	9/7/2018	764853	Vandalism Vandalism/ Graffiti Interior. Rear seats	done by eastcoast		937500
8231	9/7/2018	764853	Interior decals peeling off	done by eastcoast		937500
8231	9/1/2018	761497	CLEAN AIR SYSTEM PIPES	Creditor #:GB-HMG001 HM GEM ENGINES P/O #:G227929 Receiving #:236510 Date :2018-09-06		937323
8231	#####	763177	Consumables			935726
8231	#####	763177	Mechanic entered - Elec and Light Other rear side low beam o	lights checked - all working o.k.		935415
8231	#####	763106	Consumables			935726
8231	#####	763106	GLOBE 24V 70W H1			935415
8231	#####	763106	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	removed and replaced globe		935415
8231	#####	761497	NUT VOSS 232 22mm MERCEDES (49G4527WABCO)			934642
8231	#####	761497	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)			934642
8231	#####	761497	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE			934642
8231	#####	761497	KIT O-RING SMALL VOSS (A0309971748)			934642
8231	#####	761497	KIT O-RING LARGE VOSS (A6739970145)			934642







8231	#####	680929	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	871576
8231	#####	680929	VEHICLE SAFETY INSPECTION	871576
8231	#####	679946	SILENCER DOOR VALVE SILENCER	870940
8231	#####	679946	FILTER PNEUMATIC REGULATOR DOOR RAM (AW20-02H-C)	870940
8231	#####	679946	BRACKET FILTER REGULATOR	870940
8231	#####	679946	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON	870940
8231	#####	679946	BUTTON CLIPPARD DOOR VALVE 4924811	870940
8231	#####	679946	Ops Entered - Fault - Passenger Doors - Route: 900 - Stud P	870940
8231	8/8/2017	678943	Consumables	869843
8231	8/8/2017	678943	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)	869523
8231	8/8/2017	678943	LAMP CLEAR/AMBER FRONT INDICATOR WRAP-AROUND	869523
8231	8/8/2017	678943	Elec and Light - Front RH bottom park light out	869523
8231	8/3/2017	677913	Please remove old posters and fit new one along with hangers	868499
8231	#####	672319	CLEAN AIR SYSTEM PIPES	865138
8231	#####	674536	Consumables	864562
8231	#####	674536	LED INTERIOR ROOF LIGHT (Use P/No. NR87676G)	864562
8231	#####	674536	Mechanic entered - Elec and Light Interior Lights	864562
8231	#####	673974	Consumables	864562
8231	#####	673974	FIRTREE CLIP SIDE PILLAR	864343
8231	#####	673974	Elec and Light - RHs interior lights n/w x 2	864343
8231	#####	673974	Engine - Oil leak from sump oil pipe LHS	864343
8231	#####	673971	Engine - Oil leak from sump oil pipe LHS	864343
8231	#####	673975	Mechanic entered - Body Other Rear engine hatch insulation c	864343
8231	#####	673973	Body (None) Rear step inside bus has yellow grip missing	864343
8231	#####	672319	Check air System repair as require	864343
8231	#####	672071	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR	864343
8231	#####	672071	Suspension - RHR rear airbag leaking	864343
8231	#####	672071	Fluid Leaks - Check for coolant leak	864343
8231	#####	672071	Engine - Oil leak from oil pressure switch at filters	864343
8231	#####	672071	Consumables	864343
8231	#####	672071	AMBER REFLECTOR	864343
8231	#####	672071	Elec and Light - LH amber reflectors missing	864343
8231	#####	672071	BOLT BUMPER BAR BOLT SPECIAL	864343
8231	#####	672071	PLASTIC WASHER	864343
8231	#####	672071	Body - Secure rear bumper LH 1/4 panel	864343
8231	#####	672071	Body (None) Sunvisor shoots up when go over a bump.	864343
8231	#####	672319	VALVE MANUAL DRAIN VALVE	864343
8231	#####	672319	Check air System repair as require	864343
8231	#####	672071	Air System - Front air tank drain valve leaking	864343
8231	#####	672071	Drv entered - Elec and Light Exterior Lights	864343
8231	#####	672319	COMPRESSOR PIPE UNION	864343
8231	#####	672319	AIR COMPRESSOR COOLANT PIPE 0500	864343
8231	#####	672319	SEAL O-RING POWER STEERING PUMP MERCEDES 0500LE	864343
8231	#####	672319	GASKET COMPRESSOR 0500LE (A4571304815)	864343
8231	#####	672319	Check air System repair as require	864343
8231	#####	672319	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)	864343
8231	#####	672319	KIT AIR LINE FITTING VOSS 22MM (5020114)	864343
8231	#####	672319	KIT AIR LINE FITTING VOSS 22MM (5020114)	864343
8231	#####	672319	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115	864343
8231	#####	672319	SEAL RING A/DRYER	864343
8231	#####	672319	VALVE 4 WAY CIRCUIT PROTECTION VALVE	864343
8231	#####	672319	COUPLING AIR HOSE COMPRESSOR MERCEDES 0500 (50G4501)	864343
8231	#####	672319	HOSE COMPRESSOR TO UNLOADER MERCEDES (A0014292135)	864343
8231	#####	672319	Check air System repair as require	864343
8231	7/7/2017	672319	AIR LINE 0500	866235
8231	7/7/2017	672319	AIR COMPRESSOR 0500 EURO 3 A45	864343
8231	7/7/2017	672319	SILENCER 0500	864343
8231	7/7/2017	672319	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE	864343
8231	7/7/2017	672319	KIT CYCLONE CONDENSER VALVE KIT	864343
8231	7/7/2017	672319	KIT HALDEX COIL KIT MERCEDES 0500LE (49G0027)	864343
8231	7/7/2017	672319	KIT DRAIN VALVE KIT BOTTOM	864343
8231	7/7/2017	672319	KIT HALDEX CONDENSER KIT TOP (CYCLONE)	864343
8231	7/7/2017	672319	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER	864343
8231	7/6/2017	672319	AIR LINE 0500	864343
8231	7/6/2017	672319	AIR LINE 0500 EURO 3	864343
8231	7/6/2017	672319	AIR LINE 0500 EURO 3	864343
8231	7/6/2017	672319	Check air System repair as require	864343
8231	7/5/2017	672101	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	864343
8231	#####	671419	Fluid Leaks Rear of bus	863790
8231	#####	671204	R/R top elbow hosefitted clampstopped up coolant and escorted bus to depot. Re c- check coolant level - ok. Steam clean engine.	863790
8231	#####	671204	Ref to w/o # 671204	863790
8231	#####	671419	Breakdown	863790
8231	#####	671419	Breakdown	863790
8231	#####	670732	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROGRAM UPDATE	863480
8231	#####	670611	Breakdown#:33469 - Ops Entered - Breakdown - Breakdown Road	863480
8231	#####	670611	Breakdown#:33469 - Ops Entered - Breakdown - Breakdown Road	863480
8231	#####	668273	Consumables	862286
8231	#####	668273	GLOBE 24V 70W H1	861261
8231	#####	668024	Remove old Green 2016/17 registration Label and/ or Blue EF	861261
8231	#####	668279	Body Rear Door Operation Faulty REAR DOOR SEAL IS HANGING	861261
8231	#####	668474	Consumables	862286
8231	#####	668474	Consumables	862286
8231	#####	668474	Consumables	862286
8231	#####	668474	Consumables	862286
8231	#####	668474	Consumables	862286
8231	#####	668474	Consumables	862286
8231	#####	668474	CARRY OUT A SERVICE AS PER CHECK LIST completed.	861261
8231	#####	668474	CARRY OUT A SERVICE AS PER CHECK LIST completed.	861261
8231	#####	668029	Consumables	861261
8231	#####	668029	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	861261
8231	#####	668029	VEHICLE SAFETY INSPECTION completed.	861261
8231	#####	668029	GLOBE 24V SW WEDGE INSTRUMENT PANEL (17197)	861261
8231	#####	668029	AMBER REFLECTOR	861261
8231	#####	668273	Elec and Light - RHF lower park light n/w	861261
8231	#####	666202	REPLACE /FIT ANTI GRAFFITI FIL	860474
8231	#####	666202	REPLACE /FIT ANTI GRAFFITI FIL	860474

8231	#####	667004 Breakdown Road Defect Unaffacts Serviceair leaking	bus B/Down near Dande Plaze fixed temperaly and drive to depot fixed air leak bus ok.	860036
8231	6/8/2017	666420 Ops Entered - Fault - CCTV not recording - since 27/04/2017	checked, recording	859570
8231	6/7/2017	666202 Vandalism - Fit & Replace anti graffiti film - L 124 R 12	REPLACED	859570
8231	6/6/2017	666039 HEATER-DEMISTER VALVE TAP MERC 0500 (DHW4008)		859323
8231	6/6/2017	666039 Fluid Leaks Front of bus	Remove and replace coolant heater valve and steam clean roadtest check heater operation ok topped-up coolant.	859323
8231	6/2/2017	665094 SEAL 4 WAY PROTECTION VALVE BARREL MERCEDES 0500LE		858128
8231	6/1/2017	665094 Check and repair no air for the door	check and fixed faulty air system road test bus ok.	858048
8231	#####	664030 SEAT SEAT ASSY ISRI A6008 AIR LUMBAR CHANGE OVER		857333
8231	#####	664030 Body - Replace drivers seat	fit a reco driver seat	857333
8231	#####	663010 Consumables		856305
8231	#####	663010 Fit A3 Poster/Hangers	Fitted	85612
8231	#####	661347 Bus had steam coming from engine hatch - unable to see leak	Rectify coolant leak found heater hose leaking. C/F - Replace heater hoses	854175
8231	#####	661347 Bus had steam coming from engine hatch - unable to see leak	Rectify coolant leak found heater hose leaking. C/F	854175
8231	5/5/2017	658435 Body - Internal body rattles	Secured plastic panels-	851199
8231	5/3/2017	659230	Assisting	851199
8231	5/3/2017	659230	Tensioned front tyres.	851199
8231	5/3/2017	658435 Consumables		851701
8231	5/3/2017	658435 TYRE 11R22.5N NEW		851199
8231	5/3/2017	658435 VALVE MANUAL DRAIN VALVE		851199
8231	5/3/2017	658435 KIT AIR LINE FITTING VOSS 22MM (5020114)		851199
8231	5/2/2017	658435 Wheels and Tyres - RHR tyre has flat spots	R/R front tyres and tensioned wheel nuts with Shalen.	851199
8231	5/2/2017	658435 Warning Lights Coolant	Finished job and road tested - ok.	851199
8231	5/1/2017	658435 Suspension - Suspension leaning right rear	Calibrated suspension and repair air leaks.	851199
8231	5/1/2017	658435 Fluid Leaks - Water pump leaking		851199
8231	5/1/2017	658435 Engine - Steamclean engine & gearbox	Done	851199
8231	5/1/2017	658435 Warning Lights Coolant	Fitted new radiatorwashed intercoolerfitted to bus.Modified fan shroud brackets.	851199
8231	5/1/2017	658435 RADIATOR 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G192565 Receiving #:199375 Date :2017-05-01	851199
8231	#####	658435 Fluid Leaks - Water pump leaking	R/R water pump. STARTED to removed radiator. C/F	851199
8231	#####	658435 PUMP WATER PUMP WITH GASKETS MERCEDES 0500LE (50A4323)		851199
8231	#####	658152	VEHICLE SAFETY INSPECTION completed	851199
8231	#####	658152	VEHICLE SAFETY INSPECTION completed	851199
8231	#####	658152	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Matt and Mohamad done	851199
8231	#####	658152	VEHICLE SAFETY INSPECTION completed	851199
8231	#####	658152 GLOBE 24V 5W SINGLE CONTACT (17181)		851199
8231	#####	658193 Consumables		851199
8231	#####	658193 Elec and Light - bus stop sign light out.	replaced.globe.	851199
8231	#####	658193 Elec and Light - One interior light out.	replaced.	851199
8231	#####	658193 Body - Both doors emergency door button cover broken		851199
8231	#####	658193 EMERGENCY EXIT BUTTON PULL COVER (16906)		851199
8231	#####	655963 Fluid Leaks - Rectify coolant leaks at Transmission.	Checked for leaks and road test bus with Alan	849069
8231	#####	656859 Air System Air_Leak Rear from retarder hose.	fit new air union seals,road tested checked coolant ok.	849069
8231	#####	656859 Air System Air_Leak Rear from retarder hose.	Changed seals and road test for coolant leaks.	849069
8231	#####	656859 AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115		849069
8231	#####	655963 Fluid Leaks - Rectify coolant leaks at Transmission.	R/R coolant pipe.Secured pipe brackets missing bolts. Also secured air compressor flex hose.Top up coolant.	849069
8231	#####	655963 COOLANT PIPE	Creditor #:GB-WH004 WHITEHORSE TRUCKS PTY LTD P/O #:G191676 Receiving #:198437 Date :2017-04-18	849069
8231	#####	655963 Fluid Leaks - Rectify coolant leaks at Transmission.	checked and found g/box cooler pipe leak parts on order.	849069
8231	4/3/2017	654390	tensioned both side rear wheel nut with Ranjith	847046
8231	#####	653821 Consumables		846574
8231	#####	653821 Consumables		846574
8231	#####	653821 Mechanic entered - Wheels and Tyres Wheel Nut Retension	RETENSIONED	845551
8231	#####	653037 Brakes - RHR caliper faulty	fit new r/h/r caliper and rear brake pads.	845551
8231	#####	653037 Mechanic entered - Brakes Other rear brake pads worn.	fit new r/h/r caliper and rear brake pads.	845551
8231	#####	653037 Mechanic entered - Brakes Other rear brake pads worn.		845551
8231	#####	653037 OSR BRAKE CALLIPER		846574
8231	#####	653037 SET DISC PAD SET SCANIA / MERCEDES 0500	Creditor #:GB-TRAD20 TRADE BRAKE AND CLUTCH CO. P/O #:G190392 Receiving #:197243 Date :2017-03-29	845551
8231	#####	653037 Air System - Air lines around dryer leaking	fit new seals to 4way valve/air dryer.	845551
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		846194
8231	#####	652888 Consumables		845551
8231	#####	652888		845551
8231	#####	652357 Vandalism Vandalism/ Graffiti Interior Graffiti at Rear	CARRY OUT A SERVICE AS PER CHECK LIST	844522
8231	#####	652357 Vandalism - NSR graffiti	REF TO DEFECT # 635430	844522
8231	#####	651243	REF TO DEFECT # 635430	843955
8231	#####	651243 KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed	843955
8231	#####	651243 KIT HALDEX COIL KIT MERCEDES 0500LE (A9G0027)		843955
8231	#####	651243 KIT HALDEX CONDENSER KIT TOP (CYCLONE)		843955
8231	#####	651243	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed	843955
8231	#####	651243	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed	843955
8231	#####	651243 FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		843955
8231	#####	651243 KIT CYCLONE CONDENSER VALVE KIT		843955
8231	#####	651243 HALDEX COIL BASE OIL SEPARATOR (A9G0031)		843955
8231	#####	651243 KIT DRAIN VALVE KIT BOTTOM		843955
8231	#####	651243 FITTING STRAIGHT JOINER 6mm (1106000)		843955
8231	#####	650565 Ops Entered - Fault - Fuel - Route: 900 - Monash University	removed fuel line and fuel water seperater head clean and fixed same as bleed air in fuel system road test bus ok.	842939
8231	#####	650565 Body (None)NEAR SIDE MIRROR LOOSE	fixed ns side mirror	842939
8231	3/1/2017	648690	Assisting	840845
8231	3/1/2017	648690	Tensioned pos 3 and 4 tyres	840845
8231	#####	648447	Assisting	840845
8231	#####	648447	Tensioned pos 3 and 4 tyres	840845
8231	#####	647961 Consumables		840917
8231	#####	647961 TYRE 11R22.5N NEW		840845
8231	#####	606157 CARRY OUT ROLLAWAY SYSTEM	Roqv: 194471 (Refer Kerrie's email 7/3)	832173
8231	#####	647935	VEHICLE SAFETY INSPECTION Safety Inspection Completed	840845
8231	#####	647935	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	840845
8231	#####	647935	VEHICLE SAFETY INSPECTION Safety Inspection Completed	840845
8231	#####	647961 Mechanic entered - Wheels and Tyres Worn N/S/R tyres worn	Replaced tyres position 3 and 4 with Ryan and tensioned all wheel nuts	840845
8231	#####	647961 Mechanic entered - Wheels and Tyres Worn N/S/R tyres worn	Replaced tyres position 3 and 4 with Alex and tensioned all wheel nuts	840845
8231	#####	647982 Consumables		840917
8231	#####	647982 ARM INDICATOR ARM MERCEDES 0500LE (50V4710)		840845





8231	7/7/2016	601575	Fix rear pasenger seat fraim	fitted 11 rivet	800580
8231	7/6/2016	601575	Gearbox Driveline Tailshaft uni - (gearbox end ) worn.	replaced	800500
8231	7/6/2016	601575	PROPSHAFT ASSY	Creditor #:GB-GID001 GJ DRIVELINE P/O #:G171762 Receiving #:178051 Date :2016-07-07	800580
8231	7/5/2016	601575	COOLANT PIPE		800500
8231	7/5/2016	601575	Fluid Leaks Coolant leak on Transmission hose( On top of c	replaced the transmission coolant top brass pipe	800500
8231	7/4/2016	601575	Gearbox Driveline Tailshaft uni - (gearbox end ) worn.	removed the shaft sent away	800500
8231	7/4/2016	601575	HOSE ENG TO G/BOX COOLER MERC 0500LE 50M0562		800500
8231	7/4/2016	601575	Fluid Leaks Coolant leak on Transmission hose( On top of co	replaced the hose	800500
8231	7/4/2016	601575	Engine Radiator support rubber split.	replaced	800500
8231	7/4/2016	601575	MERC RADIATOR MOUNT BUSHING 50N0105		800500
8231	#####	600788			800500
8231	#####	600788		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	800500
8231	#####	600788		VEHICLE SAFETY INSPECTION	800500
8231	#####	600829	GLOBE 24V 21W SINGLE CONTACT (HLR2421)		800500
8231	#####	600829	Mechanic entered - Elec and Light Exterior Lights Reverse li	Remove and replace globe	800500
8231	#####	600829	Consumables		800580
8231	#####	600843	Body Loose door hinge	Tightened hinge.	800500
8231	#####	600655	KIT AIR LINE FITTING VOSS 22MM (5020114)		800500
8231	#####	600655	VALVE MANUAL DRAIN VALVE		800500
8231	#####	600655	Air System Air_Leak Rear	fixed air leak from suspension air tank road test bus ok.need to check suspension hight.	800500
8231	#####	599526	Engine (None): Flat Batt	fitetee batteries to bus.	799477
8231	#####	599526	Consumables		799485
8231	#####	599526	NUT BATTERY TERMINAL BRASS NEGATIVE (BRASS)		799477
8231	#####	599526	LAMP INTERIOR AND REVERSING		799477
8231	#####	599526	Elec and Light Flat Batteries	fitted new battery too bus. all working ok.	799477
8231	#####	599526	Elec and Light - NSR reverse light broken		799477
8231	#####	599526	Elec and Light - OSR reverse light loose		799477
8231	#####	599526	Ops Entered - Fault - Comm Equip - Route: 900 - Wellington		799477
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables		799485
8231	#####	599504	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	799477
8231	#####	599504	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	799477
8231	#####	598798	Consumables		799242
8231	#####	598798	Mechanic entered - Elec and Light Flat Batteries	jump started.	798628
8231	#####	597427	Please remove any old poster and fit new A3 poster and add	done by fleet support	798096
8231	6/5/2016	595980		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	797157
8231	6/6/2016	595980	HALDEX COIL BASE OIL SEPERATOR (49G0031)		797157
8231	6/6/2016	595980	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		797157
8231	6/6/2016	595980	HALDEX CONDENSER KIT TOP(CYCLONE)		797157
8231	6/6/2016	595980	CYCLONE CONDENSER VALVE KIT		797157
8231	6/6/2016	595980		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	797157
8231	6/3/2016	595669	Hetar hose leaking	Removed heater hose and cut to suit.Top up coolantroad tested and re-checked coolant level - ok.	796432
8231	#####	594622	Consumables		795624
8231	#####	594622	Elec and Light - Bus wont start	Jump started	795410
8231	#####	593402	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND MAP POCKET INSTA	Already location there for wallet	793885
8231	#####	593040	Consumables		793885
8231	#####	593040	Mechanic entered - Elec and Light Flat Batteries	jump started.	793353
8231	#####	591799	Mechanic entered - Fluid Leaks Other	added coolant - low.	791857
8231	#####	590858		re-tensioned nuts on wheels 5 and 6.	791000
8231	5/9/2016	590233	Consumables		791000
8231	5/9/2016	590233	TYRE NEW 11R22.5N		790297
8231	5/9/2016	590233	HOSE ENG TO G/BOX COOLER MERC	Creditor #:GB-WH004 WHITEHORSE TRUCKS PTY LTD P/O #:G167556 Receiving #:173347 Date :2016-05-09	790673
8231	5/6/2016	590210		Safety inspection completed	790297
8231	5/6/2016	590210		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	790297
8231	5/6/2016	590210		VEHICLE SAFETY INSPECTION	790297
8231	5/6/2016	590233	Wheels and Tyres - Tyre pos 56 low	replaced	790297
8231	5/6/2016	590233	Mechanic entered - Wheels and Tyres Worn	Changed tyres position 5 and 6	790297
8231	5/6/2016	590233	Fluid Leaks - Coolant rubber hose on top of the g/box leaki	Replaced coolant hose	790297
8231	5/6/2016	590233	Fluid Leaks - Oil leaking inside the gate?	checked OK	790297
8231	5/6/2016	590263	As per Campaign 2/16 Review and Reset Camera Angles and ensu	re set camera angle audio only on front camera.	790297
8231	#####	589201	Mechanic entered - Elec and Light Flat Batteries	jump started.	788463
8231	#####	589201	Consumables		789351
8231	#####	589145	CCTV Timestamp Incorrect by +1hr	adjusted the time	788463
8231	#####	587275	Elec and Light - Bus wont start	Jump started	786653
8231	#####	587275	Consumables		786653
8231	#####	585579	NITROGEN DRY D SIZE		785916
8231	#####	585579	AIR CON REFRIDGERANT		785916
8231	#####	587060	Elec and Light - Bus wont start	Jump started	785916
8231	#####	587060	Consumables		786653
8231	#####	586659		re-tensioned nuts on wheels 3 and 4.	785916
8231	#####	586704	Mechanic entered -Steering Other	added power steering fluid - low.	785916
8231	#####	586329	Engine (None): won't start...w/shop attended and started v	flat batteries - jump started.	785884
8231	#####	586257			785884
8231	#####	586257		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Transmission Service Completed	785884
8231	#####	586257			785884
8231	#####	586257		removed wheels 3 and 4. removed leaking valve ext. inflated both to specs. wheels not re-fitted. damaged studs to be replaced.	785884
8231	#####	586256	WHEEL NUT MERCEDES BENZ 0500		785884
8231	#####	586256	Tyre pos 4 need replace	Fit tyres 3 and 4	785884
8231	#####	586256	WHEEL STUD FRONT/REAR MERCEDES BENZ 0500		785884
8231	#####	586256	Consumables		785884
8231	#####	585579	BROWN TIP SOLDER STICK		785884
8231	#####	585579	BLUE TIP SOLDER STICK	Creditor #:GB-ACT002 ACTROL PARTS P/O #:G165806 Receiving #:171486 Date :2016-04-12 8231	785884
8231	#####	584598	A/C Heating Not Cooling	Creditor #:GB-ACT002 ACTROL PARTS P/O #:G165806 Receiving #:171486 Date :2016-04-12 8231	785884
8231	#####	585579	A/C Heating Not Cooling	Remove and replaced section off discharge pipe rerun pipe so the vibrasorber lays away from the bus frame pressure test vac and charge with R407C there is no documented charge for the tk modification so 7 kg refrigerant was put into unit will run for awhile and check in warmer weather	784560
8231	#####	585579	A/C Heating Not Cooling	ref to w/o # 584598	784560
8231	#####	585559	Mechanic entered - Elec and Light Exterior Lights	re-secure (nsr) bottom indicator with clips - fallen off.	784560
8231	#####	585520	Mechanic entered - Elec and Light Flat Batteries	jump started.	784560
8231	#####	585559	Consumables		785884
8231	#####	585520	Consumables		785884
8231	4/7/2016	585147	PWR STRG FILTER		784552
8231	4/7/2016	585147		CARRY OUT C SERVICE AS PER CHECK LIST	784552
8231	4/7/2016	585147			784552
8231	4/7/2016	585147	FUEL FILTER MERC 0500LE		784552



8231	#####	567857	Mechanic entered - Body Drivers Seat Leaning	removed driver's seat and put in store. fitted another seat. checked operation - o.k. tightened loose seat belt buckle.	767397
8231	#####	567237	UNIVERSAL JOINT 0405	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G160031 Receiving #:165797 Date :2015-12-29	767070
8231	#####	567237	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -	Replaced tail shaft cross joint.	759265
8231	#####	567237	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -	Fitted new uni -joints and road tested - ok	759265
8231	#####	566794	Body Drivers Seat Controls	Assembled parts	766862
8231	#####	566833	Consumables		765862
8231	#####	566833	Elec and Light - BUS WONT START	JUMP STARTED	766512
8231	#####	566794	KIT PIVOT & BUSH ISRI	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G159945 Receiving #:165743 Date :2015-12-24	766862
8231	#####	566794	OUTER LEVER ISRI SEAT A6008	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #:G159945 Receiving #:165743 Date :2015-12-24	766862
8231	#####	566794	Body Drivers Seat Controls	Checked and ordered parts	766512
8231	#####	565148	HOSE INTAKE PIPE 0500LE	Creditor #:GB-WH004 WHITEHORSE TRUCKS PTY LTD P/O #:G159598 Receiving #:165204 Date :2015-12-16	765925
8231	#####	565148	Engine Low Powerboost leaks	Replace rubber hose	765773
8231	#####	565202	CCTV (None) Hard Drive recording only 1 frame for every	checked cctv found ips set to 0.1 changed it to 10 and checked playback and ok.	765773
8231	#####	565202	CCTV (None) Hard Drive recording only 1 frame for every 1	assisted elias with changing frame rate in settings	765773
8231	#####	565148	Engine Low Powerboost leaks	Road tested and found engine got boost leak.Removed lower intercoolerhose and repaired temporarily.Ordered part.	765773
8231	#####	563457	Mechanic entered - Air System Air_Leak Front rear door	crack hose	763981
8231	#####	561711	Consumables		762852
8231	#####	561711	Ops Entered - Fault - Wheels and Tyres Vibration - Route:	Front tyres new - road tested no fault found	762195
8231	#####	561687	Consumables		762195
8231	#####	561687	Consumables		762195
8231	#####	561687	Consumables		762195
8231	#####	561687	Consumables		762195
8231	#####	561687	Consumables		762195
8231	#####	561540		CARRY OUT A SERVICE AS PER CHECK LIST	762195
8231	#####	561540		CLEAN A/C FILTERS done by nick	762195
8231	#####	561540		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with nick	762195
8231	#####	561540		VEHICLE SAFETY INSPECTION Completed with nick nick done top	762195
8231	#####	561540			762195
8231	#####	561540		ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	762195
8231	#####	561540		ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	762195
8231	#####	561540			762195
8231	#####	561401	DECAL MAKE YOUR MARK		762195
8231	#####	561401	Campaign 20/15 Audit & Update of Safety Decals.Requires a		762195
8231	#####	560160	Remove Old Poster and Fit new All Night Public Transport Po		762195
8231	#####	557509	BODY SHOP SUPPLIES	completed	761739
8231	#####	557509	PAINT SUPPLIES		761421
8231	#####	558900	Consumables		761098
8231	#####	558897	Consumables		761098
8231	#####	558895	Consumables		761098
8231	#####	558900	Mechanic entered - Elec and Light Other	jump started - battery flat.	760751
8231	#####	558897	Ops Entered - Fault - Desto Signs - Route: 900 - Oakleigh S	check ok.	760751
8231	#####	558895	Ops Entered - Fault - Desto Signs - Route: 900 - Stud Park	remove desto control unit and change with other bus desto ok.	760751
8231	#####	558858	Air System Air leak on retarder conection	Repaired	760751
8231	#####	557253	CARRY OUT ANNUAL INSPECTION	Creditor #:GB-ROAD01 Road Safety Inspections P/O #:G157796 Receiving #:163756 Date :2015-11-16	760751
8231	#####	557663		CARRY OUT A/C - A SERVICE AS PER CHECK LIST	759265
8231	#####	557509	Vandalism/ Graffiti Interior / Fleet Support has	ANNUAL SAFETY INSPECTION (RWC # H 1389130 Completed 04/11/15)	759265
8231	#####	557253	Service	prepared bus for RSI	758597
8231	#####	556607	Service	fixed drivers seat stitched a rip back together. replaced high beam light surrounding because old one was rusting	758597
8231	#####	556236	Retension tyres 34	re tensioned wheels 3 and 4	758597
8231	#####	555986	KIT AIR LINE FITTING VOSS 22MM 5020114		758597
8231	#####	555986	WIPER REFILL SUIT TX800+TX900		758597
8231	#####	555986	CLAMP SUIT TYRE VALE EXTENSION T18 & T19		758597
8231	#####	555986	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		758597
8231	#####	555986	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		758597
8231	#####	555986	Gearbox Driveline Trans pipe leaking coolant	Check for coolant leaks replace hose clamp fitted two new clamp and steam clean trans. area and roadtested do long roadtest and re check for coolant leaks found still leaking. check for fault found pipe have small split causing for coolant leaking above trans. hose. remove hose clamp adjust hose to cover the split cut n	758597
8231	#####	555986	HOSE ENG TO G/BOX COOLER MERIC 0500LE 50N0562		758597
8231	#####	555986	RAD CAP MERIC BENZ SIGHT GLASS SIDE 50N0701 A0005014615		758597
8231	#####	555986	Body Rear bumper bar missing screws	Replace missing screws and remove and fitted washer for screw and tightened all screws for bumper and some panel.	758597
8231	#####	556201	Ops Entered - Fault - Body Windows Front - Route: 900 - Wel	repaired the blind job completed	758597
8231	#####	555986	Air System Air_Leak Rear at air dryer hose	Remove and replace a ring air line hose for air tank air dryer hose and air protection valve air line hose seal. re check for air leaks all fine.	758597
8231	#####	555986	KIT AIR LINE FITTING VOSS 22MM 5020114		758597
8231	#####	555986	KIT AIR LINE FITTING VOSS 22MM 5020114		758597
8231	#####	556164		CARRY OUT FIRE SAFETY INSPECTION AS PERCHECK LIST- completed	758597
8231	#####	555956		PRE ANNUAL SAFETY INSPECTION CHECK complete	758597
8231	#####	555986	Wipers and Washers Wipers Not_Cleaning Screen	Remove and replace wiper blade.	758597
8231	#####	555986	TYRE NEW 11R22.5N		758597
8231	#####	555986	Wheels and Tyres Worn pos & 4 tyres	Remove tyre replace with two(2) new skinless tyre. put one tyre to rack half worn. tensioned all wheel nuts.	758597
8231	#####	555986	Suspension N/S/R air bag leaking	Remove and replace air bag.	758597
8231	#####	555986	Gearbox Driveline Trans pipe leaking coolant	Change coolant trans. hose found leaking. clean under bus and engine andtop and inside floor. roadtested found still coolant leaking around trans pipeoil cooler. c/o	758597
8231	#####	555986	Engine Radiator cap leaking coolant	Remove and replace fitted new radiator cap.	758597
8231	#####	555986	Body Secure rear modesty panel	Secured	758597
8231	#####	554422	BODY SHOP SUPPLIES		757038
8231	#####	554422	PAINT SUPPLIES		757038
8231	#####	554422	UNREPORTED- N/S/F roof	repaired ns top header and painted refuelled and parked	757038
8231	#####	553014	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 5020115		754911
8231	#####	553014	Drv entered - Air System Air_Leak Rear	fixed air leak bus ok.	754911
8231	#####	551769	Consumables		754183
8231	#####	551769	Elec and Light (None) desto not working	change control unit clean desto unit conector desto ok.	754183
8231	#####	551099	Body (None) Desto not working	removed desto computer unplugged and re plugged and now ok checked a few destinations and ok.	753776
8231	#####	550428		re-tensioned nuts on wheels 1 and 2.	753013
8231	#####	550360	TYRE NEW 11R22.5N		753013
8231	#####	550360	Wheels and Tyres - Tyre 1 needs replacing	replaced tyres 1 and 2 tensioned bus	753013
8231	#####	550248	Consumables		753013
8231	#####	550248	INSERT LAMP QH 72046		753013
8231	#####	550248	Elec and Light - Exit light at front door n/w	cut cable ties and checked power at the plug power at plug so fitted new light put everything back together and ok.	753013
8231	#####	549652	BRAKE+ CLUTCH PEDAL PAD 0500LE		752543
8231	#####	549460			752356
8231	#####	549460		CLEAN A/C FILTERS	752356
8231	#####	549460		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	752356
8231	#####	549460		VEHICLE SAFETY INSPECTION	752356
8231	#####	549651	Replace A3 poster with Victorian Seniors Festival Poster	replaced	752543
8231	#####	549442	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	completed	752356
8231	#####	549652	Brakes - Replace brake pedal rubber	Replaced	752543
8231	#####	549260	Ops Entered - Fault - Air System Air_Leak Rear - Route: 90	Repaired air leak on air tank valve	752356
8231	#####	548700	VALVE 4 WAY CIRCUIT PROTECTION VALVE		752038
8231	#####	548700	Mechanic entered - Brakes Other 6 way valve leak	replaced.	751923





8231	#####	508093	CLAMP SUIT TYRE VALE EXTENSION T18 & T19		707612
8231	#####	508093	EXTENSION FLEXIBLE TYRE VALVE 210mm LONG		707612
8231	#####	508092	DRAIN VALVE KIT BOTTOM		707612
8231	#####	508092	HALDEX COIL KIT 0500LE 49G0027HALDEX		707612
8231	#####	508092	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		707612
8231	#####	508092	HALDEX CONDENSER KIT TOPI(CYCLONE)		707612
8231	#####	508093	Whls & Tyres Worn pos 5 & 6	Remove and replace tyre position 5 and 6 and torque wheel nuts and replace clamp and tyre valve extension	707221
8231	#####	508092	Air System Leaking from air dryer	Remove and replace o-ring kit air line of air dryer air protection valve	707221
8231	#####	508079		Re-kit Air Cyclone Separator Complete replace repair kit and refit cyclone separator	707221
8231	#####	508079		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes Complete replace repair kit	707221
8231	#####	508079	HALDEX COIL KIT 0500LE 49G0027HALDEX	Coil Kit	707221
8231	#####	508079	HALDEX COIL BASE OIL SEPERATOR	Base	707221
8231	#####	508079	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	707221
8231	#####	508079	DRAIN VALVE KIT BOTTOM	Valve Kit	707221
8231	#####	508071	Consumables		707612
8231	#####	508071	Consumables		707612
8231	#####	508071	Consumables		707612
8231	#####	508071	Consumables		707612
8231	#####	508071	Consumables	A Service complete	707221
8231	#####	508071	Consumables		707221
8231	#####	508071	Consumables	A Service complete	707221
8231	#####	508071	Consumables	Clean A/C filter	707221
8231	#####	508071	Consumables	Grease AC Compressor Clutch Bearing	707221
8231	#####	508071	Consumables	Tension Wheel Nuts To OEM Specification Alex and Pascal	707221
8231	#####	507640	Mechanic entered - Eng Cool Coolant Low	added coolant.	706834
8231	#####	506815		re-tensioned nuts on wheels 3 and 4.	705684
8231	#####	506817	Mechanic entered - Steering Other	added power steering fluid - low.	705684
8231	#####	506688	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		705684
8231	#####	506688	Mechanic entered - Whls & Tyres Puncture	changed tyres 3 (to rack) and 4 (flat). nuts tensioned with ryan.	705684
8231	#####	506688	TYRE NEW 11R22.5N		705684
8231	1/9/2015	505982	Ops Entered - Fault - Security CCTV System Faulty - Route:	reset time and datecheck and all ok.	704684
8231	1/5/2015	504977		Perform & Complete PTSV Bus Safety Inspection Completed	704040
8231	1/5/2015	504977		Tension Wheel Nuts	704040
8231	1/5/2015	504977		Perform & Complete PTSV Bus Safety Inspection Completed	704040
8231	1/5/2015	505040	Consumables		704050
8231	1/5/2015	505040	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	complete	704040
8231	#####	499977	Consumables		0
8231	#####	499977	12V 20DAMP 1100CCA (+ on left	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G146542 Receiving #:149055 Date :2014-12-31 Stock	703094
8231	#####	504099	Passenger Doors - losing air pressure from door cylinders		702451
8231	#####	504099	Air Leak Above Door	can not fine any air leak above door	702451
8231	#####	502648	Ops Entered - Breakdown - Breakdown Mech Defect Affects Serv	bus breakdown on stud rd near David rd abs light on fixed temperaly and drive to depot adjust wheel chair ramp sensor road test bus ok.	700054
8231	#####	501151	A3 Poster Change	Fitted	698808
8231	#####	499871	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G146192 Receiving #:148396 Date :2014-12-10	698808
8231	#####	499977	Elec & Light - Load test and check charge rate	put battery's back together pti checked ok.	697309
8231	#####	499871	Annual Licence	- RVC 254751 - PASSED 03/12/14	697309
8231	#####	499977	Elec & Light - Load test and check charge rate	load tested removed batteries need modification left with body shop	697309
8231	#####	499369	Consumables		0
8231	#####	493969	Elec & Light Battery Flat	jump started.	696336
8231	#####	498533			695139
8231	#####	498533		Perform & Complete PTSV Bus Safety Inspection Safety Inspection completed	695139
8231	#####	498122	Body & Acc - Needs front drivers blind	Tension Wheel Nuts	695139
8231	#####	498122	Body & Acc - Needs front drivers blind	Fixed	695139
8231	#####	498122	Body & Acc - Needs front drivers blind	Fixed With Alex	695139
8231	#####	498122	Consumables		0
8231	#####	498563	SEALS 4 WAY PROTECTION VALVE BARREL (MB 0500LE)		695139
8231	#####	498563	Air System - Repair air leak at 6way valve	Fitted new cup seals	695139
8231	#####	498122	WIPER REFILL SUIT TX800*TX900		695139
8231	#####	498122	SHOCK ABSORBER REAR		695139
8231	#####	498122	Mechanic entered - Elec & Light Battery Flat	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G145882 Receiving #:147771 Date :2014-11-24	695702
8231	#####	498122	Consumables	jump started.	695139
8231	#####	498122	Wipers & Washers - Wiper blades worn	Replace wiper blades	695139
8231	#####	498122	Suspension - NSR shocker leaking oil	Replace shocker	695139
8231	#####	498122	Air Cond - A/c not working	Checked ok	695139
8231	#####	498122	Engine - Steamclean bus	Cleaned bus	695139
8231	#####	498122	Body & Acc - Step strips in rear of bus missing	Replace four step strips	695139
8231	#####	498122	Body & Acc - Engine door hinge pin loose	Secure pin	695139
8231	#####	498122	Air System - Secure air vent hose that goes to alternator	Secure air vent hose	695139
8231	#####	498122	Air System - Air leak near transmission oil filler	Repair air leak	695139
8231	#####	497340	VOSS ADAPTOR 232 - 230 M22 X 1.5		694758
8231	#####	497340		Electrical - Batteries - Check fluid level ( leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	694684
8231	#####	497340		Overhaul air separator	694684
8231	#####	497340	Service	Inspection	694684
8231	#####	497340		Replace air dryer canister clean silence and drain reservoir	694684
8231	#####	497340		Replace angle drive oil	694684
8231	#####	497340		Test coolant level - top up if required to equate to 37C frost protection	694684
8231	#####	497340		Replace power steering filter and check level (Replace oil if required)	694684
8231	#####	497340		Inspect radiator and charge air cooler for dirt - clean	694684
8231	#####	497340		Check oil level in transmission - top up if required	694684
8231	#####	497340		Check and clean cartridge in dry tyre air cleaner	694684
8231	#####	497340		Replace pre and main fuel filters	694684
8231	#####	497340	FUEL FILTER 0500LE		694684
8231	#####	497340	AIR DRYER CANISTER VOLVO+ NL202		694684
8231	#####	497340	POWER STEERING FILTER VOLVO		694684
8231	#####	497340	FUEL FILTER MERC 0500LE		694684
8231	#####	496371	Mechanic entered - Brakes Other	replaced worn brake pedal rubber pad.	693120
8231	#####	496371	CLUTCH PEDAL RUBBER 16-240		693120
8231	#####	495109	MUFFLER MOUNT 0500LE S0T0010		692269
8231	#####	495110	AIR LINE FITTING KIT 0500LE AIR DRYER SMALL		692269
8231	#####	494986	Front doors not operating	replaced silinoid on front door	692190
8231	#####	494986	DOOR SOLENOID VALVE (with voltage surpressor)		692190
8231	#####	495109	Exhaust Broken Mount	R/R silencer mount	692190
8231	#####	495110	Air System Losing Air at air fitting	Repaired air leaks near air dryer.	692190
8231	#####	495066	Service		692190
8231	#####	495066	Service		692190
8231	#####	495066	SYNTHETIC GEAR LUBRICANT FM 75W-140 (LUZ7 )	Replace Differential oil	692190
8231	#####	495068		Grease AC Compressor Clutch Bearing	692190



8231	#####	489747	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	686811
8231	#####	489747	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	686811
8231	#####	489747	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	686811
8231	#####	489747	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	686811
8231	#####	489747	INSPECT MATOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condenser fan grills	686811
8231	#####	489747	CONDENSOR AREA: Clean condenser coils; check bolts/clamps for tension	686811
8231	#####	489747	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	686811
8231	#####	489129	Mechanic entered - Eng Cool Coolant Low	685570
8231	#####	489232		685570
8231	#####	489232	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	685570
8231	#####	489232	FILTER TRANSMISSION ZF 4139-298-038E39HD119	685570
8231	#####	489232		685570
8231	#####	489238	Mechanic entered - Elec & Light Battery Flat	684574
8231	#####	487722	WEDGE GLOBE INSTRUMENT 24V 5W	684044
8231	#####	487722	GLOBE 24V 21W SINGLE CONTACT	684044
8231	#####	487722	CLEAR FRONT INDICATOR WRAP-AROUND	684044
8231	#####	487722	Mechanic entered - Suspension High	684044
8231	#####	487722	BALJOINT LEVELING VALVE MB 03	684044
8231	#####	487722	LEVELING VALVE SENSOR	684044
8231	#####	487722	Mechanic entered - Suspension High	684044
8231	#####	487722	Mechanic entered - Elec & Light Stop lights	684044
8231	#####	487836	Ops Entered - Fault - Body & Acc Water Leak - Route: 900 -	681044
8231	#####	487836	Ops Entered - Fault - Body & Acc Water Leak - Route: 900 -	684044
8231	#####	486048	Mechanic entered - Elec & Light Battery Flat	681961
8231	#####	486099	Bus overheating	659781
8231	#####	486099	ATTEND BREAKDOWN	683409
8231	#####	485869	Suspension - Rear NS front airbag leaking	681961
8231	#####	485516	Ops Entered - Fault - Air System Leaking - Route: 900 - Hun	680965
8231	#####	485516	ELBOW 6MM	680965
8231	9/9/2014	484269	DECAL AUTHORISED OFFICER	680134
8231	9/5/2014	484269	Remove old decal and fit new Authorised Officers Decal DO N	679820
8231	9/1/2014	483087	Mechanic entered - Elec & Light Battery Flat	678203
8231	9/1/2014	482951	AIR FILTER MERC 0500LE E491L	678203
8231	#####	482953		678203
8231	#####	482953	Tension Wheel Nuts done with rene	678203
8231	#####	482953	Perform & Complete PTSV Bus Safety Inspection completed	678203
8231	#####	482953	Tension Wheel Nuts done with rene	678203
8231	#####	482953	Perform & Complete PTSV Bus Safety Inspection completed	678203
8231	#####	482951	A Service Complete	678203
8231	#####	482951	Clean A/C filter Done	678203
8231	#####	482951	Grease AC Compressor Clutch Bearing done by nick	678203
8231	#####	482951	Tension Wheel Nuts To OEM Specification Done with Nick	678203
8231	#####	482951	A Service Complete	678203
8231	#####	482951	Clean A/C filter Done	678203
8231	#####	482951	Grease AC Compressor Clutch Bearing done by nick	678203
8231	#####	482951	Tension Wheel Nuts To OEM Specification Done with Nick	678203
8231	#####	481817	Mechanic entered - Elec & Light Battery Flat	676930
8231	#####	480431	Elec & Light - Bus wont start	675538
8231	#####	480009	Brakes Holding On	675455
8231	#####	480009	AIR LINE FITTING KIT 0500LE AIR DRYER SMALL	675455
8231	#####	480009	Brakes Holding On	675455
8231	#####	479220	CONTACT BLOCK DOOR PUSH SWITCH	674741
8231	#####	479220	Ops Entered - Fault - Passenger Doors Not Operating - Route	674741
8231	#####	479220	DOOR VALVE SILENCER	674741
8231	#####	479150	Elec & Light Flat batteries	674741
8231	8/2/2014	477883	Mechanic entered - Elec & Light Battery Flat	673138
8231	#####	477407	Mechanic entered - Elec & Light Battery Flat	673138
8231	#####	477407	Mechanic entered - Elec & Light Battery Flat	673138
8231	#####	476992		672593
8231	#####	476992	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes	672593
8231	#####	476992	HALDEX CONDENSER KIT TOP(CYCLONE)	672593
8231	#####	476992	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	672593
8231	#####	476992	HALDEX COIL KIT 0500LE	672593
8231	#####	476992	DRAIN VALVE KIT BOTTOM	672593
8231	#####	476992	HALDEX COIL BASE OILSEPERATOR	672593
8231	#####	476992	CYCLONE CONDENSER VALVE KIT	672593
8231	#####	476427	Mechanic entered - Elec & Light Battery Flat	671490
8231	#####	475979	Mechanic entered - Elec & Light Battery Flat	671490
8231	#####	475562	GLOBE 24V 21W SINGLE CONTACT	671490
8231	#####	475562	Mechanic entered - Elec & Light Indicators	671334
8231	#####	473465	Brakes/replace foot valve	669152
8231	#####	474574	Ops Entered - Fault - Engine Lacking Power - Route: 900 -	669780
8231	#####	474647	Engine power loss Princess Hwy Carnegie	6692017
8231	#####	474176	Elec & Light - Bus wont start	669747
8231	#####	473504	Fit Tyre Valve Extensions To All Inner Rear Axle Wheels	669152
8231	#####	473504	Clamp Suit Tyre Valve	669152
8231	#####	473504	TYRE VALVE EXTENSION 180mm LONG	669152
8231	7/9/2014	473465	FOOT BRAKE VALVE	669342
8231	7/8/2014	473002	Ops Entered - Fault - Eng Cool Coolant Low - Route: 900 - C	669152
8231	7/8/2014	473110	Mechanic entered - Eng Cool Coolant Low	669152
8231	7/7/2014	472818	Mechanic entered - No Defect Recorded	669152
8231	7/7/2014	472814	Ops Entered - Fault - Eng Cool Leaking - Route: 900 - Stud	669152
8231	7/7/2014	472815	Mechanic entered - Eng Cool Leaking	669152
8231	7/6/2014	472795	Elec & Light - Bus wont start	669152
8231	7/4/2014	472409	32MM LOOSE WHEEL NUT INDICATOR	668623
8231	7/3/2014	472338		668623
8231	7/3/2014	472338		668623
8231	7/3/2014	472409	Fit Wheel Nut Pointers to all wheel nuts on the front axle	668623
8231	7/3/2014	472410	Body & Acc - Defective blind	668623
8231	#####	469486	Suspension Rear suspension leaning to N/S.	664634
8231	#####	468998	Elec & Light Battery Flat	664364
8231	#####	468455	LED FRONT POSITION MARKER LIGHT	663918
8231	#####	468455	GLOBE S/CONTACT 24V-10W	663918
8231	#####	468455	Elec & Light Exit light and bus stop lights n/w.	663802
8231	#####	468403		663802
8231	#####	468403	R/R globes	663802
8231	#####	468403	Grease AC Compressor Clutch Bearing	663802
8231	#####	468403	Tension Wheel Nuts To OEM Specification	663802







8231	#####	424550	O405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		613296
8231	#####	424485	NARVA 24V REVERSING BUZZER		613296
8231	#####	424485	Mechanic entered - Elec & Light Reverse Lights reverse buzze	replaced reverse buzzer	613296
8231	9/7/2013	423468	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	Completed	612281
8231	9/6/2013	423940	Organise Mbenz Recall SM949 to be performed by Whitehorse T	completed	613172
8231	8/2/2013	418314		Perform & Complete PTSV Bus Safety Inspection	604655
8231	8/2/2013	418314		Tension Wheel Nuts	604655
8231	8/2/2013	418314		Perform & Complete PTSV Bus Safety Inspection	604655
8231	8/2/2013	418313	ENGINE OIL BREATHER KIT 0500LE		604655
8231	8/2/2013	418313		Replace Engine Oil Breather Kit	604655
8231	8/2/2013	418313		Grease AC Compressor Clutch Bearing	604655
8231	8/2/2013	418313	AIR FILTER MERC 0500LE		604655
8231	8/2/2013	418313	OIL FILTER 1725+0500LE		604655
8231	8/2/2013	418313	ENGINE OIL DELO 400LE 15W40		604655
8231	8/2/2013	418313		Tension Wheel Nuts to Spec	604655
8231	8/2/2013	418313		A Service & Bus Safety Inspection	604655
8231	8/2/2013	418313		D-Service & Bus Safety Inspection	604655
8231	8/2/2013	418313		A Service	604655
8231	8/2/2013	418313		Clean A/C filter	604655
8231	8/2/2013	418313		Grease AC Compressor Clutch Bearing	604655
8231	8/2/2013	418313		Tension Wheel Nuts To OEM Specification	604655
8231	#####	415819	WEDGE GLOBE INSTRUMENT 24V 5W		602039
8231	#####	416819	Elec & Light - Replace NSF bottom park light	Replaced	602039
8231	#####	416213	SENSITIVE EDGE DOOR SWITCH		601130
8231	#####	415845	HALDEX CONDENSER KIT TOP(CYCLONE)		601130
8231	#####	416213	Passenger Doors - Adjust front/rear sensor	Changed front door sensitive edge switch and adjusted front/rear sens edge	601092
8231	#####	416213		Swapped with bus 8909 and bought back to depot	601092
8231	#####	416213	Passenger Doors - Adjust front door sensor	Adjusted	601092
8231	#####	416205	Heat & Demist Heater not working	Checked OK	601130
8231	#####	415845		Re-kit Air Cyclone Separator	600871
8231	#####	415845	HALDEX COIL KIT 0500LE	Coil Kit	600871
8231	#####	415845	DRAIN VALVE KIT BOTTOM	Valve Kit	600871
8231	#####	415845	HALDEX COIL BASE OIL SEPERATOR	Base	600871
8231	#####	415845	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	600871
8231	#####	415845		Re-kit Air Cyclone Separator	600871
8231	#####	415844		A Service	600871
8231	#####	415844	AIR FILTER MERC 0500LE		600871
8231	#####	415844		A Service	600871
8231	#####	415844		Clean A/C filter	600871
8231	#####	415844		Grease AC Compressor Clutch Bearing	600871
8231	#####	415844		Tension Wheel Nuts To OEM Specification	600871
8231	#####	415456	A/C BELT 0500 BENZ		599135
8231	#####	415456	AMBER REFLECTOR		599135
8231	#####	415455	Ops Entered - Fault - Air Cond Air Conditioner - blowing c		599135
8231	#####	415456	Replace missing NS mid amber reflector	Replaced	599135
8231	#####	415455	Elec & Light - Replace missing NS mid amber reflector		599135
8231	#####	415455	Ops Entered - Fault - Air Cond Air Conditioner - blowing c		599135
8231	7/5/2013	413627	Body & Acc - Lnt mirror glass broken	Replaced by Tulla 28/06/13	586194
8231	7/3/2013	413065		Perform & Complete PTSV Bus Safety Inspection	595338
8231	7/3/2013	413065		Tension Wheel Nuts	595338
8231	7/3/2013	413065		Perform & Complete PTSV Bus Safety Inspection	595338
8231	7/3/2013	413548	Passenger Doors Require Adjusted	Checked OK	595608
8231	#####	410718	Elec & Light - Bus wont start	Jump started	590485
8231	6/7/2013	408786	BLADE WIPER 1MTR		587465
8231	6/7/2013	408786	Mechanic entered - Wipers & Washers Wipers Not Working	fit new linkage and adjust them	587465
8231	6/6/2013	408786	Mechanic entered - Wipers & Washers Wipers Not Working	began fitting new wiper linkage.	587465
8231	6/5/2013	408786	WIPER LINKAGE	Creditor #:GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G125319 Receiving #:126252 Date :2013-06-05	587465
8231	6/4/2013	408786	Mechanic entered - Wipers & Washers Wipers Not Working	tried to adjust wiper linkages, not working correctly, motor is fine, ordered new linkages.	587465
8231	#####	408234	Wipers & Washers - secure wiper blades	Secured	587018
8231	#####	408079	WEDGE GLOBE INSTRUMENT 24V 5W		586639
8231	#####	408234	Body & Acc - secure exterior mirror	Secured	587018
8231	#####	408079	Elec & Light - Replace globe	Replaced	586639
8231	#####	407407		Perform & Complete PTSV Bus Safety Inspection	585959
8231	#####	407407		Tension Wheel Nuts	585959
8231	#####	407407		Perform & Complete PTSV Bus Safety Inspection	585959
8231	#####	407408		Service T - Replace Transmission Oil & Filter	585959
8231	#####	407408		Bus Safety Inspection	585959
8231	#####	407408	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	585959
8231	#####	407408	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	585959
8231	#####	407408		Service T - Replace Transmission Oil & Filter	585959
8231	#####	405322	LOW TREAD - POS 34 - 11 R22.5	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125576 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	405322	LOW TREAD - POS 34 - 11 R22.5	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125575 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	405322	WRONGLY CHARGE	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125574 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	405322	WRONGLY CHARGE	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125573 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	405322	WRONGLY CHARGE	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125572 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	405322	WRONGLY CHARGE	Creditor #:GB-BA001 BEAU REPAIRS P/O #:K124257 Receiving #:125571 Date :2013-05-24 REPLACE WITH NEW	584972
8231	#####	406890	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		584542
8231	#####	406890	SILENCER AIR VALVE 22MM		584542
8231	#####	406890	VALVE 4 WAY CIRCUIT PROTECTION VALVE		584542
8231	#####	406890	AIR DRYER MERCEDES 0500		584542
8231	#####	406890	OVERFLOW VALVE 0500LE		584542
8231	#####	406890	Eng Cool - S/clean and check coolant leak top of the engine	S/cleaned engine topped up diff oil & greased lh kingpin	584542
8231	#####	406890	Eng Cool - S/clean and check coolant leak top of the engine	Tensioned coolant hose calmp checked OK top cover fitted	584542
8231	#####	406890	Air System Leaking	Air dryer 6way valve suspension overflow valve changed air pipe nut tightened	584542
8231	#####	406650		A Service	584542
8231	#####	406650		A Service	584542
8231	#####	406650		Clean A/C filter	584542
8231	#####	406650		Grease AC Compressor Clutch Bearing	584542
8231	#####	406650		Tension Wheel Nuts To OEM Specification	584542
8231	#####	405994	Breakdown in Glen Waverley st. - suspension down time out 7	bring bus back to depot	582878
8231	#####	405322	Whls & Tyres - Replace tyre pos 34 - low tread	Replaced	582096
8231	#####	405383	Whls & Tyres - Replace tyres 34	Replaced	582096
8231	5/3/2013	404126	Whls & Tyres - Check tyre pressure in pos 3	Checked inflated	579377
8231	5/1/2013	403497	Steering Steering Whlcannot be adjusted	fixed	578454
8231	5/1/2013	403497	Passenger Doors Door Brakes	repaired airline to g/box checked rear door brake and OK	578454

8231	5/1/2013	403506	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	audited	578283
8231	5/1/2013	403497	Sun Visor clip Broken also no music radio installed in bus	fixed	578454
8231	#####	402745		Perform & Complete PTVS Bus Safety Inspection	576655
8231	#####	402745		Tension Wheel Nuts	576655
8231	#####	402745		Perform & Complete PTVS Bus Safety Inspection	576655
8231	#####	402281	Elec & Light - Bus wont start	Jump started	575826
8231	#####	395898	ROAD SAFETY INSPECTIONS	Creditor #:ROAD01 Road Safety Inspections P/O #:G121246 Receiving #:123770 Date :2013-04-17	574642
8231	#####	401214	FLOOR HATCH SCREWS		574201
8231	#####	401214	Body & Acc - Replace floor hatch screw assembly	Replaced	574201
8231	#####	399744	BALL JOINT ROD LEVELLING	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G122716 Receiving #:123586 Date :2013-04-12	574201
8231	#####	399744	LEVELLING VALVE BALL JOINT	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G122716 Receiving #:123586 Date :2013-04-12	574201
8231	#####	399744	NUT	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G122716 Receiving #:123586 Date :2013-04-12	574201
8231	#####	399744	FREIGHT	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G122716 Receiving #:123586 Date :2013-04-12	574201
8231	#####	395899	ROAD SAFETY INSPECTIONS	Creditor #:ROAD01 Road Safety Inspections P/O #:G121246 Receiving #:123533 Date :2013-04-11	574201
8231	#####	399744	Suspension Bus lining need leveling valve adjustment	Assisted Alan and adjusted leveling valve OK	568647
8231	#####	399744	Suspension Bus lining need leveling valve adjustment	fit new rear level valve rod	568647
8231	#####	400964	Body & Acc - Repair engine hatch door	Welded stud housings for engine hatch door inside & replaced with new hatch bolts fuelled & parked	574201
8231	#####	399744	Brakes - Fault Code B54347 on dash	Fitted new as old ones were leaking	568647
8231	#####	399744	Brakes - Fault Code B54347 on dash	Fitted 2 new rear brake chambers	568647
8231	#####	399744	BRAKE BOOSTER REAR N/S MB0500LE		568647
8231	#####	399744	BRAKE BOOSTER REAR O/S MB0500LE		568647
8231	#####	400733		A Service	568647
8231	#####	400733		A Service	568647
8231	#####	400733		Clean A/C filter	568647
8231	#####	400733		Grease AC Compressor Clutch Bearing	568647
8231	#####	400733		Tension Wheel Nuts To OEM Specification	568647
8231	#####	400733		fit new rear realy valve	568647
8231	#####	399744	Air System leak on rear and front rele valve	fit new rear realy valve	568647
8231	#####	399744	Air System leak on rear and front rele valve		568647
8231	4/9/2013	399744	FRONT RELAY PROPORTIONAL VALVE 0500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:G122656 Receiving #:123400 Date :2013-04-09	568647
8231	4/9/2013	399744	RELAY VALVE	Adjusted doors and secured top hinge bolts	574201
8231	4/8/2013	399744	Passenger Doors front need adjustment		568647
8231	4/8/2013	399923	BATTERY 12V 190 AMP 1000CCA (+ on right side)		574201
8231	4/8/2013	399923	BATTERY 12V 190 AMP 1000CCA (+ on right side)		574201
8231	4/8/2013	399744	Brakes - Fault Code B54347 on dash	Checked OK	568647
8231	4/5/2013	399099	Tradein casing	Creditor #:BEA001 BEAUREPARES P/O #:G122276 Receiving #:123236 Date :2013-04-05 REPLACE WITH NEW	574201
8231	4/5/2013	399099	Tradein casing	Creditor #:BEA001 BEAUREPARES P/O #:G122276 Receiving #:123235 Date :2013-04-05 REPLACE WITH NEW	574201
8231	4/5/2013	399099	FLAT - POS 6 - 11 R22.5 - NEW	Creditor #:BEA001 BEAUREPARES P/O #:G122276 Receiving #:123234 Date :2013-04-05 REPLACE WITH 295/80 SUPPLIED BY GRENDA	574201
8231	4/5/2013	399099	WORN - POS 5 - 11 R22.5 - NEW	Creditor #:BEA001 BEAUREPARES P/O #:G122276 Receiving #:123234 Date :2013-04-05 REPLACE WITH NEW	574201
8231	4/5/2013	399923	Elec & Light - Load test batteries	Changed N200 batteries	568647
8231	4/4/2013	399923	Elec & Light - Load test batteries	Batteries dead & ordered new	568647
8231	4/4/2013	399484	BATTERY 12V 190 AMP 1000CCA (+ on right side)		568647
8231	4/3/2013	399484	Elec & Light - Bus wont start	Non start attempt to start with batteries	568647
8231	4/2/2013	399099	Whls & Tyres - Replace tyre pos 56 - worn flat	Replaced	568647
8231	4/2/2013	399484	Elec & Light - Bus wont start	Jump started and put on pit checked batteries NO good need replacing	568647
8231	4/2/2013	399491	Elec & Light - Bus wont start	Jump started	568647
8231	4/2/2013	399491	Elec & Light - Bus wont start	Jump started	568647
8231	#####	395899	Annual Licence	RVC 021873 - Passed	568647
8231	#####	398202	Air Cond - AC n/w	Found a/c working very poorly needs a service	574201
8231	#####	397949	HALDEX COIL KIT 0500LE		571341
8231	#####	397949	HALDEX CONDENSER KIT TOP(CYCLONE)		571341
8231	#####	397949	CYCLONE CONDENSER VALVE KIT		571341
8231	#####	397949	DRAIN VALVE KIT BOTTOM		571341
8231	#####	397949		Inspect radiator and charge air cooler for dirt - clean	571145
8231	#####	397949	POWER STEERING FILTER VOLVO		571145
8231	#####	397949	AIR DRYER CANISTER VOLVO+ NL202		571145
8231	#####	397949	FUEL FILTER 0500LE		571145
8231	#####	397949	FUEL FILTER MERC 0500LE		571145
8231	#####	397949		Replace power steering filter and check level (Replace oil if required)	571145
8231	#####	397949		Test coolant level - top up if required to equate to 37C frost protection	571145
8231	#####	397949		Electrical - Batteries - Check fluid level ( leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	571145
8231	#####	397949		Replace final drive oil	571145
8231	#####	397949		Overhaul air separator and inspect bus for RSI	571145
8231	#####	397949		Check oil level in transmission - top up if required	571145
8231	#####	397949		Check and clean cartridge in dry type air cleaner	571145
8231	#####	397949		Replace pre and main fuel filters	571145
8231	#####	397949		Replace air dryer canister clean silence and drain reservoir	571145
8231	#####	397949		Replace angle drive oil	571145
8231	#####	397949		Rear Axle Lube	571145
8231	#####	398126	Investigation/Inspection RSI	Inspected for RSI and steam clean	571341
8231	#####	397967	Body & Acc Driver complaining could not see of mirror	Changed miior	571145
8231	#####	0	Imported Service History	Imported Service History	571145
8231	#####	396757	L.E.D SIDE MARKER PENEI RED/AMBER		570803
8231	#####	397663	WEDGE GLOBE INSTRUMENT 24V 5W		570803
8231	#####	396757	RED REFLECTOR 94X44MM		570415
8231	#####	397416	Elec & Light Wont start	Jump start	570415
8231	#####	397663	Elec & Light/O/S parker missing	replace globes	570803
8231	#####	393529	AIR LINE FITTING 0500	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120859 Receiving #:122419 Date :2013-03-18	570803
8231	#####	393529	AIR LINE OLIVE 0500	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120859 Receiving #:122419 Date :2013-03-18	570803
8231	#####	393529	AIR LINE NUT 0500	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120859 Receiving #:122419 Date :2013-03-18	570803
8231	#####	393529	AIR LINE 0500	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120859 Receiving #:122419 Date :2013-03-18	570803
8231	#####	393529	AIR LINE 0500	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120859 Receiving #:122419 Date :2013-03-18	570803
8231	#####	396757	Elec & Light O/Side clearance light out and reflector missi	Fixed	568855
8231	3/8/2013	393529	AIR DRYER CANISTER VOLVO+ NL202		568647
8231	3/8/2013	393529	Air System - comp. pres. cooling sys	Top up coolant - clean engine - Road tested OK Assist Alan	568647
8231	3/8/2013	393529	Air System - comp. pres. cooling sys	Top up coolant - clean engine - Road tested OK	568647
8231	3/7/2013	393529	TULLA TO DANDENONG	Creditor #:AAA003 AAA TOWING SERVICE P/O #:G120436 Receiving #:122017 Date :2013-03-07	568647
8231	3/7/2013	393529	Air System - comp. pres. cooling sys	Changed air dryer canister repaired coolant leak at compressor r/tested	568647
8231	3/7/2013	393529	Air System - comp. pres. cooling sys	Fit condensor pipes & checked leaks	568647
8231	3/1/2013	393529	INSPECTION HOIE GASKET	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G120726 Receiving #:121795 Date :2013-03-01	568647
8231	#####	393529	SAFETY VALVE		568647
8231	#####	393529	Air System - comp. pres. cooling sys	refitting radiator brackets refitted panles & clow catches & mopped inside	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Top up coolant finish fitting radiator diagnose air pipe blockage remove blocked pipe	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Fitted radiator	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Radiator etc	568647
8231	#####	393529	GASKET SUIT 0500LE COMPRESSOR A4571304815		568647

8231	#####	393529	Air System - comp. pres. cooling sys	Refit compressor & pas pump	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Removed header tank and radiator support bolts & radiator hoses	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Remove compressor	568647
8231	#####	393987	Elec & Light - Bus wont start	Jump started at Tulla 18/02/13	568647
8231	#####	393529	RADIATOR 0500LE	Creditor #MULD01 MULTISPARES LTD P/O #G120512 Receiving # :121209 Date :2013-02-20	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Assist to bring bus in w/shop	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Assist to bring bus in w/shop	568647
8231	#####	393529	Air System - comp. pres. cooling sys	Assist to bring bus in w/shop	568647
8231	#####	393183	MUFFLER MOUNT 0500LE	Assist to bring bus in w/shop	568137
8231	#####	393092	RAD CAP MERC BENZ SIGHT GLASS SIDE		568137
8231	#####	392927		Perform & Complete PTSV Bus Safety Inspection	567878
8231	#####	392927		Tension Wheel Nuts	567878
8231	#####	392927		Perform & Complete PTSV Bus Safety Inspection	567878
8231	#####	393203	Complete Campaign 16/12 as required	Alloy wheels	568137
8231	#####	393168	Air Cond - Clean a/c filters	Cleaned	568137
8231	#####	393183	Exhaust - Replace muffler mount	Replaced	568137
8231	#####	393092	Eng Cool - Replace radiator cap	Replaced	567878
8231	#####	392537	GLOBE H1 24V 70W		567391
8231	2/8/2013	391702	WORN - POS 6 - 11 R22.5 - NEW	Creditor #BEA001 BEAUREPAIRS P/O #K119847 Receiving # :120743 Date :2013-02-08 REPLACE WITH NEW	567391
8231	2/8/2013	392537	Ops Entered - Fault - Elec & Light Headlights - L/H headlig	Replaced	567391
8231	2/5/2013	391702	Whls & Tyres - Replace tyre pos 6 - worn	replaced	566172
8231	2/5/2013	392054	Breakdown - Glen Waverly - OUT 1.00 pm BACK 2.00 pm - Front	Van 619. Unable to fault door	566517
8231	2/4/2013	391834	Whls & Tyres - Replace tyre 6	Replaced washed rim & torqued w/nuts	566172
8231	#####	389735	Eng Cool - Leaking coolant from radiator cap	Tullamarine replaced radiator cap as req 18/01/13	561925
8231	#####	386618	DRAIN VALVE KIT BOTTOM		558812
8231	#####	386618	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	558812
8231	#####	386618	HALDEX COIL BASE OIL SEPERATOR	Base	558812
8231	#####	386618	HALDEX COIL KIT 0500LE	Coil Kit	558812
8231	#####	386647	Elec & Light - Bus wont start	Jump started	559319
8231	1/9/2013	387912	AMBER REFLECTOR		559319
8231	1/8/2013	387965	Steering Heavy	Found steering shaft u/j at steering box siezed removed shaft free of u/j & lubed	559319
8231	1/8/2013	387912	Elec & Light - Replace missing NSF amber reflector	Replaced	559319
8231	1/4/2013	387232	Steering - Loose steering wheel cover 4way valve leaking	c/o	558812
8231	1/4/2013	386860	DISC PAD SET SCANIA MB0500		558812
8231	1/4/2013	386860	HUB CAP GASKET 0500LE		558812
8231	1/4/2013	386860	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		558812
8231	1/4/2013	386860	HUB SEAL FRONT INNER MERCEDES BENZ 0500LE		558812
8231	1/4/2013	386860	HUB SEAL FRONT OUTER MERCEDES BENZ 0500LE		558812
8231	1/3/2013	386860	HUB CAP GASKET 0500LE		558812
8231	1/3/2013	386860	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500		558812
8231	1/3/2013	386860	Brakes - Front rotor low (36)	Fit LHS rotor caliper hub & brake pads	558812
8231	1/3/2013	386860	HUB SEAL FRONT OUTER MERCEDES BENZ 0500LE		558812
8231	1/3/2013	386860	HUB SEAL FRONT INNER MERCEDES BENZ 0500LE		558812
8231	1/2/2013	386860	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		558812
8231	#####	386771	AMBER REFLECTOR		558812
8231	#####	386860	Brakes Front Discs Worn	replaced with rotors	558812
8231	#####	386860	Brakes - Front rotor low (36)	Removing	558812
8231	#####	386860	Air System - Air line leaking near air dryer	Checked 4way valve leaking	558812
8231	#####	386860	Air System - overflow valve leaking	replaced	558812
8231	#####	386821	Engine - Complete chassis greasing	Completed	558812
8231	#####	386616		Perform & Complete PTSV Bus Safety Inspection done.	558812
8231	#####	386616		Tension Wheel Nuts done	558812
8231	#####	386616		Perform & Complete PTSV Bus Safety Inspection done.	558812
8231	#####	386771	Elec & Light - Replace reflector	Replaced	558812
8231	#####	386617		Tension Wheel Nuts to Spec	558812
8231	#####	386617	ENGINE OIL DELD 400LE 15W40		558812
8231	#####	386617		D-Service & Bus Safety Inspection done	558812
8231	#####	386617		A Service & Bus Safety Inspection done	558812
8231	#####	386617			558812
8231	#####	386617		Grease AC Compressor Clutch Bearing	558812
8231	#####	386617	ENGINE OIL BREATHER KIT 0500LE		558812
8231	#####	386617		Replace Engine Oil Breather Kit	558812
8231	#####	386618	Service	Re-kit Air Cyclone Separator done	558812
8231	#####	386618		Re-kit Air Cyclone Separator done	558812
8231	#####	386617		Tension Wheel Nuts To OEM Specification	558812
8231	#####	386617		Grease AC Compressor Clutch Bearing	558812
8231	#####	386617		Clean A/C filter	558812
8231	#####	386617		A Service	558812
8231	#####	385478	CAMPAIGN - Inspect front chassis cracks	checked ok - 18/12/12	555382
8231	#####	385007	GLOBE H1 24V 70W		554888
8231	#####	385007	Elec & Light - Replace NS headlight globe	Replaced	554888
8231	#####	384513	Elec & Light - Bus wont start	Jump started	554280
8231	#####	384068	HINGE DRIVERS COMPARTMENT		553862
8231	#####	384068	CHECK STRAP DRIVERS DOOR HINGE		553862
8231	#####	384476	Air System - Low air pressure	Found 6way valve leaking replaced cup washers bus still leaking found one off inside seal leak removed from old and replaced bus OK to use	553862
8231	#####	383905	LOW TREAD - POS 5 - 11 R22.5 -	Creditor #BEA001 BEAUREPAIRS P/O #K117532 Receiving # :118166 Date :2012-12-07 REPLACE WITH NEW	553862
8231	#####	384068	Accident Damaged # 36369 R/R. rear bumper-bar o/s. end dec	prep paint o/s/r corner bar refit bar with decals reflectors. refit driver compartment door new hinges and strap.	553862
8231	#####	384068	F/GLASS REAR O/S BUMPER CORNER	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #G117596 Receiving # :118131 Date :2012-12-07	553862
8231	#####	384068	AMBER REFLECTOR		553862
8231	#####	384068	RED REFLECTOR 94X44MM		553862
8231	#####	383905	Whls & Tyres - Replace tyre pos 5 - low tread	replaced	553531
8231	#####	383919	Whls & Tyres - Replace tyre 5	Replaced	553531
8231	#####	383919	Whls & Tyres - Replace tyre 5	Torqued w/nuts	553531
8231	#####	383451	Elec & Light - Bus wont start	Jump started	552781
8231	#####	382149	DRIVERS BLIND PULL KNOB		552167
8231	#####	382286		Perform & Complete PTSV Bus Safety Inspection	550255
8231	#####	382286		Tension Wheel Nuts	550255
8231	#####	382623	Elec & Light - Bus wont start	Jump started	551557
8231	#####	381847	Test and reapiir security syste	Creditor #LON001 LONSDALE ST ELECTRICS P/O #G116846 Receiving # :117561 Date :2012-11-26	551557
8231	#####	381847	Security - Test and repair security system	Adjust date and time - test ok	550255
8231	#####	382149	Body & Acc san blind U/S	Fixed	550605
8231	#####	381084	Security - Check security system	Adjust time date and turn off day light saving - OK	548406
8231	#####	381084	Test security system	Creditor #LON001 LONSDALE ST ELECTRICS P/O #G116599 Receiving # :117079 Date :2012-11-15	548406

8231	#####	379879	Elec & Light - Bus wont start	Jump started	545027
8231	#####	379885	Elec & Light - Bus wont start	Jump started	545027
8231	#####	379431		Tension Wheel Nuts To OEM Specification	545026
8231	#####	379431		Grease AC Compressor Clutch Bearing	545026
8231	#####	379431		Clean A/C filter	545026
8231	#####	379431		A Service	545026
8231	#####	378617	LED FRONT POSITION MARKER LIGHT		543334
8231	#####	378546		Perform & Complete PTSV Bus Safety Inspection	542985
8231	#####	378546		Tension Wheel Nuts	542985
8231	#####	378546		Perform & Complete PTSV Bus Safety Inspection	542985
8231	#####	378545	Random Vehicle Audit		542985
8231	#####	374227	Side wall damage - Scrap	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116263 Date :2012-10-26	543400
8231	#####	374227	Side wall damage - Scrap	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116274 Date :2012-10-26	543400
8231	#####	374241	Side wall damage - Scrap	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116263 Date :2012-10-26	543400
8231	#####	374241	BALD	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116263 Date :2012-10-26	543400
8231	#####	374241	Side wall damage - Scrap	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116274 Date :2012-10-26	543400
8231	#####	374241	BALD	Creditor # :BEA001 BEAUREPAIRES P/O #G114443 Receiving #:116274 Date :2012-10-26	543400
8231	#####	378617	Elec & Light - Replace both plate LEDs	Replaced	542985
8231	#####	377839	Air Cond - Clean a/c filters	Cleaned	541729
8231	#####	376463	COMPRESSOR OIL AIR CON		538957
8231	#####	376463	FILTER DRIER THERMO KING		538957
8231	#####	376463	VOLTR BOOST PUMP COACH		538957
8231	#####	376798	Eng Cool - Add coolant	Added	538957
8231	#####	376463	FUSE BLADE 10AMP		538672
8231	#####	376463	20AMP BLADE FUSE		538672
8231	#####	376360	Body & Acc Mirrors Interior rear door missing	Replaced	537923
8231	#####	376360	REAR DOOR CONVEX MORRROR		537923
8231	#####	376463		Replace compressor oil	537923
8231	#####	376463		B Service	537923
8231	#####	376463		Replace filter drier	537923
8231	#####	376464		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	537923
8231	#####	376464		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	537923
8231	#####	376464		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	537923
8231	#####	376464		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	537923
8231	#####	376464		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	537923
8231	#####	376464		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	537923
8231	#####	376464		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	537923
8231	#####	376464		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	537923
8231	#####	376464		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	537923
8231	#####	376464		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	537923
8231	#####	376464		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	537923
8231	#####	376463		Replace boost pump + apprentice training	537923
8231	#####	376463		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	537923
8231	#####	376463		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	537923
8231	#####	376463		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	537923
8231	#####	376463		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	537923
8231	#####	376463		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	537923
8231	#####	376463		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	537923
8231	#####	376463		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	537923
8231	#####	376463		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	537923
8231	#####	376463		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	537923
8231	#####	376463		Assisted bruce	537923
8231	#####	376463		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	537923
8231	#####	376463		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	537923
8231	#####	376182	Elec & Light - Bus wont start	Jump started	537533
8231	#####	375667	Elec & Light - Bus wont start	Jump started	536769
8231	#####	375498	Ops Entered - Fault - Desto Signs - Route: 902 - Springval	Check destination no fault found	536769
8231	#####	375551	Air Cond - Clean a/c filter	Cleaned	536790
8231	#####	374049	WORN - POS 34 - 11 R22.5 - NE	Creditor # :BEA001 BEAUREPAIRES P/O #G114369 Receiving #:114898 Date :2012-09-27 REPLACE WITH NEW	534890
8231	#####	374227	Whls & Tyres - Scrap tyre - sidewall damage	Scrapped	534400
8231	#####	374241	Whls & Tyres - Scrap tyre - sidewall damage	Scrapped	534400
8231	#####	374049	Whls & Tyres - Replace tyre pos 34 - worn	Replaced	534400
8231	#####	374099	Whls & Tyres - Replace tyres 34	Replaced	534400
8231	#####	373723	Body & Acc - Polish exterior panels/headers (checked on 16/0	Polished	534387
8231	#####	373723	Cut into drivers dash to fit new h/brake unit	Cut into	534387
8231	#####	373556	Ops Entered - Fault - Brakes Hand Brake - Route: 901 - Dan	change parking brake value fix plate and road test bus ok.	534387
8231	#####	373723	UNREPORTED - Repair & paint NS rear w/arch panel	Repaired	534387
8231	#####	373253		Perform & Complete PTSV Bus Safety Inspection	534387
8231	#####	373253		Tension Wheel Nuts	534387
8231	#####	373253		Perform & Complete PTSV Bus Safety Inspection	534387
8231	#####	372604	WORN - POS 1 - 11 R22.5 - NEW	Creditor # :BEA001 BEAUREPAIRES P/O #G113925 Receiving #:114482 Date :2012-09-20 REPLACE WITH NEW	534387
8231	#####	373461	Eng Cool - Check for coolant leak	Replaced 2 hose clamps	534387
8231	#####	372613	REPL. WINDSCREEN	Creditor # :ELI001 ELITE WINDSCREENS P/O #G113930 Receiving #:114517 Date :2012-09-20	534387
8231	#####	373078	REPLACE 8MM SAFETY FILM TO DRI	Creditor # :GLAD03 GLASSPRO MELBOURNE PTY.LTD. P/O #G114069 Receiving #:114493 Date :2012-09-20 REPLACE	534387
8231	#####	373078	Body & Acc - Replace 8mm safety film to drivers window	Replaced	534286
8231	#####	372604	Whls & Tyres - Replace tyre pos 1 - worn	Replaced	533781
8231	#####	372613	SUB - NS windscreen cracked from side to side	sent to Elite - 17/09/2012	533781
8231	#####	372613	Body & Acc. Windows Windscreen has a crack on the N/S cmr.	sent to Elite - 17/09/2012	533781
8231	#####	372405	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		533781
8231	#####	372405	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		533781
8231	#####	372405	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		533781
8231	#####	372405	Drv entered - Brakes Losing Air	Adjusted park brake tank air pressure fixed air leak from 4way valve air line r/tested bus OK	533218
8231	#####	372726	Whls & Tyres - Replace tyre pos 1	Replaced	533781
8231	#####	372405	Drv entered - Brakes Losing Air	Changed air dryer assy air line fitting kit adjusted air pressure and r/tested bus OK	533218
8231	#####	372405	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		533218
8231	#####	372405	AIR DRYER MERCEDES 0500		533218
8231	#####	372405	Brakes R/H/Rear brake booster leaking	Checked both boosters not leaking OK	533218
8231	#####	372405	Drv entered - Brakes Losing Air	Needs new RHR brake booster	533218
8231	#####	372364	Ops Entered - Fault - Brakes Losing Air - Route: 900 - Wel	Fitted new accumulator solenoid valve & air tank drain valve	533218
8231	#####	372364	Ops Entered - Fault - Air System Slow To Build - Route: 90	Fitted new valves	533218
8231	#####	9/5/2012	371283 Eng Cool - Add coolant	Added	531741
8231	#####	370128	GLOBE 24V 21W SINGLE CONTACT		529028
8231	#####	370128	SIDE INDICATOR R/H		529028
8231	#####	370581	Eng Cool - Add coolant	Added	530072
8231	#####	370128	Elec & Light Indicators front indicator missing	Fitted new indicators & globe	529028

8231	#####	370254	Eng Cool	Coolant Low	Fitted new coolant hose to boost pump topped up coolant r/tested OK	529028
8231	#####	369851			Tension Wheel Nuts To OEM Specification	528873
8231	#####	369851			A Service	528873
8231	#####	369851			Clean A/C filter	528873
8231	#####	369851			Grease AC Compressor Clutch Bearing	528873
8231	#####	363836	Supply and install decals		Creditor #ATT001 ATTITUDE SIGNS P/O #:G112554 Receiving #:113263 Date :2012-08-24	528561
8231	#####	369476	Elec & Light	Replace ns clearance light globe	Replaced	528141
8231	#####	369514	Eng Cool	Check for coolant leak	Assisted Dulkith	528141
8231	#####	369514	Eng Cool	Check for coolant leak	Changed boost pump to transmission cooler pipe valve heater hose top up coolant r/tested bus OK	528141
8231	#####	369483	Eng Cool	Add coolant	Added	528141
8231	#####	369476	Comm Equip	Radio fallen inside dash	Secured	528141
8231	#####	369476	Comm Equip	Radio fallen inside dash	Removed radio and gave to Greg	528141
8231	#####	369100	Eng Cool	Add coolant	Added	527601
8231	#####	369891	Elec & Light	Interior lights n/w	Checked and found switch plug was out refitted OK	525706
8231	#####	363836	Replace decals		Creditor #ATT001 ATTITUDE SIGNS P/O #:G111111 Receiving #:112924 Date :2012-08-17	526244
8231	#####	368428			Perform & Complete PTSV Bus Safety Inspection	525969
8231	#####	368428			Tension Wheel Nuts	525969
8231	#####	368215	Eng Cool	Add coolant	Added	525656
8231	#####	368024	Elec & Light	Bus wont start	Jump started	525350
8231	#####	368024	Elec & Light	Bus wont start	Jump started	525350
8231	#####	368022	Eng Cool	Add coolant	Added	525350
8231	#####	368022	Eng Cool	Add coolant	Added	525350
8221	8/4/2012	366696			Adjust Tappets	522710
8231	8/2/2012	366634	Vandalism	Remove graffiti from OSR inner windows & walls	Removed	522710
8231	8/2/2012	366631	Eng Cool	Add coolant	Added	522710
8231	#####	364114	AIR CON	REFRIDGERANT		518823
8231	#####	364114	COMPRESSOR OIL	AIR CON		518823
8231	#####	364114	Consumable	- TOOLUNG		518823
8231	#####	363926	PASS SEAT	HANDGRIP CENTRA MK 2		518823
8231	#####	364340	BATTERY 12V 150 AMP	1000CCA (+ on right side)		517522
8231	#####	364340	Elec & Light	Battery Flat	checked alternator charge. replaced batteries.	517522
8231	#####	364114	Air Cond	Climate control n/w fault light is on	Fixed	517504
8231	#####	363926	Body & Acc	Decal on rear window needs replacing (Checked)	replaced	517522
8231	#####	363926	Body & Acc	Paint till stand	Painted	517522
8231	#####	363926	Body & Acc	Replace seat cushions - rear	replaced	517522
8231	#####	363926	Body & Acc	Secure all lower skirt panels	secured	517522
8231	#####	363926	Body & Acc	replace passenger seat hand grips - rear NS	Replaced	517522
8231	#####	363926	Body & Acc	Front blind needs repairing (Checked on 05/04/12)	repaired	517522
8231	#####	363926	Body & Acc	Replace licensed to carry (No) seat (No) adult	Replaced	517522
8231	#####	364267	Body & Acc	Fit rear edge rear of bus	Fited	517522
8231	#####	364266	Body & Acc	Mirrors Exterior paint	Painted	517522
8231	#####	363836	Accident Damaged # 35542 R/R	rear bumper-bar reflectors (2	Prep mask and painted	517522
8231	#####	363836	UNREPORTED - Repair & paint	front header	Prep mask - painted	517522
8231	#####	363879			Perform & Complete PTSV Bus Safety Inspection	517504
8231	#####	363879			Tension Wheel Nuts	517504
8231	#####	363879			Perform & Complete PTSV Bus Safety Inspection	517504
8231	#####	360551	Removed unloader stim	replace all O rings - Replace Comp. oi	Pressure tested found unloader stem weeping repairwill be done next wed	509257
8221	#####	363911	Ops Entered	- Fault - Eng Cool W/ning Light - Route: 901 -		517504
8231	#####	363811	CYCLONE CONDENSER VALVE KIT		Condenser Valve Kit.	517504
8231	#####	363811			Re-kit Air Cyclone Separator	517504
8231	#####	363811				517504
8231	#####	363811	HALDEX COIL KIT	0500LE	Coil Kit	517504
8231	#####	363811	DRAIN VALVE KIT	BOTTOM	Valve Kit	517504
8231	#####	363811	HALDEX COIL BASE	OIL SEPARATOR	Base	517504
8231	#####	363678	BROOM HEAD	(09803211)		516244
8231	#####	363678	Body & Acc	replace broom head	Given to Leo	516244
8231	#####	363082	DOWN LIGHT	LED		515176
8231	7/9/2012	363082	Elec & Light	Replace front door step light	Replaced	515176
8231	7/8/2012	362905	Eng Cool	Add coolant	Added	514689
8231	7/7/2012	362897	Passenger Doors	Rear door wont close	Went to KSB and adjusted rear door	514689
8231	7/4/2012	362078	Whls & Tyres	Replace worn tyres pos.5. 6.		513424
8231	7/4/2012	362069	Whls & Tyres	Replace worn tyres pos.5.6.		513424
8231	7/3/2012	362157	Whls & Tyres	Replace tyres pos.5.6.	Replaced	513424
8231	7/3/2012	360216	Mechanic entered	- Eng Cool Leaking	Fit new coolant hose to pipe at trans. cooler	508427
8221	7/3/2012	362008			Replace Engine Oil Breather Kit	513265
8231	7/3/2012	362008	ENGINE OIL	BREATHER KIT 0500LE		513265
8231	7/3/2012	362008			Grease AC Compressor Clutch Bearing	513265
8231	7/3/2012	362008	AIR FILTER	MERC 0500LE		513265
8231	7/3/2012	362008	OIL FILTER	1725+0500LE		513265
8231	7/3/2012	362008	ENGINE OIL	DELO 400LE 15W40		513265
8231	7/3/2012	362008			Tension Wheel Nuts to Spec	513265
8231	7/3/2012	362008			A Service & Bus Safety Inspection	513265
8221	7/3/2012	362008			D-Service & Bus Safety Inspection	513265
8231	7/3/2012	362008			A Service	513265
8231	7/3/2012	362008			Clean A/C filter	513265
8231	7/3/2012	362008			A Service	513265
8231	7/3/2012	362008			Grease AC Compressor Clutch Bearing	513265
8231	7/3/2012	362008			Tension Wheel Nuts To OEM Specification	513265
8231	7/1/2012	349637	TIE ROD	END R/H		491500
8231	#####	352587	Replace	Ventura decal	Creditor #MULD001 MULTISPARES LTD P/O #:G106557 Receiving #:106990 Date :2012-04-10	511619
8231	#####	360787	AMBER REFLECTOR	SIDE MOUNT	Creditor #ATT001 ATTITUDE SIGNS P/O #:G109198 Receiving #:110623 Date :2012-06-28	509546
8231	#####	360557				509257
8231	#####	360557			Tension Wheel Nuts	509257
8231	#####	360557			Perform & Complete PTSV Bus Safety Inspection	509257
8231	#####	360777	Air Cond	- Clean a/c filter	Cleaned	509546
8231	#####	360551	Air Cond	- A/C oil leak	Pressure tested found unloader stem weeping repairwill be done next wed	509257
8231	#####	360787	Elec & Light	Secure loose light & replace reflectors	Resecured & replaced	509546
8231	#####	360778	Eng Cool	Add coolant	Added	509546
8231	#####	360216	Mechanic entered	- Eng Cool Leaking	Look for bus cant find supervisor found in Tulla	509427
8231	#####	360130	Breakdown	- Doncaster Shopping Centre - OUT 4.30 pm BACK 7.	Van 619. Drove bus back to depot OK back in service	508427
8231	#####	359878	Elec & Light	Replace NS indicator globe	Replaced	508196
8231	#####	359279	Eng Cool	Check for coolant leak	Repaired leak on heater hose	506905
8231	#####	359171	Eng Cool	Add coolant	Added	506000
8231	6/8/2012	354932	DRIVERS SEAT	BELT BUCKLE		504370
8231	6/7/2012	358509	Elec & Light	Bus wont start	Jump started	504370

8231	6/7/2012	358509	Elec & Light - Replace globes	Replaced	504370
8231	6/6/2012	358014	Suspension - Front OS airbag suspension minor crack	check ok serviceable	503821
8231	6/6/2012	358100	A/C BELT 0500 BENZ		503821
8231	6/6/2012	358014	Exhaust - Exhaust muffler mount broken	check ok	503821
8231	6/6/2012	358014	Engine - Replace angle drive oil	ngle drive oil and check leak ok	503821
8231	6/6/2012	358014	Brakes - Rear brakes and rotors need replacing 26mm	change o/s rear brake calliper piston boot fix brake calliper to bus put fix new pads top u diff oil road test and clean work area bus ok	503821
8231	6/6/2012	358014	Air System - Air dryer leaking all the time	change air line o ring kit ok	503821
8231	6/5/2012	358014	Suspension - Front OS airbag suspension minor crack	Doubled up	503821
8231	6/5/2012	358014	Gearbox - Transmission coolant hose leak next to drive shaft		503821
8231	6/5/2012	358014	Exhaust - Exhaust muffler mount broken	Doubled up	503821
8231	6/5/2012	358014	Engine - Replace angle drive oil	Doubled up	503821
8231	6/5/2012	358015	Body & Acc - Paint exterior mirrors and arms		503821
8231	6/5/2012	358014	Brakes - Rear brakes and rotors need replacing 26mm	Fixed NS rear axle brake caliper assy changed brake pads changed OS hub seal kit rotor adjusted os wheel bearing put axle back. Start to change brake caliper piston seal kit OS	503821
8231	6/5/2012	358014	Brake CALIPER TAPPET KIT 0500(AD04204982)		503821
8231	6/5/2012	358014	Air System - Air dryer leaking all the time	Doubled up	503821
8231	6/4/2012	357158	FRONT-REAR DISC ROTOR MERCEDES BENZ 0500		503821
8231	6/4/2012	357158	DISC PAD SET SCANIA MB0500		503821
8231	6/4/2012	357158	Mechanic entered - Brakes Brake Linings Worn		503821
8231	6/4/2012	358014	Brakes - Rear brakes and rotors need replacing 26mm	Change NS rear hub seal rotor and adjust bearing	503821
8231	6/1/2012	357158	REAR HUB SEAL KIT 0500LE		503821
8231	#####	357158	Drv entered - Air Cond Cooling Fault Light	Checked OK	503821
8231	#####	357158	Passenger Doors - Rear door brake n/w while its open	Found door override switch had been tampered with	503821
8231	#####	357158	Passenger Doors - Sensitive edges n/w	Found door override switch had been tampered with	503821
8231	#####	357158	Passenger Doors - Back door brake n/w	Found door override switch had been tampered with	503821
8231	#####	357158	Elec & Light - Bus still moves while ramp is down	Found door override switch had been tampered with	503821
8231	#####	357158	Drv entered - Elec & Light Headlights	Checked OK	503821
8231	#####	357158	Elec & Light - Horn button missing	Replaced stalk	503821
8231	#####	357158	Elec & Light - Horn n/w	Replaced stalk	503821
8231	#####	357158	INDICATOR ARM 0500LE		503821
8231	#####	357158	Mechanic entered - Elec & Light Horn button on indicato	Replaced stalk	503821
8231	#####	357273	PLASTIC WASHER		503821
8231	#####	357273	BUMPER BOLT SPECIAL		503821
8231	#####	357158	Mechanic entered - Brakes Brake Linings Worn	remove rear both side bake assyhubclean all parts and order parts	503821
8231	#####	357273	Body & Acc - Replace rear bar bolts	Replaced	503821
8231	#####	356936	No Defect Recorded	Carried out an A service	503604
8231	#####	356879	Eng Cool - Add coolant	Added	503604
8231	#####	356618	Eng Cool - Coolant leak	Removed hose from 252 and fitted to bus top up coolant	503604
8231	#####	356618	ad01501Z282 hose	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G108774 Receiving #:109054 Date :2012-05-28	503604
8231	#####	356518	Ops Entered - Fault - Eng Cool High Temperature - Router: 9	Had to wait because driver had left	503604
8231	#####	356821	Breakdown - Doncaster Rd - OUT 3.00 pm BACK 5.15 pm - Coola	Van 619. Topped up coolant (hose needs replacing)	502293
8231	#####	355093			500242
8231	#####	355093			500242
8231	#####	355093			500242
8231	#####	354932	Elec & LightO/S head light out and also fault light red sho	Tension Wheel Nuts	499717
8231	#####	354639	Elec & Light Battery Flat	Perform & Complete PTSV Bus Safety Inspection	499717
8231	#####	354509		Replace head light globe - no red light found on A/C repaired by Tullamarine	498870
8231	#####	354509		Tension Wheel Nuts To OEM Specification	498870
8231	#####	354509		Grease AC Compressor Clutch Bearing	498870
8231	#####	354509		Clean A/C filter	498870
8231	#####	354509		A Service	498870
8231	#####	354509			498870
8231	5/6/2012	352587	Ventura decals to be supplied fitted to SmartBus	Replaced	495725
8231	5/4/2012	358100	Engine - Replace belts	Replaced	497324
8231	5/2/2012	350616	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G107176 Receiving #:107945 Date :2012-05-02	496012
8231	5/2/2012	353030	GLOBE H1 24V 70W		496012
8231	5/1/2012	353030	Elec & Light - RH headlight n/w	Checked OK	496012
8231	5/1/2012	353030	Body & Acc - Straighten mirror arm	Straightened & replaced mirror took from one in workshop	496012
8231	#####	352681	Elec & Light - Bus wont start	Jump started	495725
8231	#####	350616	Annual Licence	RWC 381321 - Passed	491885
8231	#####	351815	Elec & Light - Bus wont start	Jump started	494476
8231	#####	351843	Air System - Rebuild ACS	Rebuilt	494476
8231	#####	341349	HALDEX COIL BASE OIL SEPARATOR		493971
8231	#####	341349	HALDEX CONDENSER KIT TOPI(CYCLONE)		493971
8231	#####	341349	CYCLONE CONDENSER VALVE KIT		493971
8231	#####	351513	Eng Cool - Add coolant	Added	493552
8231	#####	350802	Air Cond - Clean a/c filters	Cleaned	492270
8231	#####	350411	L.E.D SIDE MARKER PERE1 RED/AMBER		491885
8231	#####	350639	Elec & Light - Bus wont start	Jump started	491885
8231	#####	350411	Elec & LightRear L/H parking light U/S	replaced light	491501
8231	#####	350586	Eng Cool - Add coolant	Added	491529
8231	#####	349637	GEARBOX OIL COOLER LINE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G106701 Receiving #:107132 Date :2012-04-13	491501
8231	#####	349869	RAD CAP MERC BENZ SIGHT GLASS SIDE		491500
8231	#####	349869		Overhaul air separator	491500
8231	#####	349868	Wheel Alignment - need to check alignment		491500
8231	#####	349869	AIR FILTER MERC 0500LE		491500
8231	#####	349869	RPM BORATE EP LUBE 220	Rear Axle Lube	491500
8231	#####	349869		Replace final drive oil DONE	491500
8231	#####	349869		Electrical - Batteries - Check fluid level ( leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals DONE	491500
8231	#####	349869		Inspect radiator and charge air cooler for dirt - clean DONE	491500
8231	#####	349869		Check oil level in transmission - top up if required DONE	491500
8231	#####	349869			491500
8231	#####	349869	AIR DRYER CANISTER VOLVO+ NL202		491500
8231	#####	349869	FUEL FILTER 0500LE		491500
8231	#####	349869	FUEL FILTER MERC 0500LE		491500
8231	#####	349869	POWER STEERING FILTER VOLVO		491500
8231	#####	349869			491500
8231	#####	349869		Check and clean cartridge in dry type air cleaner DONE	491500
8231	#####	349869		Replace pre and main fuel filters DONE	491500
8231	#####	349869		Replace air dryer canister clean silence and drain reservoir DONE	491500
8231	#####	349869		Replace angle drive oil	491500
8231	#####	349869		Test coolant level - top up if required to equate to 37C frost protection DONE	491500
8231	#####	349869		Replace power steering filter and check level (Replace oil if required) DONE	491500
8231	#####	349637	Steering - Drag link rear ball joint - worn 2.5mm	Replaced fitted wheels & tensioned	491500
8231	#####	349831	GLOBE S/CONTACT 24V-10W		491500
8231	#####	349613	Annual Body Inspection	Inspected	491500
8231	4/5/2012	349512		Tension Wheel Nuts	491240
8231	4/5/2012	349512		Perform & Complete PTSV Bus Safety Inspection	491240
8231	4/5/2012	349512		Perform & Complete PTSV Bus Safety Inspection	491240

8231	4/5/2012	349831	Elec & Light - Replace globe	Replaced	491500
8231	#####	348347	AMBER REFLECTOR SIDE MOUNT		488838
8231	#####	348347	Elec & Light - Replace os reflector	Replaced	488838
8231	#####	348028	Eng Cool - Add coolant	Added	488487
8231	#####	347497	brakes Bus Stop - not releasing	sent to Volgren - 22/03/2012 checked recurring fault sent to volgren	487411
8231	#####	347497	Brakes Bus Stop - not releasing	Checking why bus wont move put override switch on	487411
8231	#####	347148	Gearbox - Wont select gears	Repaired by Dysons 08/02/12 = \$60.94 ex gst	486634
8231	#####	347151	Eng Cool - Broken fan belt	Repaired by Dysons 18/02/12 = \$53.22 ex gst	486634
8231	#####	345338	SOLENIOD VALVE DOOR RAMS		485505
8231	#####	346366	Accident - Front bumper smashed needs replacing	Dismantled front bar painted bumper from 8378 assembled	485505
8231	#####	345830		Service T - Replace Transmission Oil & Filter	485505
8231	#####	345830	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	485505
8231	#####	345830	FILTER TRANSMISSION ZF 4139-298-038E9HD119	ZF Transmission Filter	485505
8231	#####	345830		Bus Safety Inspection	485505
8231	#####	345830		Service T - Replace Transmission Oil & Filter	485505
8231	3/9/2012	346055	Passenger Doors - Front door n/w prop	Replaced solenoid	484439
8231	3/9/2012	345591	Dash warning lights coming ON	Checked for alternator warning lamp ON adjusted loose alternator belt and topped up coolant road tested ok	484063
8231	3/7/2012	345338	Passenger Doors - Faulty door operation	Checked out front door leaking air replaced solenoid valve	483451
8231	3/7/2012	345191		Service completed	483451
8231	3/6/2012	344807	AIR FILTER MERC 0500LE		483151
8231	3/6/2012	345044	Body & Acc - Drivers seat spring broken no adjustment	Checked seat got parts from economy bolts & secured shaft	483151
8231	3/6/2012	345044	Body & Acc - Dial on drivers seat n/w	Checked seat got parts from economy bolts & secured shaft	483151
8231	3/6/2012	345086	Body & Acc - Reattach fire extinguisher	Reattached	483151
8231	3/5/2012	344807		Tension Wheel Nuts	482851
8231	3/5/2012	344807		Perform & Complete PTSV Bus Safety Inspection	482851
8231	3/5/2012	344808		A Service	482851
8231	3/5/2012	344808		Grease AC Compressor Clutch Bearing	482851
8231	3/5/2012	344808		Tension Wheel Nuts To OEM Specification	482851
8231	3/5/2012	344808		Clean A/C filter	482851
8231	#####	344100	Investigation/Inspection - Bus wont move	Clean A/C filter	481051
8231	#####	343232	Passenger Doors - Check door button operation	Assisted driver	479251
8231	#####	343157	Eng Cool - Add coolant	Checked fuel & park	479251
8231	#####	343169	Eng Cool - Add coolant	Added	479251
8231	#####	340715	DP 11R22.5 148/145L TL SP350A	Added	479251
8231	#####	342915	Eng Cool - Add coolant	Creditor #BEA001 BEAU REPAIRS P/O #K103889 Receiving #:105139 Date :2012-02-21 Replace with tyre	478951
8231	#####	342785	Eng Cool - Replace coolant line	Added	478951
8231	#####	342785	AIR LINE FITTING KIT 0500LE AIR DRYER	Removed floor cover changed coolant line	478651
8231	#####	342785	Air System - Replace airline O ring	Replaced	478651
8231	#####	342785	HALDEX COIL KIT OIL SEPARATOR	rekitted fuelled & parked bus	478651
8231	#####	342785	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	rekitted fuelled & parked bus	478651
8231	#####	342785	Air System - Rekit cyclo pack	rekitted fuelled & parked bus	478651
8231	#####	342619	Breakdown - Doncaster - OUT 2.30 pm BACK 6.10 pm - Air leak	Van 619. Found air compressor coolant hose leak fixed temp bus u/s (need to replace coolant hose)	478051
8231	#####	342619	A/C BELT 0500 BENZ	Van 619. Found air compressor coolant hose leak fixed temp bus u/s (need to replace coolant hose)	478051
8231	#####	341465	Accident - Broken NS mirror head	Replaced ns mirror head on 16/01/12 = \$58.22 NO gst	475801
8231	2/9/2012	341160	Passenger Doors - Front door air leak	Ass Greg with door fault	475686
8231	2/9/2012	341160	Passenger Doors - Front door air leak	Fuelled and parked	475686
8231	2/9/2012	341160	Passenger Doors - Front door air leak	Pulled off hoses checked solenoids now working OK	475686
8231	2/9/2012	341343	Elec & Light - Bus wont start	Jump started	475801
8231	2/9/2012	341349		Re-kit Air Cyclone Separator	475801
8231	2/8/2012	340922	Passenger Doors Adjust all doors	adjust all doors	475330
8231	2/7/2012	340715	Whls & Tyres - Replace tyres 34 - low tread	Replaced	475330
8231	2/6/2012	340729	Whls & Tyres - Replace NSR both tyres	Replaced	475330
8231	2/3/2012	340272	Elec & Light - Bus wont start	Jump started by Tullamarine 31/01/12 = \$12.71 inc	474790
8231	#####	339408	Passenger Doors - Check doors	Checked OK	473321
8231	#####	338249	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		471396
8231	#####	338249	Brakes - Brake pedal worn	Checked OK	471035
8231	#####	338249	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		471035
8231	#####	338249	Air System - Water seperator air leak	Air leaking from 6 way valve rectified also from pipe line O ring changed checked OK fuelled & parked	471035
8231	#####	337280	Passenger Doors Faulty Controls	Checked working OK	468777
8231	#####	337280	Heat & Demist - Heater n/w blowing cold air	Checked demister no heat found tap was turned off under bus	468777
8231	#####	337468	Eng Cool - Check for coolant leak	Tightened hose clamp & topped up coolant	468777
8231	#####	337239	Eng Cool - Add coolant	Added	468777
8231	#####	337113	Passenger Doors - Check doors	Checked out unable to fault	468777
8231	#####	337013	Gearbox - Repair oil leak at transmission cooler	Fitted new trans oil cooler coolant hose top up coolant r/tested OK	468329
8231	#####	336957	Passenger Doors - Check front door	Checked temp repaired	468329
8231	1/8/2012	336510	Elec & Light - Bus wont start	Jump started	467672
8231	1/7/2012	336220		Tension Wheel Nuts to Spec	467206
8231	1/7/2012	336220	ENGINE OIL DELO 400LE 15W40		467206
8231	1/7/2012	336220	OIL FILTER 1725+0500LE		467206
8231	1/7/2012	336220	AIR FILTER MERC 0500LE		467206
8231	1/7/2012	336220		Grease AC Compressor Clutch Bearing	467206
8231	1/7/2012	336220		Replace Engine Oil Breather Kit	467206
8231	1/7/2012	336220		A Service & Bus Safety Inspection	467206
8231	1/7/2012	336220		D-Service & Bus Safety Inspection	467206
8231	1/7/2012	336220		Clean A/C filter	467206
8231	1/7/2012	336220		A Service	467206
8231	1/7/2012	336220		Tension Wheel Nuts To OEM Specification	467206
8231	1/7/2012	336220		Grease AC Compressor Clutch Bearing	467206
8231	1/1/2012	335690	Elec & Light - Bus wont start	Jump started	466317
8231	#####	335500	Elec & Light - Bus wont start	Jump started	463961
8231	#####	335502	Eng Cool - add coolant	Added	465961
8231	#####	335079	Eng Cool - Add coolant	Added	465235
8231	#####	334862	Passenger Doors - Front door fault	adjusted & lubed all doors	464851
8231	#####	334862	Body & Acc - Sunblind ratchet faulty	Repaired	464851
8231	#####	329904	SCRAP	Creditor #BEA001 BEAU REPAIRS P/O #G101929 Receiving #:103016 Date :2011-12-22	464851
8231	#####	334399	Eng Cool - Add coolant	Added	463962
8231	#####	334399	Eng Cool - Add coolant	Added	463962
8231	#####	334319		Done at Roadworthy inspection - Doc 135831 - 17/12/2011	463962
8231	#####	334319		Tension Wheel Nuts	463962
8231	#####	334319		Perform & Complete PTSV Bus Safety Inspection	463962
8231	#####	334209	Eng Cool - Check for coolant leak	Repaired	463517
8231	#####	333871	Eng Cool - Add coolant	Added	462564
8231	#####	333871	Eng Cool - Add coolant	Added	462564
8231	#####	333795	Passenger Doors - Adjust rear doors	Adjusted and lubed top mechanism	462113
8231	#####	333520	Eng Cool - Add coolant	Added	461712

8231	#####	333302	Eng Cool - Add coolant	Added	461173
8231	#####	332736	Eng Cool - Add coolant	Added	460275
8231	#####	332736	Eng Cool - Add coolant	Added	460275
8231	#####	331888	Air Cond - Clean a/c filters	Cleaned	458050
8231	#####	331628	Brakes - brakes locking on - possible bus stop brake fault	Found broken wire inside door box replaced wire clip and r/test to check door brake	457589
8231	#####	331628	Brakes - brakes locking on - possible bus stop brake fault	Checked front and rear brake pads	457589
8231	#####	329904	BALD POS 1-2 11R NEW	Creditor #BEAD01 BEAUREPARES P/O #G100671 Receiving #101836 Date :2011-11-28	456973
8231	#####	330721	Eng Cool - Add coolant	Added	455380
8231	#####	330721	Eng Cool - Add coolant	Added	455380
8231	#####	330351	AIR FILTER MERC 0500LE		453915
8231	#####	330495	Eng Cool - Add coolant	Added	453915
8231	#####	330495	Eng Cool - Add coolant	Added	453915
8231	#####	329970	DISC PADS SCANIA L94+0500 MERC		453915
8231	#####	330386	Passenger Doors - Door brake on	Found stones under wheel chair ramp r/tested OK	453915
8231	#####	330351	Eng Cool - Check for coolant leak	Repaired leak loose connection on header tank	453915
8231	#####	329904	Whls & Tyres - Replace tyres 12 - worn	Replaced	453456
8231	#####	327676	HOSE	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G100616 Receiving #101457 Date :2011-11-18	453456
8231	#####	329970	Whls & Tyres - Need to change tyres 123 & 4	Changed tyres	453456
8231	#####	329959	Breakdown - Stud Rd near Heatherton Rd - OUT 5.00 pm BACK 5	Van 619. Maybe by mistake driver turned door brake switch r/tested nothing wrong	453456
8231	#####	329970	Brakes - Replace front brake pads	Replaced	453456
8231	#####	328487	Wipers & Washers - Replace wiper link and pivot	Change NS wiper assy	453238
8231	#####	328487	BLADE WIPER 1MTR		453238
8231	#####	327676	Eng Cool - Replace coolant pipe	Changed coolant header tank pipe	453238
8231	#####	329239		A Service	453238
8231	#####	329239		Clean A/C filter	453238
8231	#####	329239		Grease AC Compressor Clutch Bearing	453238
8231	#####	329239		Tension Wheel Nuts To OEM Specification	453238
8231	#####	328487	Wipers & Washers - Replace wiper link and pivot	Change OS wiper link and pivot wiper arm blade assy and adjust wiper link	453238
8231	#####	327676	COOLANT PIPE EXP TANK MERC 0500LE		453238
8231	#####	327676	Elec & Light - Change battery side	Changed	453238
8231	#####	328487	WIPER LINK 37593+37592	Creditor #VOI001 VOLGREN AUSTRALIA P/L P/O #G100386 Receiving #101290 Date :2011-11-14	453238
8231	#####	328844	PRESSURE CAP 78AR 0MDS+0500LE		453238
8231	#####	328487	wiper arm link VG2183	Creditor #VOI001 VOLGREN AUSTRALIA P/L P/O #G100278 Receiving #101183 Date :2011-11-10	453238
8231	#####	328487	R/H WIPER ARM (BOSCH) LONG		453238
8231	#####	328487	BLADE WIPER 1MTR		453238
8231	#####	328839	Air Cond - Clean a/c filters	Cleaned	453238
8231	#####	328844	Eng Cool - Replace coolant cap	Replaced	453238
8231	#####	328487	Wipers & Washers - Replace wiper link and pivot	Pulled apart but dont have parts ordred parts	453238
8231	#####	328379	Eng Cool - Add coolant	Added	453238
8231	#####	327435	POS 6 11R NEW	Creditor #BEAD01 BEAUREPARES P/O #G100017 Receiving #100988 Date :2011-11-07	452790
8231	#####	327676	Gearbox - Replace g/box coolant hose	Start to remove coolant pipe	451794
8231	#####	327676	A0008321894 COOLANT G/BOX HOSE	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G98897 Receiving #100916 Date :2011-11-04 8231	451794
8231	#####	327435	Whls & Tyres Worn tyre pos 6	replaced	451638
8231	#####	327611	Whls & Tyres - Replace tyres 56	Replaced tyres had to undo nuts manually & tensioned w/nuts	451794
8231	#####	326664	WEDGE GLOBE INSTRUMENT 24V 3W		449816
8231	#####	326664	GLOBE INDICATOR 24V-18W SINGLE CONTACT		449816
8231	#####	326664	CLEAR FRONT INDICATOR WRAP-AROUND		449816
8231	#####	326924	CAMPAIGN - Install retro - reflector tape on rear engine ha	Installed by Attitude signs	451011
8231	#####	326664	Elec & Light - Replace bottom side indicator	Replaced with new	449816
8231	#####	326691	Eng Cool - Add coolant	Added	449816
8231	#####	324769	AIR CON REFRIDGERANT		448416
8231	#####	324769	AIR CON O RING FREON GAS		448416
8231	#####	324769	FILTER DRIER THERMO KING		448416
8231	#####	325934	Passenger Doors - Front door wont shut	checked OK	448304
8231	#####	325934	Bus wont start	Jump started	448304
8231	#####	325897	Passenger Doors - Adjust front door	Adjusted	447592
8231	#####	325097	WABCO FOOT VALVE MERC 0500LE	Creditor #MUL001 MULTISPARES LTD P/O #G99237 Receiving #100185 Date :2011-10-20	446925
8231	#####	325492	Elec & Light - Bus wont start	Jump started	446925
8231	#####	325097	Air System - Bad air leak from foot valve	Replaced foot valve r/tested	446908
8231	#####	325061	Elec & Light - Bus wont start	Went to KSB and jump started bought back to GBS	446908
8231	#####	325097	Air System - Bad air leak from foot valve	Parts on order	446908
8231	#####	324769	Locate and repair refrigerant at unloaders	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	446908
8231	#####	324769		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	446908
8231	#####	324769		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	446908
8231	#####	324769		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	446908
8231	#####	324769		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	446908
8231	#####	324769		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	446908
8231	#####	324769		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	446908
8231	#####	324769		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	446908
8231	#####	324769		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	446908
8231	#####	324769		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	446908
8231	#####	324769		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	446908
8231	#####	324945	Elec & Light - Clean battery terminals	Cleaned with hot water	446908
8231	#####	324590	Elec & Light - Bus wont start	Jump started	446519
8231	#####	324560	Eng Cool - Add coolant	Added	446519
8231	#####	324367	Elec & Light - Bus wont start	Jump started	446254
8231	#####	324049	Suspension - Replace NS swaybar link rod	sway bar link rod	446208
8231	#####	324049	Suspension - Replace NS swaybar link rod	Changed front NS sway bar link rod & r/tested	446208
8231	#####	321698	AG283201089 sway bar link rod	Fitted	446208
8231	#####	323946	CAMPAIGN - Fit covers on retarder switches in electrical cen	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G98917 Receiving #99754 Date :2011-10-11 8231	446208
8231	#####	321698	Suspension - OSF swaybar anti roll bar link rod worn	Assisted Dulith with sway bar link	445757
8231	#####	321698	Suspension - OSF swaybar anti roll bar link rod worn	Changed OS sway bar link rod and r/test but need to change NS link rod also ordered parts bus u/s	445757
8231	#####	321698	Passenger Doors - Adjust front & rear door sensitive edges	Adjusted front/rear door sensitive edges and door ramp speed	445757
8231	#####	321698	STABILISER LINK RHS	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G98405 Receiving #99340 Date :2011-09-29	445757
8231	#####	321904	Air Cond - Clean a/c filters	Cleaned	445757
8231	#####	321698	Suspension - OSF swaybar anti roll bar link rod worn	R/tested and checked front OS sway bar link ball joint worn need to change link	445757
8231	#####	321593	Elec & Light - Bus wont start	Jump started	445757
8231	#####	321404		Tension Wheel Nuts	445641
8231	#####	321404		Perform & Complete PTSV Bus Safety Inspection	445641
8231	#####	321404		Perform & Complete PTSV Bus Safety Inspection	445641
8231	#####	321574	Drv entered - Passenger Doors Other	Checked OK	445757
8231	#####	320416	POS 3 11R NEW	Creditor #BEAD01 BEAUREPARES P/O #G98053 Receiving #98993 Date :2011-09-21	445022
8231	#####	320416	replace worn tyre pos 3	done	444358
8231	#####	320157	Whls & Tyres - NSR low tread	replaced tyre	443908
8231	#####	320158	Body & Acc - Drivers front blind wont stay down	Checked no problem found	443908



8231	#####	304834	Coolant leak on transmission cooler pipe - hose clamp	Secured	416597
8231	#####	304834	Steam clean bus	checked OK	416597
8231	#####	304834	BOD - Replace passenger seats arm rest & hand grips - OS re	Checked OK	416597
8231	#####	304834	BOD - Secure hand rails - rear door top	Checked OK	416597
8231	#####	304834	BOD - Polish exterior panels/headers & touch up paint work	Checked OK	416597
8231	#####	304834	BOD - Adjust rear doors replace top rollers	Checked OK	416597
8231	#####	304834	BOD - Replace emergency exit push button under b/bar	Replaced	416597
8231	#####	304770	Clean a/c filters	Cleaned	416341
8231	#####	304714	Secure dash board	Secured	416341
8231	6/9/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Completed all works	416085
8231	6/9/2011	301473	UNREPORTED - Replace rear bumper bar & paint	Completed all works	416085
8231	6/9/2011	301473	Accident Damaged # 32183 R/R. n/s/r. w/arch brush & trimsn	Completed all works	416085
8231	6/8/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Painted 6 & 7	415829
8231	6/8/2011	301473	UNREPORTED - Replace rear bumper bar & paint	Replaced	415829
8231	6/8/2011	301473	Accident Damaged # 32183 R/R. n/s/r. w/arch brush & trimsn	Painted	415829
8231	6/8/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Painted	415829
8231	6/8/2011	301473	UNREPORTED - Repair & paint front bumper bar and decals	repaired	415829
8231	6/8/2011	301473	ACC - Rear bumper damaged NS	same job	415829
8231	6/2/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Repaired NS 67 panels ready for primer	414289
8231	6/2/2011	301473	UNREPORTED - Replace rear bumper bar & paint	Started repairing	414289
8231	6/2/2011	301473	Accident Damaged # 32183 R/R. n/s/r. w/arch brush & trimsn	Repaired ready for primer	414289
8231	6/2/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Ready for primer	414289
8231	6/1/2011	302495	Adjust rear door	Checked & adjusted rear door	414033
8231	6/1/2011	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Repairing	414033
8231	#####	302035	ROAD SAFETY INSPECTIONS	Creditor #ROAD01 Road Safety Inspections P/O #:G92914 Receiving #:94050 Date :2011-05-31	413777
8231	#####	302035	Annual Inspection -	RWC 583167 - Passed	413264
8231	#####	301765	COMM - No channel 1 on 2way	Checked working OK	412751
8231	#####	302438	Replace Grenda decals x 4	Replaced	412495
8231	#####	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	NS panel 4 c/o	412239
8231	#####	302151	BOD - Secure all lower skit panels	Secured	411983
8231	#####	302151	N/S mud flap missing	Replaced with new	411983
8231	#####	302151	BOD - Replace mud flaps - OSF NSR	Replaced	411983
8231	#####	301473	MUD FLAPS GRENDA MF60X30GRE RED		411983
8231	#####	301473	Accident Damaged # 32183 R/R. n/s/r. w/arch brush & trimsn	Began with repairs c/o	411983
8231	#####	301621	Add coolant	Added	410956
8231	#####	301527	FU - Faulty fuel	Checked OK	410956
8231	#####	301765	COMM - 2way not smart bus	Left 2way until we can find old one	410956
8231	#####	301765	COMM - Radio AM/FM is n/w	Checked n/w	410956
8231	#####	301734	BOD - Paint exterior mirrors and arms	Painted	410956
8231	#####	301734	BOD - Repair drivers blind - 1	Repaired	410956
8231	#####	301734	BOD - Repair & paint till stand	Repaired	410956
8231	#####	301734	BOD - Replace drivers compartment door hinges	Replaced	410956
8231	#####	301473	HINGE DRIVERS COMPARTMENT		410956
8231	#####	301473	UNREPORTED - Replace rear bumper bar & paint	Replaced centre section off 8260 bar still not damaged	410956
8231	#####	301473	UNREPORTED - Repair & paint NS No 5 panel & replace NS No 4	Started making panel no 4	410956
8231	#####	300340	Replace front LH headlight globe	25/03/11 - Replaced by Tulla - \$11.00 inc GST	409159
8231	#####	298857	LED CLEARANCE LIGHT (RED ALMBER)		408389
8231	5/9/2011	299915	Adjust front door sensitive edge	adjusted	408133
8231	5/9/2011	299915	Rear door jammed wont close	Fitted door regulator	408133
8231	5/9/2011	299915	Rear door jammed wont close	Fixed up rear door bus will not move loose connection	408133
8231	5/9/2011	299356	AIR REGULATOR		408133
8231	5/5/2011	299379		Replace power steering filter and check level (Replace oil if required)	407106
8231	5/5/2011	299379		Check oil level in transmission - top up if required	407106
8231	5/5/2011	299379		Inspect radiator and charge air cooler for dirt - clean	407106
8231	5/5/2011	299379		Electrical - Batteries - Check fluid level ( leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	407106
8231	5/5/2011	299379		Replace final drive oil	407106
8231	5/5/2011	299379		Test coolant level - top up if required to equate to 37C frost protection	407106
8231	5/5/2011	299379		Replace angle drive oil	407106
8231	5/5/2011	299379	FUEL FILTER MERC 0500LE		407106
8231	5/5/2011	299379	AIR DRYER CANISTER VOLVO+ NL202		407106
8231	5/5/2011	299379	POWER STEER FILTER B10M		407106
8231	5/5/2011	299379		Replace air dryer cansiter clean silence and drain reservoir	407106
8231	5/5/2011	299379		Replace pre and main fuel filters	407106
8231	5/5/2011	299379		Check and clean cartridge in dry tyre air cleaner	407106
8231	5/5/2011	299379	FUEL FILTER 0500LE		407106
8231	5/5/2011	299366	ANN - Annual Body Inspection		407106
8231	5/5/2011	299356	Front doors not operating correctly	Fixed	407106
8231	5/5/2011	299419	Inspect bus for RSI	Inspected	407106
8231	5/5/2011	299857	Replace clearance light	Replaced	407106
8231	5/3/2011	299166	Sensitive edge on both ddors Faulty	Sens edge on both doors OK - leaking from emergency exit button C/O Job	406593
8231	#####	298972	Front door mechanism is malfunctioning	Refer to Dyon's Defect no - 86394 - Adjust sensitive edge on front and rear doors - Tested working ok both doors opening and closing properly	405566
8231	#####	297777	PD - Doors will not operate correctly	Checked by Branko on service no fault found	402741
8231	#####	297777	Div entered - Passenger Doors Intermittent	Checked by Branko on service no fault found	402741
8231	#####	297617		Tension Wheel Nuts To OEM Specification	402741
8231	#####	297617		A Service & Bus Safety Inspection	402741
8231	#####	297617	AIR FILTER MERC 0500LE		402741
8231	#####	297617		Grease AC Compressor Clutch Bearing	402741
8231	#####	297617		Clean A/C filter	402741
8231	#####	297133	Add coolant	Added	401201
8231	4/7/2011	296831	Add coolant	Added	399917
8231	4/1/2011	295841	Check fault codes	Found problem with driver tampering with door interlock switch and retarder switch	398377
8231	#####	295275	Add coolant	Added	397607
8231	#####	294479	Door valve leaks	Fitted door regulator	396067
8231	#####	294128	Add coolant	Added	395297
8231	#####	293332	BR - Handbrake not always holding	Fit handbrake valve & fit all electric pilu in fuse box	394784
8231	#####	293332	BR - Handbrake not always holding	Stripped fuse box to replace handbrake	394528
8231	#####	293332	a0034307581 PARK BRAKE VALVE	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G89763 Receiving #:90741 Date :2011-03-17 8231	394528
8231	#####	293352	WEDGE GLOBE INSTRUMENT 24V 3W		394015
8231	#####	293503	Bus wont start	Jump started	394015
8231	#####	293332	BR - Handbrake not always holding	Checked handbrake n/w	394015
8231	#####	293352	Replace bottom NSF park light	Replaced	393502
8231	#####	293332	BR - Handbrake not always holding	Rectified r/tested OK	393246
8231	#####	291198	POS 3-4-5-6 11R NEW	Creditor #BEA001 BEAUREPAIRS P/O #:G88971 Receiving #:90452 Date :2011-03-10	392733
8231	#####	292803	STEEL CLAW CATCHES		392733
8231	3/9/2011	292803	COMM - 2way doesn't go on smart bus channel	Checked OK	392477

8231	3/9/2011	292803	BR - Handbrake sometimes not engaging	Changed rear brake pads r/tested changed rear panel lock fixed coolant leak from coolant return pipe	392477
8231	3/9/2011	292803	DISC PADS SCANIA L94+0500 MERC		392477
8231	3/8/2011	292806	Add coolant	Added	392221
8231	#####	291456	GLOBE S/CONTACT 24V-10W		390167
8231	#####	291198	Replace tyre pos 3456	Replaced	389397
8231	#####	291456	Replace globe	REplaced	389397
8231	#####	291130	AIR FILTER MERC 0500LE		389397
8231	#####	291259	WHL - NSR tyres 4mm & O5	Replaced all 4 rear tyres & cleaned rims	389141
8231	#####	291259	WHL - NSR tyres 4mm & O5	Replaced all 4 rear tyres & cleaned rims	389141
8231	#####	291187	Clean a/c filters	Cleaned	389141
8231	#####	291259	Repair air leak at fitting into air tank	Repaired	389141
8231	#####	291128	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	389141
8231	#####	291128		Service T - Replace Transmission Oil & Filter	389141
8231	#####	291128	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF ecofluid A Plus Synthetic Transmission Oil	389141
8231	#####	291128		Bus Safety Inspection	389141
8231	#####	291132	HALDEX COIL KIT 0500LE	Coil Kit	389141
8231	#####	291132	Refitted air separator	Re-kit Air Cyclone Separator	389141
8231	#####	291132	Assisted	Re-kit Air Cyclone Separator	389141
8231	#####	291131	Ref to w/o # 291132	Re-kit Air Cyclone Separator	389141
8231	#####	291132	Removed air separator	Re-kit Air Cyclone Separator	389141
8231	#####	291132	WATER SEPARATOR SCANIA+VOLVO	Water Separator Kit	389141
8231	#####	291132	HALDEX COIL BASE OIL SEPARATOR	Base	389141
8231	#####	291132	DRAIN VALVE KIT BOTTOM	Valve Kit	389141
8231	#####	291130		A Service & Bus Safety Inspection	389141
8231	#####	291130		Clean A/C filter	389141
8231	#####	291130		Grease AC Compressor Clutch Bearing	389141
8231	#####	291130		Tension Wheel Nuts To OEM Specification	389141
8231	#####	291130		A Service & Bus Safety Inspection	389141
8231	#####	290142	Add coolant	Added	387087
8231	#####	289323	STARTER RELAY 24V-300AMP 0500LE		386831
8231	#####	289323	Bus wont start	Checked found broken earth wire near battery repaired tested OK	385575
8231	#####	289446	Starting salonoiid U/S	Changed main battery solenoid started OK when finished turned bus off now bus wont start	385805
8231	#####	289399	Breakdown - Blackburn - OUT 9.00 am BACK 10.15 am - No batt	C/O bus 8261. Found master relay faulty (ordered new waiting)	385549
8231	2/9/2011	289034	Clean a/c filter	Cleaned	385293
8231	#####	286474	Check doors	Checked front & rear NO faults found	380157
8231	#####	286351	Replace dip stick	Replaced	380157
8231	#####	286351	DIP STICK MERCEDES 0500LE		378617
8231	#####	284330	TWO WAY NO POWER	Creditor #:REB001 CIM CONCEPTS P/O #:G87047 Receiving #:88268 Date :2011-01-14	376306
8231	1/5/2011	284330	EN - NO engine oil filter need to replace	Replaced	376306
8231	1/5/2011	284330	COMM - 2way radio not clear	Removed & sent for repairs	376306
8231	1/5/2011	284125	AIR LINE FITTING KIT 0500LE AIR DRYER		376306
8231	1/4/2011	284294	Brake fault	Repaired 4way valve	376050
8231	1/4/2011	284125	AIR - air pres not building	Replaced seals in 4way valve	376050
8231	1/4/2011	284125	AIR - air pres not building	Repaired air leak on air line fitting at 4way valve	376050
8231	1/4/2011	284125	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		376050
8231	#####	284020	Rear door switch n/w	Went to KSB depot Ass Dulkhith	375023
8231	#####	284020	Rear door switch n/w	Went to KSB depot removed switch from bus 8239 and fixed to 8231	375023
8231	#####	283860	back door bus goes while open	Fixed switched off door over ride switch tested OK	374767
8231	#####	283857	BR - Warning light BS 1302 came on in amber	Checked OK	374767
8231	#####	282781	POS 1 11R NEW	Creditor #:BEA001 BEAU REPAIRS P/O #:G86442 Receiving #:87771 Date :2010-12-29	374511
8231	#####	282781	replace worn tyre pos 1	replace worn tyre pos 1	372457
8231	#####	282815	GLOBE 24V 1.2W SWF SWITCH		372457
8231	#####	282879	Add coolant	Added	372457
8231	#####	282841	Replace NS front tyre	Replaced	372201
8231	#####	282813	Random Vehicle Audit	Inspected	372201
8231	#####	282815	Replace BR headlight globe	Replaced	372201
8231	#####	282815	Repair coolant pipe heat shield	Repaired	372201
8231	#####	282815	Fit new speaker cover RHS	Fitted new	372201
8231	#####	282841	Replace bolts in front hand rail	Replaced	372201
8231	#####	282723	AIR FILTER MERC 0500LE		372201
8231	#####	282723		Grease AC Compressor Clutch Bearing	372201
8231	#####	282723	ENGINE OIL BREATHER KIT 0500LE		372201
8231	#####	282723		Replace engine oil breather kit	372201
8231	#####	282723		D-Service & Bus Safety Inspection	372201
8231	#####	282723		A Service & Bus Safety Inspection	372201
8231	#####	282723		Tension Wheel Nuts to Spec	372201
8231	#####	282723	ENGINE OIL DELO 400LE 15W40		372201
8231	#####	282723	OIL FILTER 1725+0500LE		372201
8231	#####	282723		A Service & Bus Safety Inspection	372201
8231	#####	282723		Tension Wheel Nuts To OEM Specification	372201
8231	#####	282723		Grease AC Compressor Clutch Bearing	372201
8231	#####	282723		Clean A/C filter	372201
8231	#####	279789	50A4323 WATER PUMP	Creditor #:MUL001 MULTISPARES LTD P/O #:G84802 Receiving #:87237 Date :2010-12-14 50A4323 -Water pump	370661
8231	#####	281768	Clean graffiti	Cleaned	369634
8231	#####	280151	POS 2 11R NEW	Creditor #:BEA001 BEAU REPAIRS P/O #:G85564 Receiving #:86968 Date :2010-12-08	369121
8231	#####	281141	Front door cannot close sometime cannot open	Checked OK	369121
8231	#####	258733	REPLACE DEACALS N/S	Creditor #:ATT001 ATTITUDE SIGNS P/O #:G78649 Receiving #:86788 Date :2010-12-06	368608
8231	#####	280470	VAN - Graffiti inside	Cleaned	368738
8231	#####	280371	WHL - OSF tyre 4mm	Replaced No 2 tyre & torqued w/nuts	367582
8231	#####	280151	replace worn tyre pos 2	replace worn tyre pos 2	367582
8231	#####	279809	Direct Purchase - MECHANICAL	Creditor #:MUL001 MULTISPARES LTD P/O #:G84802 Receiving #:86259 Date :2010-11-25 Gasket -Water pump	365785
8231	#####	278958	Add coolant	Added	365015
8231	#####	278638	PRESSURE CAP 7BAR 0405+0500LE		364245
8231	#####	278427	AIR - Foot valve leaking	Checked air leak with Neven and found exhaust brake solenoid leaking replaced with another nus & r/tested	363989
8231	#####	278427	AIR - Foot valve leaking	Repaired air leak on exhaust brake solenoid valve r/tested	363989
8231	#####	278427	WIP - Realign wiper arms	Realigned wiper arms	363649
8231	#####	278427	AC - Wiring loose around ac comp	Secured	363649
8231	#####	278427	PD - Front door valves require silencers	Checked OK	363649
8231	#####	277989	A/C BELT 0500 BENZ		363649
8231	#####	277989	BELT BOTTOM ALTERNATOR MERC 0500LE		363649
8231	#####	277989	EN - Engine coolant pump leaking	Completed job	363649
8231	#####	277989	L.E.D.GLOBE FOR SWF SWITCH		363649
8231	#####	277989	AMBER REFLECTOR SIDE MOUNT		363649
8231	#####	278638	Replace radiator cap	Replaced	363649
8231	#####	278427	BR - Park brake valve loose	Tightened	363649

8231	#####	278427	BR - Brake lines rubbing on front axle	Checked OK	363649
8231	#####	278404	BRAK - slight air noise when applying pedal	Checked for air leaks on road	363649
8231	#####	278427	AIR - Foot valve leaking	Cannot find where leak is coming from	363649
8231	#####	278427	AIR - Air leak at 4way protection valve	Checked NO leaks found	363649
8231	#####	277989	VAN - Remove graffiti from seats	Removed	363649
8231	#####	277989	VAN - Slashed rear seat	Replaced	363649
8231	#####	277989	PD - front door open/close erratically	Checked & adjusted door sensors	363649
8231	#####	277989	EN - Engine coolant pump leaking	Replace pump	363649
8231	#####	277989	EL - Reflector missing OS	Replaced	363649
8231	#####	277989	EL - emergency exit light u/s	Checked OK	363649
8231	#####	277989	EL - switch lights n/w	Fitted LEDs	363649
8231	#####	277989	FU - Fuel gauge faulty	Checked OK	363649
8231	#####	277989	BOD - Slashed rear seat	same as	363649
8231	#####	277989	BOD - Replace floor tread at rear	Replaced	363649
8231	#####	277989	BOD - Replace internal license to carry decal	Replaced	363649
8231	#####	277989	BOD - Panels above front door loose	Secured	363649
8231	#####	277989	Repair & polish NS 456	Repaired & polished	363649
8231	#####	277989	BOD - Replace internal emergency exit decal	Replaced	363649
8231	#####	276355	BRAK - when braking stop warning light comes on	same as	360011
8231	#####	276355	ABS light comes on on dash	Checked front & rear brake pads and r/tested OK	360011
8231	#####	274479	COMPRESSOR OIL AIR CON		358180
8231	#####	274479	FILTER DRIER THERMO KING		358180
8231	#####	275466	Adjust rear door	Adjusted	357681
8231	#####	275334	Adjust rear door	Adjusted	357633
8231	#####	275303	Adjust doors sensitive edge	Adjusted	357633
8231	#####	275252	Adjust door sensor	Adjusted	357633
8231	#####	275303	COOL - Coolant pipe at NS of ac comp loose	Tighten up coolant pipe clamp	357633
8231	#####	275303	COOL - Coolant boost pump leaking	Repaired leak on pump	357633
8231	#####	275303	COOL - Coolant leak at heater taps next to trans	Repaired leak on heater taps	357633
8231	#####	274620	PD - Adjust front door closing speed	Assist Adjusted door sensors	356431
8231	#####	274620	PD - Adjust front door closing speed	Check bus wont move and found door brakes not releasing replace sensors switch and adjust door.	356431
8231	#####	274620	PD - Adjust front door closing speed	Adjusted door sensors	356431
8231	#####	274479		D Service	356431
8231	#####	274479		Check boost pump condition	356431
8231	#####	274479		Check & replace electric motor brushes	356431
8231	#####	274479		Replace compressor oil	356431
8231	#####	274479		Replace filter drier	356431
8231	#####	274479		C Service	356431
8231	#####	274479		B Service	356431
8231	#####	274479		Replace filter drier	356431
8231	#####	274479		Replace compressor oil	356431
8231	#####	274479		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	356431
8231	#####	274479		CONDENSOR AREA: Clean condenser coils; check bolts/clamps for tension	356431
8231	#####	274479		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condenser motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condenser fan grills	356431
8231	#####	274479		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	356431
8231	#####	274479		REFRIGERATION FILTER DRIVER: Replace filter dryer; check pump operation;	356431
8231	#####	274479	Compressor cradle is cracked. SSTK warranty	COMPRESSOR: Carry out efficiency tests; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	356431
8231	#####	274479		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	356431
8231	#####	274479		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	356431
8231	#####	274479		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	356431
8231	#####	274479		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	356431
8231	#####	274479		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	356431
8231	#####	273474	POS 1 11R NEW FIT GBS TYRE	Creditor #BEA001 BEAUREPAIRES P/O #G83297 Receiving #84615 Date :2010-10-13	354882
8231	#####	273474	replace worn tyre pos 1	replace worn tyre pos 1	354799
8231	#####	273698	Replace tyre 1	Replaced	354799
8231	#####	272522	Add coolant	Added	351696
8231	#####	272456	Breakdown - Stud Rd & Wellington Rd - OUT 12.30 pm - BACK 1	Used van 619. Checked all bus r/tested OK gave back to operation	351576
8231	#####	271495	Clean a/c filter	Cleaned	350104
8231	#####	262295	Adjust door speed	Adjusted & r/tested	349779
8231	#####	271186	Bus wont start	Jump started	349779
8231	#####	269936	AMBER REFLECTOR SIDE MOUNT		349779
8231	#####	270403	Clean a/c filter	Cleaned	349779
8231	#####	269936	Replace side reflector OS rear	Replaced	349779
8231	#####	269936	Replace Licensed to carry back window	Replaced	349779
8231	#####	269936	Replace emergency exit decal back window	Replaced	349779
8231	#####	269936	Paint new rear bumper NS	Painted & refitted new rear NS b/bar	349779
8231	#####	269936	F/GLASS REAR N/S CORNER BUMPER(LIGHT)		349779
8231	#####	269803	Add coolant	Added	349507
8231	#####	269803	Add coolant	Added	349507
8231	9/9/2010	269272		A Service & Bus Safety Inspection	349054
8231	9/9/2010	269272		Tension Wheel Nuts To OEM Specification	349054
8231	9/9/2010	269272		Grease A/C Compressor Clutch Bearing	349054
8231	9/9/2010	269272		Clean A/C filter	349054
8231	9/8/2010	269060	WATER SEPERATOR SCANIA+VOLVO		348766
8231	9/7/2010	269060	AIR - Air pressure releasing badly from behind RH rear wheel	Rekit water separator and r/tested	348766
8231	9/6/2010	267807	POS 3-4-5-6 11R NEW 2 WORN 2	Creditor #BEA001 BEAUREPAIRES P/O #G81473 Receiving #83035 Date :2010-09-06	347214
8231	#####	267807	replace worn tyres pos 3-4 and fix flat pos 5-6	replace worn tyre pos 3-4 and fix flat pos 5-6	346767
8231	#####	267647	Replace all rear tyres	Replaced all	345485
8231	#####	267584	Remove graffiti	Cleaned	345485
8231	#####	267647	BR - Code in amber BS 5506	r/tested No fault found	345485
8231	#####	267647	ACC - Replace NS 34 panels paint 5 & decals	Checked job has been	345485
8231	#####	267647	ACC - Repair & paint & decal NS 7 panel	Checked job has been done	345485
8231	#####	266601	Add coolant	Added	343451
8231	#####	266055	Add coolant	Added	342342
8231	#####	265747	Add coolant	Added	341909
8231	#####	265313	EL - alt not charging	Put the engine cover inside the bus & under the rear seat fuelled & parked	341792
8231	#####	265313	EL - alt not charging	Removed top alternator wiring and connected wires to bottom alt running OK	341792
8231	#####	265420	SDG4603W 1WAY VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G80763 Receiving #82034 Date :2010-08-12	341792
8231	#####	265420	Fixed air dryer air line air leak adjusted safety valve on a	Re-kit Air Cyclone Separator	341792
8231	#####	265313	EL - alt not charging	Take off alternators put on 1 alternator	341792
8231	#####	265313	EL - alt not charging	Rebuilt alt for bus	341792
8231	#####	265313	EL - alt not charging	Ass Brad with removal of alternators for repair replace bottom alt only	341792
8231	#####	265420	Replaced air dryer unit replaced oil separator unit cleane	Re-kit Air Cyclone Separator	341792
8231	#####	265420	WATER SEPERATOR SCANIA+VOLVO	Water Separator Kit	341792
8231	#####	265420	HALDEX COIL BASE OIL SEPERATOR	Base	341792

8231	#####	265420	DRAIN VALVE KIT BOTTOM	Valve Kit	341792
8231	#####	265420	HALDEX COIL KIT 0500LE	Coil Kit	341792
8231	#####	265282	Add coolant	Added	341792
8231	8/6/2010	262295	HTR - heater n/w	R/tested demister working OK hot	336363
8231	8/6/2010	262295	EL - Battery charge indicator light n/w - checked NO globe	Found under dash	336363
8231	8/6/2010	262295	ELE - battery clip missing	Replaced	336363
8231	8/6/2010	262295	ELE - a/c fault light staying on	Unable to fault	336363
8231	8/6/2010	262295	COMM - Audio speaker damaged	replaced	336363
8231	8/3/2010	262295	Demister n/w	Switch is sticky checked OK	339643
8231	8/3/2010	262295	Saloon light n/w	Replaced globe	339643
8231	#####	263255	COOL - water level warning light comes on sometimes level o	Ref to w/order # 263256	338003
8231	#####	263256	COOL - water level warning light comes on sometimes level o	checked ok	338003
8231	#####	263025	Clean a/c filter	Cleaned	337615
8231	#####	263025	Clean a/c filter	Cleaned	337615
8231	#####	263015	AIR - Rear drivers side air leak	Bring to workshop assist Dulkith to check for air leak	337615
8231	#####	263015	AIR - Rear drivers side air leak	Checked rear airbags & air leak NONE found	337615
8231	#####	262598	Check for brakes coming on	Repaired by Dysons 14/05/10. Found leaking engine brake solenoid No repairs carried out at this stage. Total cost \$ 75.00	336804
8231	#####	262297	VAN - graffiti on back window	Cleaned graffiti	335998
8231	#####	262145	Add coolant	Added	335591
8231	#####	262145	Add coolant	Added	335591
8231	#####	260859	15AMP BLADE FUSE		334450
8231	#####	261560	Add coolant	Added	334112
8231	#####	261560	Add coolant	Added	334112
8231	7/9/2010	261701	BOD - Polish OS rear window glass - KNIGHTS	Polished	334450
8231	7/7/2010	260285	GLOBE S/CONTACT 24V-10W		332196
8231	7/7/2010	260285	CLEANED AIR FILTER MERC 0500LE		332196
8231	7/6/2010	260859	ELE - replace globe in bus stopping sign	replaced globe	332943
8231	7/6/2010	260858	BODY - replace yellow anti slip rubber	replaced	332943
8231	7/6/2010	260285		Clean A/C filter	332196
8231	7/6/2010	260285	Service	A Service & Bus Safety Inspection	332196
8231	7/6/2010	260285		Tension Wheel Nuts To OEM Specification	332196
8231	7/6/2010	260285		Grease AC Compressor Clutch Bearing	332196
8231	7/6/2010	260285		A Service & Bus Safety Inspection	332196
8231	7/5/2010	260724	Bus wont start	Jump started	332615
8231	7/5/2010	260724	Bus wont start	Jump started	332615
8231	7/2/2010	258225	WATER SEPERATOR SCANIA+VOLVO		329628
8231	7/2/2010	258225	DRAIN VALVE KIT BOTTOM		329628
8231	7/1/2010	260201	COOL - Incorrect coolant dosages	Fixed coolant rekit air separator	332196
8231	7/1/2010	260201	COOL - Incorrect coolant dosages	Fitted overhauled water separator & fitted new seals to air pipe on 4way protection valve	332196
8231	#####	258225	Service	Overhaul air separator remove air separator clean parts c/o	329628
8231	#####	260198	VAN - Drv entered - Vandalism Graffiti	Cannot remove scratched into window	332196
8231	#####	260084	BD - split heater hose @ Ringwood Stn. - actioned to Invicta		332196
8231	#####	260201	COOL - Incorrect coolant dosages	drain coolant c/o	332196
8231	#####	260201	COOL - Incorrect coolant dosages	Fix coolant line replace cooler tap (not finished)	332196
8231	#####	260262	Grendas driver reported low coolant light on. Mechanic sent	Travel to Ringwood and check for low coolant light on. Heater hose above trans split. Turn off heater taps and top up coolant. Ok to return to depot	332196
8231	#####	260084	VALVE BALL 1/2 HEATER		332196
8231	#####	259161	ROAD SAFETY INSPECTIONS	Creditor # :ROA001 Road Safety Inspections P/O #:G78875 Receiving #:80326 Date :2010-06-29	331789
8231	#####	259161	annual inspection -	Passed - BC 125035	330487
8231	#####	259161	annual inspection -	Passed	330487
8231	#####	258992	Adjust tyre pressure	Adjusted	331584
8231	#####	258225	GLOBE INDICATOR 24V-18W SINGLE CONTACT		329628
8231	#####	258225	INDICATOR LAMP SUIT B12BLE		329628
8231	#####	258733	Repairs to NS roof air intake bracket	Prep & repainted n/s 3 due to colour difference painted n/s/r corner roof fibre glass section	329747
8231	#####	258733	BOD - Drivers seat - replace cushion	Replaced	329747
8231	#####	258772	BR - Brake problem shakes the bus	GB ECU reprogrammed by Mercedes	329747
8231	#####	258733	ACC - Repair lower rear door stainless steel panel	Replaced	329747
8231	#####	257460	POS 4 11R NEW FLAT	Creditor # :BEA001 BEAUREPARES P/O #:G78274 Receiving #:79970 Date :2010-06-18 R	329747
8231	#####	258619	The TIM machine has no power	Given to control room	329747
8231	#####	258733	BOD - Replace exit only on rear doors	Replaced	329747
8231	#####	258733	BOD - Secure fit timetable holder	Checked found OK	329747
8231	#####	258733	Repairs to NS roof air intake bracket	Began repairs applied fibre filler and body filler painted grey primer	329747
8231	#####	258733	BOD - Destination blind - security - door	Secured	329747
8231	#####	258733	BOD - Clean graffiti - floor seats & side walls	Cleaned	329747
8231	#####	258733	BOD - Replace emergency exit decals with safety hammers	Replaced	329747
8231	#####	258733	BOD - Rear step edges replace or fit inserts - rear	Refitted	329747
8231	#####	258733	Paint exterior mirrors and arms	Painted	329747
8231	#####	258733	BOD - Secure ticket machine stand	Secured	329747
8231	#####	258733	BOD - Replace interior decals - priority seating	Replaced	329747
8231	#####	258733	BOD - Grendas name address & weight - OSF No 1 panel - rem	Removed	329747
8231	#####	258733	BOD - Replace side reflectors - NS	Replaced	329747
8231	#####	258733	BOD - Clean air condition filter secure vents	Cleaned	329747
8231	#####	258733	BOD - Fit end caps to seat frames	Fitted	329747
8231	#####	258733	BOD - Paint tilt stand	Painted	329747
8231	#####	258733	BOD - Replace licensed to carry (No) seat (No) adult passen	Replaced	329747
8231	#####	258733	BOD - Replace emergency exit push button under panel	Replaced	329747
8231	#####	258733	BOD - Polish exterior panels/headers & touch up paint work	Polished	329747
8231	#####	258733	BOD - Secure fit timetable holder	Secured	329747
8231	#####	258733	BOD - N/S front wheel brush needs replacing	Replaced	329747
8231	#####	258733	BOD - Secure all lower skit panels	Secured	329747
8231	#####	258733	CENTRA SEAT EVD CAPS	258733	329747
8231	#####	258733	15LTR RUBBISH BINS	258733	329747
8231	#####	258733	CUSHION FOAM S17	258733	329747
8231	#####	258733	AMBER REFLECTOR SIDE MOUNT	258733	329747
8231	#####	258733	2MM X 1200MM X 2400MM FLAT ALUMINIUM	258733	329747
8231	#####	258733	BOD - Replace exit only on rear doors	Replaced	329747
8231	#####	258733	ACC - Repair lower rear door stainless steel panel	Removed panel	329747
8231	#####	258733	Accident Damaged # 30606 Repair o/s/f. bumper-bar cornera/	Began repairs	329747
8231	#####	258733	Accident Damaged # 30758 R/R. Front bumper-baro/s. No 1 el	Began repairs	329747
8231	#####	258450	PD - Back door opening	Adjusted sensitive edge	329747
8231	#####	258450	PD - Back door opening	Adjusted sensitive edge	329747
8231	#####	258225	INDICATOR LAMP SUIT B12BLE		329628
8231	#####	258225	POWER STEER FILTER B10M		329628
8231	#####	258225	AIR DRYER CANISTER VOLVO+ NL202		329628
8231	#####	258225	FUEL FILTER 0500LE		329628
8231	#####	258225	FUEL FILTER MERC 0500LE		329628



8231	#####	247045	Clean a/c filter	Cleaned	314732
8231	3/9/2010	246849	DOWN LIGHT LED		313830
8231	3/6/2010	246849	Replace downlight	Replaced	313830
8231	3/2/2010	245971	AIR 5 - Losing air when handbrake applied	removed air dryer and overhaul fitted bus working o/k bus exhaust soc badly cracking check air dryer again	312595
8231	3/2/2010	245971	AIR 5 - Losing air when handbrake applied	fixed air dryer control valve	312595
8231	3/1/2010	257415	MIL LIGHT STILL ON	Creditor #WHHT001 WHITEHORSE TRUCKS P/O #G78270 Receiving #81350 Date :2010-07-28	334840
8231	3/1/2010	362078	BALD - New - 11.00R 22.5 - pos	Creditor #BEAD01 BEAUREPARES P/O #G110493 Receiving #110996 Date :2012-07-05 Replace with new	514363
8231	3/1/2010	246028	Front door wont close	Repaired front door and checked	312595
8231	3/1/2010	246028	Front door wont close	Checked front door not shutting changed air switch on bumper bar	312595
8231	3/1/2010	246028	Front door wont close	Repaired front door and checked	312595
8231	3/1/2010	262295	rotron boost pump	Creditor #SOU005 SOUTHERN STATES THERMO KING P/O #G79391 Receiving #80994 Date :2010-07-19 231	336363
8231	3/1/2010	262295	FREIGHT	Creditor #SOU005 SOUTHERN STATES THERMO KING P/O #G79391 Receiving #80994 Date :2010-07-19	336363
8231	3/1/2010	261701	REPAIR W/SCREEN	Creditor #KN001 KNIGHTS WINDSCREEN REPAIRS P/O #G79719 Receiving #80990 Date :2010-07-19	336363
8231	3/1/2010	260084	hose as required	Creditor #CON001 CONSOLIDATED BEARING CO. P/O #G79039 Receiving #80796 Date :2010-07-13 8231	334450
8231	3/1/2010	255669	CHECK BRAKE FAULT	Creditor #SWHT001 WHITEHORSE TRUCKS P/O #G78063 Receiving #80692 Date :2010-07-09	333568
8231	3/1/2010	245971	DIRECT BRAKES	Creditor #MU001 MULTISPARES LTD P/O #G75214 Receiving #76710 Date :2010-03-01	312595
8231	3/1/2010	245971	AIR 5 - Losing air when handbrake applied	Replaced regulator valve replaced air dryer canister rekit bottom part of the air dryer	312595
8231	3/1/2010	245971	SINGLE AIR DRYER KIT 0500LE		312595
8231	3/1/2010	245971	AIR DRYER CANISTER VOLVO+ NL202		312595
8231	3/1/2010	245971	CLIPPARD VALVE DOOR OPEN/CLOSE		312595
8231	#####	246028	Front door wont close	Checked sensors door button still wont close	312595
8231	#####	245463	Clean a/c filter	Cleaned	311188
8231	#####	242740	POS 3 11R NEW	Creditor #BEAD01 BEAUREPARES P/O #G74398 Receiving #76391 Date :2010-02-18	309493
8231	#####	244416	32MM LOOSE WHEEL NUT INDICATOR		308745
8231	#####	244551	Add coolant	Added	308469
8231	#####	244416		A Service & Bus Safety Inspection	308455
8231	#####	244416		Tension Wheel Nuts To OEM Specification	308455
8231	#####	244416		Grease AC Compressor Clutch Bearing	308455
8231	#####	244416		Clean A/C filter	308455
8231	#####	244416		A Service & Bus Safety Inspection	308455
8231	#####	244740	Bus bouncing on suspension	Replaced leaking valve on air tank	308455
8231	#####	244050	Clean a/c filter	Cleaned	307593
8231	2/9/2010	243901	Add coolant	Added	307265
8231	2/4/2010	242118	LH DRILL BIT 6MM AND 8MM	Creditor #ECO001 ECONOMY BOLT CO. P/L P/O #G74236 Receiving #75988 Date :2010-02-04	305171
8231	2/1/2010	242860	Replace tyre No 3	Replaced & torqued w/nuts	304457
8231	2/1/2010	242860	Replace tyre No 3	Replaced	304010
8231	2/1/2010	242860	Replace tyre No 3	Replaced	304010
8231	2/1/2010	242860	Replace tyre No 3	Replaced	304010
8231	2/1/2010	242740	Replace tyre pos 3 - punctured	Replaced	303202
8231	#####	242486	Secure emergency button	Secured button	302798
8231	#####	242384	Add coolant	Added	302798
8231	#####	242118	Remove alt belt	Drill out broken bolt on alt bracket	302588
8231	#####	242118	ALTERNATOR SPECIAL BOLT		302588
8231	#####	242118	Remove alt belt	Removed alternator fit new bolt to alternator bracket fit alt and belts fuelled & parked	302588
8231	#####	242118	Remove alt belt	help Phil remove alt and bracket bolt broken remove 2 broken studs.	302588
8231	#####	242118	Remove alt belt	remove alt and bracket bolt broken remove 2 broken studs.	302588
8231	#####	242115	MERC ALTERNATOR BELT TOP 0500LE (A39)		301588
8231	#####	242115	Breakdown Wellington Road Mulgrave. Broken alt. belt. Ou	Change over bus 227 jump start bus disconnect door over ride switch. (removed broken alt bracket and two broken studs.)	302588
8231	#####	241168	POS 6 11R225 NEW	Creditor #BEAD01 BEAUREPARES P/O #G73901 Receiving #75578 Date :2010-01-19	301521
8231	#####	241604	Clean a/c filter	Cleaned	301521
8231	#####	241168	Replace tyre pos 6 - bald	Replaced	299554
8231	#####	241022	PUMP WIPER-WASHER 24 VOLT		299554
8231	#####	241209	Replace windscreen washer	Replaced	299554
8231	#####	241209	Change O/S rear tyres	Replaced	299554
8231	#####	239502	POS 6	Creditor #BEAD01 BEAUREPARES P/O #G73525 Receiving #75406 Date :2010-01-13	299554
8231	#####	241209	Remove graffiti from rear	Removed	299554
8231	#####	241022	AIR FILTER MERC 0500LE		299554
8231	#####	241022		Service T - Replace Transmission Oil & Filter	299554
8231	#####	241022	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	299554
8231	#####	241022		Bus Safety Inspection	299554
8231	#####	241022	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	299554
8231	#####	241022		Clean A/C filter	299554
8231	#####	241022		A Service & Bus Safety Inspection	299554
8231	#####	241022		Tension Wheel Nuts To OEM Specification	299554
8231	#####	241022		Grease AC Compressor Clutch Bearing	299554
8231	#####	240793	clean a/c filters	cleaned filters	298785
8231	1/5/2010	240233	adjust rear door	adjusted rear door sensitive edge	297478
8231	1/5/2010	240170	coolant top up	coolant top up	297478
8231	1/2/2010	239967	replace alternator belt (top)	replaced.	297072
8231	1/2/2010	239967	MERC ALTERNATOR BELT TOP 0500LE (A39)		297072
8231	#####	239786	Retarder blocking more coming when is full of passengers	R/tested bus but did not find a fault	296200
8231	#####	239502	Replace tyre pos 6 - punctured	Replaced	294766
8231	#####	239542	Change o/s rear tyre	Changed	295172
8231	#####	239063	WIPER REFILL SUIT TX800-TX900		293237
8231	#####	239063	L/H side windscreen wiper needs replacing	Changed the blade and adjusted washer	293237
8231	#####	238843	Clean a/c filter	Cleaned	292546
8231	#####	238176	Add coolant	Added	289875
8231	#####	238016	Door interlock n/w	Checked out rear door found override switch under dash on	289722
8231	#####	238064	Replace belt	Replaced	289722
8231	#####	238064	Replace belt	Replaced main belt	289722
8231	#####	238064	A/C BELT 0500 BENZ		288975
8231	#####	238016	Back door need to be fix you can drive this bus with back	Turned switch off working OK	289722
8231	#####	237819	Add coolant	Added	289004
8231	#####	237770	Wiper blade broken	Replaced wiper blade and adjusted	289004
8231	#####	237770	BLADE WIPER 1MTR		289004
8231	#####	237781	Drv entered - Brakes Other	Checked OK	289004
8231	#####	237442	A/C belt u/s	Checked OK	288134
8231	#####	237333	Check retarder	Ref to w/order # 237442	288134
8231	#####	237442	RET accumulator solenoid leaking air	Replaced accumulator valve	288134
8231	#####	237442	ACCUMULATOR RETARDER VALVE 812BLE		288134
8231	#####	237442	O RING VALVE TO RESERVOIR 7MM X 2MM ZF		288134
8231	#####	237189	GAS STAY 450N 710MM EXT LENGTH	Creditor #JUN001 UNIVERSAL ENG. SUPPLIES P/L P/O #G72608 Receiving #74335 Date :2009-12-02	288134
8231	#####	237333	Retarder cuts in & out violently when braking almost puts p	R/tested checked retarder working but needs new solinoid leaking air	288134
8231	#####	237144	Clean a/c filter	Cleaned	287802
8231	#####	237189	Door not working	Fit terminals to electrics in door	287802

8231	#####	237092	Adjust wiper arm	Adjusted	287798
8231	#####	237092	front door sensitive edge n/w	Adjusted front door air controls	287798
8231	#####	237051	Random order oudit	Inspected at service	287798
8231	#####	237069	AMBER REFLECTOR SIDE MOUNT		287802
8231	#####	237069	Replace side reflector	Replaced	287798
8231	#####	237069	Clean radiator	S/cleaned	287802
8231	#####	237069	Clean radiator	S/cleaned	287798
8231	#####	237075	Change gas struts for engine bay hatch	Changed	287798
8231	#####	236650	COMP PIPE HOSE	Creditor # :ENZ001 Enzed Dandenong P/O #:G72649 Receiving #:74185 Date :2009-11-30	287798
8231	#####	236975		A Service & Bus Safety Inspection	287802
8231	#####	236975		Grease AC Compressor Clutch Bearing	287798
8231	#####	236975		Clean A/C filter	287798
8231	#####	236975		A Service & Bus Safety Inspection	287798
8231	#####	236975		Tension Wheel Nuts To OEM Specification	287798
8231	#####	236652	Check rear door	Checked and adjusted rear door sensor	286709
8231	#####	236650	Bus wont move brakes locked on	Removed and fitted new compressor pipe	286709
8231	#####	236468	clean graffiti	cleaned graffiti	286321
8231	#####	236330	ALTERNATOR BOLT BOTTOM		285917
8231	#####	236330	A/C BELT 0500 BENZ		285917
8231	#####	236330	Change main water pump belt	Changed	285610
8231	#####	235460	Drv entered - Wipers & Washers Other	Cleaned jets and adjusted wipers	284062
8231	#####	235460	Water for wipers please	Fitted washer motor	284062
8231	#####	235460	Clean graffiti	Cleaned	283476
8231	#####	235460	replace yellow strip	Replaced	283476
8231	#####	234309	Add coolant	Added	279908
8231	#####	234301	Clean graffiti off rear of bus	Cleaned	279908
8231	#####	234301	GLOBE HIGH BEAM 24V70W H1		279908
8231	#####	234301	R/H headlight out	Replaced both globes battled with screws	279908
8231	#####	233893		Grease AC Compressor Clutch Bearing	278818
8231	#####	233893		Tension Wheel Nuts To OEM Specification	278818
8231	#####	233893		A Service & Bus Safety Inspection	278818
8231	#####	233893		A Service & Bus Safety Inspection	278818
8231	#####	233893		Clean A/C filter	278818
8231	#####	233436	Clean a/c filter	Cleaned	276448
8231	#####	233362	add coolant	added coolant	276448
8231	#####	233185	Service	replaced drag link nut	276448
8231	#####	233185	repair g/box retarder	repair g/box retarder air hose air leak.	276336
8231	#####	232918	MERC ALTERNATOR BELT TOP 0500LE (A39)		276336
8231	#####	232918	fan belt broken dash light on	replace alternator belt fuel and park	276115
8231	#####	232630	add coolant	added coolant	276115
8231	#####	232525	A0019905451 NUT B/JOINT	Creditor # :SWHT001 WHITEHORSE TRUCKS P/O #:G71411 Receiving #:73029 Date :2009-10-20	276115
8231	#####	232525	A0024600148 ball joint drag li	Creditor # :SWHT001 WHITEHORSE TRUCKS P/O #:G71411 Receiving #:73029 Date :2009-10-20	276115
8231	#####	232525	Drag link ball joint u/s	replaced.	276115
8231	#####	232525	SNAP ON SILENCER A/DRYER		276115
8231	#####	232525	Check noise on drive train - diff checked OK	road tested and found air dryer exhaust making noise replaced air dryer silencer.	276115
8231	#####	232525	Overhead ticket light dull need extra one fitted above till	checked ok.	276115
8231	#####	232525	transmission coolant pipe banjo coolant leak	re tight banjo nut	276115
8231	#####	232422		C Service	275512
8231	#####	232422		B Service	275512
8231	#####	232422		Replace filter drier	275512
8231	#####	232422		Replace compressor oil	275512
8231	#####	232422		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	275512
8231	#####	232422		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	275512
8231	#####	232422		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	275512
8231	#####	232422		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	275512
8231	#####	232422		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	275512
8231	#####	232422		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	275512
8231	#####	232422		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	275512
8231	#####	232422		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	275512
8231	#####	232422		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	275512
8231	#####	232422		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	275512
8231	#####	232422		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	275512
8231	#####	232732	top up coolant	top up	275512
8231	#####	232422	FILTER DRIER THERMO KING		275113
8231	#####	230417	POS 6 11R225 NEW FLAT	Creditor # :BEA001 BEAUREPAIRS P/O #:G70839 Receiving #:72906 Date :2009-10-15	275104
8231	#####	231745	add coolant	added coolant	273113
8231	#####	231418	Replace Damage O/S Wiper Blade	Wrong bus.	272661
8231	#####	229687	POS 2 11R225 NEW	Creditor # :BEA001 BEAUREPAIRS P/O #:G70653 Receiving #:72582 Date :2009-10-01	270862
8231	#####	229302	POS 1 11R225 NEW FLAT	Creditor # :BEA001 BEAUREPAIRS P/O #:G70510 Receiving #:72574 Date :2009-10-01	270862
8231	#####	230663	Wheel chair ramp - edging broken	checked OK	270337
8231	#####	230607		D-Service & Bus Safety Inspection	270337
8231	#####	230607		A Service & Bus Safety Inspection	270337
8231	#####	230607		Tension Wheel Nuts to Spec	270337
8231	#####	230607			270337
8231	#####	230607		Grease AC Compressor Clutch Bearing	270337
8231	#####	230607		Grease AC Compressor Clutch Bearing	270337
8231	#####	230607		Clean A/C filter	270337
8231	#####	230607		A Service & Bus Safety Inspection	270337
8231	#####	230607		Tension Wheel Nuts To OEM Specification	270337
8231	#####	230491	Replace # 6 tyre	Replaced	270097
8231	#####	230491	Replace # 6 tyre	Changed	270097
8231	#####	230491	Replace # 6 tyre	Replaced	270097
8231	#####	230417	repair flat tyre pos 6	Replaced	270097
8231	#####	229687	Replace tyre pos 2 - air leak	Replaced	270097
8231	#####	229755	Change tyre pos 2	Changed	267656
8231	#####	229302	Replace tyre pos 1 - punctured	Replaced	267656
8231	#####	229343	Replace tyre # 1	Replaced & torqued w/nuts	266639
8231	#####	229343	Replace tyre # 1	Replaced	266639
8231	#####	229343	Replace tyre # 1	Replaced	266639
8231	#####	229343	Replace tyre # 1	Replaced	266639
8231	#####	229461	Adjust back door sensors	Adjusted	266639
8231	#####	229099	Drv entered - Passenger Doors Slow	Repaired by Volgren	266480
8231	#####	229099	Drv entered - Passenger Doors Slow	Repaired by Volgren	266480
8231	#####	229099	Rear door switch or something because you have to open and	Repaired by Volgren	266480

8231	9/8/2009	228655	Leaking air behind back door	Checked OK	264610
8231	9/8/2009	228466	Rear doors not shutting have to keep pressing the button	Repaired by Volgren	264803
8231	9/8/2009	228467	Ops Entered - Passenger doors - 2-Road Defect Unaffected Serv	Repaired by Volgren	264412
8231	9/8/2009	228467	Rear door not good open	Repaired by Volgren	264610
8231	9/7/2009	228408	Rear door playing up have to push button many times before i	Adjusted sensitive edge sensor	264412
8231	9/7/2009	228395	Add coolant	Added	264412
8231	9/4/2009	228302	Back door has trouble closing	Adjusted door ram	263516
8231	9/2/2009	227891	Drv entered - Passenger Doors Not Operating	Adjusted OK	262931
8231	9/2/2009	227891	Drv entered - Passenger Doors Not Operating		262931
8231	9/2/2009	227891	Drv entered - Passenger Doors Slow	Adjusted OK	262931
8231	9/2/2009	227891	Drv entered - Brakes Other		262931
8231	9/1/2009	227891	Adjust rear door	Adjusted	262616
8231	#####	227589		Clean A/C filter	261406
8231	#####	227589		Grease AC Compressor Clutch Bearing	261406
8231	#####	227589		Tension Wheel Nuts To OEM Specification	261406
8231	#####	227589		A Service & Bus Safety Inspection	261406
8231	#####	227589		A Service & Bus Safety Inspection	261406
8231	#####	227589	AIR FILTER MERC 0500LE		262248
8231	#####	227411	Rear door wont close	Found broken air line repaired	261124
8231	#####	227411	Rear door wont close	Assist mech fixing rear door	261124
8231	#####	227304	Ops Entered - Breakdown - 3-Change Over Other Request - Ro	Ops changed bus over	260720
8231	#####	227304	Ops Entered - Fault - Brakes - Route: 900 - Brandon Park D	Ops chaged bus over	260720
8231	#####	227012	Add coolant	Added	260071
8231	#####	226737	Brakes sometimes appear to grab rev counter drops to zero	Check air leaks- none check disc brake OK bus rotor has a ridge r/tested Could not find fault as described	259032
8231	#####	225863	Add coolant	Added	255549
8231	#####	224850	Change N/S indicator globe	Changed	252974
8231	#####	224850	GLOBE S/CONTACT 24V-10W		253060
8231	#####	224747		A Service & Bus Safety Inspection	252974
8231	#####	224747		Tension Wheel Nuts To OEM Specification	252974
8231	#####	224747		Grease AC Compressor Clutch Bearing	252974
8231	#####	224747		Clean A/C filter	252974
8231	#####	224747		A Service & Bus Safety Inspection	252974
8231	#####	224640	Add oil	Added	252521
8231	#####	224598	Bus wont move	Checked bus found driver switched electro brake on fuelled bus	252274
8231	#####	224449	Breakdown - Warragul Rd - OUT 8.45 pm BACK 10.45 pm - Door	C/O bus 114. Turned off the 2 override switches & returned to depot	251906
8231	#####	224243	Add coolant	Added	251496
8231	#####	224243	Coolant leak	Repaired	251496
8231	#####	224243	Coolant leak	Tightened hose clamp and filled coolant	251906
8231	#####	224205	Wipers stopped & started when on high a few times	Adjusted wipers	251496
8231	#####	223483	Add coolant	Added	249497
8231	#####	222680	Ops Entered - Fault - Air Cond - Route: 901 - Dandenong St	Commission test bus OK r/tested bus OK cleaned return air filter	247220
8231	#####	222415	Ops Entered - Fault - Passenger Doors - Route: 901 - Kirkh	Repaired front door	247319
8231	#####	222415	Ops Entered - Fault - Passenger Doors - Route: 901 - Kirkh	Repaired front door	247220
8231	#####	222415	Drv entered - Passenger Doors Intermittent	Checked	247220
8231	#####	222415	Drv entered - Air System Leaking	Replaced front middle relay valve	247220
8231	#####	222415	Drv entered - Air System Leaking	Repaired coolant leak from heater hose	247220
8231	#####	222415	Drv entered - Air System Leaking	Replaced front middle relay valve	247319
8231	#####	222415	50G1405 RELAY VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G68398 Receiving #70178 Date :2009-07-10	247220
8231	7/8/2009	222448	Add coolant	Added	247220
8231	7/8/2009	222415	Drv entered - Air System Leaking	Removed front brake relay valve & ordered parts	247220
8231	7/7/2009	222351	Remove graffiti	Removed	246900
8231	7/7/2009	222415	Drv entered - Air System Leaking	Checked for air leak	247220
8231	#####	221073	ROAD SAFETY INSPECTIONS	Creditor #ROAD01 Road Safety Inspections P/O #G68015 Receiving #6986 Date :2009-06-30	245011
8231	#####	221588	Front door playing up & not closing when you push button	Checked out front door unable to fault	244408
8231	#####	221588	Ops Entered - Fault - Passenger Doors - Route: 901 - Dand	Unable to fault	244408
8231	#####	221609	Replace alternator belt	Fitted alternator belt	244408
8231	#####	221609	Replace alternator belt	Assist mechanic with belt	244408
8231	#####	221609	MERC ALTERNATOR BELT TOP 0500LE (A39)		244408
8231	#####	221609	Replace alternator belt	Assist mechanic with belt	244408
8231	#####	221073	Annual inspection - BC 134488	Annual inspection - BC 134488	243591
8231	#####	221364	Replace globes in Bus Stopping signal	Replaced	243816
8231	#####	220742	Coolant leaking through radiator hose near angle drive	Secured radiator hose	243816
8231	#####	220742	Adjust alternator belt	Adjusted belt & fixed bolt on radiator panel	243816
8231	#####	221255	Demister ducts - drivers	Replaced demister ducts	243816
8231	#####	221255	Safety triangles and decals - replace	Replaced decals	243816
8231	#####	220742	Brake pedal pad worn	Changed pedal pad	242327
8231	#####	221294		Tension Wheel Nuts To OEM Specification	243816
8231	#####	221294		Grease AC Compressor Clutch Bearing	243816
8231	#####	221294		Clean A/C filter	243816
8231	#####	221294		A Service & Bus Safety Inspection	243816
8231	#####	221294	GLOBE INST 24V 2W		243816
8231	#####	221294		A Service & Bus Safety Inspection	243816
8231	#####	221225	Add coolant	Added	243591
8231	#####	220742	Wiper arms need to adjust for self stop	Adjusted	243063
8231	#####	220742	LED FRONT POSITION MARKER LIGHT		243063
8231	#####	220742	Boost pump top hose connection leaking	Secured	243063
8231	#####	220742	Steamclean the bus	Cleaned	243063
8231	#####	220742	Coolant leaking through hose connecting to g/box cooler pipe	Secured	243063
8231	#####	220861	Add coolant	Added	243063
8231	#####	220535	Paint exterior mirrors and arms	Painted	242326
8231	#####	220535	Clean air condition filter secure vents	Cleaned	243063
8231	#####	220535	Secure all lower skit panels	Secured	243063
8231	#####	220535	Grind flat exhaust bracket N/S rear	Repaired	243063
8231	#####	220535	Touch up paint work		243063
8231	#####	220535	Replace wheel arch rubber - N/S front	Replaced	243063
8231	#####	220535	N/F wheel arch brush missing	Replaced	243063
8231	#####	220742	BRAKE+ CLUTCH PEDAL PAD 0500LE		243063
8231	#####	220535	Air duct hoses need to be fixed near inter cooler	Secured	243183
8231	#####	220535	Air duct hoses need to be fixed near inter cooler	Secured	243063
8231	#####	220535	Rear N/S bumper damaged	Repaired	242326
8231	#####	220535	Rear N/S bumper damaged	Replaced rear N/S corner	243183
8231	#####	220535	Repair & paint N/S front top header	Repaired	243063
8231	#####	220535	Polish N/S rear lower panels	Polished	243063
8231	#####	220535	RED REFLECTOR 94X44MM		243063
8231	#####	220724	Add coolant	Added	242327

8231	#####	220621	P.T.I Inspection	242326
8231	#####	220621	Replace angle drive oil	242326
8231	#####	220621	Replace air dryer canister clean silence and drain reservoir	242326
8231	#####	220621	POWER STEER FILTER B10M	242326
8231	#####	220621	AIR DRYER CANISTER VOLVO+ NL202	242326
8231	#####	220621	FUEL FILTER 0500LE	242326
8231	#####	220621	FUEL FILTER MERC 0500LE	242326
8231	#####	220621	WATER SEPERATOR SCANIA+VOLVO	242326
8231	#####	220621	Replace final drive oil	242326
8231	#####	220621	P.T.I Inspection	242327
8231	#####	220621	Check and clean cartridge in dry tyre air cleaner	242326
8231	#####	220621	Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	242326
8231	#####	220621	Check oil level in transmission - top up if required	242326
8231	#####	220621	Inspect radiator and charge air cooler for dirt - clean	242326
8231	#####	220621	Electrical - Batteries - Check fluid level ( leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	242326
8231	#####	220621	Overhaul air seperator	242326
8231	#####	220621	ROCKER COVER GASKET 0500LE	242327
8231	#####	220621	Replace power steering filter and check level (Replace oil if required)	242326
8231	#####	220621	Adjust engine valve clearances 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	242326
8231	#####	220621	Test coolant level - top up if required to equate to 37C frost protection	242326
8231	#####	220621	Replace pre and main fuel filters	242326
8231	#####	220523	Annual body inspection	241656
8231	#####	220535	Paint till stand	242326
8231	#####	220535	Replace emergency exit decals with safety hammers	242326
8231	#####	220535	Replace Licensed to carry (No) seat (No) adult passengers	242326
8231	#####	220535	Clean graffiti - floor seats side walls	242326
8231	#####	220535	Safety triangles and decals - replace	242326
8231	#####	220535	Demister ducts - drivers	242326
8231	#####	220535	Destination blind - security	242327
8231	#####	220535	F/GLASS REAR N/S BUMPER CORNER	242326
8231	#####	220535	Replace Exit Only on rear doors	242326
8231	#####	220535	Replace safety triangle decal	242326
8231	#####	220535	Repair & paint N/S rear corner	242327
8231	#####	220535	HESS DEMISTER OUTLET	242326
8231	#####	220535	SAFETY TRIANGLE DECAL	242326
8231	#####	220460	Clean graffiti off rear of bus	241656
8231	#####	220460	Change rear door sensor	241656
8231	#####	220460	Change rear door sensor	241656
8231	#####	220387	Add coolant	241656
8231	#####	220422	Breakdown - Princes Hwy/ North Rd Oakleigh - OUT 6.00 pm BA	241656
8231	#####	220422	Adjusted rear door sensor	241656
8231	#####	218685	POS 3-4 11R225 NEW	241266
8231	#####	220341	Faulty back door	241266
8231	#####	220341	Ops Entered - Fault - Passenger Doors - Route: - Change o	241266
8231	#####	220188	Yellow rubber rear back floor - loose	240911
8231	#####	220047	Check rear door opens/shut very quickly	240007
8231	#####	219966	Add coolant	240007
8231	6/9/2009	219786	Add coolant	239153
8231	6/8/2009	219721	Adjust rear door sensor	238970
8231	6/7/2009	219708	Replace front brake pads	238970
8231	6/7/2009	219708	DISC PADS SCANIA L94+0500 MERC	238970
8231	6/2/2009	219200	Add coolant	237413
8231	6/1/2009	219070	Add coolant	237029
8231	#####	218855	Add coolant	236625
8231	#####	218685	Replace tyre pos 34 - worn	236345
8231	#####	218634	Change N/S/R both wheels	236335
8231	#####	218634	Change N/S/R both wheels	236345
8231	#####	218634	Coolant leak from transmission cooler pipe	236335
8231	#####	218634	GEARBOX COOLANT PIPE MERCEDES BENZ 0500	236345
8231	#####	218634	Coolant leak from transmission cooler pipe	236345
8231	#####	218634	Air leak near transmission accumulator	236335
8231	#####	218175	Front door switch not working properly	234827
8231	#####	218176	A Service & Bus Safety Inspection	234827
8231	#####	218176	Tension Wheel Nuts To OEM Specification	234827
8231	#####	218176	Grease AC Compressor Clutch Bearing	234827
8231	#####	218176	Clean A/C filter	234827
8231	#####	218176	A Service & Bus Safety Inspection	234827
8231	#####	218153	Ops Entered - Fault - Vandalism - Route: 900 - Stud Park	234570
8231	#####	218153	Ops Entered - Vandalism	234570
8231	#####	218007	Drv entered - Passenger Doors Intermittent	234570
8231	#####	218069	Drv entered - Elec & Light Headlights	234570
8231	#####	218069	GLOBE HIGH BEAM	234570
8231	#####	218007	Rear hammer doors - maybe button	234570
8231	#####	218007	EMERGENCY HAMMERS	234570
8231	#####	218007	Drv entered - Body & Acc Interior	234570
8231	#####	218152	Breakdown - Stud Park shops - OUT 7.30 am BACK 8.30 am - Ha	234570
8231	#####	218007	Brakes slow to pull up	234570
8231	#####	217075	Add coolant	231295
8231	5/5/2009	216566	Add coolant	229800
8231	#####	216186	Set rear door sensor	228403
8231	#####	216055	Replace N/S/R airbag	228090
8231	#####	216055	BALL JOINT VOLVO	228403
8231	#####	216055	Ops Entered - Fault - Air System - Route: 901 - Dandenong	228090
8231	#####	216055	Ops Entered - Air System	228090
8231	#####	215934	Replace top alternator belt	227733
8231	#####	215934	Replace top alternator belt	228090
8231	#####	215883	Add coolant	227733
8231	#####	215391	Add coolant	226566
8231	#####	215254	Add coolant	226154
8231	#####	214921	A Service	225740
8231	#####	214921	Tension Wheel Nuts to Spec	225740
8231	#####	214921	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	225740
8231	#####	214921	AIR FILTER MERC 0500LE	225740
8231	#####	214921	A Service	225740
8231	#####	214921	OIL FILTER 1725+0500LE	225740
8231	#####	214921	Grease AC Compressor Clutch Bearing	225740

8231	#####	214921	D-Service	225740
8231	#####	214921	A Service	225740
8231	#####	214921	Tension Wheel Nuts To OEM Specification	225740
8231	#####	214921	Grease AC Compressor Clutch Bearing	225740
8231	#####	214921	Clean A/C filter	225740
8231	#####	213579	Creditor #BEA001 BEAUREPAIRES P/O #:G65723 Receiving #:67712 Date :2009-04-14	223680
8231	4/9/2009	214223	Add coolant	222328
8231	4/3/2009	213579	REPLACE DAMAGED TYRE POS 6	220802
8231	4/2/2009	213453	R/H/Rear tyre flat	220446
8231	4/2/2009	213452	R/H/Rear tyre flat	220446
8231	4/2/2009	213495	Drv entered - Elec & Light Headlights	220446
8231	4/2/2009	213495	GLOBE HIGH BEAM	220446
8231	4/2/2009	213495	Drv entered - Elec & Light Headlights	220446
8231	4/2/2009	213495	WEDGE GLOBE INSTRUMENT 24V 3W	220802
8231	4/2/2009	213453	Replace rear brake pads	220446
8231	4/2/2009	213453	DISC PADS SCANIA L94+0500 MERC	220802
8231	#####	212794	POS 1 11R225 NEW FLAT	220039
8231	#####	212794	Replace tyre pos 1 - puncture	219004
8231	#####	212985	Front door does not want to open	219004
8231	#####	212865	A Service	219004
8231	#####	212865	Tension Wheel Nuts To OEM Specification	219004
8231	#####	212865	Grease AC Compressor Clutch Bearing	219004
8231	#####	212865	Clean A/C filter	219004
8231	#####	212865	A Service	219179
8231	#####	212865	AIR FILTER MERC 0500LE	219004
8231	#####	212823	Ops Entered - Fault - Whls & Tyres - Route: 901 - Dandenon	218681
8231	#####	212823	Ops Entered - Whls & Tyres	218681
8231	#####	212837	Drv entered - Passenger Doors Faulty Controls	218681
8231	#####	212822	Breakdown - Stud Rd Rowville - OUT 9.00 am BACK 10.30 am -	218681
8231	#####	212822	Breakdown - Stud Rd Rowville - OUT 9.00 am BACK 10.30 am -	219004
8231	#####	212398	Front door controller n/w takes heaps of pushes to open	217495
8231	#####	212123	Add coolant	216752
8231	#####	212225	Retarder staying on	216752
8231	#####	211613	Recall for fuel line upgrade SM730	216129
8231	#####	211711	Add coolant	216129
8231	#####	210065	POS 5 11R225 NEW	215723
8231	#####	211524	Breakdown - Dandenon Frankston Rd near Carrum Downs - OUT	215559
8231	#####	211368	check coolant	214765
8231	3/2/2009	210065	Replace tyre pos 5 - worn	211866
8231	3/2/2009	210230	Adjust front door	211866
8231	3/2/2009	210230	CONTACT BLOCK DOOR PUSH SWITCH	211975
8231	3/2/2009	210238	Breakdown - Boronia Rd - OUT 6.30 am BACK 8.00 am - No air	218666
8231	#####	210107	Change pos 5 tyre	218666
8231	#####	210107	Damager seat cover at rear of bus	218666
8231	#####	210107	Cracked belts	218666
8231	#####	210107	MERC ALTERNATOR BELT TOP 0500LE (A39)	218666
8231	#####	210098	Losing air somewhere at the front	218666
8231	#####	210098	UNION STRAIGHT AIR LINE FITTING	218666
8231	#####	210098	AIR DRYER KIT	218666
8231	#####	209580	Top up coolant	210218
8231	#####	209354	Add coolant	209370
8231	#####	209329	A Service	209370
8231	#####	209329	Tension Wheel Nuts To OEM Specification	209370
8231	#####	209329	Grease AC Compressor Clutch Bearing	209370
8231	#####	209329	A Service	209370
8231	#####	209329	AIR FILTER MERC 0500LE	209370
8231	#####	208902	Doors faulty	207962
8231	#####	208902	Doors faulty	208276
8231	2/4/2009	207505	POS 3 REAR NEW	203798
8231	2/2/2009	207505	Replace tyre pos 3 - worn	203005
8231	2/1/2009	207559	Pos 3 tyre needs changing	203005
8231	#####	207222	Add oil	201521
8231	#####	206667	Alternator mounting bracket - one bolt broken	199681
8231	#####	206667	Alternator mounting bracket - one bolt broken	200309
8231	#####	206667	Alternator mounting bracket - one bolt broken	200309
8231	#####	206760	Hose clamp broken in coolant pipe under the engine	200212
8231	#####	206760	Air leaks on top of transmission	200212
8231	#####	206542	Annual Random Audit	199681
8231	#####	206528	Completed	199681
8231	#####	206528	Service T - Replace Transmission Oil & Filter	199681
8231	#####	206528	ZF Ecofluid A Plus Synthetic Transmission Oil	199681
8231	#####	206528	ZF Transmission Filter	199681
8231	#####	206528	Tension Wheel Nuts To OEM Specification	199681
8231	#####	206528	Grease AC Compressor Clutch Bearing	199681
8231	#####	206528	A Service	199681
8231	#####	206407	Breakdown - Endeavour Hills - OUT 5.10 am back 6.00 AM - Be	198953
8231	#####	206301	Replace alternator belts	198543
8231	#####	206301	MERC ALTERNATOR BELT TOP 0500LE (A39)	198543
8231	#####	206301	A/C BELT 0500 BENZ	198953
8231	#####	206279	Refill coolant	198543
8231	#####	204818	Check fault code	193033
8231	#####	204027	POS 4 11R225 NEW TYRE	189697
8231	#####	204027	Replace tyre pos 4 - bald	189483
8231	#####	204112	Change N/S rear tyre	189483
8231	#####	203982	A Service	189483
8231	#####	203982	Tension Wheel Nuts To OEM Specification	189483
8231	#####	203982	Grease AC Compressor Clutch Bearing	189483
8231	#####	203982	A Service	189483
8231	#####	178321	12V 200AMP 1100CCA	184322
8231	#####	202655	Drv entered - Passenger Doors Faulty Controls	184126
8231	#####	202655	The back door plays doesn't close all the time- there is a	184126
8231	#####	202020	4 WAY PROTECTION VALVE BARREL SEALS (M8 0500LE)	183926
8231	#####	202020	WATER SEPERATOR SCANIA+VOLVO	183926
8231	#####	202020	Air leak at rear when bus is on	182208
8231	#####	202020	Air leak from 6way valve	182208

8231	#####	202499	Breakdown - Stud Park Shopping Centre - OUT 7.30 pm BACK 8.	Used van 619. Jump started	183653
8231	#####	202047	Refill coolant	Refilled	182594
8231	#####	202020	Air leak at rear when bus is on	Checked for air leak sent bus out need to bring back for repairs	182208
8231	#####	201904	Left headlight needs alignment	Adjusted the headlight	181937
8231	#####	201905	L/H mirror back door have to close twice	Replaced the mirror checked the back door OK	181937
8231	#####	200392	REAR NEW 11R	Creditor #BEA001 BEAUREPARES P/O #:G61632 Receiving #63753 Date :2008-11-19 RETURN CASE	180723
8231	#####	200137	AURORA VALVE CONTROLLER	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G61935 Receiving #63704 Date :2008-11-18	180723
8231	#####	201313	DIP STICK MERCEDES 0500LE		180470
8231	#####	201313		D-Service	180142
8231	#####	201313		A Service	180142
8231	#####	201313		Tension Wheel Nuts to Spec	180142
8231	#####	201313	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		180142
8231	#####	201313	OIL FILTER 1725+0500LE		180142
8231	#####	201313	AIR FILTER MERC 0500LE		180142
8231	#####	201313		A Service	180142
8231	#####	201313		Tension Wheel Nuts To OEM Specification	180142
8231	#####	201357	Coolant leak	Repaired coolant leak	180142
8231	#####	200865	JUMP START BUS		178928
8231	#####	200995	Alternator belt U/S	Replace alternator belt and broken bolt	178928
8231	#####	200995	ALTERNATOR BOLT ADJUSTER		179242
8231	#####	200995	MERC ALTERNATOR BELT TOP 0500LE (A39)		179242
8231	#####	200607	O/S/R tyres U/S	Replace tyres	177786
8231	#####	200392	Replace tyre No.5 and 6	Replace tyre No.5 and 6	177786
8231	#####	200137	Heater control knob missing has been for some weeks cannot	Fitted knob	176560
8231	#####	200137	Vehicle covered in eggs drivers side mirror filthy	Clean mirrors	176560
8231	#####	200137	Neutral lamp cover missing	Fit N in gear control buttons	176560
8231	#####	200137	BUTTON PUSH NEUTRAL		176923
8231	#####	182414	Fit wiper blades properly	Fitted	175726
8231	#####	182028	Alternator mount bolt /one of tre broken/	Removed broken and replaced	175005
8231	#####	180402	POS 4 11R225 NEW TYRE	Creditor #BEA001 BEAUREPARES P/O #:G60860 Receiving #63160 Date :2008-10-29	175005
8231	#####	182028	Alternator mount bolt /one of tre broken/	Began replacing alternator bracket bolt	175005
8231	#####	181757	Breakdown - Cnr Wellington & Wanda Rds - OUT 5.00 pm BACK 6	Stripped bus 229 bolt & spacer from alternator to fit fitted alt belt	173984
8231	#####	181343	Adjust alternator belt	Adjusted	173984
8231	#####	181631	Refill coolant	Refilled	173984
8231	#####	181343	MERC ALTERNATOR BELT TOP 0500LE (A39)		173984
8231	#####	181343	Coolant leak from header tank outlet pipe - looks like pin	Changed header tank outlet pipe	172845
8231	#####	181757	Breakdown - Cnr Wellington & Wanda Rds - OUT 5.00 pm BACK 6	C/O bus 239. Found broken bolt in alternator drilled bolt out (couldn't find one in store)	173984
8231	#####	181343	Alternator mounting plate one bolt broken	Replaced bottom alternator bracket bolt was missing	172845
8231	#####	181343	Rear door sensor needs adjusting (Checked 04/09/08 servcab	Checked OK	173163
8231	#####	181343	Rear door sensor needs adjusting (Checked 04/09/08 servcab	Checked OK	173163
8231	#####	181276	CLIPPARD VALVE DOOR OPEN/CLOSE		172845
8231	#####	181276	Door valve air leak	Replaced	172845
8231	#####	181276	Door valve air leak	Replaced	173163
8231	#####	181271		A Service	172845
8231	#####	181271		Tension Wheel Nuts To OEM Specification	172845
8231	#####	181271	AIR FILTER MERC 0500LE		172845
8231	#####	181271		A Service	172845
8231	#####	180902	AC blowing hot air	Replaced blown 3amp fuse for fresh air ram run unit down to 21C all OK	171559
8231	#####	180435	At slow speeds there is a noticeable thump coming from the N	Replaced N/R inner tyre and /f/tested OK	170423
8231	#####	180402	Replace tyre pos 4 - worn	Replaced	170423
8231	#####	180349		Replace compressor oil	170139
8231	#####	180349		Replace filter drier	170139
8231	#####	180349		B Service	170139
8231	#####	180349		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	170139
8231	#####	180349		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	170139
8231	#####	180349		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	170139
8231	#####	180349		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	170139
8231	#####	180349		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	170139
8231	#####	180349		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	170139
8231	#####	180349		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	170139
8231	#####	180349		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	170139
8231	#####	180349		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condenser fan grills	170139
8231	#####	180349		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	170139
8231	#####	180349	Service as per list	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	170139
8231	#####	180349	FILTER DRIER THERMO KING		170423
8231	#####	179470	Change front tyres	Changed	166111
8231	#####	179469	Breakdown - Dandenong/Frankston rd - OUT 7.00 am BACK 7.30	C/O bus 230. Door OK	166111
8231	#####	179127	Drv entered - Passenger Doors Other	Put door switch in ON position	165383
8231	#####	178321	Battery saver light on	Fitted air dryer coil charged batteries put alternator cover back on and put floor down	164969
8231	#####	179086	Breakdown - Caulfield Station - OUT 6.15 pm BACK 7.45 pm -	Used van 619. Driver had knocked switch on dash	164969
8231	#####	178321	Battery saver light on	Checked wiring diagram found short in air dryer bgean fitting new part	164969
8231	#####	178321	HALDEX COIL KIT 0500LE		164969
8231	#####	178321	Battery saver light on	Checked both alternators both charging checked solenoids in battery box cannot find short	164969
8231	#####	178321	Battery saver light on	FOUND Short in D + CIRCUIT	164969
8231	#####	178321	Check / repair alternator not charging.	checked all elects possible faulty alternator	164969
8231	#####	178171	No saloon lights	reset circuit breaker	164969
8231	9/4/2008	177428	Adjust sensitive edge	Adjusted	162340
8231	9/4/2008	177433	Remove graffiti	DULKITH - Removed	162340
8231	9/4/2008	177302		A Service	161929
8231	9/4/2008	177302		Tension Wheel Nuts To OEM Specification	161929
8231	9/4/2008	177302	AIR FILTER MERC 0500LE		162340
8231	9/4/2008	177302	DULKITH		162340
8231	#####	176991	Wont raise or lower floor not good for prams or wheel chair	A Service	161162
8231	#####	176719	Drv entered - Ticket Equip Other	Reset key	158988
8231	#####	176424	Refit belt	Checked by Joe	158791
8231	#####	176424	MERC ALTERNATOR BELT TOP 0500LE (A39)	Refitted	158791
8231	#####	176424	Refit belt		158791
8231	#####	176254	Automatic door closer n/w	Refitted	158481
8231	#####	174882	COMPLETE 9/BAR	Checked & repaired by Volgren	158481
8231	#####	174882	F/GLASS CORNER PIECE	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G59009 Receiving #61270 Date :2008-08-22 231	158481
8231	#####	174882	OUTER H/LIGHT	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G59009 Receiving #61270 Date :2008-08-22 231	158481
8231	#####	175771	Direct Purchase - BODYWORK	Creditor #:TIN002 TINT FX P/O #:G59289 Receiving #61253 Date :2008-08-21 Tint front windscreen and front doors	158179
8231	#####	175732	Inspect for driveline warranty - Due on 1/8/08	Completed	156772
8231	#####	175771	Tint windscreen & front door glasses.	Completed by Tint FX	157177
8231	#####	174882	CLEAR FRONT INDICATOR WRAP-AROUND		156526





8231	#####	155500	Breakdown - Chadstone Shopping Centre- OUT 9.15 am BACK 9.4	C/O bus 23. Put in fuel returned to depot	89956
8231	#####	155437	READJUST ALL DOORS	Readjust doors	89956
8231	#####	155428	Alternator belt missing	Fit belt	89956
8231	#####	155428	MERC ALTERNATOR BELT TOP 0500LE		89956
8231	#####	155399	Broknedown at Stud park S/C. Battery light on. C/O bus 220.	Brought bus back need to fit new alter. belt	89956
8231	#####	155399	Broknedown at Stud park S/C. Battery light on. C/O bus 220.	Brought bus back need to fit new alter. belt	89956
8231	#####	155182	Tyres extremely rough & lumpy - bone shaker to drive	Replaced front tyres	89552
8231	#####	155217	Replace tyres pos. 1 & 2 replace with Grenda's cases	rep. tyres pos. 1 & 2 (unevan treads)	89819
8231	#####	153975	Battery light on	Replaced top alt belt	86205
8231	#####	153975	MERC ALTERNATOR BELT TOP 0500LE		86472
8231	#####	152842	Adjusted alternator belts	Adjusted alternator belts	82672
8231	#####	152820	Breakdown - Alternator belt broken Monash Uni left at 11.00	C/o. bus at Monash uni. returned to depot & replaced both alternator belts.	82672
8231	#####	152820	MERC ALTERNATOR BELT TOP 0500LE		82672
8231	#####	152820	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		82672
8231	#####	152525	Move driverscreen		81439
8231	#####	152525	MOVE SCREEN		81439
8231	#####	152408	Remove graffiti	Creditor #VOI001 VOLGREN AUSTRALIA P/L P/O #:G50188 Receiving #:44512 Date :2007-10-24	81139
8231	#####	152408	Replace rear yellow stripe	Removed	81139
8231	#####	152355		Replaced	81139
8231	#####	152355		A Service	80777
8231	#####	152355		Tension Wheel Nuts To OEM Specification	80777
8231	#####	152355	CLEANED AIR FILTER MERC 0500LE		81139
8231	#####	152355		A Service	80777
8231	#####	152355		A Service	81439
8231	#####	152202	Replace alternator belt	Replace top alternator belt	80501
8231	#####	151645	Ops Entered - Air Cond	Found boost pump fuse blown due to rubeled wire in loom above compressor insulate and fit shield hose	79176
8231	#####	151626	Breakdown - Cnr Jackson & Wellington Rds - OUT 7.50 pm Back	C/O u 229. Replaced globe on site returned to depot fuelled & parked	78900
8231	#####	151626	GLOBE HIGH BEAM		79176
8231	#####	149894	A/C fault light comes on red	Replaced blown unloader fuse trace fault back rubeled wire on loom where it enters the rear frame	73731
8231	#####	149894	FUSE BLADE 10AMP		73731
8231	#####	148694	POS 3 BOLT IN TREAD	Creditor #BEA001 BEAU REPAIRS P/O #:G48863 Receiving #:43536 Date :2007-09-12 231	72546
8231	#####	148271	Remove rear seat graffiti	Removed	72546
8231	#####	149205		A Service	72315
8231	#####	149205		Tension Wheel Nuts To OEM Specification	72315
8231	#####	149205		A Service	72315
8231	9/5/2007	148694	Replaced tyre pos. 3 - Bolt in tread	Replaced	70830
8231	9/3/2007	148637	Replace N/S/R outer tyre	Replaced had bolt in it	70663
8231	#####	148391	LED CLEARANCE LIGHT (RED AMBER)		70663
8231	#####	148391	Replace side clearance light	Replaced	70663
8231	#####	148306	Repair L/H top rubber strap	Repaired	70663
8231	#####	147331	O/S headlights not working	Fit O/S front headlamp globe	67347
8231	#####	147331	GLOBE HIGH BEAM		67347
8231	8/7/2007	146415	Rear door sticks very slow to open	Adjust rear doors.	63847
8231	8/2/2007	146040	Replace alt belt	Replaced	62933
8231	8/2/2007	145936		A Service	62933
8231	8/2/2007	145936		Tension Wheel Nuts To OEM Specification	62933
8231	8/2/2007	145936		A Service	62933
8231	8/2/2007	145936	MERC ALTERNATOR BELT TOP 0500LE		62933
8231	7/9/2007	143979	BLADE WIPER 1MTR		57370
8231	7/8/2007	143979	Replace wiper blade.	Replace wiper blade	57370
8231	7/7/2007	0	Imported Service History	Imported Service History	0
8231	7/6/2007	142960	ROAD SAFETY INSPECTIONS	Creditor #ROA001 Road Safety Inspections P/O #:G45721 Receiving #:41919 Date :2007-07-06 Annual Inspection	56711
8231	7/6/2007	143192	Service	refitted new light	56711
8231	7/5/2007	142511	MERC VG2183 DOOR NO 17582 DOOR	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G45863 Receiving #:41888 Date :2007-07-05	56289
8231	7/1/2007	142960	Annual Inspection -	ANNUAL INSPECTION BC 106103 - PASSED	55027
8231	#####	143193	Repair & repaint N/S/F top corner f/glass	Prepare for painting	55578
8231	#####	143193	Repair & repaint N/S/F top corner f/glass	Prepare for painting	55578
8231	#####	143192	Complete steamclean	Cleaned	55578
8231	#####	143192	Interior LED light n/w	Fitted back hatch and ordered parts	55578
8231	#####	143192	CLEAR L.E.D. INTERIOR LIGHT		55578
8231	#####	143192	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		55578
8231	#####	143192	Steamclean & check fuel tank for leaks	Checked OK	55578
8231	#####	143193	Rear left hand seat damaged	Replaced	55578
8231	#####	143193	Replace O/S front wheel arch brush missing	Replaced	55578
8231	#####	143193	Accident damage no 13105 - Replace rear door rear seal rea	Replaced rear door realigned rear door & polished panels	55578
8231	#####	143193	Repair & repaint N/S/F top corner f/glass	Prepare for painting	55578
8231	#####	143106	Left side reflector light broken	Replaced reflector	55027
8231	#####	142516	Adjust all belts	Adjust	54085
8231	#####	142511	Replace n/s/r clearance light	Replace light	54085
8231	#####	142516	Secure clean adjust front & rear doors	Clean and adjust	54085
8231	#####	142516	Wheel chair ramp - operation & clean	Clean check	54085
8231	#####	142516	Polish exterior panels/headers & touch up paint work	Polish	54085
8231	#####	142516	Clean air condition filter secure vents	Clean	54085
8231	#####	142511	Secure replace paint exterior mirrors and arms	Secure	54085
8231	#####	142511	Paint till stand	Paint	54085
8231	#####	142511	Secure or replace side reflectors - N/S rear	Replace	54085
8231	#####	142511	Secure all lower skit panels	Secure	54085
8231	#####	142511	AMBER REFLECTOR SIDE MOUNT		54197
8231	#####	142516	Polish & touch up N/S/R corner panels mid to top	Polish and touch up	54085
8231	#####	142511	Polish out scrape marks No 5 O/S lower panel	Polish	54085
8231	#####	142511	Replace rear of rear door appature rubber remove scrape m	Polish and touch up fixed	54085
8231	#####	142512	Accident damage no 13105 - Replace rear door rear seal rea		54085
8231	#####	142477		A Service	54085
8231	#####	142477		Tension Wheel Nuts To OEM Specification	54085
8231	#####	142477	LED CLEARANCE LIGHT (RED AMBER)		54197
8231	#####	142477		A Service	54197
8231	#####	142052		Top-up coolant level (must equate to -37C frost protection)	52924
8231	#####	142052		Change oil in fan angle drive	52924
8231	#####	142052		Change air drier canister; clean silencer & drain air reservoir	52924
8231	#####	142052		Change pre and main fuel filter	52924
8231	#####	142052		Check power steering oil level	52924
8231	#####	142052		Check & clean filter cartridge in dry-type air cleaner	52924
8231	#####	142052		Remove disassemble & clean cyclone separator (apply water repellant grease to electrical connections) check drainage function for leaks	52924
8231	#####	142052		Check oil level in transmission & top-up if required	52924
8231	#####	142052		Inspect radiator & charge-air cooler for dirt - clean if required	52924
8231	#####	142052		Electrical - BATTERIES: check fluid level (leave air gap when topping up) CABLES: check cable connections are firm with good contact on ALL battery terminals	52924

8231	#####	142052	AIR DRYER CANISTER MAN NL202+VOLVO		53271
8231	#####	142052	Mechanical inspection		52924
8231	#####	142052	Mechanical inspection		53271
8231	#####	142052		Adjust Engine Valve Clearance	52924
8231	#####	142140	Annual body check	Body check	53271
8231	5/8/2007	139300		A Service	45134
8231	5/8/2007	139300		Tension Wheel Nuts to Spec	45134
8231	5/8/2007	139300	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		45134
8231	5/8/2007	139300	OIL FILTER 1725+0500LE		45134
8231	5/8/2007	139300	AIR FILTER MERC 0500LE		45134
8231	5/8/2007	139300		D-Service	45134
8231	5/8/2007	139300		A Service	45134
8231	5/8/2007	139300		Tension Wheel Nuts To OEM Specification	45134
8231	5/1/2007	138671	A/C not cooling	Repaired by Thermoking	39444
8231	#####	137747	Air conditioner faulty.	Work with Thermoking on warranty issues	39444
8231	#####	137747	Air conditioner faulty.	Repaired by Thermoking	39444
8231	#####	137747	Air conditioner faulty.	Checked system for error. Found that unit has lost all its refrigerant. Thermoking warranty	39444
8231	#####	137550	Service	replaced idler tensioner (took off bus No 218)	39060
8231	#####	137550	Breakdown in Gladstone Rd. A/C. & main drive belt is off. L	c/o. bus returned to depot & replaced idler tensioner pulley.	39060
8231	#####	137550	MERC ALTERNATOR BELT TOP 0500LE		39247
8231	#####	137550	A/C BELT 0500 BENZ		39247
8231	#####	137409	Service		38822
8231	#####	137409		A Service	38822
8231	#####	137409		Tension Wheel Nuts To OEM Specification	38822
8231	#####	137409		A Service	38822
8231	#####	137409			38822
8231	4/7/2007	137127	Replace top alternator bolts x3 realign belt and tension	Replace bolts	38159
8231	4/2/2007	136789	Rear N/S clearance light cover broken	Has been fitted	36212
8231	#####	136664	Rear N/S clearance light cover broken	Replace clearance light	35985
8231	#####	136664	LED CLEARANCE LIGHT (RED AMBER)		36212
8231	#####	135541	LED CLEARANCE LIGHT (RED AMBER)		32415
8231	#####	135541	Replaced parker light / globe	rep. globe	32415
8231	3/8/2007	134757		A Service	29070
8231	3/8/2007	134757		Tension Wheel Nuts To OEM Specification	29070
8231	3/8/2007	134757		A Service	29070
8231	3/7/2007	134818	Breakdown - Princess Hwy Chadstone - OUT 2.00 pm BACK 3.00	C/O bus 230. Returned to depot and replaced top alternator belt	29070
8231	3/7/2007	134818	MERC ALTERNATOR BELT TOP 0500LE		29404
8231	3/6/2007	134606	Retarder comes on as soon as you take your foot off accler	Flicked switch in middle pos need to make cover	28782
8231	3/6/2007	134606	Retarder comes on as soon as you take your foot off accler	Fitted retarder switch cover	28782
8231	3/3/2007	134372	Air conditioner has red light on occasionally.	Repaired cracked pipe	28001
8231	3/3/2007	134372	Drv entered - Air Cond Air Conditioner	pressure tested- found suction hose has slight leaks is warranty.	28001
8231	#####	132893	Replace A/C & lower alternator belt	Replaced belts and jumpstartd	24910
8231	#####	132893	A/C BELT 0500 BENZ		25178
8231	#####	132893	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		25178
8231	#####	132851	Small water leak from engine compartment	Repaired coolant leak roadtested	25178
8231	#####	132851	Radio not working.	Radio working OK	25178
8231	#####	132851	Drv entered - Air Cond Cooling Fault Light	A/C working OK	25178
8231	#####	132851	Drv entered - Eng Cool Leaking	Assisted Greg with leaking boost pump	25178
8231	#####	131110	Adjust alternator belts	Adjusted	20001
8231	#####	131110	Two way radio faulty.	Checked OK	20001
8231	#####	131076		A Service	20001
8231	#####	131076		Tension Wheel Nuts To OEM Specification	20001
8231	#####	131076		A Service	20001
8231	#####	130748	Check / repairs to doors & brake interlock system.	Take to Volgren checked out electrics found two wires on relay wrong way	18953
8231	#####	130603	Annual random audit...	Completed	18689
8231	#####	130681	Check brake pedal	Checked OK	18953
8231	#####	130681	Adjust alternator belts	Adjusted	18953
8231	1/5/2007	130099	Bus moves with rear door open.	Went to Monash checked bus out unable to fix fault on site	17559
8231	1/5/2007	130099	Service	reset switches to correct positions	17559
8231	#####	129506	Tighten hose clamp at tap near radiator	Tightened	15333
8231	#####	129179	DO NOT OVERTAKE TURNING DECAL		14197
8231	#####	129179	POWDER COATED NOTICE BOARDS		14197
8231	#####	129179	SAFETY TRIANGLE DECAL		14197
8231	#####	129179	GIVE WAY SIGN (SMALL)		14197
8231	#####	129179	Fit all decals & regulation signs as required.	Checked all decals and took Nos from bus	14045
8231	#####	129179	Fit all decals & regulation signs as required.	Checked all decals and took Nos from bus	14045
8231	#####	129163	Air conditioner comes on intermitant. Faulty	Found unit had no refrigerant in system	13688
8231	#####	129162	Air conditioner comes on intermitant. Faulty		13688
8231	#####	128217	MERC ALTERNATOR BELT TOP 0500LE		10379
8231	#####	128217	Replace alternator belt	Replaced	10037
8231	#####	128086		A Service	10037
8231	#####	128086		Tension Wheel Nuts To OEM Specification	10037
8231	#####	128086		A Service	10037
8231	#####	127977	Water hammer check and replace elbows as required/fit insu	Repaired by ThermoKing	9498
8231	#####	127977	No air conditioner not very nice for new bus.	Repaired by Thermo King	9498
8231	#####	127977	Drv entered - Air Cond Cooling Fault Light	Repaired by Thermo King	9498
8231	#####	127977	Drv entered - Air Cond Air Conditioner	Repaired by Thermo King	9498
8231	#####	127977	Air conditioner making a banging noise fom vent in roof.	Repaired by Thermo King	9498
8231	#####	128104	Road test for coolant	Roadtested	9860
8231	#####	128005		A Service	9860
8231	#####	128005		Tension Wheel Nuts To OEM Specification	9860
8231	#####	127739	Warning comes with fault code MR 4905	Repaired by Whitehorse	9387
8231	#####	127841	Breakdown - Oakleigh - No power Code MR 4905 - Dep 9.20 Ret	C/O bus return to depot and went to Whitehorse for repairs	9387
8231	#####	127771	Breakdown - Cnr Wellington & Springvale Rds OUT 6.00pm BACK	C/O bus 228. Could not find fault checked all bus	9161
8231	#####	127504	Fuel & park bus	Fuelled & parked	8792
8231	#####	127504	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz		8895
8231	#####	127189	A/C. fault light on & not cooling please unlock windows fo	REP. UNDER WARRANTY - SOUTHERN STATES THERMO KING	8283
8231	#####	126667	Boost Pump for A/C. in engine bay leaking.	Repair by Thermo King - warranty	7434
8231	#####	125942	Warranty Service - 5000 kms		6068
8231	#####	125581	Coolant leaks.	secured hose clamp	4469
8231	#####	125293	2way E button till pin	Fitted	3936
8231	#####	125293	New bus - Decals	Fit all decals	3936
8231	#####	125293	2way E button till pin	Fitted	3936
8231	#####	125293	New bus - Decals	Fit all decals	3936
8231	#####	124907	Electrical failure - no accessory lights/indicators tim et	checked all elects located fault in solenoid took to Volgren & parts replaced under Warranty	2787
8231	#####	124906	Breakdown - Caulfield Monash drive.No electrical power/let	c/o. bus & returned to depot for check / repairs	2787

