

Veh#	Date	W/O#	Description	Notes	Odometer
214	5/27/2026	1339644	CLOSING OFF DEFECT AS BUS IS GOING TO AUCTION	COMPLETE	1547155
214	5/27/2026	1339007	BUS GOING TO AUCTION	BUS GOING TO AUCTION BELT WAS NOT FITTED .	1547155
214	5/27/2026	1343817	Decommission of Bus for Auction	COMPLETE	1547155
214	5/27/2026	1343817	Decommission of Bus for Auction	COMPLETE	1547155
214	5/13/2026	1340628	Body Windows Side- window seal channel removed t	Assisting	1547155
214	5/13/2026	1340628	Body Windows Side- window seal channel removed t	Cleaned channel and window groove drill out broken rivets and fit c	1547155
214	5/11/2026	1338593	GLASS RESEAL	Creditor #:VB-OBR001 O'BRIENS GLASS INDUSTRIES P/O #:O409721 R	1547155
214	5/11/2026	1338593	Mechanic entered - Body Windows Side N/S third win	O409721 - CARRIED OUT BY OBRIANS WINDSCREENS	1547155
214	5/9/2026	1339644	Mechanic entered - Suspension Other O/S/R bump st	ORDERED BUMP STOP X 1 - 8-5-26	1547155
214	5/9/2026	1339644	Mechanic entered - Suspension Other N/S/F airbag cr	ORDERED AIR BAG X 1 - 8-5-26	1547155
214	5/9/2026	1339645	Mechanic entered - Engine Other Front lower radiato	CHECKED RADIATOR MOUNTS. FOUND SERVICABLE . THEIR HOMELEY	1547155
214	5/9/2026	1339643	Mechanic entered - Body Other 1x O/S wall disable se	CHECKED DISABLED SEAT BASES PLASTICS FOUND SERVICBLE	1547155
214	5/7/2026	1339189		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1547155
214	5/7/2026	1339189		VEHICLE SAFETY INSPECTION	1547155
214	5/7/2026	1339189		ANNUAL SAFETY INSPECTION SERIAL #RSI 077862 WORKSHOP SUPE	1547155
214	5/7/2026	1339290		PRE ANNUAL SAFETY INSPECTION CHECK - REFER WORK ORDER : 133	1547155
214	5/6/2026	1339007	Mechanic entered - Engine Other Alternator belt near	ORDERED AC BELT - 6-5-26	1547155
214	4/23/2026	1336115		PRE ANNUAL SAFETY INSPECTION CHECK Completed PRE RSI inspecti	1547025
214	4/23/2026	1336115		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1547025
214	4/23/2026	1336137	HEADLAMP INSERT HELLA 90MM L/FLOOR 0500 9314365038525		1547025
214	4/23/2026	1336137	Mechanic entered - Elec and Light Exterior Lights N/S	removed old high beam lamp fit new item from stock checked for fu	1547025
214	4/23/2026	1336137	Mechanic entered - Elec and Light Exterior Lights O/S	Removed and fitted new parklight / indicator lamp with new indicat	1547025
214	4/23/2026	1336137	SEAT CUSH SUPER SLIM SGL CVR - CL		1547025
214	4/23/2026	1336137	FRONT INDICATOR OFFSIDE HL2158		1547025
214	4/23/2026	1336137	Consumables		1547025
214	4/23/2026	1336137	Mechanic entered - Body Passenger Seat Torn 1x O/S	Removed and fitted new seat base cover.	1547025
214	4/23/2026	1336137	Mechanic entered - Body Front_Door Operation Fault	Adjusted sensitive edge and checked door operation all okay.	1547025
214	4/23/2026	1336137	Consumables		1547025
214	3/12/2026	1326657		Assisting	1547025
214	3/12/2026	1326657		VEHICLE SAFETY INSPECTION	1547025
214	3/12/2026	1326657		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1547025
214	3/12/2026	1326656		VEHICLE SAFETY INSPECTION	1547025
214	3/12/2026	1326789	Mechanic entered - Suspension Other N/S/R BOTTOM	removed N/S/R BOTTOM TORQUE ROD AND repaired N/S/R BOTTO	1547025
214	3/12/2026	1326789	Mechanic entered - Body Other o/s/middle body pan	tightened o/s/middle body panel screws ok.	1547025
214	3/12/2026	1326789	Mechanic entered - Body Other rear smoking decal m	replaced rear smoking decal ok.	1547025
214	3/12/2026	1326789	Mechanic entered - Body Other n/s/r 3rd seat	seat base drilled and fitted new nuts and bolt.	1547025
214	3/4/2026	1325021	Consumables		1546816
214	3/4/2026	1325000	Consumables		1546816
214	3/4/2026	1325021	Mechanic entered - Elec and Light Desto Fault Desto f	Opened up desto. Found wrong plug being used. Removed one side	1546816
214	3/4/2026	1325000	CHARGER USB 5V 3A DUAL CONVERTER MODULE BUS MINDER		1546816
214	3/4/2026	1325000	Mechanic entered - Driver Tablet Missing	Removed bus minder and cradle from bus 8228 and fitted into 214.	1546816
214	3/4/2026	1325000	BUSMINDER CABLE USB A TO C TYPE 5V3A		1546816
214	2/26/2026	1323461		COMPLETED BY ATS 15/2/26	1546816
214	2/3/2026	1318110	Consumables		1546816
214	2/3/2026	1318110	Mechanic entered - Elec and Light Flat Batteries	Jump started bus. Let sit for 30 minutes	1546816
214	12/17/2025	1309768		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorque all whe	1546816
214	12/17/2025	1309768		VEHICLE SAFETY INSPECTION carry out safety inspection.	1546816
214	12/16/2025	1309555		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out as per cl	1546816
214	10/1/2025	1293608	Mechanic entered - Body Other Saloon light switch le	Removed switch removed lens sourced part sanded down lens sligl	1546816
214	10/1/2025	1292972	AIR CONDITIONING REPAIR	Creditor #:VB-COL004 COLD DRIVE PTY LTD P/O #:O395995 Receiving	1546816
214	9/29/2025	1292972		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Assisting - PO:O395!	1546816
214	9/23/2025	1292033		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retorque all whe	1546816
214	9/23/2025	1292033		VEHICLE SAFETY INSPECTION carry out safety inspection.	1546816
214	9/23/2025	1292111	Consumables		1546816
214	9/23/2025	1292111	Mechanic entered - Elec and Light Interior Lights n/s r	fit new fluro.	1546816
214	9/23/2025	1292108	Mechanic entered - Body Front_Door Operation Fault	adjust safety edge switch.	1546816
214	9/23/2025	1292107	Mechanic entered - Body Other front blind guide rod	secure rod.	1546816
214	9/17/2025	1290925	Mechanic entered - Gearbox Driveline Other cannot s	bus had no ign power; this issue was fixed and found not selecting t	1546816
214	9/16/2025	1290420	RELAY 5 PIN CHANGE OVER 24V 10/20 AMP 68052		1546816
214	9/16/2025	1290420		traced and found a broken gnd wire to the solenoid. repaired and fit	1546816
214	9/15/2025	1290420	RAIL >>>ENGINE CRANKS BUT DOES NOT START	checked and found Cranking but not starting no dash lights and fuel.	1546816
214	9/9/2025	1289263		COMPLETED BY ATS 16/8/25	1546816
214	7/24/2025	1278260	BATTERYS TO BE REPLACED - BUS VOR - AWAITING AI	Removed and replaced battery with new from stock. Starting up ok i	1546816
214	7/24/2025	1278260	BATTERY EXSN94SCMF 1450AAC EMFN150L		1546816
214	7/24/2025	1278260	Consumables		1546816
214	7/1/2025	1265108	TIE ROD ASSY MERC BENZ 0500LE	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT387723 Receiving	1546816
214	6/17/2025	1270873		VEHICLE SAFETY INSPECTION Done with VSI ref WO#1269679.	1546816

214	6/17/2025	1270873		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1546816
214	6/17/2025	1270891	Consat (None) Emergency Duress Alarm repeatedly a	duress button was stuck down so i sprayed inox and pressed alot to	1546816
214	6/16/2025	1269679	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT389025 R	1546816
214	6/12/2025	1269942	Mechanic entered - Body Other emergency sticker	got the old sticker off wiped with prepsol and stuck new sticker part	1546816
214	6/12/2025	1269942	DECAL EMERGENCY EXIT ROCK BLACK/WHITE		1546816
214	6/12/2025	1269942	Consumables		1546816
214	6/11/2025	1269679	Service	ANNUAL SAFETY INSPECTION #RSI071624	1546816
214	6/10/2025	1269537	Mechanic entered - Fluid Leaks Other A/C compressor	Checked A/C compressor for leaks very slight leak so cleaned up aga	1546816
214	6/4/2025	1268491	Random check and chassis wash.	Completed check and chassis wash	1546816
214	6/4/2025	1268491	Consumables		1546816
214	6/2/2025	1267796	Random check and chassis wash.	Incorrect entry.	1546816
214	6/2/2025	1267797	Random check and chassis wash.	Incorrect entry.	1546816
214	6/2/2025	1267796	Consumables		1546816
214	6/2/2025	1267797	Consumables		1546816
214	5/22/2025	1265794	Mechanic entered - Body Other under carriage wash ;	Prep for undercarrige spray used scraper to remove flaky parts wash	1546690
214	5/22/2025	1265794	STONEGUARD PLUS SZ L253 1000ML		1546690
214	5/22/2025	1265794		preped and sprayed body deadner	1546690
214	5/22/2025	1265794	Consumables		1546690
214	5/21/2025	1265108		replaced complete tie rod end check and reset wheel alignment	1546690
214	5/19/2025	1265066		PRE ANNUAL SAFETY INSPECTION CHECK completed pre annual safet	1546690
214	5/19/2025	1265066		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed cctv b se	1546690
214	5/19/2025	1265108	Mechanic entered - Steering Other n/s tie rod end pla	ordered parts	1546690
214	5/14/2025	1264322		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complat fir	1546690
214	4/4/2025	1256905		VEHICLE SAFETY INSPECTION Completed Safety inspection and A serv	1546609
214	4/4/2025	1256905		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1546609
214	4/4/2025	1256998	Wheels and Tyres	Tyre were required to be booked out	1546609
214	4/4/2025	1256998	TYRE 295/80R22.5 RECAP		1546609
214	4/4/2025	1256998	Consumables		1546609
214	4/4/2025	1256915		CARRY OUT A SERVICE AS PER CHECK LIST Completed A service at sar	1546609
214	4/4/2025	1256915	Consumables		1546609
214	4/4/2025	1256915	Consumables		1546609
214	4/4/2025	1256915	Consumables		1546609
214	3/20/2025	1251578		jump start bus in the yard test batteries put batteries on charge disc	1546609
214	3/20/2025	1251578	Consumables		1546609
214	3/19/2025	1251578		removed dash panel that had a bunch of rounded off bolts removed	1546609
214	3/11/2025	1251578	Mechanic entered - Elec and Light Flat Batteries	fitted starter motor onto bus and starts first time but bus has fault c	1546609
214	3/11/2025	1251578		removed starter motor from bus 226 assisted DB fitted starter moto	1546609
214	3/7/2025	1251008		COMPLETED BY ATS 26/2/2025	1546609
214	3/4/2025	1249953		VEHICLE SAFETY INSPECTION Safety inspection completed as per che	1546609
214	3/4/2025	1249953		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1546609
214	2/14/2025	1245394	PERFORM CAMPAIGN 02/25 2025 PTV FARE DECAL RE DONE 13/02/2025		1546609
214	1/14/2025	1238633	A/C Heating	Checked A/C for not cooling problem. Found A/C compressor engag	1546609
214	12/31/2024	1236228	Workshop Tablet Entered -Elec and Light - Indicators	resecured indicator stalk as it was adrift	1544519
214	12/31/2024	1236228	Indicator Stork Faulty - Unable to make Right Turn Inc	double entry	1544519
214	12/31/2024	1236228	Consumables		1544519
214	12/17/2024	1234215	Workshop Tablet Entered -Tow hook hanging under fi	removed hook and mount as we dont use	1542927
214	12/17/2024	1234215	Consumables		1542927
214	12/14/2024	1233603	Drv entered - Driver Tablet No Power	defect entered twice.	1542227
214	12/14/2024	1233603	Ops Entered - Fault - BusMinder - Route: 837 - Berwic	checked over tablet chatgind system. found charging cable unplugg	1542227
214	12/14/2024	1233603	Consumables		1542227
214	12/13/2024	1226521	TOW FROM BERWICK TO DANDENONG	Creditor #:CT-EAG001 EAGLE TOWING & SALVAGE P/O #:CT375878 R	1542227
214	12/12/2024	1233093	SWITCH BELL PUSH (340037)		1541420
214	12/12/2024	1233093	Workshop Tablet Entered -ERROR - Fault type not set	replaced new bell swtich \ repaired broken air line	1541420
214	12/11/2024	1232756	Workshop Tablet Entered -Body - Front_Door Operati	checked front works ok 30 times close and open lube rollers	1541420
214	12/11/2024	1232756	Consumables		1541420
214	12/10/2024	1232648		VEHICLE SAFETY INSPECTION completed vsi	1541420
214	12/10/2024	1232648		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed reter	1541420
214	12/9/2024	1232218	Drv entered - Body Front_Door Operation Faulty	replaced broken bolt and replaced new bolt inside front door	1540490
214	12/9/2024	1232410	Drv entered - Body Front_Door Operation Faulty	could not fault released for service	1540490
214	12/9/2024	1232218	Consumables		1540490
214	12/9/2024	1232410	Consumables		1540490
214	12/6/2024	1231897		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Completed CCTV A :	1540490
214	12/1/2024	1226521	Fault#:39399 - Ops Entered - Fault - Breakdown Tyre f	Attended break down. Found front bumper bar damaged and air hos	1539873
214	11/28/2024	1230298	Workshop Tablet Entered -Body - Front_Door Operati	checked front door operation could not find fault f/door operating r	1539123
214	11/28/2024	1230298	Consumables		1539123
214	11/28/2024	1230298	Consumables		1539123
214	11/26/2024	1229665		CARRY OUT A SERVICE AS PER CHECK LIST completed A service fixed	1538699
214	11/26/2024	1229665	Consumables		1538699

214	11/26/2024	1229665 Consumables		1538699
214	11/25/2024	1229395 SWITCH COMBINATION MERC BENZ 0500LE A0085450124		1538377
214	11/25/2024	1229395 Ops Entered - Fault - Dash Switches Not Working - Ro	fitted new indicator stalk	1538377
214	11/21/2024	1227946 DECAL WHEELCHAIR		1537536
214	11/21/2024	1227946 DECAL EMERGENCY EXIT PRESS BUTTON UNDER BUMPER		1537536
214	11/21/2024	1227946 DECAL VENTURA ROUTE SMALL 490MM x 145MM		1537536
214	11/21/2024	1227946 DOOR PILLAR RUBBER		1537536
214	11/21/2024	1227946	fit up 2 bumper corners and bumper centre2 headlight corners and	1537536
214	11/20/2024	1227946	perp maskup and paint black wheels all front parts	1537536
214	11/20/2024	1227946 HARDENER DEBEER FAST 2.5L(F3255)		1537536
214	11/20/2024	1227946 PRIMER DEBEER WHITE HS 3LTR(F3988)		1537536
214	11/19/2024	1227946	repair left and right hed light corners and front put body filer sender	1537536
214	11/19/2024	1227946	fitup front panels removed panels and put into spray booth.	1537536
214	11/18/2024	1227946	take off bumper bar	1537536
214	11/12/2024	1226683 Fit axle to the bus and complete break test report due	Fitted back N/S axle tensioned bolt 420nm. test the brake fitted bac	1537536
214	10/18/2024	1221735 Workshop Tablet Entered -ERROR - Fault type not set	removed the rear seats took the bracket off and cleaned it up on the	1534590
214	10/18/2024	1221904 Consumables		1534590
214	10/18/2024	1221904 Workshop Tablet Entered -Elec and Light - Exterior Lig	Replaced blown globe.	1534590
214	10/17/2024	1221071 REPLACE ANTI GRAFFITI FILM. AU	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT373553	1534590
214	10/17/2024	1221657 Consumables		1534590
214	10/17/2024	1221657 Workshop Tablet Entered -Elec and Light - Exterior Lig	replaced n/s front head light bulb	1534590
214	10/15/2024	1221071 Vandalism REPLACE ANTI GRAFFITI FILM. AUDIT 1118. Completed by GlassProtech 14.10.2024 - SM		1534271
214	10/8/2024	1219184 Consumables		1533225
214	10/8/2024	1219184 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 5 and 6 wheel nuts. (Odometer 533422kms).	1533225
214	10/8/2024	1219184 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 5 and 6 wheel nuts. (Odometer 533422kms).	1533225
214	10/7/2024	1218952 VALVE AIR FILTER CHECK 22mm CYCLONE		1533225
214	10/7/2024	1218952 AIR DRYER ASSY MERC 0500LE A0004302915		1533225
214	10/7/2024	1218952	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST carried out air sy	1533225
214	10/7/2024	1218952 SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1533225
214	10/7/2024	1218952 CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1533225
214	10/4/2024	1218651 PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BU DONE		1533225
214	10/3/2024	1218361 Mechanic entered - Fluid Leaks Other R/H rear hub se	Removed wheels on Pos 5 & 6 and removed hub. Removed seals an	1533185
214	10/3/2024	1218361 SEAL KIT REAR HUB MERC BENZ 0500LE E3 - E5 1F1304		1533185
214	10/1/2024	1217701	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1532780
214	10/1/2024	1217701	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1532780
214	9/24/2024	1216404	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST completed dif	1532172
214	9/24/2024	1216404 OIL DIFFERENTIAL SYNGEAR 75W-140 VALVOLINE		1532172
214	9/11/2024	1213887 Consumables		1529915
214	9/11/2024	1213887 BusMinder - Cord issue	Twice entered.	1529915
214	9/11/2024	1213887 Ops Entered - Fault - Driver Tablet No Power - Route:	Checked in the morning - 90% and charging.	1529915
214	9/4/2024	1212300	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list	1528670
214	9/4/2024	1212300 FILTER DRYER AIR COND THERMO KING 2750300 DML305R		1528670
214	9/4/2024	1212300 FAN CONDENSOR A/C CITI-RT		1528670
214	9/4/2024	1212300 RELAY AIR CONDITIONING 5 PIN THERMOKING		1528670
214	9/4/2024	1212300 RELAY 5 PIN CHANGE-OVER C/W DIODE		1528670
214	9/4/2024	1212300	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replace righe side nu	1528670
214	9/3/2024	1212232 Consumables		1528670
214	9/3/2024	1212232 Workshop Tablet Entered -Elec and Light - Exterior Lig	Replaced blown globe.	1528670
214	8/29/2024	1210620 Workshop Tablet Entered -Elec and Light - Indicators	replaced new globe	1527343
214	8/28/2024	1210345 Drv entered - Elec and Light Exterior Lights	replaced new globe	1527343
214	8/28/2024	1210566	COMPLETED BY ATS 17/8/2024	1527343
214	8/26/2024	1193038 Consumables		1527583
214	8/26/2024	1193038	removed and replaced sensitive edge door seals on bothy front Pax	1527158
214	8/21/2024	1193038 AU-24157-2115 - Nosing Rubber	Creditor #:CT-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O	1527583
214	8/21/2024	1193038 CONSUMABLE DELIVERY CHARGE	Creditor #:CT-SMC001 SMC CORPORATION (AUSTRALIA) PTY LTD P/O	1527583
214	8/17/2024	1208152 Consumables		1526240
214	8/17/2024	1208152 Drv entered - Body Drivers Seat Controls	Checked driver seat controls all operating normally. No faults found.	1526240
214	8/7/2024	1205843	VEHICLE SAFETY INSPECTION completed VSI pressure wash eng and	1524860
214	8/7/2024	1205843	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS COMPLETED ret	1524860
214	8/7/2024	1205965 Mechanic entered - Vandalism Vandalism/ Graffiti Int	clean graffiti	1524860
214	8/7/2024	1205968 Mechanic entered - Suspension Other n/s rear of fron	replaced n/s rear of front air bag	1524860
214	8/7/2024	1205968 AIRBAG FRT/RR MERC BENZ 0500LE E3 - E5 OH1830 49Y2200		1524860
214	8/7/2024	1193038 Service	Parts ordered on the 07.08.2024	1524860
214	8/7/2024	1193038 Manifold Stud M8 x 1.25 x 50Lo	Creditor #:CT-BUR001 BURSON AUTOMOTIVE PTY LTD P/O #:CT3700:	1524964
214	8/7/2024	1205847 Consumables		1524860
214	8/7/2024	1205847 Consumables		1524860
214	8/7/2024	1205847	CARRY OUT C SERVICE AS PER CHECK LIST completed c service	1524860
214	8/7/2024	1205847 OIL SAMPLE TEST KIT		1524860

214	8/7/2024	1205847	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1524860
214	8/7/2024	1205847	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1524860
214	8/7/2024	1205847	FILTER AIR MERC BENZ 0500LE E3 - E5 A0040941704		1524860
214	8/7/2024	1205847	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151		1524860
214	8/7/2024	1205847	FILTER FUEL/WATER SEPARATOR MERC 0500LE >E5 A0004771302		1524860
214	8/7/2024	1205847	FILTER POWER STEER SCANIA ALL MODELS		1524860
214	8/7/2024	1205847	Consumables		1524860
214	8/7/2024	1205847	Consumables		1524860
214	8/7/2024	1205847		CARRY OUT B SERVICE AS PER CHECK LIST completed b service	1524860
214	8/7/2024	1205847	OIL ENGINE ALL FLEET PLUS E900 15W-40		1524860
214	8/7/2024	1205847	Consumables		1524860
214	8/7/2024	1205847	Consumables		1524860
214	8/7/2024	1205847		CARRY OUT A SERVICE AS PER CHECK LIST completed a service	1524860
214	8/1/2024	1193038	Mechanic entered - Body Other both sensitive edge ri	Waiting on parts. 01.07.2024	1524351
214	8/1/2024	1193038	Mechanic entered - Body Other both sensitive edge ri	Ordered new rubbers with Jess. 06.06.2024	1524351
214	7/30/2024	1203973	Drv entered - Wipers and Washers Wipers Not_Cleari	Tested lubed mechanism - working good.	1523307
214	7/30/2024	1203980	Drv entered - Wipers and Washers Wipers Noisy	Ref WO#1203973.	1523307
214	7/30/2024	1203978	Drv entered - A/C Heating Not Heating	Tested - engine 70C saloon 19C Demister 25C outside 7C. No fault fo	1523307
214	7/23/2024	1202235		fitted new gear selector.	1522204
214	7/23/2024	1202577	Workshop Tablet Entered -Elec and Light - Warning Li	Battery light on because bus was not running. Instructed driver how	1522204
214	7/23/2024	1202577	Consumables		1522204
214	7/22/2024	1202235	Mechanic entered - Gearbox Driveline Other Gear seli	I've ordered a new gear selector.	1522204
214	7/22/2024	1202235	SELECTOR GEAR PANEL 5 BUTTON 12PIN		1522204
214	7/20/2024	1202199		Assisted with A Service.	1522204
214	7/20/2024	1202199		CARRY OUT A SERVICE AS PER CHECK LIST A service complete.	1522204
214	7/20/2024	1202199	Consumables		1522204
214	7/20/2024	1202199	Consumables		1522204
214	7/18/2024	1201502		Brought vehicle up to operating temperature. checked Temperature	1522151
214	7/17/2024	1201502	Drv entered - A/C Heating Not Heating	outside temp 11 degress engine temp 40 ac vents 10 degress demist	1522151
214	7/16/2024	1201242	Drv entered - Body Water Leaks Roof	resealed roof	1522151
214	7/15/2024	1200480	Ops Entered - Fault - Elec and Light Indicators Not Wo	checked indicator all ok	1521636
214	7/15/2024	1200480	Consumables		1521636
214	7/13/2024	1200427	Workshop Tablet Entered -Elec and Light - Exterior Li	replaced o/s front indicator bulb	1521636
214	7/13/2024	1200427	Consumables		1521636
214	7/11/2024	1199823	Drv entered - Body Water Leaks Roof	removed and resealed top roof and side windows	1521417
214	7/11/2024	1199823	SAUSAGE BLACK SIKA		1521417
214	7/6/2024	1198800	Ops Entered - Fault - A/C Heating Not Heating - Rout	heater heating to around 22 degrees after 15 mins	1520432
214	7/6/2024	1198829	Workshop Tablet Entered -Gearbox Driveline - Tempe	Checked - working good.	1520432
214	7/6/2024	1198799	Workshop Tablet Entered -Elec and Light - Indicator ri	replaced o/s indicator globe and parker globe	1520432
214	7/6/2024	1198799	Consumables		1520432
214	7/6/2024	1198882	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WF	Done	1520432
214	7/3/2024	1197887	Workshop Tablet Entered -Body - Rear_Door Operatic	adjusted rear door sensitive edge	1519554
214	6/29/2024	1193048		removed old number plate and fitted new one to rear of bus	1519554
214	6/28/2024	1193037	Mechanic entered - Engine Other Radiator fan shroud	Replaced P clamp shroud not in country but still RWC.	1519686
214	6/19/2024	1193774	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT366432 R	1518503
214	6/12/2024	1193774		VEHICLE SAFETY INSPECTION	1516986
214	6/12/2024	1193774		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1516986
214	6/12/2024	1193774		VEHICLE SAFETY INSPECTION	1516986
214	6/12/2024	1193774		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1516986
214	6/12/2024	1193774		ANNUAL SAFETY INSPECTION SERIAL # RSI065181 WORKSHOP SUPE	1516986
214	6/11/2024	1193191	STONEGUARD PLUS SZ L253 1000ML		1516986
214	6/7/2024	1193193	Mechanic entered - Vandalism Vandalism/ Graffiti Int	cleaned graffiti from rear of seats	1516211
214	6/7/2024	1193037	GASKET ENGINE OIL COOLER MERC	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT366250 Receiving	1517244
214	6/7/2024	1193195	Mechanic entered - Body Passenger Seat Torn Both fc	replaced gas struts on forward facing flip seats and resecured moun	1516211
214	6/7/2024	1193194	Mechanic entered - Body Other under body spray on	replaced emergency exit decal and no smoking decal cleaned rever:	1516211
214	6/7/2024	1193195	STRUT GAS STAY LIFT UP SEAT		1516211
214	6/7/2024	1193195	STRUT GAS STAY LIFT UP SEAT		1516211
214	6/7/2024	1193194	SWITCH STOP YELLOW (62628)(50V2242)		1516211
214	6/7/2024	1193194	SWITCH STOP YELLOW (62628)(50V2242)		1516211
214	6/7/2024	1193192	Mechanic entered - Body Body Damage N/S front wh	removed locking pin straightened sharp edge on centre panel	1516211
214	6/7/2024	1193191	Mechanic entered - Body Other under body spray on	refreshed/touched up body deadener	1516211
214	6/7/2024	1193191	STONEGUARD PLUS SZ L253 1000ML		1516211
214	6/6/2024	1193037	Mechanic entered - Engine Other Radiator fan shroud	Ordered replacement parts with Jess	1516211
214	6/6/2024	1192989	Random check.	Random Check completed. All defects entered into TIMS	1516211
214	6/6/2024	1193048	Mechanic entered - Body Body Damage Rear number	Ordered number plate.	1516211
214	6/4/2024	1192377	Engine and radiator wash	carried out engine and radiator wash	1515610
214	5/31/2024	1191910	Mechanic entered - Elec and Light Exterior Lights fron	replaced n/s indicator light complete	1515419
214	5/31/2024	1191910	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1515419

214	5/31/2024	1191910 Consumables			1515419
214	5/23/2024	1094266 Drv entered - A/C Heating Not Heating	Tested - ok.		1513805
214	5/23/2024	1190031 Drv entered - Driver Tablet No Power	Checked in the morning - 63% and charging. No fault found.		1513805
214	5/23/2024	1190030 Drv entered - Consat Driver Touch Screen	Tested screen tested communication with OCC - no fault found.		1513805
214	5/23/2024	1190030 Consumables			1513805
214	5/23/2024	1190031 Consumables			1513805
214	5/21/2024	1189674 Driver Tablet Entered -Elec and Light - Warning Light (checked vehicle for fault codes. only inactive faults present. cleared		1513572
214	5/21/2024	1189674 Consumables			1513572
214	5/16/2024	1188780	PRE ANNUAL SAFETY INSPECTION CHECK Carried out Pre-annual Safe		1512799
214	5/16/2024	1188780	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Carried out B Servic		1512799
214	5/16/2024	1188810	PRE ANNUAL SAFETY INSPECTION CHECK Ref WO#1188780.		1512799
214	5/16/2024	1188810	CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Carried out B Servic		1512799
214	5/16/2024	1188798	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST done		1512799
214	5/10/2024	1187507 Workshop Tablet Entered -Fluid Leaks - Rear of bus cc	l checked visually for coolant leaks but there was nothing other thar		1511650
214	4/24/2024	1184449 Workshop Tablet Entered -A/C Heating - Demister No	Tested demister and A/C for operation. A/C working normally. Demi		1509475
214	4/24/2024	1184449 KNOB HEATER CONTROL			1509475
214	4/22/2024	1183918	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST transmission		1508963
214	4/22/2024	1183918 OIL ZF GEARBOX SYNTHETIC ECOFLUID A PLUS			1508963
214	4/22/2024	1183918 FILTER ZF ECOMAT GEARBOX 4139-298-038 3098081			1508963
214	4/22/2024	1183865	VEHICLE SAFETY INSPECTION completed VSI and retensioned wheel r		1508963
214	4/22/2024	1183865	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS vehicle safety ct		1508963
214	4/22/2024	1183897 Consumables			1508963
214	4/22/2024	1183897 Mechanic entered - Elec and Light Interior Lights salor	replaced fluoro lighting tested okay		1508963
214	4/22/2024	1183868 Consumables			1508963
214	4/22/2024	1183868	CARRY OUT A SERVICE AS PER CHECK LIST		1508963
214	4/22/2024	1183868 Consumables	completed a service		1508963
214	4/16/2024	1182584 Workshop Tablet Entered -Gearbox Driveline - cannot	Cleaned and lubed gear selector.		1508062
214	4/11/2024	1181514 Workshop Tablet Entered -Body - Windows FrontFror	removed and replaced new blind rod \ mountings		1507278
214	4/11/2024	1181514 Consumables			1507278
214	3/27/2024	1179068 PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SA DONE			1504704
214	3/26/2024	1178840 Workshop Tablet Entered -Body - Drivers Seat Contro	install second driver seat		1504523
214	3/26/2024	1178840 Ops Entered - Fault - Body Drivers Seat Controls - Ro	assisted with seat instal		1504523
214	3/26/2024	1178840 Consumables			1504523
214	3/13/2024	1176121	TEST AND TAG DONE 6/3/24		1501883
214	3/8/2024	1175381	VEHICLE SAFETY INSPECTION Carried out safety Inspection.		1501400
214	3/8/2024	1175381	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe		1501400
214	3/8/2024	1175420 Workshop Tablet Entered -Driver Tablet - Not Chargin	Repaired refer w/o 1175421.		1501400
214	3/8/2024	1175421 Ops Entered - Fault - Driver Tablet Not Charging - Ro	Repaired wiring to driver tablet.		1501400
214	3/8/2024	1175419 Ops Entered - Fault - Driver Tablet No Power - Route:	Repaired refer w/o 1175421.		1501400
214	3/8/2024	1175418 Ops Entered - Fault - Driver Tablet Not Charging - Ro	Repaired refer w/o 1175421.		1501400
214	3/8/2024	1175418 Consumables			1501400
214	3/8/2024	1175419 Consumables			1501400
214	3/8/2024	1175420 Consumables			1501400
214	3/8/2024	1175421 Consumables			1501400
214	2/13/2024	1169383 Workshop Tablet Entered -A/C Heating - Not Cooling	checked a/c clutch on inside vents blowing 20 degrees out side 36 de		1496585
214	2/7/2024	1167905 Mechanic entered - Wheels and Tyres Wheel Nut Ret	completed retension		1495893
214	2/7/2024	1167905	completed retension		1495893
214	2/7/2024	1167905 Consumables			1495893
214	2/6/2024	1167645 Mechanic entered - Elec and Light Other Headlight sw	Replaced headlight switch.		1495870
214	2/6/2024	1167645 SWITCH HEADLIGHT MERC BENZ 0500LE E3 50V2220			1495870
214	2/6/2024	1167645 HEADLIGHT SWITCH SHIELD			1495870
214	2/6/2024	1167645 KNOB HDLIGHT SWITCH MERC BENZ 0500LE E3			1495870
214	2/6/2024	1167645 Consumables			1495870
214	2/6/2024	1167496 Workshop Tablet Entered -Brakes - Foot_Brakes Pullir	assisted dave with new caliper		1495870
214	2/6/2024	1167496 Mechanic entered - Brakes Other R/H rear brake pads	Replaced OSR brake rotor and pads		1495870
214	2/6/2024	1167496	Replaced rotor and pads on L/H/RR. Refit all rear wheels and torque		1495870
214	2/6/2024	1167496 BRAKE DISC FRT / RR MERC BENZ 0500LE E3>E6 50F3339			1495870
214	2/6/2024	1167496 BRAKE PADS FRT / RR MERC 0500LE E3>E5 49G7501BERAL			1495870
214	2/6/2024	1167497	Checked brakes anfd found L/H/RR calipier seized causing brakes to		1495870
214	2/6/2024	1167496 SEAL KIT REAR HUB MERC BENZ 0500LE E3 - E5 1F1304			1495870
214	2/6/2024	1167496 BOLT REAR DISC TORX HD MERC BENZ 0500LE A9429902804			1495870
214	2/6/2024	1167496 CALIPER BRAKE LH/RR MERC BENZ 0500LE A0024207183			1495870
214	2/1/2024	1166572 SEAT CUSH SINGLE CEN CVR CI			1495129
214	2/1/2024	1166572	CARRY OUT A SERVICE AS PER CHECK LIST A service complete.		1495129
214	2/1/2024	1166572	Assisted frank with A service. Replaced seat cushion.		1495129
214	2/1/2024	1166572 Consumables			1495129
214	2/1/2024	1166572 Consumables			1495129

214	1/13/2024	1163296	Mechanic entered - Body Other back seat n/s seat bræ rremoved and welded cracked rear seats	1493456
214	1/13/2024	1163296	Consumables	1493456
214	1/11/2024	1162910	VEHICLE SAFETY INSPECTION completed VSI replaced o/s side indicat	1493456
214	1/11/2024	1162910	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS COMPLETED ret	1493456
214	1/11/2024	1162978	Mechanic entered - Brakes Other o/s front booster ai Ordered hose repair.	1493456
214	1/11/2024	1162978	undo front o/s brake booster air line after repair fitted back the air l	1493456
214	1/11/2024	1162978	Fabricate front brake booster	Creditor #:CT-HEM001 HEMA'S HOSE SERVICES P/O #:CT357467 Rece
214	1/11/2024	1162911	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed cctv a se	1493456
214	1/5/2024	1161646	Workshop Tablet Entered -Body - Windows Frontdrivi Checked - no fault found. Lubed rails.	1492460
214	1/5/2024	1161646	Consumables	1492460
214	1/3/2024	1160933	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 P1 done by refuelers	1492170
214	12/23/2023	1159794	Consumables	1491411
214	12/23/2023	1159794	Mechanic entered - Elec and Light Flat Batteries	Jump started bus after lights were left on. Tested batteries and both
214	12/8/2023	1156942	O-RING KIT SMALL VOSS A0309971748	1489668
214	12/8/2023	1156942	O-RING KIT LARGE VOSS A6739970145	1489668
214	12/8/2023	1156942	SILENCER AIR VALVE CLIP ON 69MM 432-407-070-0	1489668
214	12/8/2023	1156942	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE	1489668
214	12/8/2023	1156942	AIR DRYER ASSY MERC 0500LE A0004302915	1489668
214	12/8/2023	1156942	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401	1489668
214	12/8/2023	1156942	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed air sy	1489668
214	12/8/2023	1156942	HOSE COMP - UNLOADER MERC BENZ 0500 A0014292135 A0014292735	1489668
214	12/8/2023	1156942	COUPLING AIR HOSE - COMP MERC BENZ 0500LE A0089970889	1489668
214	12/8/2023	1156942	VALVE AIR FILTER CHECK 22mm CYCLONE	1489668
214	12/8/2023	1156942	VALVE CIRCUIT PROTECTION MERC BENZ 0500LE	1489668
214	11/30/2023	1155178	I also found the main belt was U/S and three main belt pulleys were	1488276
214	11/30/2023	1155178	BELT MICRO V SERPENT 9 RIB 2120mm LNG A0019935696	1488276
214	11/30/2023	1155178	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Tune up service coi	1488276
214	11/30/2023	1155178	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221	1488276
214	11/30/2023	1155178	PULLEY IDLER/ADJUSTER MERCEDES 0500LE(50N0041G)	1488276
214	11/22/2023	1153635	PTI Tablet Entered - CCTV has no Lights on seems to r inspected CCTV fuses wiring and connections. all ok. Hard Drive key	1486911
214	11/15/2023	1151999	Accident #56093 - OFFSIDE REAR	removed and replaced new coolant hatch
214	11/15/2023	1151999	HATCH PLAIN COOLANT SURROUND 165 x194MM(WHITE)	1485762
214	11/15/2023	1151999	LATCH DOOR COOLANT HATCH 1/4 TURN	1485762
214	11/14/2023	1151999	LAMP LED SIDE RED/AMBER PERE1 52-98002	1485762
214	11/14/2023	1151999	Accident #56093 OFFSIDE-Rear marker light and cool: replaced marker light	1485762
214	11/10/2023	1151403	Mechanic entered - Wheels and Tyres Wheel Nut Ret: Retensioned position 5 and 6 wheel nuts. (Odometer 1485653kms).	1485437
214	11/10/2023	1151403	Mechanic entered - Wheels and Tyres Wheel Nut Ret: Retensioned position 5 and 6 wheel nuts. (Odometer 1485653kms).	1485437
214	11/10/2023	1151403	Consumables	1485437
214	11/8/2023	1151091	VEHICLE SAFETY INSPECTION completed VSI CLEAN GRAFFITI replace	1485305
214	11/8/2023	1151091	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed reteti	1485305
214	11/8/2023	1151114	TYRE 295/80R22.5 RECAP	1485305
214	11/8/2023	1151114	Wheels and Tyres check/replace pos 3 tyre	replaced pos 5 and 6 tyres with new recap
214	11/8/2023	1151114	Consumables	1485305
214	11/2/2023	1145963	replace engine ECU smal plug	1484810
214	11/2/2023	1146056	chchange the new hard drive seted up	1484810
214	10/27/2023	1148952	Consumables	1483745
214	10/27/2023	1148952	PTI Tablet Entered -Elec and Light - Exterior Lights L/t replaced new globe	1483745
214	10/23/2023	1146056	checked over cctv and rebooted no more warning light	1483077
214	10/20/2023	1145963	ECU PLUG 16 PIN	Creditor #:CT-WHI001 WHITEHORSE TRUCK CENTRE P/O #:CT352744
214	10/16/2023	1146064	Consumables	1481779
214	10/16/2023	1146064	Driver Tablet Entered -Elec and Light - Desto FaultMyl Replaced terminal tested and ok.	1481779
214	10/13/2023	1146064	Driver Tablet Entered -Elec and Light - Desto FaultMyl found broken connection at ticket machine relay. Notified supervisor	1481779
214	10/13/2023	1146056	Driver Tablet Entered -CCTV - Warning Light On	CCTV recording and live on server. Ordered new hard drive as it was
214	10/13/2023	1146056	DRIVE SOLID STATE 1TB (17128E-	Creditor #:CT-STR100 STREAMAX AUSTRALIA P/O #:CT352544 Receiv
214	10/13/2023	1146056	CONSUMABLE - DELIVERY CHARGE	Creditor #:CT-STR100 STREAMAX AUSTRALIA P/O #:CT352544 Receiv
214	10/12/2023	1145963	Engine and transmission wash.	after when the engine was cleaned put some dielectrical grease to p
214	10/12/2023	1145963	engine gearbox chassis wash	1481779
214	10/10/2023	1145390	Consumables	1481286
214	10/10/2023	1145390	Consumables	1481286
214	10/10/2023	1145390	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709	1481286
214	10/10/2023	1145390	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709	1481286
214	10/10/2023	1145390	CARRY OUT B SERVICE AS PER CHECK LIST completed servive	1481286
214	10/10/2023	1145390	OIL SAMPLE TEST KIT	1481286
214	10/10/2023	1145390	BREATHER OIL MIST MERC BENZ 0500LE A5410100163	1481286
214	10/10/2023	1145390	Assisted with B Service.	1481286
214	10/10/2023	1145390	Consumables	1481286
214	10/10/2023	1145390	Consumables	1481286
214	10/10/2023	1145390	CARRY OUT A SERVICE AS PER CHECK LIST completed service	1481286

214	10/6/2023	1144846 Consumables		1481049
214	10/6/2023	1144846 Workshop Tablet Entered -Body - Front_Door Operati	found bolt loose on top of door adjusted door and tightend bolt .	1481049
214	10/5/2023	1144335 Consumables		1480647
214	10/5/2023	1144335 Ops Entered - Fault - BusMinder No Power - Route: 9	Checked - 30% in the morning and charging.	1480647
214	10/2/2023	1143696 Workshop Tablet Entered -windscreen visor will not :	UNTWISTED VISOR IT NOW STAYS DOWN	1480016
214	9/28/2023	1143290 Consumables		1480016
214	9/28/2023	1143290 Ops Entered - Fault - Body Rear_Door Operation Fault	Checked doors several times - both front and rear open and close wi	1480016
214	9/28/2023	1143290 Ops Entered - Fault - Body Rear_Door Operation Fault	Inspected both front and rear doors no problem found with door op	1480016
214	9/14/2023	1139675	checked the circuit repaire the connections	1479273
214	9/14/2023	1140289 SENSOR LEVELLING VALVE ECAS MERC BENZ 0500LE A0015420018		1479273
214	9/14/2023	1140289	checked the circuits change the position sensor	1479273
214	9/14/2023	1139298 A/C A service	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT350503 Receivin	1479273
214	9/13/2023	1140289 Workshop Tablet Entered -Suspension - Kneel/ Raise	checked found kneel faulty [casba to look thursday]	1478898
214	9/12/2023	1140208 Workshop Tablet Entered -A/C Heating - Not Heating	checked vents fans all working	1478898
214	9/12/2023	1140189 Consumables		1478898
214	9/12/2023	1140189 Consumables		1478898
214	9/12/2023	1140189	CARRY OUT A SERVICE AS PER CHECK LIST completed A service	1478898
214	9/8/2023	1139675 Workshop Tablet Entered -Wipers and Washers - Wip	Checked wipers and found n/w on fast speed. Possible wiper motor	1478595
214	9/7/2023	1139298	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Done by Cameron (C	1478418
214	9/5/2023	1138394 Consumables		1477628
214	9/5/2023	1138394 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 1 and 2 wheel nuts. (Odometer 1477819kms).	1477628
214	9/5/2023	1138394 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 1 and 2 wheel nuts. (Odometer 1477819kms).	1477628
214	9/4/2023	1138149	VEHICLE SAFETY INSPECTION Safety inspection complete.	1477628
214	9/4/2023	1138149 SEAT CUSH DBL CEN 680 CVR - CL		1477628
214	9/4/2023	1138149 SEAT CUSH SINGLE CEN CVR CI		1477628
214	9/4/2023	1138149	Replaced both front tyres. L/H front had a flat spot.	1477628
214	9/4/2023	1138149 O-RING KIT LARGE VOSS A6739970145		1477628
214	9/4/2023	1138149 AIRBAG FRT/RR MERC BENZ 0500LE E3 - E5 OH1830 49Y2200		1477628
214	9/4/2023	1138149 TYRE 295/80R22.5 NEW		1477628
214	9/4/2023	1138149	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1477628
214	9/4/2023	1138149	Replaced the R/H front of rear air bag.	1477628
214	9/4/2023	1138149	Replaced the sensitive edge switch on the rear door. I also adjusted	1477628
214	9/4/2023	1138149	Replaced leaking air fittings and broken seat bases assisted frank wi	1477628
214	8/25/2023	1135813 Consumables		1476640
214	8/25/2023	1135813 Drv entered - BusMinder Damaged	removed and replaced new converter bus minder	1476640
214	8/25/2023	1135813 USB 5V 3A DUAL CONVERTER MODULE BUS MINDER		1476640
214	8/25/2023	1136056	Done by ATS 15/8/23 CT347555 INV T24-305889	1476640
214	8/21/2023	1134636 Drv entered - Fluid Leaks Rear of bus	presure test did not found any defects	1476056
214	8/10/2023	1132335 Drv entered - A/C Heating Not Heating	Checked A/C and was ok demister 27 degrees A/C 21 degrees outsid	1474474
214	8/10/2023	1132470 PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMI	Done by Refuelers	1474474
214	8/9/2023	1131954 Consumables		1474474
214	8/9/2023	1131954 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 3 and 4 wheel nuts. (Odometer 474677kms).	1474474
214	8/9/2023	1131954 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 3 and 4 wheel nuts. (Odometer 474677kms).	1474474
214	8/8/2023	1131762 Consumables		1474474
214	8/8/2023	1131762 Wheels and Tyres; Check/Replace tyre on Pos 3	replaced 2 new tyres \ replaced new claw catche	1474474
214	8/8/2023	1131762 TYRE 295/80R22.5 RECAP		1474474
214	8/8/2023	1131762 STEEL CLAW CATCHES (SET UES2132)		1474474
214	7/31/2023	1130078 Workshop Tablet Entered -A/C Heating - Not Heating	Checked A/C 23 degrees demist 28 degrees outside temp 12 degree	1473377
214	7/31/2023	1129956 Consumables		1473377
214	7/31/2023	1129956 Driver Tablet Entered -Elec and Light - Two Way Radic	Checked with OPS - no fault found.	1473377
214	7/24/2023	1128496 Drv entered - A/C Heating Demister Not Heating	tested operation of demister. warm air is coming from demister afte	1472198
214	7/24/2023	1128496	Tested demister and A/C with Stu both are working well	1472198
214	7/21/2023	1128041 Workshop Tablet Entered -BusMinder - Not Charged \	In the morning - 63% and charging.	1471485
214	7/21/2023	1128041 Consumables		1471485
214	7/20/2023	1127764 Drv entered - BusMinder Unable To Log In	Charging good.	1471485
214	7/20/2023	1127764 Consumables		1471485
214	7/20/2023	1127851 Workshop Tablet Entered -Body - Rear_Door Operati	fix the RPD problem change the door swich working now	1471485
214	7/20/2023	1125541 SWITCH DR CONTACT NORMALLY OPEN M22-K10		1471485
214	7/20/2023	1125541	fix the RPD problem change the door swich working now	1471485
214	7/20/2023	1125541 Consumables		1471485
214	7/20/2023	1127851 Consumables		1471485
214	7/19/2023	1127594 PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PT	Done by Ethan.	1471485
214	7/18/2023	1125861 CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT346803 R	1471775
214	7/13/2023	1125541	checked the RPD unit fix caple of brocken wire test is the door open	1470374
214	7/12/2023	1125861	VEHICLE SAFETY INSPECTION	1470374
214	7/12/2023	1125861	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1470374
214	7/12/2023	1125861	ANNUAL SAFETY INSPECTION SERIAL #_RSI 057332 WORKSHOP SU	1470374
214	7/12/2023	1125541	I checked the door operation and found that both front and rear dor	1470374

214	7/12/2023	1125958	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTAL Done by Volgren.		1470374
214	7/11/2023	1125541	Workshop Tablet Entered -Body - Front_Door Operati	Replaced the front interior door switch. Door is operating correctly r	1470374
214	7/11/2023	1125541	BUTTON RED EMRGENCY EXIT		1470374
214	7/11/2023	1125559	Workshop Tablet Entered -Brakes - Foot_Brakes Pullir Test drive - no fault found.		1470374
214	7/6/2023	1124039	STONEGUARD PLUS SZ L253 1000ML		1470174
214	7/6/2023	1124039		repaired rust on step and sprayed black	1470174
214	7/6/2023	1124039	Consumables		1470174
214	7/4/2023	1124038	Random check and chassis wash.	completed random check and chassis wash	1469807
214	7/4/2023	1124039		checked rust after Sandy washed under body rusted through small p	1469807
214	7/4/2023	1124038	Consumables		1469807
214	6/28/2023	1122971	Bus for AMTEK.	Done	1469115
214	6/28/2023	1122971	Consumables		1469115
214	6/23/2023	1121371	STONEGUARD PLUS SZ L253 1000ML		1468751
214	6/23/2023	1121371		preped and sprayed body deadner	1468751
214	6/23/2023	1121371	Consumables		1468751
214	6/23/2023	1121372	VALVE ECAS MERC BENZ 0500LE -> 000507 49V0022WABCO		1468751
214	6/23/2023	1121372	BUTTON CLIPPARD DOOR VALVE 11916-2		1468751
214	6/23/2023	1121372	O-RING KIT LARGE VOSS(A6739970145)		1468751
214	6/23/2023	1121372	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1468751
214	6/23/2023	1121372	TEST CONNECTION SCHREUDER TYPE 22mm		1468751
214	6/23/2023	1121372	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1468751
214	6/23/2023	1121372	MALE ELBOW 6MM X 1/8		1468751
214	6/23/2023	1121372	MALE RUN TEE 6MM X 1/8		1468751
214	6/23/2023	1121372		replaced ecas valve body replaced air fitting seal kit repaired other a	1468751
214	6/21/2023	1121373	LAMP HEAD INSERT HELLA 100MM L/FLOOR 0500 29204		1468431
214	6/21/2023	1121373	LAMP HEAD INSERT HELLA 100MM L/FLOOR 0500 29204		1468431
214	6/21/2023	1121373	Consumables		1468431
214	6/21/2023	1121371		secured rear seat	1468431
214	6/21/2023	1121372		ecas control valve needs replacing need to rebook another day CHE	1468431
214	6/20/2023	1121373	Workshop Tablet Entered -headlights are very dull giv	replaced low beam head lights both side adjust the beam ray both s	1468391
214	6/20/2023	1121371	Mechanic entered - Body Other Body deadner commi	pressure wash bottom of the bus	1468391
214	6/20/2023	1121372	Mechanic entered - Air System Other small air leak frc	was fixing air leakage eco body valve cross tread had to pull out corr	1468391
214	6/20/2023	1121372	VOSS NUT 232 22MM MERC BENZ 0500LE A000997483401		1468391
214	6/16/2023	1120941		VEHICLE SAFETY INSPECTION completed VSI	1467843
214	6/16/2023	1120941		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed reter	1467843
214	6/16/2023	1120945		PRE ANNUAL SAFETY INSPECTION CHECK completed pre rsi with VSI	1467843
214	6/16/2023	1120945		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed service	1467843
214	6/16/2023	1120945	Service	Assisted with Pre-annual Safety Inspection.	1467843
214	6/15/2023	1120544	Mechanic entered - Body Other radiator panel loose	removed and secured radiator panel	1467674
214	6/15/2023	1120544	Consumables		1467674
214	6/15/2023	1120529		worked with Csaba for fire safety inspection training.	1467674
214	6/15/2023	1120529		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fir	1467674
214	5/19/2023	1115801		completed retension	1464272
214	5/19/2023	1115801	Mechanic entered - Wheels and Tyres Wheel Nut Ret	completed retension	1464272
214	5/19/2023	1115801	Consumables		1464272
214	5/19/2023	1115590		CARRY OUT A SERVICE AS PER CHECK LIST A service complete.	1464272
214	5/19/2023	1115590		assisted frank with A service	1464272
214	5/19/2023	1115590		Replaced position 6 tyre with a run out.	1464272
214	5/19/2023	1115590	Consumables		1464272
214	5/19/2023	1115590	Consumables		1464272
214	5/19/2023	1115590	Consumables		1464272
214	5/18/2023	1115336	Elec and Light Exterior Lights- headlight	Replaced headlight globe headlights working	1464272
214	5/18/2023	1115336	Consumables		1464272
214	5/10/2023	1113495	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 3 and 4 wheel nuts. (Odometer 463316kms).	1463096
214	5/10/2023	1113495	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 3 and 4 wheel nuts. (Odometer 463316kms).	1463096
214	5/10/2023	1113495	Consumables		1463096
214	5/8/2023	1113192	PTI Tablet Entered -Wheels and Tyres - Flat or Leaking	replaced p3 tyre with runout tyre	1462619
214	5/8/2023	1113192	Consumables		1462619
214	5/6/2023	1112840	Drv entered - Gearbox Driveline Rough Gear Change	Checked oil level test drive - gears change up and down smooth. No	1462619
214	5/3/2023	1112148		VEHICLE SAFETY INSPECTION Carried out Safety Inspection. Repaired	1462240
214	5/3/2023	1112148		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1462240
214	5/3/2023	1112148	O-RING KIT LARGE VOSS(A6739970145)		1462240
214	5/3/2023	1112229	Mechanic entered - Vandalism Vandalism/ Graffiti Int	cleaned graffiti	1462240
214	4/1/2023	1106833	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned 3+4	1459135
214	4/1/2023	1106833	Consumables		1459135
214	3/30/2023	1106559	Wheels and Tyres check/replace pos 3 tyre.	replaced pos 3 with runout tyre	1458955
214	3/30/2023	1106559	Consumables		1458955
214	3/21/2023	1104242	Driver Tablet Entered - Indicators Not returning to its	Not a roadworthy issue.	1457524

214	3/16/2023	1103251	PAINTSHOP - PAINT PANEL X 1 AS REQUESTED BY PAK	perp and paint	1457112
214	3/15/2023	1103000	Mechanic entered - Body Other O/S/F side & middle f	needs new panel on o\s\ [waiting on panels] rreplaced 1 new pan	1457042
214	3/15/2023	1103027	BODYSHOP - FABRICATE PANEL X 1 AS REQUESTED BY	made new panel	1457042
214	3/15/2023	1103027	SHEET ALUMIN 2400x1200x2mm		1457042
214	3/3/2023	1100785	A/C Heating	Replaced evaporator fan motors	1455796
214	3/2/2023	1100571	Consumables		1455626
214	3/2/2023	1100571	Indicator lights -no sound on dash and the indicator s	Not a Moorabbin bus	1455626
214	2/24/2023	1099112	Workshop Tablet Entered -A/C Heating - Not Cooling	c tested ok	1454992
214	2/24/2023	1099112	Workshop Tablet Entered -A/C Heating - Not Cooling	Tested ok	1454992
214	2/24/2023	1099112	Workshop Tablet Entered -A/C Heating - Not Cooling	Tested ok	1454992
214	2/24/2023	1099112	Ops Entered - Fault - A/C Heating Not Cooling - Route	Tested found clutch fuse blown check ohms across coil check wiring	1454992
214	2/24/2023	1099112	Workshop Tablet Entered -A/C Heating - Not Cooling	Tested ok	1454992
214	2/21/2023	1098297		VEHICLE SAFETY INSPECTION Carried out safety service. Removed an	1454451
214	2/21/2023	1098297		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1454451
214	2/21/2023	1098297	MUDFLAP 605MM X 330MM		1454451
214	2/16/2023	1097378		FIRE EXTINGUISHER TEST & TAG Done by ATS on PO CT337076 15.2.2	1453816
214	2/13/2023	1096186	Mechanic entered - Fluid Leaks Rear of bus Coolant le	Pressure tested the cooling system and found that the leak was com	1453216
214	2/13/2023	1096186	Mechanic entered - Fluid Leaks Rear of bus Coolant le	assisted frank replacing hose running along top of the engine	1453216
214	2/13/2023	1096186		Repaired the coolant leak at pipe on top of the engine. Pressure test	1453216
214	2/7/2023	1094266	CONDENSOR FAN A/C CITI-RT	Creditor #-:CT-DAN002 DANDENONG RADIATORS PTY LTD P/O #-:CT33	1454152
214	2/7/2023	1094266	Drv entered - A/C Heating Not Cooling IN THE DRIVER	Replaced right bank front and center evaporator fan motors right ou	1452808
214	2/6/2023	1094266	MOTOR A/C EVAPORATOR FAN	Creditor #-:CT-DAN002 DANDENONG RADIATORS PTY LTD P/O #-:CT33	1453051
214	2/2/2023	1094238	Consumables		1452103
214	2/2/2023	1094238	Mechanic entered - Wheels and Tyres Wheel Nut Ret	retensioned wheel nuts with stuart on p3 and p4	1452103
214	2/2/2023	1094238	Mechanic entered - Wheels and Tyres Wheel Nut Ret	retentioned wheel nuts with bishop	1452103
214	2/2/2023	1094266	Drv entered - A/C Heating Not Cooling IN THE DRIVER	tested A/C for operation. O/S boost fans not operating.	1452103
214	1/31/2023	1093924	Consumables		1451856
214	1/31/2023	1093924	Mechanic entered - Wheels and Tyres Damaged P3 ty	Replaced a runout tyre for P3 and bookback wheel nuts retension(D	1451856
214	1/31/2023	1093924	Mechanic entered - Wheels and Tyres Damaged P3 ty	replaced tyre in position 3 at 452104kms tyre wall was worn throug	1451856
214	1/16/2023	1090297	Ops Entered - Fault - A/C Heating Not Cooling - Route	repaired and replavced rebrand decal on rear	1450908
214	1/16/2023	1090297	PRESSURE PACK VOLGREN ORANGE		1450908
214	1/13/2023	1090297	Ops Entered - Fault - A/C Heating Not Cooling - Route	fibra glass rear corner [needs more work done]	1450908
214	1/13/2023	1090980		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Completed CCTV se	1450908
214	1/13/2023	1090980	Consumables		1450908
214	1/13/2023	1090980		CARRY OUT A SERVICE AS PER CHECK LIST A service completed and w	1450908
214	1/13/2023	1090980	Consumables		1450908
214	1/12/2023	1090297	AIR CON REFRIDGERANT		1450908
214	1/12/2023	1090297	NITROGEN DRY E SIZE		1450908
214	1/12/2023	1090297	Ops Entered - Fault - A/C Heating Not Cooling - Route	Test found unit unit has lost refrigerant traced back to weeping pipe	1450908
214	1/11/2023	1090297	Ops Entered - Fault - A/C Heating Not Cooling - Route	Checked - A/C compressor n/w. Bruce to have a look.	1450908
214	1/11/2023	1090297	Drv entered - A/C Heating Not Cooling	Multi entered	1450908
214	1/11/2023	1090297	Drv entered - A/C Heating Not Cooling	Multi entered	1450908
214	1/5/2023	1089461	Consumables		1450456
214	1/5/2023	1089461	Workshop Tablet Entered -BusMinder - Unable To Lo	removed connected wire charging ok	1450456
214	12/22/2022	1087717	Mechanic entered - Air System Air_Leak Rear	Repaired air leak.	1449138
214	12/20/2022	1087292	NO AIR IN DRIVER AREA	checked heating in drivers seat area air works with demister turned	1448616
214	12/20/2022	1087292	REGULATOR ALTERNATOR BOSCH 140AMP MERC 0500LE 1197311315		1448616
214	12/10/2022	1085853		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1447318
214	12/10/2022	1085853		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1447318
214	12/10/2022	1085874	Mechanic entered - Body Other Clippard valve leaking	Replaced clippard valve and button.	1447318
214	12/10/2022	1085874	BUTTON CLIPPARD DOOR VALVE 11916-2		1447318
214	12/10/2022	1085874	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1447318
214	12/10/2022	1085874	Consumables		1447318
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719	DRYER AIR ASSY MERC 0500LE(A0004302915)		1446169
214	11/29/2022	1083719	VALVE DRAIN CONDENSOR MERC 0500LE(A0054327401)		1446169
214	11/29/2022	1083719	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1446169
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719		Assisted rod	1446169
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719	O-RING KIT LARGE VOSS(A6739970145)		1446169
214	11/29/2022	1083719	VALVE AIR FILTER CHECK 22mm CYCLONE		1446169
214	11/29/2022	1083719		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed servi	1446169
214	11/22/2022	1082491	Engine- Pre-engine transmission and radiator wash.	Carried out Pre-summer wash.	1445247
214	10/28/2022	1078057	Ops Entered - Fault - Wipers and Washers Wipers Not	removed and replaced 2 wipers	1442217
214	10/28/2022	1078057	WIPER BLADE 900mm (SWB23)(N90)		1442217

214	10/28/2022	1078057	BOSTIK SAUSAGE BLACK		1442217
214	10/18/2022	1075948	PERFORM CAMPAIGN 10/22 WEAR A FACE MASK WH	Removed decals.	1441045
214	10/17/2022	1075675	Whilst driving the bus drive button popped out and t	Cleaned and lubed gear selector. Replaced D button.	1441045
214	10/1/2022	1072395		VEHICLE SAFETY INSPECTION completed VSI	1439322
214	10/1/2022	1072395		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed reter	1439322
214	10/1/2022	1072395		completed safety inspection	1439322
214	9/15/2022	1069881		CARRY OUT C SERVICE AS PER CHECK LIST carried out C service as pe	1437507
214	9/15/2022	1069881	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)		1437507
214	9/15/2022	1069881	FILTER FUEL MERC BENZ 0500LE -> E5 A0004771302		1437507
214	9/15/2022	1069881	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151		1437507
214	9/15/2022	1069881	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1437507
214	9/15/2022	1069881	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881		CARRY OUT B SERVICE AS PER CHECK LIST	1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881		CARRY OUT A SERVICE AS PER CHECK LIST carried out C service as per	1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/15/2022	1069881	Consumables		1437507
214	9/2/2022	1066931	REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT328166	1436597
214	9/2/2022	1067289	Mechanic entered - Elec and Light Exterior Lights L/H	Removed light two bolts was broken. Extracted faulty inserts install r	1436293
214	9/2/2022	1067289	Drv entered - Elec and Light Exterior Lights	Twice entered	1436293
214	9/2/2022	1067289	Consumables		1436293
214	8/31/2022	1066931	Rectify Vandalism -R2+R3	Repairs done by Glassprotect	1436137
214	8/26/2022	1066059		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list des	1435883
214	8/26/2022	1066059	FILTER DRYER AIR COND THERMO KING 2750300		1435883
214	8/26/2022	1066059	OIL COMPRESSOR AIR CONDITIONING		1435883
214	8/26/2022	1066059		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1435883
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707		CARRY OUT B SERVICE AS PER CHECK LIST	1435567
214	8/22/2022	1064707	OIL SAMPLE KIT AMPOL		1435567
214	8/22/2022	1064707	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709		1435567
214	8/22/2022	1064707	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1435567
214	8/22/2022	1064707	FILTER AIR MERC 0500LE(A0040941704)		1435567
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707	Consumables		1435567
214	8/22/2022	1064707		CARRY OUT A SERVICE AS PER CHECK LIST carried out A + B sevices	1435567
214	8/5/2022	1061453		Done by ATS on 04.08.2022 on Purchase order CT326135 - Shonah	1433699
214	7/19/2022	1056898	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT324972 R	1432085
214	7/13/2022	1056898		VEHICLE SAFETY INSPECTION Assisting RSI inspectors P/O CT324972	1431443
214	7/13/2022	1056898		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1431443
214	7/13/2022	1056898		ANNUAL SAFETY INSPECTION SERIAL # _____ WC	1431443
214	7/11/2022	1056448	Engine RSI Chassis wash	Completed chassis wash for RSI	1431239
214	7/11/2022	1056435	Mechanic entered - Engine Other remove weld and re	Removed snapped mount Welded muffler mount reinstalled repaire	1431239
214	7/8/2022	1056016	Mechanic entered - Wheels and Tyres Wheel Nut Ret	retension all rear	1431239
214	7/8/2022	1056016	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned all rear wheel nuts. (Odometer 431262kms).	1431239
214	7/8/2022	1056016	Consumables		1431239
214	7/6/2022	1055581	Mechanic entered - Body Other drivers seat knob	replaced new seat knob	1431239
214	7/6/2022	1055581	HANDLE HEIGHT & RAKE ORANGE		1431239
214	7/6/2022	1055581	Consumables		1431239
214	7/5/2022	1055422		assisted for service	1431239
214	7/5/2022	1055422		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1431239
214	7/5/2022	1055422		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1431239
214	7/5/2022	1055422		Assisting assisted with VSI	1431239
214	7/5/2022	1055461	TYRE 295/80R22.5 RECAP		1431239
214	7/5/2022	1055461	TYRE 295/80R22.5 RECAP		1431239
214	7/5/2022	1055461	TYRE 295/80R22.5 RECAP		1431239
214	7/5/2022	1055461	Mechanic entered - Wheels and Tyres Worn all rear	replaced all rear tyres	1431239
214	7/5/2022	1055461	TYRE 295/80R22.5 RECAP		1431239
214	7/5/2022	1055461	Mechanic entered - Wheels and Tyres Worn all rear	Assisted with tyre replacement.	1431239
214	7/5/2022	1055461	Consumables		1431239

214	7/5/2022	1055481	Mechanic entered - Vandalism Vandalism/ Graffiti Int	cleaned window vandalism and back of seats	1431239
214	7/5/2022	1055505	Mechanic entered - Body Other	replace damaged reflector at r	1431239
214	7/5/2022	1055505	REFLECTOR RED 94MM X 4MM 84052		1431239
214	7/5/2022	1055505	Consumables		1431239
214	7/5/2022	1055502	Mechanic entered - Air System Air_Leak Rear	Rekitted air valve on top of air tank.	1431239
214	7/5/2022	1055502	VALVE MANUAL DRAIN 22MM VOLVO B7RLE(1081328-5)(1581425-4)		1431239
214	7/5/2022	1055502	O-RING KIT LARGE VOSS(A6739970145)		1431239
214	7/5/2022	1055502	Mechanic entered - Air System Air_Leak Rear	repaired air leaks rear of bus	1431239
214	7/4/2022	1055088	Mechanic entered - Elec and Light Other eng. hatch sv	Checked and found the engine hatch inhibitor switch faulty. We dor	1431235
214	7/4/2022	1055088	SWITCH R/RIGHT ENGINE HATCH MERC 0500LE		1431235
214	7/4/2022	1055088		Replaced engine hatch inhibitor switch.	1431235
214	7/4/2022	1055088	Consumables		1431235
214	7/1/2022	1054965	Mechanic entered - Elec and Light Flat Batteries	started bus and charged batteries	1431235
214	7/1/2022	1054965	Consumables		1431235
214	6/27/2022	1053524	Mechanic entered - Suspension Other	replace all 4 sh replaced all 4 shock absorbers	1431235
214	6/27/2022	1053524	Mechanic entered - Suspension Other	replace all 4 sh assisted rod with replacing shock absorbers	1431235
214	6/27/2022	1053524	Mechanic entered - Suspension Other	replace all 4 sh Assisted with shockabsorber replacement.	1431235
214	6/25/2022	1053491	SHOCKER FRONT MERC 0500LE A628	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT323896 Receiving	1431235
214	6/23/2022	1053455		PRE ANNUAL SAFETY INSPECTION CHECK completed pre annual VSI	1431040
214	6/23/2022	1053455		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed service	1431040
214	6/23/2022	1053455		Assisted with Pre-annual safety inspection.	1431040
214	6/23/2022	1053455	O-RING KIT LARGE VOSS(A6739970145)		1431040
214	6/23/2022	1053455		replaced ns front drop arm	1431040
214	6/23/2022	1053491	Mechanic entered - Suspension Other Rear air bags le	Replaced R/H air bag rear of axle.	1431040
214	6/23/2022	1053491	AIRBAG FRT - RR MERC BENZ 0500LE E3 - E5 OH1830 49Y2200		1431040
214	6/23/2022	1053490	LINK SWAY BAR LINK L/H FRONT MERCEDES 0500		1431040
214	6/23/2022	1053490	SWAY BAR DROP ARM R/H		1431040
214	6/23/2022	1053490	Mechanic entered - Suspension Other Front drop arm	replaced front drop arms	1431040
214	6/23/2022	1053491	Mechanic entered - Suspension Other Rear air bags le	replaced N/S rear of rear air bag	1431040
214	6/23/2022	1053524	Mechanic entered - Suspension Other	replace all 4 sh orderd parts	1431040
214	6/23/2022	1053502	Mechanic entered - Body Other	clean rust off batt car cleaned rust and painted carrier at rust points	1431040
214	6/23/2022	1053502	Consumables		1431040
214	6/16/2022	1052241		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fir	1430829
214	5/10/2022	1045185	Consumables		1427973
214	5/10/2022	1045185	Consumables		1427973
214	5/10/2022	1045185	Driver seat position not in correct place	checked position ok	1427973
214	4/30/2022	1043310	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED CC	Done	1427339
214	4/11/2022	1040162		VEHICLE SAFETY INSPECTION completed VSI	1426159
214	4/11/2022	1040162		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed reter	1426159
214	3/8/2022	1033969	Drv entered - A/C Heating Not Cooling	Tested - ambient temp 26C saloon blowing 19 C. No fault found. Clos	1422448
214	2/21/2022	1030183	Mechanic entered - Vandalism Vandalism/ Graffiti Int	cleaned graffiti	1420377
214	2/21/2022	1030148	Handbrake lever cover missing	replaced rubber knob that was damaged	1420377
214	2/21/2022	1030148	Handbrake lever cover missing	replaced handbrake handle cover	1420377
214	2/21/2022	1030143	Consumables		1420377
214	2/21/2022	1030143	Consumables		1420377
214	2/21/2022	1030143	Consumables		1420377
214	2/21/2022	1030143		CARRY OUT A SERVICE AS PER CHECK LIST completed service	1420377
214	2/11/2022	1028346	Tablet Entered - Elec and Light - Exterior Lights	check wirings of rear r/h clearance light found broken wire repaired	1419269
214	2/11/2022	1028346	Consumables		1419269
214	2/7/2022	1027156		Done by ATS Purchase Order CT315000 on 2nd Feb 2022	1418974
214	2/7/2022	1027156		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1418974
214	2/3/2022	1026439		VEHICLE SAFETY INSPECTION completed VSI	1418580
214	2/3/2022	1026439		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1418580
214	2/2/2022	1025964	Mechanic entered - Elec and Light Exterior Lights R/H	replaced new amber light	1418033
214	2/2/2022	1025964	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1418033
214	2/2/2022	1025964	Consumables		1418033
214	1/31/2022	1025518	Replace windscreen	Creditor #:CT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:CT315041 Re	1418301
214	1/31/2022	1025518	Mechanic entered - WINDSCREEN R/H Bottom Corner	Replaced by AlphaGlass	1417943
214	1/31/2022	1025518	Consumables		1418301
214	1/18/2022	1023181	Ops Entered - Fault - Engine Belts_Loose Noisy Missin	Fan belt was too loose. I tensioned it up.	1416951
214	1/14/2022	1021737	Elec and Light rectify warning light on in dash.	removed seat and replaced fuel sensor	1416847
214	1/14/2022	1021737	Consumables		1416847
214	1/13/2022	1021737	Repair oil sender and engine s	Creditor #:CT-CAR008 CARDINIA P/O #:CT314015 Receiving #:329522	1416847
214	1/12/2022	1022326	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL I	replaced stickers with new	1416741
214	1/11/2022	1021737	Elec and Light rectify warning light on in dash.	removed seat and and check fuel sender wires ordered new part ch	1416650
214	1/11/2022	1021737	SENDER UNIT FUEL	Creditor #:CT-DAI002 DAIMLER TRUCKS SOMERTON P/O #:CT313931	1416741
214	1/11/2022	1021961	Mechanic entered - Body Other front step grip pad ne	replaced grip pad on front step	1416650
214	1/11/2022	1021961	Consumables		1416650

214	1/11/2022	1021940		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST carried out CCTV se	1416650
214	1/10/2022	1021737	Elec and Light rectify warning light on in dash.	Oil sender wiring repaired by Graham (CardiniaAuto).	1416650
214	1/7/2022	1020669	BUSH RUBBER SLEEVE RADIATOR 0500LE(A0009872143)		1416650
214	1/7/2022	1020669	Mechanic entered - Fluid Leaks Rear of bus looks like	Assembled radiator and fan housing and shroud. Refit to bus.	1416650
214	1/7/2022	1020669	Mechanic entered - Fluid Leaks Rear of bus looks like	Assisted Dave	1416650
214	1/6/2022	1020669	RADIATOR ASSY - VALEO	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT313776 Receiving	1416741
214	1/6/2022	1020669	Repair radiator	Creditor #:CT-PAK001 PAKENHAM RADIATOR SERVICE P/O #:CT313776	1416741
214	1/5/2022	1020669	Mechanic entered - Fluid Leaks Rear of bus looks like	removed all connection of radiator and intercoolerto pull out dism	1416650
214	1/4/2022	1020669	Mechanic entered - Fluid Leaks Rear of bus looks like	pressure test and found leaking in radiatort core	1416650
214	11/29/2021	1014488	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	1413684
214	11/29/2021	1014488	Service	Assisting completed differential service	1413684
214	11/26/2021	1011203	Mechanic entered - Body Other driver door cabin mo	fitted new driver door safety screen fitted two new gas struts to bat	1413314
214	11/26/2021	1011203	Consumables		1413556
214	11/24/2021	1011203	62076 drivers screen plastic	Creditor #:CT-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:CT311087	1413556
214	11/16/2021	1011908	Mechanic entered - Suspension Other r/l/h/r shock m	duplicate enter done before by ROBERTO	1411563
214	11/16/2021	1011203	Mechanic entered - Body Other driver door cabin mo	resealed side wiundows \ secured modestrty panel [waiting on dri	1411563
214	11/15/2021	1011203	330mm x 500nm	Creditor #:CT-UNI001 UNIVERSAL ENGINEERS SUPPLIES P/O #:CT3108	1411563
214	11/12/2021	1011028		VEHICLE SAFETY INSPECTION safety check follows checklist	1411004
214	11/12/2021	1011028		assised roberto with safety inspection	1411004
214	11/12/2021	1011028		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1411004
214	11/12/2021	1011146	Mechanic entered - Elec and Light Exterior Lights reve	reverse light wire wasnt connected properly connected reverse wir	1411004
214	11/12/2021	1011146	Consumables		1411004
214	11/12/2021	1011203	Mechanic entered - Body Other driver door cabin mo	secured post resealed side window [needs new screen]	1411004
214	11/12/2021	1011028	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTA	carried out campaign	1411004
214	11/12/2021	1011028	PERFORM CAMPAIGN 20/20 PRE SUMMER PREVENTA	cleaned enginebay	1411004
214	10/29/2021	1008344		retension wheels retension 1+2	1408546
214	10/29/2021	1008344		Retensioned position 1 and 2 wheel nuts. (Odometer 409422kms).	1408546
214	10/29/2021	1008344	Consumables		1408546
214	10/28/2021	1008136	PAINT LACQUER SPRAY HIGH GLOSS WHITE 400G		1408546
214	10/28/2021	1008136	Wheels and Tyres check/replace pos 1 tyre.	Assisted with tensioning the wheel nuts.	1408546
214	10/28/2021	1008136	TYRE 295/80R22.5 NEW		1408546
214	10/28/2021	1008136	Wheels and Tyres check/replace pos 1 tyre.	removed and replaced 2 front tyres	1408546
214	10/28/2021	1008148	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Incorrect open close due to OPS can't use this bus. Bookback.	1408546
214	10/28/2021	1008136	Consumables		1408546
214	10/28/2021	1008148	Consumables		1408546
214	10/27/2021	1007842	Mechanic entered - Fluid Leaks Rear of bus coolant	removed and replaced new coolant pipe	1408546
214	10/27/2021	1007842	HOSE BEND 90 DEGREE 2.1/4		1408546
214	10/26/2021	1007559	Coolant leak	tighten loose coolant pipe and refilled	1408546
214	10/14/2021	1005433	BusMinder Unable To Log In reported software issue	Replaced Bus Minder. Old bus minder number was BMN01244. New	1407214
214	10/14/2021	1005481	Ops Entered - Fault - BusMinder Unable To Log In - R	replaced the unit ref wo 1005433	1407214
214	10/14/2021	1005433	Consumables		1407214
214	10/14/2021	1005481	Consumables		1407214
214	9/29/2021	1001419	Consumables		1405958
214	9/29/2021	1001419	Gas struts on radiator hatch u/s - 450N 500mm.	fitted new gas struts to radiator hatch	1405958
214	9/27/2021	1001419	strutts 450nm x 500mm	Creditor #:CT-UNI001 UNIVERSAL ENGINEERS SUPPLIES P/O #:CT307;	1405958
214	9/23/2021	1001419	Gas struts on radiator hatch u/s - 450N 500mm.	Ordered gas struts.	1405771
214	9/22/2021	1001260	Pre-summer engine and radiator wash.	steamwash engine and radiator	1405771
214	9/22/2021	1001260		CARRY OUT A SERVICE AS PER CHECK LIST carry out serviced follows c	1405771
214	9/22/2021	1001260	Consumables		1405771
214	9/22/2021	1001260	Consumables		1405771
214	9/22/2021	1001260	Consumables		1405771
214	9/6/2021	997472		VEHICLE SAFETY INSPECTION Carried out safety service. Replaced a g	1403531
214	9/6/2021	997472		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1403531
214	9/3/2021	996854	A/C A service	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT306319 Receiving	1403176
214	9/3/2021	996854		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Done by Jimmy (Cold	1403176
214	8/31/2021	994851	Clean air system pipes.	Creditor #:CT-HMG001 HM GEM ENGINES P/O #:CT305760 Receiving	1402943
214	8/27/2021	995099	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMEN	fitted decals as per campaign	1402364
214	8/27/2021	995099	PERFORM CAMPAIGN 17/21 QR CODE DECAL FITMEN	performed campaign	1402364
214	8/26/2021	994851		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST completed Air sy	1402364
214	8/26/2021	994851	KIT O-RING LARGE VOSS (A6739970145)		1402364
214	8/26/2021	994851	VALVE DRAIN CONDENSOR MERCEDES 0500LE(A0054327401)		1402364
214	8/26/2021	994851	HOSE COMPRESSOR TO UNLOADER MERCEDES (A0014292135)		1402364
214	8/26/2021	994851	COUPLING AIR HOSE - COMP MERC BENZ 0500LE A0089970889		1402364
214	8/26/2021	994851	FILTER AIR DRYER C/W COALESCING VOLVO B13R 21620181		1402364
214	8/26/2021	994851	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1402364
214	8/20/2021	993303	Mechanic entered - Elec and Light Exterior Lights Top	replaced new n\s top parkers	1401159
214	8/20/2021	993303	Consumables		1401159
214	8/12/2021	991642	Drv entered - A/C Heating Not Heating	Tested - engine close to 80C demister 29C saloon 21C ambient 9C. Ne	1400089

214	8/12/2021	991642	Drv entered - A/C Heating Demister Not Heating	Twice entered	1400089
214	8/6/2021	990425		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1399576
214	8/6/2021	990425		Assisting - Done by ATS 05.08.2021 - CT303989 - Shonah	1399576
214	8/6/2021	990425		Done by ATS 05.08.2021 - CT303989 - Shonah	1399576
214	8/1/2021	985445	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT302745 R	1400914
214	7/22/2021	985047	KIT O-RING LARGE VOSS (A6739970145)		1397428
214	7/22/2021	985047	Consumables		1397428
214	7/20/2021	985332	Mechanic entered - Body Other Air tank hatch struts	replaced air tank hatch struts	1396805
214	7/20/2021	985332	Consumables		1396805
214	7/19/2021	985047	OVERFLOW VALVE 0405/0500 (A4341000220)		1396805
214	7/15/2021	985332	strutts 580mm x 350n	Creditor #:CT-UNI001 UNIVERSAL ENGINEERS SUPPLIES P/O #:CT3027	1396559
214	7/14/2021	985445		VEHICLE SAFETY INSPECTION	1396311
214	7/14/2021	985445		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1396311
214	7/14/2021	985445		ANNUAL SAFETY INSPECTION SERIAL #RSI 038149 _____ WORKSHOP :	1396311
214	7/14/2021	985445		Assisting	1396311
214	7/14/2021	985445	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1396311
214	7/13/2021	985048	Pre ASI Steam clean	Complete steam clean.	1396311
214	7/13/2021	985047	Random check and chassis wash.	Carried out Random Check and Chassis wash. Replaced leaking over	1396311
214	7/13/2021	985332	Mechanic entered - Body Other Air tank hatch struts	Ordered gas strutts.	1396311
214	7/13/2021	985048	Consumables		1396311
214	7/12/2021	985009	REAR WHEEL WATER SPRAY BRUSH FALLING OFF	refitted wheel arch brush	1396022
214	7/12/2021	985048	Pre ASI Steam clean	Started steam clean. Had to hand over bus half way through due to :	1396022
214	7/12/2021	985009	Consumables		1396022
214	7/2/2021	983334	Vandalism Window Film Replacement L3	Done by GlassProtech	1395439
214	7/2/2021	983334	Vandalism Window Film Replacement L3	Assisting	1395439
214	7/1/2021	983334	REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT300252,	1395542
214	6/30/2021	980784	Annual fire safety inspection.	Creditor #:CT-CAR008 CARDINIA P/O #:CT301206 Receiving #:316122	1395439
214	6/24/2021	981786	Ops Entered - Fault - Beeping noise- MYKI machine	Bus was changed on road due to beeping checked noise - ticket macl	1394923
214	6/24/2021	981786	Consumables		1394923
214	6/23/2021	981676	Mechanic entered - Wheels and Tyres Wheel Nut Reti	completed retension	1394840
214	6/23/2021	981676	Mechanic entered - Wheels and Tyres Wheel Nut Reti	completed retension	1394840
214	6/23/2021	981676	Consumables		1394840
214	6/23/2021	981381	Mechanic entered - Body Other Surface rust under frc	cleaned underbody and scraped old body deadner off and applied n	1394840
214	6/23/2021	981381	Mechanic entered - Body Other Surface rust under frc	assisted rod	1394840
214	6/23/2021	981381	UNDERBODY SEALER L250 1000ML		1394840
214	6/23/2021	981381	UNDERBODY SEALER L250 1000ML		1394840
214	6/23/2021	981381	Consumables		1394840
214	6/22/2021	981381	Drv entered - A/C Heating Demister Not Heating	found outside temp 6 degrees and demister blowing 24 degrees on :	1394772
214	6/22/2021	981381	Drv entered - A/C Heating Not Heating	found A/C in saloon blowing 16 degrees outside temp 6	1394772
214	6/22/2021	981381	CALIPER BRAKE OSR MERC 0500LE -> 000718		1394772
214	6/22/2021	981381	Mechanic entered - Brakes Other Recheck R/H rear oi	started job on pit and removed tyres and found job needed more tir	1394772
214	6/22/2021	981381	SET DISC PAD SET SCANIA / MERCEDES 0500		1394772
214	6/18/2021	980737		VEHICLE SAFETY INSPECTION Safety inspection complete.	1394172
214	6/18/2021	980737		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1394172
214	6/18/2021	980737		Assisted Frank	1394172
214	6/18/2021	980737		PRE ANNUAL SAFETY INSPECTION CHECK Pre annual safety inspectio	1394172
214	6/18/2021	980737		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST CCTV service compl	1394172
214	6/18/2021	980784		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Annual fire s	1394172
214	6/16/2021	980281	O/S WINDSCREEN ? WATER COMMING FROM THE SU	resealed side windows	1394029
214	6/16/2021	980297	NO 888 OR 889 IN DESTO	Uploaded new data.	1394029
214	6/16/2021	980281	Consumables		1394029
214	6/16/2021	980297	Consumables		1394029
214	6/7/2021	978607	Wheels require paint.	preped and painted 4 wheels	1392621
214	6/7/2021	978607	Consumables		1392621
214	6/2/2021	977879	Engine Belts_Loose Noisy Missing Fan shaft bearing f	Replaced bearings in fan shaft.	1392459
214	6/2/2021	977879	BEARING A/C CLUTCH BEARING (50V3335BRG)		1392459
214	6/2/2021	977879	SEAL TENSIONER HUB M1095		1392459
214	6/2/2021	977879	TAPERED ROLLER BEARING		1392459
214	5/26/2021	976647		CARRY OUT B SERVICE AS PER CHECK LIST Done by Wayne	1391331
214	5/26/2021	976647		Assisting Completed	1391331
214	5/26/2021	976647	FILTER AIR FILTER MERC BENZ 0500LE A0040941704		1391331
214	5/26/2021	976647	OIL SAMPLE KIT CALTEX		1391331
214	5/26/2021	976647	FILTER OIL FILTER MERCEDES A0001801709		1391331
214	5/26/2021	976647	Consumables		1391331
214	5/26/2021	976647	Consumables		1391331
214	5/26/2021	976647	Consumables		1391331
214	5/26/2021	976647		CARRY OUT A SERVICE AS PER CHECK LIST	1391331
214	5/26/2021	976647		CARRY OUT A SERVICE AS PER CHECK LIST	1391331

214	5/26/2021	976647 Consumables		1391331
214	5/26/2021	976647 Consumables		1391331
214	5/26/2021	976647 Consumables		1391331
214	5/24/2021	976093 Ops Entered - Fault - Elec and Light Exterior Lights -Of	removed light and replaced top right indicator globe	1390989
214	5/19/2021	975225 Ops Entered - Fault - Engine Belts_Loose Noisy Missin	I roadtested the bus and found that the fan belt was squeeling. I adj	1390627
214	5/11/2021	973448	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Tune up service coi	1389611
214	5/11/2021	973448 FILTER ZF ECOMAT GEARBOX 4139-298-038 1193281		1389611
214	5/11/2021	973448	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Transmissior	1389611
214	4/16/2021	968461	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1385766
214	4/16/2021	968461	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1385766
214	4/16/2021	968461	assisted dave with safety service	1385766
214	4/16/2021	968461 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheel nuts on Pos 345 & 6 to specs.	1385766
214	4/16/2021	968461 Consumables		1385766
214	4/15/2021	968280 Wheels and Tyres Worn replace pos 6 tyre.	Replaced all rear tyres. All tyres were U/S except for position 5. That	1385766
214	4/15/2021	968280 Wheels and Tyres Worn replace pos 6 tyre.	Assisted Frank.	1385766
214	4/15/2021	968280 TYRE 295/80R22.5 RECAP		1385766
214	4/15/2021	968280 Consumables		1385766
214	4/13/2021	967765 Ops Entered - Fault - Elec and Light - LEFT INDICATOR	replaced ns indicator and parker globe	1385353
214	4/13/2021	967765 Consumables		1385353
214	4/12/2021	967239 Ops Entered - Fault - Elec and Light - Left side headligl	Replaced blown globe.	1384992
214	4/12/2021	967240 Mechanic entered - Elec and Light Exterior Lights L/H	Refer w/o 967239.	1384992
214	4/12/2021	967239 Consumables		1384992
214	4/12/2021	967240 Consumables		1384992
214	3/30/2021	964898 Place new poster over the top attach hangers to hand	Done by Refuellers	1383174
214	3/29/2021	964630 PERFORM CAMPAIGN 10/21 FITMENT OF AUTHORISE	Done by Ronnie and Ethan	1383174
214	3/10/2021	959573 PERFORM CAMPAIGN 09/21 POSITIONING OF 2021 P1	Carried out campaign as required. Need and 'Authorised Officers' sti	1379876
214	3/4/2021	958501 LAMP STOP/TAIL LED HELLA		1379214
214	3/4/2021	958501 Mechanic entered - Elec and Light Exterior Lights top	Checked tail light and found fault in wiring. Repaired wire but tail lig	1379214
214	3/4/2021	958501 Consumables		1379214
214	3/1/2021	955388 Please test and repair a/c not	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT293668 Receiving	1379532
214	2/23/2021	955388 Ops Entered - Fault - A/C Heating Not Cooling - Route	Replaced AC solenoid. Shortened the wire and replaced the lug term	1377915
214	2/22/2021	955388 SOLENOID 24V 200AMP 4-WAY ELEC	Creditor #:CT-ASH001 ASHDOWN INGRAM P/O #:CT292509 Receiving	1378665
214	2/18/2021	955388 Ops Entered - Fault - A/C Heating Not Cooling - Route	Checked a/c system clutch operation ok but not getting cold pipes si	1377915
214	2/17/2021	954699 Consumables		1377915
214	2/17/2021	954699 Ops Entered - Fault - Body Passenger Seat Torn - Off	s replaced back rest [was on drivers area]	1377550
214	2/17/2021	954744 Leave old poster in and fit you must wear a maskover	Fitted poster	1377550
214	2/15/2021	953037 Mechanic entered - Elec and Light Other Batteries ne	Fitted new batteries.	1377335
214	2/12/2021	953037 BATTERY 1100CCA POS ON LHS E	Creditor #:CT-BAT005 BATTERY POWER CENTRE P/O #:CT293043 Rec	1377053
214	2/11/2021	952956	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1376969
214	2/11/2021	952956	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1376969
214	2/11/2021	953037 Mechanic entered - Elec and Light Other Batteries ne	Ordered batteries.	1376969
214	2/11/2021	952907	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1376969
214	2/11/2021	952907	Assisting - Done by ATS on 07/02 PO CT291945 - Shonah	1376969
214	2/11/2021	952907	Done by ATS on 07/02 PO CT291945 - Shonah	1376969
214	2/11/2021	952956 Consumables		1377053
214	2/11/2021	952956 Consumables		1377053
214	2/11/2021	952956 Consumables		1377053
214	2/11/2021	952956	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service.	1376969
214	2/8/2021	952454	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1376418
214	2/8/2021	952454	Assisting	1376418
214	2/8/2021	951916 Keep ol poster in holder and place Travel off Peak anc	Not supplied	1376140
214	1/13/2021	946613 Please fit A3 poster over COVID-19 poster and hanger	Applied A3 poster and hangers as per campaign.	1371956
214	1/9/2021	945591	Closed as per Ben Willis.	1371165
214	1/9/2021	945591	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1371165
214	1/8/2021	945473 Removed N/S/F window COVID-19 & MYKI decals and Done		1371165
214	12/31/2020	943864 Ops Entered - Fault - A/C Heating Demister Not Heatir	Checked and find heater taps closed. Opened taps and road test anc	1368797
214	12/22/2020	942417 THERMOSTAT 71 DEG MERC 0405+0500LE A0032033275 A0042038475		1368622
214	12/22/2020	942417 THERMOSTAT 71 DEG MERC 0405+0500LE A0032033275 A0042038475		1368622
214	12/22/2020	942417 Mechanic entered - Fluid Leaks Rear of bus header ta	replaced both thermostats and re sealed and refilled cooling system	1368622
214	12/22/2020	941922 Mechanic entered - Air System Air_Leak Rear	repaired air leak at rear of bus	1368622
214	12/22/2020	941922 KIT O-RING SMALL VOSS (A0309971748)		1368622
214	12/21/2020	942417 Mechanic entered - Fluid Leaks Rear of bus header ta	Has small leak at thermostat housing	1368231
214	12/21/2020	941846 Mechanic entered - Engine Noisy or Rattling Fan bear	Replaced angle drive. Cleaned radiator and intercooler thoroughly.	1368231
214	12/21/2020	941846 STRUT GAS STAY 350Nm 430mm LONG		1368231
214	12/21/2020	941846 Mechanic entered - Engine Noisy or Rattling Fan bear	replaced angle drive and repaired heater hose	1368231
214	12/18/2020	942303 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned position 1 and 2 wheel nuts after the roadtest. Retorqu	1368231
214	12/18/2020	942303 Consumables		1368618
214	12/18/2020	941261 0249978882 hose	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT289885 Receiving	1368622

214	12/18/2020	941261	Mechanic entered - Fluid Leaks Rear of bus coolant le	Replaced header tank. Also replaced 2 hoses.	1368231
214	12/18/2020	941261	TANK COOLANT HEADER MERC BENZ 0405NH 0500LE		1368231
214	12/18/2020	942151	Mechanic entered - Brakes Other LH front brake pads	Replaced R/H front brake rotors and pads. Also replaced hub and be	1368231
214	12/18/2020	942151	SET DISC PAD SET SCANIA / MERCEDES 0500		1368231
214	12/18/2020	942151	ROTOR FRONT & REAR MERC 0500LE A9424230112		1368231
214	12/18/2020	942151	HUB SEAL FRONT INNER MERCEDES BENZ 0500LE		1368231
214	12/18/2020	942151	HUB SEAL FRONT OUTER MERCEDES BENZ 0500LE		1368231
214	12/18/2020	942151	BOLT FRT BRAKE DISC MERC BENZ 0500LE A910105014019		1368231
214	12/18/2020	942151	Mechanic entered - Brakes Other LH front brake pads	Removed L/H/FR brake caliper and hub. Dismantled hub and replac	1368231
214	12/17/2020	941811		VEHICLE SAFETY INSPECTION Completed	1368231
214	12/17/2020	941811		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed	1368231
214	12/17/2020	941872	Mechanic entered - Suspension Other Level sensor b	Replaced worn level sensor ball joints on LH rear	1368231
214	12/17/2020	941872	BALL JOINT SUSP LEVELLING VALVE MERC BENZ 0500LE		1368231
214	12/17/2020	941846	ANGLE DRIVE FAN 0500LE A62950	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT289885 Receiving	1368622
214	12/17/2020	941846	Mechanic entered - Engine Noisy or Rattling Fan bear	Please order angle drive	1368231
214	12/17/2020	941884	Mechanic entered - Dash Other Park brake light not w	Replaced switch on booster	1368231
214	12/17/2020	941884	SWITCH PARK BRAKE 6.7 BAR MERC BENZ 0500LE A0025453914		1368231
214	12/17/2020	941884	Consumables		1368596
214	12/17/2020	941922	Mechanic entered - Air System Air_Leak Rear	Fitted o ring kits to 7 fittings has leakingtest port need to order	1368231
214	12/17/2020	941922	KIT O-RING LARGE VOSS (A6739970145)		1368231
214	12/16/2020	941261	0249978882 HOSE	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT289721 Receiving	1368231
214	12/15/2020	941112	Supply body supply solenoid.	Creditor #:CT-CAR008 CARDINIA P/O #:CT289639 Receiving #:302392	1368231
214	12/15/2020	941261	Mechanic entered - Fluid Leaks Rear of bus coolant le	Leaking from small bleed hose at bottom of header tank Tightened c	1367946
214	12/14/2020	941112	Ops Entered - Fault - A/C Heating Not Cooling - no air	replaced Ac solinoid and created new main cable to solinoid as was	1367946
214	11/28/2020	937859	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS	Completed	1365211
214	11/25/2020	936341	Mechanic entered - Elec and Light Exterior Lights fron	replaced globe as needed	1364318
214	11/25/2020	936341	Consumables		1364911
214	11/19/2020	934713	Rear right window marked with fine tip marker.	Removed graffiti.	1363350
214	11/19/2020	934992	Ops Entered - Fault - BusMinder Unable To Log In - R	Checked bus minder after trip - working good battery 92% and charg	1363350
214	11/19/2020	934992	Consumables		1363870
214	11/17/2020	933723	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE `	removed stickers	1363101
214	11/17/2020	933723	Remove old poster and fit you must wear a face mask	replaced poster	1363101
214	11/16/2020	933239	Mechanic entered - Body Other L/H/RR panels bent p	removed and strighten rear panel as needed	1362742
214	11/16/2020	933239	Consumables		1363101
214	11/16/2020	933239	Consumables		1363101
214	11/10/2020	931860	Ops Entered - Fault - Fluid Leaks Rear of bus - alarm o	Replaced split coolant hose from boost pump through chassis to tra	1361856
214	11/10/2020	932181	Pre summer engine and radiator wash.	Carried out Engine and Radiator Wash.	1361856
214	11/10/2020	932181	Consumables		1362232
214	11/10/2020	932181	Consumables		1362232
214	11/10/2020	932168		CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service.	1361856
214	11/10/2020	932168	Consumables		1362232
214	11/10/2020	932168	Consumables		1362232
214	11/10/2020	932168	Consumables		1362232
214	10/29/2020	929590	Fit new Myki Decals & refit COVID-19 decals new posi	Fitted decals as per campaign requirements.	1360252
214	10/28/2020	925600	A/C Heating Not Cooling	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT285408 Receiving	1360252
214	10/26/2020	928530		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS retension comp	1359543
214	10/26/2020	928530		Assisting Assisted Rodney	1359543
214	10/26/2020	928530		VEHICLE SAFETY INSPECTION VSI complete and repaired rear seat	1359543
214	10/26/2020	928530	Take oil sample.	collected oil sample	1359543
214	10/26/2020	928530	OIL SAMPLE KIT CALTEX		1359543
214	10/21/2020	925600	Ops Entered - Fault - A/C Heating Not Cooling - Route	Cold Drive have replace the compressor and carried out the repairs	1359149
214	10/21/2020	925600	PAINT GLOSS BLACK AEROSOL		1359149
214	10/19/2020	925600	Please sypply a screw type com	Creditor #:CT-QTK001 QTK GROUP P/O #:CT285441 Receiving #:2986	1359543
214	10/16/2020	927013	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG	Installed e-tag as per campaign.	1357995
214	10/16/2020	926963	KIT O-RING LARGE VOSS (A6739970145)		1357995
214	10/16/2020	926963		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed	1357995
214	10/16/2020	926963	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE A0054327401		1357995
214	10/16/2020	926963	FILTER AIR DRYER C/W COALESCING VOLVO B13R 21620181		1357995
214	10/12/2020	925600	Ops Entered - Fault - A/C Heating Not Cooling - Route	Assisting	1357164
214	10/12/2020	925600	Drv entered - A/C Heating Not Cooling	Twice entered	1357164
214	10/2/2020	923532	Drv entered - A/C Heating Warning Light On	Checked - no warning light on saloon 19C demister 26C. OK.	1355755
214	10/1/2020	905459	seat repair	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT279122 Receiving	1355681
214	9/14/2020	919733	DRIVERS CAB DOOR YOU HAVE TO SLAM IT.BUS IS ON	removedand replaced new lock and adjustment as needed	1352849
214	9/14/2020	919733	SIDE BIN LOCK PINS (UES 600-0487)		1352849
214	9/14/2020	919733	Consumables		1353410
214	9/8/2020	917618	Please carry out A/C A&B Servi	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT282943 Receiving	1352849
214	9/2/2020	917618		CARRY OUT A/C - B SERVICE AS PER CHECK LIST	1351251
214	9/2/2020	917618		Compressor mount is U/S	1351251

214	9/2/2020	917618	Welded cracks in A/C compressor bracket	1351251
214	9/2/2020	917618	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1351251
214	8/31/2020	917185	VEHICLE SAFETY INSPECTION Safety inspection complete.	1350877
214	8/31/2020	917185	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1350877
214	8/31/2020	917185	Assisting	1350877
214	8/31/2020	917185	Replaced R/H rear of rear air bag.	1350877
214	8/31/2020	917185	Replaced rear window Emergency Exit sticker. (Exterior).	1350877
214	8/31/2020	917185	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR	1350877
214	8/31/2020	917185	Open floor and steam clean engine and transmission. Removed both floor hatches and steam cleaned engine and transmi	1350877
214	8/20/2020	915070	Mechanic entered - Wheels and Tyres Wheel Nut Ret Retorqued wheel nuts on Pos 345 & 6 to specs.	1348487
214	8/20/2020	915070	Consumables	1349078
214	8/18/2020	914647	SET DISC PAD SET SCANIA / MERCEDES 0500	1348383
214	8/18/2020	914647	Mechanic entered - Brakes Other Recheck R/H rear br Replaced rear pads. Also replaced position 5 and 6 tyres. Position 5 i	1348383
214	8/18/2020	914647	TYRE 295/80R22.5 RECAP	1348383
214	8/18/2020	914647	CARRY OUT C SERVICE AS PER CHECK LIST Completed	1348383
214	8/18/2020	914647	Assisting Completed	1348383
214	8/18/2020	914647	OIL SAMPLE KIT CALTEX	1348383
214	8/18/2020	914647	FILTER FUEL MERCEDES (A5410900151)	1348383
214	8/18/2020	914647	FILTER OIL FILTER MERCEDES A0001801709	1348383
214	8/18/2020	914647	FILTER STEERING FILTER (153468) (0153468)(349619)	1348383
214	8/18/2020	914647	FILTER FUEL FILTER MERCEDES BENZ (A0004771302)	1348383
214	8/18/2020	914647	FILTER AIR FILTER MERCEDES BENZ (C27-1170)	1348383
214	8/18/2020	914647	Consumables	1348487
214	8/18/2020	914647	Consumables	1348487
214	8/18/2020	914647	CARRY OUT B SERVICE AS PER CHECK LIST	1348383
214	8/18/2020	914647	Consumables	1348487
214	8/18/2020	914647	Consumables	1348487
214	8/18/2020	914647	CARRY OUT A SERVICE AS PER CHECK LIST	1348383
214	8/18/2020	914647	Consumables	1348487
214	8/18/2020	914647	Consumables	1348487
214	8/17/2020	914205	Replace graffiti film - L1	1348110
214	8/17/2020	914205	Replace graffiti film - L1	1348110
214	8/13/2020	914205	REPAIR VANDALISED WINDOWS	1348110
214	8/6/2020	911598	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1346286
214	8/6/2020	911598	Assisting - Done by ATS on 05/08/2020 - CT277842 - Shonah	1346286
214	8/6/2020	911598	Done by ATS on 05/08/2020 - CT277842 - Shonah	1346286
214	8/4/2020	910898	Remove old A3 Poster and fit with You can no longer Done by a spare driver - Shonah	1345753
214	7/31/2020	910256	Consumables	1345479
214	7/31/2020	910256	Consumables	1345479
214	7/31/2020	910256	CARRY OUT A SERVICE AS PER CHECK LIST	1345395
214	7/31/2020	910256	A service complete.	1345395
214	7/31/2020	910256	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615	1345395
214	7/28/2020	909258	Mechanic entered - Wheels and Tyres Wheel Nut Ret Retorqued wheel nuts on Pos 5 & 6 to specs.	1344015
214	7/28/2020	909258	Mechanic entered - Wheels and Tyres Wheel Nut Retension pos	1344015
214	7/28/2020	909258	Consumables	1344849
214	7/27/2020	909025	Mechanic entered - Wheels and Tyres Worn P6 replaced pos 6 tyre with run out tyre	1344015
214	7/27/2020	909025	Consumables	1344618
214	7/24/2020	905459	SEAT REPAIR	1344618
214	7/24/2020	908729	Consumables	1344618
214	7/24/2020	908729	Driver Sated: The bus minder is not charging due to t Checked bus minder AM was 3% and charging ok.	1344015
214	7/20/2020	907788	Mechanic entered - Elec and Light Exterior Lights L/H Replaced L/H side rear clearance lamp.	1343254
214	7/20/2020	907788	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)	1343254
214	7/20/2020	907788	Consumables	1343500
214	7/17/2020	906831	CARRY OUT YEARLY INSPECTION	1344015
214	7/15/2020	906831	VEHICLE SAFETY INSPECTION	1342060
214	7/15/2020	906831	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1342060
214	7/15/2020	906831	ANNUAL SAFETY INSPECTION SERIAL #_RSI 034612_____	1342060
214	7/15/2020	906831	Assisting	1342060
214	7/15/2020	906936	Mechanic entered - Air System Air_Leak Rear air leak repaired air leak with new joiner and replaced clipper door valve	1342060
214	7/15/2020	906936	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON	1342060
214	7/15/2020	906936	BUTTON CLIPPARD DOOR VALVE 49Z4811	1342060
214	7/10/2020	905833	Mechanic entered - Body Other Give way and emerga removed fade stickers and replaced new as needed	1341386
214	7/10/2020	905833	'GIVE WAY' DECAL 240MM X 225MM	1341386
214	7/10/2020	905833	Consumables	1341788
214	7/8/2020	905459	VEHICLE SAFETY INSPECTION Safety inspection complete.	1341220
214	7/8/2020	905459	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1341220
214	7/8/2020	905459	Replaced passenger seat. (3rd from the back R/H window side). Use	1341220
214	7/8/2020	905459	Consumables	1341386

214	7/8/2020	905459	Random check and full chassis wash	Random check and chassis wash complete.	1341220
214	7/2/2020	904381	Drv entered - A/C Heating Not Heating	Checked - engine 70C saloon 19C demister 26C - no fault found.	1340720
214	7/2/2020	870328	SENSOR BRAKE PAD WEAR MERC B	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT267595RET Receiv	1341114
214	7/1/2020	903057	seat repair	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT278290 Receivi	1340720
214	6/29/2020	903057	Mechanic entered - Vandalism Other slashed disable	replaced repaired disable seat rest as needed	1339760
214	6/29/2020	903634	Mechanic entered - Elec and Light Exterior Lights L/H	Replaced globe	1339760
214	6/25/2020	903057	Mechanic entered - Vandalism Other slashed disable	removed seat rest [waiting on repairs]	1338085
214	6/24/2020	902789		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST completed cctv serv	1338085
214	6/24/2020	902789		PRE ANNUAL SAFETY INSPECTION CHECK completed pre annual safty	1338085
214	6/24/2020	902919	Mechanic entered - Steering Other replace both front	replaced both front drop arms	1338085
214	6/24/2020	902919	DROP LINK SWAY BAR A6283201189		1338085
214	6/24/2020	902919	LINK SWAY BAR LINK L/H MERCEDES 0500 A6283201089		1338085
214	6/24/2020	902940	Mechanic entered - Brakes Other O/S rear booster lea	replaced off side rear booster	1338085
214	6/24/2020	902940	O/S/RR BRAKE BOOSTER 20/24 MERC 0500LE		1338085
214	6/24/2020	902811		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Done by Gra	1338085
214	6/24/2020	902811	Annual fire safety inspection	Creditor #:CT-CAR008 CARDINIA P/O #:CT278074 Receiving #:289858	1339470
214	6/23/2020	902501	Mechanic entered - Elec and Light Flat Batteries load	load tested at 6.30 am and passed. load tested batteries after run 12	1338085
214	6/22/2020	902409	Mechanic entered - Elec and Light Flat Batteries	jump started bus and checked charging rate ok	1338085
214	6/20/2020	902117	Mechanic entered - Elec and Light Exterior Lights R/H	Replaced blown globe	1338085
214	6/19/2020	901697	Ops Entered - Fault - Elec and Light Flat Batteries - Ro	load tested bateries and found forward batterie failing orderd batte	1338085
214	6/19/2020	901697	Ops Entered - Fault - Elec and Light Flat Batteries - Ro	Fitted second hand battery as per PH instructions	1338085
214	6/18/2020	901697	Ops Entered - Fault - Elec and Light Flat Batteries - Ro	Jump started	1338085
214	6/17/2020	901410	Ops Entered - Fault - Elec and Light Flat Batteries - Ro	jump start	1338085
214	6/15/2020	900829	Ops Entered - Fault - Elec and Light Flat Batteries - Ro	Jump started bus at approx. 6:10am.	1337836
214	6/10/2020	899888	Fit A3 Poster in poster frame and fit decals as request	Fitted decals.	1336968
214	6/1/2020	897573	when you push the throttle bus will not go	Checked - no fault found.	1335022
214	6/1/2020	897573	Consumables		1335526
214	5/26/2020	896704	Drv entered - A/C Heating Not Cooling	Checked - engine 75C demister 32C saloon 21C. No fault found.	1334394
214	5/26/2020	896704	Drv entered - A/C Heating Not Heating	Checked - engine 75C demister 32C saloon 21C. No fault found.	1334394
214	5/26/2020	896684	Drv entered - Elec and Light Interior Lights	Replaced inverter and tube	1334394
214	5/26/2020	896684	INVERTER 24 Volt 36 Watt MAN		1334394
214	5/26/2020	896684	Consumables		1334593
214	5/18/2020	894933		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1332721
214	5/18/2020	894933		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1332721
214	5/18/2020	894933		assisted dave with safety replaced one overhead grab handle	1332721
214	5/18/2020	894933	PLASTIC TRIANGLE HANDSTRAP GREY		1332721
214	5/15/2020	894608	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Retensioned all rear @ 332499	1331406
214	5/15/2020	894608	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Assisting	1331406
214	5/15/2020	894608	Consumables		1332721
214	5/14/2020	894319	TYRE 295/80R22.5 RECAP		1331406
214	5/14/2020	894319	Mechanic entered - Wheels and Tyres Other Position	Replaced 2 recap tyres for N/S/R and a run out tyre for O/S/R/O. Bor	1331406
214	5/14/2020	894319	Consumables		1332499
214	5/13/2020	891198	seat repair	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT274363 Receivi	1332721
214	5/13/2020	894057	Ops Entered - Fault - Suspension Hard - Route: 929 - I	Checked and find front suspension faulty. Checked sensorwiring anc	1331406
214	5/12/2020	893718	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Retorqued wheel nuts on Pos 3 & 4 to specs.	1331406
214	5/12/2020	893718	Consumables		1332089
214	5/11/2020	893642		CARRY OUT A SERVICE AS PER CHECK LIST A service complete. Positio	1331406
214	5/11/2020	893642		Assisting assisted frank with A service and replaced tyre pos 4 with ri	1331406
214	5/11/2020	893642	Consumables		1331735
214	5/11/2020	893642	Consumables		1331735
214	4/29/2020	891198	Mechanic entered - Vandalism Other 1 seat base torn	fitted new seat base into bus	1328939
214	4/29/2020	891062	Mechanic entered - Elec and Light Exterior Lights Rea	Checked rear lights found side marker has slight moisture inside. Re	1328939
214	4/29/2020	891062	LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1328939
214	4/29/2020	891062	Mechanic entered - Elec and Light Exterior Lights Rea	Checked O/S/R all park lights and number plate light wirings and cor	1328939
214	4/29/2020	891062	Consumables		1329545
214	4/28/2020	890810	Mechanic entered - Elec and Light Exterior Lights rear	Checked wiring and found bad connections in 2 terminals. Repaired	1328939
214	4/28/2020	890810	Mechanic entered - Elec and Light Exterior Lights rear	Checked fuses relay connectors and wirings etc and reset batteries a	1328939
214	4/28/2020	890810	Consumables		1329338
214	4/20/2020	889235	LWR O/S BREAK LIGHT OUT	Replaced led tail light for O/S/R.	1327053
214	4/20/2020	889235	LAMP STOP/TAIL LED HELLA		1327053
214	4/20/2020	889235	Consumables		1327672
214	4/14/2020	887760	Mechanic entered - Elec and Light Exterior Lights R/H	Checked all lights - no fault found.	1326153
214	4/14/2020	887760	Consumables		1326648
214	4/9/2020	887435	A4 notification to be printed off in colour laminated a	completed campaign	1325858
214	4/1/2020	885402		VEHICLE SAFETY INSPECTION Carried out safety service. Removed gra	1323582
214	4/1/2020	885402		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1323582
214	3/25/2020	883629	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Retorqued wheel nuts on Pos 1 & 2 to specs.	1321226
214	3/25/2020	883629	Consumables		1322713

214	3/24/2020	882704	Wheels and Tyres check/replace pos 1	replaced pos 1 and 2 tyres	1321226
214	3/24/2020	882704	Wheels and Tyres check/replace pos 1	Assisted Rodney replaced pos 1+2	1321226
214	3/24/2020	882704	TYRE 295/80R22.5 NEW		1321226
214	3/24/2020	882704	Consumables		1322489
214	3/24/2020	883194	Tape off front Seats of All Route and Rail Buses with s	Assisting - Completed 06-20 Campaign	1321226
214	3/24/2020	883194	Tape off front Seats of All Route and Rail Buses with s	Completed 06-20 Campaign	1321226
214	3/23/2020	882533	Engine Replace muffler mount.	Replaced	1321226
214	3/23/2020	882533	Engine Replace muffler mount.	Assisting	1321226
214	3/23/2020	882533	EXHAUST MOUNT MERC BENZ 0500LE A0004910285		1322243
214	3/23/2020	882222	Remove old poster and fit Reduce Your Risk of Coron:	Done	1321226
214	3/20/2020	881618	Mechanic entered - Wheels and Tyres Wheel Nut Ret:	Retorqued wheel nut on Pos 3 & 4 to specs.	1321226
214	3/20/2020	881618	Consumables		1321921
214	3/19/2020	881345	Wheels and Tyres check/replace pos 3	Replaced tyre on pos 3 with runout.	1321226
214	3/19/2020	881345	Consumables		1321664
214	3/4/2020	878391	Mechanic entered - Elec and Light Exterior Lights L/H	Replaced blown globe.	1318536
214	3/4/2020	878391	Consumables		1318982
214	2/28/2020	877710	Mechanic entered - Wheels and Tyres Wheel Nut Ret:	Carried out wheel nut retension with Rodney on Pos 3+4 bus @ 318	1318113
214	2/28/2020	877710	Mechanic entered - Wheels and Tyres Wheel Nut Ret:	assisted	1318113
214	2/28/2020	877710	Consumables		1318312
214	2/27/2020	877142	Mechanic entered - Fluid Leaks Rear of bus LH rear hu	Replaced L/H/RR hub seals.	1317802
214	2/27/2020	877142	KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)		1317802
214	2/27/2020	877142	Mechanic entered - Fluid Leaks Rear of bus LH rear hu	assisted in replacing l/h rear hub seal	1317802
214	2/27/2020	877142	please supply 1 x locktite bea	Creditor #:CT-BUR001 BURSON AUTOMOTIVE PTY LTD P/O #:CT2698;	1318113
214	2/27/2020	877124	SIDE BIN LOCK PINS		1317802
214	2/27/2020	877124	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCRE:	replaced new sreen and bars as needed	1317802
214	2/27/2020	877124	HINGE DRIVERS DOOR S/S 60mmX60mm (12205)(802505)		1317802
214	2/25/2020	876731		CARRY OUT A SERVICE AS PER CHECK LIST Completed Replaced wash	1317587
214	2/25/2020	876731	PUMP WASHER PUMP 24 VOLT		1317587
214	2/25/2020	876731	Consumables		1317802
214	2/25/2020	876731	Consumables		1317802
214	2/18/2020	874951	Vandalism - Window film Replacement - L2 R1	Assisting - Done by GlassProtech - Shonah	1315910
214	2/18/2020	874951	Vandalism - Window film Replacement - L2 R1	Done by GlassProtech - Shonah	1315910
214	2/18/2020	875082		Assisting - Done by ATS On Order number CT267197 - Shonah	1315910
214	2/18/2020	875082		Done by ATS On Order number CT267197 - Shonah	1315910
214	2/18/2020	875082		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1315910
214	2/17/2020	874951	Window film replacement	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT269049	1316916
214	2/11/2020	873412		VEHICLE SAFETY INSPECTION Safety inspection complete.	1314432
214	2/11/2020	873412		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1314432
214	2/11/2020	873412	HEAD LAMP INSERT HELLA 90MM L/FLOOR 0500 (9314365038525)		1314432
214	2/11/2020	873412		Replaced L/H high beam lens.	1314432
214	2/11/2020	873414		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Air system servic	1314432
214	2/11/2020	873414	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1314432
214	2/11/2020	873414	FILTER AIR DRYER C/W COALESCING VOLVO B13R 21620181		1314432
214	2/11/2020	873414	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1314432
214	1/31/2020	870582	Mechanic entered - Wheels and Tyres Wheel Nut Ret:	Retorqued Wheel nuts on Pos 345 & 6 to specs.	1311405
214	1/31/2020	870582	Consumables		1311928
214	1/30/2020	870328	Ops Entered - Fault - Brakes Warning Light On - Rout:	Replaced leaking booster and rear pads.	1311405
214	1/30/2020	870328	N/S/RR BRAKE BOOSTER 20/24 MERC 0500LE		1311405
214	1/30/2020	870328	SET DISC PAD SET SCANIA / MERCEDES 0500		1311405
214	1/30/2020	870328	Ops Entered - Fault - Brakes Warning Light On - Rout:	assisted dave in removing rough spots on brake rotor due to pads br	1311405
214	1/30/2020	870328	Ops Entered - Fault - Brakes Warning Light On - Rout:	fitted new ABS sensor on LH rear wheel	1311405
214	1/30/2020	870328	SENSOR ABS LHR 2800MM MERC B	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT267595 Receiving	1311928
214	1/30/2020	870328	SENSOR WEAR SENSOR MERCEDES	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT267595 Receiving	1311928
214	1/29/2020	870145	Ops Entered - Fault - Gearbox: Gear Change -not sele:	Removed and cleaned gear selector.	1311405
214	1/24/2020	869439	Remove and wash radiator and intercooler.	Done 23/12/2019	1310452
214	1/20/2020	868249	PERFORM CAMPAIGN 01/20 POSITIONING OF 2020 PT	Done	1308957
214	1/16/2020	867517	running very rough and has low power.	Road tested bus with all accessories turned on to create load to eng	1308369
214	1/16/2020	867516	Elec and Light Warning Light On Dash; battery saver	Replaced alternator belt. Checked alternator mounting bushes for w	1308369
214	1/16/2020	867516	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		1308369
214	1/16/2020	867516	Consumables		1308957
214	1/13/2020	866724		Closed as per Ben Willis request.	1307791
214	1/13/2020	866724		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	1307791
214	1/9/2020	866009	Fault - A/C Heating Not Cooling - Route: 834 - Berwicl	Repaired by Ajith (ColdDrive) - replaced power supply solenoid	1307232
214	1/9/2020	866009	BLOWING HOT AIR		1307232
214	1/9/2020	866009	DIRECT PURCHASE - AIR CONDITIO	Creditor #:CT-COL004 COLD DRIVE PTY LTD P/O #:CT265962 Receiving	1308957
214	1/9/2020	866130	Ops Entered - Fault - Engine Noisy or Rattling - Route	greased drop links to take noise out of chassis	1307232
214	1/4/2020	865022	Mechanic entered - Vandalism Vandalism/ Graffiti Int	removed graffiti on rear seatsand walls as needed	1306417
214	1/1/2020	862774	FAN SHROUD MERC BENZ 0500LE	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT265247 Receiving	1306952

214	12/31/2019	864314	TERO UNDERBODY DEADENER 1LT		1305499
214	12/31/2019	864314	Mechanic entered - Body Other Floor underneath nee	prep and sprayed body deadner as needed	1305499
214	12/31/2019	864314	Consumables		1306072
214	12/27/2019	863937		VEHICLE SAFETY INSPECTION	1304633
214	12/27/2019	863937		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Safety inspectio	1304633
214	12/27/2019	863937		assisted frank with safety	1304633
214	12/27/2019	863967	Ops Entered - Fault - A/C Heating Not Cooling - Route	Checked the function of the AC. AC compressor clutch seems to be e	1304633
214	12/24/2019	862774	Mechanic entered - Engine Other Radiator shroud brc	replaced radiator and repaired header tank support mount	1304633
214	12/24/2019	862774	PLATE CLAMPING SIDE PANEL		1304633
214	12/24/2019	862774	PLATE CLAMPING SIDE PANEL		1304633
214	12/24/2019	862774	Mechanic entered - Engine Other Radiator shroud brc	fitted all radiator brackets and header tank together topped up cool	1304633
214	12/24/2019	851922	Accident #49531 - unreported - cracks & marks F/N/C	replaced new front middle bumper as needed	1304633
214	12/23/2019	862774	Mechanic entered - Engine Other Radiator shroud brc	removed radiator and intercooler from bus steam cleaned radiator	1304633
214	12/23/2019	862774	Mechanic entered - Engine Other Radiator shroud brc	removed and replaced fan schroud and started installing radiator	1304633
214	12/21/2019	863233	Fault#:37189 - Ops Entered - Fault - Breakdown Overl	Replaced two coolant hoses.	1304633
214	12/20/2019	863233	Fault#:37189 - Ops Entered - Fault - Breakdown Overl	Travel to breakdown in Pakenham blocked off split hose and filled w	1304633
214	12/19/2019	862774	Mechanic entered - Engine Other Radiator shroud brc	Ordered	1304264
214	12/16/2019	862147		CARRY OUT B SERVICE AS PER CHECK LIST B service complete.	1303442
214	12/16/2019	862147	FILTER OIL FILTER MERCEDES A0001801709		1303442
214	12/16/2019	862147	FILTER AIR FILTER MERCEDES BENZ		1303442
214	12/16/2019	862147	Consumables		1303708
214	12/16/2019	862147	Consumables		1303708
214	12/16/2019	862147	Consumables		1303708
214	12/16/2019	862147		CARRY OUT A SERVICE AS PER CHECK LIST A service complete.	1303442
214	12/16/2019	862147	Consumables		1303708
214	12/16/2019	862147	Consumables		1303708
214	12/16/2019	862147	Consumables		1303708
214	12/13/2019	861775	Not Cooling	Checked - A/C blows 21C - ok.	1303171
214	12/13/2019	861775	Not Cooling		1303171
214	12/7/2019	851922	Accident #49531 - unreported - cracks & marks F/N/C	Ordered N/S/F and centre bumper.	1301483
214	12/5/2019	859558	FOOT PEDAL HARD TO PUSH THEN IT SUDDENLY GIVE!	lube foot pedal as needed	1301168
214	12/5/2019	859558	Consumables		1301483
214	12/3/2019	858903	A3 Poster Frame Adhesive Decal Campaign please ren	Done by Shonah	1300540
214	11/27/2019	851922	Accident #49531 - unreported - cracks & marks F/N/C	removed and replaced new n/s corner [waiting on middle front bur	1298956
214	11/25/2019	851922	Near side Front and centre bum	Creditor #:CT-EAS004 EASTCOAST TRUCK & BUS SERVICE P/O #:CT26:	1299604
214	11/19/2019	855444		Assisting Assisting safety service.	1296944
214	11/19/2019	855444		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1296944
214	11/19/2019	855444		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1296944
214	11/7/2019	853161	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Carried out Di	1294464
214	11/6/2019	852958	Mechanic entered - Vandalism Vandalism/ Graffiti Ext	removed graffiti from bus	1294250
214	11/4/2019	852548	Replace Near side back glass	Creditor #:CT-A1W001 A1 WINDSCREENS P/O #:CT261753 Receiving	1295279
214	11/4/2019	852548	Mechanic entered - Body Other L/H side window brot	Replaced at A1 Windscreens	1294112
214	11/4/2019	852548	Consumables		1294250
214	11/4/2019	852548	Consumables		1294250
214	11/1/2019	851922	Accident #49531 - unreported - cracks & marks F/N/C	Ordered N/S/F and centre bumper.	1293387
214	10/28/2019	850730	Mechanic entered - Elec and Light Exterior Lights R/H	Replaced a globe for O/S/F park light.	1292222
214	10/18/2019	848807	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221		1290173
214	10/18/2019	848807		assisted dave	1290173
214	10/18/2019	848807		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Carried out Tune-u	1290173
214	10/18/2019	848913	A/C Heating NOT HEATING	Checked engine temperature checked demister - blowing hot air. No	1290173
214	10/9/2019	847003	Consumables		1288663
214	10/9/2019	847003	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned all rear wheel nuts.	1287586
214	10/9/2019	846644	Mechanic entered - Steering Other Drag link ball joint	Removed drag link and replaced ball joint boot and the ball joint on	1287586
214	10/9/2019	847080	CCTV- 6 MONTH SERVICE	Creditor #:CT-BWE001 BWERE ELECTRICS PTY LTD P/O #:CT259781 R	1289309
214	10/9/2019	847080	CCTV - Video loss repair	Done by Jonny BWERE	1287586
214	10/9/2019	847023	CCTV 6 mths service	Done by Johnny (BWERE)	1287586
214	10/9/2019	847004	Consumables		1288663
214	10/9/2019	847004	Mechanic entered - Body Other Vinyl on the floor nea	glue on peeling vinyl as needed	1287586
214	10/8/2019	846644	ball joint boot 49L1211	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT259604 Receiving	1288171
214	10/8/2019	846644	TIE ROD END RHT	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT259604 Receiving	1288171
214	10/8/2019	847023	CCTV 6 MTHS service	Creditor #:CT-BWE001 BWERE ELECTRICS PTY LTD P/O #:CT259751 R	1289309
214	10/7/2019	846317		Replaced an overhead grab rail handle.	1287586
214	10/7/2019	846317		Replaced 2 battery terminal clamps and a battery cable.	1287586
214	10/7/2019	846317	BATTERY JOINER CABLE		1287586
214	10/7/2019	846317	NUT BRASS BATTERY TERMINAL POSITIVE (+)		1287586
214	10/7/2019	846317		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1287586
214	10/7/2019	846317		VEHICLE SAFETY INSPECTION Safety inspection complete.	1287586
214	10/7/2019	846317	NUT BRASS BATTERY TERMINAL NEGATIVE (-) MA14HDN		1287586

214	10/7/2019	846317	PLASTIC TRIANGLE HANDSTRAP GREY		1287586
214	10/7/2019	845901	Consumables		1288171
214	10/7/2019	845901	TYRE 295/80R22.5 RECAP		1287586
214	10/7/2019	845901	TYRE 275/70R22.5 RECAP		1287586
214	10/7/2019	846317	SET DISC PAD SET SCANIA / MERCEDES 0500		1287586
214	10/7/2019	846317	Brakes - replace rear brake pads.	Replaced rear brake pads.	1287586
214	10/7/2019	846518	AIR LINE FITTING SEAL RING 0500LE AIR DRYER		1287586
214	10/7/2019	846518	VALVE 6 WAY CIRCUIT PROTECTION VALVE		1287586
214	10/7/2019	846518	Mechanic entered - Air System Air_Leak Rear Curcuit	Replaced leaking 4 way valve	1287586
214	10/7/2019	846317	Consumables		1288171
214	10/7/2019	846317	Consumables		1288171
214	10/7/2019	846317		CARRY OUT A SERVICE AS PER CHECK LIST A service complete.	1287586
214	10/5/2019	846188	Consumables		1288171
214	10/5/2019	846188	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Completed	1287586
214	10/4/2019	845901	TYRE 275/70R22.5 RECAP		1287586
214	10/4/2019	845901	TYRE 275/70R22.5 RECAP		1287586
214	10/4/2019	845901	Mechanic entered - Wheels and Tyres Worn pos 6 (3M	replaced tyres pos 5 and 6 but found brakes to be low at 5mm or les	1287586
214	9/16/2019	842151	A service	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT257755 Receiving	1284674
214	9/13/2019	842151		CARRY OUT A/C - A SERVICE AS PER CHECK LIST - Coach air carried ou	1283638
214	9/9/2019	840311	AIR CONDITIONING REPAIR	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT257300 Receiving	1284339
214	9/5/2019	840390	Consumables		1281797
214	9/5/2019	840390	Consumables		1281797
214	9/5/2019	840390	INTERNAL PANEL ABOVE THE FRONT DOOR NEEDS FIX	Drilled new holes in the plastic panel and installed 4 new riv-nuts in	1281417
214	9/5/2019	840390	INTERNAL PANEL ABOVE THE FRONT DOOR NEEDS FIX	Repaired and remounted interior panel	1281417
214	9/4/2019	840311	Service	Coach air found unloader valve for A/C at fault repaired unloader val	1281417
214	8/29/2019	838733		Assisted Suejong.	1279966
214	8/29/2019	838733		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1279966
214	8/29/2019	838733		VEHICLE SAFETY INSPECTION Carried out safety service. Replaced a s	1279966
214	8/29/2019	838733	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		1279966
214	8/29/2019	838820	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Removed graffiti inside the bus.	1279966
214	8/23/2019	837252	Consumables		1279420
214	8/23/2019	837252	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheel nuts on Pos 2 to specs.	1278534
214	8/22/2019	836974	Consumables		1279131
214	8/22/2019	836974	Mechanic entered - Wheels and Tyres Flat or Leaking	Replaced tyre on Pos 2.	1278534
214	8/22/2019	836974	TYRE 295/80R22.5 NEW		1278534
214	8/22/2019	835472	Service	Will creat bookback and get coach air to come out and carry out rep:	1278534
214	8/20/2019	836483		Done by ATS on 16/08/2019 Invoice number T20-230470	1278226
214	8/20/2019	836483		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1278226
214	8/19/2019	836108	Drv entered - Vandalism Vandalism/ Graffiti Interior	removed graffiti on rear seats as needed	1277068
214	8/15/2019	835478	Drv entered - A/C Heating Demister Not Heating	Refer w/o 835472.	1276429
214	8/15/2019	835472	Drv entered - A/C Heating Not Heating	Checked A/C heating and found compressor staying on cooling cabir	1276429
214	8/12/2019	834714	Drv entered - Gearbox Driveline Rough Gear Change	Checked gear box oil level and conditionwiring and tail shaft etc. Ro	1274925
214	8/7/2019	833783	Consumables		1274632
214	8/7/2019	833783	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheel nuts on Pos 3 & 4 to specs.	1273829
214	8/7/2019	833783	Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos		1273829
214	8/7/2019	833811	Consumables		1274632
214	8/7/2019	833811	Mechanic entered - Elec and Light Other Transmissior	Replaced blown globe.	1273829
214	8/6/2019	833514	Consumables		1274383
214	8/6/2019	833514	Mechanic entered - Wheels and Tyres Worn P3	Replaced tyres on Pos 3 & 4 and placed Pos 4 in run out cage.	1273829
214	8/6/2019	833514	TYRE 295/80R22.5 RECAP		1273829
214	8/5/2019	833307	Consumables		1274123
214	8/5/2019	833307	Consumables		1274123
214	8/5/2019	833307	Consumables		1274123
214	8/5/2019	833307	Service	Assisting	1273829
214	8/5/2019	833307		CARRY OUT A SERVICE AS PER CHECK LIST completed A service and ti	1273829
214	8/1/2019	832423	Drv entered - A/C Heating Not Heating	Checked - engine temp ok demister and saloon ok.	1272598
214	7/29/2019	831735	Consumables		1272278
214	7/29/2019	831735	brake return spring not working possible brake light c	tested tail and brake lights with Jarek and could not fault	1272046
214	7/23/2019	829326	Clean air system pipes.	Creditor #:CT-HMG001 HM GEM ENGINES P/O #:CT253199 Receiving	1271291
214	7/20/2019	830013	Consumables		1270709
214	7/20/2019	830013	Mechanic entered - Elec and Light Exterior Lights L/H	Replaced blown globe & aimed headlights.	1270176
214	7/19/2019	829216	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT253075 R	1271291
214	7/18/2019	829745	Mechanic entered - Vandalism Vandalism/ Graffiti Int	removed graffiti from bus	1269791
214	7/18/2019	829756	Consumables		1270176
214	7/18/2019	829756	Mechanic entered - Elec and Light Exterior Lights R/H	Replaced blown globe	1269791
214	7/17/2019	829216		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1269791
214	7/17/2019	829216		VEHICLE SAFETY INSPECTION	1269791
214	7/17/2019	829216		ANNUAL SAFETY INSPECTION SERIAL #RSI017049WORKSHOP SUPERV	1269791

214	7/17/2019	829212 Consumables		1270050
214	7/17/2019	829212 Chec over before RSI	Cancelled by Jarek bus didn't come from road on time.	1269791
214	7/17/2019	829326 VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		1269791
214	7/17/2019	829326 KIT O-RING LARGE VOSS (A6739970145)		1269791
214	7/17/2019	829326 FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)		1269791
214	7/17/2019	829326 KIT O-RING SMALL VOSS (A0309971748)		1269791
214	7/17/2019	829326 KIT O-RING LARGE VOSS (A6739970145)		1269791
214	7/17/2019	829326 VALVE RELAY VALVE RR MERC O500LE		1269791
214	7/17/2019	829326	assisted frank and sujeon	1269791
214	7/17/2019	829326	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Removed and re	1269791
214	7/17/2019	829326	Air system service complete. Also rekkited four air line fittings.	1269791
214	7/9/2019	827573		1268436
214	7/9/2019	827573	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued wheel	1268436
214	7/9/2019	827573	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1268436
214	7/9/2019	827102 AIR CONDITIONING REPAIR - to c	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT252393 Receiving	1268963
214	7/9/2019	827102 Drv entered - A/C Heating Not Heating	A/C repaired by Shiron (CoachAir).	1268436
214	7/6/2019	827102 Drv entered - A/C Heating Not Heating	Checked A/C heating and found compressor staying on. To be rebooc	1267396
214	7/5/2019	826987 FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		1267396
214	7/5/2019	826987	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST Transmissior	1267396
214	7/3/2019	826395 Consumables		1267121
214	7/3/2019	826395 Mechanic entered - Wheels and Tyres Worn p3	Checked P 3 and 4 tyres over 4.5 mm left.	1266596
214	6/28/2019	823897 seat repair	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT250785 Receivii	1266084
214	6/22/2019	824537 in rear seating area on windows and backs of a coupl	Cleaned massive graffitti.	1264657
214	6/20/2019	823483 Annual fire safety inspection	Creditor #:CT-CAR008 CARDINIA P/O #:CT250560 Receiving #:259534	1264399
214	6/19/2019	823897 Mechanic entered - Vandalism Vandalism/ Graffiti Int	Replaced damaged seat bases.	1264190
214	6/19/2019	823897 Mechanic entered - Vandalism Vandalism/ Graffiti Int	Cleaned graffitti	1264190
214	6/19/2019	823898 Consumables		1264399
214	6/19/2019	823898 Mechanic entered - Body Windows Front O/S 1st and	Resealed windows with sikaflex.	1264190
214	6/18/2019	823437 STRUT 330MM X 500N		1263016
214	6/18/2019	823437	PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre annual safe	1263016
214	6/18/2019	823437 KIT O-RING LARGE VOSS (A6739970145)		1263016
214	6/18/2019	823483	CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Done by Gra	1263016
214	6/15/2019	823107 Consumables		1263623
214	6/15/2019	823099 Consumables		1263623
214	6/15/2019	823107 Mechanic entered - Elec and Light Exterior Lights L/H	complete wo 823099	1263016
214	6/15/2019	823099 LENS TO SUIT 2029 (RED & AMBER)		1263016
214	6/15/2019	823099 Drv entered - Elec and Light Exterior Lights	wired in new near side rear marker	1263016
214	6/14/2019	822824	Replaced poster.	1263016
214	5/26/2019	818414 Vandalism Vandalism/ Graffiti Interior	Done by GlassProtect	1259258
214	5/25/2019	819135 Consumables		1259940
214	5/25/2019	819135 Consumables		1259940
214	5/25/2019	819135 Mechanic entered - Wheels and Tyres Wheel Nut Retri	compleated retention	1259686
214	5/23/2019	818774	Replaced rear brake pads.	1259572
214	5/23/2019	818774 SET DISC PAD SET SCANIA / MERCEDES 0500		1259572
214	5/23/2019	818774	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1259572
214	5/23/2019	818774	VEHICLE SAFETY INSPECTION Safety inspection complete.	1259572
214	5/23/2019	818769 Consumables		1259686
214	5/23/2019	818769 Consumables		1259686
214	5/23/2019	818769 Mechanic entered - Body Other wheel needs painted	preped and painted wheels as needed	1259572
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777	CARRY OUT C SERVICE AS PER CHECK LIST compleated a b c service	1259572
214	5/23/2019	818777 FILTER P/STEER SCANIA VOLVO MERCEDES (349619-7) (2192404)		1259572
214	5/23/2019	818777 KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1259572
214	5/23/2019	818777 FILTER OIL FILTER MERCEDES A0001801709		1259572
214	5/23/2019	818777	assisted frank and rod	1259572
214	5/23/2019	818777 KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1259572
214	5/23/2019	818777 FILTER FUEL FILTER MERCEDES BENZ (A0004771302)		1259572
214	5/23/2019	818777 FILTER FUEL MERCEDES (A5410900151)		1259572
214	5/23/2019	818777 FILTER OIL FILTER MERCEDES A0001801709		1259572
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777	CARRY OUT B SERVICE AS PER CHECK LIST compleated service	1259572
214	5/23/2019	818777 Consumables		1259686

214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777 Consumables		1259686
214	5/23/2019	818777	CARRY OUT A SERVICE AS PER CHECK LIST completed service	1259572
214	5/21/2019	818414 REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT248438	1259258
214	5/16/2019	817395 Drv entered - A/C Heating Not Heating	Re[placed heater tap and refitted cable to control in cab	1257719
214	5/16/2019	817395 HEATER VALVE DEMISTER MERC 0500LE		1257719
214	5/4/2019	813937 Consumables		1255254
214	5/4/2019	813937 Consumables		1255254
214	5/4/2019	813937 EMERGENCY EXIT BUTTON PULL COVER (16906)		1255022
214	5/4/2019	813937 Mechanic entered - Body Other rear interior door top	removed and replaced new cover as needed	1255022
214	5/3/2019	813992 Mechanic entered - Vandalism Vandalism/ Graffiti Int	ainted rear seats and removed graffiti	1255022
214	5/3/2019	813936 Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced 2 new disable stickers	1255022
214	5/3/2019	813959 Consumables		1255105
214	5/3/2019	813959 Consumables		1255105
214	5/3/2019	813937 Direct Purchase - BODYWORK	Creditor #:CT-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #:CT247059	1255254
214	5/3/2019	813959 Mechanic entered - Body Other yellow strip missing	replaced new yellow strip as needed	1255022
214	5/3/2019	813937 Mechanic entered - Body Other rear interior door top	needs new plastic interior rear cover panel	1255022
214	5/3/2019	814030 Please remove all old poster and fit MYKI has gone	n Done by Apprentices' - Shonah	1255022
214	5/2/2019	813674 Mechanic entered - Vandalism Vandalism/ Graffiti Int	Removed graffiti	1254667
214	5/1/2019	813055 Direct Purchase - ELECTRICAL	Creditor #:CT-BWE001 BWERE ELECTRICS PTY LTD P/O #:CT246730 R	1255254
214	5/1/2019	813055 CCTV 6 Month Service & Defect Repairs****Booked f	Done by Johny BWere	1254375
214	4/20/2019	811407 Vandalism Vandalism/ Graffiti Interior	Cleaned graffiti.	1252102
214	4/10/2019	809421	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1249961
214	4/10/2019	809421	VEHICLE SAFETY INSPECTION Carried out safety service. Replaced a fl	1249961
214	4/9/2019	809109 Consumables		1250144
214	4/9/2019	809109 Wheels and Tyres replace pos 1+2	the tyres are new clean skins I had supervisor look and the tyres do	1249961
214	4/4/2019	808177 Consumables		1249327
214	4/4/2019	808177 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheel nuts on Pos 1 & 2 to specs.	1247425
214	4/3/2019	807668 Consumables		1249066
214	4/3/2019	807668 Mechanic entered - Wheels and Tyres Worn p2 3mm	Replaced 2 new tyres for front. Bookback wheel nuts retension (DVF	1247425
214	4/3/2019	807668 TYRE 295/80R22.5 NEW		1247425
214	4/2/2019	807668 Mechanic entered - Wheels and Tyres Worn p2 3mm	Send out.	1247425
214	4/1/2019	807378 Mechanic entered - Vandalism Vandalism/ Graffiti Int	removed all graffiti from bus	1247425
214	3/29/2019	806941 Consumables		1247997
214	3/29/2019	806941 Mechanic entered - Elec and Light Exterior Lights low	Replaced globe	1247425
214	3/26/2019	806175 Consumables		1247035
214	3/26/2019	806175 Elec and Light - MYKI staff booked at Sat 23/092019 8	Done by MYKI staff	1246716
214	3/25/2019	805846 Consumables		1246716
214	3/25/2019	805846 Mechanic entered - Body Other Missing yellow safety	Replaced safety strip	1246418
214	3/20/2019	804789 Consumables		1245763
214	3/20/2019	804789 Consumables		1245763
214	3/20/2019	804789 Consumables		1245763
214	3/20/2019	804789	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A service.	1245124
214	3/14/2019	801601 Direct electrical	Creditor #:CT-CAR008 CARDINIA P/O #:CT242945 Receiving #:251520	1243883
214	3/5/2019	801601 AIR CONDITIONING REPAIR - not	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT242515 Receiving	1242501
214	3/4/2019	801601 Drv entered - A/C Heating Not Cooling		1241801
214	3/4/2019	801601 Drv entered - A/C Heating Not Cooling		1241801
214	3/4/2019	801601 Drv entered - A/C Heating Not Cooling	Repaired by Ajith (CoachAir)	1241801
214	2/27/2019	800585 DROP LINK SWAY BAR A6283201189		1240481
214	2/27/2019	800585 LINK SWAY BAR LINK L/H MERCEDES 0500		1240481
214	2/27/2019	800585		1240481
214	2/27/2019	800585	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1240481
214	2/27/2019	800585	VEHICLE SAFETY INSPECTION Carried out safety service. Replaced 2 s	1240481
214	2/19/2019	799044 Consumables		1239061
214	2/19/2019	799044 Consumables		1239061
214	2/19/2019	799044 Mechanic entered - Body Other R/H Rear panel scrap	Buffed and polished scratches	1238948
214	2/13/2019	797564	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1238026
214	2/13/2019	797564	Done on Invoice number T19-221619	1238026
214	2/8/2019	796475 Mechanic entered - Fluid Leaks Rear of bus coolant	Checked and find coolant leaks from heater hose behind headertanl	1236826
214	2/8/2019	796475 BLADE WIPER BLADE 22 INCH		1236826
214	1/26/2019	793849 Consumables		1234253
214	1/26/2019	793819 Consumables		1234253
214	1/26/2019	793849 Near side headlight is out	replaced nearside head light globe	1233881
214	1/26/2019	793819 Mechanic entered - Elec and Light Exterior Lights L/H	replaced hi and low beam near side head light globes	1233881
214	1/22/2019	791742 Consumables		1233161
214	1/22/2019	791742 BELT TENSIONER MERCEDES BENZ 0500		1232872
214	1/17/2019	791742 Mechanic entered - Elec and Light Other Alternator m	Assisted	1232000

214	1/17/2019	791742	Mechanic entered - Elec and Light Other Alternator m	Removed alternator and support bracket. Replaced bushes in brack	1232000
214	1/17/2019	791742	BELT TENSIONER MERCEDES BENZ 0500		1232000
214	1/17/2019	791742	BUSH ALTERNATOR MTG 12MM X 25MM X 37MM MERC 0500LE		1232000
214	1/17/2019	791921	Please remove old 2018 fare decals and fit new 2019	Done	1232000
214	1/15/2019	790933	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheel nuts on all rear wheels to specs.	1231809
214	1/15/2019	791222	Consumables		1232000
214	1/15/2019	791222	TERO UNDERBODY DEADENER 1LT		1231809
214	1/15/2019	791222	Mechanic entered - Body Other Flooring underneath	preped and painted body deadner as needed	1231809
214	1/11/2019	790689	STEERING LINK A/ DRIVE TO STRG	Creditor #:CT-DAI002 DAIMLER TRUCKS SOMERTON P/O #:CT238677	1231546
214	1/11/2019	790689	TYRE 295/80R22.5 RECAP		1231373
214	1/11/2019	790689	SET DISC PAD SET SCANIA / MERCEDES 0500		1231373
214	1/11/2019	790689	AMBER REFLECTOR		1231373
214	1/11/2019	790689		Replaced position 5 and 6 tyres.	1231373
214	1/11/2019	790689		Replaced rear brake pads.	1231373
214	1/11/2019	790689		Assisted Frank with safety insection secured hand pole with pop rive	1231373
214	1/11/2019	790689		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1231373
214	1/11/2019	790689		VEHICLE SAFETY INSPECTION Safety inspection complete.	1231373
214	1/11/2019	790797	Mechanic entered - Steering Other Uni joint on steeri	Fitted new steering linkage.	1231373
214	1/8/2019	789807	Consumables		1230745
214	1/8/2019	789807	Consumables		1230745
214	1/8/2019	789807		Carried out A service	1230229
214	1/2/2019	788576	Consumables		1229101
214	1/2/2019	788576	Drv entered - Body Drivers Seat Controls	Checked seat control seat belt seat cushion - no fault found.	1226750
214	12/28/2018	788138	FAN DRIVE SHAFT MERC 0500LE	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT237758 Receiving	1230524
214	12/28/2018	788138	ANGLE DRIVE FAN 0500LE A62950	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT237758 Receiving	1230524
214	12/28/2018	788138	ANGLE DRIVE FAN 0500LE A62950	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT237758RET Receiv	1230524
214	12/28/2018	788138	Breakdown#:36015 - Ops Entered - Breakdown - Brea	Replaced fan angle driveshaft due to being broken	1226750
214	12/28/2018	788138	Breakdown#:36015 - Ops Entered - Breakdown - Brea	Ordered fan shaft.	1226750
214	12/24/2018	787776	STALK INDICATOR MERCEDES 0500 LE A0085450124		1226750
214	12/24/2018	787776	Elec and Light Indicators Not Working - indicator stall	Replaced indicator stalk	1226750
214	12/19/2018	786973	AIR DRYER ASSY A0004302915		1226368
214	12/19/2018	786973	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1226368
214	12/19/2018	786973	SILENCER AIR VALVE 69MM (432-407-070-0)		1226368
214	12/19/2018	786973		Air system service. Air system service complete.	1226368
214	12/19/2018	786973	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		1226368
214	12/19/2018	786973		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	1226368
214	12/17/2018	786302	Consumables		1226142
214	12/17/2018	786302	Reseal 3 loose side windows.	Creditor #:CT-ALP003 ALPHA BUS GLASS PTY LTD P/O #:CT237129 Re	1226368
214	12/17/2018	786302	Mechanic entered - Body Windows Side L/H 3rd wind	Secured by Alpha Glass	1225760
214	12/15/2018	786261	Mechanic entered - Elec and Light Exterior Lights Fron	Replaced blown globe	1225760
214	12/7/2018	784581	Consumables		1224335
214	12/7/2018	784581	Mechanic entered - Body Other safety stickers missin	replaced stickers as needed	1223998
214	12/3/2018	782864	Drv entered - Elec and Light AM-FM Radio	Supplied and fitted new AM/FM radio.	1222726
214	11/30/2018	782866	Drv entered - Vandalism Vandalism/ Graffiti Interior	Cleaned graffiti from walls windows roof panels and back of seats.	1222137
214	11/30/2018	782864	Consumables		1222940
214	11/30/2018	782864	Drv entered - Elec and Light AM-FM Radio	Checked and find AM-FM radio faulty. Ordered radio.	1222137
214	11/30/2018	782864	RADIO/CD 12/24v WITH BLUETOOTH	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT235743 Receiving	1222726
214	11/30/2018	782947	Consumables		1222940
214	11/30/2018	782947	Mechanic entered - Body Other missing decal	REPLACED MYKI DECAL	1222137
214	11/29/2018	782568	BUSH RUBBER SLEEVE RADIATOR - 0500LE A0009872143		1222137
214	11/29/2018	782568	RADIATOR MOUNT-(STUD TYPE)		1222137
214	11/29/2018	782568	BELT FAN DRIVE MERC 0500LE A0139971992		1222137
214	11/29/2018	782568	Mechanic entered - Engine Other Radiator mount rub	Replaced 2 radiator rubber mounts and cooling fan drive belt.	1222137
214	11/28/2018	782226	Consumables		1222479
214	11/28/2018	782226	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned	1222137
214	11/27/2018	781988		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1222137
214	11/27/2018	781988		VEHICLE SAFETY INSPECTION Carried out safety service.	1222137
214	11/27/2018	782086	Consumables		1222256
214	11/27/2018	782086	TYRE 295/80R22.5 RECAP		1222137
214	11/27/2018	782086	Wheels and Tyres - Check/replace pos 3	Replaced 2 recap tyres for N/S/R. Bookback wheel nuts retension.	1222137
214	11/24/2018	781555	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Cleaned graffitti	1221189
214	11/22/2018	780098	CLEANER GRAFFITI REMOVER AMERASE PER LITRE		1220825
214	11/17/2018	780098	Mechanic entered - Vandalism Vandalism/ Graffiti Int	cleaned graffiti	1219309
214	11/7/2018	778092	Consumables		1217131
214	11/7/2018	778092	Consumables		1217131
214	11/7/2018	778092	LAMP CLEAR FRT INDICATOR WRAP-AROUND		1216681
214	11/7/2018	778092	Mechanic entered - Elec and Light Exterior Lights fron	Replaced indicator assembly	1216681
214	11/1/2018	776992	Consumables		1216385

214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1215950
214	11/1/2018	776992 FILTER OIL FILTER MERCEDES A0001801709		1215950
214	11/1/2018	776992	CARRY OUT B SERVICE AS PER CHECK LIST Carried out B Service.	1215950
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992 Consumables		1216385
214	11/1/2018	776992	CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service.	1215950
214	10/17/2018	773932 Consumables		1213532
214	10/17/2018	773932 Mechanic entered - Wheels and Tyres Other Rear whi	pped and painted wheels as needed	1212694
214	10/16/2018	773581 Consumables		1213386
214	10/16/2018	773581 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheelnuts on Pos 5 & 6 to specs.	1212694
214	10/15/2018	773221	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued wheel	1212694
214	10/15/2018	773221	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1212694
214	10/15/2018	773398 Consumables		1213152
214	10/15/2018	773398 Mechanic entered - Wheels and Tyres Worn Pos 6.	Replaced tyre on Pos 6 with runout.	1212694
214	10/15/2018	773541 BALL JOINT LEVELLING VALVE MERCEDES 0500		1212694
214	10/15/2018	773541 Ops Entered - Fault - Air System Air Not Building_Up -	RH rear levelling arm balljoint had popped off Replaced both balljoi	1212694
214	10/9/2018	771021 Repair alternator as required	Creditor #:CT-CAR008 CARDINIA P/O #:CT231219 Receiving #:239227	1211924
214	10/8/2018	769581 Drv entered - Steering Steering Wheel Faulty	Replaced hose.	1211714
214	10/5/2018	771240 Drv entered - A/C Heating Not Heating	Checked - working good.	1210839
214	10/5/2018	771240 Drv entered - A/C Heating Not Cooling	Checked - working good.	1210839
214	10/5/2018	771021 PULLEY LOWER ALT 0500LE		1210839
214	10/5/2018	771021 Drv entered - Brakes Warning Light On	Replaced alternator warning lights not presents.	1210839
214	10/4/2018	769581 DIRECT PURCHASE - MECHANICAL G	Creditor #:CT-DAI002 DAIMLER TRUCKS SOMERTON P/O #:CT230738	1210839
214	10/3/2018	769581 Drv entered - Steering Steering Wheel Faulty	Replaced power steering pump Supply hose still to be done on orde	1210831
214	10/3/2018	769581 50A7618BOSCH	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT230852 Receiving	1210831
214	10/3/2018	770541 REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEH	Assisting	1210831
214	10/3/2018	770541 REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEH	Fitted	1210831
214	10/2/2018	769581 DIRECT PURCHASE - MECHANICAL G	Creditor #:CT-DAI002 DAIMLER TRUCKS SOMERTON P/O #:CT230738	1210831
214	10/1/2018	769581 Drv entered - Steering Steering Wheel Faulty	Steering is heavier stationary at idle and is a bit lighter when revved	1210446
214	9/29/2018	769673 Drv entered - Vandalism Vandalism/ Graffiti Interior	Cleaned graffiti from seats walls and roof panels.	1209805
214	9/27/2018	769581 SILENCER AIR VALVE 69MM (432-407-070-0)		1209805
214	9/27/2018	769581 Drv entered - Steering Steering Wheel Faulty	Steering is heavier stationary at idle and is a bit lighter when revved	1209805
214	9/26/2018	769081 Consumables		1209805
214	9/26/2018	769081 Elec and Light Exterior Lights - indicator	Replaced a globe for N/S/F top indicator light.	1209296
214	9/22/2018	768418 Mechanic entered - Vandalism Vandalism/ Graffiti Ext	Graffiti cleaned	1208694
214	9/22/2018	768402 Drv entered - Steering Steering Wheel Faulty	Checked front end test drive - could not fault.	1208694
214	9/15/2018	766740 Vandalism Vandalism/ Graffiti Interior	Cleaned graffiti from seats.	1206575
214	9/14/2018	766444 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned pos 1 & 2 wheel nuts	1206575
214	9/14/2018	766444 Mechanic entered - Wheels and Tyres Wheel Nut Retension Pos		1206575
214	9/13/2018	765906 Drv entered - Steering Steering Wheel Faulty	Roadtested bus and found steering pulls to left. Checked front end f	1206575
214	9/10/2018	764526 GASKET AIR COMPRESSOR MERCEDES 0500LE		1205999
214	9/10/2018	764526 O RING P/STRG PUMP MERC 0500LE (A0159974845)		1205999
214	9/7/2018	764526 PIPE COOLANT VOITH COMPRESSOR - BLOCK 0500LE		1205862
214	9/7/2018	764526 GASKET AIR COMPRESSOR MERCEDES 0500LE		1205862
214	9/7/2018	764526 O RING P/STRG PUMP MERC 0500LE (A0159974845)		1205862
214	9/7/2018	764526 Mechanic entered - Fluid Leaks Other no coolant in h	Replaced compressor.	1205862
214	9/7/2018	764526 Mechanic entered - Fluid Leaks Other no coolant in h	Checked - ordered compressor.	1205862
214	9/7/2018	764534 A/C B service	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT228972 Receiving	1205862
214	9/6/2018	764526 POWER STEERING PUMP SEALING O	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT228870 Receiving	1205862
214	9/6/2018	764526 GASKET SUIT 0500LE COMPRESSOR	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT228971 Receiving	1205862
214	9/6/2018	764526 air compressor	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT228971 Receiving	1205862
214	9/6/2018	764534	CARRY OUT A/C - B SERVICE AS PER CHECK LIST Done by Ajith (Coach	1205862
214	9/6/2018	764534 SUPPLY SOLENOID	Creditor #:CT-CAR008 CARDINIA P/O #:CT229028A Receiving #:23661	1205862
214	9/6/2018	764534	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1205862
214	9/6/2018	764534	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1205862
214	9/4/2018	763888	Done by ATS Invoice Number T19-213886	1205292
214	9/4/2018	763888	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1205292
214	9/3/2018	763730 RADIATOR CAP 70KPA - BEHR A0005014615		1205101
214	9/3/2018	763730 Ops Entered - Fault - Warning Lights Coolant - Route:	Couldn't find a coolant leak but the coolant was low. When I remove	1205101
214	8/30/2018	763019 Drv entered - A/C Heating Not Heating	Checked - Engine 80C Demister 29 Saloon 21 - all ok.	1204633
214	8/29/2018	762868 Drv entered - Vandalism Vandalism/ Graffiti Interior	Graffiti removed	1203869

214	8/29/2018	762580	Mechanic entered - Fluid Leaks Rear of bus not sure w	Checked bus and found coolant leaking from cap on header tank. Re	1203869
214	8/29/2018	762587	Consumables		1204633
214	8/29/2018	762587	Mechanic entered - Elec and Light Other Not starting	Found starter inhibitor switch bracket has come dislodged. Redrillec	1203869
214	8/24/2018	761554		VEHICLE SAFETY INSPECTION carry out safety inspection	1203132
214	8/24/2018	761554		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1203132
214	8/24/2018	761648	KIT O-RING LARGE VOSS (A6739970145)		1203132
214	8/24/2018	761648	Mechanic entered - Air System Air_Leak Rear air leaki	Replaced O'ring kit	1203132
214	8/24/2018	761644	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1203132
214	8/24/2018	761644	Mechanic entered - Air System Air_Leak Front Air leak	Replaced valve clipperd	1203132
214	8/24/2018	761644	BUTTON CLIPPARD DOOR VALVE 49Z4811		1203132
214	8/21/2018	760724	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDEF	Done	1202453
214	8/20/2018	760412	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Wheel nuts retension for all rear @202276kms.	1202118
214	8/18/2018	760195	Consumables		1201929
214	8/18/2018	760195	Chassis wash	Done	1201598
214	8/17/2018	759647	Mechanic entered - Brakes Other LH rear brakes low	Outer pad	1201598
214	8/16/2018	759647	SET DISC PAD SET SCANIA / MERCEDES 0500		1201598
214	8/16/2018	759647	ROTOR FRONT & REAR MERCEDES 0500LE		1201598
214	8/16/2018	759647	Mechanic entered - Brakes Other LH rear brakes low	Outer pad	1201598
214	8/16/2018	759647	Mechanic entered - Brakes Other LH rear brakes low	Replaced rear brake pads & roters	1201598
214	8/14/2018	759046	Mechanic entered - Wheels and Tyres Wheel Nut Reti	Retensioned	1200967
214	8/13/2018	758997	Mechanic entered - Wheels and Tyres Worn POS 4 wc	Fitted runout	1200967
214	8/13/2018	758983	Consumables		1201267
214	8/13/2018	758983	Consumables		1201267
214	8/13/2018	758983	Consumables		1201267
214	8/13/2018	758983		CARRY OUT A SERVICE AS PER CHECK LIST	1200967
214	8/13/2018	758983		Completed A service	1200967
214	8/1/2018	735257	fit door override switch as per	Creditor #:CT-BWE001 BWERE ELECTRICS PTY LTD P/O #:CT218499 R	1202800
214	7/26/2018	755242	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Graffiti cleaned	1197364
214	7/25/2018	754629	Consumables		1197364
214	7/25/2018	754629	Drv entered - Elec and Light Indicators Not Working	Checked indicators and hazard lights and found working normally.	1196658
214	7/23/2018	754288	Drv entered - A/C Heating Not Heating	Checked - Engine temperature close to 80 demister and A/C ok.	1196350
214	7/16/2018	751673	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT224213 R	1196350
214	7/16/2018	752899	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBER'	Fitted	1195003
214	7/11/2018	751673		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1193867
214	7/11/2018	751673		VEHICLE SAFETY INSPECTION	1193867
214	7/11/2018	751673		ANNUAL SAFETY INSPECTION SERIAL #RSI015322 WORKSHOP SU	1193867
214	7/9/2018	751009	Carry out random safety check	Carry out steem cleaned	1193342
214	7/9/2018	751009	Consumables		1193867
214	7/9/2018	751009	Carry out complete steamclean	Steem cleaned	1193342
214	6/28/2018	748699		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Done.	1191134
214	6/25/2018	747907	Consumables		1190708
214	6/25/2018	747907	Ops Entered - Fault - Elec and Light Exterior Lights - R	Replaced globe	1190423
214	6/22/2018	747374	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LAB	Done by Refueller.	1190143
214	6/20/2018	746689		Assisting Safety inspection complete.	1189615
214	6/20/2018	746689		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1189615
214	6/20/2018	746689		VEHICLE SAFETY INSPECTION Completed safety inspection Replaced I	1189615
214	6/20/2018	746689	LOW WATER PROBE 500LE		1189615
214	6/20/2018	746689	BUCKLE SEAT BELT PASSENGER COACH (340045)		1189615
214	6/20/2018	746689		PRE ANNUAL SAFETY INSPECTION CHECK Pre annual safety inspectio	1189615
214	6/20/2018	745654	SEAT REPAIR	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT222353 Receiv	1189615
214	6/20/2018	744179	rebranding	Creditor #:CT-TRA005 TRANSCAL P/O #:CT221915 Receiving #:23039	1190423
214	6/20/2018	746684		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST	1189615
214	6/20/2018	746684	FIRE SAFETY AND BUS MINDER	Creditor #:CT-CAR008 CARDINIA P/O #:CT222730 Receiving #:230127	1189615
214	6/20/2018	746684	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER II	completed	1189615
214	6/19/2018	746356	Consumables		1189615
214	6/19/2018	746356	Consumables		1189615
214	6/19/2018	746356	Ops Entered - Fault - Body Rear_Door Operation Fault	removed and replaced new mounting as needed	1189465
214	6/15/2018	745655	SUPLERSLIM PLASTIC BASE		1188987
214	6/15/2018	745655	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced new plastic cover as needed	1188987
214	6/15/2018	745654	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced new seat base as needed	1188987
214	6/15/2018	745664	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DE	Done by Roni	1188987
214	6/13/2018	744971	Drv entered - Steering Steering Wheel Faulty	Road tested bus and checked steering. found functioning normaly ai	1187392
214	6/12/2018	744612	Consumables		1188239
214	6/12/2018	744612	Drv entered - Elec and Light AM-FM Radio	Checked with other driver - works good.	1187392
214	6/8/2018	744179	Drv entered - Accident	repaired o\s rear panel as needed[trancal to decal]	1187392
214	6/8/2018	744179	Accident#:47380 - Ops Entered - Accident - Bus Hittin	Transcal have replaced the decal	1187392
214	6/4/2018	743068	Consumables		1187024
214	6/4/2018	743068	Consumables		1187024

214	6/4/2018	743068		completed as per checklist.	1186722
214	6/4/2018	743068		CARRY OUT A SERVICE AS PER CHECK LIST Asissting.	1186722
214	5/29/2018	741784		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1184543
214	5/29/2018	741784		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1184543
214	5/26/2018	741381	Consumables		1184854
214	5/26/2018	741381	Mechanic entered - Elec and Light Exterior Lights L/H	replaced blown head light globe. Was no power to the globe.	1184543
214	5/23/2018	740526	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - M\	Done by Refueller - Shonah	1183906
214	5/14/2018	738384	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1181550
214	5/14/2018	738384	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		1181550
214	5/14/2018	738384	VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		1181550
214	5/14/2018	738384		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Carried out Air S	1181550
214	5/1/2018	732652	Consumables		1179330
214	5/1/2018	732652	Service	Fitted new ECU test drive and ok.	1178913
214	4/30/2018	735782	Mechanic entered - Wheels and Tyres Other Pos 6 rin	preped and painted wheels as needed	1178913
214	4/27/2018	735187	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheelnuts on Pos 5 & 6 to specs.	1178099
214	4/27/2018	735257	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OV	Done by Johnny (BWere)	1178099
214	4/26/2018	734918	Wheels and Tyres worn pos 5+6	Replaced tyres on Pos 5 & 6 with runouts.	1178099
214	4/26/2018	735143	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Graffiti cleaned	1178099
214	4/26/2018	732652	Consumables		1178715
214	4/26/2018	732652	ecu	Creditor #:CT-DAI001 DAIMLER TRUCKS LAVERTON P/O #:CT217900 F	1178913
214	4/24/2018	732471	Consumables		1178403
214	4/24/2018	732471	75MM WHEELARCH BRUSH 2.5M PER WHEEL SOLD BY METRE		1178099
214	4/20/2018	733996	Drv entered - Suspension Hard	Refer w/o 733998.	1176740
214	4/20/2018	733998	Drv entered - Suspension Hard	Checked suspension and found functioning normally. Raise lower ar	1176740
214	4/17/2018	733401	AIR LINE FITTING SEAL RING O500LE AIR DRYER		1176177
214	4/17/2018	733401	Mechanic entered - Air System Air_Leak Rear Ari leaki	Replaced rubbed through air line from 4 way valve and seals in fittin	1176177
214	4/16/2018	732411	seat repair	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT217795 Receivii	1176429
214	4/16/2018	732410	PLASTIC TRIANGLE HANDSTRAP GREY		1175665
214	4/16/2018	732652	Check ECU connections.	Creditor #:CT-CAR008 CARDINIA P/O #:CT217952 Receiving #:225437	1176429
214	4/16/2018	732652	Service	Ordered new ECU	1175665
214	4/13/2018	732652	Mechanic entered - Elec and Light Other Bus won't st:	After safety inspection removed coolant header tank & replaced co	1175665
214	4/13/2018	732652	Service	Bus not starting. Suspect ECU plug wet or corroded. towed bus off pi	1175665
214	4/13/2018	732652	Mechanic entered - Elec and Light Other Bus won't st:	Assisted Graeme. Started fitting antenna. Haven't finished yet.	1175665
214	4/13/2018	732652	ECU CAM LOCK PIN BUSH HOUSING		1175665
214	4/13/2018	732652	ECU CAP (SUITS 0500)		1175665
214	4/12/2018	732325	AMBER REFLECTOR		1175665
214	4/12/2018	732325		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1175665
214	4/12/2018	732325		VEHICLE SAFETY INSPECTION Carry out Safety inspection	1175665
214	4/12/2018	732468	Mechanic entered - Vandalism Vandalism/ Graffiti Int	removed griffiti on rear seats as needed	1175665
214	4/12/2018	732411	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced 3 new seat base as needed	1175665
214	4/12/2018	732410	PLASTIC TRIANGLE HANDSTRAP GREY		1175665
214	4/12/2018	732410	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced 4 new grab handles as neded	1175665
214	4/12/2018	732443	Mechanic entered - Fluid Leaks Rear of bus Coolant le	Replaced broken hose	1175665
214	4/12/2018	732416	Consumables		1176045
214	4/12/2018	732417	Consumables		1176045
214	4/12/2018	732416	Mechanic entered - Body Other revers light lamp refl	replaced new reflector	1175665
214	4/12/2018	732471	75MM WHEELARCH BRUSH 2.5M PER WHEEL SOLD BY METRE		1175665
214	4/12/2018	732471	Mechanic entered - Body Other wheel arch brushes	replaced 2 new wheel arch brushes as needed	1175665
214	4/12/2018	732417	BLADE WIPER BLADE 900mm SWB23		1175665
214	4/12/2018	732417	Mechanic entered - Body Other wiper refill needs to f	fixed	1175665
214	4/12/2018	732434	Mechanic entered - Air System Air_Leak Rear	Replaced Air line fitting kits	1175665
214	4/12/2018	732434	VOSS NUT 232 22MM (A000997483401)		1175665
214	4/12/2018	732434	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1175665
214	4/12/2018	732342	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Carry out Difs	1175665
214	4/5/2018	730840	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retorqued wheelnuts on Pos 5 & 6 to specs.	1173684
214	4/4/2018	730557	Wheels and Tyres check/replace pos 3+4	Replaced run out tyre for pos 6	1173684
214	3/26/2018	729354	Consumables		1172420
214	3/26/2018	729354	Drv entered - Elec and Light Indicators Not Working	Replaced blown globe in RH front parker	1172095
214	3/23/2018	728692	Consumables		1171925
214	3/23/2018	728692	INDICATOR LAMP L.E.D.		1171363
214	3/23/2018	728692	Mechanic entered - Elec and Light Exterior Lights Low	Replaced L/H/RR lower LED indicator.	1171363
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421			1171363
214	3/22/2018	728421	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1171363
214	3/22/2018	728421	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1171363
214	3/22/2018	728421	FILTER P/STEER SCANIA VOLVO M/BENZ (E10H02) 0153468_1585618		1171363

214	3/22/2018	728421	FILTER FUEL FILTER MERCEDES 0500LE		1171363
214	3/22/2018	728421	FILTER P/STEER SCANIA VOLVO M/BENZ (E10H02) 0153468_1585618		1171363
214	3/22/2018	728421	FILTER P/STEER SCANIA VOLVO M/BENZ (E10H02) 0153468_1585618		1171363
214	3/22/2018	728421	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1171363
214	3/22/2018	728421		CARRY OUT C SERVICE AS PER CHECK LIST Carry out AB & C Service	1171363
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421		CARRY OUT B SERVICE AS PER CHECK LIST	1171363
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/22/2018	728421	Consumables		1171817
214	3/20/2018	727882	Drv entered - A/C Heating Not Cooling	Checked - working good.	1170689
214	3/16/2018	727323	TEST CONNECTION SCHREUDER TYPE 22mm		1170406
214	3/16/2018	727323	Mechanic entered - Breakdown Air System Fault Won	Travel to Berwick and found test fitting blown out. returned to depo	1170406
214	3/13/2018	725824	seat repairs	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT215517 Receivi	1169792
214	3/9/2018	725824	Mechanic entered - Body Passenger Seat Torn N/S Dis	replaced new disable seat as needed	1168137
214	3/9/2018	725763	Mechanic entered - Vandalism Other pos 6 tyre rim n	Painted 2 wheels as needed	1168137
214	3/8/2018	725506	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Carry out Retentened wheel nuts	1168137
214	3/8/2018	725506	Mechanic entered - Fluid Leaks Rear of bus Coolant le	Steem cleaned motor & checked fluid leak . replaced 2X hose clamp	1168137
214	3/7/2018	724990	Wheels and Tyres replace pos 5+6	Replaced run out tyre for pos 6	1168137
214	3/5/2018	724436	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO AC	done	1167885
214	2/26/2018	722566	Please remove any old poster and fit new ones multi	Done by ReFuelers - Shonah	1165760
214	2/24/2018	722178	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Torqued wheelnuts on Pos 3 & 4 to specs.	1165760
214	2/23/2018	721964		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued wheelr	1165760
214	2/23/2018	721964		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1165760
214	2/23/2018	721993	Mechanic entered - Wheels and Tyres Worn Pos 4.	Replaced tyre on Pos 4 with runout.	1165760
214	2/20/2018	721072	PLASTIC TRIANGLE HANDSTRAP GREY		1164881
214	2/20/2018	721072	Mechanic entered - Body Other Multiple grab handle:	replaced 7 hand grab handles as needed	1164881
214	2/16/2018	720410		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1164623
214	2/16/2018	720410		Asset ID A08625	1164623
214	2/12/2018	719303	Mechanic entered - Vandalism Vandalism/ Graffiti Ext	Graffiti cleaned	1163189
214	2/9/2018	718570	Drv entered - Vandalism Vandalism/ Graffiti Interior	removed griffiti on walls \seats as needed	1162640
214	2/9/2018	718555	Perform Campaign 27/17 Positioning of 2018 PTV Far	replaced fare stickers as needed	1162640
214	2/2/2018	716829	Fault - Suspension Hard / HIGH	Checked front leveling valve and found broken wire occasionally dis	1160567
214	2/1/2018	716656	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		1160567
214	2/1/2018	716656	Suspension Kneel/ Raise - driver reports bus sitting h	Replaced R/H front burst air bag.	1160567
214	1/30/2018	716044	Consumables		1160567
214	1/30/2018	716044	Consumables		1160567
214	1/30/2018	716044	Consumables		1160567
214	1/30/2018	716044	Consumables		1160567
214	1/30/2018	716044	Body Rear doors U/S	Ref WO# 715950	1160131
214	1/29/2018	715950	Consumables		1160217
214	1/29/2018	715950	Consumables		1160217
214	1/29/2018	715950	Consumables		1160217
214	1/29/2018	715950	Consumables		1160217
214	1/29/2018	715950	Mechanic entered - Body Rear_Door Operation Faulty	Checked door and repair switch wiring and reset override switch and	1160131
214	1/23/2018	715009	Mechanic entered - Brakes Other door brakes not wo	Checked Door brakes Working OK	1159895
214	1/10/2018	712597	Mechanic entered - Elec and Light Indicators Not Wor	fit globe.	1157715
214	1/5/2018	711939		VEHICLE SAFETY INSPECTION safety completed	1156841
214	1/5/2018	711939		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1156841
214	1/4/2018	711465	door brakes not working	checked operation of door brakes with doors opend and 1000 rpm. c	1156772
214	12/22/2017	709656	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retentioned wheel nuts pos 3 & 4	1156427
214	12/22/2017	709683	Drv entered - Vandalism Vandalism/ Graffiti Interior	removed griffiti as needed	1156427
214	12/22/2017	709683	Consumables		1156687
214	12/22/2017	709683	N/S/R rims need paint.	Painted wheels as needed	1156427
214	12/21/2017	709536	Wheels and Tyres replace pos 3+4	Replaced pos 3 runout tyre. Pos 4 has 6mm deep tread.	1156427
214	12/19/2017	708885	Drv entered - Vandalism Vandalism/ Graffiti Interior	preped and painted rear 2 seat backs as needed	1155530
214	12/18/2017	708699	Consumables		1155859
214	12/18/2017	708699	Rear_Door Operation Faulty problem with back door	Lubricated door hitches	1155530
214	12/18/2017	708610	Consumables		1155859
214	12/18/2017	708610	Consumables		1155859
214	12/18/2017	708610		CARRY OUT A SERVICE AS PER CHECK LIST Carry out A service as per c	1155530
214	12/9/2017	707079	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Graffiti cleaned	1153959
214	12/1/2017	705265	Consumables		1152906
214	12/1/2017	705265	Drv entered - Elec and Light Indicators Not Working	Checked indicators for work approx. 5 mins - could not fault.	1152371
214	11/26/2017	703224	AIR CONDITIONING REPAIR not co	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT207974 Receiving	1151706

214	11/24/2017	704109 VALVE 4 WAY CIRCUIT PROTECTION VALVE		1151148
214	11/24/2017	704109 KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1151148
214	11/24/2017	704109 SILENCER SNAP ON SILENCER AIR DRYER (49G3202)		1151148
214	11/24/2017	704109 Mechanic entered - Air System Other Four way valve	Replaced 4 way valve. Also fitted new silencer on the air drier and re	1151148
214	11/23/2017	703726	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1150640
214	11/23/2017	703726	VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1150640
214	11/23/2017	703725 Consumables		1151148
214	11/23/2017	703725 Wheels and Tyres pos 5+6 on 24/11/2017	Checked tyres and found still servicable. Refer Safety Inspection she	1150640
214	11/23/2017	703224	Ofloader coils replaced by Coachair --Karu	1150640
214	11/22/2017	703407 Drv entered - Vandalism Vandalism/ Graffiti Interior	Carry out interior Graffiti cleaned.	1150640
214	11/22/2017	703405	CARRY OUT FIRE EXTINGUISHER TEST & TAG Completed by ATS	1150640
214	11/21/2017	701519 DIRECT PURCHASE - VANDALISM	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT207182 Receivi	1150640
214	11/21/2017	703224 Drv entered - A/C Heating Not Cooling	No air blowing out of LH side vents and very little from RH side	1150366
214	11/15/2017	701328 Drv entered - Vandalism Vandalism/ Graffiti Interior	Painted rear seat backs as needed	1148632
214	11/14/2017	701328 Drv entered - Vandalism Vandalism/ Graffiti Interior	prep'd as needed [waiting to be painted]	1148632
214	11/14/2017	701519 Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced 1 new seat base as needed	1148632
214	11/3/2017	698094 Service	Washed	1146802
214	10/31/2017	698420 REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT206188	1146225
214	10/31/2017	698420 Vandalism - Repair Modesty film on windows	Done by GlassProtect - Shonah	1146225
214	10/30/2017	698094 Remove intercooler wash intercooler and radiator	removed guard & fixed agane.hot water machine broken.Rebook	1145925
214	10/27/2017	697483 Please remove the 2 x Do Not Enter decals at the extr	Removed stickers as required	1145324
214	10/23/2017	696093 HARDENER DELFLEET GRAFFITI RESISTANT PER 500ML		1143931
214	10/23/2017	696093 CLEANER GRAFFITI REMOVER AMERASE PER LITRE		1143931
214	10/21/2017	696093 Mechanic entered - Vandalism Vandalism/ Graffiti Int	Painted seat back as needed	1143931
214	10/21/2017	696093 Consumables		1144202
214	10/21/2017	696093 Consumables		1144202
214	10/21/2017	696093 Mechanic entered - Body Other wheels needs painted		1143931
214	10/17/2017	695076 Remove old poster and fit new A3 Posters and hange	Fitted new poster as per campaign	1142946
214	10/14/2017	694161 Drv entered - Vandalism Vandalism/ Graffiti Interior	Cleaned graffiti	1142657
214	10/11/2017	693169 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Assisting	1141715
214	10/11/2017	693169 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retensioned 123+4	1141715
214	10/10/2017	693089	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Wheel nut tensi	1141715
214	10/10/2017	693089	VEHICLE SAFETY INSPECTION Safety inspection complete.	1141715
214	10/10/2017	693089	Replaced R/H side side indicator lamp.	1141715
214	10/10/2017	693089 INDICATOR SIDE INDICATOR R/H		1141715
214	10/10/2017	693105 Mechanic entered - Wheels and Tyres Worn Position	Replaced N/S/F & O/S/F 2x steer tyres. Replaced N/S/R Outer tyre (1141715
214	10/10/2017	693105 TYRE 295/80R22.5 NEW		1141715
214	10/10/2017	693105 Mechanic entered - Wheels and Tyres Worn Position 1 and 3 ty		1141715
214	10/10/2017	693088 Consumables		1141809
214	10/10/2017	693088 Consumables		1141809
214	10/10/2017	693088 Consumables		1141809
214	10/10/2017	693088	CARRY OUT A SERVICE AS PER CHECK LIST A service complete.	1141715
214	10/9/2017	692550 PERFORM 19/17 DOOR BRAKE INTERLOCK FITMENT A	Checked by Wayne - Shonah	1141525
214	10/5/2017	691739 Drv entered - Vandalism Vandalism/ Graffiti Interior	removed graffiti on rear seats as needed	1140570
214	10/1/2017	688310 Clean air system pipes.	Creditor #:CT-HMG001 HM GEM ENGINES P/O #:CT203398 Receiving	1143931
214	9/25/2017	688656 Remove old A3 Posters with Seniors Festival please le	Done by Refuellers - Shonah	1137906
214	9/22/2017	688310 FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		1137772
214	9/22/2017	688310 VALVE DRAIN VALVE CONDENSOR MERCEDES O500LE		1137772
214	9/22/2017	688310	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Carry outAir syst	1137772
214	9/20/2017	687783 Consumables		1137545
214	9/20/2017	687783 DO NOT ENTER REAR DOOR DECAL 125MM REED/WHITE		1137202
214	9/20/2017	687783 PERFORM CAMPAIGN 09/17 REAR DOOR WARNING S	Fitted by Refueller - Shonah	1137202
214	9/14/2017	686458 Consumables		1136401
214	9/14/2017	686458 Drv entered - Body Drivers Seat Leaning	Repaced driver's seat.	1136401
214	9/14/2017	686458 SEAT DRIVERS SEAT L/H AIR LUMBAR 6500/517		1136401
214	9/12/2017	684552 Service	Recheck with test drive - ok.	1135714
214	9/12/2017	685381 Consumables		1136064
214	9/12/2017	685381 DIRECT PURCHASE - ELECTRICAL	Creditor #:CT-CAR008 CARDINIA P/O #:CT202389 Receiving #:209784	1136401
214	9/10/2017	685410 Carry out A service	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT202416 Receiving	1135714
214	9/8/2017	685410 Drv entered - A/C Heating Not Heating	Done with service.	1135071
214	9/8/2017	685381 Elec and Light - Repair main battery supply wiring.	Job done by Graham (Auto electr)	1135071
214	9/8/2017	685410	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Done by Karu (Coach	1135071
214	9/5/2017	684564 Mechanic entered - Vandalism Vandalism/ Graffiti Ext	buffed n\s panels as needed	1134410
214	9/5/2017	684552 Steering Shakes/ Wobbles at speed of 80kmh and ab	still ok need balace front wheel	1134410
214	9/5/2017	684552 FILTER AIR FILTER MERCEDES BENZ O500LE (E491L)		1134410
214	9/5/2017	684565 A/C Heating (None) - heater / demister not working	Checked - demister 28C saloon 21C - ok.	1134410
214	9/5/2017	684552 Engine Low Power	check it replace new air filter ok	1134410
214	8/25/2017	682557 Mechanic entered - Wheels and Tyres Wheel Nut Ret	Retention all rear wheel nuts	1132653

214	8/24/2017	681912	SET DISC PAD SET SCANIA / MERCEDES 0500		1132653
214	8/24/2017	681912	LAMP INTERIOR AND REVERSING (1413)		1132653
214	8/24/2017	681912			1132653
214	8/24/2017	681912		Carry out safety inspection	1132653
214	8/23/2017	681912			1132653
214	8/23/2017	681912		VEHICLE SAFETY INSPECTION	1132653
214	8/23/2017	681912		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1132653
214	8/23/2017	681947	Carry out Campaign 07/17	Creditor #:CT-BWE001 BWERE ELECTRICS PTY LTD P/O #:CT201209 R	1133838
214	8/23/2017	681947	Campaign 07/17 WIFI CCTV UPGRADE.Cordinate upgr	Done by John (BWere)	1132653
214	8/19/2017	681131	Consumables		1131697
214	8/19/2017	681131	Mechanic entered - Elec and Light Exterior Lights l/h f	Replaced N/S/F park light globe	1131697
214	8/18/2017	681117	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Job has been done as required.	1131697
214	8/4/2017	678069	Consumables		1128909
214	8/4/2017	678069	Mechanic entered - Elec and Light Exterior Lights R/H	Replaced blown globe.	1128348
214	8/4/2017	678140	Please remove old posters and fit new one along with done		1128348
214	8/1/2017	681912	BRAKE CALIPER TAPPET KIT 0500	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT201064 Receiving	1132653
214	8/1/2017	681912	BRAKE CALIPER TAPPET KIT 0500	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT201064 Receiving	1132653
214	8/1/2017	677259	Consumables		1128009
214	8/1/2017	677259	Consumables		1128009
214	8/1/2017	677259	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1127788
214	8/1/2017	677259	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E16		1127788
214	8/1/2017	677259		CARRY OUT B SERVICE AS PER CHECK LIST	1127788
214	8/1/2017	677259	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EAS500M05)		1127788
214	8/1/2017	677259	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1127788
214	8/1/2017	677259	FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)		1127788
214	8/1/2017	677259			1127788
214	8/1/2017	677259	Consumables		1128009
214	8/1/2017	677259	Consumables		1128009
214	8/1/2017	677259		CARRY OUT A SERVICE AS PER CHECK LIST	1127788
214	7/14/2017	673234	CARRY OUT YEARLY INSPECTION	Creditor #:CT-ROA001 ROAD SAFETY INSPECTIONS P/O #:CT197700 R	1125069
214	7/13/2017	673409	Consumables		1123564
214	7/13/2017	673409	Body- LH/R FRAME RUST & LH/R TOP SUPPORT LOOSI	removed rust frame and replaced new as needed	1123023
214	7/12/2017	673234		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1123023
214	7/12/2017	673234		VEHICLE SAFETY INSPECTION	1123023
214	7/12/2017	673234	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1123023
214	7/12/2017	673234		Assisting repair leaking joints and for rsi	1123023
214	7/12/2017	673234		ANNUAL SAFETY INSPECTION SERIAL #RSI 00957	1123023
214	7/10/2017	672759	Carry out random safety check		1122670
214	7/10/2017	672759	Carry out random safety check	random safety check done	1122670
214	7/10/2017	672791	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		1122670
214	7/10/2017	672791	Mechanic entered - Air System Other leaking from ne:	replace leaking air unit useing o ring kit	1122670
214	7/10/2017	672796	Accident#:45694 - Ops Entered - Accident -damage at	removed repaired 2 panel as needed	1122670
214	7/7/2017	672362	Consumables		1122670
214	7/7/2017	672362	Drv entered - Elec and Light Indicators Not Working	Checked indicators and found operating normally. Operated indicati	1121998
214	7/5/2017	672017	Drv entered - A/C Heating Not Heating	Ckecked - demister 29C saloon 24C. Could not fault.	1121655
214	6/30/2017	670989	Drv entered - Steering Excessive Play	check front end ok check tyre pressures foud slitliy play on angle ste	1119823
214	6/30/2017	670987	Consumables		1120373
214	6/30/2017	670987	Mechanic entered - Elec and Light Exterior Lights fron	replace gloube	1119823
214	6/29/2017	670841	PERFORM CAMPAIGN 05/17 BUS DESTINATION PROG	Checked / Uploaded by Refueller	1119823
214	6/28/2017	670516	Consumables		1119823
214	6/28/2017	670516	Carry out complete steamclean	Completed steam clean	1119628
214	6/26/2017	669800	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Cleaned graffitti	1118699
214	6/22/2017	668890	FILTER TRANSMISSION ZF (4139-298-038) (4139 298 038 01)		1118405
214	6/22/2017	668890		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST trans mistior	1118405
214	6/22/2017	669167	Consumables		1118699
214	6/22/2017	668889	Consumables		1118699
214	6/22/2017	668889	Drv entered - Body Windows Side	removed and resealed side window as needed	1118405
214	6/22/2017	668889	Drv entered - Body Windows Side		1118405
214	6/22/2017	669167	Remove old Green 2016/17 registration Label and/ or	Done by Refuellers	1118405
214	6/22/2017	668900	Mechanic entered - Brakes Other Air leaking from foo	Replaced foot valve.	1118405
214	6/22/2017	668900	BRAKE VALVE FOOT BRAKE MERCEDES BENZ 0500LE (A4800010050)		1118405
214	6/16/2017	667728		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Torqued all whe	1117476
214	6/16/2017	667728		VEHICLE SAFETY INSPECTION Carried out Safety Inspection.	1117476
214	6/16/2017	667845		PRE ANNUAL SAFETY INSPECTION CHECK Carried out Annual Safety Ir	1117476
214	6/16/2017	667765	Carry out annual fire safety i	Creditor #:CT-CAR008 CARDINIA P/O #:CT195861 Receiving #:202852	1117797
214	6/16/2017	667765		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Done byGra	1117476
214	6/15/2017	662100	BATTERY 12V 200AMP 1100CCA + LHS EMFN200L		1117476
214	6/13/2017	666893	Consumables		1117109

214	6/13/2017	666893	Mechanic entered - Elec and Light Other N/S headligh	Replaced blown globe.	1116859
214	5/31/2017	662100	DIRECT PURCHASE - ELECTRICAL	Creditor #:CT-CAR008 CARDINIA P/O #:CT194040 Receiving #:201863	1114738
214	5/29/2017	663354	Service	Checked bus history no drivers complaint.	1113817
214	5/25/2017	663354	Drv entered - Steering Shakes/ Wobbles	Checked wheels and steering system - ok. Test drive - very little wobl	1112510
214	5/24/2017	663119	Consumables		1113191
214	5/24/2017	663119	Drv entered - Elec and Light Indicators Not Working	Checked indicators - no fault found. Indicator stalk not self cancellin	1112510
214	5/19/2017	659246	DIRECT PURCHASE - ACCIDENT	Creditor #:CT-TRA005 TRANSCAL P/O #:CT193214 Receiving #:201330	1113191
214	5/19/2017	662432	Accident - NEAR SIDE REAR - Rebranding refer wo 65	Rebranding by Transcal on 19/05/2017	1111819
214	5/18/2017	660884	DIRECT PURCHASE - VANDALISM	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT193545 Receiving	1111806
214	5/18/2017	662100	Breakdown Road Defect Affects Service	Graham replaced Alternator and wayne road tested	1111540
214	5/18/2017	662100	REGULATOR VOLTAGE REGULATOR (0405NH) (94V0003) (VR3014G)		1111540
214	5/18/2017	662100	Breakdown Road Defect Affects Service	Replaced regulator - still not charging. Require new alternator.	1111540
214	5/18/2017	662100	Breakdown Road Defect Affects Service	Attended broken down bus. Found all belts still intact but alternator	1111540
214	5/17/2017	626721	DECAL # 2 125mm BLACK		1111540
214	5/16/2017	661464	Consumables		1111540
214	5/16/2017	661464	Fit A3 Poster/Hangers	Done by Rob Snow	1110945
214	5/12/2017	660884	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replaced seats as needed	1110663
214	5/12/2017	660884	SQUAB CENTRA SEAT MELBOURNE BLUE		1110663
214	5/12/2017	660884	SEAT FOAM CUSHION CENTRA SEAT MELBOURNE BLU		1110663
214	5/12/2017	660946	Consumables		1110936
214	5/12/2017	660946	Consumables		1110936
214	5/12/2017	660946	Consumables		1110936
214	5/12/2017	660946		CARRY OUT A SERVICE AS PER CHECK LIST Completed A service	1110663
214	5/12/2017	660946	NARVA 24V REVERSING BUZZER		1110663
214	5/11/2017	660650	Consumables		1110936
214	5/11/2017	660547	Consumables		1110936
214	5/11/2017	660650	sim cards fitteed by BWere	Sim Cards fitted by BWERE	1110663
214	5/11/2017	660547	Mechanic entered - Elec and Light Exterior Lights rhf	Replaced blown globe.	1110663
214	5/10/2017	660127	Consumables		1110663
214	5/10/2017	660127	DIRECT PURCHASE - GLASS	Creditor #:CT-A1W001 A-1 Windscreens P/O #:CT193205 Receiving #	1110663
214	5/9/2017	660127	Body Windows Front - windscreen cracked almost rig	Job done by A1 on 10/05/2017. Fitted new winscreen seal.	1110186
214	5/6/2017	659749	Mechanic entered - Wheels and Tyres Wheel Nut Ret	Completed retension	1109373
214	5/5/2017	659496	DIRECT PURCHASE - TYRES	Creditor #:CT-TYR002 TYRES4U P/O #:CT193001 Receiving #:199891	1110186
214	5/5/2017	659496	Mechanic entered - Wheels and Tyres Other Position	replace x2 new rethread 295 80 22.5	1109373
214	5/5/2017	659496	Mechanic entered - Wheels and Tyres Other Position	replaced P5-6 with new recaps	1109373
214	5/4/2017	659246	Mechanic entered - Accident - NEAR SIDE REAR unrep	repaired rear fibra glass and painted as needed	1109373
214	5/2/2017	658759	DECAL VENTURA 630x185mm		1108734
214	5/2/2017	658759	Mechanic entered - Fluid Leaks Other coolant leak at	removed cracked pipe and jarek used the oxy but it didnt work. jarek	1108734
214	5/2/2017	658759	Consumables		1109373
214	5/2/2017	658759	Mechanic entered - Body Other Rear ventura decal d	fitted new decal	1108734
214	5/1/2017	660650	Direct Purchase - ELECTRICAL	Creditor #:CT-BWE001 BWERE ELECTRICS P/O #:CT193450 Receiving	1110663
214	4/28/2017	658386	LAMP SIDE MARKER (RED+AMBER)		1108578
214	4/28/2017	658386		Safety inspection complete.	1108578
214	4/28/2017	658386		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1108578
214	4/28/2017	658386		VEHICLE SAFETY INSPECTION Completed safety inspection. fank to ro	1108578
214	4/28/2017	658386	DECAL BATTERY 9516396		1108578
214	4/28/2017	658386	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1108578
214	4/28/2017	658386	DECAL PLEASE KEEP CLEAR DOOR OPENS INWARDS		1108578
214	4/26/2017	657440	REPAIR VANDALISED WINDOWS	Creditor #:CT-GLA010 GLASSPROTECH MELBOURNE P/O #:CT192133	1107955
214	4/21/2017	657440	Vandalism - Re Film L1 L2 R1 R2	Done by glass Protect - Shonah	1106687
214	4/5/2017	654925	FILTER REGULATOR ASSEMBLY		1103571
214	4/5/2017	654925	Air System small Air_Leak Front	Replaced air regulator.	1103571
214	4/1/2017	627326	REPAIR STEERING BOX	Creditor #:CT-HYD001 HYDROSTEER PTY.LTD. P/O #:CT191153 Receiving	1103948
214	3/29/2017	653476	Consumables		1102522
214	3/29/2017	653476	Consumables		1102522
214	3/29/2017	653476	Drv entered - Elec and Light Indicators Not Working	Checked indicators and hazard lights. Fouind operating normally. Co	1101931
214	3/27/2017	648601	Consumables		1102251
214	3/27/2017	648601	Consumables		1102251
214	3/27/2017	648601	Direct Purchase - ELECTRICAL	Creditor #:CT-WHI001 WHITEHORSE TRUCK CENTRE P/O #:CT188716	1101582
214	3/17/2017	651322	Mechanic entered - Wheels and Tyres Other wheel nu	complete retension	1099663
214	3/16/2017	651117	GLOBE 24V1.2WWEDGE (HLW241.20)(47706)(SWFLED)(E-596FWLED)		1099132
214	3/16/2017	651117		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done	1099132
214	3/16/2017	651117		VEHICLE SAFETY INSPECTION done	1099132
214	3/16/2017	651096	DIRECT PURCHASE - TYRES	Creditor #:CT-TYR002 TYRES4U P/O #:CT189590 Receiving #:196331	1099663
214	3/16/2017	651096	Wheels and Tyres Worn replace pos 4 on 16/03/2017	replace x2 tyres 295 80 22.5 P 3 4 RETHREADS	1099132
214	3/16/2017	651226	Mechanic entered - Engine Other boose pipe leaking	remove weld bracket replace new clamp done	1099132
214	3/16/2017	651232	OVERFLOW VALVE 0405/0500 (A4341000220)		1099132
214	3/16/2017	651232	Mechanic entered - Air System Air_Leak Rear from o	replace new over flow valve	1099132

214	3/9/2017	650017	Drv entered - A/C Heating Not Cooling	Checked A/C and found compressor engaging and A/C blowing out 2	1098087
214	3/7/2017	649382	AIR CONDITIONING REPAIR	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT188908 Receiving	1097121
214	3/6/2017	643868	Direct Purchase - ELECTRICAL	Creditor #:CT-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #:CT18899	1097121
214	3/6/2017	649382	A/C Heating Not Cooling	Checked by Raj - No Fault found (Shonah)	1097395
214	3/2/2017	648601	Reprogrammed at Whitehorse as per Pine		1096984
214	3/1/2017	648601	Mechanic entered - Dash Speedo Not Working	removed faulty dash and replaced with new one. to be roadtested.	1096984
214	2/28/2017	648432	Consumables		1096984
214	2/28/2017	648432	Consumables		1096984
214	2/28/2017	648432	Consumables		1096984
214	2/28/2017	648432		CARRY OUT A SERVICE AS PER CHECK LIST Completed A service	1096716
214	2/25/2017	647544	DIRECT PURCHASE - VANDALISM	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT188276 Receiving	1096512
214	2/24/2017	647544	Mechanic entered - Vandalism Vandalism/ Graffiti Int	removed and replaced new lift up disable seat	1095549
214	2/24/2017	647543	Consumables		1096512
214	2/24/2017	647543	Mechanic entered - Body Other wheels needs painte	pped and painted 1 rear wheel	1095549
214	2/23/2017	643868	Drv entered - A/C Heating Not Cooling	Checked A/C operations - working ok.	1095549
214	2/23/2017	643868	UNIT CONTROL UNIT ICU 402		1095549
214	2/23/2017	643868	BATCH ADAPTER ICU400/402 MOBITEC		1095549
214	2/23/2017	643868	Consumables		1096180
214	2/23/2017	643868	Upgrade desto controller to USB style controller		1095549
214	2/21/2017	646198	AIR CONDITIONING REPAIR	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT187929 Receiving	1095549
214	2/20/2017	646198	Drv entered - A/C Heating Not Cooling	RAJ -- REPLACED FAULTY EVAP MOTORS and repaired wiring	1094907
214	2/18/2017	645905	Vandalism Vandalism/ Graffiti Interior	pped and painted rear seats as needed	1094503
214	2/18/2017	645905	Consumables		1094740
214	2/18/2017	645905	Elec and Light Exterior Lights - O/S headlight out.	alredy done head light same job number	1094503
214	2/18/2017	645905	Mechanic entered - Elec and Light Exterior Lights o/s l	O S front head light gloube replace	1094503
214	2/18/2017	645905	GLOBE 24V 70W H1		1094503
214	2/17/2017	645636	Consumables		1094740
214	2/17/2017	645856	Consumables		1094740
214	2/17/2017	645856	Dash Speedo Not Working.	Swapped dash with second hand dash .. monitor to confirm fault bee	1094503
214	2/17/2017	645636	Elec and Light (None)- driver reports indicators not c	Serviceable - will not replace.	1094503
214	2/17/2017	645783	Please remove any old poster and fit either Good Nev	Changed poster as required	1094503
214	2/16/2017	645072	Consumables		1094503
214	2/16/2017	645072	Mechanic entered - Elec and Light Other electrical fau	Removed speedo drive connection and cleaned terminals. Refit and	1094322
214	2/16/2017	645072	Drv entered - Dash Speedo Not Working	Checked speedo - showing 20kph on park. Parked on PIT than go on	1094322
214	2/15/2017	644762	Consumables		1094322
214	2/15/2017	644762	Drv entered - Dash Guages Not Working	Checked gauges dash lights - working good.	1094176
214	2/14/2017	626721	HARDENER DELFLEET GRAFFITI RESISTANT PER 500ML		1093810
214	2/14/2017	644699	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CON	Carried out Campaign and update spreadsheet	1093810
214	2/10/2017	644036	AIR DRYER MERCEDES 0500 (49G8505WABCO)		1093379
214	2/10/2017	644036		Finished off air system service.	1093379
214	2/10/2017	644036	KIT DRAIN VALVE KIT BOTTOM		1093379
214	2/10/2017	644036	KIT CYCLONE CONDENSER VALVE KIT		1093379
214	2/10/2017	644036		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Overhauled cycl	1093379
214	2/9/2017	643868	Upgrade desto controller to USB style controller		1093177
214	2/8/2017	643645	A/C Heating Not Cooling	Checked air con. Still seems to be working. Could not find a fault wit	1093023
214	2/8/2017	627326	Direct Purchase - ELECTRICAL	Creditor #:CT-CAR011 CARDINIA P/O #:CT187041 Receiving #:193638	1093502
214	2/6/2017	640591	DIRECT PURCHASE - CHASSIS	Creditor #:GB-HEM001 HEMA'S HOSE SERVICES P/O #:CT186855 Rec	1093502
214	2/6/2017	640591	Service	Replaced broken P/S hose washed box bleed system and ok.	1092468
214	2/6/2017	640591	Warning Lights Engine - low power steering oil light c	Assisting	1092468
214	2/6/2017	642963	Consumables		1092637
214	2/6/2017	642967	Consumables		1092637
214	2/6/2017	642963	Mechanic entered - Elec and Light Exterior Lights n/s	Checked - working ok.	1092468
214	2/6/2017	642967	Mechanic entered - Elec and Light Exterior Lights n/s	checked all lights and could not fault.	1092468
214	2/3/2017	627326	Fluid Leaks - Steering box leaking oil	Refit steering box. topped up and bled system.	1092330
214	2/1/2017	642201		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Tune-up service co	1092330
214	2/1/2017	627326	Fluid Leaks - Steering box leaking oil	Rechecked - require replace front seal (small from steering shaft).	1076754
214	2/1/2017	627326	Fluid Leaks - Steering box leaking oil	CLEANE STEERRING BOX SEND OUT TO MONITOR WHERE OIL LEAK IS	1076754
214	1/31/2017	627326	Fluid Leaks - Steering box leaking oil	Removed steering box and sent out for repairs.	1092330
214	1/29/2017	641170	Service A/C as per attached sh	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT186289 Receiving	1092078
214	1/27/2017	641170	A/C Heating Not Cooling	Done by Raj with Service on 27/01/2017 R7R Faulty Cond motor x 5	1091657
214	1/27/2017	641185	Fit New 2107 Large and Small Fares Small Concession:	replaced concession decal	1091657
214	1/27/2017	641170		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Done by Raj on 27/01	1091657
214	1/27/2017	641170		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Done by Raj on 27/01	1091657
214	1/25/2017	640693	INDICATOR LOOSE WHEEL NUT INDICATOR 32mm		1091203
214	1/25/2017	640693	Wheels and Tyres (None) O/S/F wheel nut pointer mi	Fitted pointer as required.	1091203
214	1/25/2017	640591	Mechanic entered - Steering Other steering box leakir	Booked to remove and repair.	1091203
214	1/25/2017	640693	Consumables		1091657
214	1/25/2017	640692	Consumables		1091657

214	1/25/2017	640693 Elec and Light (None) Wheel chair ramp not working. Checked - could not fault.	1091203
214	1/25/2017	640692 GLOBE 24V 5W (HLG245) (2627)	1091203
214	1/25/2017	640692 Mechanic entered - Elec and Light Exterior Lights lhf u Replaced blown globe.	1091203
214	1/25/2017	640694 PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING Carried out campaign - no labels used.	1091203
214	1/20/2017	640013 Consumables	1091000
214	1/20/2017	640013 Elec and Light Exterior Lights lower park light n/w Checked all park lights ok at this time.	1090502
214	1/16/2017	639055 TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1089538
214	1/16/2017	639055 VEHICLE SAFETY INSPECTION	1089538
214	1/16/2017	639154 Consumables	1090133
214	1/16/2017	639154 Elec and Light Warning Light On Dash-battery light 2. Checked ok.	1089538
214	1/16/2017	639055 Body- exterior sticker onback of bus - Ventur -missin Checked ok.	1089538
214	1/5/2017	632101 HOSE ENG/TRANS	1085631
214	1/5/2017	632101 HOSE ENG TO G/BOX COOLER MERC 0500LE 50N0562	1085631
214	12/30/2016	635887 GLOBE 24V 4W SINGLE CONTACT [BOX 10]	1085631
214	12/30/2016	635887 Mechanic entered - Elec and Light Exterior Lights remove and replace N/S/F parker globe .	1085631
214	12/22/2016	634740 Mechanic entered - Wheels and Tyres Wheel Nut Ret Retensioned 3+4	1085237
214	12/21/2016	634697 Mechanic entered - Fluid Leaks Other diff brether con remove line and cut it and repair as needed	1085237
214	12/21/2016	634535 KIT SEAL KIT REAR HUB MERCEDES 0500LE (1F1304) (50F1317)	1085237
214	12/21/2016	634535 Mechanic entered - Fluid Leaks Other N/S/R hub oil le replace ns rear hub seal clean all the wheel and rims	1085237
214	12/21/2016	634599 A3 POSTER CHANGE X 4 ENDING JAN 2017 PLEASE SEE DONE BY BOB	1085237
214	12/19/2016	634013 Consumables	1084896
214	12/19/2016	634013 COOLANT DOOR HATCH 1/4 TURN LATCH	1084145
214	12/19/2016	634013 Mechanic entered - Body Other coolant flap latch brc removed and replaced new coolant flap	1084145
214	12/13/2016	633021 Consumables	1083638
214	12/13/2016	633021 Dash Speedo Not Working Checked with GPS - working good. Tacho not reading.	1082974
214	12/7/2016	632101 HOSE ENG TO G/BOX COOLER MERC 0500LE 50N0562	1081834
214	12/7/2016	632101 Mechanic entered - Engine Other Thermostat hose w drain coolant replace thermostat houseing hose finish it ok	1081834
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 FILTER FUEL FILTER MERCEDES 0500LE	1081834
214	12/7/2016	631955 CARRY OUT C SERVICE AS PER CHECK LIST Carried out C Service.	1081834
214	12/7/2016	631955 FILTER P/STEER SCANIA VOLVO M/BENZ 0153468_1585618-0_153468	1081834
214	12/7/2016	631955 FILTER FUEL FILTER MERCEDES 0500LE	1081834
214	12/7/2016	631955 FILTER AIR FILTER MERCEDES BENZ 0500LE (E491L)	1081834
214	12/7/2016	631955 KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)	1081834
214	12/7/2016	631955 FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)	1081834
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 CARRY OUT B SERVICE AS PER CHECK LIST Carried out B Service.	1081834
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 Consumables	1082173
214	12/7/2016	631955 CARRY OUT A SERVICE AS PER CHECK LIST Carried out A Service.	1081834
214	12/1/2016	606312 Consumables	1080434
214	12/1/2016	606312 KIT ROLLAWAY PROTECTION DEVIC Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE179200 Re	1083893
214	11/30/2016	630697 Consumables	1080054
214	11/30/2016	630697 Mechanic entered - Body Other 2 hoses on chassis be Moved hoses used rubber seperation and secured.	1079770
214	11/30/2016	630651 KIT AIR LINE FITTING VOSS 22MM (50Z0114)	1079770
214	11/30/2016	630651 AIR LINE FITTING SEAL RING 0500LE AIR DRYER	1079770
214	11/30/2016	630651 Mechanic entered - Brakes Foot_Brakes Leaking Air Replaced leaking foot valve and rekkited one air line.	1079770
214	11/30/2016	630651 BRAKE VALVE FOOT BRAKE MERCEDES BENZ 0500LE (A4800010050)	1079770
214	11/29/2016	630420	1079770
214	11/29/2016	630420 TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1079770
214	11/29/2016	630420 VEHICLE SAFETY INSPECTION	1079770
214	11/29/2016	630419 Mechanic entered - Body Other Body deadner needs removed all rotten body deadner ready 4 spray on	1079770
214	11/29/2016	630609 Mechanic entered - Body Other radiator rubber bush replace broken rubber bush	1079770
214	11/29/2016	630609 BUSH RUBBER SLEEVE RADIATOR - 0500LE A0009872143	1079770
214	11/29/2016	630419 Direct Purchase - BODYWORK Creditor #:CT-BAY005 BAYFORD GROUP PTY LTD P/O #:CT182471 Rec	1079770
214	11/29/2016	630609 Consumables	1079914
214	11/29/2016	630419 Consumables	1079914
214	11/29/2016	630221 FILTER OIL FILTER MERCEDES BENZ 1725+0500LE (E161H01D28)	1079770
214	11/29/2016	630221 KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EA'	1079770
214	11/29/2016	630221 Consumables	1079914
214	11/29/2016	630221 Consumables	1079914
214	11/29/2016	630221 Consumables	1079914
214	11/28/2016	630419 Direct Purchase - BODYWORK Creditor #:CT-BAY005 BAYFORD GROUP PTY LTD P/O #:CT182429 Rec	1079770
214	11/28/2016	630309 Mechanic entered - Body Other Drivers door needs re repaired drivers door fibra glass	1079770
214	11/28/2016	630293 Mechanic entered - Body Other Battery panel needs f Roni cut handle slots.	1079770

214	11/28/2016	630291	Mechanic entered - Body Other Rear hatch struts not	Replaced gas struts with second hand ones as didnt have correct on	1079770
214	11/28/2016	630282	Mechanic entered - Body Other battery panel not clo	removed and cut panel to close properly	1079770
214	11/28/2016	630309	Consumables		1079914
214	11/28/2016	630293	Consumables		1079914
214	11/28/2016	630291	Consumables		1079914
214	11/28/2016	630282	Consumables		1079914
214	11/28/2016	630221		CARRY OUT B SERVICE AS PER CHECK LIST Completed B service and r	1079770
214	11/28/2016	630221	VALVE EXTENSION-130mm Metal type		1079770
214	11/28/2016	630221		Carried out B Service.	1079770
214	11/28/2016	630221	Consumables		1079914
214	11/28/2016	630221	Consumables		1079914
214	11/28/2016	630221	Consumables		1079914
214	11/28/2016	630221		CARRY OUT A SERVICE AS PER CHECK LIST	1079770
214	11/27/2016	629440	AIR CONDITIONING REPAIR	Creditor #:CT-COA003 COACHAIR PTY LTD P/O #:CT182141 Receiving	1079770
214	11/24/2016	629337		Repaired by Coachair	1078662
214	11/23/2016	629572	Mechanic entered - Vandalism Other Hammer remov	Replaced missing hammer	1078328
214	11/23/2016	629572	EMERG HAMMER KIT		1078328
214	11/23/2016	629440	BELT AIR CONDITIONING MERCEDES BENZ 0500		1078328
214	11/23/2016	629440	PULLEY ADJUSTER IDLER PULLEY MERCEDES 0500 (A0005501833)		1078328
214	11/23/2016	629440	A/C clutch or compressor seized up..Coachair booker	Repaired by Raj -- Coachair ..fitted new clutch coil	1078328
214	11/22/2016	629337	Mechanic entered - Breakdown Other A/C pulley seiz	Arrived on site. Removed the remains of the old belt. Fitted cable tie	1078328
214	11/21/2016	626721	CLEANER GRAFFITI REMOVER AMERASE PER LITRE		1077570
214	11/18/2016	628009	Consumables		1077794
214	11/18/2016	628009	Drv entered - Elec and Light AM-FM Radio	Checked antenna and found bad connection in antenna lead. Repair	1077570
214	11/17/2016	628479	Consumables		1077570
214	11/17/2016	628009	VOLTAGE REDUCER 24V-12V ..8AMP		1077327
214	11/17/2016	628009	Drv entered - Elec and Light AM-FM Radio	Supplied and fitted radio. Radio working fine but antenna faulty rec	1077327
214	11/17/2016	628479	Elec and Light Two Way Radio - 2WAY REPROGRAMM	Done by AA Radios	1077327
214	11/16/2016	628009	DIRECT PURCHASE	Creditor #:CT-MUL001 MULTISPARES LTD P/O #:CT181655 Receiving	1077327
214	11/16/2016	628009	Drv entered - Elec and Light AM-FM Radio	Checked AM/FM radio and found unserviceable. Need to order new	1077233
214	11/15/2016	627211	Consumables		1077233
214	11/15/2016	624015	Consumables		1077233
214	11/15/2016	627211	reset speedo parrameters	Creditor #:CT-WHI001 WHITEHORSE TRUCK CENTRE P/O #:CT181411	1079770
214	11/15/2016	627211		reprogrammed by Whitehorse trucks	1077044
214	11/15/2016	624015	REPROGRAM TWO WAY TO DANDENONG	Creditor #:GB-AAR001 AA RADIO SERVICES PTY LTD P/O #:G180149 R	1077233
214	11/14/2016	626721	DIRECT PURCHASE - VANDALISM	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT181120 Receivii	1077327
214	11/14/2016	628479	reprogram 2 way to depot	Creditor #:CT-AAR001 AA RADIO SERVICES PTY LTD P/O #:CT180786 f	1077327
214	11/11/2016	627211	Ops Entered - Fault - Dash Speedo Not Working - Rou	Cleaned contacts at sender which stopped speedo dropping out but	1075595
214	11/10/2016	626721	Bad Vandalism on inside bus been delivered to Paker	painted griffiti on interior and painted 4 wheels	1075595
214	11/10/2016	626517	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Cleaned prepped and painted both interior floor and wheels. Buffed	1075595
214	11/10/2016	627053	Consumables		1075652
214	11/10/2016	627053	BELT SEAT BELT R/H A60RH		1075595
214	11/10/2016	627053	Mechanic entered - Body Other drivers seat belt miss	replaced new drivers seat belt as needed	1075595
214	11/9/2016	626721	DECAL # 4 125mm BLACK		1075595
214	11/9/2016	626721	DECAL # 2 125mm BLACK		1075595
214	11/9/2016	626721	DECAL # 1 125mm BLACK		1075595
214	11/9/2016	626721	Bad Vandalism on inside bus been delivered to Paker	Assisting	1075595
214	11/9/2016	626721	Bad Vandalism on inside bus been delivered to Paker	painted on griffiti walls and seat back as needed	1075595
214	11/9/2016	626517	DIRECT PURCHASE - VANDALISM	Creditor #:CT-SUP100 SUPERIOR TAILORING P/O #:CT180890 Receivii	1075652
214	11/9/2016	626517	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Removed all side panels painted and put back. Cleaned prepped anc	1075595
214	11/9/2016	626517	Mechanic entered - Vandalism Vandalism/ Graffiti Int	done some masking	1075595
214	11/8/2016	626517	CENTRA CUSHION CLIP LH		1075595
214	11/8/2016	626517	CENTRA CUSHION CLIP RH		1075595
214	11/8/2016	626517	PASS SEAT HANDGRIP CENTRA MK 2		1075595
214	11/8/2016	626517	Mechanic entered - Vandalism Vandalism/ Graffiti Int	Replaced 8 torn seats and 1 head rest/handle. Started sanding down	1075595
214	11/8/2016	626517	Mechanic entered - Vandalism Vandalism/ Graffiti Int	replace sear pads x6	1075595
214	11/4/2016	626517	DIRECT PURCHASE - VANDALISM	Creditor #:CT-HOL001 CAMIRA GROUP PTY LTD P/O #:CT180678 Rece	1075652
214	11/3/2016	625046	Consumables		1075652
214	11/3/2016	625046	Drv entered - Elec and Light AM-FM Radio	Bus moved to cardinia	1075595
214	11/2/2016	616275	ICU 400 controller need repair	as above	1068959
214	11/1/2016	616275	REPAIR ICU 400 CONTROLLER	Creditor #:GB-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #:G177213	1077044
214	10/31/2016	625046	Consumables		1075652
214	10/31/2016	625046	Ops Entered - Fault - Dash Speedo Not Working - Rou	roadtested to check speedo working ok. showing correct speed whe	1075595
214	10/26/2016	624015	Consumables		1075338
214	10/26/2016	624015	Elec and Light Two Way Radio: 2 WAY RADIO NOT TR	As above	1075318
214	10/26/2016	624015	Elec and Light Two Way Radio	Reprogramed two way radio to dandenong by AA radio	1075318
214	10/26/2016	624015	Drv entered - Comm Equip	As above	1075318
214	10/26/2016	624209	Fit A3 poster to holder either Explore Melbourne or P	Fitted by Fleet Support	1075338

214	9/28/2016	618878	REF TO W/O 618811	1070209
214	9/28/2016	618811	Re-tensioned wheel nuts position 125 and 6 with Dulkith	1070209
214	9/28/2016	618811	done	1070209
214	9/28/2016	619171 Consumables		1070691
214	9/28/2016	619171 A3 Poster Change please remove old poster and fit Vi	Completed by Fleet Support	1070691
214	9/27/2016	618381 Consumables		1070472
214	9/27/2016	618381 TYRE 11R22.5R RECAP		1070209
214	9/27/2016	618381 TYRE 11R22.5N NEW		1070209
214	9/27/2016	618543 Consumables		1070472
214	9/27/2016	618543 GLOBE 24V 3W INSTRUMENT		1070209
214	9/26/2016	618174	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1070209
214	9/26/2016	618174	VEHICLE SAFETY INSPECTION	1070209
214	9/26/2016	618174		1070209
214	9/26/2016	618380 Consumables		1070209
214	9/26/2016	618381 Wheels and Tyres	Replaced tyres pos 12 56 with nick and re-tensioned	1070209
214	9/26/2016	618381 Wheels and Tyres replace tyre no 1/2and 5/6.	Replaced tyres pos 12 56 with nick and re-tensioned	1070209
214	9/26/2016	618380 Wheels and Tyres - Tyre 6 worn	Assisting	1070209
214	9/26/2016	618380 Wheels and Tyres - Tyre 6 worn		1070209
214	9/26/2016	618543 Elec and Light - Replace parker globe	Replaced	1070209
214	9/26/2016	618380 CCTV Fix front facing camera position	Pascal fixed	1070209
214	9/26/2016	618025 Accident damage - N/S/R - Acc # DAN 44009. *INTERN	Cut and applied PTV decal to suit	1070209
214	9/26/2016	618025 LAMP LED SIDE LAMP RED/AMBER PEREI (52-98002)		1070209
214	9/26/2016	618025 LIGHT BRAKE LIGHT LED		1070209
214	9/26/2016	618025 Accident damage - N/S/R - Acc # DAN 44009. *INTERN	fitted new side LED light. fitted new break/parkerlight	1070209
214	9/23/2016	617778 Drv entered - A/C Heating Not Heating	Commission tested unit found that the return air filter is blocked ren	1070209
214	9/16/2016	616275 Consumables		1069227
214	9/16/2016	616275 ICU 400 controller need repair	removed from bus 208 and fit to bus 214 and bus 214 controller senc	1068959
214	9/15/2016	616180 Fluid Leaks - Hydraulic oil leaking	Steam clean - road tested no leaks found - Posseble from engine oil	1068904
214	9/14/2016	615847 Anti-Graffiti film L1L2L3R1R3		1068413
214	9/14/2016	614335 Supply and apply PTV Accident	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G176604 Receiving #:1	1068662
214	9/9/2016	614986 Consumables		1068413
214	9/9/2016	614986 Ops Entered - Fault - Desto Signs - Route: - Arrive Da as above		1067889
214	9/9/2016	614986 Ops Entered - Fault - Desto Signs - Route: 811d - Danr	Removed desto controller from bus 208 and fitted to bus 214	1067889
214	9/9/2016	614335 Accident damage - O/S - Acc # DAN 42796. *INTERNAL*		1067889
214	9/8/2016	614335 Accident damage - O/S - Acc # DAN 42796. *INTERNAL	Continued repairs	1067889
214	9/8/2016	614335 Accident damage - O/S - Acc # DAN 42796. *INTERNAL	refit o/s/r punch panel inner trim panels around radiator reflectors :	1067889
214	9/8/2016	614335 WHEEL ARCH BRUSH PLASTIC 10375		1067889
214	9/8/2016	614335 BODY SHOP SUPPLIES		1067889
214	9/8/2016	614335 PAINT SUPPLIES		1067889
214	9/7/2016	614335 Accident damage - O/S - Acc # DAN 42796. *INTERNAL	Continued Mask up the bus painted nsr wheel arch panel and os low	1067889
214	9/7/2016	614335 Accident damage - O/S - Acc # DAN 42796. *INTERNAL	prep work to rear maskup	1067889
214	9/7/2016	614335 2MM X 1200MM X 2400MM FLAT ALUMINIUM		1067889
214	9/1/2016	611989 DIRECT PURCHASE - VANDALISM	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE175619	1069439
214	8/30/2016	612929 Consumables		1066570
214	8/30/2016	612929 Please remove old poster and fit new Legacy poster	Replaced Poster	1066570
214	8/25/2016	611989 Vandalism Vandalism/ Graffiti Interior - replace glass fi		1065966
214	8/12/2016	609693 Consumables		1064082
214	8/12/2016	609693 Consumables		1064082
214	8/12/2016	609693 Consumables		1064082
214	8/12/2016	609693 Consumables		1064082
214	8/12/2016	609693	CARRY OUT A SERVICE AS PER CHECK LIST	1063963
214	8/11/2016	609314 Mechanic entered - Elec and Light Reverse Buzzer	Secured the wires and tested.Works OK.	1063517
214	8/6/2016	608451 Consumables		1062883
214	8/6/2016	608451 PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 PO v		1062682
214	8/3/2016	607947 Elec and Light/ relay		1062257
214	8/1/2016	599853 SINGLE SEAT BACK REST	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERV	1065768
214	8/1/2016	599853 SINGLE SEAT BASE	Creditor #:PT-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERV	1065768
214	7/27/2016	605731 Drv entered - Heat & Demist		1061335
214	7/27/2016	606318 Drv entered - Heat & Demist	Replaced the demister fan motor and all vent collers and topped up	1061335
214	7/27/2016	606312 PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVEN`	completed	1061335
214	7/25/2016	605731 Drv entered - Heat & Demist	replaced fan motor	1060937
214	7/23/2016	605596	VEHICLE SAFETY INSPECTION Completed saftey inspection.	1060331
214	7/23/2016	605596	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1060331
214	7/18/2016	604622 Consumables		1059678
214	7/18/2016	604622 Consumables		1059678
214	7/18/2016	604622 DECAL FIRE EXTINGUISHER DOWN ARROW		1059474
214	7/18/2016	604622 Mechanic entered - Body Other FIRE EXTINGUISHER DECALS CAMPA		1059474
214	7/14/2016	604092 Drv entered - A/C Heating Not Heating	completed on 11/7/2016	1058749

214	7/14/2016	604092	Drv entered - A/C Heating Not Heating		1058749
214	7/14/2016	604037	Consumables		1058949
214	7/14/2016	604037	Consumables		1058949
214	7/14/2016	604037	TRIANGLE SAFETY DOUBLE SIDED 3 BOX		1058749
214	7/14/2016	604037	Mechanic entered - Body Other missing safety triangle	replaced missing safety triangle	1058749
214	7/11/2016	599853	fit window film	Creditor #:PT-GLA010 GLASSPROTECH MELBOURNE P/O #:PE171622	1058148
214	7/11/2016	603021	Ops Entered - Fault - A/C Heating Not Heating - Route	Check over heater valves at back of bus all ok. check operation of h	1058148
214	7/6/2016	601758	DIRECT PURCHASE - BUS INSPECTI	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE171816 R	1059893
214	7/5/2016	601758		ANNUAL SAFETY INSPECTION SERIAL #	1056846
214	7/4/2016	601474	Consumables		1056846
214	7/4/2016	601474	Consumables		1056846
214	7/4/2016	601474	paint wheel chair ramp and fit non slip sand- ref; vernon		1056846
214	7/4/2016	601474	DECAL EMER EXIT P/B UNDER BUMPER		1056846
214	7/1/2016	605731	EVAPORATOR FAN MOTOR	Creditor #:PT-COO020 COOLDRIVE DISTRIBUTION P/O #:PE173177 Re	1061857
214	6/29/2016	599853	DIRECT PURCHASE - VANDALISM	Creditor #:PT-GLA001 GLASS ASSIST PTY LTD P/O #:PE171243 Receivi	1056846
214	6/29/2016	600737	Vandalism Vandalism/ Graffiti Interior/ window film	completed	1056846
214	6/29/2016	600690	A/C Heating demister not working	double fault recorded	1056846
214	6/29/2016	600718	SINGLE SEAT BASE		1056846
214	6/29/2016	600718	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		1056846
214	6/29/2016	600718	carry out RSI repairs	Replace various air fittings at rear of bus. Replace o/s wiper insert. R	1056846
214	6/29/2016	600718	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		1056846
214	6/29/2016	600718	MIRROR HEAD		1056846
214	6/28/2016	600537	Steam clean for RSI	steamed cleaned for rsi	1056846
214	6/25/2016	599853	DIRECT PURCHASE - VANDALISM	Creditor #:PT-FIA001 FIRST IMPRESSIONS AUTO P/O #:PE171175 Rec	1056846
214	6/24/2016	599853	Vandalism / seats / grafitti / side glass		1056846
214	6/23/2016	599698	Consumables		1056846
214	6/23/2016	599698	Consumables		1056846
214	6/23/2016	599698	AIR BAG FRONT & REAR 0405 / 0500 REAR / B10M / B7R REAR		1056846
214	6/23/2016	599698		O/S/F Mudflap replaced.	1056846
214	6/23/2016	599698	RSI repairs	O/S/RF Air bag replaced.	1056846
214	6/23/2016	599698		4X seat bases and 4Xseat backs replaced.	1056846
214	6/23/2016	599698		Rear yellow floor strip replaced.	1056846
214	6/22/2016	599327	Consumables		1056846
214	6/22/2016	599327	GLOBE 24V 18W		1056823
214	6/22/2016	599327	Mechanic entered - Elec and Light Indicators Not Wor	Replace globe	1056823
214	6/20/2016	599060	Ops Entered - Fault - Wipers and Washers Wipers Loo	adjusted and tightend wiper arms on spindles and replaced o/s wipe	1056079
214	6/20/2016	598700	Drv entered - Cool & AC Sys	Run to temp and check heat/cooling and demister operation. Found	1056079
214	6/20/2016	599066	LAMP LED SIDE MARKER PEREI RED/AMBER (LLX30131)		1056079
214	6/20/2016	599066	Mechanic entered - Accident - OFF SIDE REAR	replaced o/s rear marker led light	1056079
214	6/17/2016	598567	Consumables		1056079
214	6/17/2016	598567	Consumables		1056079
214	6/17/2016	598567	Please remove any old poster and fit new A3 poster and add		1055881
214	6/16/2016	598249	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	1055672
214	6/14/2016	597269	Drv entered - Heat & Demist	tested demisters found to be brushless motor which takes 10 second	1055204
214	6/9/2016	596384	Suspension/ front/rear shocks /steering wheel	replaced front of rear shocks and replaced steering wheel	1054445
214	6/9/2016	596211	carry out fire insp	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE16978	1056846
214	6/8/2016	596384	STEERING WHEEL 0500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE169875 Receiving	1056846
214	6/8/2016	596384	REAR SHOCKER 0500LE	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE169875 Receiving	1056846
214	6/8/2016	596384	Suspension/ front/rear shocks /steering wheel		1054238
214	6/7/2016	596140		PRE ANNUAL SAFETY INSPECTION CHECK Checked and listed all defec	1054132
214	6/7/2016	596141	Consumables		1054238
214	6/7/2016	596141	Elec and Light drivers out	replaced.	1054132
214	6/7/2016	596211		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Completed.	1054132
214	6/3/2016	595334	Consumables		1053913
214	6/3/2016	595334	Drv entered - Heat & Demist	all good demister motor has 10sec delay please inform drivers of thi	1053348
214	6/3/2016	595549	-Replace Drivers Camera with a 2.1mm Thoreb unit-Pi ben were		1053348
214	6/2/2016	595336	Consumables		1053553
214	6/2/2016	595244	Consumables		1053553
214	6/2/2016	595336	Ops Entered - Fault - Desto Signs - Route: 781 - Frank: checked all good		1053348
214	6/2/2016	595244	Ops Entered - Fault - Dash Speedo Not Working - Rou	Checked all speedo wiring and connectors road tested could not fau	1053348
214	6/1/2016	595211	Consumables		1053348
214	6/1/2016	595211	Ops Entered - Fault - Desto Signs - Route: - R Seaview	Tested unable to fault desto system.	1053099
214	6/1/2016	595549	DIRECT PURCHASE - ELECTRICAL	Creditor #:PT-BWE001 BWERE ELECTRICS PTY LTD P/O #:PE171060 Re	1056846
214	6/1/2016	595549	DIRECT PURCHASE - ELECTRICAL	Creditor #:PT-THO005 THOREB AUSTRALIA PTY LTD P/O #:PE168281 I	1056846
214	6/1/2016	595156	Consumables		1053348
214	6/1/2016	595156	Consumables		1053348
214	6/1/2016	595156	PERFORM CAMPAIGN 04/16 DRIVERS WALLETS AND	fit drivers wallet	1053099
214	5/30/2016	594555	Consumables		1053099

214	5/30/2016	594555	Wheels and Tyres o/s/r worn	4-5mm all good	1052941
214	5/27/2016	594095	Consumables		1052396
214	5/27/2016	594095	pass grab handles	Replace missing grab handle	1051562
214	5/26/2016	593821	Ops Entered - Fault - Air System Air Not Building_Up -	No Fault found	1051562
214	5/20/2016	592896		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1050591
214	5/20/2016	592896		VEHICLE SAFETY INSPECTION	1050591
214	5/20/2016	592895	Drv entered - Heat & Demist		1050591
214	5/20/2016	592895	MUFFLER MOUNT 0500LE 50T0010		1050591
214	5/20/2016	592895	Mechanic entered - Engine Noisy or Rattling one muff	replaced one muffler mount	1050591
214	5/20/2016	592881	Consumables		1050754
214	5/20/2016	592881	replace windscreen	Creditor #:PT-GLA001 GLASS ASSIST PTY LTD P/O #:PE168574 Receivi	1051130
214	5/20/2016	592881	Ops Entered - Fault - Body Windows Front - Route: 778 - Fr		1050591
214	5/20/2016	592881	windscreen cracked	done by glassassist	1050591
214	5/19/2016	592521	GLOBE H1 24V 70W		1050174
214	5/19/2016	592521	Mechanic entered - Elec and Light Exterior Lights	O/S head light globe replaced.	1050174
214	5/17/2016	590986	Consumables		1050174
214	5/17/2016	590986	Retrimmed Base Assy 6008		1049975
214	5/12/2016	590531	INTAKE SUCTION PIPE 0500LE 50N	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE167853-1 Receivin	1050414
214	5/12/2016	591178	Consumables		1049582
214	5/12/2016	591178	Mechanic entered - Body Passenger Seat Torn missing	fitted seat back to seat that was missing one. cant send old one awa	1048798
214	5/12/2016	591178	SINGLE SEAT BACK REST		1048798
214	5/11/2016	590986	Retrimmed Base Assy 6008		1048798
214	5/11/2016	590986	Mechanic entered - Body Drivers Seat Controls	secure bus panels replace drivers seat cushion adjust drivers door ar	1048798
214	5/11/2016	590995	springs	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:PE167853	1049142
214	5/11/2016	590995	AIRBAG FRONT AND REAR 0405/0500REAR/ B10M/B7R REAR		1048798
214	5/11/2016	590995	Air System rear air bags leaking	O/S/R/R airbag rplaced and tested.	1048798
214	5/11/2016	590998	CYCLONE CONDENSER VALVE KIT		1048798
214	5/11/2016	590998	HALDEX CONDENSER KIT TOP(CYCLONE)		1048798
214	5/11/2016	590998	KIT AIR LINE FITTING VOSS 22MM 50Z0114		1048798
214	5/11/2016	590998	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		1048798
214	5/11/2016	590998		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST Completed.	1048798
214	5/11/2016	590998			1048798
214	5/11/2016	590997	Consumables		1049142
214	5/11/2016	590997	Consumables		1049142
214	5/11/2016	590997	Consumables		1049142
214	5/11/2016	590997	RAD CAP MERC BENZ SIGHT GLASS SIDE 50N0701 A0005014615		1048798
214	5/11/2016	590997		CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1048798
214	5/9/2016	590531	Breakdown#:32535 - Ops Entered - Breakdown - Brea	Travel to Golfinks rd. Trace to cracked cast pipe to water pump. Ret	1048601
214	5/5/2016	531285	FAN DRIVE OIL 0500LE		1048089
214	5/1/2016	588739	make up hose APS	Creditor #:PT-ENZED ENZED DANDENONG P/O #:PE166965 Receiving	1049142
214	4/28/2016	588739	Mechanic entered - Air System Air_Leak Rear	Locate air leak at air-charge flexi line to air drier remove flex line fro	1046695
214	4/14/2016	585210	Consumables		1044286
214	4/14/2016	585210	TYRE RECAP 11R22.5R		1044080
214	4/14/2016	585210	Ops Entered - Fault - Wheels and Tyres Worn - Route	Pos 3 tyre replaced and torqued to 600 NM.	1044080
214	4/8/2016	585210	Ops Entered - Fault - Wheels and Tyres Worn - Route: 770 -		1042525
214	4/8/2016	584834	temp sender	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE165547CR Receivi	1044080
214	4/7/2016	584834	temp sender	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE165547 Receiving	1044286
214	4/7/2016	584834	Low Water Probe	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:PE165686 Receiving	1044080
214	4/6/2016	584789	Consumables		1042525
214	4/6/2016	584789	Ops Entered - Fault - Wheels and Tyres Worn - Route	tyre is 2.7mm to 5mm	1041907
214	4/6/2016	584834	Fluid Leaks LOW COOLANT LIGHT ON	replaced censor	1041907
214	3/30/2016	583654	GLOBE H1 24V 70W HLC2470		1040578
214	3/30/2016	583654		VEHICLE SAFETY INSPECTION	1040578
214	3/30/2016	583654		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1040578
214	3/23/2016	582503	Consumables		1038951
214	3/23/2016	582503	Consumables		1038951
214	3/23/2016	582503	152 FAN HUB BEARING	Creditor #:PT-FRANBA FRANKSTON BEARINGS (AUST) P P/O #:PE164€	1038951
214	3/22/2016	582503	SINGLE SEAT BASE		1038422
214	3/22/2016	582503	Ops Entered - Fault - Body Passenger Seat Torn - Rou	FIT NEW SEAT BASE CUSHION	1038422
214	3/16/2016	581548	Decal Emergency Exit P/B under Panel		1036763
214	3/16/2016	581548	Accident - NEAR SIDE MID # 42669	replaced panel and door rubber	1036763
214	3/9/2016	580494	Consumables		1036125
214	3/9/2016	580494	Consumables		1036125
214	3/9/2016	580494	The Campaign requires all Bus destinations systems to be in		1035729
214	3/3/2016	577798	n/s battery panel complete wit	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE162924 Receivi	1034731
214	3/3/2016	577798	rear door aperture rubber	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE162924 Receivi	1034731
214	3/2/2016	577798	Ops Entered - Accident - Bus Hit Stationary Object - Route		1034391
214	3/1/2016	578492	(1) incooler leaking (2) steering box leak		1034391

214	3/1/2016	578492 (1) incooler leaking (2) steering box leak		1034391
214	3/1/2016	578910 0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		1034391
214	3/1/2016	578910 Air System leaking rear suspension		1034391
214	3/1/2016	578911 Consumables		1034434
214	3/1/2016	578911 Consumables		1034434
214	3/1/2016	578911	CARRY OUT B SERVICE AS PER CHECK LIST	1034391
214	3/1/2016	578911 AIR FILTER MERC 0500LE E491L		1034391
214	3/1/2016	574595 carry out service	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE161801 Receiving	1036125
214	3/1/2016	578911 Consumables		1034434
214	3/1/2016	578911 Consumables		1034434
214	3/1/2016	578911	CARRY OUT A SERVICE AS PER CHECK LIST	1034391
214	2/24/2016	577798 Ops Entered - Accident - Bus Hit Stationary Object - R Travel to Overport rd. Found n/s battery panel n/s badly damaged. F		1034391
214	2/22/2016	577431 Consumables		1034182
214	2/22/2016	577431 Consumables		1034182
214	2/22/2016	577431 Camapign 20/15 Audit & Update of Safety Decals.Requires a		1033985
214	2/8/2016	574595	CARRY OUT A/C - A SERVICE AS PER CHECK LIST	1031537
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/30/2016	573247 Drv entered - Heat & Demist	no fault found--delayed fan motor	1029892
214	1/30/2016	573247 Drv entered - Heat & Demist		1029892
214	1/28/2016	572845	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1029545
214	1/28/2016	572845	VEHICLE SAFETY INSPECTION Completed.	1029545
214	1/16/2016	570528 Consumables		1026740
214	1/16/2016	570528 PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS		1026327
214	12/30/2015	567363 Consumables		1022588
214	12/30/2015	567363 Consumables		1022588
214	12/30/2015	567363 Consumables		1022588
214	12/30/2015	567363	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1021911
214	12/23/2015	566683 Consumables		1021473
214	12/23/2015	566683 Campaign 23_15 A3 Poster Change	fit A3 poster as required	1021159
214	12/18/2015	565595	Retensioned pos 3 and 4 wheel nuts to 600 NM.	1020026
214	12/18/2015	565612 Mechanic entered - Air System Air_Leak Rear	Checked for air leak fixed air leak with connector at auxilary air tank	1020026
214	12/16/2015	565235	VEHICLE SAFETY INSPECTION	1019865
214	12/16/2015	565235	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1019865
214	12/16/2015	565260 Consumables		1020026
214	12/16/2015	565260 TYRE RECAP 11R22.5R		1019865
214	12/16/2015	565260 Mechanic entered - Wheels and Tyres Worn pos 4 tyr replaced pos 4 tyre		1019865
214	12/16/2015	565241 Consumables		1020026
214	12/16/2015	565241 Drv entered - Body Drivers Seat Leaning		1019865
214	12/16/2015	565242 DISC PAD SET SCANIA MB0500		1019865
214	12/16/2015	565242 Mechanic entered - Brakes Warning Light On front an replaced front and rear brake pads		1019865
214	12/14/2015	564712 Consumables		1019693
214	12/14/2015	564712 as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hc Campaign completed as required		1019339
214	12/1/2015	556087 TORQUE ROD BUSH	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15;	1009557
214	12/1/2015	561486 REPAIR CCTV	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE15862	1017930
214	11/26/2015	561486 CCTV Warning Light/ N/W	comp0leted by lonsdale	1015125
214	11/26/2015	561225 Consumables		1015200
214	11/26/2015	561225 Remove Old Poster and Fit new All Night Public Transport Po		1015125
214	11/18/2015	559481 Consumables		1014328
214	11/18/2015	559481 Complete task as instructed in Fleet Campaign 09/15		1014130
214	11/9/2015	552626 Consumables		1011879
214	11/9/2015	552626 DIRECT PURCHASE - BUS INSPECTION		1011643
214	11/2/2015	556665 Mechanic entered - Wipers and Washers Wipers Loos	Remove and weld loose wiper crank arm. Refit and adjust o/s linkag	1009557
214	10/29/2015	556087 REAR AXLE TORQUE ROD BUSHES WORN	Remove rear bottom torque rod's both sides. take it to dandenong r	1009235
214	10/29/2015	556087 REAR AXLE TORQUE ROD BUSHES WORN		1009235
214	10/28/2015	555949	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	1009120
214	10/28/2015	555949	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	1009120
214	10/28/2015	555949	CLEAN A/C FILTERS	1009120
214	10/28/2015	555949	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1009120
214	10/28/2015	555949	VEHICLE SAFETY INSPECTION	1009120
214	10/20/2015	554297 Consumables		1007083
214	10/20/2015	554297 Campaign 11/15. Fit 2 x Supplied Decals to Internal S fit decals as required by campaign instructions		1006943

214	10/20/2015	554309 Consumables		1007083
214	10/20/2015	554309 Consumables		1007083
214	10/20/2015	554309 Consumables		1007083
214	10/20/2015	554309		1006943
214	10/20/2015	554309	CARRY OUT A SERVICE AS PER CHECK LIST Completed.	1006943
214	10/16/2015	553355 BOSCH REGULATOR 0500LE ALT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15	1006596
214	10/15/2015	553355 REGULATOR VOLTAGE 0405NH 94V0003 VR3014G		1005813
214	10/15/2015	553355 Mechanic entered - Gearbox Driveline Other	Fit half shaft to ns rear hub. Check Alternator found alternator not c	1005813
214	10/14/2015	553355 tow in	Creditor #:PT-EAG001 EAGLE TOWING AND SALVAGE P/O #:PE15749	1009557
214	10/12/2015	552626 INDICATOR LAMP (85930)		1005235
214	10/12/2015	552626 Mechanic entered - Elec and Light Exterior Lights NSF	Bring bus into workshop no correct indicator assembly in stock. fit si	1005235
214	10/8/2015	552072	CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST air service comp	1004090
214	9/30/2015	550220 Consumables		1001822
214	9/30/2015	550220 Replace A3 poster with Victorian Seniors Festival Post	Replaced A3 Poster as required	1001631
214	9/28/2015	549392 Ops Entered - Fault - Steering Pulling - Route: 833 - Fr	Check steering/suspension and brakes. Road test no fault found	1000857
214	9/23/2015	548378 Ops Entered - Fault - A/C Heating Not Heating - Route	Road tested bus to warm up motor checked with infrared gun. Foun	999056
214	9/22/2015	548151	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	999056
214	9/22/2015	548151	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	999056
214	9/22/2015	548151	CLEAN A/C FILTERS	999056
214	9/22/2015	548151	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	999056
214	9/22/2015	548151	VEHICLE SAFETY INSPECTION Completed saftey inspection	999056
214	9/21/2015	547918 Consumables		999056
214	9/21/2015	547918 non slip strips off on floor	replace skid strip in back	998781
214	9/21/2015	547918 non slip strips off on floor	Cut out and fit new non-slip strip on rear section of floor.	998781
214	9/15/2015	547026 Drv entered - Heat & Demist	no fault found	997369
214	9/4/2015	545299 Ops Entered - Fault - A/C Heating Noisy - Filter Blocke	checked and no fault found	994513
214	9/2/2015	544658 Mechanic entered - Gearbox Driveline Other reverse l	locate bus check over connections on reverse beeper. no faults foun	993685
214	8/25/2015	543306 repair damage 3 41567 / 41613	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15	993685
214	8/25/2015	543306 DIRECT PURCHASE ACCIDENT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15	993685
214	8/25/2015	543306 Accident / # 41567 / 41613	repaired by ECTB	992132
214	8/13/2015	540950 Ops Entered - Accident - Bus Hit Stationary Object - R	done by ECTB	991580
214	8/13/2015	540950 Ops Entered - Accident - Bus Hit Stationary Object - Route		991580
214	8/13/2015	540950 Ops Entered - Accident - Sundry - Route: - DISPLAY: 7711-		991580
214	8/11/2015	540332 Ops Entered - Fault - Heat & Demist - Route: 782 - Fr	completed	991580
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Mechanic entered - Body Drivers Seat Controls	tighten back on drivers seat tighten all body panels and b/bars	991580
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333	CARRY OUT C SERVICE AS PER CHECK LIST	991580
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333	CARRY OUT B SERVICE AS PER CHECK LIST	991580
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333 Consumables		991903
214	8/11/2015	540333	CARRY OUT A SERVICE AS PER CHECK LIST	991580
214	8/10/2015	540075	CARRY OUT VALVE ADJUSTMENT TURBO CHECK & INTERCOOLER/RAI	991580
214	8/10/2015	540075 ROCKER COVER GASKET 0500LE		991580
214	8/1/2015	538756 Demister NOT WORKING at all	has 10 sec delay	990061
214	8/1/2015	538762 0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		990061
214	8/1/2015	538762 Air System 2xrear air bags	replaced 2	990061
214	7/31/2015	538490 1MT MULTI FIT WIPER REFILL		990061
214	7/31/2015	538490 Ops Entered - Fault - Wipers and Washers Wipers Loo	O/S wiper refill replaced.	990061
214	7/31/2015	538714 FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		990061
214	7/31/2015	538714 PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		990061
214	7/31/2015	538714 Mechanic entered - Air System Air Not Building_Up	rekitted air dryer	990061
214	7/30/2015	538425 Ops Entered - Fault - A/C Heating Not Heating - Route	no fault found	989791
214	7/30/2015	538456 Ops Entered - Fault - Elec and Light Warning Light On	reset air dryer	989791
214	7/29/2015	538183 Complete Campaign 6/15 A3 Marketing Poster Chang	Completed campaign as required	989493
214	7/27/2015	537654 Gearbox Driveline/replace drive shaft and air dryer	fitted drive shaft and air dryer	988695
214	7/27/2015	537147 Mechanic entered - Body Front_Door Operation Fault	repace drivers door lock and fit new hinges	988695
214	7/24/2015	537147 OVERHAUL DRIVE SHAFT	Creditor #:PT-GJD001 GJ DRIVELINE P/O #:PE154018 Receiving #:159	990366
214	7/24/2015	537147 Mechanic entered - Body Front_Door Operation Fault	replace drivers door catch	988695
214	7/23/2015	537038	VEHICLE SAFETY INSPECTION Carry out safety inspection as per check	988695
214	7/23/2015	537038	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	988695
214	7/23/2015	537038	CLEAN A/C FILTERS	988695

214	7/23/2015	537038	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	988695
214	7/23/2015	537038	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	988695
214	7/23/2015	537147	Mechanic entered - Gearbox Driveline Vibration Driveshaft n	988695
214	7/23/2015	537038	Mechanic entered - Body Other secure rear buper bar secure outside panels adjust and tighten drive	988695
214	7/23/2015	537038	KIT AIR LINE FITTING VOSS 22MM 50Z0114	988695
214	7/23/2015	537038	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115	988695
214	7/23/2015	537038	Mechanic entered - Air System Air_Leak Rear air leak Replace 6 way protection valve. replace all o ring kits in connections	988695
214	7/23/2015	537038	CIRCUIT PROTECTION VALVE	988695
214	7/22/2015	536948	Ops Entered - Fault - A/C Heating Not Heating - Route: NO FAULT FOUND	988695
214	7/22/2015	536745	Drv entered - AC Heating Not Heating does work waiting time 5sec	988695
214	7/17/2015	536294	Ops Entered - Fault - Steering Shakes/ Wobbles - Rou test drove and no fault found	988052
214	7/16/2015	535263	BLADE WIPER 1MTR Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	988052
214	7/15/2015	535842	Ops Entered - Fault - A/C Heating Not Heating - Route: 833	987789
214	7/15/2015	535842	Drv entered - Heat & Demist replaced fan motor	987789
214	7/15/2015	535843	Consumables	987818
214	7/15/2015	535843	Consumables	987818
214	7/15/2015	535843	Consumables	987818
214	7/15/2015	535843	CARRY OUT A SERVICE AS PER CHECK LIST	987789
214	7/14/2015	535521	BLOWER ASSY DOUBLE SPAL Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	987789
214	7/14/2015	535521	Ops Entered - Fault - Heat & Demist - Route: 832 - Frz replaced motor	987692
214	7/13/2015	535263	Mechanic entered - Wipers and Washers Wipers Not_	987435
214	7/6/2015	533994	DIRECT PURCHASE - BUS INSPECTI Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE153259 R	990366
214	7/6/2015	534282	GLOBE WEDGE INSTRUMENT 24V 5W	986044
214	7/6/2015	534282	Mechanic entered - Elec and Light Exterior Lights n.s.f Open NSF light panel replace wedge globe. test and close panel. Rer	986044
214	7/6/2015	534282	GLOBE 24V 5W BAYONETT	986044
214	7/3/2015	533994	ANNUAL SAFETY INSPECTION (RWC #)	985275
214	7/1/2015	533631	RSI final Completed and finalised.Greasing to be done after Fr axel steam cle	985255
214	6/25/2015	531732	Consumables	984175
214	6/25/2015	531732	LAMP INTERIOR AND REVERSING	984175
214	6/25/2015	531732	LAMP INTERIOR AND REVERSING	984175
214	6/25/2015	531732	CLEAR FRONT INDICATOR WRAP-AROUND	984175
214	6/25/2015	531732	SAGE OVERCENTRE LATCH Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	984175
214	6/25/2015	531732	(1) REAR SEAT CLAMPS (2) high beam lamp (3) engine FIT NEW HEADLIGHT O/S FRONT FIT NEW O/S FRONT INDICATOR REI	984175
214	6/24/2015	532641	steam clean for RSI steam cleaned.	983916
214	6/24/2015	532441	Consumables	984175
214	6/24/2015	532441	GLOBE H1 24V 70W	983916
214	6/24/2015	532441	Mechanic entered - Elec and Light Exterior Lights N/S Replaced.	983916
214	6/22/2015	531732	(1) REAR SEAT CLAMPS (2) high beam lamp (3) engine hatch st	982294
214	6/19/2015	531732	SAGE OVERCENTRE LATCH Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	983093
214	6/19/2015	531732	GAS STRUT 430NM X 450MM Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	983093
214	6/19/2015	531732	HEADLAMP UNIT Volgren Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE15:	983093
214	6/17/2015	531285	Inspect radiator and charge air cooler for dirt - clean	982294
214	6/17/2015	531285	tighten side panels secure rear b/bar glue lino back to front w/arch :	982294
214	6/17/2015	531285	FUEL FILTER MERC 0500LE	982294
214	6/17/2015	531285	FUEL FILTER 0500LE	982294
214	6/17/2015	531285	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)	982294
214	6/17/2015	531285	FILTER P/STEER SCANIA VOLVO M/BENZ 0153468-1585618-0-153468	982294
214	6/17/2015	531285	FAN DRIVE OIL 0500LE	982294
214	6/17/2015	531285	Overhaul air seperator	982294
214	6/17/2015	531285	Electrical - Batteries - Check fluid level (leave air gap when topping u	982294
214	6/17/2015	531285	Check oil level in transmission - top up if required	982294
214	6/17/2015	531285	Check and clean cartridge in dry type air cleaner	982294
214	6/17/2015	531285	Replace pre and main fuel filters	982294
214	6/17/2015	531285	Replace air dryer cansiter clean silence and drain reservoir	982294
214	6/17/2015	531285	Replace angle drive oil	982294
214	6/17/2015	531285	Test coolant level - top up if required to equate to 37C frost protect	982294
214	6/17/2015	531285	Replace power steering filter and check level (Replace oil if required)	982294
214	6/17/2015	531285	PRE ANNUAL SAFETY INSPECTION CHECK Completed checks and reco	982294
214	6/5/2015	529726	ROTATE REAR AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	978869
214	6/5/2015	529726	ROTATE FRONT AXLE TYRES LEFT TO RIGHT MT & IBS ONLY	978869
214	6/5/2015	529726	CLEAN A/C FILTERS	978869
214	6/5/2015	529726	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	978869
214	6/5/2015	529726	VEHICLE SAFETY INSPECTION	978869
214	6/5/2015	529739	Consumables	979002
214	6/5/2015	529803	Consumables	979002
214	6/5/2015	529803	LED FRONT POSITION MARKER LIGHT	978869
214	6/5/2015	529803	GLOBE 24V 18W	978869
214	6/5/2015	529803	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)	978869

214	6/5/2015	529803 Elec and Light Interior Lights		978869
214	6/5/2015	529739 LED FRONT POSITION MARKER LIGHT		978869
214	6/5/2015	529739 Replace 2x front exit led lamps	Completed	978869
214	6/5/2015	529739 Drv entered - Elec and Light Exterior LightsHeadlights	Check and adjust headlights	978869
214	6/1/2015	528582 carry out fire safety inspecti	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:PE15200	979941
214	5/29/2015	528627 Consumables		978097
214	5/29/2015	528627 Audit Route buses for correct Decals and positions. Re	decal audit completed	978038
214	5/29/2015	528582	FIRE SAFETY INSPECTION AS PER CHECK LIST - lonsdale	978038
214	5/20/2015	527177	retensioned nuts.	974786
214	5/19/2015	526882 Elec and Light INDICATOR N/W		974348
214	5/18/2015	526701	retensioned nuts.	974143
214	5/18/2015	526700 Consumables		974348
214	5/18/2015	526700 TYRE RECAP 11R22.5R		974143
214	5/18/2015	526700 Wheels and Tyres replace position # 3 side wall dama	replaced tyre #3.	974143
214	5/15/2015	526417 Consumables		973735
214	5/15/2015	526417 TYRE RECAP 11R22.5R		973495
214	5/15/2015	526417 Mechanic entered - Wheels and Tyres Worn	Replace o/s/r tyres	973495
214	5/15/2015	526416 Ops Entered - Fault - Elec and Light Exterior Lights - H	adjusted headlights	973495
214	5/15/2015	526417 Consumables		973735
214	5/15/2015	526417 Consumables		973735
214	5/15/2015	526417 Consumables		973735
214	5/15/2015	526417 Consumables		973735
214	5/15/2015	526417	A Service	973495
214	5/15/2015	526417	Clean A/C filter	973495
214	5/15/2015	526417	Grease AC Compressor Clutch Bearing	973495
214	5/15/2015	526417	Tension Wheel Nuts To OEM Specification	973495
214	4/30/2015	523964 Drv entered - AC Heating Not Heating		969498
214	4/30/2015	523964 Drv entered - Comm Equip		969498
214	4/30/2015	523963 FILTER TRANSMISSION ZF (4139-298-038)(4139 298 C ZF Transmission Filter		969498
214	4/30/2015	523963 ZF SYNTHETIC GEARBOX OIL ECOFLUID A PLUS PER LTI ZF Ecofluid A Plus Synthetic Transmission Oil		969498
214	4/30/2015	523963	REPLACE TRANSMISSION OIL & FILTER	969498
214	4/27/2015	523206	Clean A/C filter.	968618
214	4/27/2015	523206	Rotate Rear Axle Tyres Left to Right - MT & IBS only	968618
214	4/27/2015	523206	Rotate Front Axle Tyres Left to Right - MT & IBS only	968618
214	4/27/2015	523206	Tension Wheel Nuts	968618
214	4/27/2015	523206	Perform & Complete TSV Bus Safety Inspection safety completed def	968618
214	4/27/2015	523215 Booster RHR 0500 634.220	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE145	968618
214	4/27/2015	523215 R/H rear brake booster leaking	air leak fixed tightened clamp	968618
214	4/16/2015	521470 retension wheel nuts on position 1 to 670nm	COMPLETED	966337
214	4/14/2015	521186 TYRE NEW 11R22.5N		965996
214	4/14/2015	521186 RH front tyre 3mm	Replace tyre	965996
214	4/14/2015	521037 GLOBE 24V 18W		965996
214	4/14/2015	521037 OSF top park light u/s	r/r lights replace globes	965996
214	4/14/2015	521037 Mechanic entered - Elec and Light Other o/s/f top parklight		965996
214	4/14/2015	521037 GLOBE 24V 5W BAYONETT		965996
214	4/14/2015	521147 Temp repair to unreported damage to n/s	repair n/s panel damage	965996
214	4/10/2015	520513 GLOBE H1 24V 70W		964226
214	4/10/2015	520513 Mechanic entered - Elec and Light Exterior Lights O/S	Replaced globe	964226
214	4/9/2015	520416 Hole in intercooler	servicable	964226
214	4/1/2015	515960 Valve Proportioning Relay Mer	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14;	961924
214	3/30/2015	518754 Replace See Something Say Something Poster	Campaign completed.	960810
214	3/16/2015	516226	Clean A/C filter.	957853
214	3/16/2015	516226	Tension Wheel Nuts	957853
214	3/16/2015	516226	Perform & Complete TSV Bus Safety Inspection	957853
214	3/16/2015	516226	Rotate Rear Axle Tyres Left to Right - MT & IBS only	957853
214	3/16/2015	516226	Rotate Front Axle Tyres Left to Right - MT & IBS only	957853
214	3/16/2015	516238 brake modulator valve leaking	Replace valve and reposition pipes. Check for leaks ok	957853
214	3/16/2015	516227	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air	957853
214	3/16/2015	516227	Re-kit Air Cyclone Separator Completed	957853
214	3/16/2015	516227 AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		957853
214	3/16/2015	516227 CYCLONE CONDENSER VALVE KIT		957853
214	3/13/2015	515960 brake modulator valve leaking	REPLACED VALVE	957853
214	3/13/2015	515942 Consumables		957853
214	3/13/2015	515942 Consumables		957853
214	3/13/2015	515942 Consumables		957853
214	3/13/2015	515942 MINATURE GLOBE 24V - 4 W		957853
214	3/13/2015	515942	Replace Engine Oil Breather Kit	957853
214	3/13/2015	515942 ENGINE OIL BREATHER KIT 0500LE (EAS500M05)		957853

214	3/13/2015	515942		Grease AC Compressor Clutch Bearing	957853
214	3/13/2015	515942	AIR FILTER MERC 0500LE E491L		957853
214	3/13/2015	515942	OIL FILTER 1725+0500LE		957853
214	3/13/2015	515942	OIL ENGINE DELO 400LE 15W40 (LU18)		957853
214	3/13/2015	515942		Tension Wheel Nuts to Spec	957853
214	3/13/2015	515942		A Service & Bus Safety Inspection	957853
214	3/13/2015	515942		D-Service & Bus Safety Inspection	957853
214	3/13/2015	515942	Consumables		957853
214	3/13/2015	515942	Consumables		957853
214	3/13/2015	515942	Consumables		957853
214	3/13/2015	515942		A Service	957853
214	3/13/2015	515942		Clean A/C filter	957853
214	3/13/2015	515942		Grease AC Compressor Clutch Bearing	957853
214	3/13/2015	515942		Tension Wheel Nuts To OEM Specification	957853
214	3/4/2015	514463	Drv entered - Air Cond Air Conditioner	no fault found	954805
214	3/2/2015	514086	Service	incorrectly entered	954253
214	2/24/2015	513042	Ops Entered - Fault - Air Cond Air Conditioner - Route	repaired by coachair	952710
214	2/23/2015	512805	Drv entered - Elec & Light Interior Lights	completed	952414
214	2/20/2015	512301	Update destination Files and Check display	Campaign completed by operations.	951750
214	2/18/2015	512081	Complete AM/FM radio saloon speaker modification	Campaign completed.	951443
214	2/2/2015	509438	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E		947620
214	2/2/2015	509438	LED FRONT POSITION MARKER LIGHT		947620
214	2/2/2015	509438		Perform & Complete TSV Bus Safety Inspection	947620
214	2/2/2015	509438		Clean A/C filter.	947620
214	2/2/2015	509438		Tension Wheel Nuts	947620
214	2/1/2015	500574	THROTTLE PEDAL ASSEMBLY	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14	936833
214	2/1/2015	508395	DIRECT PURCHASE ACCIDENT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14	950936
214	1/27/2015	508395	Ops Entered - Accident - Bus Hit Stationery Vehicle - I	Repaired by Eastcoast	945835
214	1/27/2015	507587	CONSUMABLES	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE147572 Receiving	947621
214	1/27/2015	507587	FILTER MATT 10MM GREY	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE147572 Receiving	947621
214	1/27/2015	507587	DRIER 5/8 ORING 305 FS	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE147572 Receiving	947621
214	1/27/2015	507587	REFRIG OIL SOLEST 68	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE147572 Receiving	947621
214	1/27/2015	507587	LABOUR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE147572 Receiving	947621
214	1/27/2015	508490		B Service	945835
214	1/27/2015	508490		Replace filter drier	945835
214	1/27/2015	508490		Replace compressor oil	945835
214	1/27/2015	508490		SERVICED 20/1/15 W/O 507587	945835
214	1/27/2015	508490		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	945835
214	1/27/2015	508490		COMPRESSOR: Carry out efficiency test; check unloader control; che	945835
214	1/27/2015	508490		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	945835
214	1/27/2015	508490		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pull	945835
214	1/27/2015	508490		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	945835
214	1/27/2015	508490		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	945835
214	1/27/2015	508490		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	945835
214	1/27/2015	508490		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	945835
214	1/27/2015	508490		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	945835
214	1/27/2015	508490		CONDENSOR AREA: Clean condenser coils; check boltsclamps for ten	945835
214	1/27/2015	508490		EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	945835
214	1/20/2015	507520	Mechanic entered - Elec & Light Interior Lights front s	Replaced front step down light	944607
214	1/20/2015	507616	front door light out	completed by anthony	944607
214	1/20/2015	507519	Drv entered - Brakes Noisy	Checked front and rear brake pads rotors and for any audible air lea	944607
214	1/20/2015	507587		C Service	944607
214	1/20/2015	507587		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	944607
214	1/20/2015	507587		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pull	944607
214	1/20/2015	507587		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	944607
214	1/20/2015	507587		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	944607
214	1/20/2015	507587		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	944607
214	1/20/2015	507587		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	944607
214	1/20/2015	507587		CONDENSOR AREA: Clean condenser coils; check boltsclamps for ten	944607
214	1/20/2015	507587		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	944607
214	1/20/2015	507587		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	944607
214	1/20/2015	507587		EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	944607
214	1/20/2015	507587		COMPRESSOR: Carry out efficiency test; check unloader control; che	944607
214	1/19/2015	507562	front door light out		944607
214	1/14/2015	506787	GLOBE H1 24V 70W		943623
214	1/14/2015	506787	Drv entered - Elec & Light Headlights	Replaced N/S headlight globe	943623
214	1/12/2015	506210	Consumables		943196
214	1/12/2015	506210	COMPLETE VEHICLE DETAILS AUDIT CHECK LIST	Completed	943059

214	1/8/2015	505704 Consumables		942811
214	1/8/2015	505704 Mechanic entered - Body & Acc Exterior	adjust and lubricate doors	942811
214	1/8/2015	505680 Ops Entered - Breakdown - Breakdown Change Over f	no fault found	942811
214	1/2/2015	504748 Ops Entered - Fault - Air Cond Clean Return Air Filter i	checked a/c and cleaned filter	940562
214	12/31/2014	504518 Consumables		0
214	12/31/2014	504518 GLOBE 24V 18W		940315
214	12/31/2014	504518 O/F indicator not working	Replaced globe	940315
214	12/30/2014	504304 coolant leaking from header tank hose	pushed hose over damaged pipe and tied-up to stop rubbing.	940303
214	12/30/2014	504304 MINATURE GLOBE 24V - 4 W		940303
214	12/30/2014	504304 coolant leaking from header tank hose		940303
214	12/30/2014	504162 Consumables		0
214	12/30/2014	504162 Consumables		0
214	12/30/2014	504162 Consumables		0
214	12/30/2014	504162	A Service	940303
214	12/30/2014	504162	Clean A/C filter	940303
214	12/30/2014	504162	Grease AC Compressor Clutch Bearing	940303
214	12/30/2014	504162	Tension Wheel Nuts To OEM Specification	940303
214	12/23/2014	503544 steering wheel covering loose	re sealed passenger window fit do not over take turning sticker	938719
214	12/22/2014	503082	saftey inspection completed	938302
214	12/19/2014	503082 CLEAR FRONT INDICATOR WRAP-AROUND		938044
214	12/19/2014	503082 GLOBE WEDGE 24V/5W		938044
214	12/19/2014	503082	Clean A/C filter.	938044
214	12/19/2014	503082	Rotate Rear Axle Tyres Left to Right - MT & IBS only	938044
214	12/19/2014	503082	Rotate Front Axle Tyres Left to Right - MT & IBS only	938044
214	12/19/2014	503082	Perform & Complete TSV Bus Safety Inspection	938044
214	12/19/2014	503082	Tension Wheel Nuts	938044
214	12/17/2014	502626 Drv entered - Other	no fault found	937385
214	12/16/2014	502440 A3 Poster Change	Campaign completed.	937103
214	12/9/2014	501069 Graffiti in bus and all over floor and wheel surrounds	tried graffiti remover thinners some came off alot didn't.	935928
214	12/9/2014	500574 Engine keeps cutting out	replaced acc pedal assembly	935928
214	12/9/2014	501016 SYNTHETIC GEAR LUBRICANT FM 75W-140 (LU27)		935928
214	12/9/2014	501016 Service	Replace Differential oil	935928
214	12/7/2014	500574 Engine keeps cutting out	Was told keeps coming out of gear. Remove clean and check g/box p	935928
214	11/28/2014	499283 front door light out	checked all door lights no fault found	934020
214	11/12/2014	496012 Fit Tyre Valve Extensions To All Inner Rear Axle Whee	Ref managers meeting 05/11/14	933400
214	11/12/2014	496106 Consumables		0
214	11/12/2014	496106 Remove Legacy Poster and replace with See Somethir	Campaign done.	933400
214	10/27/2014	493061	Clean A/C filter.	928881
214	10/27/2014	493061	Tension Wheel Nuts	928881
214	10/27/2014	493061	Perform & Complete TSV Bus Safety Inspection	928881
214	10/21/2014	489985 AIR CONDITIONING REPAIR	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE144671 Receiving	927508
214	10/17/2014	490324 11R new	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE144470 Receivii	926343
214	10/15/2014	491154 1MT MULTI FIT WIPER REFILL		925848
214	10/15/2014	491154 Drv entered - Wipers & Washers Worn	O/S wiper Refil Replaced.	925848
214	10/15/2014	491154 Drv entered - Brakes Noisy	Tested no noise detected.	925848
214	10/9/2014	490324 Retension wheel nuts N/F	Retension to 600 Nm	924803
214	10/9/2014	490325 Preform temp repair to N/R	Temp repair to corner panel and replaced indicator light	924803
214	10/9/2014	490325 INDICATOR LAMP L.E.D.		924803
214	10/8/2014	490127 Tyre Pos 1 low and leaking from nail	Replaced tyre and tension to 600 Nm	924724
214	10/8/2014	489985 Drv entered - Air Cond Cooling Fault Light	complerted by coachair	924724
214	10/8/2014	489985 Drv entered - Air Cond Cooling Fault Light		924724
214	10/8/2014	489985 Drv entered - Air Cond Cooling Fault Light		924724
214	10/8/2014	489985 Drv entered - Air Cond Air Conditioner [See printed defect		924724
214	10/8/2014	490066 Consumables		0
214	10/8/2014	490066	Tension Wheel Nuts To OEM Specification	924724
214	10/8/2014	490066	Grease AC Compressor Clutch Bearing	924724
214	10/8/2014	490066	Clean A/C filter	924724
214	10/8/2014	490066	A Service	924724
214	9/30/2014	487676 PARKBRAKE VALVE 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14:	922898
214	9/29/2014	488175 cut slots in battery panel for opening	cut holes in battery door panel and fit decal	922583
214	9/26/2014	487676 Drv entered - Brakes Hand Brake	replaced handbreak valve	921750
214	9/25/2014	487676 Drv entered - Other	completed	921750
214	9/25/2014	487676 Drv entered - Other	completed	921750
214	9/25/2014	487676 Drv entered - Brakes Hand Brake	completed	921750
214	9/25/2014	487604 replace battery panel	remove n/s panel fit new panel	921750
214	9/24/2014	486284 11R recaps	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE143752 Receivii	921750
214	9/24/2014	486284 FITTING	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE143752 Receivii	921750
214	9/24/2014	486284 DISPOSAL CHARGE	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE143752 Receivii	921750

214	9/24/2014	486284	supply and paint white n/s bat	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:PE143675 Receiv	921750
214	9/18/2014	486381	EMERGENCY EXIT (HAMMER)		919876
214	9/18/2014	486381		Clean A/C filter.	919876
214	9/18/2014	486381		Rotate Rear Axle Tyres Left to Right - MT & IBS only	919876
214	9/18/2014	486381		Rotate Front Axle Tyres Left to Right - MT & IBS only	919876
214	9/18/2014	486381		Tension Wheel Nuts	919876
214	9/18/2014	486381		Perform & Complete TSV Bus Safety Inspection	919876
214	9/18/2014	486284	Mechanic entered - Whls & Tyres Worn Position 3&4	Replace n/s/r tyres and torque to 600nm	919876
214	9/18/2014	486381	SEAL TENSIONER HUB		919876
214	9/18/2014	486381	TAPERED ROLLER BEARING		919876
214	9/18/2014	486381	GLOBE WEDGE 24V 1.2W HLW241.2 (47706 SWFLED E-596WLED)		919876
214	9/18/2014	486381	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		919876
214	9/18/2014	486381	O/H fan drive		919876
214	9/17/2014	486284	Ops Entered - Accident - Bus Hit Stationary Object - Route		919876
214	9/11/2014	485358	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		917863
214	9/11/2014	485358	air leaks	completed	917863
214	9/11/2014	485318		Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air	917863
214	9/11/2014	485318	HALDEX COIL KIT 0500LE 49G0027HALDEX	Coil Kit	917863
214	9/11/2014	485318		Re-kit Air Cyclone Separator	917863
214	9/9/2014	484824	Drv entered - Other	as above	917351
214	9/9/2014	484868	Drv entered - Desto Signs	tested signs and no fault found	917351
214	9/9/2014	484824	Brakes noisy and handbrake not holding	Checked and found holding OK but has a little brake squeal Ok	917351
214	9/9/2014	484824	Drv entered - Brakes Hand Brake	as above	917351
214	9/9/2014	484824	Ops Entered - Fault - Brakes Hand Brake - Route: - Ar as above		917351
214	9/9/2014	484824	Drv entered - Brakes Other	tested bus and no fault found	917351
214	9/5/2014	484296	Remove old decal and fit new Authorised Officers Decal	Decal fitted.	916375
214	8/29/2014	479103	LEVELLING VALVE SENSOR	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14:	914775
214	8/22/2014	481382	Remove old A3 poster & replace with Legacy or Penal Campaign	done.	912217
214	8/14/2014	479987		Clean A/C filter.	911023
214	8/14/2014	479987		Rotate Rear Axle Tyres Left to Right - MT & IBS only	911023
214	8/14/2014	479987		Rotate Front Axle Tyres Left to Right - MT & IBS only	911023
214	8/14/2014	479987		Tension Wheel Nuts	911023
214	8/14/2014	479987		Perform & Complete TSV Bus Safety Inspection	911023
214	8/14/2014	476130	N200 BATTERY-MAINTANENCE FREE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14:	911054
214	8/14/2014	478358	LAMP INTERIOR AND REVERSING	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14:	911054
214	8/9/2014	479103	rear leveling valve sensors worn	re[placed both rear level valve sensors	910040
214	8/8/2014	478461	FITTING	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE142090 Receivi	910811
214	8/8/2014	478461	PUNCTURE	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE142090 Receivi	910811
214	8/8/2014	479031	GLOBE 24V 5W BAYONETT		910040
214	8/8/2014	479031	MINATURE GLOBE 24V - 4 W		910040
214	8/8/2014	479031		Replace Engine Oil Breather Kit	910040
214	8/8/2014	479031		Grease AC Compressor Clutch Bearing	910040
214	8/8/2014	479031	AIR FILTER MERC 0500LE E491L		910040
214	8/8/2014	479031	OIL FILTER 1725+0500LE		910040
214	8/8/2014	479031	ENGINE OIL DELO 400LE 15W40 (LU18)		910040
214	8/8/2014	479031		Tension Wheel Nuts to Spec	910040
214	8/8/2014	479031		A Service & Bus Safety Inspection	910040
214	8/8/2014	479031		D-Service & Bus Safety Inspection	910040
214	8/8/2014	479031		A Service	910040
214	8/8/2014	479031		Clean A/C filter	910040
214	8/8/2014	479031		Grease AC Compressor Clutch Bearing	910040
214	8/8/2014	479031		Tension Wheel Nuts To OEM Specification	910040
214	8/6/2014	478461	Mechanic entered - Whls & Tyres Puncture O/S/F tyre	Replaced with a used cleanskin and torqued.	909257
214	8/5/2014	478358		A Service	909257
214	8/5/2014	478358	LED FRONT POSITION MARKER LIGHT		909257
214	8/5/2014	478358	LAMP INTERIOR AND REVERSING		909257
214	8/5/2014	478358	GLOBE 24V 18W		909257
214	8/5/2014	478358		Replaced N/S reverse lights and R/H number plate light	909257
214	8/5/2014	478358		Clean A/C filter	909257
214	8/5/2014	478358		Grease AC Compressor Clutch Bearing	909257
214	8/5/2014	478358		Tension Wheel Nuts To OEM Specification	909257
214	8/1/2014	472443	BUS INSPECTION LARGE >25 SEATS	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:PE140910 R	910300
214	8/1/2014	469076	MERCEDES REAR ENGINE DOOR SWIT	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14(908060
214	8/1/2014	469076	Gas Strut 680n 530mm	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14(908060
214	8/1/2014	469076	COVER REAR DOOR ROOF CONTROL P	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14(908060
214	8/1/2014	469076	MUD FLAP	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14(908060
214	8/1/2014	469076	Brake Pedal Rubber (A107291018	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:PE14(908060
214	7/31/2014	476772	repair ac system water tubes	Creditor #:PT-COA003 COACHAIR PTY LTD P/O #:PE141819 Receiving	909629

214	7/28/2014	476772	coolant leak	completed by Coachair	907403
214	7/25/2014	476409	Ops Entered - Accident - Sundry - Route: 782 - Tasma	REPLACED BUMPER	905978
214	7/23/2014	475964	Mechanic entered - Elec & Light Battery Flat	jump started/ replaced batts	905978
214	7/23/2014	476130	repair not starting	replaced batts	905978
214	7/22/2014	475797	Drv entered - Steering Steering Whl [See printed defe	Adjusted steering linkage on column	905978
214	7/22/2014	475797	Drv entered - Heat & Demist Demisters Cold	completed	905978
214	7/22/2014	475797	Drv entered - Heat & Demist No Heaters	completed	905978
214	7/22/2014	475797	Drv entered - Heat & Demist Heater Cold	Checked heater demister found 41.8 degrees blowing out at wind sc	905978
214	7/22/2014	475704	Mechanic entered - Elec & Light Battery Flat	Jump started Load tested batteries found 7.5 volts on both and dro	905978
214	7/21/2014	475424	Mechanic entered - Elec & Light Battery Flat	jump started	905978
214	7/18/2014	475099	Mechanic entered - Elec & Light Battery Flat	Jump Started.	905239
214	7/18/2014	475195	LH parker out		905239
214	7/18/2014	475195	GLOBE WEDGE 24V/5W		905239
214	7/14/2014	474068	Mechanic entered - Elec & Light Battery Flat	Jumpstarted.	904140
214	7/4/2014	472463		Perform & Complete TSV Bus Safety Inspection	901870
214	7/4/2014	472463		Tension Wheel Nuts	901870
214	7/4/2014	472463		Rotate Front Axle Tyres Left to Right - MT & IBS only	901870
214	7/4/2014	472463		Rotate Rear Axle Tyres Left to Right - MT & IBS only	901870
214	7/4/2014	472463		Clean A/C filter.	901870
214	7/4/2014	472443	annaul inspection	completed	901870
214	7/4/2014	472463	Fit Wheel Nut Pointers to all wheel nuts on the front	completed	901870
214	7/4/2014	472594	Mechanic entered - Elec & Light Interior Lights Rear d	Replace lamp	901870
214	7/4/2014	472594	LED FRONT POSITION MARKER LIGHT		901870
214	7/1/2014	471531		Carry out R.S.I service	901870
214	7/1/2014	471531	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		901870
214	7/1/2014	471531	FUEL FILTER MERC 0500LE		901870
214	7/1/2014	471531	FUEL FILTER 0500LE		901870
214	7/1/2014	471531	FAN DRIVE OIL 0500LE		901870
214	7/1/2014	471531	Mechanic entered - Annaul Body Inspection	refit front o/s wheel arch	901870
214	7/1/2014	471671	Drv entered - Other [See printed defect for more info	Replaced interior step light front door	901870
214	7/1/2014	471671	Ops Entered - Fault - Elec & Light Interior Lights - Rou	completed	901870
214	7/1/2014	471671	Drv entered - Elec & Light Interior Lights	completed	901870
214	7/1/2014	471759	Fit Myki decals as requiredFit Recruitment decal as re	DECALS FITTED.	901870
214	7/1/2014	471548	repair air leaks	Replaced air fitting kits near air drier	901870
214	6/30/2014	471531		Electrical - BATTERIES: check fluid level (leave air gap when topping	901870
214	6/30/2014	471531		Check oil level in transmission & top-up if required	901870
214	6/30/2014	471531		Check & clean filter cartridge in dry-type air cleaner	901870
214	6/30/2014	471531		Check power steering oil level	901870
214	6/30/2014	471531		Change pre and main fuel filter	901870
214	6/30/2014	471531		Change air drier cannister; clean silencer & drain air reservoir	901870
214	6/30/2014	471531		Change oil in fan angle drive	901870
214	6/30/2014	471531		Top-up coolant level (must equate to -37C frost protection)	901870
214	6/30/2014	471531		Inspect radiator & charge-air cooler for dirt - clean if required	901870
214	6/30/2014	471457	Mechanic entered - Annaul Body Inspection	secure disabled seats	901870
214	6/30/2014	471548	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		901870
214	6/30/2014	471548	repair air leaks		901870
214	6/26/2014	471046	Remove Fair Evasion A3 Poster & Replace with MYKI /	DECALS FITTED	900438
214	6/26/2014	470989	Fit New Myki Decal as Per PTV fitting instructions	completed	900438
214	6/23/2014	469076	(1) REPLACE O/S PANEL STRUTS (2) REPLACE BRAKE Pt	completed	900075
214	6/23/2014	470118	(1) REPLACE O/S PANEL STRUTS (2) REPLACE BRAKE Pt	r/r rear door overhead panel replace o/s rear door stuts	900075
214	6/20/2014	469694	Mechanic entered - Elec & Light Interior Lights Fr doo	Fixed and tested.	899145
214	6/17/2014	469076	(1) REPLACE O/S PANEL STRUTS (2) REPLACE BRAKE Pt	completed	898038
214	6/13/2014	468501	check over for RS1	Checked and recorded defects.	896856
214	6/13/2014	468501	L.E.D SIDE MARKER PEREI RED/AMBER LLX30131		896856
214	6/13/2014	468501	Mechanic entered - Elec & Light Park Lights N/S/R sid	Replaced.	896856
214	6/12/2014	468274	CUSHION FOAM 517 - (ct)		896856
214	6/12/2014	468274	replace drivers seat	fit reco drivers seat and new cushoun	896856
214	6/4/2014	466503	FRANCHISEE CASE	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE139616 Receivi	896165
214	6/4/2014	466503	DISPOSAL CHARGE	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE139616 Receivi	896165
214	6/4/2014	466503	FITTING	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE139616 Receivi	896165
214	6/4/2014	466503	11R22.5 RECAMIC DRIVE PATTERN	Creditor #:PT-MIC002 MICHELIN AUSTRALIA P/O #:PE139616 Receivi	896165
214	6/3/2014	466670	Retorque o/s/r wheel nuts to 600nm	Completed	893607
214	6/2/2014	466503	Replace tyre pos 5	Replace o/s/r tyres due to damaged tread to pos 5. pos 6 back to rac	893607
214	6/2/2014	466391		A Service	893607
214	6/2/2014	466391		Clean A/C filter	893607
214	6/2/2014	466391		Grease AC Compressor Clutch Bearing	893607
214	6/2/2014	466391		Tension Wheel Nuts To OEM Specification	893607
214	5/30/2014	466119		Clean A/C filter.	893041

214	5/30/2014	466119	Rotate Rear Axle Tyres Left to Right - MT & IBS only	893041
214	5/30/2014	466119	Rotate Front Axle Tyres Left to Right - MT & IBS only	893041
214	5/30/2014	466119	Tension Wheel Nuts	893041
214	5/30/2014	466119	Perform & Complete TSV Bus Safety Inspection	893041
214	5/27/2014	465361	Adjust Tappets	891561
214	5/23/2014	463025	RADIATOR HOSE UPPER 0500LE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P138
214	5/22/2014	464556	Ops Entered - Fault - Comm Equip Not Receiving - Ro	checked all ok
214	5/21/2014	464396	Drv entered - Other	889889
214	5/21/2014	464396	Drv entered - Body & Acc Passenger Seat Cushion [Se	once again tested and found no fault
214	5/19/2014	463876	Remove A3 Marketing Poster CATCHING A BUS	Fit A3 Marketing
214	5/17/2014	463577	GLOBE WEDGE 24V/5W	888221
214	5/17/2014	463577	Mechanic entered - Elec & Light Park Lights	Replaced N/F park light globe
214	5/15/2014	463155	Drv entered - Suspension Hard	air dryer replaced by Ross
214	5/15/2014	463170	Ops Entered - Breakdown - Breakdown Change Over	completed
214	5/15/2014	463206	overhaul air dryer	Clean out and assemble air drier
214	5/14/2014	462979	Ops Entered - Fault - Suspension Hard - Route: - Off	checked and no fault found
214	5/14/2014	462670	Drv entered - Comm Equip Not Opertating	checked ok
214	5/14/2014	463025	RADIATOR HOSE UPPER 0500LE	887195
214	5/14/2014	463025	Ops Entered - Breakdown - Breakdown Road Defect U	Travel to crib point and replaced water pump hose and fill coolant a
214	5/5/2014	461009	Ops Entered - Fault - Body & Acc Drivers Seat Mount	tested seat and found in good working condition
214	5/3/2014	461026	GLOBE 24V 18W	884158
214	5/3/2014	461026	LH indicator out	884158
214	5/1/2014	460485		Clean A/C filter.
214	5/1/2014	460485		Rotate Rear Axle Tyres Left to Right - MT & IBS only
214	5/1/2014	460485		Rotate Front Axle Tyres Left to Right - MT & IBS only
214	5/1/2014	460485		Tension Wheel Nuts
214	5/1/2014	460485		Perform & Complete TSV Bus Safety Inspection
214	4/22/2014	458929	Remove A3 Hold On Poster and Fit A3 Catching a bus	completed
214	4/20/2014	458741	GLOBE H1 24V 70W	880240
214	4/20/2014	458741	Ops Entered - Fault - Elec & Light Headlights - Route:	Replaced O/S Headlight Globe
214	4/19/2014	458887	WHEEL NUT SQUIRREL	879612
214	4/19/2014	458887	rear squirrels missing	879875
214	4/16/2014	457046	front doors damaged acc # 38941	adjust doors test sensitive edges
214	4/15/2014	457046	sikaflex	Creditor #:PT-FRANBA FRANKSTON BEARINGS (AUST) P P/O #:P13784
214	4/15/2014	457046	front doors damaged acc # 38941	878856
214	4/14/2014	456149	SENSITIVE EDGE RUBBERS	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:P137522 Receivin
214	4/14/2014	457046	front doors damaged acc # 38941	repair front doors repair front doors
214	4/11/2014	457046	front doors damaged acc # 38941	repair front door repair front door
214	4/9/2014	457163	GLOBE WEDGE 24V 1.2W	878856
214	4/9/2014	457163		Clean A/C filter
214	4/9/2014	457163		A Service
214	4/9/2014	457163		Grease AC Compressor Clutch Bearing
214	4/9/2014	457163		Tension Wheel Nuts To OEM Specification
214	4/4/2014	456023	Drv entered - Body & Acc Drivers Seat Mount	completed
214	4/4/2014	456149	Mechanic entered - Accident Front	Front door and cr repair floor hatches repair accident damage
214	4/3/2014	456017	Drv entered - Body & Acc Drivers Seat Controls [See p	fittede new seat base
214	3/31/2014	455017	Mechanic entered - Elec & Light Park Lights	Replaced light all working ok replaced top left hand park light all ok
214	3/31/2014	455017	GLOBE 24V 5W BAYONETT	877698
214	3/20/2014	453164	Perform Campaign 1_14 School Bus Light Globe Check	n/a
214	3/19/2014	452877	Drv entered - Elec & Light Interior Lights	Checked interior lights found all working.
214	3/17/2014	452450	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	873970
214	3/17/2014	452450		873754
214	3/17/2014	452450		Clean A/C filter.
214	3/17/2014	452450		Rotate Rear Axle Tyres Left to Right - MT & IBS only
214	3/17/2014	452450		Rotate Front Axle Tyres Left to Right - MT & IBS only
214	3/17/2014	452450		Tension Wheel Nuts
214	3/17/2014	452450		Perform & Complete TSV Bus Safety Inspection Carried out Safety ins
214	3/17/2014	452448		873754
214	3/17/2014	452448	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.
214	3/17/2014	452448		Re-kit Air Cyclone Separator Replaced the air cyclone seperator and
214	3/17/2014	452448	HALDEX COIL KIT 0500LE	Coil Kit
214	3/17/2014	452448	DRAIN VALVE KIT BOTTOM	Valve Kit
214	3/17/2014	452448	HALDEX COIL BASE OIL SEPERATOR	Base
214	3/12/2014	451738	GLOBE H1 24V 70W	873754
214	3/12/2014	451738	LH headlight out	872230
214	3/7/2014	451174	Service	Service T - Replace Transmission Oil & Filter
214	3/7/2014	451174	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter
214	3/7/2014	451174	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil
214	3/7/2014	451174		Service T - Replace Transmission Oil & Filter

214	3/3/2014	450355	retension o/s rear wheel nuts to 600nm	retensioned to spec	869524
214	3/2/2014	450111	DOOR LIMIT SWITCH		868961
214	3/2/2014	450111	engine door limit switch n/w	replaced switch	868961
214	2/24/2014	447949	FILTER DRIER THERMO KING		867116
214	2/24/2014	447949	COMPRESSOR OIL AIR CON		867116
214	2/22/2014	449038	GLOBE WEDGE 24V/5W		866861
214	2/22/2014	449038	LH parker out		866861
214	2/20/2014	448427	cctv repairs	Creditor #:PT-LON002 LONSDALE ST AUTO ELECTRICS P/O #:P135430	869890
214	2/20/2014	448427	repair cctv system	completed by lonsdale auto	865811
214	2/20/2014	448441	Ops Entered - Accident - Collision In-Out of Bus Stop -	completed. buffed up o/s paint work	865811
214	2/20/2014	447949	Mechanic entered - Accident Side	clean up accident damage	865811
214	2/19/2014	447641	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135259 Receiving #:137	867116
214	2/19/2014	447641	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135259 Receiving #:137	867116
214	2/19/2014	447326	BALANCE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135204 Receiving #:137	867116
214	2/19/2014	447326	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135204 Receiving #:137	867116
214	2/19/2014	447326	DP 11R22.5 148/145L TL SP350A	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P135204 Receiving #:137	867116
214	2/18/2014	448022	retension o/s rear wheel nuts to 600nm	Retension wheels O/R to 600 Nm	865219
214	2/18/2014	448023	OIL FILTER 1725+0500LE		865219
214	2/18/2014	448023	ENGINE OIL DELO 400LE 15W40		865219
214	2/18/2014	448023		Tension Wheel Nuts to Spec	865219
214	2/18/2014	448023		A Service & Bus Safety Inspection	865219
214	2/18/2014	448023		D-Service & Bus Safety Inspection	865219
214	2/18/2014	448024		Replace Engine Oil Breather Kit	865219
214	2/18/2014	448024		Grease AC Compressor Clutch Bearing	865219
214	2/18/2014	448024	AIR FILTER MERC 0500LE		865219
214	2/18/2014	448024	OIL FILTER 1725+0500LE		865219
214	2/18/2014	448024	ENGINE OIL DELO 400LE 15W40		865219
214	2/18/2014	448024		Tension Wheel Nuts to Spec	865219
214	2/18/2014	448024		A Service & Bus Safety Inspection	865219
214	2/18/2014	448024		D-Service & Bus Safety Inspection	865219
214	2/18/2014	448024	GLOBE WEDGE 24V 1.2W		865219
214	2/18/2014	448023		Replace Engine Oil Breather Kit	865219
214	2/18/2014	448023	ENGINE OIL BREATHER KIT 0500LE (EAS500M05)		865219
214	2/18/2014	448023		Grease AC Compressor Clutch Bearing	865219
214	2/18/2014	448023	AIR FILTER MERC 0500LE		865219
214	2/18/2014	447949		Check & replace electric motor brushes	865219
214	2/18/2014	447949		Replace compressor oil	865219
214	2/18/2014	447949		Replace filter drier	865219
214	2/18/2014	447949		D Service	865219
214	2/18/2014	447949		Check boost pump condition	865219
214	2/18/2014	447949		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	865219
214	2/18/2014	447949		CONDENSOR AREA: Clean condenser coils; check bolts/clamps for ten	865219
214	2/18/2014	447949		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	865219
214	2/18/2014	447949		EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	865219
214	2/18/2014	447949		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	865219
214	2/18/2014	447949		COMPRESSOR: Carry out efficiency test; check unloader control; che	865219
214	2/18/2014	447949		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	865219
214	2/18/2014	447949		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	865219
214	2/18/2014	447949		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	865219
214	2/18/2014	447949		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	865219
214	2/18/2014	447949		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	865219
214	2/18/2014	448024		A Service	865219
214	2/18/2014	448024		Clean A/C filter	865219
214	2/18/2014	448024		Grease AC Compressor Clutch Bearing	865219
214	2/18/2014	448024		Tension Wheel Nuts To OEM Specification	865219
214	2/18/2014	448023		A Service	865219
214	2/18/2014	448023		Clean A/C filter	865219
214	2/18/2014	448023		Grease AC Compressor Clutch Bearing	865219
214	2/18/2014	448023		Tension Wheel Nuts To OEM Specification	865219
214	2/16/2014	447641	Mechanic entered - Whls & Tyres Puncture O/S drives	Both 5 and 6 position drives replaced and torqued.	864841
214	2/14/2014	447419	Mechanic entered - Whls & Tyres Retension Wheel N	retensioned to spec	863774
214	2/14/2014	447417	AIR DRYER CANISTER VOLVO+ NL202		863774
214	2/14/2014	447417	PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		863774
214	2/14/2014	447417	AIR DRYER UNLOADER KIT		863774
214	2/14/2014	447417	overhaul air dryer		863774
214	2/12/2014	447326	Mechanic entered - Whls & Tyres Worn	changed Postion 1 tyre	863774
214	2/12/2014	447180	air dryer leaking	replaced air dryer	863567
214	2/11/2014	446884		Clean A/C filter.	863404

214	2/11/2014	446884		Tension Wheel Nuts	863404
214	2/11/2014	446884		Perform & Complete TSV Bus Safety Inspection	863404
214	2/11/2014	446885		A Service	863404
214	2/11/2014	446885		Clean A/C filter	863404
214	2/11/2014	446885		Grease AC Compressor Clutch Bearing	863404
214	2/11/2014	446885		Tension Wheel Nuts To OEM Specification	863404
214	2/9/2014	446554	Remove BTS Equipment Fuses	completed	862471
214	2/5/2014	446077	Mechanic entered - Elec & Light Park Lights Fr N/S par	repaired stop light wiring	860999
214	2/5/2014	445920	rego plate light out	Checked both working.	860999
214	2/3/2014	445714	Mechanic entered - Whls & Tyres Worn N/S/F tyre wc	checked has 3mm on tread	860612
214	1/31/2014	445394	driver seat belt n/w	r/r drivers seat belt	859626
214	1/30/2014	443335	CHECK VALVE 22MM CYCLONE AIR FILTER		854381
214	1/24/2014	444586	Ops Entered - Fault - Wipers & Washers Wipers Not W	Tighten spindle nuts through bulk head. Adjust sweep angels. Rewel	857445
214	1/22/2014	442026	N/S/F TOP ACCIDENT DAMAGE	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P133f	857445
214	1/22/2014	442025	N/S/R TOP ACCIDENT REPAIR	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P133f	857445
214	1/22/2014	442024	O/S/F REPAIR	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P133f	857445
214	1/19/2014	443870	Mechanic entered - Wipers & Washers Loose	secured by ross	855488
214	1/19/2014	443869	RAD CAP MERC BENZ SIGHT GLASS SIDE		855488
214	1/19/2014	443869	rad cap leaking	replaced cap	855488
214	1/15/2014	443335	DISC PAD SET SCANIA MB0500		854381
214	1/15/2014	443335	A/C BELT 0500 BENZ		854381
214	1/15/2014	443335		Clean A/C filter.	854381
214	1/15/2014	443335		Tension Wheel Nuts	854381
214	1/15/2014	443335		Perform & Complete TSV Bus Safety Inspection Carried out saftey ins	854381
214	1/15/2014	443335	Mechanic entered - Air Cond Belt Replacement Main	Replaced and tested	854381
214	1/15/2014	443335	Mechanic entered - Brakes Other Rear brakes pads w	Replaced and tested	854381
214	1/15/2014	443335	Mechanic entered - Brakes Other Rear brakes pads w	Replaced and tested	854381
214	1/14/2014	443196	Mechanic entered - Body & Acc Interior	go to eastcoast and fit drivers seat into bus	854381
214	1/7/2014	441992	Mechanic entered - Body & Acc Drivers Seat Cushion	overhauled	854381
214	1/7/2014	441977	Ops Entered - Fault - Body & Acc Drivers Seat Mount -	overhauled	854381
214	1/7/2014	441976	Ops Entered - Fault - Body & Acc Drivers Seat Mount -	replace seat internals with new kit	854381
214	1/7/2014	442027	N/S MID ACCIDENT DAMAGE REPAIR	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P133f	857445
214	1/6/2014	441992	Mechanic entered - Body & Acc Drivers Seat Cushion	remove drivers seat and take bus to eastcoast	854381
214	1/6/2014	441977	Ops Entered - Fault - Body & Acc Drivers Seat Mount -	completed	854381
214	1/6/2014	441976	Ops Entered - Fault - Body & Acc Drivers Seat Mount -	completed	854381
214	1/6/2014	442028	Accident Damaged # 31269 R/R. front bumper bar der	Completed.	854381
214	1/6/2014	442027	Accident Damaged # 36265 R/R. n/s. lower body pane	Sent to Eastcoast.	854381
214	1/6/2014	442026	Unreported n/s/f top damage Acc No 38455.	Sent to Eastcoast.	854381
214	1/6/2014	442025	Unreported n/s/r top damage Acc No 38454.	Sent to Eastcoast.	854381
214	1/6/2014	442023	Accident Damaged # 31600 R/R. O/S/R. bumper-bar r	Completed.	854381
214	1/6/2014	442024	Unreported o/s/f damage.Acc No 38453.	Sent to Eastcoast.	854381
214	1/3/2014	441213	PUNCTURE TRUCK-FITTED	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P133470 Receiving #:135	854381
214	12/31/2013	441516	retension position no 4 to 600nm	retensioned	852567
214	12/29/2013	441213	Mechanic entered - Whls & Tyres Puncture	Replaced flat tyre Pos 4 and tension to 600NM	852064
214	12/22/2013	440544	Drv entered - Body & Acc Drivers Seat Belt [See printe	freed up belt	849595
214	12/17/2013	439877		Clean A/C filter	848685
214	12/17/2013	439877		Grease AC Compressor Clutch Bearing	848685
214	12/17/2013	439877		Tension Wheel Nuts To OEM Specification	848685
214	12/17/2013	439877		A Service	848685
214	12/13/2013	439126	Drv entered - Other	as above	848078
214	12/13/2013	439126	Drv entered - Other	no defect found	848078
214	12/13/2013	439115	Drv entered - Body & Acc Drivers Seat Belt	completed	848078
214	12/13/2013	439115	Drv entered - Body & Acc Other	cut and polish bus cut and polish bus	848078
214	12/11/2013	438640	Drv entered - Other	as above	847385
214	12/11/2013	438640	Ops Entered - Breakdown - Breakdown Road Defect U	as above	847385
214	12/11/2013	438640	Ops Entered - Breakdown - Breakdown Road Defect A	completed by white horse fuel pipe	847385
214	12/10/2013	438620	Organise Mbenz Recall SM949 to be performed by WI	Completed on site by Whitehorse.	847385
214	12/10/2013	438396	FUEL FILTER MERC 0500LE		847036
214	12/10/2013	438396	Mechanic entered - Fuel Leaking	completed by white horse	847036
214	12/10/2013	438556	Ops Entered - Fault - Fuel Leaking - Route: 785 - Franl	compaine done by white horse	847036
214	12/9/2013	438396	Mechanic entered - Fuel Leaking	Checked for fuel leak and not starting. Found braide fuel line from p	847036
214	12/5/2013	437951	GLOBE WEDGE 24V/5W		845735
214	12/5/2013	437951	front park lights not working	replaced n/s park light	845735
214	11/30/2013	437236	sticky acc pedal	lubed mico switch	844332
214	11/29/2013	437129	NUT BRASS BATTERY TERMINAL POSITIVE		844252
214	11/29/2013	437129		replaced positive battery terminal	844252
214	11/29/2013	437129		Clean A/C filter.	844252
214	11/29/2013	437129		Rotate Rear Axle Tyres Left to Right - MT & IBS only	844252

214	11/29/2013	437129		Rotate Front Axle Tyres Left to Right - MT & IBS only	844252
214	11/29/2013	437129		Tension Wheel Nuts	844252
214	11/29/2013	437129		Perform & Complete TSV Bus Safety Inspection	844252
214	11/27/2013	436690	Drv entered - Body & Acc Drivers Seat Back Rest [See	repaired air flow to seat	843152
214	11/22/2013	436153	Ops Entered - Fault - Cool & AC Sys Drivers Fan - Rout	completed	841983
214	11/22/2013	436153	replace drivers seat	replaced drivers seat	841983
214	11/19/2013	435539	Drv entered - Wipers & Washers Other	Checked wiper washers and wiper found ok.	840963
214	11/19/2013	435539	Drv entered - Air Cond Air Conditioner	Found air con working.	840963
214	11/19/2013	435539	Ops Entered - Fault - Air Cond Cooling Fault Light - Rc	Found air con working.	840963
214	11/19/2013	435505	Drv entered - Other	no fault found	840963
214	11/18/2013	435083	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131925 Receiving #:133	841249
214	11/18/2013	435083	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131925 Receiving #:133	841249
214	11/18/2013	434897	SEAT ASSY ISRI 6008 AIR LUMBAR	Creditor #:PT-EAS001 EASTCOAST TRUCK & BUS SERVICE P/O #:P1319	842538
214	11/15/2013	435237	retension rear wheel nuts to 600nm	rear wheels retensioned to 600nm	839634
214	11/15/2013	435083	Pos 2-3 3mm	COMPLETED	839634
214	11/15/2013	435061	Mechanic entered - Whls & Tyres Worn L/H rear tyres	Replaced N/S rear tyres.	839634
214	11/15/2013	435056	L.E.D SIDE MARKER PEREI RED/AMBER		839634
214	11/15/2013	435056	RH clearance light out	Replaced OS rear clearance light.	839634
214	11/14/2013	434897	can not adjust seat cushion	CHECKED SEAT REPLACED BUM PART	839634
214	11/11/2013	434296	Ops Entered - Accident - Bus Hit Other Bus - Route: -	Completed.	838674
214	11/7/2013	433823	pos 2 5 & 6	retorqued to 670nm all round	837366
214	11/4/2013	433431	Drv entered - Vandalism Graffiti	completed	836342
214	10/31/2013	432281	BALANCE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131221 Receiving #:132	836342
214	10/31/2013	432281	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131221 Receiving #:132	836342
214	10/31/2013	432281	DP 11R22.5 148/145L TL SP350A	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131221 Receiving #:132	836342
214	10/31/2013	432281	SP 11R22.5 MCA-R DHR CUST/STOR	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P131221 Receiving #:132	836342
214	10/29/2013	432626		Clean A/C filter.	834514
214	10/29/2013	432626		Rotate Rear Axle Tyres Left to Right - MT & IBS only	834514
214	10/29/2013	432626		Rotate Front Axle Tyres Left to Right - MT & IBS only	834514
214	10/29/2013	432626		Tension Wheel Nuts	834514
214	10/29/2013	432626		Perform & Complete TSV Bus Safety Inspection	834514
214	10/29/2013	432625		A Service	834514
214	10/29/2013	432625		Clean A/C filter	834514
214	10/29/2013	432625		Grease AC Compressor Clutch Bearing	834514
214	10/29/2013	432625		Tension Wheel Nuts To OEM Specification	834514
214	10/28/2013	432281	Mechanic entered - Whls & Tyres Worn O/S steer and	Replaced O/S steer and the drives and torqued.	834271
214	10/28/2013	432415	Drv entered - Other	completed by mick	834271
214	10/28/2013	432414	Drv entered - Other	completed by mick	834271
214	10/28/2013	432412	DRIVERS SEAT SHOCKER		834271
214	10/28/2013	432412	Drv entered - Body & Acc Drivers Seat Controls [See p	dissaemle seat remove seat shocker fit new shocker reassemble sei	834271
214	10/24/2013	431925	Ops Entered - Fault - Heat & Demist No Heaters - Rou	checked demoster working at 25 degrees..air con on	833120
214	10/22/2013	431385	Drv entered - Suspension Hard	Checked suspension components could not fault any. Road tested fc	831993
214	10/22/2013	431581	Drv entered - Other	no fault found	829829
214	10/21/2013	431382	Drv entered - Vandalism Graffiti	removed graffiti	831993
214	10/17/2013	430748	Ops Entered - Fault - Body & Acc Drivers Seat Cushion	replaced shock	831230
214	10/17/2013	430731	Mechanic entered - Body & Acc Drivers Seat Mount	fit gas strut to drivers seat	831230
214	10/17/2013	430647	Mechanic entered - Body & Acc Exterior	remove decals	831230
214	10/16/2013	430279	tyre pos 5 low	servicable at 5mm	830873
214	10/14/2013	429891		Re-kit Air Cyclone Separator	830297
214	10/13/2013	429863	Drv entered - Body & Acc Exterior [See printed defect	Repair loose panels	830000
214	10/9/2013	429282	Perform Campaign 01_13 CCTV and GPS AUDIT inspec	Completed.	828417
214	10/3/2013	428212	Drv entered - Suspension Hard	no fault found	826070
214	10/2/2013	427901	Drv entered - Body & Acc Drivers Seat Mount [See pri	checked by ross stacky found in good working order	826070
214	10/1/2013	426655	Rebrand to VENTURA	Creditor #:PT-TRA009 TRANSCAL P/O #:P130566 Receiving #:131959	829537
214	9/30/2013	429042	GLOBE 24V16W		826070
214	9/30/2013	429042	RH indicator out		826070
214	9/27/2013	427440	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per C:	Completed.	824798
214	9/25/2013	427124		Clean A/C filter.	824186
214	9/25/2013	427124		Rotate Rear Axle Tyres Left to Right - MT & IBS only	824186
214	9/25/2013	427124		Rotate Front Axle Tyres Left to Right - MT & IBS only	824186
214	9/25/2013	427124		Tension Wheel Nuts	824186
214	9/25/2013	427124		Perform & Complete TSV Bus Safety Inspection	824186
214	9/24/2013	426931	Drv entered - Body & Acc Drivers Seat Controls [See p	repaired by ross starky	823837
214	9/23/2013	426655	Carry out campaign as per Fleet re-branding Procedu	completed	823486
214	9/20/2013	426371	Ops Entered - Fault - Security CCTV System Faulty - Rc	completed	822546
214	9/11/2013	424708	Remove A3 Marketing Poster 30/9Fit Marketing Poste	Poster up to date.	820438
214	9/11/2013	424708	Perform sticker audit on vehicles ensuring that correc	Missing all or part of sticker #123457111416&18.	820438
214	9/11/2013	424790		Replace Engine Oil Breather Kit	820438

214	9/11/2013	424790		Grease AC Compressor Clutch Bearing	820438
214	9/11/2013	424790	ENGINE OIL DELO 400LE 15W40		820438
214	9/11/2013	424790		Tension Wheel Nuts to Spec	820438
214	9/11/2013	424790		A Service & Bus Safety Inspection	820438
214	9/11/2013	424790		D-Service & Bus Safety Inspection	820438
214	9/11/2013	424790	AIR FILTER MERC 0500LE		820438
214	9/11/2013	424790	OIL FILTER 1725+0500LE		820438
214	9/11/2013	424790	FUEL FILTER 0500LE		820438
214	9/11/2013	424790		Tension Wheel Nuts To OEM Specification	820438
214	9/11/2013	424790		A Service Service.Replaced fuel filter.Fit exhaust bracket to cooler pi	820438
214	9/11/2013	424790		Clean A/C filter	820438
214	9/11/2013	424790		Grease AC Compressor Clutch Bearing	820438
214	9/6/2013	423968	GLOBE WEDGE 24V 1.2W		818757
214	9/6/2013	423968	3x rocker switches out	Replaced 3 rocker switch globed.	818757
214	8/30/2013	419981	REPAIR HORN FAULT	Creditor #:PT-VOLGRE VOLGREN AUSTRALIA P/O #:P129127 Receiving	818017
214	8/30/2013	422756	SYNTHETIC GEAR LUBRICANT FM 75W-140		816338
214	8/30/2013	422756	Service	Replace Differential oil	816338
214	8/30/2013	422752		Grease AC Compressor Clutch Bearing	816338
214	8/30/2013	422752		Tension Wheel Nuts To OEM Specification	816338
214	8/30/2013	422752		A Service	816338
214	8/30/2013	422752		Clean A/C filter	816338
214	8/23/2013	421546	MUFFLER MOUNT 0500LE		814173
214	8/23/2013	421546		Clean A/C filter.	814173
214	8/23/2013	421546		Rotate Rear Axle Tyres Left to Right - MT & IBS only	814173
214	8/23/2013	421546		Rotate Front Axle Tyres Left to Right - MT & IBS only	814173
214	8/23/2013	421546		Tension Wheel Nuts	814173
214	8/23/2013	421546		Perform & Complete TSV Bus Safety Inspection	814173
214	8/16/2013	420486	Drv entered - Accident	completed.	811843
214	8/13/2013	419981	horn problems	repaired by volgren	811238
214	8/12/2013	419660	Mechanic entered - Body & Acc Exterior	remove decals and cut and polish	811238
214	8/7/2013	418447	11R22.5-A GRADE CASE CHG	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P127887 Receiving #:125	811238
214	8/7/2013	418447	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P127887 Receiving #:125	811238
214	8/7/2013	418447	SP 11R22.5 SP327 8A GRADE CASE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P127887 Receiving #:125	811238
214	8/7/2013	419038	retension rear wheel nuts to 600nm	retensioned rear wheel nuts	810870
214	8/6/2013	418847	Mechanic entered - Passenger Doors Other	door jammed.Refitted front door front half pivot at top	810498
214	8/4/2013	418447	Mechanic entered - Whls & Tyres Puncture	Replaced tyre Pos 4 & tension wheel nuts	809798
214	8/1/2013	417962	Drv entered - Elec & Light Headlights	REPLASD HEAD GLOBES	809798
214	8/1/2013	417962	Ops Entered - Fault - Elec & Light Headlights - Route: done		809798
214	7/30/2013	417294	Ops Entered - Fault - Elec & Light Headlights - Route: carried out by josh		809150
214	7/25/2013	416973	Mechanic entered - Elec & Light Headlights n/s headli completed		807829
214	7/19/2013	415979		Tension Wheel Nuts	804836
214	7/19/2013	415979		Perform & Complete TSV Bus Safety Inspection	804836
214	7/19/2013	415979	EMERGENCY EXIT BUTTON PULL COVER		804836
214	7/19/2013	415979	Service	Clean A/C filter.	804836
214	7/19/2013	415979		Rotate Rear Axle Tyres Left to Right - MT & IBS only	804836
214	7/19/2013	415979		Rotate Front Axle Tyres Left to Right - MT & IBS only	804836
214	7/19/2013	415979	0405 ANSAIR FRONT AND REAR AIR BAG B10M/B7R REAR		804836
214	7/19/2013	415982	Drv entered - Vandalism Damaged Seat	found no damaged seats	804836
214	7/19/2013	415981	Drv entered - Vandalism Wndow Etch	windows are etched needs replacing	804836
214	7/19/2013	415980	Drv entered - Vandalism Graffiti	graffitti needs to be cleaned	804836
214	7/19/2013	415984	headlights are set for LH vehicle	changed headlights to rh vehicle and adjusted	804836
214	7/19/2013	415983	Drv entered - Elec & Light Headlights	checked and adjusted headlights	804836
214	7/16/2013	415208	LH parker out	replaced	803883
214	7/16/2013	415284		Tension Wheel Nuts To OEM Specification	803883
214	7/16/2013	415284		A Service replaced park light and emergancy led light	803883
214	7/16/2013	415284		Clean A/C filter	803883
214	7/16/2013	415284		Grease AC Compressor Clutch Bearing	803883
214	7/15/2013	413311	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		803531
214	7/5/2013	413682	ANNUAL INSPECTION	Creditor #:PT-ROASAF ROAD SAFETY INSPECTIONS P/O #:P126655 Re	804109
214	7/5/2013	413682	Annaul inspection	completed F251607	800459
214	7/5/2013	413529	Replace o/s front drop arm	fitted	800459
214	7/5/2013	413351	check air leak	done by anthony	800459
214	7/4/2013	413501	clean and park for RSI	cleaned ready for rsi	800459
214	7/4/2013	413311	drop arm 50y3522	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P126611 Receiving #	800459
214	7/4/2013	413311	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		800459
214	7/4/2013	413311	CIRCUIT PROTECTION VALVE		800459
214	7/4/2013	413311	last days check for RSI	Carried out RSI checks. Replaced suspension valve six way protection valve	800459
214	7/1/2013	412088	FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P126262 Receiving #:125	802950

214	7/1/2013	412088 SP 11R22.5 SP327 CUST/STOR CAS	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P126262 Receiving #:128	802950
214	7/1/2013	412777 steam clean for RSI	cleaned for rsi	799585
214	6/29/2013	412590 AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		799234
214	6/29/2013	412590 air leak from air dryer	Replaced air hose 12mm x 1.5 on six way valve. replaced air fitting r	799234
214	6/27/2013	412085 replace head lamps	replaced lamps	798510
214	6/27/2013	411949 9x12mm pipe	Creditor #:PT-WHITRU WHITEHORSE TRUCK CENTRE P/O #:P126222 I	799585
214	6/26/2013	412085 hl1030-24v	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P126258 Receiving #	799585
214	6/26/2013	412085 hl1028	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P126258 Receiving #	799585
214	6/26/2013	412102 replace front modisty pannel	incorrectly entered	798510
214	6/25/2013	412088 CHANGE REAR TYRE		798510
214	6/25/2013	411535 Drv entered - Elec & Light Headlights [See printed def	R/H Hi beam is loosing it's reflector and need replacing.	797756
214	6/25/2013	411818 HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500		797756
214	6/25/2013	411818 GLOBE H1 24V 70W		797756
214	6/25/2013	411818 repair head light problem	Replaced R/H Hi/Low beam headlight and globe. Repaired wining to	797756
214	6/25/2013	411949 air pipe leak	replaced pipe	797756
214	6/24/2013	411535	Top-up coolant level (must equate to -37C frost protection)	797756
214	6/24/2013	411535	Electrical - BATTERIES: check fluid level (leave air gap when topping l	797756
214	6/24/2013	411535	Inspect radiator & charge-air cooler for dirt - clean if required	797756
214	6/24/2013	411535	Check oil level in transmission & top-up if required	797756
214	6/24/2013	411535	Check & clean filter cartridge in dry-type air cleaner	797756
214	6/24/2013	411535	Check power steering oil level	797756
214	6/24/2013	411535	Change pre and main fuel filter	797756
214	6/24/2013	411535	Change air drier cannister; clean silencer & drain air reservoir	797756
214	6/24/2013	411535	Change oil in fan angle drive	797756
214	6/24/2013	411535 assist with safety inspection		797756
214	6/24/2013	411535 Drv entered - Elec & Light Headlights [See printed defect fo		797756
214	6/19/2013	410968 Drv entered - Elec & Light Headlights [See printed def	cleaned by josh	796313
214	6/18/2013	410733 replace l/s mirror and bracket	replaced mirror and bracket	796148
214	6/15/2013	410300	Clean A/C filter.	795140
214	6/15/2013	410300	Rotate Rear Axle Tyres Left to Right - MT & IBS only	795140
214	6/15/2013	410300	Rotate Front Axle Tyres Left to Right - MT & IBS only	795140
214	6/15/2013	410300	Tension Wheel Nuts	795140
214	6/15/2013	410300	Perform & Complete TSV Bus Safety Inspection	795140
214	6/15/2013	410300 AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		795140
214	6/5/2013	408894 Drv entered - Other [See printed defect for more info]	reseal front windscreen remove old sealer clean and replace sealer	791962
214	6/4/2013	408612 Drv entered - Other	no fault found	791962
214	6/4/2013	408611 Drv entered - Elec & Light Headlights	all in good order	791962
214	6/4/2013	408610 Drv entered - Elec & Light Headlights [See printed def	all in good order	791962
214	6/3/2013	408834 Perform Campaign as per Instructions Ensure that app	checked and backing decal fitted	791962
214	6/1/2013	408332 Ops Entered - Fault - Passenger Doors Not Operating -	Checked front door not closing replaced bircha pressure switch and	790899
214	6/1/2013	413311 suspension valve 50y2515wabco	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P126586 Receiving #	800459
214	5/29/2013	407759 ROCKER COVER GASKET 0500LE	Rocker Cover Gasket	790315
214	5/29/2013	407759	Adjust Tappets	790315
214	5/29/2013	407755 Drv entered - Other [See printed defect for more info]	checked ok	788492
214	5/29/2013	407755		788492
214	5/29/2013	407755	A Service Carried out A service as per schedule.	788492
214	5/29/2013	407755	Clean A/C filter	788492
214	5/29/2013	407755	Grease AC Compressor Clutch Bearing	788492
214	5/29/2013	407755	Tension Wheel Nuts To OEM Specification	788492
214	5/27/2013	407461 Drv entered - Other	no action	789570
214	5/27/2013	407459 Drv entered - Other	no action	789570
214	5/23/2013	407414 Drv entered - Other		788492
214	5/23/2013	407414 Drv entered - Other		788492
214	5/23/2013	407414 Drv entered - Other		788492
214	5/23/2013	407414 Drv entered - Other		788492
214	5/23/2013	407414 HALDEX COIL KIT 0500LE	Coil Kit	788492
214	5/23/2013	407414 DRAIN VALVE KIT BOTTOM	Valve Kit	788492
214	5/23/2013	407414 HALDEX COIL BASE OIL SEPERATOR	Base	788492
214	5/23/2013	407414 CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	788492
214	5/23/2013	407414	Re-kit Air Cyclone Separator	788492
214	5/21/2013	406070 Mechanic entered - Passenger Doors Require Adjuste	Adjusted the sencitive edge of fr pass door and checked for operatic	787011
214	5/21/2013	406070 Drv entered - Elec & Light Headlights	Checked all in good working order.	787011
214	5/20/2013	405261 BALANCE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124327 Receiving #:125	789942
214	5/20/2013	405261 11R22.5-A GRADE CASE CHG	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124327 Receiving #:125	789942
214	5/20/2013	405261 FITTING TRUCK	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124327 Receiving #:125	789942
214	5/20/2013	405261 SP 11R22.5 SP327 8A GRADE CASE	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124327 Receiving #:125	789942
214	5/20/2013	405261 DP 11R22.5 148/145L TL SP350A	Creditor #:PT-BEA001 BEAUREPAIRES P/O #:P124327 Receiving #:125	789942

214	5/20/2013	406070 SWAY BAR DROP ARM	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P124532 Receiving #	787748
214	5/17/2013	406070 Mechanic entered - Suspension Noisy	o/s/f sway bar u/s a lot of up and movement and noisy when driving	785550
214	5/17/2013	405872 Mechanic entered - Elec & Light Park Lights o/s top u/ repaired wiring		785550
214	5/16/2013	405844 GLOBE 24V 5W BAYONETT		785550
214	5/16/2013	405844 OS top parker U/S	replaced globe	785550
214	5/14/2013	405484 RETOURQE WHEELS TO 670 NM	Retension wheel nuts	784787
214	5/14/2013	405371 Ops Entered - Fault - Body & Acc Drivers Seat Mount -	repaired wheel rest spring	784787
214	5/13/2013	405200	Clean A/C filter.	784494
214	5/13/2013	405200	Rotate Rear Axle Tyres Left to Right - MT & IBS only	784494
214	5/13/2013	405200	Rotate Front Axle Tyres Left to Right - MT & IBS only	784494
214	5/13/2013	405200	Tension Wheel Nuts	784494
214	5/13/2013	405200	Perform & Complete TSV Bus Safety Inspection	784494
214	5/13/2013	405261 REPLACE WORN TYRES POS 1 3&4	replaced n/s front tyre and o/s rear both tyres	784494
214	5/13/2013	405166 LH parker out	re checked ok	784494
214	5/13/2013	405166 GLOBE WEDGE 24V/5W		784494
214	5/13/2013	405166 LH parker out		784494
214	5/13/2013	405196 till pin needs replacing	manufacture and fit new till pin	784494
214	5/6/2013	404245 HEADER TANK	Creditor #:PT-MUL001 MULTISPARES LTD P/O #:P123916 Receiving #	787748
214	5/6/2013	404245 header tank u/s	Breakdown at Karingul S/C. Header tank pipe broken. Temp repair &	782199
214	4/24/2013	402527 Ops Entered - Fault - Heat & Demist Demisters Cold -	opened taps and tested all ok	778086
214	4/24/2013	402636 Mechanic entered - Air System Leaking	replace oring on air dryer	778086
214	4/22/2013	401691 SWAY BAR DROP ARM REAR 0500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:P123075 Receiving #:12	777758
214	4/19/2013	401862 Retension n/s/r wheel nuts 600nm.	Retentioned N/S/R wheel nuts.	775779
214	4/18/2013	401691 N/R sway bar lime rust from joint	Replaced N/S/R swaybar drop arm.	775779
214	4/18/2013	401691 Mechanic entered - Suspension Noisy		775779
214	4/18/2013	401691 Mechanic entered - Suspension Noisy N/S rear sway bar drop a		775779
214	4/18/2013	401691 Drv entered - Other [See printed defect for more information		775779
214	4/18/2013	401691 Drv entered - Other [See printed defect for more information		775779
214	4/18/2013	401691 Mechanic entered - Eng Cool Leaking		775779
214	4/18/2013	401753 intercooler hose o/s u/s (spring support)	Replaced turbo intercooler pipe	775779
214	4/18/2013	401607 RED MALE BULLET TERMINAL	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P123084 Receiving #	777758
214	4/18/2013	401607 battery cable	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P123084 Receiving #	780150
214	4/18/2013	401607 RED MALE BULLET TERMINAL	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P123084 Receiving #	780150
214	4/18/2013	401607 RED FEMALE BLADE TERMINAL	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P123084 Receiving #	780150
214	4/18/2013	401607 BLUE FEMALE BLADE TERMINAL(100	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P123084 Receiving #	780150
214	4/18/2013	401691 lumbar wont go backwithout force. Seat bottoms out	Checked all works OK.	775779
214	4/18/2013	401691 security pin for till missing		775779
214	4/18/2013	401691 Drv entered - Body & Acc Water Leak [See printed defect for		775779
214	4/18/2013	401713		775779
214	4/18/2013	401713	A Service & Bus Safety Inspection	775779
214	4/18/2013	401713	D-Service & Bus Safety Inspection	775779
214	4/18/2013	401713 AIR FILTER MERC 0500LE		775779
214	4/18/2013	401713	Replace Engine Oil Breather Kit	775779
214	4/18/2013	401713 ENGINE OIL BREATHER KIT 0500LE		775779
214	4/18/2013	401713 OIL FILTER 1725+0500LE		775779
214	4/18/2013	401713 ENGINE OIL DELO 400LE 15W40		775779
214	4/18/2013	401713	Tension Wheel Nuts to Spec	775779
214	4/18/2013	401713		775779
214	4/18/2013	401713	A Service	775779
214	4/18/2013	401713	Clean A/C filter	775779
214	4/18/2013	401713	Grease AC Compressor Clutch Bearing	775779
214	4/18/2013	401713	Tension Wheel Nuts To OEM Specification	775779
214	4/17/2013	401543 hose A0249970382	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P123026 Receiving #	777758
214	4/17/2013	401543 dump stops A6293200077	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P123026 Receiving #	777758
214	4/17/2013	401543 intercooler hose o/s u/s (spring support)	REPLACED HOSE	775779
214	4/17/2013	401607 Drv entered - Body & Acc Drivers Seat Controls [See p as w/o 401605		775779
214	4/17/2013	401606 Drv entered - Body & Acc Drivers Seat ControlsThe lur as per w/o 401605		775779
214	4/17/2013	401605 Drv entered - Body & Acc Drivers Seat Cushion [See pi replaced bottom part by ross		775779
214	4/12/2013	400995		775246
214	4/12/2013	400995 GLOBE S/CONTACT 24V-10W		775246
214	4/12/2013	400995	Rotate Front Axle Tyres Left to Right - MT & IBS only	775246
214	4/12/2013	400995	Clean A/C filter.	775246
214	4/12/2013	400995	Rotate Rear Axle Tyres Left to Right - MT & IBS only	775246
214	4/12/2013	400995	Tension Wheel Nuts	775246
214	4/12/2013	400995	Perform & Complete TSV Bus Safety Inspection	775246
214	4/10/2013	400444 Drv entered - Other [See printed defect for more info	Defect # 422392 noise from front left wheel. ~ Checked king pin for m	774365
214	3/27/2013	398801	Bus Safety Inspection	770274
214	3/27/2013	398801 FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	770274

214	3/27/2013	398801 ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	770274
214	3/27/2013	398801	Service T - Replace Transmission Oil & Filter	770274
214	3/21/2013	397973 Drv entered - Suspension Noisy [See printed defect fo	Checked for any loose components in suspension found front O/S ar	768386
214	3/21/2013	397972 sounds like brakes are slightly on-squeals while drivin	Checked brake pad thickness on all four brakes pads in good conditi	768386
214	3/19/2013	398212 Drv entered - Air System Losing Air [See printed defec	check air system for leaks found air leak at front door brake switch ti	768012
214	3/18/2013	397303 Drv entered - Wipers & Washers Other [See printed d	Tightend O/S wiper arm mount nut Replaced N/S wiper insert.	767217
214	3/18/2013	397303 1MT MULTI FIT WIPER REFILL	Tightend O/S wiper arm mount nut Replaced N/S wiper insert.	767217
214	3/18/2013	397304 Drv entered - Elec & Light Headlights [See printed def	Checked head lights both working and bright alignment O.K for servi	767217
214	3/14/2013	397398 pass seat squab loose	seat repaired	767217
214	3/8/2013	396496	Perform & Complete TSV Bus Safety Inspection	764875
214	3/8/2013	396496	Tension Wheel Nuts	764875
214	3/8/2013	396496	Rotate Front Axle Tyres Left to Right - MT & IBS only	764875
214	3/8/2013	396496	Rotate Rear Axle Tyres Left to Right - MT & IBS only	764875
214	3/8/2013	396496	Clean A/C filter.	764875
214	3/8/2013	396496 GLOBE H1 24V 70W	Repalced globe	764875
214	3/8/2013	396496 rh headlight globe out& ramp light out	Repalced globe	764875
214	3/8/2013	396496 GLOBE WEDGE 24V 1.2W	Repalced globe	764875
214	3/6/2013	395771 ONE PIECE WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P121212 Receiving #:12	769632
214	3/6/2013	395771 replace winscreen	windscreen replaced by elete windsreens	763927
214	2/26/2013	394650 Ops Entered - Accident - Broken Window-Windscreen	SEE WO/ 394367	761833
214	2/25/2013	394367 rear window	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P120743 Receiving #:12	761833
214	2/25/2013	394367 replace broken rear window	REAR WINDOW REPLACED BY ELETE WINDSCREENS	761569
214	2/25/2013	394349 Drv entered - Steering Other [See printed defect for more in		761569
214	2/25/2013	395771 WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P121800 Receiving #:12	768012
214	2/25/2013	394105 11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P120661 Receivi	762626
214	2/25/2013	394105 FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P120661 Receivi	762626
214	2/22/2013	394146 replaced both n/s rear	replaced tyres	761291
214	2/22/2013	394176 Drv entered - Vandalism Graffiti	cleaned	761291
214	2/22/2013	394204 Drv entered - Vandalism Graffiti	as per w/o 394176	761291
214	2/22/2013	394871 Drv entered - Vandalism Wndow Etch	all done	761569
214	2/22/2013	394871 Drv entered - Vandalism Wndow Etch	ok	761569
214	2/22/2013	394871 Drv entered - Vandalism Graffiti	cleaned	761569
214	2/22/2013	394183 Mechanic entered - Suspension Leaking	Suspension regulator valve and a air line joint rekitted.	761291
214	2/22/2013	394105 AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		761291
214	2/22/2013	394105	Tension Wheel Nuts To OEM Specification	761291
214	2/22/2013	394105	Grease AC Compressor Clutch Bearing	761291
214	2/22/2013	394105	Clean A/C filter	761291
214	2/22/2013	394105	A Service	761291
214	2/21/2013	393914 Drv entered - Vandalism Wndow Etch	cleaned	761152
214	2/21/2013	394019 Mechanic entered - Steering Steering Whl	refitted steering adjuster	761152
214	2/8/2013	391811 FILTER DRIER THERMO KING		756730
214	2/8/2013	391811 A/C COMPRESSOR OIL		756730
214	2/5/2013	391811	B Service	755795
214	2/5/2013	391811	Replace filter drier	755795
214	2/5/2013	391811	Replace compressor oil	755795
214	2/5/2013	391811	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	755795
214	2/5/2013	391811	CONDENSOR AREA: Clean condensor coils; check boltsclamps for ten	755795
214	2/5/2013	391811	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	755795
214	2/5/2013	391811	EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	755795
214	2/5/2013	391811	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	755795
214	2/5/2013	391811	COMPRESSOR: Carry out efficiency test; check unloader control; che	755795
214	2/5/2013	391811	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	755795
214	2/5/2013	391811	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	755795
214	2/5/2013	391811	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	755795
214	2/5/2013	391811	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	755795
214	2/5/2013	391811	Clean R/A & F/A filters; Inspect and report on condition; Replace filte	755795
214	2/4/2013	391468	Perform & Complete TSV Bus Safety Inspection Carried out saftey ins	754913
214	2/4/2013	391468	Tension Wheel Nuts	754913
214	2/4/2013	391468	Clean A/C filter.	754913
214	2/3/2013	391439 replace air fitting kit on 6 way valve	replaced fitting kits	754913
214	1/21/2013	389542 leaking coolant	repaired leak on radiator hose clamp	751361
214	1/21/2013	389591 Coolant leak	check and tighten radiator top hose	751361
214	1/21/2013	389542 Coolant leak		751361
214	1/18/2013	388860 Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P119025 Receivi	752073
214	1/18/2013	388860 FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P119025 Receivi	752073
214	1/18/2013	388860 BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P119025 Receivi	752073
214	1/16/2013	388860 O/S/F tyre low 2.5mm	Replaced O/S front tyre road test and retension wheel nuts.	749601
214	1/16/2013	387979 BRAKE PADS M/B 0500LE (49G7501)		749601

214	1/9/2013	387979	Perform & Complete TSV Bus Safety Inspection	747666
214	1/9/2013	387979	Tension Wheel Nuts	747666
214	1/9/2013	387979	Rotate Front Axle Tyres Left to Right - MT & IBS only	747666
214	1/9/2013	387979	Rotate Rear Axle Tyres Left to Right - MT & IBS only	747666
214	1/9/2013	387979	Clean A/C filter.	747666
214	1/9/2013	387979	AIR DRIER KIT MERCEDES 0500LE	747666
214	1/9/2013	387979	Complete Campaign 16/12 as required	747666
214	1/9/2013	387979	Re-kit Air Cyclone Separator	747666
214	1/9/2013	387979	CYCLONE CONDENSER VALVE KIT	747666
214	1/9/2013	387979	Condenser Valve Kit.	747666
214	1/9/2013	387979	HALDEX COIL BASE OIL SEPERATOR	747666
214	1/9/2013	387979	Base	747666
214	1/9/2013	387979	DRAIN VALVE KIT BOTTOM	747666
214	1/9/2013	387979	Valve Kit	747666
214	1/9/2013	387979	HALDEX COIL KIT 0500LE	747666
214	1/9/2013	387979	Coil Kit	747666
214	1/9/2013	387979	Tension Wheel Nuts To OEM Specification	747666
214	1/9/2013	387979	Grease AC Compressor Clutch Bearing	747666
214	1/9/2013	387979	Clean A/C filter	747666
214	1/9/2013	387979	A Service	747666
214	1/8/2013	387664	Drv entered - Security Other [See printed defect for more info] written as cash box pin missing...no fault found	747355
214	1/2/2013	387516	Drv entered - Vandalism Other	745855
214	1/2/2013	387521	Drv entered - Vandalism Graffiti	745855
214	12/21/2012	385882	Drv entered - Brakes Noisy [See printed defect for more info] checkedTestdriven no abnormilities found is OK.	741872
214	12/18/2012	385442	GLOBE H1 24V 70W	740724
214	12/18/2012	385442	LH headlight out	740724
214	12/17/2012	384704	SP 11R22.5 SP327 A GRADE CASE	742195
214	12/17/2012	384704	FITTING	742195
214	12/17/2012	384704	11R22.5 - A GRADE CASE CHG	742195
214	12/15/2012	385195	LH parker out	740508
214	12/15/2012	385195	GLOBE WEDGE 24V/5W	740508
214	12/12/2012	384704	Tension Wheel Nuts	738666
214	12/12/2012	384704	Rotate Front Axle Tyres Left to Right - MT & IBS only	738666
214	12/12/2012	384704	Rotate Rear Axle Tyres Left to Right - MT & IBS only	738666
214	12/12/2012	384704	Clean A/C filter.	738666
214	12/12/2012	384699	Perform & Complete TSV Bus Safety Inspection	738666
214	12/12/2012	384699	Tension Wheel Nuts	738666
214	12/12/2012	384699	Rotate Front Axle Tyres Left to Right - MT & IBS only	738666
214	12/12/2012	384699	Rotate Rear Axle Tyres Left to Right - MT & IBS only	738666
214	12/12/2012	384699	Clean A/C filter.	738666
214	12/12/2012	384704	Perform & Complete TSV Bus Safety Inspection	738666
214	12/12/2012	384704	worn x 2	738666
214	12/4/2012	383911	Air leak	736245
214	12/4/2012	383911	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	736245
214	11/29/2012	381673	11R22.5 SP327 P/C RTD	734794
214	11/29/2012	381673	FITTING	734794
214	11/26/2012	382338	Water pump inspection hole leaking. Thermostat housing gaske	733790
214	11/26/2012	382338	Water pump inspection hole leaking. Thermostat housing gask	733790
214	11/23/2012	382338	WATER PUMP	733790
214	11/20/2012	381673	Creditor #:MUL001 MULTISPARES LTD P/O #:P116865 Receiving #:11	733790
214	11/20/2012	381673	Grease AC Compressor Clutch Bearing	731835
214	11/20/2012	381673	Tension Wheel Nuts to Spec	731835
214	11/20/2012	381673	A Service & Bus Safety Inspection	731835
214	11/20/2012	381673	D-Service & Bus Safety Inspection	731835
214	11/20/2012	381673	ENGINE OIL DELO 400LE 15W40	731835
214	11/20/2012	381673	OIL FILTER 1725+0500LE	731835
214	11/20/2012	381673	AIR FILTER MERC 0500LE	731835
214	11/20/2012	381673	ENGINE OIL BREATHER KIT 0500LE	731835
214	11/20/2012	381673	A Service	731835
214	11/20/2012	381673	Clean A/C filter	731835
214	11/20/2012	381673	Grease AC Compressor Clutch Bearing	731835
214	11/20/2012	381673	Tension Wheel Nuts To OEM Specification	731835
214	11/13/2012	379376	AIR CON REFRIDGERANT	729655
214	11/4/2012	379572	repair n/s indicator	726796
214	11/2/2012	379376	Drv entered - Vandalism Graffiti	726796
214	11/2/2012	379376	Drv entered - Air Cond Air Conditioner [See printed defect	726796
214	11/2/2012	379379	Drv entered - Passenger Doors Other [See printed def no fault found no fault found	725957
214	11/2/2012	379379	Service	725957
214	11/2/2012	379381	Drv entered - Heat & Demist Heater Cold	725957
214	11/2/2012	379380	Drv entered - Heat & Demist Demisters Cold	725957
214	11/2/2012	379377	Drv entered - Gearbox Faulty Selector [See printed de vary hard to select neutral swapped gear shift selctor	725957
214	11/2/2012	379376	Drv entered - Other [See printed defect for more informatio	726796

214	11/2/2012	379376	Drv entered - Comm Equip Other [See printed defect for more		726796
214	11/2/2012	379376	Drv entered - Comm Equip Distortion		726796
214	11/2/2012	379376	Windscreen rubber on O/S coming away from body		726796
214	11/2/2012	379378	Windscreen rubber on O/S coming away from body	REFFITTED WINDSCREEN RUBBER	725957
214	11/2/2012	379376	Brake solenoid leaking air		726796
214	11/1/2012	379268	Drv entered - Ticket Equip VAL	reported to operations	725957
214	11/1/2012	379355	Windscreen rubber on O/S coming away from body	refit windscreen rubber	725957
214	11/1/2012	382344	Windscreen rubber on O/S coming away from body		726316
214	10/30/2012	378749	low water sender faulty		724970
214	10/29/2012	378749	LOW WATER PROBE 500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:P115831 Receiving #:11	728330
214	10/29/2012	378577	replace low water sender		724970
214	10/29/2012	378577	LOW WATER PROBE 500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:P115760 Receiving #:11	725580
214	10/25/2012	377886	fan motors	Creditor #:DAN013 DANDENONG RADIATOR SERVICE P/L P/O #:P1157	724530
214	10/23/2012	377886	Drv entered - Air Cond Air Conditioner [See printed defect for more	Replace right bank evap fan. Remove scale from fins	723432
214	10/16/2012	376755	refit steering adjuster cylinder		721793
214	10/4/2012	374672	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P114551 Receiving #:	723063
214	10/4/2012	374672	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P114551 Receiving #:	723063
214	10/4/2012	374672	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P114551 Receiving #:	723063
214	10/4/2012	374672	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P114551 Receiving #:	723063
214	10/3/2012	374938	Water pump leaking		718007
214	10/3/2012	374938	Ops Entered - Fault - Body & Acc Destination Blind - F	repaired drivers blind. also repaired water leak from boost pump ho	718007
214	10/1/2012	374797	Drv entered - Brakes Losing Air	Replaced N/S rear brake chamber with a new unit & tested.	717562
214	9/29/2012	374670		Clean A/C filter.	717562
214	9/29/2012	374670		Perform & Complete TSV Bus Safety Inspection	717562
214	9/29/2012	374670		Tension Wheel Nuts	717562
214	9/29/2012	374670		Rotate Front Axle Tyres Left to Right - MT & IBS only	717562
214	9/29/2012	374670		Rotate Rear Axle Tyres Left to Right - MT & IBS only	717562
214	9/29/2012	374672	replace n/s rear tyres and n/s front		717562
214	9/29/2012	374670		Tension Wheel Nuts To OEM Specification	717562
214	9/29/2012	374670		Grease AC Compressor Clutch Bearing	717562
214	9/29/2012	374670		Clean A/C filter	717562
214	9/29/2012	374670		A Service	717562
214	9/25/2012	373868	Ops Entered - Fault - Eng Cool Leaking - Route: -	repaired as per w/o 373838	716668
214	9/25/2012	373838	radiataor coolant leak		716668
214	9/25/2012	373838	CUSHION EXHAUST PIPE		716668
214	9/25/2012	373838	RADIATOR	Creditor #:MUL001 MULTISPARES LTD P/O #:P114303 Receiving #:11	716668
214	9/25/2012	373838	radiataor coolant leak		716668
214	9/24/2012	373775	rectify engine coolant leak		716668
214	9/17/2012	372761	drivers vent no air		714152
214	9/17/2012	372761	Drv entered - Engine Other [See printed defect for more	Repaired bot. alt. belt tightning rodReplaced belt & adjusted.	714152
214	9/17/2012	372761	Mechanic entered - Elec & Light Other	Replace n/s clearance light assy rear.	714152
214	9/15/2012	372557	replace alt belt		714152
214	8/22/2012	369238	Needs wheel alignment	Rotated front tyres. Bus stoped pulling to left sudden but pulls to th	707215
214	8/21/2012	368942		Perform & Complete TSV Bus Safety Inspection .Carried out inspectic	707215
214	8/21/2012	368942		Tension Wheel Nuts	707215
214	8/21/2012	368942		Rotate Front Axle Tyres Left to Right - MT & IBS only	707215
214	8/21/2012	368942		Rotate Rear Axle Tyres Left to Right - MT & IBS only	707215
214	8/21/2012	368942		Clean A/C filter.	707215
214	8/21/2012	368942	EXHAUST BRAKE SOLENOID 0500	Creditor #:MUL001 MULTISPARES LTD P/O #:P112641 Receiving #:11	712165
214	8/21/2012	368020	steering column covers	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P112326 Receiving #	707215
214	8/21/2012	368020	shell	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P112326 Receiving #	707215
214	8/21/2012	368942	bottom front rad mount u/s cotton reel type		707215
214	8/21/2012	369064	replace n/s body decals		706769
214	8/21/2012	369064	BODY DECALS NS PANELS 2 3 4 5	Creditor #:ATT001 ATTITUDE SIGNS P/O #:P113290 Receiving #:1136	711170
214	8/15/2012	368020	Drv entered - Steering Other steering columb covers broken		705448
214	8/8/2012	367270	Drv entered - Wipers & Washers Missing	Replaced N/S wiper blade assywiper motorWasher jet adjusted testi	704390
214	8/8/2012	367270	BLADE WIPER 1MTR		704390
214	8/8/2012	367270	PUMP WIPER-WASHER 24 VOLT		704390
214	8/3/2012	364612	STOP LAMP DURALED L.E.D	Creditor #:MUL001 MULTISPARES LTD P/O #:P111231 Receiving #:11	703347
214	7/31/2012	366016		Tension Wheel Nuts To OEM Specification	701860
214	7/31/2012	366016		Carried out service as per scedule.	701860
214	7/31/2012	366016	PUMP WIPER-WASHER 24 VOLT		701860
214	7/26/2012	365462	R/H headlight out		700133
214	7/26/2012	365462	GLOBE H1 24V 70W		700133
214	7/24/2012	365147	neutral button does not always work	removed and lubed	699558
214	7/24/2012	365070	Wipers difficult to switch on & off	replace switch with 2nd hand part	699558
214	7/24/2012	365090	Upper & lower lumbar does not work. Both are full in	checked operation of lumber supports all in good working order	699558
214	7/22/2012	364612	Needs stop/tail LED U/S. Hella part 2330v		698900

214	7/20/2012	364888	L/H exterior mirror cracked (top to bottom)		699229
214	7/19/2012	364418	O/S parker U/S		698575
214	7/19/2012	364418	MINATURE GLOBE 24V - 4 W		698575
214	7/13/2012	363550	PAINT PANELS		696726
214	7/9/2012	362400	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P110596 Receiving	701860
214	7/9/2012	362740	repair o/s panels		696726
214	7/6/2012	362400	Annual rsi inspection		696726
214	7/6/2012	362400	Annual rsi inspection		696726
214	7/5/2012	362362	repair side panels		696726
214	7/5/2012	362362	AMBER REFLECTOR		696726
214	7/4/2012	362075	SIDE PANEL REPAIRS		696726
214	7/3/2012	361708	Service		696726
214	7/3/2012	361915	RSI repairs		696726
214	7/3/2012	361915	RSI repairs		696726
214	7/3/2012	361915	RPM BORATE EP LUBE 220	Rear Axle Lube	696726
214	7/3/2012	361915		Replace Rear Axle Oil	696726
214	7/3/2012	361915		Electrical - BATTERIES: check fluid level (leave air gap when topping u	696726
214	7/3/2012	361915		Inspect radiator & charge-air cooler for dirt - clean if required	696726
214	7/3/2012	361915		Check oil level in transmission & top-up if required	696726
214	7/3/2012	361915		Check & clean filter cartridge in dry-type air cleaner	696726
214	7/3/2012	361915		Check power steering oil level	696726
214	7/3/2012	361915		Change pre and main fuel filter	696726
214	7/3/2012	361915		Change air drier cannister; clean silencer & drain air reservoir	696726
214	7/3/2012	361915		Change oil in fan angle drive	696726
214	7/3/2012	361915		Top-up coolant level (must equate to -37C frost protection)	696726
214	7/3/2012		0 Imported Service History	Imported Service History	696726
214	7/2/2012	361797		Tension Wheel Nuts	696726
214	7/2/2012	361797		Rotate Front Axle Tyres Left to Right - MT & IBS only	696726
214	7/2/2012	361797		Perform & Complete TSV Bus Safety Inspection	696726
214	7/2/2012	361797		Clean A/C filter.	696726
214	7/2/2012	361797		Rotate Rear Axle Tyres Left to Right - MT & IBS only	696726
214	7/2/2012	361708		Check oil level in transmission & top-up if required	696726
214	7/2/2012	361708		Check & clean filter cartridge in dry-type air cleaner	696726
214	7/2/2012	361708		Check power steering oil level	696726
214	7/2/2012	361708		Change pre and main fuel filter	696726
214	7/2/2012	361708		Change air drier cannister; clean silencer & drain air reservoir	696726
214	7/2/2012	361708		Change oil in fan angle drive	696726
214	7/2/2012	361708	RPM BORATE EP LUBE 220	Rear Axle Lube	696726
214	7/2/2012	361708		Replace Rear Axle Oil	696726
214	7/2/2012	361708		Electrical - BATTERIES: check fluid level (leave air gap when topping u	696726
214	7/2/2012	361708		Inspect radiator & charge-air cooler for dirt - clean if required	696726
214	7/2/2012	361708		Top-up coolant level (must equate to -37C frost protection)	696726
214	6/12/2012	358838	Radio not working. Lights up but no noise through speakers		691296
214	6/12/2012	358837	Drv entered - Elec & Light Other [See printed defect for mo		691296
214	6/12/2012	358835	Radio AM/FM not working. Could u please fix. I woulc fit new am/fm radio		691296
214	5/31/2012	359746		Re-kit Air Cyclone Separator	688455
214	5/31/2012	359746	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	688455
214	5/31/2012	359746	HALDEX COIL BASE OIL SEPERATOR	Base	688455
214	5/31/2012	359746	DRAIN VALVE KIT BOTTOM	Valve Kit	688455
214	5/31/2012	359746	HALDEX COIL KIT 0500LE	Coil Kit	688455
214	5/30/2012	359744	Service	Adjust Tappets	689799
214	5/30/2012	356615	ALTERNATOR DELCO 24V 180 AMP	Creditor #:MUL001 MULTISPARES LTD P/O #:P108885 Receiving #:10	689799
214	5/28/2012	356615	Drv entered - Elec & Light Battery Flat [See printed defect		688278
214	5/28/2012	356615	Drv entered - Elec & Light Dash		688278
214	5/25/2012	356344	Drv entered - Air System Leaking [See printed defect f	Circuit protection valve replaced tested all OK	687212
214	5/25/2012	356344	CIRCUIT PROTECTION VALVE		687212
214	5/25/2012	356344	AIR LINE FITTING KIT 0500LE AIR DRYER		687212
214	5/18/2012	355487		Clean A/C filter.	686040
214	5/18/2012	355487		Perform & Complete TSV Bus Safety Inspection	686040
214	5/18/2012	355487		Tension Wheel Nuts	686040
214	5/18/2012	355487		Rotate Front Axle Tyres Left to Right - MT & IBS only	686040
214	5/18/2012	355487		Rotate Rear Axle Tyres Left to Right - MT & IBS only	686040
214	5/18/2012	355488		D-Service & Bus Safety Inspection	686040
214	5/18/2012	355488		A Service & Bus Safety Inspection	686040
214	5/18/2012	355488		Tension Wheel Nuts to Spec	686040
214	5/18/2012	355488	ENGINE OIL DELO 400LE 15W40		686040
214	5/18/2012	355488	OIL FILTER 1725+0500LE		686040
214	5/18/2012	355488	AIR FILTER MERC 0500LE		686040

214	5/18/2012	355488		Grease AC Compressor Clutch Bearing	686040
214	5/18/2012	355488		Replace Engine Oil Breather Kit	686040
214	5/18/2012	355488	ENGINE OIL BREATHER KIT 0500LE		686040
214	5/18/2012	355488		A Service	686040
214	5/18/2012	355488		Tension Wheel Nuts To OEM Specification	686040
214	5/18/2012	355488		Grease AC Compressor Clutch Bearing	686040
214	5/18/2012	355488		Clean A/C filter	686040
214	5/10/2012	353628	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P107757 Receiving	685058
214	5/10/2012	353628	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P107757 Receiving	685058
214	5/8/2012	353627	door glass	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P107759 Receiving #:10	686253
214	5/7/2012	353627	replace broken door glass rear half		682428
214	5/3/2012	353628	POS 3 4 5 & 6		681693
214	4/12/2012	350024	Drv entered - Gearbox Faulty Selector [See printed de	checked works OK	674771
214	4/7/2012	349539	REPAIR STEERING COLUME LOCKING MEC		673104
214	3/28/2012	347650	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P105992 Receiving	670922
214	3/28/2012	347650	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P105992 Receiving	670922
214	3/28/2012	347650	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P105992 Receiving	670922
214	3/23/2012	347650		Perform & Complete TSV Bus Safety Inspection	668562
214	3/23/2012	347650		Tension Wheel Nuts	668562
214	3/23/2012	347650		Rotate Front Axle Tyres Left to Right - MT & IBS only	668562
214	3/23/2012	347650		Rotate Rear Axle Tyres Left to Right - MT & IBS only	668562
214	3/23/2012	347650	Drv entered - Gearbox Faulty Selector [See printed defect f		668562
214	3/23/2012	347650	Engine oil dipstick broken		668562
214	3/23/2012	347650		Service T - Replace Transmission Oil & Filter	668562
214	3/23/2012	347650	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	668562
214	3/23/2012	347650		Bus Safety Inspection	668562
214	3/23/2012	347650	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	668562
214	3/23/2012	347650		Grease AC Compressor Clutch Bearing	668562
214	3/23/2012	347650		Clean A/C filter	668562
214	3/23/2012	347650		A Service	668562
214	3/23/2012	347650		Tension Wheel Nuts To OEM Specification	668562
214	3/20/2012	346913	top rad hose leaking		667335
214	2/29/2012	344029		Perform & Complete TSV Bus Safety Inspection	660821
214	2/29/2012	344029		Tension Wheel Nuts	660821
214	2/29/2012	344029			660821
214	2/28/2012	343788	Drv entered - Desto Signs	no fault found	660582
214	2/20/2012	342658	GLOBE 24V 5W BAYONETT		657906
214	2/20/2012	342658	top clearance light out....in header		657906
214	2/14/2012	341603	driver states that the bus is leaking coolant	LH RV mirror smashed replaced & adjusted	656677
214	2/13/2012	341603	driver states that the bus is leaking coolant		656677
214	2/13/2012	341603	A/C BELT 0500 BENZ		656677
214	2/13/2012	341603	TOW BUS TO DEPOT from Dunns Rd	Creditor #:ASS001 ASSOCIATED TOWING P/O #:P104241 Receiving #:	660582
214	2/9/2012	341047	Drv entered - Gearbox Faulty Selector [See printed defect f		655230
214	2/9/2012	341043	Drv entered - Elec & Light Indicators [See printed defect f		655230
214	2/9/2012	341043	Indicators dont cancel	Lubed & checked indicator switch. Self cancel pale has been broken.	655230
214	2/8/2012	341009	door controls faulty	Micro switches had foreign substance plit in them. Cleaned and lube	655230
214	2/8/2012	341009	BELT BOTTOM ALTERNATOR MERC 0500LE		655230
214	2/8/2012	341009	A/C BELT 0500 BENZ		655230
214	2/8/2012	340923	GLOBE WEDGE 24V/5W		655230
214	2/8/2012	340923	L/H front bottom park light out	found blown parker globe replace with new one check ok	655230
214	2/4/2012	340358		Perform & Complete TSV Bus Safety Inspection	653902
214	2/4/2012	340358		Tension Wheel Nuts	653902
214	2/4/2012	340357	Drv entered - Wipers & Washers Washers Not Working		654287
214	2/4/2012	340357	Drv entered - Passenger Doors Noisy [See printed defect for		654287
214	2/4/2012	340357	Drv entered - Heat & Demist No Heaters		654287
214	2/4/2012	340357	Drv entered - Other [See printed defect for more informatio		654287
214	2/4/2012	340357	Static noise; very annoying and loud from speakers		654287
214	2/4/2012	340357	Lumbar controls wont inflate or deflate		654287
214	2/4/2012	340357		Clean A/C filter	654287
214	2/4/2012	340357		Tension Wheel Nuts To OEM Specification	654287
214	2/4/2012	340357		Grease AC Compressor Clutch Bearing	654287
214	2/4/2012	340357		A Service	654287
214	2/4/2012	340357	PUMP WIPER-WASHER 24 VOLT		654287
214	1/31/2012	339513	Wiper ar loose	Tightened	653123
214	1/31/2012	339513	Ops Entered - Fault - Wipers & Washers - Route: 784 - Osbo		653123
214	1/27/2012	338688	FILTER DRIER THERMO KING		651827
214	1/27/2012	338688	evap fan motor		651827
214	1/27/2012	338688	AIR CON REFRIDGERANT		651827

214	1/25/2012	338885 engine dip sticks	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P103385 Receiving #	651341
214	1/24/2012	338688 Drv entered - Cool & AC Sys Other [See printed defect for m		651098
214	1/24/2012	338688 Air con not working	Replace all left evap motors	651098
214	1/24/2012	338688 A/c not working properly		651098
214	1/24/2012	338688	C Service	651098
214	1/24/2012	338688	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	651098
214	1/24/2012	338688	CONDENSOR AREA: Clean condenser coils; check bolts/clamps for ten	651098
214	1/24/2012	338688	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	651098
214	1/24/2012	338688	EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	651098
214	1/24/2012	338688	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	651098
214	1/24/2012	338688	COMPRESSOR: Carry out efficiency test; check unloader control; che	651098
214	1/24/2012	338688	Clean R/A & F/A filters; Inspect and report on condition; Replace filte	651098
214	1/24/2012	338688	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	651098
214	1/24/2012	338688	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	651098
214	1/24/2012	338688	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	651098
214	1/24/2012	338688	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	651098
214	1/10/2012	333496 FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P101827 Receivi	647070
214	1/10/2012	333496 11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P101827 Receivir	647070
214	1/9/2012	336207 DP 11R22.5 148/145L TL SP350A	Creditor #:BEA001 BEAUREPAIRES P/O #:P102654 Receiving #:10389	649215
214	1/9/2012	336207 Fitting	Creditor #:BEA001 BEAUREPAIRES P/O #:P102654 Receiving #:10389	649215
214	1/9/2012	336207 BALANCE BUS-	Creditor #:BEA001 BEAUREPAIRES P/O #:P102654 Receiving #:10389	649215
214	1/9/2012	336337 annual inspection	e136634	646511
214	1/5/2012	336018		645483
214	1/5/2012	336018	Tension Wheel Nuts	645483
214	1/5/2012	336018	Perform & Complete TSV Bus Safety Inspection	645483
214	1/5/2012	336207 replace damaged n/s front tyre		645793
214	1/5/2012	335999 replace o/s front tyre..new		645483
214	1/5/2012	336124 Drv entered - Passenger Doors Faulty Controls	checked pass doors and controls no fault found.	645483
214	1/5/2012	334045 o ring air pipe small 50z0115	Creditor #:MUL001 MULTISPARES LTD P/O #:PR102040 Receiving #:1	645793
214	12/28/2011	335018 alt light on	Rectified sh circuit in top Altbrushes replaced tested OK	642831
214	12/19/2011	334045 Drv entered - Air System Losing Air [See printed defec	removed overhauled and installed air dryer	641231
214	12/19/2011	334045 PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		641231
214	12/19/2011	334045 AIR DRYER UNLOADER KIT		641231
214	12/19/2011	334045 AIR DRYER CANISTER VOLVO+ NL202		641231
214	12/14/2011	333496	D-Service & Bus Safety Inspection	639944
214	12/14/2011	333496	A Service & Bus Safety Inspection	639944
214	12/14/2011	333496	Tension Wheel Nuts to Spec	639944
214	12/14/2011	333496	Grease AC Compressor Clutch Bearing	639944
214	12/14/2011	333496	Replace Engine Oil Breather Kit	639944
214	12/14/2011	333496	Carry out service as per schedule.	639944
214	12/14/2011	333496 ENGINE OIL DELO 400LE 15W40		639944
214	12/14/2011	333496 OIL FILTER 1725+0500LE		639944
214	12/14/2011	333496 AIR FILTER MERC 0500LE		639944
214	12/14/2011	333496 ENGINE OIL BREATHER KIT 0500LE		639944
214	12/14/2011	333496 GLOBE H1 24V 70W		639944
214	12/14/2011	333496	Tension Wheel Nuts To OEM Specification	639944
214	12/14/2011	333496	Grease AC Compressor Clutch Bearing	639944
214	12/14/2011	333496	Clean A/C filter	639944
214	12/14/2011	333496	A Service	639944
214	12/6/2011	332305 Drv entered - Elec & Light Battery Flat [See printed de	Replaced both batteries checked OK	637800
214	12/6/2011	332305 BATTERY 12V 190 AMP 1000CCA		637800
214	11/30/2011	331046 11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P101013 Receivi	640639
214	11/30/2011	331046 FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P101013 Receivi	640639
214	11/25/2011	331046	Tension Wheel Nuts	634700
214	11/25/2011	331046	Perform & Complete TSV Bus Safety Inspection	634700
214	11/25/2011	331045 DRAIN VALVE KIT BOTTOM	Valve Kit	634700
214	11/25/2011	331045 HALDEX COIL KIT 0500LE	Coil Kit	634700
214	11/25/2011	331045 WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	Water Seperator Kit	634700
214	11/25/2011	331045	Re-kit Air Cyclone Separator	634700
214	11/25/2011	331045 HALDEX COIL BASE OIL SEPERATOR	Base	634700
214	11/15/2011	329198 Drv entered - Elec & Light Other [See printed defect for mor		630820
214	11/15/2011	329198 GLOBE H1 24V 70W		630820
214	11/14/2011	328956 Drv entered - Engine Other [See printed defect for mc	Top alt belt replaced ok	630820
214	11/14/2011	328956 TOP ALT BELT 0500LE		630820
214	11/7/2011	327835 Ops Entered - Fault - Suspension - Route: - Arrive Se	n/s front and o/s rear sway bars need replacement	627938
214	10/28/2011	326817	Perform & Complete TSV Bus Safety Inspection	625596
214	10/28/2011	326817	Tension Wheel Nuts	625596
214	10/28/2011	326816	Tension Wheel Nuts To OEM Specification	625596

214	10/28/2011	326816		Grease AC Compressor Clutch Bearing	625596
214	10/28/2011	326816		Clean A/C filter	625596
214	10/28/2011	326816		A Service	625596
214	10/17/2011	324744	Drv entered - Passenger Doors Faulty Controls	adjusted and lubed rear pass door	621005
214	10/11/2011	323883	Drv entered - Elec & Light Reverse Lights [See printed	Install reverse buzzer.	619527
214	10/11/2011	323883	NARVA 24V REVERSING BUZZER		619527
214	9/30/2011	322369		Perform & Complete TSV Bus Safety Inspection	616270
214	9/30/2011	322369		Tension Wheel Nuts	616270
214	9/27/2011	321695	Ops Entered - Fault - Body & Acc - Route: - Arrive Hasting		615297
214	9/22/2011	321216	L/H W/S washer jets missing....fitted made up jet		613870
214	9/21/2011	320828	Drv entered - Air System Leaking [See printed defect for mo		613523
214	9/12/2011	319290	repair broken alt adjusting bolt bracket		610702
214	9/12/2011	319020	AIR LINE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P97720 Receiving #:	610702
214	9/12/2011	319020	AIR LINE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P97720 Receiving #:	610702
214	9/12/2011	319152		Grease AC Compressor Clutch Bearing	610702
214	9/12/2011	319152		Clean A/C filter	610702
214	9/12/2011	319152		Tension Wheel Nuts To OEM Specification	610702
214	9/9/2011	319020	AIR LEAK FROM AIR DRYER LINE	Replaced rubbed through air line. Cleaned & replaced 2 fitting seals.	610520
214	9/7/2011	318406	Drv entered - Heat & Demist Heater Cold		609447
214	9/7/2011	318407	Drv entered - Heat & Demist Heater Cold		609447
214	9/7/2011	318408	Drv entered - Heat & Demist No Heaters		609447
214	9/7/2011	318409	Drv entered - Heat & Demist Heater Cold		609447
214	9/1/2011	317445		Perform & Complete TSV Bus Safety Inspection	607627
214	9/1/2011	317445		Tension Wheel Nuts	607627
214	9/1/2011	317445			607627
214	8/30/2011	317121	L/H side indicator globe		607392
214	8/30/2011	317121	GLOBE INDICATOR 24V-18W SINGLE CONTACT		607392
214	8/25/2011	316279	Front stabiliser drop arm ball joints U/S		605692
214	8/20/2011	315475	TOP ALT BELT 0500LE	Creditor #:BUR001 BURSON AUTO PARTS P/O #:P96874 Receiving #:	605897
214	8/20/2011	315475	replace top alt belt		603652
214	8/20/2011	315475	TOP ALT BELT 0500LE		603652
214	8/18/2011	315076	Drv entered - Vandalism Graffiti [See printed defect for	CLEANEDOK	602891
214	8/18/2011	314971	Drv entered - Elec & Light Park Lights	Adjusted F/O/S headlight Checked all ok	602891
214	8/10/2011	313194	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P96311 Receiving	605323
214	8/10/2011	313194	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P96311 Receiving	605323
214	8/10/2011	313194	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P96311 Receiving	605323
214	8/8/2011	313194	replaced o/s front tyre		566212
214	8/8/2011	313174	replaced n/s head light globe		566212
214	8/8/2011	313174	GLOBE H1 24V 70W		566212
214	8/8/2011	313130	Drv entered - Air System Losing Air [See printed defect	ex brake solinoid leaking..	595046
214	8/7/2011	313299			599654
214	8/7/2011	313299	GLOBE INDICATOR 24V-18W SINGLE CONTACT		599654
214	8/7/2011	313299	SIDE INDICATOR L/H		599654
214	7/28/2011	311119	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P95679 Receiving	601483
214	7/28/2011	311119	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P95679 Receiving	601483
214	7/28/2011	311119	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P95679 Receiving	601483
214	7/28/2011	311119	Tred low & side wall scrubbed		595046
214	7/27/2011	311598	BATTERY 12V 190 AMP 1000CCA		595815
214	7/27/2011	311598	test and replace batterys		595815
214	7/27/2011	311575	AIR FILTER MERC 0500LE		595815
214	7/27/2011	311575	OIL FILTER 1725+0500LE		595815
214	7/27/2011	311575		Replace engine oil breather kit	595815
214	7/27/2011	311575		Grease AC Compressor Clutch Bearing	595815
214	7/27/2011	311575		Tension Wheel Nuts to Spec	595815
214	7/27/2011	311575		A Service & Bus Safety Inspection	595815
214	7/27/2011	311575		D-Service & Bus Safety Inspection	595815
214	7/27/2011	311575			595815
214	7/27/2011	311575	ENGINE OIL BREATHER KIT 0500LE		595815
214	7/27/2011	311575	ENGINE OIL DELO 400LE 15W40		595815
214	7/27/2011	311575			595815
214	7/27/2011	311575		Grease AC Compressor Clutch Bearing	595815
214	7/27/2011	311575		Clean A/C filter	595815
214	7/27/2011	311575		Tension Wheel Nuts To OEM Specification	595815
214	7/27/2011	311575		A Service	595815
214	7/25/2011	308785	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P94977 Receiving	595046
214	7/21/2011	307676	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P94667 Receiving	593950
214	7/21/2011	307676	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P94667 Receiving	593950
214	7/20/2011	316287	HALDEX COIL KIT 0500LE	Coil Kit	593623

214	7/20/2011	316287	DRAIN VALVE KIT BOTTOM	Valve Kit	593623
214	7/20/2011	316287	HALDEX COIL BASE OIL SEPERATOR	Base	593623
214	7/20/2011	316287	WATER SEPERATOR SCANIA+VOLVO+MB (HAL90364)	Water Seperator Kit	593623
214	7/20/2011	316287		Re-kit Air Cyclone Separator	593623
214	7/14/2011	309514	Ops Entered - Fault - Whls & Tyres - Route: - Take a Rigid		591067
214	7/8/2011	308783		Change oil in fan angle drive	589531
214	7/8/2011	308783		Change pre and main fuel filter	589531
214	7/8/2011	308783		Change air drier cannister; clean silencer & drain air reservoir	589531
214	7/8/2011	308783		Top-up coolant level (must equate to -37C frost protection)	589531
214	7/8/2011	308783		Adjust Engine Valve Clearance	589531
214	7/8/2011	308783	Road Safety Inspection		589531
214	7/8/2011	308783		Electrical - BATTERIES: check fluid level (leave air gap when topping u	589531
214	7/8/2011	308783		Inspect radiator & charge-air cooler for dirt - clean if required	589531
214	7/8/2011	308783		Check oil level in transmission & top-up if required	589531
214	7/8/2011	308783		Check & clean filter cartridge in dry-type air cleaner	589531
214	7/8/2011	308783		Check power steering oil level	589531
214	7/8/2011	308785	annaul inspection		589531
214	7/6/2011	307630	Front suspension is very hard the bus doesnt ride over bumps		589531
214	7/5/2011	308024	AMBER REFLECTOR	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P94759 Receiving #:	597767
214	7/4/2011	308024	Accident Damaged # 32469 R/R. n/s/f. wheel arch brush lowe		589531
214	7/1/2011	307681		Top-up coolant level (must equate to -37C frost protection)	589181
214	7/1/2011	307681	AIR DRYER CANISTER VOLVO+ NL202		589181
214	7/1/2011	307681		Change oil in fan angle drive	589181
214	7/1/2011	307681		Change air drier cannister; clean silencer & drain air reservoir	589181
214	7/1/2011	307681			589181
214	7/1/2011	307681		Change pre and main fuel filter	589181
214	7/1/2011	307681		Check power steering oil level	589181
214	7/1/2011	307681		Check & clean filter cartridge in dry-type air cleaner	589181
214	7/1/2011	307681		Check oil level in transmission & top-up if required	589181
214	7/1/2011	307681		Inspect radiator & charge-air cooler for dirt - clean if required	589181
214	7/1/2011	307681		Electrical - BATTERIES: check fluid level (leave air gap when topping u	589181
214	7/1/2011	307681		Adjust Engine Valve Clearance	589181
214	7/1/2011	307676		replaced o/s rear tyres	589181
214	7/1/2011	307676			589181
214	7/1/2011	307676			589181
214	7/1/2011	307630	Front suspension is very hard the bus doesnt ride over bumps		589181
214	7/1/2011	362740	side panels x 4	Creditor #:VOLGRE VOLGREN AUSTRALIA P/O #:P110652 Receiving #:	700477
214	7/1/2011	307618		A Service	588655
214	7/1/2011	307618		Tension Wheel Nuts To OEM Specification	588936
214	7/1/2011	307618		Grease AC Compressor Clutch Bearing	588936
214	7/1/2011	307618		Clean A/C filter	588936
214	7/1/2011	307618	AIR DRYER CANISTER VOLVO+ NL202		589181
214	7/1/2011	307618			589181
214	7/1/2011	307618	GLOBE WEDGE 24V 1.2W		588936
214	6/30/2011	307418	Needs new washer jet	all in good working order	588655
214	6/25/2011	306790	Drv entered - Wipers & Washers Loose	Tightened the spindal of O/S Wiper armThe washer jet u/s needs a r	587208
214	6/24/2011	316286		Tension wheel nuts	587546
214	6/24/2011	316286		Perform & Complete TSV Bus Safety Inspection	587546
214	6/17/2011	304928	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P93787 Receiving #:	588310
214	6/17/2011	304928	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P93787 Receiving #:	588310
214	6/11/2011	304928	N/S rear worn		582715
214	5/23/2011	301774	S&F ZT SIDE	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P92758 Receiving #:942	579445
214	5/23/2011	301774	N/S rear window cracked		575920
214	5/23/2011	301888	N/S rear window cracked		575920
214	5/21/2011	301681		A Service & Bus Safety Inspection	575511
214	5/21/2011	301681		Tension Wheel Nuts To OEM Specification	575511
214	5/21/2011	301681		Grease AC Compressor Clutch Bearing	575511
214	5/21/2011	301681		Clean A/C filter	575511
214	5/10/2011	299852	replace broken n/s no 4 window		572139
214	5/10/2011	299852	SIDE WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P92128 Receiving #:932	572995
214	5/9/2011	299492	BRAIDED COMPRESSOR PIPE 0500LE	Creditor #:MUL001 MULTISPARES LTD P/O #:P92035 Receiving #:945	581483
214	5/6/2011	299492	GASKET TURBO MOUNT	Creditor #:MUL001 MULTISPARES LTD P/O #:P92012 Receiving #:942	579445
214	5/6/2011	299492	AIR DRYER ASSY	Creditor #:MUL001 MULTISPARES LTD P/O #:P92012 Receiving #:942	579445
214	5/6/2011	299492	replace air dryer assy		571414
214	5/6/2011	299492	replace air dryer assy		571414
214	4/21/2011	297333	water pump assy	Creditor #:MUL001 MULTISPARES LTD P/O #:P91154 Receiving #:924C	566498

214	4/20/2011	293006	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P89751 Receiving	566212
214	4/20/2011	293006	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P89751 Receiving	566212
214	4/20/2011	297965		Clean A/C filter	566212
214	4/20/2011	297965		Grease AC Compressor Clutch Bearing	566212
214	4/20/2011	297965		Tension Wheel Nuts To OEM Specification	566212
214	4/20/2011	297965		A Service & Bus Safety Inspection	566212
214	4/15/2011	297333	water pump leaking coolant		565288
214	4/7/2011	296359	Drv entered - Passenger Doors Faulty Controls		563299
214	4/7/2011	296359		Bus Safety Inspection	563299
214	4/7/2011	296359	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	563299
214	4/7/2011	296359	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	563299
214	4/7/2011	296359		Service T - Replace Transmission Oil & Filter	563299
214	3/25/2011	295512	Drv entered - Passenger Doors Loose	Checked both front and rear doors. Did not pick any loose part in the	559324
214	3/24/2011	317329	Drv entered - Vandalism Damaged Seat [See printed c	replace slashed seat base	559058
214	3/24/2011	294706		Tension Wheel Nuts To OEM Specification	558805
214	3/24/2011	294706		A Service & Bus Safety Inspection	558805
214	3/24/2011	294706		Clean A/C filter	558805
214	3/24/2011	294706		Grease AC Compressor Clutch Bearing	558805
214	3/18/2011	316316	High speed not working	repair demister switch	557306
214	3/11/2011	293006	Rear N/S tyre needs replacing		554376
214	3/7/2011	292406	WATER SEPERATOR SCANIA+VOLVO	Water Seperator Kit	553329
214	3/7/2011	292406		Cleaned Air CycloneSeparator	553329
214	2/23/2011	290981	Drv entered - Passenger Doors Faulty Controls		549659
214	2/23/2011	290980		Replace engine oil breather kit	549659
214	2/23/2011	290980	ENGINE OIL BREATHER KIT 0500LE		549659
214	2/23/2011	290980		Grease AC Compressor Clutch Bearing	549659
214	2/23/2011	290980	AIR FILTER MERC 0500LE		549659
214	2/23/2011	290980	OIL FILTER 1725+0500LE		549659
214	2/23/2011	290980	ENGINE OIL DELO 400LE 15W40		549659
214	2/23/2011	290980		Tension Wheel Nuts to Spec	549659
214	2/23/2011	290980		A Service & Bus Safety Inspection	549659
214	2/23/2011	290980		D-Service & Bus Safety Inspection	549659
214	2/23/2011	290980		Grease AC Compressor Clutch Bearing	549659
214	2/23/2011	290980		Tension Wheel Nuts To OEM Specification	549659
214	2/23/2011	290980		A Service & Bus Safety Inspection	549659
214	2/23/2011	290980		Clean A/C filter	549659
214	2/3/2011	287328	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P87848 Receiving	547350
214	2/3/2011	287328	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P87848 Receiving	547350
214	1/29/2011	287328	N/S rear outer tyre low tread		540453
214	1/29/2011	287328		Clean A/C filter	540453
214	1/29/2011	287328		Grease AC Compressor Clutch Bearing	540453
214	1/29/2011	287328		Tension Wheel Nuts To OEM Specification	540453
214	1/29/2011	287328		A Service & Bus Safety Inspection	540453
214	1/24/2011	286606	alt light flickering		538767
214	1/24/2011	286673	Drv entered - Elec & Light Altern Light [See printed dr	Both alt brushes replaced. 3 Tacho & ripple wires replaced all work o	538918
214	1/24/2011	286023	COMPRESSOR OIL AIR CON		538918
214	1/24/2011	286023	FILTER DRIER THERMO KING		538918
214	1/18/2011	286023		B Service	536823
214	1/18/2011	286023		Replace filter drier	536823
214	1/18/2011	286023		Replace compressor oil	536823
214	1/18/2011	286023		EVAPORATOR AREA: Clean evaporator coils; check water valves & pij	536823
214	1/18/2011	286023		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	536823
214	1/18/2011	286023		COMPRESSOR: Carry out efficiency test; check unloader control; che	536823
214	1/18/2011	286023		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	536823
214	1/18/2011	286023		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	536823
214	1/18/2011	286023		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	536823
214	1/18/2011	286023		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	536823
214	1/18/2011	286023		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	536823
214	1/18/2011	286023		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	536823
214	1/18/2011	286023		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for ten	536823
214	1/18/2011	286023		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	536823
214	1/12/2011	285238	Neutral button doesnt click down	REMOVE AND CLEAN SHFT ASSY	534555
214	1/11/2011	285045	Drv entered - Cool & AC Sys Other [See printed defect for m		534338
214	1/11/2011	285045	Drv entered - Cool & AC Sys Not Operating		534338
214	1/11/2011	285045	Drv entered - Air Cond Air Conditioner		534338
214	1/11/2011	285045	Drv entered - Cool & AC Sys Poor		534338
214	1/11/2011	285045	Drv entered - Cool & AC Sys Poor		534338
214	1/11/2011	285023	Drv entered - Air Cond Air Conditioner		534338

214	1/5/2011	284192	A Service & Bus Safety Inspection	532260
214	1/5/2011	284192	Clean A/C filter	532260
214	1/5/2011	284192	Grease AC Compressor Clutch Bearing	532260
214	1/5/2011	284192	Tension Wheel Nuts To OEM Specification	532260
214	1/3/2011	283992	LOW AIR PRESSURE.	531921
214	1/3/2011	283981	NOT MAKING AIR AT MORNINGTON. NIGHT RIDER BU	531635
214	1/3/2011	283980	LOW AIR PRESSURE replaced air dryer and filter	531635
214	12/31/2010	283855	Drv entered - Gearbox Slip found neutral button has to be pressed down all the way to select. O	530643
214	12/13/2010	281662	H1 GLOBE 24V 70W	525687
214	12/13/2010	281662	CLEAR FRONT INDICATOR WRAP-AROUND	525687
214	12/13/2010	281662	O/S HEADLIGHT NOT WORKING.N/S FRONT INDICATOR LENS SMASHE	525687
214	12/13/2010	281662	N/S front parker cracked	525687
214	12/3/2010	281356	Clean A/C filter	522632
214	12/3/2010	281356	Grease AC Compressor Clutch Bearing	522632
214	12/3/2010	281356	Tension Wheel Nuts To OEM Specification	522632
214	12/3/2010	281356	A Service & Bus Safety Inspection	522632
214	11/22/2010	278706	Drv entered - Engine Other	518419
214	11/19/2010	278400	DISC SECURING BOLT Creditor #:MUL001 MULTISPARES LTD P/O #:P84936 Receiving #:863	520090
214	11/19/2010	278400	REAR HUB SEAL KIT 0500LE Creditor #:MUL001 MULTISPARES LTD P/O #:P84936 Receiving #:863	520090
214	11/19/2010	278400	DISC ROTOR 016.295-00 Creditor #:MUL001 MULTISPARES LTD P/O #:P84936 Receiving #:863	520090
214	11/18/2010	278400	DISC PAD SET Creditor #:MUL001 MULTISPARES LTD P/O #:P84910 Receiving #:863	519707
214	11/18/2010	278400	REPLACE REAR DISK PADS	518082
214	11/9/2010	277119	Drv entered - Other [See printed defect for more informatio	515137
214	11/1/2010	276121	Drv entered - Suspension Noisy	512719
214	11/1/2010	276121	Red battery light flashes on & off	512719
214	11/1/2010	276121	WATER SEPERATOR SCANIA+VOLVO Water Seperator Kit	512719
214	11/1/2010	276121	Re-kit Air Cyclone Separator	512719
214	11/1/2010	276121	A Service & Bus Safety Inspection	512719
214	11/1/2010	276121	Tension Wheel Nuts To OEM Specification	512719
214	11/1/2010	276121	Grease AC Compressor Clutch Bearing	512719
214	11/1/2010	276121	Clean A/C filter	512719
214	10/28/2010	274532	TRADE IN Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/28/2010	274532	BALANCE Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/28/2010	274532	FITTING Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/28/2010	274532	Direct Purchase - TYRES Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/26/2010	274532	FITTING Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/26/2010	274532	11R22.5 SP327 P/C RTD Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P83639 Receiving	518298
214	10/20/2010	274532	Replace all drive tyres and O/S front tyre.	508916
214	10/20/2010	274532	Service	508916
214	10/5/2010	272502	Drv entered - Passenger Doors Faulty Controls	503845
214	10/5/2010	272502	Drv entered - Passenger Doors Other [See printed defect for	503845
214	10/5/2010	272502	Drv entered - Air System Losing Air [See printed defect for	503845
214	10/5/2010	272502	Grease AC Compressor Clutch Bearing	503845
214	10/5/2010	272502	AIR FILTER MERC 0500LE	503845
214	10/5/2010	272502	OIL FILTER 1725+0500LE	503845
214	10/5/2010	272502	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	503845
214	10/5/2010	272502	Tension Wheel Nuts to Spec	503845
214	10/5/2010	272502	A Service & Bus Safety Inspection	503845
214	10/5/2010	272502	D-Service & Bus Safety Inspection	503845
214	10/5/2010	272502	A Service & Bus Safety Inspection	503845
214	10/5/2010	272502	Clean A/C filter	503845
214	9/28/2010	270653	11R22.5 SP327 P/C RTD Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P82397 Receiving	503845
214	9/28/2010	270653	FITTING Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P82397 Receiving	503845
214	9/28/2010	270653	TYRE RECYCLE Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P82397 Receiving	503845
214	9/20/2010	270653	N/S tyres rear	498643
214	9/20/2010	269961	BATTERY 800CCA Creditor #:MUL001 MULTISPARES LTD P/O #:P82411 Receiving #:837	498727
214	9/20/2010	270582	windscreen cracked	498643
214	9/20/2010	270591	replace cracked windscreen	498643
214	9/20/2010	270582	Direct Purchase - BODYWORK Creditor #:ELI001 ELITE WINDSCREENS P/O #:P82358 Receiving #:836	498643
214	9/17/2010	269097	Direct Purchase - TYRES Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P81865 Receiving	499466
214	9/17/2010	269097	FITTING Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P81865 Receiving	499466
214	9/17/2010	269097	BALANCE Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P81865 Receiving	499466
214	9/15/2010	269961	Drv entered - Elec & Light Altern Light [See printed defec	496390
214	9/15/2010	269961	Drv entered - Elec & Light	496390
214	9/15/2010	269961	Drv entered - Elec & Light	496390
214	9/8/2010	269097	CHANGE DAMAGED N/S FRONT TYRE	493738
214	8/30/2010	267928	Tension Wheel Nuts To OEM Specification	490416
214	8/30/2010	267928	Grease AC Compressor Clutch Bearing	490416

214	8/30/2010	267928	Clean A/C filter	490416
214	8/30/2010	267928	A Service & Bus Safety Inspection	490416
214	8/12/2010	265527 BRAKEPADS M/B O500LE (AFTERMAR	Creditor #:MUL001 MULTISPARES LTD P/O #:P80800 Receiving #:822	486261
214	8/12/2010	265527 replace front and rear brake pads	REPLACE FRONT AND REAR BRAKE PADS	484042
214	7/31/2010	263956	Clean A/C filter	480134
214	7/31/2010	263956	Grease AC Compressor Clutch Bearing	480134
214	7/31/2010	263956	A Service & Bus Safety Inspection	480134
214	7/31/2010	263956	Tension Wheel Nuts To OEM Specification	480134
214	7/28/2010	263515 N/S mirror U/S	REPLACE BROKEN MIRROR HEAD	479514
214	7/28/2010	263515 MIRROR METAGAL L/H		479514
214	7/12/2010	261344 BROKEN SIDE WINDOW.		474100
214	7/9/2010	261152 annual inspection	BC125408	473337
214	7/8/2010	261079 replace rear air bags n/s	replace n/s rear air bags	473337
214	7/7/2010	260956 replace licenced to carry sticker		473337
214	7/6/2010	260783 replace worn driver door hinges		473337
214	7/2/2010	260363 Drv entered - Body & Acc Drivers Seat Back Rest [See printe		473337
214	7/2/2010	260363 Drv entered - Body & Acc Drivers Seat Back Rest [See	Lumbar support must be faulty was disconnected previously. Connec	473337
214	7/2/2010	259694 Service		472775
214	7/1/2010	259694 Accident Damaged # 21030 R/R. n/s/r. clearance light.Repair		472775
214	6/28/2010	259770	Remove disassemble & clean cyclone separator (apply water repella	472775
214	6/28/2010	259770	Inspect radiator & charge-air cooler for dirt - clean if required	472775
214	6/28/2010	259770	Electrical - BATTERIES: check fluid level (leave air gap when topping u	472775
214	6/28/2010	259770	Check power steering oil level	472775
214	6/28/2010	259770	Top-up coolant level (must equate to -37C frost protection)	472775
214	6/28/2010	259770	Adjust Engine Valve Clearance	472775
214	6/28/2010	259770	Change oil in fan angle drive	472775
214	6/28/2010	259770	Change air drier cannister; clean silencer & drain air reservoir	472775
214	6/28/2010	259770	Change pre and main fuel filter	472775
214	6/28/2010	259770	Check & clean filter cartridge in dry-type air cleaner	472775
214	6/28/2010	259694 Body check and repairs for R.S.I.		472775
214	6/28/2010	259694 Drv entered - Body & Acc Drivers Seat Back Rest [See printe		472775
214	6/22/2010	258983 Drv entered - Vandalism Graffiti		471019
214	6/22/2010	258983 Drv entered - Vandalism Graffiti		471019
214	6/22/2010	258983 Drv entered - Passenger Doors Faulty Controls		471019
214	6/22/2010	258983 Heaterand demister not working		471019
214	6/22/2010	258983 Drv entered - Other		471019
214	6/22/2010	258983 Drv entered - Other		471019
214	6/22/2010	258983 Drv entered - Air System Leaking		471019
214	6/22/2010	258983 Drv entered - Air System Losing Air [See printed defect for		471019
214	6/22/2010	258983	A Service & Bus Safety Inspection	471019
214	6/22/2010	258983	Tension Wheel Nuts To OEM Specification	471019
214	6/22/2010	258983	Grease AC Compressor Clutch Bearing	471019
214	6/22/2010	258983	Clean A/C filter	471019
214	6/9/2010	257652 Drv entered - Wipers & Washers Wipers Not Working		466980
214	6/9/2010	257652 Drv entered - Wipers & Washers Other [See printed defect fo		466980
214	6/7/2010	257229 Both doors wont always stay open.	checked switches and door operation found drink spilled in door swi	465717
214	6/7/2010	257230 Drv entered - Passenger Doors Intermittent [See print	operation checked senitive edges checked	465717
214	5/28/2010	256167 SERVICE CALL	Creditor #:BEN002 BENTECH SECURITY P/O #:P77966 Receiving #:794	463905
214	5/28/2010	256167 POWER SUPPLY & TIMER	Creditor #:BEN002 BENTECH SECURITY P/O #:P77966 Receiving #:794	463905
214	5/28/2010	256167 SECURITY SYSTEM NOT WORKING		463019
214	5/28/2010	232034 REPAIR ELEC PROBLEM	Creditor #:BWE001 BWERE ELECTRICS P/O #:G71264 Receiving #:792	462676
214	5/26/2010	255784 air drier kit	Creditor #:MUL001 MULTISPARES LTD P/O #:P77868 Receiving #:795	464948
214	5/26/2010	255784 AIR DRYER UNLOADER KIT	Creditor #:MUL001 MULTISPARES LTD P/O #:P77868 Receiving #:795	464948
214	5/26/2010	255784 AIR DRYER LEAKING		462032
214	5/24/2010	254106 FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P77416 Receiving	462676
214	5/24/2010	254106 11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P77416 Receiving	462676
214	5/24/2010	255470 Drv entered - Passenger Doors Faulty Controls		462032
214	5/24/2010	255470 Drv entered - Other [See printed defect for more informatio		462032
214	5/24/2010	255470 CD PLAYER NOT WORKING		462032
214	5/24/2010	255470 Drv entered - Body & Acc Other		462032
214	5/24/2010	255470 Drv entered - Body & Acc Drivers Seat Back Rest [See printe		462032
214	5/24/2010	255470 Drv entered - Brakes Park Brake Light On		462032
214	5/24/2010	255470	Bus Safety Inspection	462032
214	5/24/2010	255470 ZF GEARBOX FILTER	ZF Transmission Filter	462032
214	5/24/2010	255470 ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	462032
214	5/24/2010	255470	Service T - Replace Transmission Oil & Filter	462032
214	5/24/2010	255470	Tension Wheel Nuts To OEM Specification	462032
214	5/24/2010	255470	A Service & Bus Safety Inspection	462032

214	5/24/2010	255470	Clean A/C filter	462032	
214	5/24/2010	255470	Grease AC Compressor Clutch Bearing	462032	
214	5/20/2010	254982	Drv entered - Heat & Demist Other	REPLACE DRIVERS FOOT WELL BALL VENT	460389
214	5/17/2010	254435	Drv entered DOOR OPEN BUUTTON FAULTY CUASUIN	INSPECTED AND FOUND DRINK SPILT IN DOOR SWITCHES REMOVED	459513
214	5/17/2010	254434	MIRROR METAGAL L/H		459513
214	5/17/2010	254434	Drv entered - replace n/s mirror head	replace broken n/s mirror head assy	459513
214	5/12/2010	254105	Drv entered - Wipers & Washers Other		458531
214	5/12/2010	254106	Replace all rear drive tyres.		458531
214	5/12/2010	254105		Replace engine oil breather kit	458531
214	5/12/2010	254105	AIR FILTER MERC 0500LE		458531
214	5/12/2010	254105	OIL FILTER 1725+0500LE		458531
214	5/12/2010	254105	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		458531
214	5/12/2010	254105		Tension Wheel Nuts to Spec	458531
214	5/12/2010	254105		A Service & Bus Safety Inspection	458531
214	5/12/2010	254105		D-Service & Bus Safety Inspection	458531
214	5/12/2010	254105		Grease AC Compressor Clutch Bearing	458531
214	5/12/2010	254105		Clean A/C filter	458531
214	5/12/2010	254105		Grease AC Compressor Clutch Bearing	458531
214	5/12/2010	254105		A Service & Bus Safety Inspection	458531
214	5/4/2010	252854	BRAKEPADS M/B 0500LE (AFTERMAR	Creditor #:MUL001 MULTISPARES LTD P/O #:P77027 Receiving #:784	456903
214	5/3/2010	252854	replace front brake pads	REPLACE WORN FRONT BRAKE PADS	455966
214	4/27/2010	251953	1MT MULTI FIT WIPER REFILL		452546
214	4/24/2010	251953	Drv entered - Wipers & Washers Not Cleaning Screen	REPLACE WIPER BLADES	452546
214	4/24/2010	251953	Drv entered - Passenger Doors Require Adjusted [See	CHECKED DOOR ADJUSTMENT FOUND OK CLEANED DOOR CONTROL	452546
214	4/24/2010	251953	Drv entered - Passenger Doors Require Adjusted	SEE ABOVE	452546
214	4/24/2010	251953	Drv entered - Comm Equip Not Transmitting	CHECKED RADIO OPERATION FOUN OK	452546
214	4/24/2010	251953	Drv entered - Brakes Other [See printed defect for more inf		452546
214	4/24/2010	251951		A Service & Bus Safety Inspection	452546
214	4/24/2010	251951		Tension Wheel Nuts To OEM Specification	452546
214	4/24/2010	251951		Grease AC Compressor Clutch Bearing	452546
214	4/24/2010	251951		Clean A/C filter	452546
214	4/22/2010	251796	Drv entered - Other check and rectify door switch fau	check door switch operation	452103
214	4/8/2010	249990	rectify coolant leak n/s rear of bus	rework performed by 22 celsius	447677
214	4/1/2010	249123	SUB CONTRACTED AIR CONDITION	Creditor #:CELO01 22 CELSIUS P/O #:P76082 Receiving #:77665 Date :	447497
214	4/1/2010	249123	HEATER HOSE	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P76143 Receiving #:7	447497
214	3/30/2010	249123	repair a/c heating pipes	REPAIR PERFORMED BY 22CEL TO A/C HEAT RISER PIPES	447497
214	3/29/2010	247857	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75730 Receiving	452546
214	3/29/2010	247857	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75730 Receiving	452546
214	3/29/2010	247857	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P75730 Receiving	452546
214	3/25/2010	248716	Drv entered - Elec & Light Altern Light [See printed dr	replace upper alt brushes	445740
214	3/25/2010	248716	BRUSH KIT 55AMP ALT B10M MK3		445740
214	3/23/2010	248409	Drv entered - Other seat frame broken	REPLACE TRON REAR SEAT BASE	444989
214	3/17/2010	247857	Replace worn rear drive tyre.		443449
214	3/17/2010	247735		A Service & Bus Safety Inspection	443209
214	3/17/2010	247735		Tension Wheel Nuts To OEM Specification	443209
214	3/17/2010	247735		Grease AC Compressor Clutch Bearing	443209
214	3/17/2010	247735		Clean A/C filter	443209
214	3/16/2010	246952	HARD DRIVE	Creditor #:BEN002 BENTECH SECURITY P/O #:P75460 Receiving #:771	440426
214	3/16/2010	246952	COLOUR CAMAREA	Creditor #:BEN002 BENTECH SECURITY P/O #:P75460 Receiving #:771	440426
214	3/16/2010	246952	LABOUR CHARGE	Creditor #:BEN002 BENTECH SECURITY P/O #:P75460 Receiving #:771	440426
214	3/16/2010	246952	WARNING LIGHT	Creditor #:BEN002 BENTECH SECURITY P/O #:P75460 Receiving #:771	440426
214	3/7/2010	246952	repaair security system		440426
214	3/2/2010	245647	VIBRA-SORBA DISCHARGE		438728
214	3/2/2010	245647	AIR CON REFRIDGERANT		438728
214	3/1/2010	361708	RUBBER SLEEVE RADIATOR	Creditor #:MUL001 MULTISPARES LTD P/O #:P110317 Receiving #:11	696726
214	3/1/2010	361708	SOLENOID EXH BRAKE	Creditor #:MUL001 MULTISPARES LTD P/O #:P110317 Receiving #:11	696726
214	3/1/2010	361708	SWAY BAR DROP ARM	Creditor #:MUL001 MULTISPARES LTD P/O #:P110317 Receiving #:11	696726
214	3/1/2010	362400	RELAY VALVE	Creditor #:MUL001 MULTISPARES LTD P/O #:P110623 Receiving #:11	698230
214	3/1/2010	261152	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P79369 Receiving	477778
214	3/1/2010	246174	Door switches faulty rear door worst that front.Often	Rear door sensitive edge adjusted working ok. No red dash detected	438480
214	3/1/2010	261344	Direct Purchase - BODYWORK	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P79403 Receiving #:809	475447
214	2/25/2010	245647	Drv entered - Air Cond Cooling Fault Light [See printed def		437078
214	2/25/2010	245647	Drv entered - Air Cond Cooling Fault Light		437078
214	2/25/2010	245647	A/C HOSE CHAFED AND LEAKING GAS.		437078
214	2/25/2010	245647	Drv entered - Air Cond Cooling Fault Light.		437078
214	2/25/2010	245647	Drv entered - Cool & AC Sys Not Operating	replace worn vibrosber hose	437078
214	2/25/2010	245706	Drv entered - Passenger Doors Require Adjusted [See printed		437513
214	2/25/2010	245647	Drv entered - Elec & Light Wrning Light [See printed defect		437078

214	2/25/2010	245706	Loosing air from rear		437513
214	2/19/2010	241475	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P74098 Receiving #:	436916
214	2/19/2010	241475	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P74098 Receiving #:	436916
214	2/19/2010	241475	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P74098 Receiving #:	436916
214	2/19/2010	241475	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P74098 Receiving #:	436916
214	2/1/2010	242774	TOP ALT. BELT LOOSE.		436591
214	1/29/2010	242546	Service		435770
214	1/29/2010	242546	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P74333 Receiving #:	435977
214	1/29/2010	242546	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P74333 Receiving #:	435977
214	1/29/2010	242546	CONSUMABLE DELIVERY CHARGE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P74333 Receiving #:	435977
214	1/28/2010	242546	COOLANT LEAK AT HEADER TANK.		435770
214	1/27/2010	242285	Direct Purchase - BODYWORK	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P74268 Receiving #:757	435483
214	1/27/2010	242285	Drv entered - Vandalism Wndow Etch [See printed defect for		435483
214	1/18/2010	241317	COMPRESSOR OIL AIR CON		433174
214	1/18/2010	241317	FILTER DRIER THERMO KING		433174
214	1/18/2010	241475		Clean A/C filter	433174
214	1/18/2010	241475		A Service & Bus Safety Inspection	433174
214	1/18/2010	241475		Tension Wheel Nuts To OEM Specification	433174
214	1/18/2010	241475		Grease AC Compressor Clutch Bearing	433174
214	1/15/2010	241317		Check boost pump condition	432020
214	1/15/2010	241317		Check & replace electric motor brushes	432020
214	1/15/2010	241317		Replace compressor oil	432020
214	1/15/2010	241317		Replace filter drier	432020
214	1/15/2010	241317		D Service	432020
214	1/15/2010	241317		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	432020
214	1/15/2010	241317		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	432020
214	1/15/2010	241317		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	432020
214	1/15/2010	241317		CONDENSOR AREA: Clean condenser coils; check boltsclamps for ten	432020
214	1/15/2010	241317		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	432020
214	1/15/2010	241317		EVAPORATOR AREA: Clean evaporator coils; check water valves & pi	432020
214	1/15/2010	241317		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	432020
214	1/15/2010	241317		COMPRESSOR: Carry out efficiency test; check unloader control; che	432020
214	1/15/2010	241317		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	432020
214	1/15/2010	241317		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	432020
214	1/15/2010	241317		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	432020
214	12/30/2009	239579	STOP LIGHT SWITCH.	Creditor #:MUL001 MULTISPARES LTD P/O #:P73536 Receiving #:750	426396
214	12/29/2009	239579	Drv entered - Other [See printed defect for more info]	replace step light globe	426250
214	12/29/2009	239580	Drv entered - Elec & Light Interior Lights [See printed	replace step light	426250
214	12/24/2009	239177	pad set	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P73425 Receiving #:	425132
214	12/23/2009	239342	Drv entered - Other		424445
214	12/23/2009	239177	replace rear brake pads		423695
214	12/18/2009	238920	Ops Entered - Fault - Engine - Route: 781 - Frankston R/S		422983
214	12/17/2009	238831	TOP ALT BELT 0500LE		422983
214	12/17/2009	238831	REPLACE UPPER ALT DRIVE BELT		422983
214	12/17/2009	238789	AIR LEAK FROM BRAKE MODULAOR VALVE	overhaul 4 way protection valve	422673
214	12/17/2009	238759		A Service & Bus Safety Inspection	422673
214	12/17/2009	238759		Tension Wheel Nuts To OEM Specification	422673
214	12/17/2009	238759		Grease AC Compressor Clutch Bearing	422673
214	12/17/2009	238759		Clean A/C filter	422673
214	12/7/2009	237894	Back door wont always shut or open. Sometimes it wi	adjusted sensitive edge. working ok.	418565
214	12/2/2009	237295	A/C doesn't cool	Found unloaded No2 wire shorted repair wire. Clean filter and testec	417779
214	12/2/2009	237296	Say card default 16/ not lights outside.Desto displaying N		417779
214	12/2/2009	237279	o/s REAR SIDE PANEL NEEDS SECURING		417779
214	11/25/2009	235443	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P72256 Receiving #:	417779
214	11/25/2009	236576	Headlight globe out	Globe replaced	415907
214	11/25/2009	236576	H1 GLOBE 24V 70W		415907
214	11/16/2009	235429	N/S washer jet missing		412177
214	11/16/2009	235443	REPLACE BOTH N/S REAR TYRES.		412177
214	11/16/2009	235429	Drv entered - Passenger Doors Faulty Controls		412177
214	11/16/2009	235429	Drv entered - Elec & Light Headlights		412177
214	11/16/2009	235429		Clean A/C filter	412177
214	11/16/2009	235429		Grease AC Compressor Clutch Bearing	412177
214	11/16/2009	235429		Tension Wheel Nuts To OEM Specification	412177
214	11/16/2009	235429		A Service & Bus Safety Inspection	412177
214	10/30/2009	234018	Desto: a block appears across the top of the desto. Bl	repaires performed by moditec aust	406429
214	10/24/2009	232115	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P71327 Receiving #:	405511
214	10/17/2009	231594	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P71208 Receiving #:	412883
214	10/16/2009	232122	replace engine dip stick	Replaced	401146

214	10/15/2009	232115	Change flat O/S Inner tyre.		401146
214	10/15/2009	232122	DIP STICK	Creditor #:DAI001 DAIMLER CHRYSLER P/O #:P71332 Receiving #:73C	403479
214	10/15/2009	232113		Grease AC Compressor Clutch Bearing	401146
214	10/15/2009	232113	AIR FILTER MERC 0500LE		401146
214	10/15/2009	232113	OIL FILTER 1725+0500LE		401146
214	10/15/2009	232113	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		401146
214	10/15/2009	232113		A Service & Bus Safety Inspection	401146
214	10/15/2009	232113		D-Service & Bus Safety Inspection	401146
214	10/15/2009	232113		Clean A/C filter	401146
214	10/15/2009	232113		Tension Wheel Nuts To OEM Specification	401146
214	10/15/2009	232113		A Service & Bus Safety Inspection	401146
214	10/14/2009	232028		Replaced O/S Inner rear tyre	400778
214	10/14/2009	232028	Drv entered - Passenger Doors Require Adjusted	Adjusted rear doors	400778
214	10/14/2009	232028	Drv entered - Other [See printed defect for more informatio		400778
214	10/14/2009	232028	HORN	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P71316 Receiving #:	401396
214	10/14/2009	232028	Drv entered - Elec & Light Horn		400778
214	10/14/2009	232028	Drv entered - Elec & Light Horn [See printed defect for mor		400778
214	10/14/2009	232028	Drv entered - Elec & Light Horn [See printed defect for mor		400778
214	10/14/2009	232033	Drv entered - Elec & Light Horn	Horn fitted	400778
214	10/14/2009	232034	Drv entered - Elec & Light Horn [See printed defect for mor		400778
214	10/14/2009	232028	AM/FM radio poor reception	All good	400778
214	10/14/2009	232028	Drv entered - Body & Acc Other		400778
214	10/12/2009	231587	Drv entered - Elec & Light Reverse Lights [See printed	Repaired buzzer wiring	399152
214	10/10/2009	231594	REPLACE N/S/R OUTTER TYRE.		399747
214	9/30/2009	229999	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P70736 Receiving #:	398827
214	9/28/2009	230409	Drv entered - Engine Low Oil Level		394682
214	9/28/2009	230409	Drv entered - Other		394682
214	9/23/2009	229999	Change both O/S rear drive wheels.		393505
214	9/23/2009	222018	DECALS TO O/S X 3 PANELS	Creditor #:ATT001 ATTITUDE SIGNS P/O #:P75182 Receiving #:76661	438058
214	9/23/2009	229998		Clean A/C filter	393505
214	9/23/2009	229998		Grease AC Compressor Clutch Bearing	393505
214	9/23/2009	229998		Tension Wheel Nuts To OEM Specification	393505
214	9/23/2009	229998		A Service & Bus Safety Inspection	393505
214	9/14/2009	229000	REAR WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P70424 Receiving #:72C	391117
214	9/14/2009	229000	Ops Entered - Accident - Broken Window/Windscreen - Route:		390729
214	9/8/2009	228448	Drv entered - Vandalism Graffiti		389005
214	9/8/2009	228448	Drv entered - Vandalism Graffiti		389005
214	8/21/2009	226790		Clean A/C filter	383215
214	8/21/2009	226790		Grease AC Compressor Clutch Bearing	383215
214	8/21/2009	226790		Tension Wheel Nuts To OEM Specification	383215
214	8/21/2009	226790		A Service & Bus Safety Inspection	383215
214	8/10/2009	225590	Drv entered - Cool & AC Sys Not Operating	REFIT TOP ALT BELT	379608
214	8/10/2009	225589	Drv entered - Heat & Demist No Demisters	REFIT TOP ALT BELT	379608
214	8/10/2009	225589	Drv entered - Elec & Light Interior Lights	REFIT TOP ALT BELT	379608
214	7/27/2009	224453	Drv entered - Other	inspected and could not fault operation of footwell heater outlet fou	374728
214	7/25/2009	224076		A Service & Bus Safety Inspection	373692
214	7/25/2009	224076		Tension Wheel Nuts To OEM Specification	373692
214	7/25/2009	224076		Grease AC Compressor Clutch Bearing	373692
214	7/25/2009	224076		Clean A/C filter	373692
214	7/13/2009	222293	Direct Purchase - BODYWORK	Creditor #:PSS001 PARTS SUPPLY SOLUTIONS P/O #:P68353 Receiving #:	371191
214	7/13/2009	222640	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P68509 Receiving #:	371785
214	7/13/2009	221812	INTERNAL PANEL	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:P68206 Receiving #:	371191
214	7/13/2009	221777	DIRECT PURCHASE ACCIDENT	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:P68186 Receiving #:	371191
214	7/10/2009	222640	ANNUAL INSPECTION	BC135270	370132
214	7/9/2009	222018	Service	replace o/s damaged panels replace decals repair rear bumper rep	370132
214	7/8/2009	222018	Service		370132
214	7/7/2009	222293	REPLACE WIPER BLADE ASSYS		370132
214	7/7/2009	222018	Service		370132
214	7/3/2009	222018	Accident Damaged No 20465 R/R.O/S. Lower panels N		370132
214	7/2/2009	221842	REPLACE REAR AIR BAGS		370132
214	7/2/2009	223803	REPLACE ENGINE DRIVE BELT PULLYES	performed at r-s-i	370132
214	7/1/2009	221642		Electrical - BATTERIES: check fluid level (leave air gap when topping u	369872
214	7/1/2009	221642		Check oil level in transmission & top-up if required	369872
214	7/1/2009	221642		Inspect radiator & charge-air cooler for dirt - clean if required	369872
214	7/1/2009	221812	REPLACE CRACKED OVERHEAD DOOR CONTROL PANEL		370132
214	7/1/2009	221777	DAMMAGED O/S NO 3 PANEL REPLACE DECALS {UNREPORTED}		370132
214	6/30/2009	221642		Remove disassemble & clean cyclone separator (apply water repellat	369872
214	6/30/2009	221642		Check & clean filter cartridge in dry-type air cleaner	369872

214	6/30/2009	221642		Check power steering oil level	369872
214	6/30/2009	221642		Change pre and main fuel filter	369872
214	6/30/2009	221642		Change air drier cannister; clean silencer & drain air reservoir	369872
214	6/30/2009	221642		Change oil in fan angle drive	369872
214	6/30/2009	221642		Top-up coolant level (must equate to -37C frost protection)	369872
214	6/30/2009	221642		Adjust Engine Valve Clearance	369872
214	6/30/2009	221642	Drv entered - Vandalism Graffiti		369872
214	6/30/2009	221642	Drv entered - Vandalism Graffiti		369872
214	6/17/2009	220406	Drv entered - Passenger Doors Faulty Controls		365261
214	6/17/2009	220406	LEFT HEADLIGHT ON LOW BEAM SHINES IN TO ONCOMMING TRAFFIC {		365261
214	6/17/2009	220406		Clean A/C filter	365261
214	6/17/2009	220406		Grease AC Compressor Clutch Bearing	365261
214	6/17/2009	220406		Tension Wheel Nuts To OEM Specification	365261
214	6/17/2009	220406		A Service & Bus Safety Inspection	365261
214	6/16/2009	218009	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P67126 Receivin	365553
214	6/16/2009	218009	FITTING BUS - RUNOUT	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P67126 Receivin	365553
214	6/11/2009	219913	replace lower alt pully assy	PERFROMED BY WHITEHOUSE TRUCKS DANDY	363445
214	6/5/2009	219509	Drv entered - Vandalism Graffiti	CLEAN SEATS AND REAR WALLS AND FLOOR	361353
214	6/4/2009	219477	replace lower alt pully	WARRENTY SERVICE PERFORMED BY WHITEHOUSE TRUCKS DANDY	361353
214	5/28/2009	217667	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P66974 Receivin	358841
214	5/28/2009	217667	BALANCE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P66974 Receivin	358841
214	5/28/2009	217667	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P66974 Receivin	358841
214	5/28/2009	217667	GY 11R22.5 148/145J MCS METRO	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P66974 Receivin	358841
214	5/28/2009	223800	DOWNLOAD TRANSMISSION PROGRAM SUPPYED BY ;	preformed by zf aust	358585
214	5/22/2009	218235	Service	BACK UP MECHANIC AND CLEAN UP SPILL	356823
214	5/22/2009	218235	Service		356823
214	5/22/2009	218235	OIL WARNING LIGHT ON AT KARINGAK HUB.		356823
214	5/21/2009	218284	Drv entered - Comm Equip Not Transmitting	CHECK UNIT OPERTION ON ROAD TEST AND FOUND OK CHECKED OPI	356667
214	5/21/2009	218009	OIL FILTER 1725+0500LE		356309
214	5/21/2009	218009	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		356309
214	5/21/2009	218009		Tension Wheel Nuts to Spec	356309
214	5/21/2009	218009		A Service & Bus Safety Inspection	356309
214	5/21/2009	218009		D-Service & Bus Safety Inspection	356309
214	5/21/2009	218009		Grease AC Compressor Clutch Bearing	356309
214	5/21/2009	218009	AIR FILTER MERC 0500LE		356309
214	5/21/2009	218009		Clean A/C filter	356309
214	5/21/2009	218009		Grease AC Compressor Clutch Bearing	356309
214	5/21/2009	218009		Tension Wheel Nuts To OEM Specification	356309
214	5/21/2009	218009		A Service & Bus Safety Inspection	356309
214	5/18/2009	217667	N/S FRONT TYRE GOING DOWN AT FRANKSTONE HOS	travel to bus and gchange dammaged n/s front tyre	355668
214	5/7/2009	216827	GEARSHIFT DOWN SHIFT ISSUE 3RD GEAR	CHECK AND RAOD TEST BUS WITH ZF AUST CAPTURE FAULT AND DO	351831
214	5/5/2009	216477	Drv entered - Passenger Doors Faulty Controls		350940
214	5/5/2009	216477	Drv entered - Passenger Doors Faulty Controls		350940
214	5/5/2009	216477	Drv entered - Passenger Doors Door Brakes		350940
214	5/5/2009	216477	Drv entered - Heat & Demist Demisters Cold		350940
214	5/5/2009	216477	Drv entered - Gearbox Harsh Thumping		350940
214	5/5/2009	216477	Drv entered - Engine Other		350940
214	4/17/2009	214793	DOR LIGHT FRONT DOOR GLOBE BURNT OUT	REPLACE GLOBE	344701
214	4/16/2009	214597	BRAKES GRABBING CENTER DOOR CLOSING ON THER	CHECK AND ADJUST SENSITVE EDGE	344089
214	4/9/2009	214519	replace rear brake pads	REPLACE REAR BRAKE PADS	341800
214	4/8/2009	214345	Service	ADJUST ALT DRIVE BELTS TIGHTEN DRIVER COMPARTMENT DOOR TIK	341800
214	4/8/2009	214345	REPLACE REAR MARKER LAMP	replace cracked marker lamp assy	341577
214	4/8/2009	214345	ZF GEARBOX FILTER	ZF Transmission Filter	341577
214	4/8/2009	214345	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	341577
214	4/8/2009	214345		Service T - Replace Transmission Oil & Filter	341577
214	4/8/2009	214345		Grease AC Compressor Clutch Bearing	341577
214	4/8/2009	214345		Clean A/C filter	341577
214	4/8/2009	214345		Tension Wheel Nuts To OEM Specification	341577
214	4/8/2009	214345		A Service	341577
214	4/3/2009	212089	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P65316 Receivin	339645
214	4/3/2009	212089	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P65316 Receivin	339645
214	4/3/2009	212089	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P65316 Receivin	339645
214	4/3/2009	212089	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P65316 Receivin	339645
214	3/25/2009	214520	Drv entered - Wipers & Washers Disconnected	REPLACE WIPER BLADES	336576
214	3/23/2009	212269	1MT MULTI FIT WIPER REFILL		334995
214	3/20/2009	212269	Drv entered - Wipers & Washers Rubber Adrift	REPLACE WIPER BLADES	334522
214	3/20/2009	212089	REPLACE REAR TYRES	REPLACE N/S REAR TYRES	334320
214	3/20/2009	212264	Drv entered - Vandalism Graffiti	CLEAN REAR SEATS AND WINDOWS	334522

214	3/20/2009	212065	check gear shift operation		334320
214	3/20/2009	212065	Drv entered - Other		334320
214	3/20/2009	212065	Drv entered - Other.BROKEN LIGHT RIGHT REAR.		334320
214	3/20/2009	212065	reapir winscreen chip		334320
214	3/20/2009	212065		Clean A/C filter	334320
214	3/20/2009	212065		Grease AC Compressor Clutch Bearing	334320
214	3/20/2009	212065		Tension Wheel Nuts To OEM Specification	334320
214	3/20/2009	212065		A Service	334320
214	2/20/2009	209393	check retarder operation said to be coming on and of	check and loctate fault replace retarder relay and check operation	324153
214	2/20/2009	209288		Grease AC Compressor Clutch Bearing	323792
214	2/20/2009	209288		Tension Wheel Nuts To OEM Specification	323792
214	2/20/2009	209288		A Service	323792
214	2/7/2009	207283	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		319152
214	2/1/2009	221642	gasket paper	Creditor #:BUR003 BURSON AUTO PARTS P/O #:P68350 Receiving #:	370132
214	1/29/2009	207283	REPLACE SEALS IN 6 WAY VALVE	OVERHAUL VALVE	315566
214	1/24/2009	207022	Called in to replace thrown belts		314394
214	1/20/2009	206576	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63614 Receiving #:	313288
214	1/20/2009	206576	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63614 Receiving #:	313288
214	1/20/2009	206576	VERN COMPLETED SERVICE.		313005
214	1/20/2009	206576	Drv entered - Other		312656
214	1/20/2009	206576	Drv entered - Other [See printed defect for more informatio		312656
214	1/20/2009	206576		Grease AC Compressor Clutch Bearing	312656
214	1/20/2009	206576		Tension Wheel Nuts To OEM Specification	312656
214	1/20/2009	206576		A Service	312656
214	1/15/2009	206284	FIT NEW SEDEMENT BOAL BLEED AND TEST.		311327
214	1/15/2009	206105	CONSUMABLE DELIVERY CHARGE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63434 Receiving #:	311327
214	1/15/2009	206105	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63434 Receiving #:	311327
214	1/14/2009	205976	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P63387 Receiving #:	311098
214	1/14/2009	206105	Drain on bottom of fuel seperator failed.		311098
214	1/14/2009	206105	ORDER PART MAKE UP TEMP. PLUG.		311098
214	1/14/2009	206105	FIT UP TEMP. PLUG TO KEEP OPERATIONAL.		311098
214	1/13/2009	205976	REPLACE O/S FRONT TYRE		310730
214	1/12/2009	205880		Grease AC Compressor Clutch Bearing	310574
214	1/12/2009	205880	AIR FILTER MERC 0500LE		310574
214	1/12/2009	205880	OIL FILTER 1725+0500LE		310574
214	1/12/2009	205880	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		310574
214	1/12/2009	205880		Tension Wheel Nuts to Spec	310574
214	1/12/2009	205880		A Service	310574
214	1/12/2009	205880		D-Service	310574
214	1/9/2009	205581	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63264 Receiving #:	309514
214	1/9/2009	205581	Direct Purchase - MECHANICAL	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P63264 Receiving #:	309514
214	1/8/2009	205581	AIR DRYER NOT ALLOWING SYSTEM TO BUILD AIR NEEDS O/H.AUL.6		309514
214	12/24/2008	204671	repair air leak at 4 way protection valve	REMOVE AND REPIAR 4 WAY PROTECTION VALVE AND CHECK OPERA	304780
214	12/22/2008	204302		C Service	304099
214	12/22/2008	204302		B Service	304099
214	12/22/2008	204302		Replace filter drier	304099
214	12/22/2008	204302		Replace compressor oil	304099
214	12/22/2008	204302		UNIT PERFORMANCE TEST: Run unit & check gas charge; check cond	304099
214	12/22/2008	204302		CONDENSOR AREA: Clean condensor coils; check boltsclamps for ten	304099
214	12/22/2008	204302		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	304099
214	12/22/2008	204302		EVAPORATOR AREA: Clean evaporator coils; check water valves & pij	304099
214	12/22/2008	204302		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	304099
214	12/22/2008	204302		COMPRESSOR: Carry out efficiency test; check unloader control; che	304099
214	12/22/2008	204302		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	304099
214	12/22/2008	204302		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pull	304099
214	12/22/2008	204302		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	304099
214	12/22/2008	204302		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	304099
214	12/22/2008	204302		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	304099
214	12/18/2008	204070	squeeking noise in engine bay		303443
214	12/18/2008	204070	Drv entered - Elec & Light Stop lights		303443
214	12/18/2008	204070	Drv entered - Elec & Light Park Lights		303443
214	12/18/2008	204070		Grease AC Compressor Clutch Bearing	303443
214	12/18/2008	204070		Tension Wheel Nuts To OEM Specification	303443
214	12/18/2008	204070		A Service	303443
214	12/17/2008	201580	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P62038 Receiving #:	303611
214	12/17/2008	201580	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P62038 Receiving #:	303611
214	12/17/2008	201580	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P62038 Receiving #:	303611
214	12/17/2008	201580	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P62038 Receiving #:	303611

214	12/10/2008	203758	1MT MULTI FIT WIPER REFILL		301214
214	12/10/2008	203758	Drv entered - Wipers & Washers Disconnected	replace wiper blades	300846
214	12/9/2008	202493	SIDE WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P62292 Receiving #:643	300493
214	12/5/2008	203036	Drv entered - Cool & AC Sys Not Operating		298260
214	12/1/2008	202493	REPLACE BROKEN N/S REAR WINDOWS	replace broken n/s rear window	297074
214	12/1/2008	203205	Drv entered - Passenger Doors Faulty Controls	CHECK AND ADJSUT DOOR OPERATION	297921
214	11/27/2008	202287	Drv entered - Passenger Doors Require Adjusted		296446
214	11/27/2008	202287	Drv entered - Other	CHECK AND ADJSUT SENSITVE EDGEDS	296446
214	11/19/2008	201580	replace rear tyres		293909
214	11/19/2008	201579		Tension Wheel Nuts To OEM Specification	293909
214	11/19/2008	201579		A Service	293909
214	11/8/2008	200350	LED CLEARANCE LIGHT (RED AMBER)		289798
214	11/8/2008	200350	replace broken n/s marker lamp {not repaorted}	replace marker lamp assy	289798
214	10/29/2008	181964		B Service	285871
214	10/29/2008	181964		Replace filter drier	285871
214	10/29/2008	181964		Replace compressor oil	285871
214	10/29/2008	181964	FILTER DRIER THERMO KING		286425
214	10/29/2008	181964	COMPRESSOR OIL AIR CON		286425
214	10/29/2008	181964		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condi	285871
214	10/29/2008	181964		CONDENSOR AREA: Clean condensor coils; check boltsclamps for ten	285871
214	10/29/2008	181964		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporat	285871
214	10/29/2008	181964		EVAPORATOR AREA: Clean evaporator coils; check water valves & pij	285871
214	10/29/2008	181964		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump ope	285871
214	10/29/2008	181964		COMPRESSOR: Carry out efficiency test; check unloader control; cher	285871
214	10/29/2008	181964		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler p	285871
214	10/29/2008	181964		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulle	285871
214	10/29/2008	181964		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	285871
214	10/29/2008	181964		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5	285871
214	10/29/2008	181964		Clean R/A & F/A filters; Inspect and report on condition; Replace filte	285871
214	10/28/2008	181855	Drv entered - Whls & Tyres Other		285065
214	10/28/2008	181854	Ops Entered - Swap		285065
214	10/28/2008	181855	Drv entered - Elec & Light Other		285065
214	10/28/2008	181855	Drv entered - Body & Acc Exterior		285065
214	10/28/2008	181855	Drv entered - Brakes Park Brake Light On		285065
214	10/28/2008	181854		A Service	285065
214	10/28/2008	181855	Drv entered - Other		285065
214	10/28/2008	181855		Tension Wheel Nuts To OEM Specification	285065
214	10/28/2008	181855		A Service	285065
214	10/28/2008	181854		Tension Wheel Nuts To OEM Specification	285065
214	10/28/2008	181854	Service		285871
214	10/13/2008	180398	replace upper alt drive belt	RPLCE UPPER ALT DRIVE BELT	280715
214	10/11/2008	180457	no rear lights	REPLACE STOLEN FUSES FROM ELECTRICAL PANEL	279946
214	10/8/2008	179571	FRONT WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P60600 Receiving #:627	280715
214	10/2/2008	179571	Drv entered - Other	REPLACE DAMMAGED WINDSCREEN	276678
214	9/26/2008	179260		Tension Wheel Nuts To OEM Specification	275734
214	9/26/2008	179260		A Service	275734
214	9/16/2008	178307	A/C BELT 0500 BENZ		271876
214	9/16/2008	178307	BELT TOP ALT B7R		271876
214	9/16/2008	178307	REPLACE UPPER ALT BELT	replace upper alt belt and main enginr drive belt	271876
214	9/8/2008	178109	Drv entered - Elec & Light Headlights	REPLACE N/S HEADLAMP GLOBE	268939
214	8/28/2008	176757	Drv entered - Passenger Doors Faulty Controls	on road test checked operation found ok	264207
214	8/28/2008	176757	Drv entered - Heat & Demist No Heaters		264207
214	8/28/2008	176757	Drv entered - Heat & Demist Demisters Cold		264207
214	8/28/2008	176757	AIR FILTER MERC 0500LE		264207
214	8/28/2008	176757	OIL FILTER 1725+0500LE		264207
214	8/28/2008	176757	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		264207
214	8/28/2008	176757		Tension Wheel Nuts to Spec	264207
214	8/28/2008	176757		A Service	264207
214	8/28/2008	176757		D-Service	264207
214	8/28/2008	176757		Tension Wheel Nuts To OEM Specification	264207
214	8/28/2008	176757		A Service	264207
214	8/19/2008	175948	Drv entered - Elec & Light Headlights	REPLACE BLOWN O/S HEADLAMP GLOBE	260810
214	7/31/2008	172216	FIT DECALS	Creditor #:ATT001 ATTITUDE SIGNS P/O #:P58264 Receiving #:60746	253709
214	7/30/2008	173658	TYRE RECYCLE	Creditor #:BEA001 BEAUREPAIRES P/O #:P58596 Receiving #:60647 C	253350
214	7/30/2008	173658	Fitting	Creditor #:BEA001 BEAUREPAIRES P/O #:P58596 Receiving #:60647 C	253350
214	7/30/2008	173658	11R22.5 SP327 P/C RTD	Creditor #:BEA001 BEAUREPAIRES P/O #:P58596 Receiving #:60647 C	253350
214	7/30/2008	173658	RECAP	Creditor #:BEA001 BEAUREPAIRES P/O #:P58596 Receiving #:60647 C	253350
214	7/22/2008	171986	SIDE WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P57969 Receiving #:603	250436

214	7/22/2008	172658 ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:P58245 Receiving #:	250436
214	7/21/2008	172808 SIDE WINDOW	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P58308 Receiving #:	249703
214	7/21/2008	172216 PANELS AS PER SAMPLE	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:P58148 Receiving #:	249703
214	7/14/2008	172808 replace broken n/s rear window	REPLACE N/S REAR WINDOW	248162
214	7/14/2008	173600 Drv entered - Other		248162
214	7/10/2008	172658 ANNUAL INSPECTION	BC120018	247640
214	7/9/2008	173658 REPLACE N/S REAR TYRES		247640
214	7/9/2008	172216 Service		247640
214	7/8/2008	172216 Service		247640
214	7/7/2008	172216 Service		247640
214	7/4/2008	172107	Adjust Engine Valve Clearance	247640
214	7/4/2008	172216 REPAIR N/S REAR ENGINE BAY DOOR AND N/S MID NO3 PANEL		247640
214	7/3/2008	172107	Change air drier cannister; clean silencer & drain air reservoir	247640
214	7/3/2008	172107	Top-up coolant level (must equate to -37C frost protection)	247640
214	7/3/2008	172107	Electrical - BATTERIES: check fluid level (leave air gap when topping u	247640
214	7/3/2008	172107	Change pre and main fuel filter	247640
214	7/3/2008	172107	Check power steering oil level	247640
214	7/3/2008	172107	Check & clean filter cartridge in dry-type air cleaner	247640
214	7/3/2008	172107	Remove disassemble & clean cyclone separator (apply water repella	247640
214	7/3/2008	172107	Check oil level in transmission & top-up if required	247640
214	7/3/2008	172107	Inspect radiator & charge-air cooler for dirt - clean if required	247640
214	7/3/2008	172107	Change oil in fan angle drive	247640
214	7/3/2008	172107 Drv entered - Vandalism Graffiti		247640
214	7/3/2008	172107 Drv entered - Passenger Doors Not Operating		247640
214	7/3/2008	172107 Drv entered - Passenger Doors		247640
214	7/3/2008	172107 Drv entered - Passenger Doors Faulty Controls		247640
214	7/3/2008	172107 Drv entered - Passenger Doors Other		247640
214	7/3/2008	172107 Drv entered - Passenger Doors Not Operating	clean flid spill from door switches	247640
214	7/3/2008	172107 Drv entered - Heat & Demist Noisy		247640
214	7/3/2008	172107 small w/scrren chip		247640
214	7/3/2008	172107 FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	247640
214	7/3/2008	172107 ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	247640
214	7/3/2008	172107	Service T - Replace Transmission Oil & Filter	247640
214	7/3/2008	172107	A Service	247640
214	7/3/2008	172107	Tension Wheel Nuts To OEM Specification	247640
214	7/3/2008	172107	A Service	247640
214	7/3/2008	172107	Tension Wheel Nuts To OEM Specification	247640
214	7/2/2008	171986 REPLACE BROKEN N/S REAR NO 5 WINDOW	REPLACE N/S NO 5 WINDOW	247361
214	6/13/2008	170542 Drv entered - Passenger Doors Faulty Controls	CHECK AND ADJSUT SENITVE EDGE	241803
214	6/6/2008	170114 Drv entered - Body & Acc Mirrors Exterior		239521
214	6/6/2008	170114 Drv entered - Other		239521
214	6/6/2008	170114	Tension Wheel Nuts To OEM Specification	239521
214	6/6/2008	170114	A Service	239521
214	5/6/2008	167288 1MT MULTI FIT WIPER REFILL		229345
214	5/6/2008	167288 Drv entered - Wipers & Washers Rubber Adrift	REPLACE WIPER BLADES	228834
214	5/6/2008	167288 Drv entered - Passenger Doors Faulty Controls	CHECK DOOR OPERATION	228834
214	5/6/2008	167288 Drv entered - Elec & Light Interior Lights		228834
214	5/6/2008	167288 Drv entered - Elec & Light Interior Lights		228834
214	5/6/2008	167288 Drv entered - Elec & Light Interior Lights		228834
214	5/6/2008	167288 Drv entered - Elec & Light Altern Light		228834
214	5/6/2008	167288 Drv entered - Body & Acc Windows		228834
214	5/6/2008	167288 Drv entered - Brakes Other		228834
214	5/6/2008	167288	A Service	228834
214	5/6/2008	167288	Tension Wheel Nuts To OEM Specification	228834
214	5/6/2008	167288 Drv entered - Other	REPLACE SPOT LIGHT ABOVE FRONT DOOR	228834
214	5/1/2008	166803 replace front and rear brake pads	replace front and rear brake pads	226926
214	5/1/2008	166803 PAD SET	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:P55189 Receiving #:	227853
214	4/16/2008	165507 Drv entered - Comm Equip Faulty	checked operation on all chennels and found ok	221672
214	4/9/2008	164783 CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P54520 Receiving #:	222299
214	4/3/2008	164783 Drv entered - Other		217912
214	4/3/2008	164783 REPLACE O/S FRONT TYRE AND N/S REAR DRIVE TYRES		217912
214	4/3/2008	164783 Drv entered - Suspension Kneeling System		217912
214	4/3/2008	164439	A Service	217259
214	4/3/2008	164439	D-Service	217259
214	4/3/2008	164439 AIR FILTER MERC 0500LE		217259
214	4/3/2008	164439 OIL FILTER 1725+0500LE		217259
214	4/3/2008	164439 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		217259
214	4/3/2008	164439	Tension Wheel Nuts to Spec	217259

214	4/3/2008	164439		Tension Wheel Nuts To OEM Specification	217259
214	4/3/2008	164439		A Service	217259
214	3/19/2008	162044	CONSUMABLE SUPPLIES SURCHARGE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P53470 Receiving	213416
214	3/19/2008	162044	Direct Purchase - TYRES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P53470 Receiving	213416
214	3/19/2008	162044	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P53470 Receiving	213416
214	3/19/2008	162044	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P53470 Receiving	213416
214	3/19/2008	163536	n/s park light u/s		212751
214	3/15/2008	163261		Tension Wheel Nuts To OEM Specification	211504
214	3/15/2008	163261		A Service	211504
214	3/3/2008	162229	replace broken o/s front window	REPLACE BROKEN O/S NO2 WINDOW	207212
214	2/22/2008	162024	REPLACE LEAKING WATER PUMP ASSY		204835
214	2/18/2008	161249	REPLACE BRKEN N/S REAR WINDOWS	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P53140 Receiving #:472	203738
214	2/18/2008	161249	clean glass and replace broken n/s rear windows	REPLACE BROKEN N/S WINDOWS	203738
214	2/11/2008	162044	REPLACE N/S FRONT TYRE SIDEWALL DAMMAGED REI	REPLACE DAMMAGED N/S FRONT TYRE REPLACE NE/S REAR DRIVE T	202102
214	2/11/2008	160716	H1 GLOBE 24V 70W		201081
214	2/11/2008	160716	Drv entered - Elec & Light Headlights	replace headlamp globe	201081
214	2/11/2008	160816		A Service	201081
214	2/11/2008	160816		Tension Wheel Nuts To OEM Specification	201081
214	2/1/2008	159993	AIR CON. SWITCH KEPT FLICKERING EVENTUALY AIR CON STOPED W		199543
214	2/1/2008	159991	ALT. NOT CHARGING.		199543
214	1/8/2008	158061		A Service	192035
214	1/8/2008	158061		Tension Wheel Nuts To OEM Specification	192035
214	12/13/2007	156407		Tension Wheel Nuts To OEM Specification	183400
214	12/13/2007	156407		A Service	183400
214	11/28/2007	155195	BUS WILL NOT KNEEL PARK LAMPS STAY ON	LOCATE ELECTRICAL FAULT FOUND FAULTY 30 AMP MAIN SUPPLY FU	178394
214	11/14/2007	153873	RECAPS	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:P50609 Receiving	177078
214	11/9/2007	153873	REPLACE REAR DRIVE AXLE TYRES	REPLACE REAR DRIVE AXLE TYRES AND FIT TO O-E-M SPECS	173539
214	11/9/2007	153685		A Service	173300
214	11/9/2007	153685	AIR FILTER MERC 0500LE		173300
214	11/9/2007	153685	OIL FILTER 1725+0500LE		173300
214	11/9/2007	153685	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		173300
214	11/9/2007	153685		Tension Wheel Nuts to Spec	173300
214	11/9/2007	153685		D-Service	173300
214	11/9/2007	153685		Tension Wheel Nuts To OEM Specification	173300
214	11/9/2007	153685		A Service	173300
214	11/7/2007	153437	AIR CONDITIONER FAULT LIGHT ON.SEE FAULT DEFECT 145429.		172612
214	11/7/2007	153437	Drv entered - Air Cond Air Conditioner	UNIT RECTIFIED BY THERMOKING REPLACED LEAKING COMPRESSOF	172612
214	11/7/2007	153437	Drv entered - Elec & Light Interior Lights		172612
214	10/30/2007	152872	REPLACE WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P50298 Receiving #:447	171225
214	10/30/2007	152872	replace broken windscreen	REPLACE BROKEN WIND SCREEN	170639
214	10/10/2007	151432	REPAIR W/SCREEN	Creditor #:KNI003 KNIGHTS WINDSCREEN P/O #:P49862 Receiving #:	164919
214	10/10/2007	151432	repair chipped windscreen	REPAIR CHIPPED W/SCREEN	164578
214	10/10/2007	151421		A Service	164578
214	10/10/2007	151421		Tension Wheel Nuts To OEM Specification	164578
214	10/9/2007	151365	A/C NOT COOLING	REPLACE FAULTY HIGH PRESURE SWITCH AND CHECK OPERATION PE	164366
214	10/9/2007	151771	AIR CON. NOT WORKING FAULT LIGHT ON.	SE DEFECT 144814	164578
214	10/4/2007	150987	EMERGENCY HAMMERS		163163
214	10/4/2007	150987	REPLACE 2 MISSING EMRGNCY EXIT HAMMERS.		163163
214	9/19/2007	149913	Polish side panels	Polished	158281
214	9/19/2007	149913	Fit new wheel arch mould	Refitted wheel arch brush	158281
214	9/19/2007	149736	REPLACE WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:P49325 Receiving #:437	158606
214	9/18/2007	149785	DOOR OPEN LIGHT KEEPS ON WHEN DOORS ARE SHU	FOUND DOOR OVERRIDE SWITCH TURNED OFF	158006
214	9/18/2007	149736	REPLACE DAMMAGED W/SCREEN	TRVAEL TO ELETE WINSCREENS AND REPLACE WINDSCREEN	157659
214	9/13/2007	149385	A/C VIBROSOBER HOSE U/S	REPLACE VIBROSOBER HOSE AND RECHARGE SYSTEM	156135
214	9/13/2007	149397	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	156135
214	9/13/2007	149397	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	156135
214	9/13/2007	149397		Service T - Replace Transmission Oil & Filter	156135
214	9/13/2007	149397		Tension Wheel Nuts To OEM Specification	156135
214	9/13/2007	149397		A Service	156135
214	9/8/2007	148978		Tension Wheel Nuts To OEM Specification	154598
214	9/8/2007	148978		A Service	154598
214	8/10/2007	146620	Drv entered - Passenger Doors Require Adjusted	check and adjsut door speeds	145222
214	8/10/2007	146620	Drv entered - Passenger Doors Faulty Controls		145222
214	8/10/2007	146620	PARK BRAKE WARNING LIGHT COMES ON WHEN MO	check operation found ok	145222
214	8/10/2007	146620	Drv entered - Brakes Other	check brakes found ok road test and check	145222
214	8/10/2007	146620	Drv entered - Other		145222
214	8/10/2007	146620		Tension Wheel Nuts To OEM Specification	145222
214	8/10/2007	146620		A Service	145222

214	7/30/2007	144050 TYRE RECYCLE	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P46784 Receiving	145560
214	7/30/2007	144050 FITTING	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P46784 Receiving	145560
214	7/30/2007	144050 CASES	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P46784 Receiving	145560
214	7/30/2007	144050 11R22.5 SP327 P/C RTD	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P46784 Receiving	145560
214	7/27/2007	144246 ROAD SAFETY INSPECTIONS	Creditor #-:ROA001 Road Safety Inspections P/O #-:P47129 Receiving	145560
214	7/12/2007	144246 annual inspection		137276
214	7/10/2007	144050	Tension Wheel Nuts To OEM Specification	137276
214	7/10/2007	144050	A Service	137276
214	7/9/2007	143973 REPAIR AND REPAINT REAR BUMPER	REPAIR AND PANIT DAMMAGED REAR BUMPER AND N/S REAR HEAD	136816
214	7/2/2007	143407 REPLACE LEFT HAND SIDE MIRROR HEAD AND MIRROR	replace lh mirror arm	134921
214	6/22/2007	142780 Drv entered - Fuel Other		131968
214	6/22/2007	142780 FUEL CAP / FUEL TANK.UNDID CAP FILLED THEN HAD	modify fuel filler opening	131968
214	6/22/2007	142780 MODIFY FUEL FILLER HOLE		131968
214	6/21/2007	142658 MIRROR METAGAL L/H		131638
214	6/21/2007	142658 BROKEN LEFT MIRROR HEAD	REPLACE BROKEN MIRROR HEAD	131638
214	6/18/2007	141505 PANELS AS PER SAMPLES	Creditor #-:VOL001 VOLGREN AUSTRALIA P/L P/O #-:P44918 Receiving	130962
214	6/6/2007	141507	Check oil level in transmission & top-up if required	128834
214	6/6/2007	141507	Remove disassemble & clean cyclone separator (apply water repellent)	128834
214	6/6/2007	141507	Check & clean filter cartridge in dry-type air cleaner	128834
214	6/6/2007	141507	Check power steering oil level	128834
214	6/6/2007	141507	Change pre and main fuel filter	128834
214	6/6/2007	141507	Change air drier cannister; clean silencer & drain air reservoir	128834
214	6/6/2007	141507	Change oil in fan angle drive	128834
214	6/6/2007	141507	Top-up coolant level (must equate to -37C frost protection)	128834
214	6/6/2007	141507	Adjust Engine Valve Clearance	128834
214	6/6/2007	141507	Electrical - BATTERIES: check fluid level (leave air gap when topping up)	128834
214	6/6/2007	141507	Inspect radiator & charge-air cooler for dirt - clean if required	128834
214	6/6/2007	141505 REPLACE DAMMAGED O/S NO 4 PANEL AND O/S REAR	replace o/s no 4and 5 panels panit and fit to vehicle	128834
214	6/6/2007	141506 AIR FILTER MERC 0500LE		128834
214	6/6/2007	141506 OIL FILTER 1725+0500LE		128834
214	6/6/2007	141506 ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		128834
214	6/6/2007	141506	Tension Wheel Nuts to Spec	128834
214	6/6/2007	141506	A Service	128834
214	6/6/2007	141506	D-Service	128834
214	6/6/2007	141506	A Service	128834
214	6/6/2007	141506	Tension Wheel Nuts To OEM Specification	128834
214	5/2/2007	138404 CASE	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	5/2/2007	138404 TYRE RECYCLE	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	5/2/2007	138404 BALANCE BUS-	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	5/2/2007	138404 Fitting	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	5/2/2007	138404 11R22.5 SP327 P/C RTD	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	5/2/2007	138404 11R22.5 148/145L TL SP350A DUN	Creditor #-:BEA001 BEAUREPAIRES P/O #-:P43123 Receiving #-:40346 C	119218
214	4/27/2007	138404 Drv entered - Whls & Tyres Vibrate	replace front tyres	117911
214	4/27/2007	138721 Drv entered - Steering Pulls Left		118281
214	4/27/2007	138721 Drv entered - Passenger Doors Faulty Controls		118281
214	4/27/2007	138404 COMPARED WITH OTHER MERCS THE RETARDER IS H/	checked and found ok	117911
214	4/27/2007	138393	A Service	117911
214	4/27/2007	138393	Tension Wheel Nuts To OEM Specification	117911
214	4/10/2007	137118 Ops Entered - Passenger Doors	repair and check all door top rollers comming loose adjusst and chec	113888
214	4/3/2007	137313 HEADLIGHT OUT	REPLACE HEADLIGHT GLOBE NOISE COMMING FROM FRONT DOOR L	112928
214	4/2/2007	137144 Service	guide bar n/s/f door bent fixedreline door all ok	112598
214	3/19/2007	135519	Tension Wheel Nuts To OEM Specification	108987
214	3/19/2007	135519	A Service	108987
214	3/13/2007	135032 A/C BELT 0500 BENZ		107138
214	3/13/2007	135032 REPLACE LOWER ALT BELT	replace engine drive belt	107138
214	3/2/2007	134461 DRIVERS BLIND BROKEN	DISMANTLE AND REPAIR DRIVERS BLIND WORK OK IF ONLY PULLED C	104348
214	2/26/2007	133852 Drv entered - Passenger Doors Faulty Controls		103417
214	2/26/2007	133852 Drv entered - Passenger Doors Require Adjusted		103417
214	2/26/2007	133852 R H Rear clearance lamp broken		103417
214	2/26/2007	133852 HAND BRAKE LIGHT COMES ON INTERMITANTLY		103417
214	2/13/2007	133317 REAR DOOR STICKING CLOSED PUSH BUTTON TO OPEI	CHECK AND ADJUST DOOR SENITVE EDGE	99522
214	2/8/2007	131715 Direct Purchase - TYRES	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P38532 Receiving	98597
214	2/8/2007	131715 FITTING	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P38532 Receiving	98597
214	2/8/2007	131715 CASES	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P38532 Receiving	98597
214	2/8/2007	131715 11R22.5 SP327 P/C RTD	Creditor #-:BEA002 BEAUREPAIRES FOR TYRES P/O #-:P38532 Receiving	98597
214	1/25/2007	131715 REPLACE WORN TYRES	REPLACE REAR TYRES AND FIT TO O-E-M SPECS	95004
214	1/25/2007	131535 Drv entered - Passenger Doors Faulty Controls	CHECKED DURING SERVICE. FOUND TO BE WORKING CORRECTLY.	95004
214	1/25/2007	131535 Drv entered - Passenger Doors Faulty Controls	CHECKED DURING SERVICE. FOUND TO BE OPERATING PROPERLY.	95004

214	1/25/2007	131535		Tension Wheel Nuts To OEM Specification	95004
214	1/25/2007	131535		A Service	95004
214	12/21/2006	128428	11R22.5 SP327 P/C RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:37029 Receiving	86852
214	12/21/2006	128428	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:37029 Receiving	86852
214	12/21/2006	128428	FITTING	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:37029 Receiving	86852
214	12/21/2006	128428	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:37029 Receiving	86852
214	12/12/2006	128610	PULLS TO LEFT	no fault found	84415
214	12/12/2006	128531		D-Service	84415
214	12/12/2006	128531		A Service	84415
214	12/12/2006	128531		Tension Wheel Nuts to Spec	84415
214	12/12/2006	128531	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		84415
214	12/12/2006	128531	OIL FILTER 1725+0500LE		84415
214	12/12/2006	128531		A Service	84415
214	12/12/2006	128531		Tension Wheel Nuts To OEM Specification	84415
214	12/11/2006	128428	REPLACE LEFT HAND REAR OUTER FLAT TYRE		84226
214	12/7/2006	127905	WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:36824 Receiving #:3684	82900
214	12/6/2006	128142	rear door will not close opisite tyabb football ground	recover bus from tyabb and return to depot repair top rear door pivc	82664
214	12/4/2006	127905	replace broken windscreen	REPLACE BROKEN WINDSCREEN	82141
214	11/20/2006	126719	REPLACE UPPER ALT BELT		78614
214	11/20/2006	126720	Ops Entered - Swap	NNA	78614
214	11/20/2006	126719	TOP ALT BELT 0500LE		78614
214	11/4/2006	125541		Tension Wheel Nuts To OEM Specification	74929
214	11/4/2006	125541		A Service	74929
214	10/7/2006	123335		A Service	66889
214	10/7/2006	123335		Tension Wheel Nuts To OEM Specification	66889
214	10/6/2006	123338	replace lower alt drive belt	replace lower alt drive belt	66889
214	10/6/2006	123338	ALTERNATOR BELT		66889
214	10/2/2006	122842	replace lower alt drive belt	REMOVE AND REPLACE LOWER ALT BELT	65681
214	9/28/2006	122368	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:35054 Receiving #:	65131
214	9/23/2006	122368	annaul inspection	BC099794	63832
214	9/22/2006	122321	PANIT WHEELS AND TYRES		63832
214	9/21/2006	122168	Service		63832
214	9/20/2006	122168	REPAIR N/S FRONT HEADER DAMAGE AND PANIT		63446
214	9/20/2006	122168	repair o/s no 5 panel and paint and replace decals		63446
214	9/15/2006	121843		Check power steering oil level	62360
214	9/15/2006	121843		Change air drier cannister; clean silencer & drain air reservoir	62360
214	9/15/2006	121843		Change pre and main fuel filter	62360
214	9/15/2006	121843		Check & clean filter cartridge in dry-type air cleaner	62360
214	9/15/2006	121843		Remove disassemble & clean cyclone separator (apply water repella)	62360
214	9/15/2006	121843		Check oil level in transmission & top-up if required	62360
214	9/15/2006	121843		Inspect radiator & charge-air cooler for dirt - clean if required	62360
214	9/15/2006	121843		Electrical - BATTERIES: check fluid level (leave air gap when topping u	62360
214	9/15/2006	121843		Adjust Engine Valve Clearance	62360
214	9/15/2006	121843		Top-up coolant level (must equate to -37C frost protection)	62360
214	9/15/2006	121843		Change oil in fan angle drive	62360
214	9/12/2006	120931	CASE	Creditor #:BEA001 BEAUREPAIRES P/O #:34583 Receiving #:34776 Da	61913
214	9/12/2006	120931	11R22.5 SP327 P/C RTD	Creditor #:BEA001 BEAUREPAIRES P/O #:34583 Receiving #:34776 Da	61913
214	9/12/2006	120931	TYRE RECYCLE	Creditor #:BEA001 BEAUREPAIRES P/O #:34583 Receiving #:34776 Da	61913
214	8/31/2006	120931	replace worn tyre pos 3 and fit to o-e-m specs		58038
214	8/31/2006	120744	Ops Entered - Passenger Doors		58038
214	8/31/2006	119756	Service	fit new inter cooler hose	58189
214	8/31/2006	120750		Service T - Replace Transmission Oil & Filter	58038
214	8/31/2006	120750	TEXAMATIC 1888	Transmission Oil	58038
214	8/31/2006	120750	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	58038
214	8/31/2006	120750		Tension Wheel Nuts To OEM Specification	58038
214	8/31/2006	120750		A Service	58038
214	8/28/2006	120437	fit large cappactiy fuel tanks	fitted by whitourse trucks	57765
214	8/23/2006	119756	INTERCOOLER HOSE	Creditor #:MERO01 DAIMLER CHRYSLER AUSTRALIA P/O #:34224 Rec	57022
214	8/21/2006	119741	SUPPLY + FIT FRONT WINDSCREEN	Creditor #:ELI001 ELITE WINDSCREENS P/O #:34221 Receiving #:3424	56304
214	8/18/2006	119756	replace dammaged intercooler inlet hose		55568
214	8/18/2006	119741	REPLACE CRACKED WINDSCREEN	replace windscreen performed by elete windcreens	55568
214	8/16/2006	119619	Drv entered - Passenger Doors Faulty Controls interm	CHECK AND ADJUST REAR DOOR SENITIVE EDGE ASSY	55051
214	8/11/2006	119239	LED CLEARANCE LIGHT (RED AMBER)		54110
214	8/11/2006	119239	replace broken n/s clearance lamp assy broken	REPLACE BROKEN CLEARANCE LAMP ASSY	54110
214	8/5/2006	118756		A Service	52153
214	8/5/2006	118756		Tension Wheel Nuts To OEM Specification	52153
214	8/3/2006	118590	park light stop lights on dash sometimes flash on whe	FOUND TO BE RAMP LIGHT SWITCH ADJSUTED	51866
214	8/3/2006	118591	Air drier passing oil	CHECKED AND OPERATION FOUND OK IS NORMAL OPERATION AFTEF	51866

214	7/31/2006	118205	Rear left light housing broken.	REPLACE BROKEN LAMP UNIT	50362
214	7/31/2006	118205	LED CLEARANCE LIGHT (RED AMBER)		50950
214	7/27/2006	118104	CHECK AND ADJUST ALT DRIVE BELTS	check and adjust alt drive belts	49996
214	7/20/2006	117621	CHECK AND RECONFIGURE COOLING FAN SPEED	task performed by benz aust	48427
214	7/20/2006	119156	rear left clearance light broken	replace led marker lamp	48427
214	7/20/2006	119156	LED CLEARANCE LIGHT (RED AMBER)		48644
214	6/29/2006	115125	TYRE RECYCLE	Creditor #:BEA001 BEAUREPAIRES P/O #:32760 Receiving #:32994 Da	46342
214	6/29/2006	115125	11R22.5 SP327 P/C RTD	Creditor #:BEA001 BEAUREPAIRES P/O #:32760 Receiving #:32994 Da	46342
214	6/29/2006	115125	11R22.5 A GRADE CASING	Creditor #:BEA001 BEAUREPAIRES P/O #:32760 Receiving #:32994 Da	46342
214	6/15/2006	115125		D-Service	44530
214	6/15/2006	115125	Service	Replaced pos 3 & 4 tyres	44530
214	6/15/2006	115125	Service	Tension Wheel Nuts To OEM Specification	44530
214	6/15/2006	115125		A Service	44530
214	6/9/2006	113707	11R22.5 SP331 P/CURE RTD	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:32305 Receiving	43700
214	6/9/2006	113707	CASES	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:32305 Receiving	43700
214	6/9/2006	113707	TYRE RECYCLE	Creditor #:BEA002 BEAUREPAIRES FOR TYRES P/O #:32305 Receiving	43700
214	5/24/2006	113707	REPLACE O/S REAR TYRES		38141
214	5/24/2006	113696		A Service	38141
214	5/24/2006	113696		Tension Wheel Nuts To OEM Specification	38141
214	5/18/2006	113185	REPAIR W/SCREEN	Creditor #:KNI003 KNIGHTS WINDSCREEN P/O #:32025 Receiving #:3	36982
214	5/18/2006	113182	STICKER SMALL NO FOOD OR DRINK	Creditor #:BUS002 BUS SALES P/O #:32024 Receiving #:32021 Date :2	36982
214	5/17/2006	113169	WROTE UP NO HEAT 3 WEEKS AGO FIRST TIME DRIVEN IN 3 WEEKS		36362
214	5/17/2006	113169	heating took forever to warm up		36362
214	5/17/2006	113180	w/screen wipers ceased working in down storm for a	found water entry into wiper motor plug and cleaned and greased and oiled on check	36362
214	5/17/2006	113169	DEMISTER HEAT ONLY A/C JUST BLEW COLD AIR	SERVICE PERFORMED BY SOUTHERN STATES THRMO KING FOUND SE	36362
214	5/17/2006	113185	REPAIR O/S WINDSCREEN CHIP	REPAIR WINDSCREEN CHIP	36362
214	5/17/2006	113182	There are no drinking or eating decals fitted to bus		36362
214	4/21/2006	111423	REPLACE BROKEN N/S CLEARANCE LAMP	remove and replace n/s rear clearance lamp assy	27837
214	4/21/2006	111423		Service T - Replace Transmission Oil & Filter	27837
214	4/21/2006	111423	TEXAMATIC 1888	Transmission Oil	27837
214	4/21/2006	111423	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	27837
214	4/21/2006	111423		Tension Wheel Nuts To OEM Specification	27837
214	4/21/2006	111423		A Service	27837
214	4/3/2006	110250	reversing alarm not working {intermitant}		23276
214	3/29/2006	109897		A Service	22012
214	3/29/2006	109897		Tension Wheel Nuts To OEM Specification	22012
214	3/17/2006	113444	VINAL UNDER RUBBISH BIN COMMING OFF	WARRENTY PERFORMED BY VOLGREN AUST	17470
214	3/16/2006	109051	replace a/c compressor drive belt	REMOVE AND REPLACE DRIVE BELT ASSY	17024
214	3/16/2006	109051	A/C BELT 0500 BENZ		17024
214	3/16/2006	109044	BUFF BLACK MARK OFF N/S	buff mark off side of bus	17024
214	3/7/2006	108329	FAN-HUB BELT SCANIA 12.5X1330MM		13922
214	3/7/2006	108329	replace lower alt belt	REPLACE LOWER ALT BELT AND CHECK ADJSUTMENT	13922
214	3/2/2006	106743	EXCESS	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:29967 Receiving #	12284
214	2/24/2006	107679		A Service	10380
214	2/24/2006	107679		Tension Wheel Nuts	10380
214	2/24/2006	107679	Service	Tension Wheel Nuts	10380
214	2/10/2006	106743	REPAIR N/S AND O/S PANEL DAMMAGE REPLACE BATTERY PANEL DAMM		10236
214	2/2/2006	105478	1ST WARRENTY SERVICE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:29561 Receiving #:2	7737
214	1/25/2006	105478	1st warrenty service	PERFORMED BY WHITE HOUSE TRUCKS DANDY	5512
214	1/25/2006	105477	ENGINE BLOWING WITHE SMOKE AFTER START UP ST	FOUND ENGINE OIL LEVAL TO HIGH STEERING WHEEL STRAGHTED AP	5512
214	1/24/2006	105479	WINDSCREEN FRACTURE REPAIRS	Creditor #:KNI003 KNIGHTS WINDSCREEN P/O #:29563 Receiving #:2!	5512
214	1/23/2006	105463	ENGINE BLOWING SMOKE	ENGINE OVER FILLED WITH OIL	5512
214	1/23/2006	105479	REPAIR WINDSCREEN CHIP	repair windscreen chip	5512
214	1/13/2006	104829	ALT LIGHT GLOWING	alt repair affected by white house truck center dandy	4836
214	12/30/2005	104074	SECURTIY SYSTEM NOT WORKING	RECORDING UNIT FOUND FAULTY AND REPLACED	465