



Commercial Vehicle Inspection Report

Decal Number: GK28004
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21418523

Inspection Result:
PASS

FACILITY: A BIG WRENCH TRUCK TRAILER REPAIR / S17201
INSPECTOR: QIN, GUAN / 202014
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Jul-08 02:30 PM PDT
INSP. COMPLETE: 2025-Jul-08 04:15 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 14640K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2009
MAKE: GREAT DANE
MODEL:
REGI: 13156175
UNIT/FLEET#:
BODY STYLE: Semi Trailer
ODOMETER:
HUB ODOMETER: 85353 KM
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1GRAA062X9T551208
OWNER/LESSEE NAME: CORPORATE, COURIERS LOGISTIC
ADDRESS: 101B-3738 NORTH FRASER WAY
Burnaby, British Columbia
V5J 5G7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	34	34	4	4	4	10	
2	Clamp	30	Automatic	34	34	4	4	4	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	55	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: QIN, GUAN

Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-08 04:29 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CV/SE0014

7/8/2025 4:29:20 PM PDT