R13-4

Commercial Vehicle Inspection Report

Decal Number: GN57083
Decal Expiry Date: 2027-May-31
Inspection Number: 21989956 20262S2

Inspection Result: **PASS**

FACILITY:	PACIFIC COAST HEAVY TRUCK GROUP - KAMLOOPS / S6321	INSP. TYPE:	Complete	INSP. START:	2026-Nov-13 08:00 AM PDT
		INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Nov-13 11:53 AM PDT
INSPECTOR:	DESABRAIS, MORGAN CHANCE / 114532	INSP. REASON:	Semi-annual		
WORK ORDER #:	24504				

VEHICLE JUR:	British Columbia	REGI:	13187499	VIN:	3HSDZAPR1KN561536
PLATE #:	51716P	UNIT/FLEET#:		OWNER/LESSEE NAME:	KAL TIRE TRANSPORT LTD., KAL TIRE TRANSPORT LTD.
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	1540 KALAMALKA LAKE RD
VEHICLE YEAR:	2019	ODOMETER:	698043 KM		Vernon, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V1T 6V2, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	**Repaired (same day)**	CHECK ENGINE LIGHT ON
Section 2 - Suspension	Passed	
Section 3 - Brake System	**Repaired (same day)**	#2RH WHEEL SEAL LEAKING ONTO BRAKES
Section 3A - Air Brakes	**Repaired (same day)**	AIR LEAK WITH BRAKE APPLICATION AT REAR
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	**Repaired (same day)**	RH BEACON AMBER COVER FALLEN OFF
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	35	35
2	Clamp	30L	Automatic	38	38
3	Clamp	30L	Automatic	38	38

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			14	✓
9	9	8	10	
8	8	21	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	25
2	55	55
3	65	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	20
Lining (Shoe)	17	17
Lining (Shoe)	16	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: DESABRAIS, MORGAN CHANCE **Signature:**

This Inspection Report was submitted to CVSE on 2026-Nov-13 11:54 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

11/13/2026 11:54:32 AM PDT