

505**Own Plant****505: Thwaites 9 tonne ADT 24351D****Tippers Daily****Service History**

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
29/11/2013	Scheduled Maintenance	- Carry out 250hr service (1st service performed by Thwaites dealer)	251
24/05/2014	Scheduled Maintenance	- Carry out 500hr service - Replace RHS E stop	481
16/02/2015	Scheduled Maintenance	- Carry out 500hr service	881
20/05/2015	Scheduled Maintenance	- Carry out 1000hr service	1058
20/08/2015	Scheduled Maintenance	- Carry out 250hr service	1205
23/12/2015	Scheduled Maintenance	- Carry out 500hr service	1525
24/11/2016	Scheduled Maintenance	- Carry out 2000hr service	2005
14/06/2017	Scheduled Maintenance	- Carry out 250hr service - Rectify bottom articulation pin not taking grease - Replace broken grease nipples	2260
26/09/2017	Scheduled Maintenance	- Carry out 500hr service	2500

505

Own Plant

505: Thwaites 9 tonne ADT 24351D

Tippers Daily

Service History

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
27/11/2017	Scheduled Maintenance	- Free up seized park brake calliper and sdjust park brake	2634
14/12/2017	Scheduled Maintenance	- Modify steer cylinder ends to take self aligning bearings - Fabricate and install toolbox for grease gun etc - Replace horn - Replace number plate lights - Checksheet	2649
18/04/2018	Scheduled Maintenance	- Carry out 250hr service performed by Technics plant repairs - service	2812
01/08/2018	Scheduled Maintenance	- Carry out 1000 hr service	3015

505**Own Plant****505: Thwaites 9 tonne ADT 24351D****Tippers Daily****Service History**

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
07/09/2018	Scheduled Maintenance	- Replace gas struts in canopy - Replace drivers seat - Replace parkbrake pads and adjust - Spiral wrap hoist cylinder hoses - Repair lights and blinkers not working - Replace amber beacon - Repair reverse camera not working - check sheet machine - repair	3071
19/12/2018	Scheduled Maintenance	- Carry out 250 hr service - Weld in new floor in tipping body - Replace ROPS struts	3322
14/05/2019	Scheduled Maintenance	- Carry out 500 hr service	3542
02/07/2019	Scheduled Maintenance	- Replace fuel filter priming pump assembly	3616
29/10/2019	Scheduled Maintenance	- Adjust park brake	3941

505

Own Plant

505: Thwaites 9 tonne ADT 24351D

Tippers Daily

Service History

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
11/12/2019	Scheduled Maintenance	- Carry out 2000 hr service - Rewire rotating beacon	4039
09/01/2020	Scheduled Maintenance	- Replace brake pads for park brake - Adjust park brake - Repair oil leak on hydraulic tank	4062
09/05/2020	Scheduled Maintenance	- Replace rotating beacon - Replace seat belt	4279

505**Own Plant****505: Thwaites 9 tonne ADT 24351D****Tippers Daily****Service History**

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
13/07/2020	Scheduled Maintenance	- Carry out 250 hr service - Replace pins, bearings and seals in articulation - Replace seat - Replace roof struts - Repair fuel leak - Repair hole in muffler - Reseal steer cylinder and replace bearings - Repair backup alarm - Free up inching pedal - Checksheet	4341
22/09/2020	Scheduled Maintenance	- Repair broken wire for cold start solenoid switch - Run new wire for hour meter	4421
14/10/2020	Scheduled Maintenance	- Carry out 500 hr service	4470
07/04/2021	Scheduled Maintenance	- Rebuild park brake assembly - Pump up tyres	4655

505**Own Plant****505: Thwaites 9 tonne ADT 24351D****Tippers Daily****Service History**

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
21/04/2021	Scheduled Maintenance	- Replace rotating beacon - Replace RHS E stop - Free up sticking seat belt buckle	4664
27/04/2021	Scheduled Maintenance	- Replace seat belt	4673
25/05/2021	Scheduled Maintenance	- Carry out 250 hr service	4760
08/06/2021	Scheduled Maintenance	- Replace blown body lift cylinder hose	4799
16/06/2021	Scheduled Maintenance	- Adjust park brake	4806
09/10/2021	Scheduled Maintenance	- Carry out 1000 hr service - Adjust park brake - Repair wiring to rotating beacon	5035
25/10/2021	Scheduled Maintenance	- Repair body tipping valve - Repair struts for ROPS - Replace final drive oils	5050

505

Own Plant

505: Thwaites 9 tonne ADT 24351D

Tippers Daily

Service History

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
03/02/2022	Scheduled Maintenance	- Replace body tipping valve control assembly - Replace cold start switch	5180
15/02/2022	Scheduled Maintenance	- Replace battery and starter motor	5190
07/06/2022	Scheduled Maintenance	- Carry out 250 hr service - Repair LHS E stop - Adjust park brake - Replace faulty inching pedal switch	5376
11/07/2022	Scheduled Maintenance	- Replace HMU steering valve - Replace steering column - Replace steering wheel	5398
02/08/2022	Scheduled Maintenance	- Replace inching pedal switch	5430

505

Own Plant

505: Thwaites 9 tonne ADT 24351D

Tippers Daily

Service History

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
21/09/2022	Scheduled Maintenance	- Carry out 500 hr service - Replace exhaust tail pipe - Replace air cleaner box - Replace steer cylinder bearings - Repair beacon wiring	5514
17/11/2022	Scheduled Maintenance	- Carry out 250 hr service - Repair E stop wiring	5624
02/02/2023	Scheduled Maintenance	- Replace front brake supply hose and bleed up brakes - Repair damaged wiring on top of transmission	5791
23/03/2023	Scheduled Maintenance	- Carry out 2000 hr service - Replace turntable circle cylinder pins - Repair bush in chassis for turntable pin - Repair damaged RHS turntable cylinder - Repair turntable lock - Adjust hand brake	5945

505**Own Plant****505: Thwaites 9 tonne ADT 24351D****Tippers Daily****Service History**

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
13/07/2023	Scheduled Maintenance	- Replace hydraulic cooler	6144
28/08/2023	Scheduled Maintenance	- Adjust park brake	6250
21/09/2023	Scheduled Maintenance	- Repair puncture POS2 wheel going flat - Carry out 250 hr Service - Replace steering cylinder bearing barrel end - Repair damaged wiring harness to coolant sensor - repaired	6273
20/12/2023	Scheduled Maintenance	- Replace starter motor supplied by Napa	6392
22/01/2024	Scheduled Maintenance	- Replace park brake pads - Replace seat assembly (Supplied by EEA)	6415
27/02/2024	Scheduled Maintenance	- Replace gear selector - Adjust park brake	6475
28/02/2024	Scheduled Maintenance	- Carry out 500 hr service - Repair rotating beacon	6477

505

505: Thwaites 9 tonne ADT 24351D

Service History

Own Plant

Tippers Daily

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
04/06/2024	Scheduled Maintenance	- Replace ignition barrel - Repair rotating beacon wiring	6652
08/08/2024	Scheduled Maintenance	- Adjust perk brake	6725
15/04/2025	Scheduled Maintenance	- Carry out 1000 hr service - Adjust park brake - Replace both steer cylinder hoses	7121
23/09/2025	Scheduled Maintenance	- Adjust park brake	7374
01/10/2025	Scheduled Maintenance	- Replace park brake pads and adjust	7386
12/11/2025	Scheduled Maintenance	- Carry out 500 hr service	7459
16/02/2026	Scheduled Maintenance	- Replace steer cylinder bearing - Repair headlight switch/ handle - Repair chaffed harness - Repair LHS front parker light - Check sheet	7659