

R65-6

Commercial Vehicle Inspection Report

Decal Number: GC67388
Decal Expiry Date: 2025-May-31
Inspection Number: 20935280

Inspection Result:
PASS

WORK ORDER #: T1051

INSPECTOR: KAL Lally, Satnam Singh

TRUCK: 95383

INSR TYPE:

Complete

INSR START:

2024-May-16 02:30 PM PDT

INSR CLASS:

Class 3 - Trailer and Semi-Trailer

INSR COMPLETE:

2024-May-17 12:26 PM PDT

INSR REASON:

Annual

VEHICLE JUR: British Columbia
PLATE #: 33407K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2023
MAKE: UTILITY
MODEL:

REGI: 14056084
UNIT/FLEET#: T1051
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1UYVS2538P3640501
OWNER/LESSEE NAME: TRIDENT ROAD LINE GROUP LTD.,
ADDRESS: 212 12380 80 AVE, 212 12380 80 AVE
Surrey, British Columbia
V3W3A3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	37	35	7	6	6	6	
2	Clamp	30	Automatic	34	36	6	6	5	6	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)		Left	Right	Rotor Thickness or Drum Inside Diameter (mm)		
			Lining/Pad				Rotor/Drum	Left	Right
1	78	76	Lining (Shoe)		14	14	Drum		
2	76	80	Lining (Shoe)		14	13	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured. DNR

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

Inspector: Lally, Satnam Singh
This Inspection Report was submitted to CVSE on 2024-May-17 12:26 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

