

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2019 International DuraStar 4300****Test Information**

Engine	Cummins B 6.7 (6.7)
Engine Serial	CMMNS*6B u17D0670000000*74407250
VIN	1HTMMMMP8KH387327
Driveline	Class 7 4x2
Body	Truck MDHD: Conventional
Test Time	Aug. 28, 2025, 12:27 p.m.
File Length	43.807 s

Usage

Label	Value	Units
Engine Odometer	236,116	mi
Odometer (Instrument Cluster #1)	236,116	mi
Engine Total Hours of Operation	9,241.9	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	17	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Instrument Cluster #1	Source Address 33	Abnormal Update Rate	1
Previous	Body Controller	Windshield Wiper Motor ON/OFF	Current Below Normal	6
Previous	Body Controller	Windshield Wiper Motor Speed	Current Below Normal	2
Previous	Body Controller	Hydraulic Brake Fluid Level Switch	Low-most severe	126
Previous	Body Controller	Horn	Special Instruction	11
Previous	Body Controller	Manufacturer Assignable SPN	Current Below Normal	3
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Source Address 0	Data Error	1
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	4
Previous	Body Controller	Wiper Motor	Current Above Normal	126