R69-7

Commercial Vehicle Inspection Report

Decal Number: GN86409
Decal Expiry Date: 2027-Jul-31
Inspection Number: 21842895 2026282

Inspection Result: **PASS**

FACILITY:	RYDER TRUCK RENTAL - DELTA / S4595	INSP. TYPE:	Complete	INSP. START:	2026-Jul-10 08:38 AM PDT
		INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jul-10 09:38 AM PDT
INSPECTOR:	Blades, Glenn Russell / 112756				
WORK ORDER #:		INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	12920396	VIN:	3ALACXFC4KDLH4157
PLATE #:		UNIT/FLEET#:	878388	OWNER/LESSEE NAME:	ryder, truck rental
LICENCED GVW(kg):	15000	BODY STYLE:	Van	ADDRESS:	1699 cliveden ave
VEHICLE YEAR:	2019	ODOMETER:	326891 KM		Delta, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			v3m6v5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Disc	N/A	Not Applicable	0	0

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.1			11.1	✓
8.7	7.9	6.4	7.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	15.9	15.9
Pad	12.7	12.7

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor	39.81	39.92
Rotor	39.75	39.66

Comment:

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: Blades, Glenn Russell Signature:

This Inspection Report was submitted to CVSE on 2026-Jul-10 09:39 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/10/2026 9:39:16 AM PDT