

Vehicle Service Records (VSR Explorer)

Repair history MA5-809225

Registration nr: 194XYR **Chassis ID:** MA5-809225 **VIN:** 6FMM12H69JD809225
Market type: **Country:** **Delivery date:** 2018-5-2

PC	Type	Code	Description (Original)	#
   <u>2025-09-27 - Mileage: 969486 - Order nr: 3370617</u>				
		VO-1774600	Annual service. Chassis lubrication and	2.4
			oil changes included only in some models	
		VO-2330600	Fuel filter, replace (one)	0.1
		VO-1750400	Lubrication according to actual lubricat	0.3
			lubrication chart	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
			area	
		VO-2331100	Filter, water separator, replace	0.2
		VO-1751100	Lubrication of fifth wheel	0.1
		VO-1758900	Lubrication of trailer hitch	0.1
		VO-1784600	Trailer coupling, safety and function ch	0.3
			check	
		10	SUBLET: FABBRO'S AYR - ANNUAL SERVICE	
		VO-2141300	Valves and unit injectors, adjust	2.2
		VO-5616600	Air drier cassette, replace	0.4
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-6452500	Oil filter, power steering, replace	0.2
		VO-8747400	Air filter insert, A/C unit, replace	0.3
		VO-85114535	FILTER KIT (MP8/10 OIL & FUEL)	1

PC	Type	Code	Description (Original)	#
		VO-85151124	A/C FILTER (CAB AIR/POLLEN	1
		AU2-CHE23068344	20L VOLVO ENGINE OIL VDS-4.5	40
		VO-85129688	FILTER (AIR DRIER)	1
		MK-5839-870678A	FILTER (POWER STEERING)	1
		VO-21954674	STRAINER (AD-BLUE PUMP)	1
		VO-23381558	FILTER (AD-BLUE PUMP)	1
		VO-1161995	ATF DEXTRON 3 5L	1
		86	Sublet Surcharge	

2025-08-29 - Mileage: 956323 - Order nr: 3370325

		VO-1750400	Lubrication according to actual lubricat	0.3
			lubrication chart	
		10	SUBLET: FABBRO'S AYR - LUBE SERVICE	
		AU2-CHE85121792	BULLDOG HP GREASE	1
		86	Sublet Surcharge	

2025-07-26 - Mileage: 944792 - Order nr: 3369872

		VO-1774400	Basic service. Chassis lubrication and o	1.3
			oil changes included only in some models	
		VO-2330600	Fuel filter, replace (one)	0.1
		VO-1750400	Lubrication according to actual lubricat	0.3
			lubrication chart	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
			area	
		VO-2331100	Filter, water separator, replace	0.2
		10	SUBLET: FABBRO'S AYR - BASIC SERVICE	
		AU2-CHE85121792	BULLDOG HP GREASE	1
		VO-85114535	FILTER KIT (MP8/10 OIL & FUEL)	1
		VO-20579690	GASKET (SUMP PLUG)	1
		AU2-CHE23068344	20L VOLVO ENGINE OIL VDS-4.5	40
			AIR CLEANERS CHANGED THIS SERVICE - FABBRO'S AYR.	
		86	Sublet Surcharge	

2025-06-19 - Mileage: 931699 - Order nr: 3369525

			LAST SERVICE BASIC @ 919313 KMS 09.05.2025	
		VO-1750400	Lubrication according to actual lubricat	0.3
			lubrication chart	
			TRAVELLED 12386 KMS	
	*	10	FABBRO DIESEL SERVICES	
		AU2-CHE85121792	BULLDOG HP GREASE	1
	*	86	Sublet Surcharge	

2025-05-09 - Mileage: 919313 - Order nr: 3369101

		VO-1774400	Basic service. Chassis lubrication and o	1.3
			oil changes included only in some models	
		VO-2330600	Fuel filter, replace (one)	0.1
		VO-1750400	Lubrication according to actual lubricat	0.3
			lubrication chart	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
			area	
		VO-7714500	Wheel nuts, check tightening (all)	0.3
		VO-2331100	Filter, water separator, replace	0.2
		VO-1751100	Lubrication of fifth wheel	0.1
		VO-1758900	Lubrication of trailer hitch	0.1
		VO-1784600	Trailer coupling, safety and function ch	0.3
			check	
	*	10	SUBLET: FABBRO'S AYR - BASIC SERVICE	
		AU2-CHE85121792	BULLDOG HP GREASE	1
		VO-85114535	FILTER KIT (MP8/10 OIL & FUEL)	1
		VO-20579690	GASKET (SUMP PLUG)	1
		AU2-CHE23068344	Volvo VDS-4.5 20LT	40
	*	86	Sublet Surcharge	

2025-01-23 - Mileage: 908443 - Order nr: 3367970

PC	Type	Code	Description (Original)	#
	*	NSD	Next Service Due in Approx. 12500km	
	📅		This OSP:905 (LUBE)	
ⓐ	🔧	VO-1750400	Lubrication according to actual lubricat	0.3
	📅		lubrication chart	
ⓐ	🔧	VO-2601000	Coolant, change	0.4
ⓐ	*	10	SUBLET: FABBRO'S DIESEL SERVICES	
ⓐ	📦	AU2-CAL85121792	BULLDOG HP GREASE NL	1
ⓐ	📦	AU2-AMP24332694	MACK VCS-2 COOLANT 20LT	40
	📅		Next OSP: 918 (BASIC)	
ⓐ	*	86	Sublet Surcharge	

📅 🗣️ ⓐ 2024-11-19 - Mileage: 891850 - Order nr: 3367333

ⓐ	🔧	VO-1774600	Annual service. Chassis lubrication and	2.4
ⓐ	🔧	VO-2562700	Filter insert, air cleaner, replace. Onl	0.2
	📅		Only valid for primary filter	
ⓐ	🔧	VO-3212300	Alternator belt, replace	0.3
ⓐ	🔧	VO-2630700	Drive belts fan, replace	0.4
ⓐ	🔧	VO-2330600	Fuel filter, replace (one)	0.1
ⓐ	🔧	VO-1750400	Lubrication according to actual lubricat	0.3
ⓐ	🔧	VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
ⓐ	🔧	VO-7714500	Wheel nuts, check tightening (all)	0.3
ⓐ	🔧	VO-2331100	Filter, water separator, replace	0.2
ⓐ	🔧	VO-2141300	Valves and unit injectors, adjust	2.2
ⓐ	🔧	VO-5616600	Air drier cassette, replace	0.4
ⓐ	🔧	VO-6452500	Oil filter, power steering, replace	0.2
ⓐ	🔧	VO-3210700	Belt tensioner, alternator, replace	0.3
ⓐ	🔧	VO-1751100	Lubrication of fifth wheel	0.1
ⓐ	🔧	VO-1758900	Lubrication of trailer hitch	0.1
ⓐ	🔧	VO-2630800	Fan belt tensioner, replace	0.3
ⓐ	🔧	VO-1784600	Trailer coupling, safety and function ch	0.2
ⓐ	*	10	FABBRO DIESEL	
ⓐ	📦	VO-85123524	FILTER (ENGINE AIR)	2
ⓐ	📦	VO-23961764	ALT BELT (13L MACK)	1

PC	Type	Code	Description (Original)	#
		VO-23961830	FAN BELT (13L MACK)	1
		VO-85114535	FILTER KIT (MP8/10 OIL & FUEL)	1
		AU2-AMP23068344	VOLVO VDS4.5 20L	40
		VO-85129688	FILTER (AIR DRIER)	1
		MK-5839-870678A	FILTER (POWER STEERING)	1
		VO-23669027	BELT TENSIONER	1
		AU2-CAL85121792	BULLDOG HP GREASE NL	1
		VO-1161995	ATF DEXTRON 3 5L	1
		VO-21479276	BELT TENSIONER	1
		VO-85151124	FILTER (CAB AIR/POLLEN	1
		VO-8747400	Air filter insert, A/C unit, replace	0.3
		3630400	Windscreen wiper blade, replace	
		10	FABBRO DIESEL.	

2024-04-24 - Mileage: 819859 - Order nr: 3364661

		MG	Damien 0417 609 177	
			C0236 BATTERY CABLE BREAKAGE TRIDENT	
		VO-3719600	Power cable, battery to main switch, rep	0.8
		371	CABLES AND FUSES - CABLES	
		10	Sublet - FDS Ayr	
			PO: 604472 Inv: 723982	
			replace	

2024-01-17 - Mileage: 792497 - Order nr: 3363300

		MG	Damien 0417 609 177	
		1774400	Basic service	
		2330600	Fuel filter, replace (one)	
		1751300	Engine, oil and filter, replace. Lube	
		7714500	Wheel nuts, check tightening (all)	
		2331100	Filter, water separator, replace	
		1751100	Lubrication of fifth wheel	
		1758900	Lubrication of trailer hitch	

PC	Type	Code	Description (Original)	#
	*	1784600	Trailer coupling, safety and function	
	*	1750400	Lubrication according to actual	
	*	20	Sublet - FDS Ayr	
			PO: 604061 Inv: 722821	
		VO-23707800	SUPPORT BEARING	1
		VO-23137065	EXHAUST PIPE	1
		VO-1629499	CLAMP	2
		VO-990941	M10 FLANGE NUT	2
		VO-994195	FLANGE SCREW	2
		VO-25109292	LAMP	1
		VO-85114535	MP8/10 FILTER KIT	1
		VO-85151124	FILTER	1
		AU2-AMP23068344	VOLVO VDS4.5 20L	40
	*	3210100	Alternator, replace	
		VO-25110476	ALT 160AMP	1
	*	8747400	Air filter insert, A/C unit, replace	
	*	2522700	Exhaust pipe, replace (Flex Pipe to	
	*	4531200	Support bearing, overhaul. incl. remove	
			and reinstall	
	*	3550400	Position light, replace (roof mounted)	
	*	10	FABBRO AYR ALTERNATOR	
	*	10	FABBRO AYR AIR CON FILTER	
	*	10	FABBRO AYR - EXHAUST LEAK	
	*	10	FABBRO AYR CENTRE BEARING	
	*	10	FABBRO AYR ROOF LAMP	
	*	5653200	Chassis air leak, repair	
	*	10	FABBRO AIR LEAK FIREWALL	
	*	4680200	FRONT DIFF OPEERATION FAULTY	
	*	10	FABBRO AYR FRONT DIFF	
	*	4210100	Transmission, calibration	
	*	10	FABBRO AYR CALIBRATIONS	
		AU2-CAL85121792	BULLDOG HP GREASE NL	1
	*	468	REAR DIFF FAULTY SWITCH	

PC	Type	Code	Description (Original)	#
	*	10	FABBRO REAR DIFF	
			8397705	
			22117441	
			21194165	
2024-01-16 - Mileage: 0 - Order nr: 3363285				
			Repair without detail info	
2023-12-21 - Mileage: 789832 - Order nr: 3363097				
	*	ME	Damien	
		VO-2581800	Aftertreatment Urea Dosing Valve, Repla	0.5
		VO-22406383	ADBLUE PICKUP FILTER	1
		VO-82269261	FILTER	1
		VO-21647145	DOSAGE VALVE	1
		VO-21954674	STRAINER	1
		VO-23381558	ADBLUE FILTER	1
		OTH-ADB10105	ADBLUE 20LT	3
		VO-20748166	CONNECTOR,SAE 3/8	1
		VO-21032572	CLAMP	1
			Replace	
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included	
		VO-2840700	Sensor values, check	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-2584800	Strainer, replace. Pump unit	0.7
		VO-2580300	AdBlue tank, replace	1.2
		LO-258	Adblue system, complete flush	2
		VO-2598000	Program Aftertreatment Control Module (A	0.4
			(ACM)	
		VO-1902000	Road test	0.3
	*	WTY-NONGEN	Adblue 20LT	

2023-12-05 - Mileage: 784608 - Order nr: 3362870

	*	2580700	Pump unit, replace	
	*	10	TG SPARES	

2023-12-04 - Mileage: 768687 - Order nr: 5220676

	*	1774600	Annual service. Chassis lubrication and	
	*	2562700	Filter insert, air cleaner, replace.	
	*	2330600	Fuel filter, replace (one)	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	5616600	Air drier cassette, replace	
	*	2582200	Filter, AdBlue, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	1750400	Lubrication according to actual	
	*	10	TG SPARES	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2141300	Valves and unit injectors, adjust	
	*	2637500	Fan belt idler pulley, replace	
	*	6450000	Power steering equipment	
	*	10	TG SPARES POWER STEERING LEAK	
	*	4371000	Temperature-level sensor, replace	
	*	10	TG SPARES DIFF TEMP SENSOR	
	*	4651200	Pinion seal, replace	
	*	10	TG SPARES PINION SEAL	
	*	4375600	Modulator valve, replace	
	*	10	TG SPARES MODULATOR	
	*	6529100	Centre bearing, V-stay, replace	
	*	10	TG SPARES CENTRE BEARING	
	*	2611800	Expansion tank, replace	

PC	Type	Code	Description (Original)	#
	*	10	TG SPARES HEADER TANK	
   <u>2023-12-04 - Mileage: 768687 - Order nr: 3362837</u>				
	*	1774600	Annual service. Chassis lubrication and	
	*	2562700	Filter insert, air cleaner, replace.	
	*	2330600	Fuel filter, replace (one)	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	5616600	Air drier cassette, replace	
	*	2582200	Filter, AdBlue, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	1750400	Lubrication according to actual	
	*	10	TG SPARES	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2141300	Valves and unit injectors, adjust	
	*	2637500	Fan belt idler pulley, replace	
	*	6450000	Power steering equipment	
	*	10	TG SPARES POWER STEERING LEAK	
	*	4371000	Temperature-level sensor, replace	
	*	10	TG SPARES DIFF TEMP SENSOR	
	*	4651200	Pinion seal, replace	
	*	10	TG SPARES PINION SEAL	
	*	4375600	Modulator valve, replace	
	*	10	TG SPARES MODULATOR	
	*	6529100	Centre bearing, V-stay, replace	
	*	10	TG SPARES CENTRE BEARING	
	*	2611800	Expansion tank, replace	
	*	10	TG SPARES HEADER TANK	

   2023-11-07 - Mileage: 774773 - Order nr: 3362404

PC	Type	Code	Description (Original)	#
	*	ME	Damien 0417 609 177	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-5930200	Wheel speed sensor ABS, test	0.4
		VO-2840700	Sensor values, check	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-5935000	Wheel speed sensor, replace (rear axle)	0.6
		VO-1902000	Road test	0.3

2023-10-31 - Mileage: 771736 - Order nr: 3362276

	*	ME	Damien 0417 609 177	
		VO-8747700	Evaporator, sleeper, replace	2.1
		MK-3543-S1455001	EVPORATOR	1
		VO-20377031	SLEEVE	1
		AU2-WUR0890117	BRKCLNR-DON'T REORDER	1
		VO-85151124	FILTER	1
	*	87	A/C Gas R134A WTG RTA Lic - AU45908 WTG	
			RTA Lic - AU45908	
		VO-1709700	Take charge	0.3
		VO-8721600	Air filter, sleeper cab, replace	0.1
		VO-8741400	Cooling unit, performance test	0.2
			A/C not working	
			A/C evaporator cracked	
			Carried out A/C function test to locate issue	
			Found crack in evaporator	
			Removed and replaced evaporator	
			Replaced filter	
			Re-gassed vehicle	
			Tested operation, all OK	

2023-10-23 - Mileage: 768687 - Order nr: 3362202

	*	1774600	Annual service. Chassis lubrication and	
	*	2562700	Filter insert, air cleaner, replace.	

PC	Type	Code	Description (Original)	#
	*	2330600	Fuel filter, replace (one)	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	5616600	Air drier cassette, replace	
	*	2582200	Filter, AdBlue, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	1750400	Lubrication according to actual	
	*	10	TG SPARES	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2141300	Valves and unit injectors, adjust	
	*	2637500	Fan belt idler pulley, replace	
	*	6450000	Power steering equipment	
	*	10	TG SPARES POWER STEERING LEAK	
	*	4371000	Temperature-level sensor, replace	
	*	10	TG SPARES DIFF TEMP SENSOR	
	*	4651200	Pinion seal, replace	
	*	10	TG SPARES PINION SEAL	
	*	4375600	Modulator valve, replace	
	*	10	TG SPARES MODULATOR	
	*	6529100	Centre bearing, V-stay, replace	
	*	10	TG SPARES CENTRE BEARING	
	*	2611800	Expansion tank, replace	
	*	10	TG SPARES HEADER TANK	

   2023-10-13 - Mileage: 760054 - Order nr: 3362089

	*	ME	Damien 0417 609 177	
		LO-234	Fuel pipe, main filter, replace	0.8
		VO-21328763	FUEL PIPE	1
		VO-21335834	FUEL PIPE	1
		VO-20852765	GASKET	4
		VO-20852764	GASKET	1

PC	Type	Code	Description (Original)	#
		VO-22891940	HOSE	1
		VO-21078879	HOSE CLAMP	2
		VO-980464	CABLE TIE - LARGE	10
		VO-948211	CABLE TIE - SMALL	10
		LO-261	Heater supply hose, replace	0.6
			Fuel leak on fuel pump	
		LO-234	Fuel pipe, fuel pump, replace	1.1
		VO-2340800	Fittings, fuel line, replace	0.4
		VO-1820200	Localised wash for fault tracing	0.3

2023-10-05 - Mileage: 754851 - Order nr: 3361987

	*	2330100	Fuel pump, replace	
	*	2611800	Expansion tank, replace	
	*	10	TG SPARES FUEL PUMP	
	*	10	TG SPARES EXPANSION TANK	

2023-09-07 - Mileage: 742478 - Order nr: 3361589

	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	1750400	Lubrication according to actual	
	*	10	TG SPARES	
	*	8747400	Air filter insert, A/C unit, replace	
	*	8181600	Cab shock absorber, rear horizontal,	
			replace	
	*	7610800	Rear shock absorber, replace, two sides	
			(UD market)	
	*	2550500	PWM-valve waste gate, check	

PC	Type	Code	Description (Original)	#
	*	10	TG SPARES A/C FILTERS	
	*	10	FRONT CAB SHOCKS TG SPARES	
	*	10	REAR DRIVE SHOCKS TG SPARES	
	*	10	TURBO WASTEGATE VALVE TG SPARES	
	*	86	Sublet Surcharge	

2023-08-25 - Mileage: 722774 - Order nr: 3361269

		VO-20801117	WIPER SWITCH	1
		VO-3646000	Series/parallel switch, replace	0.2

2023-08-17 - Mileage: 658929 - Order nr: 5220571

	*	1750200	CARRY OUT LUBE SERVICE AS PER SCHEDULE	
	*	3500000	WORK LIGHT NOT WORKING	
	*	353	ROOF LIGHT NOT WORKING	
	*	10	SUBLET TG SPARES LUBE SERVICE	
			COMPLAINT:CARRY OUT LUBE SERVICE AS PER SCHEDULE	
			COMPLAINT:WORK LIGHT NOT WORKING	
	*	10	LIGHT ON FRONT GRILL NOT WORKING.	
			COMPLAINT:ROOF LIGHT NOT WORKING	
	*	10	ROOF LIGHT OUT	
			CAUSE:DUE AS PER VOSP	
			CORRECTION:CARRY OUT LUBE SERVICE AS PER SCHEDULE	
			TAX INV 165353 \$146.05 EX GST	
			waiting for contract to be extended	
			CREDIT AND RECHARGE TO CONTRACT AS ADVISED	
			ORIGINAL CLAIM DATE 11.05.2023 6502387	
			RECHARGED ON 3361272	
			CAUSE:INTERNAL FAILURE WITHIN THE LIGHT	
			CORRECTION:REMOVE AND REPLACE LIGHT TEST	
			OPERATION FOUND TO BE ALL OK	
			SUBLET TG SPARES TO CARRY OUT REPAIRS	
			TAX INV 165353 \$270.26 EX GST	

PC	Type	Code	Description (Original)	#
	📄		21031438	
	📄		CREDIT AND RECHARGE TO CONTRACT AS ADVISED	
	📄		ORIGINAL CLAIM DATE 11.05.2023 6502387	
	📄		RECHARGED ON 3361272	
	📄		CAUSE:LIGHT FAILURE INTERNAL	
	📄		CORRECTION:REMOVE AND REPLACE ROOF LIGHT AS REQUIRED	
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV 165353 \$208.41 EX GST	
	📄		25109292	
	📄		CREDIT AND RECHARGE TO CONTRACT AS ADVISED	
	📄		ORIGINAL CLAIM DATE 11.05.2023 6502387	
	📄		RECHARGED ON 3361272	

📄 ⓘ 2023-08-17 - Mileage: 658929 - Order nr: 3361272

ⓘ	*	1750200	CARRY OUT LUBE SERVICE AS PER SCHEDULE
ⓘ	*	3500000	WORK LIGHT NOT WORKING
ⓘ	*	353	ROOF LIGHT NOT WORKING
ⓘ	*	10	SUBLET TG SPARES LUBE SERVICE
ⓘ	*	10	LIGHT ON FRONT GRILL NOT WORKING.
ⓘ	*	10	ROOF LIGHT OUT

📄 ⓘ 2023-08-16 - Mileage: 673312 - Order nr: 5220569

ⓘ	*	1774400	Basic service. Chassis lubrication and
ⓘ	*	2330600	Fuel filter, replace (one)
ⓘ	*	1750400	Lubrication according to actual
ⓘ	*	1751300	Engine, oil and filter, replace. Lube
ⓘ	*	2331100	Filter, water separator, replace
ⓘ	*	1751100	Lubrication of fifth wheel
ⓘ	*	1758900	Lubrication of trailer hitch
ⓘ	*	1784600	Trailer coupling, safety and function
ⓘ	*	10	tg spares
	📄		PO 0602882 TAX INV 165581

PC	Type	Code	Description (Original)	#
	*	3630400	Windscreen wiper blade, replace	
	*	10	TG SPARES.	
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
			COMPLAINT:WIPERS NOT WORKING EFFICIENT	
			CAUSE:DUE SERVICE	
			CORRECTION:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
			SUBLET TG SPARES TO CARRY OUT REPAIRS	
			TAX INV 165581 \$1074.19 EX GST	
			85114535	
			contract es being extended	
			RECHGARGED ON 3361266 - CONTRACT EXTENTION	
			CAUSE:RUBBER PERISHED	
			CORRECTION:REMOVE AND REPLACE WIPER BLADES AS REQ	
			SUBLET TG SPARES TO CARRY OUT REPAIRS	
			TAX INV 165581 \$36.81 EX GST	
			82710488	
			RECHGARGED ON 3361266 - CONTRACT EXTENTION	

2023-08-16 - Mileage: 673312 - Order nr: 3361266

	*	1774400	Basic service. Chassis lubrication and
	*	2330600	Fuel filter, replace (one)
	*	1750400	Lubrication according to actual
	*	1751300	Engine, oil and filter, replace. Lube
	*	2331100	Filter, water separator, replace
	*	1751100	Lubrication of fifth wheel
	*	1758900	Lubrication of trailer hitch
	*	1784600	Trailer coupling, safety and function
	*	10	tg spares
			PO 0602882 TAX INV 165581
	*	3630400	Windscreen wiper blade, replace
	*	10	TG SPARES.

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

2023-07-30 - Mileage: 714362 - Order nr: 3360655

	*	3753300	Trailer indicator light, wires, replace.	
	*	10	SUBLET: T G Spares	
	*	2554600	Boost Pressure, check	
	*	10	TG SPARES BOOST LEAK UNDER LOAD	
			PO 0603268 TAX INV 167023	
	*	86	Sublet Surcharge	

2023-07-19 - Mileage: 721098 - Order nr: 3360890

	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	10	SUBLET: T G Spares	
		VO-85114535	FILTER KITS	1
		AU2-AMP23068344	VOLVO VDS4.5 20L	40
		AU2-CAL85121792	B/DOG HP GREASE NL	1
	*	5122700	Brake pads, replace	
	*	7224200	Rubber spring, check/replace (one).	
		VO-22254125	RUBBER SPRING	2
	*	3630400	Windscreen wiper blade, replace	
	*	10	TG SPARES WIPER BLADES	
	*	8747400	Air filter insert, A/C unit, replace	
	*	10	AC FILTER TG SPARES	
	*	7730000	Hub and bearing	
	*	10	HUB SEAL TG SPARES	
	*	10	BRAKE PADS TG SPARES	

PC	Type	Code	Description (Original)	#
	*	10	RUBBER SPRINGS TG SPARES	
	*	7705000	Wheel bearing and seal, trailing wheel	
	*	10	WHEEL BEARINGS TG SPARES	
	*	86	Sublet Surcharge	
		OTH-PMDPEX225	brake pad kit ex225	1
	*	WTY-NONGEN	OTH-PMDPEX225 BRAKE PADS \$483.33	

2023-05-19 - Mileage: 695449 - Order nr: 3360065

		MK-3543-S1455001	EVaporator	1
		VO-82781567	RECEIVER DRIER	1
	*	8740200	Evaporator, replace	
	*	10	TG SPARES	
	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	10	TG SPARES.	
		VO-22640551	MANIFOLD	1
		VO-85151124	FILTER	1
		VO-85114535	FILTER KITS	1
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		AU2-AMP23068344	VOLVO VDS4.5 20L	40
	*	86	Sublet Surcharge	
	*	5650000	Brake pipe and connections, compressed	
	*	6526000	Bushings, torque rod, replace, incl rod	
	*	2562400	Filter insert, air cleaner, replace.	
			Only valid for primary filter	
	*	10	TGS MANIFOLD LEAKING	

PC	Type	Code	Description (Original)	#
	*	10	TORQUE ROD BUSHES TGS	
	*	10	AIR FILTERS TG SPARES	
			WAITING FOR CONTRACT TO EXTEND	

2023-05-11 - Mileage: 0 - Order nr: 3359993

			Repair without detail info	
		VO-2182100	Engine mounting pad, replace (right rear	1.5
		VO-21997378	RUBBER CUSHION	2
			rear)	
		VO-2182000	Engine mounting pad, replace (left rear)	1.5

2023-03-29 - Mileage: 673312 - Order nr: 3359535

	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	10	tg spares	
			PO 0602882 TAX INV 165581	
	*	3630400	Windscreen wiper blade, replace	
	*	10	TG SPARES.	
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
			COMPLAINT:WIPERS NOT WORKING EFFICIENT	
			CAUSE:RUBBER PERISHED	
			CORRECTION:REMOVE AND REPLACE WIPER BLADES AS REQ	
			SUBLET TG SPARES TO CARRY OUT REPAIRS	
			TAX INV 165581 \$36.81 EX GST	
			82710488	
			CAUSE:DUE SERVICE	

PC	Type	Code	Description (Original)	#
	🔍		CORRECTION:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	🔍		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	🔍		TAX INV 165581 \$1074.19 EX GST	
	🔍		85114535	
	🔍		contract es being extended	

🔍 🌐 📄 2023-03-26 - Mileage: 658929 - Order nr: 3359434

🌐	*	1750200	CARRY OUT LUBE SERVICE AS PER SCHEDULE
🌐	*	3500000	WORK LIGHT NOT WORKING
🌐	*	353	ROOF LIGHT NOT WORKING
🌐	*	10	SUBLET TG SPARES LUBE SERVICE
	🔍		COMPLAINT:CARRY OUT LUBE SERVICE AS PER SCHEDULE
	🔍		COMPLAINT:WORK LIGHT NOT WORKING
🌐	*	10	LIGHT ON FRONT GRILL NOT WORKING.
	🔍		COMPLAINT:ROOF LIGHT NOT WORKING
🌐	*	10	ROOF LIGHT OUT
	🔍		CAUSE:DUE AS PER VOSP
	🔍		CORRECTION:CARRY OUT LUBE SERVICE AS PER SCHEDULE
	🔍		TAX INV 165353 \$146.05 EX GST
	🔍		waiting for contract to be extended
	🔍		CAUSE:LIGHT FAILURE INTERNAL
	🔍		CORRECTION:REMOVE AND REPLACE ROOF LIGHT AS REQUIRED
	🔍		SUBLET TG SPARES TO CARRY OUT REPAIRS
	🔍		TAX INV 165353 \$208.41 EX GST
	🔍		25109292
	🔍		CAUSE:INTERNAL FAILURE WITHIN THE LIGHT
	🔍		CORRECTION:REMOVE AND REPLACE LIGHT TEST
	🔍		OPERATION FOUND TO BE ALL OK
	🔍		SUBLET TG SPARES TO CARRY OUT REPAIRS
	🔍		TAX INV 165353 \$270.26 EX GST
	🔍		21031438

2023-02-22 - Mileage: 654952 - Order nr: 3359055

	*	258	EXHAUST PIPE CRACK
	*	1752400	Lubrication, with checks according to
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS.
			COMPLAINT:CRACK IN EXHAUST PIPE ON OUTLET OF MUFFLER
			COMPLAINT:CARRY OUT LUBE SERVICE
			CAUSE:MATERIAL FATIGUE AT WELDS/ VIBRATION
			CORRECTION:REMOVE PIPE CUT OUT PATCH FOR EXHAUST PIPE AND
			WELD ON, REFIT PIPE AND CHECK
			SUBLET TG SPARES TAX INV #164939 \$238.85 EX GST
			22575409
			CAUSE:DUE OPERATION
			CORRECTION:CARRY OUT LUBE SERVICE AS PER SCHEDULE
			SUBLET TG SPARES TO CARRY OUT REPAIRS
			TAX #164939 \$133.65 EX GST
			CAL85121792

2023-01-13 - Mileage: 627225 - Order nr: 3358635

	*	258	EXHAUST BACK PRESSURE FAULT ON DASH
	*	20	Sublet - Hartwigs
			PO: 602417 Inv: 0644
			07/11/2022 - 194XYR - 627,225kms - 11,344hrs -
			MACH TRIDENT
			VIN: 6FMM12H69JD809225
			COMPLAINT: Looked at truck and diagnosed cause of
			engine/exhaust brake sticking on
			CAUSE: Connected laptop, checked fault codes, nothing
			active Used TechTool to test actuator, found air valve
			slow to release and making strange noise
			No valve available at time so bypassed exhaust

PC	Type	Code	Description (Original)	#
	🔧		brake until parts arrived	
	🔧		CORRECTION: Once parts arrived, removed and replaced back	
	🔧		pressure valve Connected computer and cleared fault codes	
	🔧		LABOUR 3.5hrs @ \$148.50 p/hr 472.50 PARTS	
	🔧		Air Valve 21369922	
	🔧		Pipe Set 22811882	
	🔧		REPAIR DATE 07.11	

🔧 2023-01-01 - Mileage: 638738 - Order nr: 3358166

🔧	*	1774600	Annual service. Chassis lubrication and	
🔧	*	2562700	Filter insert, air cleaner, replace.	
🔧	*	2330600	Fuel filter, replace (one)	
🔧	*	1750400	Lubrication according to actual	
🔧	*	1751300	Engine, oil and filter, replace. Lube	
🔧	*	1752300	Gearbox oil and filter, replace. Lube	
🔧	*	1752700	Final drive oil, change. Lube area	
🔧	*	7714500	Wheel nuts, check tightening (all)	
🔧	*	2331100	Filter, water separator, replace	
🔧	*	5616600	Air drier cassette, replace	
🔧	*	2582200	Filter, AdBlue, replace	
🔧	*	1751100	Lubrication of fifth wheel	
🔧	*	6451400	Oil and filter, power steering, replace	
🔧	*	1758900	Lubrication of trailer hitch	
🔧	*	8747400	Air filter insert, A/C unit, replace	
🔧	*	1784600	Trailer coupling, safety and function	
🔧	*	10	TG SPARES	
🔧	🔧	VO-85114535	FILTER KITS	1
🔧	🔧	VO-23448457	OIL SAMPLING KITX1	4
🔧	🔧	VO-85123524	FILTER CARTRIDGE	2
🔧	🔧	VO-23381558	ADBLUE FILTER	1
🔧	🔧	MK-5839-870678A	FILTER P/STR GRAN	1
🔧	🔧	VO-85129688	AIR DRIER KIT	1
🔧	🔧	AU2-CAL85121792	B/DOG HP GREASE NL	1

PC	Type	Code	Description (Original)	#
		AU2-AMP23068345	VOLVO VDS4.5 208L	40
		AU2-AMP85136283	VOLVO SYNTHETIC GE	20
		AU2-CAL85136279	VOLVO SYNTH AXLE OIL 20L 97312	2
		4110100	Clutch, replace	
		VO-22191895	CRANKSHAFT SEAL	1
		VO-20483426	SEALING RING	1
		VO-85022395	EXCH CLUTCH KIT	1
		VO-1652986	BALL BEARING	1
		VO-22327069	SOLENOID VALVE	1
		VO-23417523	CYLINDER	1
		VO-20499469	RUBBER CUSHION	2
		VO-20860677	SEALING RING	1
		VO-20992763	AIR HOSE	1
		VO-20722721	AIR INLET	1
			COMPLAINT:CARRY OUT ANNUAL SERVICE AS PER SCHEDULE	
			COMPLAINT:TRANSMISSION NOT SELECTING GEARS	
		10	CLUTCH REPLACE	
		8180000	AIR LEAK LH FRONT AIR BAG	
			COMPLAINT:AIR LEAK AROUND DRIVER AREA	
		10	AIR LEAK AIR BAG LH SIDE	
		2180000	REAR ENGINE MOUNTS CRACKED	
			COMPLAINT:REAR ENGINE MOUNTS CRACKED	
		10	REAR ENGINE MOUNTS	
		9932100	Grease line, replace	
			COMPLAINT:AUTO GREASE LINES BROKEN OFF TO S CAMS	
		10	AUTO GREASER LINES	
			CAUSE:DUE OPERATION	
			CORRECTION:CARRY OUT ANNUAL SERVICE AS PER SCHEDULE	
			SUBLET TG SPARES TO CRARY OUT REPAIRS	
			TAX INV 164147 \$590.68 EX GST	
		86	Sublet Surcharge	
			CAUSE:CLUTCH SERVO U/S	
			CORRECTION:REMOVED GEARBOX CLUTCH AND FLYWHEEL. MACHINE	

PC	Type	Code	Description (Original)	#
	🗑		FLYWHEEL REFIT FLYWHEEL AND TENSION, FIT UP NEW CLUTCH	
	🗑		SERVO AND SUPPLY HOSE FIT NEW PWM VALVE FIT NEW REAL MAIN	
	🗑		SEAL REFIT GEARBOX AND ALL ACCESORIES, CARRY OUT CLUTCH	
	🗑		AND GEARBOX CALIBRATION	
	🗑		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	🗑		TAX INV 164147 \$1076.26 EX GST	
	🗑		CAUSE:LH FRONT AIR BAG LEAKING	
	🗑		CORRECTION:REMOVE AND REPLACE AIR BAG ASSEMBLY	
	🗑		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	🗑		TAX INV 164147 \$513.29 EX GST	
	🗑		21217038	
	🗑		CAUSE:MOUNTS U/S	
	🗑		CORRECTION:REMOVE AND REPLACE BOTH REAR ENGINE MOUNTS	
	🗑		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	🗑		TAX INV 164147 \$400.95 EX GST	
	🗑		CAUSE:FITTINGS BROKEN	
	🗑		CORRECTION:REPLACE GREASE LINE FITTINGS IN BOTH REAR S	
	🗑		CAM TUBES	
	🗑		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	🗑		TAX INV 164147 \$140.34 EX GST	
	🗑		3164572	

🗑🇺🇸 2023-01-01 - Mileage: 0 - Order nr: 3357883

* MG	Damien 0417 609 177
🗑	Kms:
🗑	Hrs:
* 258	EXHAUST BACK PRESSURE FAULT ON DASH
* 20	Sublet - Hartwigs
🗑	PO: 602417 Inv:
🗑	TRANSFERED TO NEW JOB 3358635

🗑🇺🇸🇩🇪🇬🇧 2022-12-15 - Mileage: 645346 - Order nr: 3358362

PC	Type	Code	Description (Original)	#
	*	8740200	Evaporator, replace	
	■	MK-3543-S1455001	EVaporator	1
	■	VO-82781567	RECEIVER DRIER	1
	📄		*** POSSIBLE POLICY CLAIM ***	
	■	VO-20443754	O-RING	3
	■	VO-20443754	O-RING	1
	■	VO-3090885	O-RING KIT	1
	📄		*** POSSIBLE POLICY CLAIM ***	
Ⓞ	■	VO-23871486	CONTROL VALVE	1
Ⓞ	*	726	SPRINGS-RR SUSPENS, HYDRAULIC & GAS SPRNG	
Ⓞ	*	2230700	Control valve, oil cooler, replace	
	📄		COMPLAINT: OIL LEAK AT OIL FILTER HEAD	
Ⓞ	*	10	CONTROL VALVE REPLACE	
	📄		COMPLAINT: AIR LEAK AT REAR SUSPENSION	
Ⓞ	*	10	AIR SPRING	
	📄		COMPLAINT: A/C NOT WORKING	
	*	10	SUBLET TG SPARES.	
	📄		CAUSE: LEAKING AIR BAG	
	📄		CORRECTION: REMOVE AND REPALCE RH FRONT DRIVE AIR BAG AS REQ	
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV 164363 \$446.47 EX GST	
	📄		21217038	
	📄		CAUSE: LEAKING BYPASS VALVE	
	📄		CORRECTION: REMOVED AND REPLACED CONTROL VALVE AS REQUIRED	
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV 164363 \$168.30 EX GST	
	📄		CAUSE: CRACKED EVAPORATOR PIPE	
	📄		CORRECTION: REMOVE AND REPLACE EVAPORATOR, REPLACED	
	📄		RECEIVER DRIER, VAC DOWN SYSTEM REGAS	
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV 164363 \$531.45 EX GST	
	📄		PARTS WARRANTY POP R/O 3355228 24.03.2022	
	📄		FITTED @ 517495 KMS	

PC	Type	Code	Description (Original)	#
	🔧		FAILED @ 645346 KMS	
	🔧		DISTANCE TRAVELLED 127851 KMS	

📅 🌐 🇬🇧 2022-11-28 - Mileage: 638738 - Order nr: 3358166

🇬🇧	🔧	VO-1750400	Lubrication according to actual	
🇬🇧	🔧	VO-1751100	Lubrication of fifth wheel	
🇬🇧	🔧	VO-1751300	Engine, oil and filter, replace. Lube	
🇬🇧	🔧	VO-1752300	Gearbox oil and filter, replace. Lube	
🇬🇧	🔧	VO-1752700	Final drive oil, change. Lube area	
🇬🇧	🔧	VO-1758900	Lubrication of trailer hitch	
🇬🇧	🔧	VO-1774600	Annual service. Chassis lubrication and	
🇬🇧	🔧	VO-1784600	Trailer coupling, safety and function	
🇬🇧	🔧	VO-2330600	Fuel filter, replace (one)	
🇬🇧	🔧	VO-2331100	Filter, water separator, replace	
🇬🇧	🔧	VO-2562700	Filter insert, air cleaner, replace.	
🇬🇧	🔧	VO-2582200	Filter, AdBlue, replace	
🇬🇧	🔧	VO-5616600	Air drier cassette, replace	
🇬🇧	🔧	VO-6451400	Oil and filter, power steering, replace	
🇬🇧	🔧	VO-7714500	Wheel nuts, check tightening (all)	
🇬🇧	🔧	VO-8747400	Air filter insert, A/C unit, replace	
🇬🇧	🔧	AU2-AMP23068345	VOLVO ENGINE OIL V	40
🇬🇧	🔧	AU2-AMP85136283	VOLVO SYNTHETIC GE	20
🇬🇧	🔧	AU2-CAL85121792	MACK HP GREASE	1
🇬🇧	🔧	AU2-CAL85136279	VOLVO SYNTHETIC RE	2
🇬🇧	🔧	MK-5839-870678A	FILTER P/STR GRAN	1
🇬🇧	🔧	VO-23381558	FILTER	1
🇬🇧	🔧	VO-23448457	OIL SAMPLING KITX1	4
🇬🇧	🔧	VO-85114535	FILTER KITS	1
🇬🇧	🔧	VO-85123524	FILTER CARTRIDGE	2
🇬🇧	🔧	VO-85129688	AIR DRIER KIT	1
🇬🇧	🔧	VO-4110100	Clutch, replace	
🇬🇧	🔧	VO-1652986	BALL BEARING	1
🇬🇧	🔧	VO-20483426	SEALING RING	1

PC	Type	Code	Description (Original)	#
		VO-20722721	AIR INLET	1
		VO-20860677	SEALING RING	1
		VO-20992763	AIR HOSE	1
		VO-22191895	CRANKSHAFT SEAL	1
		VO-22327069	SOLENOID VALVE	1
		VO-23417523	CYLINDER	1
		VO-85022395	EXCH CLUTCH KIT	1
		VO-8185500	AIR LEAK LH FRONT AIR BAG	
		VO-2180000	REAR ENGINE MOUNTS CRACKED	
		VO-20499469	RUBBER CUSHION	2
		VO-9932100	Grease line, replace	

2022-11-24 - Mileage: 634097 - Order nr: 5280063

		ROY - 0417 006 260	

	LO-430	GEARBOX STRUGGLING TO CHANGE GEAR	2
		CONNECTED SCAN TOOL AND CHECKED FAULT CODE. FOUND OLNLY ONE	
		COUNT OF GEARSELECTOR AND DATALINK FAULT. TRACED THE	
		FAULT. CHECKED DATALINK CABLE, CHECKED PLUGS AND HARNESS	
		ON ECU AND FIREWALL PLUG - ALL OKAY. REPROGRAMMED THE TECU	
		AND CALIBRATED. TEST DROVE, FOUND INACTIVE DATALINK FAULT.	
		COULDN'T FAULT TRANSMISSION - GEARS ALL OKAY. CLEARED	
		CODES. CARRIED OUT ALL THE TESTS RELATED TO THE	
		TRANSMISSION - ALL OKAY.	

	VO-1701000	Connect-disconnect of diagnostic tool	0.2
	* 91	Workshop Consumables	

2022-11-24 - Mileage: 634097 - Order nr: 3854568

		ROY - 0417 006 260	

		VO-4007000	Gearbox, clutch, engagement point, calib
			0.2

PC	Type	Code	Description (Original)	#
			calibration	
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included	
		VO-3710200	Electric wires and connections, check	0.4
	*	4320500	MID 130 Control unit, programming	
			C- GEARBOX STRUGGLING TO CHANGE GEAR	
			C- TRANSMISSION SPLITTER/GEARBOX REQUIRES CALIBRATION	
			C- CONNECTED LAPTOP AND READ FULT CODES -SEE ATTACHED PHV.	
			CHECKED ALL WIRING TO AND FROM GEAR SELECTOR AND GEARBOX	
			ECU. PROGRAMMED TECU AND CALIBRATED GEARBOX. ERASED FAULT	
			CODES AND CARRIED OUT ROAD TEST TO CHECK GEAR OPERATION,	
			ALL OKAY	
			-----	
		VO-1700400	Fault codes, test mode	1
	*	1902000	Road test	

  2022-11-21 - Mileage: 634097 - Order nr: 3854517

			ROY - 0417 006 260	
			---	
		LO-430	GEARBOX STRUGGLING TO CHANGE GEAR	2
			CONNECTED SCAN TOOL AND CHECKED FAULT CODE. FOUND OLNLY ONE	
			COUNT OF GEARSELECTOR AND DATALINK FAULT. TRACED THE	
			FAULT. CHECKED DATALINK CABLE, CHECKED PLUGS AND HARNESS	
			ON ECU AND FIREWALL PLUG - ALL OKAY. REPROGRAMMED THE TECU	
			AND CALIBRATED. TEST DROVE, FOUND INACTIVE DATALINK FAULT.	
			COULDN'T FAULT TRANSMISSION - GEARS ALL OKAY. CLEARED	
			CODES. CARRIED OUT ALL THE TESTS RELATED TO THE	
			TRANSMISSION - ALL OKAY.	
			----	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
	*	91	Workshop Consumables	

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

2022-11-03 - Mileage: 613530 - Order nr: 3357827

	*	1752400	Lubrication, with checks according to	
			lube service	
	*	10	TG SPARES	
			COMPLAINT:CARRY OUT MUBE SERVICE AS PER SCHEDULE	
			CAUSE:DUE OPERATION	
			CORRECTION:CARRY OUT LUBE SERVICE AS PER SCHEDULE	
			SUBLET TG SPARES TO CARRY OUT REPAIRS	
			TAX INV 163638 \$165.00 EX GST	

2022-10-10 - Mileage: 607797 - Order nr: 3357208

		VO-3110200	Batteries, replace (all)	0.6
		AU2-21209957	BULLDOG BATTERY - 12V	1
		VO-3116800	Battery system, test. Battery tester	0.4
		VO-3200200	Charging test, in vehicle	0.4
			COMPLAINT:NON START ON KEY.	
			CAUSE: BATTERIY COLLAPSED INTERNAL FAILURE.	
			CORRECTION: CHECKED AND LOAD TESTED ALL BETTERIES AND	
			FOUND 1 FAILED TEST. REPLACED BATTERIY AND CHECKED	
			ALTERNATOR OUTPUTS.	

2022-10-04 - Mileage: 608602 - Order nr: 3357438

		VO-7731200	Seal/oil/grease, rear wheel hub, replace	1.2
	*	350	2nd & 3rd axle trailer lights	
			flickering but not triggering circuit breaker	
			Truck and trailer	
		MK-8235-2208S1215	GASKET AXLE SHAFT	2
		OTH-MT200BC	MT BRAKE CLEAN	1
		MK-8236-MACK5	DRIVE BEARING KIT (TOOL FIT)	2
		VO-980464	CABLE TIE - LARGE	30
		MK-FT1868X8	1/2PF 3/8THR	4

PC	Type	Code	Description (Original)	#
		VO-967977	PLASTIC PIPE	7
		OTH-56092BL	yellow EYELET 9.5	4
		VO-1774400	Basic service. Chassis lubrication and o	1.3
		VO-2330600	Fuel filter, replace (one)	0.1
		VO-1750400	Lubrication according to actual lubricat	0.3
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
		VO-2331100	Filter, water separator, replace	0.2
		VO-1751100	Lubrication of fifth wheel	0.1
		VO-1758900	Lubrication of trailer hitch	0.1
		VO-1784600	Trailer coupling, safety and function ch	0.2
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
			CAUSE:DUE OPERATION	
			CORRECTION:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
		LO-565	air leak when service brake applied	1.5
		2444400	LHSR vertical takn step straighten	
		645	Power steering cap, r/r	
		VO-21383310	GASKET	1
		VO-85114535	FILTER KITS	1
		AU2-AMP23081619	VOLVO VDS4.5 1000L	38
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		VO-25162836	FLEX HOSE ASSY	1
		MK-5839-Q66297	WASHER, TOP P/S RE	1
		OTH-Z060031608	male tail piece	1
		OTH-Z010720806	adpt 1/2 to 3/8	1
		VO-2113900	Gasket, valve cover, replace	1.1
		OTH-MT200BC	MT BRAKE CLEAN	1
		VO-20538793	TAPPET COVER SEAL	1
		OTH-Z01072-0806	no 72 1/2x3/8 adaptor	1
		OTH-Z06003-1608	p3x1/2 male tailpiece	1
		WTY-NONGEN	Adaptors, tailpieces, fittings	
		VO-2150200	Gaskets, timing gear cover, replace	14.3
		VO-1820200	Localised wash for fault tracing	0.3
			power steering cap sweating/leaking	

PC	Type	Code	Description (Original)	#
			(one side)	
		VO-4662100	Axle shaft, re-seal	0.5
		VO-7730300	Inner wheel bearing race, driven or trai	0.2
			trailing wheels, replace (one)	
			Oil leak at LHS first drive wheel	
			LHS and RHS first drive seals leaking and damaged hub	
			bearings	
			Removed wheels on LHS and RHS first drive	
			Removed and replaced bearings and seals as required	
			Reassembled vehicle and washed down	
			Road tested, all OK	

   2022-08-22 - Mileage: 582924 - Order nr: 3356997

		VO-3644700	Main switch, replace	0.3
		VO-82278929	SWITCH - Res. Accel/Set-Decel	1
			COMPLAINT:CRUISE CONTROL CWITH NOT WORKING	
			CAUSE:INTERNAL FAILURE WITHIN THE SWITCH	
			CORRECTION:REMOVE AND REPLACE SWITCH AS REQUIRED	
			TEST OPERATION FOUND TO BE OK	

   2022-08-18 - Mileage: 582639 - Order nr: 3356977

		1774400	Basic service. Chassis lubrication and	
		3212300	Alternator belt, replace	
		2630700	Drive belts fan, replace	
		2330600	Fuel filter, replace (one)	
		1750400	Lubrication according to actual	
		1751300	Engine, oil and filter, replace. Lube	
		2331100	Filter, water separator, replace	
		3210700	Belt tensioner, alternator, replace	
		1751100	Lubrication of fifth wheel	
		1758900	Lubrication of trailer hitch	
		2630800	Fan belt tensioner, replace	

PC	Type	Code	Description (Original)	#
	*	1784600	Trailer coupling, safety and function	
	*	10	BASIC SERVICE	
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	■	VO-85114535	FILTER KITS	1
	■	VO-23961764	V-RIBBED BELT	1
	■	VO-23669027	BELT TENSIONER	1
	■	VO-23961830	V-RIBBED BELT	1
	■	VO-21479276	BELT TENSIONER	1
	■	AU2-AMP23068344	VOLVO VDS4.5 20L	40
	*	773	LEFT HAND REAR WHEEL SEAL	
	■	MK-1458-47691	HAND FIT SEAL XL DRIVE	1
	*	3630400	Windscreen wiper blade, replace	
	*	10	WIPER BLADES	
	*	874	CABIN A/C FILTER	
	*	10	A/C FILTER	
	*	8522400	DRIVERS SEAT MOVING UP AND DOWN	
	*	10	AIR HEIGHT CONTROL VALVE	
	*	561	AIR BLOWING OFF CONTANTLY ON AIR DRIER	
	*	10	UNLOADER VALVE	
	*	3550400	Position light, replace (roof mounted)	
	*	10	ROOF LIGHTS NOT WORKING	
	*	5639800	LEAKING AIR FITTING TREADLE VALVE	
	*	10	TREADLE VALVE LEAKING	
	■		COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	■		COMPLAINT:LH REAR HUB SEAL LEAKING	
	■		COMPLAINT:WIPERS NOT WORKING EFFICIENTLY	
	■		COMPLAINT:AIR CON NOT GETTING COLD	
	■		COMPLAINT:DRIVER SEAT MOVING UP AND DOWN CONTANTLY	
	■		COMPLAINT:AIR BLOWING OFF CONSTANTLY	
	■		COMPLAINT:ROOF LIGHTS NOT WORKING	
	■		COMPLAINT:AIR PRESSURE DROPPING	
	*	10	HUB SEAL	
	■		CAUSE:DUE OPERATION	

PC	Type	Code	Description (Original)	#
	✎		CORRECTION:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$543.98 EX GST	
	✎		CAUSE:LEAKING SEAL	
	✎		CORRECTION:REMOVED HUB, CLEAN ALL BEARINGS AND HUB,	
	✎		REPLACE BEARING CUPS AND CONES, FIT NEW HUB SEAL. LUBE UP	
	✎		BEARINGS AND REFIT HUB, ADJUST BEARINGS AND REFIT AXELS	
	✎		REFIT CALIPER AND BRAKE PADS	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$633.26 EX GST	
	✎		CAUSE:RUBBER PERISHED	
	✎		CORRECTION:REPLACE WIPER BLADES	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$34.83 EX GST	
	✎		82710488	
	✎		CAUSE:CABIN A/C FILTER BLOCKED	
	✎		CORRECTION:REPLACED CABIN AIR FILTER AS REQUIRED	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$108.76 EX GST	
	✎		85151124	
	✎		CAUSE:SEAT AIR HEIGHT CONTROL VALVE U/S	
	✎		CORRECTION:REMOVED SEAT CUSHION REPLACED VALVE AND REFIT	
	✎		CUSHION	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$246.72 EX GST	
	✎		CAUSE:UNLOADER VALVE U/S	
	✎		CORRECTION:REPLACE UNLOADER VALVE IN AIR DRIER AND FIT NEW	
	✎		SAFETY VALVE AT COMPRESSOR OUTLET	
	✎		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	✎		TAX INV #162525 \$559.21 EX GST	
	✎		22024367	
	✎		CAUSE:LIGHTS U/S	
	✎		CORRECTION:REMOVE AND REPLACE MIDDLE AND FAR RIGHT LIGHTS	

PC	Type	Code	Description (Original)	#
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV #162525 \$361.39 EX GST	
	📄		25109292	
	📄		CAUSE: LEAKING AIR FITTING AT TREADLE VALVE	
	📄		CORRECTION:REPLACE HOSE AND FITTING AT TREADLE VALVE	
	📄		SUBLET TG SPARES TO CARRY OUT REPAIRS	
	📄		TAX INV #162525 \$63.50 EX GST	
	📄		8397714	

📄 🇦🇷 🇨🇷 2022-07-14 - Mileage: 555156 - Order nr: 3356564

🇨🇷	*	465	OIL LEAK FROM FRONT DIFF THRU SHAFT	
🇨🇷	*	3528300	LH FRONT INDICATOR NOT WORKING	
🇨🇷	*	10	OIL LEAK	
🇨🇷	*	10	LH INDICATOR	
🇨🇷	*	60	SUBLET SURCHARGE	
	📄		COMPLAINT:OIL LEAKING FROM FRONT DIFF THROUGH SHAFT	

📄 🇦🇷 🇨🇷 2022-06-16 - Mileage: 558345 - Order nr: 3356220

🇨🇷	*	1774600	CARRY OUT ANNUAL SERVICE AS PER SCHEDULE	
🇨🇷	*	1750400	LUBRICATION	
🇨🇷	*	1751100	Lubrication of fifth wheel	
🇨🇷	*	1758900	Lubrication of trailer hitch	
🇨🇷	*	1784600	Trailer coupling, safety and function	
	📄		check	
🇨🇷	*	2331100	Filter, water separator, replace	
🇨🇷	*	2330600	Fuel filter, replace (one)	
🇨🇷	*	2200400	Engine oil sample, take	
🇨🇷	*	1751300	CHANGE ENGINE OIL AND FILTERS.	
🇨🇷	*	5616600	Air drier cassette, replace	
🇨🇷	*	2582200	Filter, AdBlue, replace	
🇨🇷	*	2562700	Filter insert, air cleaner, replace.	
🇨🇷	*	8747400	Air filter insert, A/C unit, replace	

PC	Type	Code	Description (Original)	#
	*	20	ATTEND TO ANNUAL SERVICE AS PER SCHEDULE	
	■	VO-85114535	FILTER KITS	1
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	■	VO-23448457	OIL SAMPLING KITX1	1
	■	AU2-AMP23068344	VOLVO VDS4.5 20L	40
	■	VO-85129688	AIR DRIER KIT	1
	■	VO-23381558	FILTER	1
	■	VO-85123524	FILTER CARTRIDGE	2
	■	VO-85151124	FILTER	1
	*	2100800	OIL LEAK AT ENGINE BREATHER	
	*	10	TG SPARES	
	*	2212300	Dipstick tube ORING, replace	
	*	10	DIPSTICK TUBE ORING	

2022-05-05 - Mileage: 540775 - Order nr: 3355826

	■	VO-23911823	EXPANSION TANK	1
	🔧	VO-2611800	Expansion tank, replace	0.7
	■	VO-20850964	HEADER TANK FITTING (ELBOW)	1
	■	VO-994556	HOSE CLAMP 13-16 MM	2
	■	VO-21053033	HOSE	1
	■	AU2-AMP85112987	MACK VCS COOLANT 5L	2
	🔧	LO-1940000	Travel to vehicle at	1
	📍		Alligator Creek Roadhouse (opposite) & return to WTG	
	*	92	60 km @ 98c/km	
	🔧	VO-2616500	Water hose, replace (hose with two clamp	0.3
	🔧	VO-2600600	Coolant system, pressure test	0.4

2022-04-04 - Mileage: 533403 - Order nr: 3355571

	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	

PC	Type	Code	Description (Original)	#
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	1784600	Trailer coupling, safety and function	
	*	10	BASIC SERVICE	
	■	VO-85114535	FILTER KITS	1
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	■	AU2-AMP23068345	VOLVO VDS4.5 208L	40
	*	5002100	STEER AXLE BRAKES	
	■	VO-22179302	KIT ADB	1
	*	10	STEER BRAKE PADS	
	*	2210500	OIL LEAK AT HYDRAULIC OIL PUMP	
	*	10	HYDRAULIC OIL PUMP	
	*	3525000	Clearance lamp, replace	
	*	10	CLEARANCE LAMP	
	*	353	LIGHTING - REAR LIGHTS	
	*	10	MARKERS	
	☒		COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	

2022-03-11 - Mileage: 523387 - Order nr: 3355368

		VO-4651300	Through shaft seal, replace	0.5
		VO-8182000	Cab shock absorber rear, replace (one)	0.4
		VO-4370000	Automatic, transmission (hydromechanical)	1
	■	MK-8235-A11205Y2729	SEAL PINION OUTPUT	1
	■	MK-8235-KIT2637	NUT, PINION & WASH	1
	■	VO-22662237	SHOCK ABSORBER	1
	■	VO-23235129	AIR SPRING	2
	■	VO-20421896	NIPPLE	1
	■	MK-FT1469X6	3/8 line 1/4 npt elbow	1
		VO-7260200	Air bellows, drive axle, replace	0.4
		VO-4511600	Propeller shaft intermediate, remove-ins	0.3
	☒		remove-install	

PC	Type	Code	Description (Original)	#
		VO-4650000	Final drive (front and rear). Secondary	1
<u>2022-03-04 - Mileage: 519919 - Order nr: 3355302</u>				
		VO-22398223	STARTER MOTOR	1
			*** POSSIBLE POLICY CLAIM ***	
	*	3310600	Starter motor, replace	
	*	10	STARTER MOTOR REPLACE	
<u>2022-02-26 - Mileage: 517495 - Order nr: 3355228</u>				
		VO-8743300	A/C compressor, replace	1.6
		VO-20721587	COMPRESSOR	1
		VO-82781567	RECEIVER DRIER	1
		VO-8211500	Bonnet lock, replace	0.6
		VO-6410800	Steering wheel position, adjust	1.1
		VO-25037181	LATCH HOOD-CHROME	1
		MK-3543-S1455001	EVaporator	1
			COMPLAINT:A/C NOT WORKING	
		VO-8701100	Refrigerant, draining for re-using	0.2
		VO-8700700	Refrigerant, filling	0.3
		VO-8740500	Dryer, replace	0.2
		VO-8747700	Evaporator, sleeper, replace	2.1
	*	94	R134A REFRIGERANT GAS	
<u>2022-02-23 - Mileage: 0 - Order nr: 5220150</u>				
	*	5611100	Compressor, replace	
		VO-85146161	EXCH COMPRESSOR K	1
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
<u>2022-01-24 - Mileage: 505909 - Order nr: 3354978</u>				
		VO-2101300	Engine, replace	8
			AND TAKE PHOTOS	

PC	Type	Code	Description (Original)	#
	❏	OTH-MT200BC	MT BRAKE CLEAN	1
	❏	VO-21383310	GASKET	1
	❏	VO-1161963	VOLVO RUBBER GREASE	1
	❏	VO-1161231	VOLVO BLACK SEALANT	1
Ⓒ	❏	VO-21339891	RUBBER HOSE	1
	❏	MK-NARV56306	CABLE TIE 1=10PK	1
	❏	VO-990951	M10 FLANGE LOCK NUT	1
Ⓒ	❏	VO-20555313	CONNECTING PIPE	1
Ⓒ	❏	VO-20479636	SEALING STRIP	1
Ⓒ	❏	VO-1547254	SEALING RING	1
Ⓒ	*	10	sublet pirtek for hose	
Ⓒ	❏	VO-1547252	SEALING RING	1
Ⓒ	👤	VO-2624500	Sealing, connecting pipe, replace. Seali	2.3
Ⓒ	❏	VO-994555	HOSE CLAMP 10-13MM	2
Ⓒ	❏	AU2-AMP85112987	MACK VCS COOLANT P	1
	*	91	Workshop Consumables	

🖨️ 🗣️ Ⓒ 2022-01-21 - Mileage: 507678 - Order nr: 3354960

Ⓒ	*	1774400	Basic service. Chassis lubrication and	
Ⓒ	*	10	CARRY OUT SERVICE AS PER SCHEDULE	
Ⓒ	❏	VO-85123524	FILTER CARTRIDGE	2
Ⓒ	❏	VO-85114535	FILTER KITS	1
Ⓒ	❏	VO-85129688	AIR DRIER KIT	1
Ⓒ	❏	VO-85151124	FILTER	1
Ⓒ	❏	AU2-CAL85121792	B/DOG HP GREASE NL	1
Ⓒ	*	2330600	Fuel filter, replace (one)	
Ⓒ	*	1750400	Lubrication according to actual	
Ⓒ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓒ	*	7714500	Wheel nuts, check tightening (all)	
Ⓒ	*	2331100	Filter, water separator, replace	
Ⓒ	*	1751100	Lubrication of fifth wheel	
Ⓒ	*	1758900	Lubrication of trailer hitch	
Ⓒ	*	2620200	Coolant pump, replace	

PC	Type	Code	Description (Original)	#
	*	5611100	Compressor, replace	
	*	1784600	Trailer coupling, safety and function	
	■	VO-85021450	PUMP UNIT, EXCH	1
	■	VO-85155724	COMPRESSOR	1
	■	AU2-AMP23068344	VOLVO VDS4.5 20L	40
	*	6522200	Torque rod, replace	
	■	VO-25164942	TORQUE ROD ASSY	2
	■	VO-85146161	EXCH COMPRESSOR K	1
	■	VO-977650	HOSE ASSEMBLY	1
	☒		COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	*	3630400	Windscreen wiper blade, replace	
	*	10	TORQUE ROD BUSHES	
	*	10	WIPER BLADES	
	*	2608800	FAN BELT CRACKED	
	*	10	FAN BELT CRACKED.	
	*	2180600	Engine mounting pad front, replace (one)	
	*	10	FRONT ENGINE MOUNT CRACKED	

   2022-01-18 - Mileage: 505013 - Order nr: 3354924

		VO-7730000	Hub and bearing	4.5
	■	MK-8235-2208S1215	GASKET AXLE SHAFT	2
	■	MK-1458-47693	SEAL WHEEL LONGLIF	2
	■	AU2-9770-5089	BRAKLEEN 500g Aer	1
	☒		LEAKING OIL.	

  2022-01-07 - Mileage: 489666 - Order nr: 5000932

		VO-2112600	Cylinder head, replace	19.5
	■	VO-85022413	EXCH CLY HEAD	1
	■	VO-21768034	GASKET KIT	1
	■	VO-1547252	SEAL W/PUMP 21MM ID	1
	■	VO-1547254	SEAL W/PUMP 50MM ID	2
	■	VO-11996	GASKET	1

PC	Type	Code	Description (Original)	#
	✖	VO-21021925	CONNECTING PIPE	1
	✖	VO-20852765	GASKET FUEL LINE	4
	✖	VO-21344774	BOLT INJECTOR HOLD DOWN	6
	✖	VO-3092340	SEALANT VOLVO GREY	1
	✖	VO-984740	FLANGE SCREW	12
	✖	VO-8192804	MP10 CAM BOLT	8
	✖	VO-990810	FLANGE SCREW	6
	✖	VO-984735	BOLT FLANGE M8 X 25 8.8 BLACK	6
	✖	VO-983472	SMALL GREY CABLE TIE	8
	✖	VO-8131393	CAGE	6
	✖	VO-21345131	SCREW	38
	✖	VO-1677370	SEALING RING	2
	✖	VO-20526428	SEALING RING	1
	✖	VO-471708	COMP INLET SEAL	1
	✖	VO-3979639	PRE HEATER GASKET	1
	✖	VO-22879256	CAMSHAFT BEARING K	6
	✖	VO-22879257	CAMSHAFT BEARING K	1
	✖	VO-85114535	MP8/10 FILTER KIT	1
	📄		*** POSSIBLE POLICY CLAIM ***	
	✖	VO-20579690	GASKET	1
	✖	AU2-AMP23068346	ENGINE OIL VDS4.5 15W-40 BULK	40
	✖	VO-85003268	EXCH UNIT INJECTO	1
	✖	VO-21503575	SEAL THERMOSTAT	1
	✖	VO-21397620	EXCH TURBOCHARGER VOLVO 13LTR	1
	✖	VO-20784537	TURBO BASE GASKET	1
	✖	VO-21940615	TURBO DRN SEAL(BLOCK	1
	✖	VO-22206133	TURBO FEED GASKET	1
	✖	VO-420643	TURBO DRAIN GASKET	1
	✖	VO-469601	TURBO DRAIN SEAL	1
	✖	VO-85123524	AIR CLEANER *NOTES	2
	✖	VO-22718180	MP8 EXH MAN KIT	1
	✖	VO-984050	NUT HEX M14 FINE PITCH PC 10	4
	✖	VO-995906	BOLT HEX M14 X 46 FINE 10.9	4

PC	Type	Code	Description (Original)	#
		VO-2141300	Valves and unit injectors, adjust	2.2
		VO-2551800	Engine turbocharger, replace. Chassis mo	2.2
		VO-2370400	Injector, replace (one)	4.3
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2100600	Cylinder Compression, test	3.1

  2022-01-07 - Mileage: 489666 - Order nr: 3016267

	LO-211	cylinder head, replace	7.8
	VO-85022413	EXCH CLY HEAD	0.4
	VO-21768034	GASKET KIT	0.4
	VO-1547252	SEAL W/PUMP 21MM ID	0.4
	VO-1547254	SEAL W/PUMP 50MM ID	0.8
	VO-11996	GASKET	0.4
	VO-21021925	CONNECTING PIPE	0.4
	VO-20852765	GASKET FUEL LINE	1.6
	VO-21344774	BOLT INJECTOR HOLD DOWN	2.4
	VO-3092340	SEALANT VOLVO GREY	0.4
	VO-984740	FLANGE SCREW	4.8
	VO-8192804	MP10 CAM BOLT	3.2
	VO-990810	FLANGE SCREW	2.4
	VO-984735	BOLT FLANGE M8 X 25 8.8 BLACK	2.4
	VO-983472	SMALL GREY CABLE TIE	3.2
	VO-8131393	CAGE	2.4
	VO-21345131	SCREW	15.2
	VO-1677370	SEALING RING	0.8
	VO-20526428	SEALING RING	0.4
	VO-471708	COMP INLET SEAL	0.4
	VO-3979639	PRE HEATER GASKET	0.4
	VO-22879256	CAMSHAFT BEARING K	2.4
	VO-22879257	CAMSHAFT BEARING K	0.4
	VO-85114535	MP8/10 FILTER KIT	0.4
	VO-20579690	GASKET	0.4
	AU2-AMP23068346	ENGINE OIL VDS4.5 15W-40 BULK	16

PC	Type	Code	Description (Original)	#
	❏	VO-85003268	EXCH UNIT INJECTO	0.4
	❏	VO-21503575	SEAL THERMOSTAT	0.4
	❏	VO-21397620	EXCH TURBOCHARGER VOLVO 13LTR	0.4
	❏	VO-20784537	TURBO BASE GASKET	0.4
	❏	VO-21940615	TURBO DRN SEAL(BLOCK	0.4
	❏	VO-22206133	TURBO FEED GASKET	0.4
	❏	VO-420643	TURBO DRAIN GASKET	0.4
	❏	VO-469601	TURBO DRAIN SEAL	0.4
	❏	VO-85123524	AIR CLEANER *NOTES	0.8
	❏	VO-22718180	MP8 EXH MAN KIT	0.4
	❏	VO-984050	NUT HEX M14 FINE PITCH PC 10	1.6
	❏	VO-995906	BOLT HEX M14 X 46 FINE 10.9	1.6
	📋		Concern: Truck has engine miss - exhaust has a bad smell	
	🔧	LO-214	valves & unit injectors, adjust	0.88
	🔧	LO-255	engine turbocharger, replace	0.88
	🔧	LO-237	injector, replace	4.3
	🔧	LO-170	connect-disconnect tech tool	0.08
	🔧	LO-210	cylinder compression test	1.24

🖨️ 🌐 📄 2021-11-29 - Mileage: 491106 - Order nr: 3354595

🔧	*	5639800	AIR LEAK FOOTBRAKE VALVE	
🔧	*	10	FOOT BRAKE VALVE LEAK	
🔧	❏	VO-21144822	VALVE	1
🔧	❏	VO-21850098	RELAY VALVE	1
🔧	*	818	FRONT CAB SUSPENSION RUBBERS	
🔧	*	10	RUBBER SPRINGS	
🔧	❏	VO-22254125	RUBBER SPRING	2
🔧	*	5253600	Load-sensing valve, replace	
	📋		COMPLAINT:AIR LEAKING FROM FOOT VALVE	
🔧	*	10	SERVICE BRAKE RELAY VALVE	
🔧	*	60	SUBLET SURCHARGE	

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

🔍🌐📄📅 2021-11-26 - Mileage: 489666 - Order nr: 3016267

	🔧	VO-1700000	connect-disconnect tech tool	0.08
🔧	🔧	VO-1700000	CONNECT-DISCONNECT TECH TOOL	0.12
	🔧	VO-2100000	cylinder compression test	1.24
🔧	🔧	VO-2100000	CYLINDER COMPRESSION TEST	1.86
	🔧	VO-2110000	cylinder head, replace	7.8
🔧	🔧	VO-2110000	CYLINDER HEAD, REPLACE	11.7
	🔧	VO-2140000	valves & unit injectors, adjust	0.88
🔧	🔧	VO-2140000	VALVES & UNIT INJECTORS, ADJUST	1.32
🔧	🔧	VO-2370000	INJECTOR, REPLACE	2.58
	🔧	VO-2370000	injector, replace	4.3
	🔧	VO-2550000	engine turbocharger, replace	0.88
🔧	🔧	VO-2550000	ENGINE TURBOCHARGER, REPLACE	1.32
	🔧	AU2-AMP23068346	VOLVO ENGINE OIL V	16
🔧	🔧	AU2-AMP23068346	VOLVO ENGINE OIL V	24
	🔧	VO-11996	GASKET	0.4
🔧	🔧	VO-11996	GASKET	0.6
	🔧	VO-1547252	SEALING RING	0.4
🔧	🔧	VO-1547252	SEALING RING	0.6
	🔧	VO-1547254	SEALING RING	0.8
🔧	🔧	VO-1547254	SEALING RING	1.2
	🔧	VO-1677370	SEALING RING	0.8
🔧	🔧	VO-1677370	SEALING RING	1.2
	🔧	VO-20526428	SEALING RING	0.4
🔧	🔧	VO-20526428	SEALING RING	0.6
	🔧	VO-20579690	GASKET	0.4
🔧	🔧	VO-20579690	GASKET	0.6
	🔧	VO-20784537	GASKET	0.4
🔧	🔧	VO-20784537	GASKET	0.6
	🔧	VO-20852765	GASKET	1.6
🔧	🔧	VO-20852765	GASKET	2.4
	🔧	VO-21021925	CONNECTING PIPE	0.4

PC	Type	Code	Description (Original)	#
G	F	VO-21021925	CONNECTING PIPE	0.6
		VO-21344774	FLANGE SCREW	2.4
G	F	VO-21344774	FLANGE SCREW	3.6
		VO-21345131	SCREW	15.2
G	F	VO-21397620	EXCH TURBOCHARGER	0.4
		VO-21397620	EXCH TURBOCHARGER	0.6
G	F	VO-21503575	SEALING RING	0.4
		VO-21503575	SEALING RING	0.6
G	F	VO-21768034	GASKET KIT	0.4
		VO-21768034	GASKET KIT	0.6
G	F	VO-21940615	SEALING RING	0.4
		VO-21940615	SEALING RING	0.6
G	F	VO-22206133	GASKET	0.4
		VO-22206133	GASKET	0.6
G	F	VO-22718180	EXH MANIFOLD KIT D	0.4
		VO-22879256	CAMSHAFT BEARING K	0.6
G	F	VO-22879256	CAMSHAFT BEARING K	2.4
		VO-22879257	CAMSHAFT BEARING K	0.4
G	F	VO-3092340	SEALANT	0.4
		VO-3092340	SEALANT	0.6
G	F	VO-3979639	GASKET	0.4
		VO-3979639	GASKET	0.6
G	F	VO-420643	GASKET	0.4
		VO-420643	GASKET	0.6
G	F	VO-469601	SEAL RING	0.4
		VO-469601	SEAL RING	0.6
G	F	VO-471708	SEALING RING	0.4
		VO-471708	SEALING RING	0.6
G	F	VO-8131393	CAGE	2.4
		VO-8131393	CAGE	3.6
G	F	VO-8192804	SCREW	3.2
		VO-8192804	SCREW	4.8
G	F	VO-85003268	EXCH UNIT INJECTO	0.4

PC	Type	Code	Description (Original)	#
		VO-85003268	EXCH UNIT INJECTO	0.6
		VO-85022413	EXCH CLY HEAD 13L	0.4
		VO-85022413	EXCH CLY HEAD 13L	0.6
		VO-85114535	FILTER KITS	0.4
		VO-85114535	FILTER KITS	0.6
		VO-85123524	FILTER CARTRIDGE	0.8
		VO-85123524	FILTER CARTRIDGE	1.2
		VO-983472	CABLE TIE	3.2
		VO-984050	HEXAGON NUT	1.6
		VO-984050	HEXAGON NUT	2.4
		VO-984735	FLANGE SCREW	2.4
		VO-984735	FLANGE SCREW	3.6
		VO-984740	FLANGE SCREW	4.8
		VO-984740	FLANGE SCREW	7.2
		VO-990810	FLANGE SCREW	2.4
		VO-990810	FLANGE SCREW	3.6
		VO-995906	HEXAGON SCREW	1.6
		VO-995906	HEXAGON SCREW	2.4
		VO-20784537	GASKET	0.6
		VO-22879256	CAMSHAFT BEARING K	3.6

   2021-11-21 - Mileage: 488516 - Order nr: 3354515

		VO-2650400	Charge air cooler, leakage test	0.9
		VO-2652000	Charge air pipe, replace	0.4
		LO-194	Travel Time to Breakdown	2
			MACK ACTION SERVICE 263144.	
		VO-85137462	BOOST HOSE CLAMP	1
		VO-20550690	HOSE	2
		VO-2650000	Charge air cooler with connection. Secon	0.8

   2021-11-10 - Mileage: 480928 - Order nr: 3354405

		5122700	Brake pads, replace	
---	---	---------	---------------------	--

PC	Type	Code	Description (Original)	#
	*	5933800	Wheel speed sensor, replace rear	
	*	10	ABS LIGHT ON FAULT ALARM RINGING	
	■	MK-8235- MDPEX225	PAD KIT	1
	■	VO-85153602	SENSOR	1
	*	10	FRONT DRIVE BRAKE PADS	
	■		COMPLAINT:FRONT DRIVE BRAKES WORN	

2021-10-06 - Mileage: 468047 - Order nr: 3354134

	■		last service basic @ 436051 kms 02/8/21 & Valve adjust	
	*	1774400	Basic service. Chassis lubrication and	
	*	1707300	Service alert system, configuration and	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1784600	Trailer coupling, safety and function	
	*	1751100	Lubrication of fifth wheel	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	10	CARRY OUT BASIC SERVICE	
	■	VO-85114535	FILTER KITS	1
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	■	AU2-CAL85121795	VDS4 (PER LITRE)	38
	*	874	AIR CONDITIONING	
	■	VO-85151124	FILTER	1
	*	3715000	Socket, trailer connection, replace	
	*	353	SIDE LIGHTING	
	*	3563600	Beacon lamp, replace	
	*	10	A/C NOT WORKING	
	*	10	TRAILER SOCKET CONNECTION	
	*	10	SIDE LIGHT NOT WORKING RHS	
	*	10	BEACON LIGHT WORKING	

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

2021-09-20 - Mileage: 457724 - Order nr: 3354005

	*	311	BATTERY AND MOUNTING PARTS - BATTERY	3
	■	AU2-21209957	BULLDOG BATTERY - 12V	
	*	10	REPLACE BATTERIES - KENNYS AUTO	
	☒		COMPLAINT:TRUCK NOT STARTING ON KEY	

2021-08-09 - Mileage: 422104 - Order nr: 3353655

	*	3531000	RH TAIL LIGHT NOT WORKING	
	☒		COMPLAINT:TRUCK PRESENTED WITH RH TAIL LIGHT BOT WORKING	
	*	10	RH TAIL LIGHT	

2021-08-02 - Mileage: 436051 - Order nr: 3353593

	*	1774400	Basic service. Chassis lubrication and	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1751100	Lubrication of fifth wheel	
	*	1784600	Trailer coupling, safety and function	
	*	2141300	Valves and unit injectors, adjust	
	*	10	SUBLET TGS CARRY OUT BASIC SVCE	
	*	10	SUBLET TG;S CARRY OUT VALVE ADJUST	
	☒		COMPLAINT: CARRY OUT VALVE ADJUSTMENT AS PER SCHEDULE	1
	■	VO-85136742	FILTER KIT	
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	*	3630400	Windscreen wiper blade, replace	
	*	8747400	Air filter insert, A/C unit, replace	
	*	2121200	Core plug, replace	
	*	10	WIPER BLADES	
	*	10	A/C FILTER	
	*	10	CORE PLUG	

PC	Type	Code	Description (Original)	#
		AU2-CAL85121795	VDS4 (PER LITRE)	40

2021-07-28 - Mileage: 431792 - Order nr: 3353540

	8740200	Evaporator, replace	
	10	REPLACE A/C EVAPORATOR	
	MK-3543-S1455001	EVPORATOR	1
		*** POSSIBLE POLICY CLAIM ***	

2021-06-09 - Mileage: 409949 - Order nr: 3353174

		VO-21293367	SEALING STRIP	1
		VO-990719	O-RING	1
		VO-23285701	OIL LEVEL SENSOR	1
		VO-22645240	SEALING RING	4
		217	OIL SUMP	
		10	OIL LEVEL SENSOR IN SUMP	
		1774600	Annual service. Chassis lubrication and	
		1751300	Engine, oil and filter, replace. Lube	
		2331100	Filter, water separator, replace	
		2601000	Coolant, change	
		2341400	Filter for fuel tank ventilation,	
		7714500	Wheel nuts, check tightening (all)	
		8747400	Air filter insert, A/C unit, replace	
		1758900	Lubrication of trailer hitch	
		1751100	Lubrication of fifth wheel	
		2582200	Filter, AdBlue, replace	
		2330600	Fuel filter, replace (one)	
		2562700	Filter insert, air cleaner, replace.	
		5616600	Air drier cassette, replace	
		1750400	Lubrication according to actual	
		6452500	Oil filter, power steering, replace	
		1784600	Trailer coupling, safety and function	
		VO-23448457	OIL SAMPLING KITX1	1

PC	Type	Code	Description (Original)	#
		VO-85136742	FILTER KIT	1
		AU2-CAL85112988	BULLDOG VCS COOLANT 20L	2
		VO-21743197	AIR CLEANER	1
		VO-85151124	FILTER	1
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		VO-23381558	FILTER	1
		VO-85123524	FILTER CARTRIDGE	2
		VO-85129688	AIR DRIER KIT	1
		MK-5839-870678A	FILTER P/STR GRAN	1
	*	2200400	Engine oil sample, take	
	*	10	CARRY OUT ANNUAL SERVICE	
		VO-25109292	LAMP	2
	*	3551800	Side marking lamp complete, replace	
	*	10	ROOF LIGHTS X 2 OUT	
		AU2-CAL85121795	VDS4 (PER LITRE)	42
		MK-8235-MDPEX225	PAD KIT	1
	*	561	pad kit	
	*	10	REPLACE REAR AXEL BRAKE PADS	
			COMPLAINT: ENGINE OIL ALARM FLICKERING.	
	*	3633300	Windscreen wiper blade rubber, replace	
	*	10	REPLACE WIPER BLADES	

2021-04-23 - Mileage: 383807 - Order nr: 3352817

	*	1774400	Basic service. Chassis lubrication and	
		VO-20923573	LINK ROD	1
	*	6430700	Link rod, replace	
		VO-85114535	FILTER KITS	1
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		VO-23448457	OIL SAMPLING KITX1	1
		VO-85151124	FILTER	1
		VO-85123524	FILTER CARTRIDGE	2
	*	10	CARRY OUT BASIC SERVICE AS PER VOSP	

PC	Type	Code	Description (Original)	#
		AU2-CAL85121795	VDS4 (PER LITRE)	38
	*	1751100	Lubrication of fifth wheel	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1707300	Service alert system, configuration and	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	2331100	Filter, water separator, replace	
	*	1784600	Trailer coupling, safety and function	
	*	352	LIGHTING - FRONT LIGHTS	
	*	10	REPLACE BULBS AS REQUIRED	
	*	10	LINK ROD REPLACE	
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	

2021-03-29 - Mileage: 375487 - Order nr: 3352635

	*	920	RINGFEEDER BUSH KIT	
	*	10	SUBLET: SERVICE/MNTCE REPAIRS	
			COMPLAINT:MOVEMENT IN TRAILER COUPLING	

2021-03-01 - Mileage: 469292 - Order nr: 809225

		VO-9600000		1
		VO-9600000		1
		VO-9600000		1

2021-01-29 - Mileage: 469291 - Order nr: 3352201

	*	873	A/C NOT WORKING	
	*	10	SUBLET TG SPARES TO INSPECT AC OPERATION	
		MK-3543-S1455001	EVaporator	1
		VO-82781567	RECEIVER DRIER	1
			Complaint: A/c not operating	
		VO-85113771	BLOWER MOTOR	1
		VO-85151124	FILTER	1
	*	8730600	Blower motor, replace	

PC	Type	Code	Description (Original)	#
	*	10	SUBLET TG SPARES TO REPLACE BLOWER MOTOR	
<u>2021-01-11 - Mileage: 357828 - Order nr: 3352095</u>				
	*	1774400	CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	LUBRICATION	
	*	1751300	CHANGE ENGINE OIL AND FILTERS	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2331100	Filter, water separator, replace	
	*	1707300	RESET SERVICE ALERT REMINDER	
	*	1751100	Lubrication of fifth wheel	
	*	1784600	Trailer coupling, safety and function	
			check	
	*	10	SUBET TG SPARES TO CARRY OUT SERVICE	
		VO-85114535	FILTER KITS	1
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		VO-23448457	OIL SAMPLING KITX1	1
		VO-85151124	FILTER	1
		VO-82278971	SWITCH - WINDOW (UP & DOWN)	1
	*	3640900	Door button, replace	
	*	2200400	Engine oil sample, take	
	*	3110200	Batteries, replace (all)	
	*	8747400	Air filter insert, A/C unit, replace	
		VO-85123524	FILTER CARTRIDGE	2
	*	3630400	Windscreen wiper blade, replace	
	*	10	WINDOW UP AND DOWN SWITCH	
	*	10	BATTERIES REPLACE	
		AU2-CAL85121795	VDS4 (PER LITRE)	38
<u>2020-12-22 - Mileage: 357730 - Order nr: 3352023</u>				
	*	285	Exhaust back pressure sensor, replace	
	*	852	Seat height level control valve, replace	

PC	Type	Code	Description (Original)	#
	*	10	SUBLET: SERVICE/MNTCE REPAIRS	
	🔧		COMPLAINT:DRIVERS SEAT AIR LEAK	
🔧	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	

🔍 📅 2020-12-01 - Mileage: 338786 - Order nr: 809225

🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1
🔧	🔧	VO-9600000		1

🔍 📅 📄 2020-11-23 - Mileage: 338785 - Order nr: 3351812

	*	253	Control valve, engine brake, replace	
	🔧	VO-22539850	AIR VALVE	1
	🔧	VO-22756465	PIPE SET	1
🔧	🔧	VO-20855371	EXHAUST MANIFOLD GASKET	6
🔧	🔧	VO-20883450	SEALING RING	2
🔧	🔧	VO-21433769	SEALING RING	2
🔧	🔧	VO-22206133	TURBO OIL FEED GASKET	1
🔧	🔧	VO-420643	TURBO OIL DRAIN GASKET	1
🔧	🔧	VO-469601	TURBO OIL DRAIN SEAL (TURBO)	1
🔧	🔧	VO-21940615	TURBO OIL DRAIN SEAL (BLOCK)	1
	*	10	SUBLET: SERVICE/MNTCE REPAIRS	
	🔧	VO-23626042	AIR VALVE	1
🔧	*	251	Gaskets, exhaust manifold, replace	

PC	Type	Code	Description (Original)	#
	📋		COMPLAINT:EXHAUST MANIFOLD GASKETS LEAKING	
🔍	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	

📅🔍🔍 2020-10-19 - Mileage: 321210 - Order nr: 3351540

🔍	*	1774400	CARRY OUT BASIC SERVICE AS PER SCHEDULE	
🔍	*	2330600	Fuel filter, replace (one)	
🔍	*	1750400	Lubrication according to actual	
🔍	*	1751300	CHANGE ENGINE OIL AND FILTERS	
🔍	*	2331100	Filter, water separator, replace	
🔍	*	1707300	RESET SERVICE ALERT REMINDER	
🔍	*	1751100	Lubrication of fifth wheel	
🔍	*	10	SUBLET: SERVICE/MNTCE REPAIRS	
🔍	📋	VO-85114535	FILTER KITS	1
🔍	📋	AU2-CAL85121792	B/DOG HP GREASE NL	1
🔍	📋	VO-21561640	IDLER PULLEY	1
🔍	📋	VO-20582550	IDLER PULLEY	1
🔍	📋	VO-22929437	FAN HUB	1
🔍	📋	VO-21372850	V-RIBBED BELT	1
🔍	*	2633700	Fan hub assembly, replace	
🔍	*	2634900	Idler pulley, fan belt, replace	
🔍	📋	AU2-CAL85121795	VDS4 (PER LITRE)	38
🔍	*	10	SUBLET TG SPARES TO CHANGE FAN HUB AS RE	
🔍	*	10	SUBLET: SERVICE/MNTCE REPAIRS..	
🔍	*	8747400	Air filter insert, A/C unit, replace	
🔍	*	5616200	Compressor safety valve, replace	
🔍	*	4651200	Pinion seal, replace	
🔍	*	10	SUBLET: SERVICE/MNTCE REPAIRS...	
🔍	*	10	SUBLET: SERVICE/MNTCE REPAIRS....	
	📋		COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	

📅🔍🔍 2020-10-06 - Mileage: 308254 - Order nr: 3351471

🔍	🔍	VO-3310600	Starter motor, replace	1.1
---	---	------------	------------------------	-----

PC	Type	Code	Description (Original)	#
		VO-22398223	STARTER MOTOR	1
			COMPLAINT:NOT STARTING ON KEY	

2020-09-17 - Mileage: 307243 - Order nr: 3351360

		VO-21341754	SHOCK ABSORBER	4
	*	7610000	Shock absorber	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	
			COMPLAINT:DRIVE SHOCKIES FOUND TO BE LEAKING AND U/S	

2020-08-20 - Mileage: 294408 - Order nr: 3351169

		VO-23059017	EXPANSION TANK	1
		AU2-CAL85112987	BULLDOG VCS COOLANT 5L	1
	*	2611800	Expansion tank, replace	
			COMPLAINT:LEAKING COOLANT HEADER TANK	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIR	

2020-08-10 - Mileage: 291777 - Order nr: 3351082

	*	1774600	Annual service. Chassis lubrication and	
	*	2562700	Filter insert, air cleaner, replace.	
	*	3212300	Alternator belt, replace	
	*	2630700	Drive belts fan, replace	
	*	2330600	Fuel filter, replace (one)	
	*	1750400	Lubrication according to actual	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	1752300	Gearbox oil and filter, replace. Lube	
	*	1752700	Final drive oil, change. Lube area	
	*	7714500	Wheel nuts, check tightening (all)	
	*	2331100	Filter, water separator, replace	
	*	5616600	Air drier cassette, replace	
	*	2582200	Filter, AdBlue, replace	
	*	6452500	Oil filter, power steering, replace	
	*	3210700	Belt tensioner, alternator, replace	

PC	Type	Code	Description (Original)	#
	*	1707300	RESET SERVICE ALERT REMINDER	
	*	1751100	Lubrication of fifth wheel	
	*	1758900	Lubrication of trailer hitch	
	*	2630800	Fan belt tensioner, replace	
	*	8747400	Air filter insert, A/C unit, replace	
	*	1706800	36 Months ECU download and oil sample.	
	*	10	SUBLET TG SPARES TO CARRY OUT SERVICE	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS.	
	■	VO-85114535	FILTER KITS	1
	■	VO-23448457	OIL SAMPLING KITX1	4
	■	VO-85123524	FILTER CARTRIDGE	2
	■	VO-21516231	FILTER, UDS	1
	■	MK-5839-870678A	FILTER P/STR GRAN	1
	■	VO-85129688	AIR DRIER KIT	1
	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
	■	VO-85151124	FILTER	1
	■	VO-21479276	BELT TENSIONER	1
	■	VO-21372850	V-RIBBED BELT	1
	■	VO-21556637	V-RIBBED BELT	1
	■	VO-21454379	BELT TENSIONER	1
	■	VO-1629499	CLAMP	1
	*	2520000	REAR EXHAUST CLAMP BROKEN	
	*	5222400	TWO FRONT STEER S LEAKING BRAKE HOSES	
	☒		COMPLAINT:CARRY OUT ANNUAL SERVICE AS PER SCHEDULE	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIR	
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIR.	
	■	AU2-CAL85121795	VDS4 (PER LITRE)	38
	■	AU2-CAL85131754PO	VOLVO GEAR OIL SYN 97315 PER L	17
	■	AU2-CAL85136280PO	VOLVO SYNTHETIC AX	35

PC	Type	Code	Description (Original)	#
----	------	------	------------------------	---

2020-06-05 - Mileage: 256034 - Order nr: 3350646

	*	3310000	NOT STARTING ON KEY, CLICKING.	
	*	30	ATTEND TO NOT STARTING ON KEY.	
			INVOICE 148245	

2020-05-07 - Mileage: 252645 - Order nr: 3350431

		VO-4670400	Differential, remove (rear rear)	1
		VO-20930114	FLANGE SCREW	4
		VO-4670500	Differential, install (rear rear)	2.8
		LO-170	CLEANING, ROAD TEST. RECHECK.	1.5
			COMPLAINT: OIL LEAKING FRON READ DIFFERENTIAL.	
		MK-8235-2208S1215	GASKET AXLE SHAFT	2
		AU2-LOC51827	Loctite 518 Gasket	2

2020-04-24 - Mileage: 239488 - Order nr: 3350359

	*	2653400	CHARGE AIR COOLER HOSES	
			Replace CAC hose on l/h side of CAC. PartÄ22908771	
	*	491	LEAKING OIL HOSES TO TRANSMISSION COOLER	
		VO-1675066	SEALING RING	1
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	
		VO-22818870	HOSE ASSEMBLY	1
		VO-22818873	HOSE ASSEMBLY	1
	*	10	SUBLET TG SPARES TO REPLACE HOSES AS REQ	

2020-04-24 - Mileage: 0 - Order nr: 5220004

	*	2653400	CHARGE AIR COOLER HOSES	
			Replace CAC hose on l/h side of CAC. PartÄ22908771	
	*	491	LEAKING OIL HOSES TO TRANSMISSION COOLER	
		VO-1675066	SEALING RING	1
	*	10	SUBLET TG SPARES TO CARRY OUT REPAIRS	

PC	Type	Code	Description (Original)	#
		VO-22818870	HOSE ASSEMBLY	1
		VO-22818873	HOSE ASSEMBLY	1
		10	SUBLET TG SPARES TO REPLACE HOSES AS REQ	

2020-03-25 - Mileage: 239488 - Order nr: 3350157

		2653400	CHARGE AIR COOLER HOSES	
			Replace CAC hose on l/h side of CAC. PartÄ22908771	
		491	LEAKING OIL HOSES TO TRANSMISSION COOLER	
		VO-22908771	CHARGE AIR HOSE	1
		VO-20550690	HOSE	2
		VO-1675066	SEALING RING	1
		10	SUBLET TG SPARES TO CARRY OUT REPAIRS	
		VO-22818870	HOSE ASSEMBLY	1
		VO-22818873	HOSE ASSEMBLY	1
		1774400	Basic service. Chassis lubrication and	
		VO-85114535	FILTER KITS	1
		VO-23448457	OIL SAMPLING KITX1	1
		2330600	Fuel filter, replace (one)	
		1750400	Lubrication according to actual	
		1751300	CHANGE ENGINE OIL AND FILTERS	
		7714500	Wheel nuts, check tightening (all)	
		2331100	Filter, water separator, replace	
		2141300	Valves and unit injectors, adjust	
		1751100	Lubrication of fifth wheel	
		2200400	Engine oil sample, take	
		10	SUBLET TG SPARES CARRY OUT SERVICE	
		10	SUBLET TG SPARES TO REPLACE HOSES AS REQ	
		265	CAC HOSES LEAKING	

2020-02-04 - Mileage: 224183 - Order nr: 8625584

		VO-3110200	Batteries, replace (all)	0.5
		VO-3116800	Battery system, test. Battery tester	0.4

PC	Type	Code	Description (Original)	#
		AU2-21209957	BULLDOG BATTERY - 12V	4
		VO-3200200	Charging test, in vehicle	0.4
			COMPLAINT: NOT STARTING ON KEY.	

2019-12-02 - Mileage: 96291 - Order nr: 809225

		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1

2019-11-14 - Mileage: 198174 - Order nr: 8625021

		VO-1774400	Basic service. Chassis lubrication and o	1.3
		VO-1750400	Lubrication according to actual lubricat	0.3
		VO-2331100	Filter, water separator, replace	0.3
		VO-2330600	Fuel filter, replace (one)	0.2
		VO-2200400	Engine oil sample, take	0.2
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
		VO-8720800	Air conditioning air filter, replace	0.5
		VO-85114535	FILTER KITS	1
		AU2-CAL85121795	VDS4 (PER LITRE)	38
		VO-23448457	OIL SAMPLING KITX1	1
		VO-85151124	FILTER	1
			COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	

PC	Type	Code	Description (Original)	#
 	<u>2019-10-21 - Mileage: 187098 - Order nr: 8624831</u>			
	*	3500000	NO PARK OR MARKER LIGHTS.	
	*	30	ATTEND TO NO ROOF OR MARKER LIGHTS.	
	*	192	VEHICLE BROKEN DOWN, TRAVEL TO VEHICLE AT	
	*	30	TRAVEL TO BREAKDOWN SITE.	
			INVOICE 37711	
 	<u>2019-09-18 - Mileage: 0 - Order nr: 8624555</u>			
	*	392	STEREO CUTTING OUT	
			JOB OPENED IN SEPTEMBER	
   	<u>2019-06-12 - Mileage: 145680 - Order nr: 8623792</u>			
		VO-1774600	Annual service	2.4
			17,033 LUBE SERVICE	
		VO-1750400	Lubrication according to actual lubricat	0.3
		VO-2330300	Fuel filter, replace (one)	0.3
		VO-2331200	Filter, water separator, replace	0.3
		VO-2200400	Engine oil sample, take	0.2
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
		VO-2562400	Filter insert, air cleaner, replace. Onl	0.2
		VO-2582200	Filter, AdBlue, replace	0.2
		VO-6452500	Oil filter, power steering, replace	0.2
		VO-5612600	Air drier, drier insert, replace	0.4
		VO-1758900	Lubrication of trailer hitch	0.1
		VO-8721600	Air filter, sleeper cab, replace	0.4
	*	4300000	SET GEARBOX START GEAR TO SECOND.	
	*	2550000	OIL LEAK AT TURBO DRAIN PIPE.	
		VO-8200000	Bonnet, front section, mudguard, foot st	0.5
		VO-85114535	FILTER KITS	1
		MK-99SX29414	KIT ANALYSIS OIL SAMPLE	1
		AU2-CAL85121795	VDS4 BULK ENGINE O	38

PC	Type	Code	Description (Original)	#
		VO-85123524	FILTER CARTRIDGE	2
		VO-21516231	FILTER, UDS	1
		MK-5839-870678A	FILTER P/STR GRAN	1
		VO-85129688	AIR DRIER KIT	1
		AU2-CAL3043448	LIPLEX HD 24 X 450	1
		VO-85151124	FILTER	1
		VO-420643	GASKET	1
		VO-469601	SEAL RING	1
		VO-21940615	SEALING RING	1
		AU2-9770-5089	BRAKLEEN 500g Aer	2
		VO-84192243	SHIM	2
		LO-170	TAKE CHARGE	0.3

2019-01-11 - Mileage: 98788 - Order nr: 8622608

		VO-1774400	Basic service. Chassis lubrication and o	5.3
			17,033 LUBE SERVICE	
		VO-1750400	Lubrication according to actual lubricat	0.3
		VO-2331100	Filter, water separator, replace	0.3
		2330600	Fuel filter, replace (one)	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
		VO-2200400	Engine oil sample, take	0.2
		VO-2141300	Valves and unit injectors, adjust	2.2
		VO-85114535	FILTER KITS	1
		MK-99SX29414	KIT ANALYSIS OIL	1
		AU2-CAL85121795	VDS4 BULK ENGINE O	38
		AU2-CAL85121792	B/DOG HP GREASE NL	1
		VO-9130476	SPLICE-BLUE(14-16)	2

2018-12-07 - Mileage: 87926 - Order nr: 8622374

		VO-5631700	Footbrake valve, replace	1.1
		VO-21144822	VALVE	1
		LO-170	take charge	0.3

PC	Type	Code	Description (Original)	#
		VO-1701200	Fault codes, reading	0.2
			complaint: BRAKE MALFUNCTION AND BRAKE LOCKING UP.	

  2018-12-03 - Mileage: 84769 - Order nr: 809225

		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1
		VO-9600000		1

  2018-09-13 - Mileage: 51026 - Order nr: 4880979

		VO-8631000	Mudflap, install. Campaign only	3
			CREDIT ON DOUNLE LABOUR AS DISCUSSED.	
	*	91	WORKSHOP CONSUMABLES	

   2018-09-05 - Mileage: 51026 - Order nr: 8621441

		VO-1774400	Basic service. Chassis lubrication and o	5.3
		VO-1750400	Lubrication according to actual lubricat	0.3
		VO-2331100	Filter, water separator, replace	0.3
	*	2330600	Fuel filter, replace (one)	
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.5
		VO-2200400	Engine oil sample, take	0.2
		LO-255	SQUEALING NOISE FROM TURBOCHARGER	2.8
		VO-21397620	TURBOCHARGER	1
		VO-1543499	FLANGE NUT	4
		VO-20573472	SPACER SLEEVE	4
		VO-20784537	GASKET	1
		VO-20855371	GASKET	6
		VO-21345127	STUD	4
		VO-21940615	SEALING RING	1

PC	Type	Code	Description (Original)	#
	■	VO-22206133	GASKET	1
	■	VO-420643	GASKET	1
	■	VO-469601	SEAL RING	1
Ⓒ	■	VO-85114535	FILTER KITS	1
Ⓒ	■	MK-99SX29414	KIT ANALYSIS OIL	1
Ⓒ	■	AU2-CAL85121792	B/DOG HP GREASE NL	1
Ⓒ	■	VO-85123524	FILTER CARTRIDGE	2
Ⓒ	■	AU2-CAL85121795	VDS4 BULK ENGINE O	38
	■	VO-21055586	MUDFLAP	2
	■	VO-990862	FLANGE SCREW	6
	■	VO-990951	FLANGE LOCK NUT	6
	■	VO-984737	FLANGE SCREW	1
	■	VO-993811	FLANGE SCREW	4
	■	VO-1675066	SEALING RING	1
	■	VO-21096684	SEALING RING	1
	🔧	VO-8631000	Mudflap, install. Campaign only	3
	📋		COMPLAINT:CARRY OUT BASIC SERVICE AS PER SCHEDULE	
	🔧	LO-170	TAKE CHARGE	0.3
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	

📋🔧 2018-08-10 - Mileage: 42602 - Order nr: 8621196

*	3500000	LIGHT ISSUE NO LIGHTS ON RIGHT SIDE.	
*	30	ATTEND TO NO LIGHTS ON RIGHT SIDE.	
📋		INVOICE 31931	

📋🔧Ⓒ📋 2018-05-30 - Mileage: 9469 - Order nr: 8620485

Ⓒ	🔧	VO-1772800	First service. After 4 weeks or maximum	5
	📋		5000 KMS	
	🔧	VO-1700800	Conversion kit , programming	1.1
	🔧	LO-371	TRAILER RED SWITCH WONT STAY IN 1/2 TURN	1
	*	3523700	SPOTLIGHTS ON BONNET BLOWS FUSES	

PC	Type	Code	Description (Original)	#
		VO-3753300	Trailer indicator light, wires, replace.	1.2
	*	3642500	SQUEAL IN EXHAUST BRAKE APPLICATION	
		LO-821	PACK SPACERS IN BONNETT - MOVEMENT	0.5
		VO-3633800	Washer reservoir, replace	0.5
	*	10	ATTEND TO SPOT LIGHTS NOT WORKING.	
		VO-85114535	FILTER KITS	1
		VO-22038908	OIL FILTER KIT	1
		MK-99SX29414	KIT ANALYSIS OIL	4
		VO-84192243	SHIM	4
	*	40	ATTEND TO OIL COOLER HOSE LEAKING.	
		AU2-CAL85121795	VDS4 BULK ENGINE O	38
		AU2-CAL85131754	VOLVO GEAR OIL 208	0.1
		MK-9727-3334800	DYNADRIIVE 80W90	0.2
		VO-85132423	CONVERSION KIT	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2

2018-05-22 - Mileage: 1 - Order nr: 809225

		VO-AGREEMENT COMMISSION		1
--	--	----------------------------	--	---

2018-05-02 - Mileage: 0 - Order nr: 8620212

		LO-177	S & F Stoneguard	2
		VO-23167938	KIT. WINDSCREEN ST	1
		VO-1900000	Miscellaneous, general. Secondary operat	0.6
		VO-8900000	Miscellaneous, general	2
			SOURCE THE SIGNS FRON B&H	
		VO-3500000	Lighting, general. Secondary operation n	0.5
		VO-7700000	Wheel, tire, hub, general	0.5
		OTH-SSR316	RIVET,3/16 S/S	8

2018-04-30 - Mileage: 100 - Order nr: 8720001

	*	10	T'VILLE - DAMAGED DOOR TRIM	
--	---	----	-----------------------------	--

PC	Type	Code	Description (Original)	#
	📅		TO BE PROCESSED AS A JOURNAL	

📅 2018-04-20 - Mileage: 0 - Order nr: 8619695

🔍	VO-1710200	Delivery service	6
🔍	LO-17010	Check for campaigns	0.4
*	9900000	Carry out HP upgrade to 535HP	
*	9900000	S & F 535HP Badges	
*	8400000	Fit supplied bling	
🔍	VO-21430124	LABEL 500HP	2
🔍	VO-8400000	Outside trim parts, glass, sealing mould	0.2
🔍	OTH-YLF0838	m88 large splined rivnut	1
🔍	VO-21029787	PANEL	1
🔍	VO-20733172	SILENCER	1
🔍	VO-4800000	Power take-off, general. Secondary opera	0.2
🔍	VO-4810000	Power-take off (gearbox). Secondary oper	1
🔍	VO-3500000	Lighting, general. Secondary operation n	0.5
🔍	VO-21430126	LABEL MP8 535HP	2
🔍	LO-177	S&F RED BUG DEFLECTORS	2.5
🔍	OTH-SSR316	RIVET,3/16 S/S	8
🔍	OTH-LARR	BUG DEFLECTOR LARGE	1
🔍	OTH-BKT4	4 BRKT KIT BUG DEFLE	1
🔍	MK-9711-00116M3	HUBCAP	2

📅 2018-03-20 - Mileage: 100 - Order nr: 8719462

*	EPA	ENVIROMENTAL	
*	91	WORKSHOP MATERIALS	
🔍	OTH-MCMK-CABSSKICK	STAINLESS KICK PANELS	1
🔍	LO-809L43C	S&F CHROME KICK PANEL	1
*	EPA	ENVIROMENTAL	
*	91	WORKSHOP MATERIALS	
🔍	LO-846L43U	UNI POD MIRROR LH	1

PC	Type	Code	Description (Original)	#
	■	MK-9711-6785HMS	KIT-CONVEX MIRROR (UNIPOD)	1
	*	91	WORKSHOP MATERIALS	
	■	MK-9732-BG12	DUST BLOWER	1
	■	MK-FT1864X4	TEE 1/4" TUBE 3 WAY	1
	☺	LO-566L43C	FIT CAB AIR BLOWER	1.27
	*	10	CUSTOM BADGE TO READ	
	☒		GRIGGS EQUIPMENT	
	☺	LO-830L43R	REMOVE CENTRAL LOCKING SWITCHES FROM	0.5
	☺	LO-850L43D	S&F DASH MAT & FLOOR MATS	0.5
	*	91	WORKSHOP MATERIALS	
	*	EPA	ENVIROMENTAL	
	■	OTH-MCMK-MATSFLOORDAS	FLOOR & DASH MATS - MACK	1
	*	91	WORKSHOP MATERIALS	
	*	EPA	ENVIROMENTAL	
	☺	LO-882L43D	DRIVERS DOOR GRAB HANDLE -SAFETY YELLOW	1.32
	■	OTH-MCMK-DOORGRAB-Y	YELLOW DRIVER DOOR GRAB HANDLE	1
	☺	LO-770P43H	SUPPLY CHROME HUBCAPS 6X4 (MACK HUBS)	1.18
	☺	LO-891P43B	S&F BATTERY ISOLATION SWITCH (RED)	6.5
	☺	LO-330P43J	S&F JUMP START PLUG - ANDERSON 350A	1.98
	☺	LO-850L43L	FIT LIFE HAMMER	0.9
	*	EPA	ENVIROMENTAL	
	*	91	WORKSHOP MATERIALS	
	■	OTH-P251-69097	LIFE HAMMER	1
	☺	LO-356L43H	FIT HELLA DAY RUNNING LED LIGHTS	5
	*	91	WORKSHOP MATERIALS	
	■	OTH-NARV56078EA	TERMINAL RING BLUE 5mm (x1)	3
	■	MK-NARV56650	DUAL WALL HEAT SHRINK 300MM	1
	■	MK-NARV56707	CONDUIT 7mm 1=10M SPLIT TUBING	1
	■	OTH-T110PMTR	CABLE 3MM TWIN CORE	4
	■	OTH-T148MTR	CABLE 3MM 3 CORE	2
	■	MK-4381-4973	CONNECTOR RELAY UN	1

PC	Type	Code	Description (Original)	#
	☒	MK-4381-5636	LED DAYTIME RUNNING KIT (12V)	1
	☒	VO-948211	CABLE TIE 4.5mm x 280mm	50
	☒	VO-994780	SCREW M5*16 TORX	1
	☒	VO-9130476	SPLICE BLUE 1 - 2.5 mm	2
	🔧	LO-360L43P	PROGRAM PTO PARAMETERS	0.94
	🔧	LO-845	S&F WORKLIGHTS MIRROR MOUNTED WITH	4.63
	🔧	LO-350	S&F DRIVING LIGHTS - LIGHTFORCE 170 XGT	8
	☒	VO-25159354	PLUG	2
	☒	MK-9732-0011UNI	HUBCAP 8-5/8 4 OR 5 SLOT	2
	☒	MK-9732-7103	HUBCAP 8 INCH SNAP	4
	☒	OTH-BMS-18R	LOCKOUT SWITCH RED	1
	☒	OTH-C35RED	35MM2 BATTERY CABLE	2
	☒	OTH-ISO-1	BATTERY ISO PLAQUE	1
	☒	OTH-75910B	SWITCH MASTER 6-32V	1
	☒	VO-941936	CABLE LUG (S35-10)	3
	☒	VO-955272	BOLT M6*20 B	1
	☒	VO-984481	CABLE LUG (S70-10)	4
	☒	VO-984726	BOLT M6*20 FL	4
	☒	VO-984730	BOLT M6*50 FL	1
	☒	VO-990949	NUT M6 FL LOC	6
	☒	OTH-SB350	ANDERSON PLUG 350AMP	1
	☒	OTH-S70-8	CABLE LUG (S70-8)	2
	☒	VO-984442	ELECTRIC CABLE, 70mm2 BLACK	2
	☒	VO-984443	BATTERY CABLE, 70mm2 RED	2
	☒	VO-990939	NUT M6 FL	2
	☒	VO-994847	WASHER M6 x 18mm	6
	☒	OTH-MCMK-MIRRORLOADLI	LOAD LIGHT - MIRROR MNTD, MACK	1
	☒	MK-EMEWP02K	W/PACK 2 WAY CONN	2
	☒	MK-NARV56600	HEAT SHRINK 1=1 150 SM.	1
	☒	MK-NARV56710	CONDUIT 10mm 1=10M SPLIT TUBIN	1
	☒	OTH-T150MTR	CABLE 4MM TWIN CORE	10
	☒	VO-25088528	TERMINAL	1

PC	Type	Code	Description (Original)	#
	■	MK-4381-3080	RELAY 12V C/OVER 5 PIN20/30AMP	1
	■	VO-82279626	SWITCH DRIVING LIGHTS	1
	■	VO-952627	P CLAMP M13	4
	■	VO-976123	RIVET 3/16" x 7/16"	4
	■	OTH-ATNSGC	LIGHTFORCE SECURITY KIT	1
	■	OTH-DL210LED	LIGHTFORCE GENESIS 210 LED	2
	■	OTH-LFDLHTS	LIGHTFORCE LED LOOM KIT	1
	*	20	GRIGGS - REMOVE SLEEPER WINGS & REPAIR	
	☺	LO-771P43Z	S&F RED ZAFETY LUG LOCKS	1
	■	OTH-ZRD33089	RED ZAFETY LUG LOCKS 285PCD	30
	☺	LO-185	TRANSPORT FROM TRAILER SALES TO RWI	0.75
	☺	LO-186	TRANSPORT FROM RWI TO TRAILER SALES	0.75
	*	30	GRIGGS - PAINT SPOTLIGHT BRACKETS	
	*	99	FUEL SUPPLY- FUEL CARD	
	*	40	SUPPLY BOLTS FOR BONNET BRACKETS	
	*	MT43STEEL	ALLOY FOR SPOTLIGHT MOUNTS	
	☺	LO-230	FUEL FOR 809225	1
	*	91	WORKSHOP MATERIALS	