

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

CH-11
SEP

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: CENOVUS CLN

Unit No: WT-02

Hr Meter: *N/A*

Date: August 17, 2026

Subcontractor: Dylqn Baryssa

[illegible][illegible]

WORK DESCRIPTION

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

**A. Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Ph: (780) 623-2242
Cell: (780) 623-0340

Site:


Date: Apr. 28/25

Subcontractor: Lane

[illegible][illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Wt-02

Date: January 4/25

Hr Meter: No Meter

Subcontractor: Dylan Boats

Description:	Hours
Removed front/	5hrs
Rear axle tires/	
drums	
changed Abs	
wires/ inspected	
Put drums/wheels	
ON	
torgued wheels	
Set Breaks	

NO.	QNTS.	Parts/Materials
	4	ABS sensors

WORK DESCRIPTION

Parts from ethos



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 36 / WT-02

Date: Jan 4 / 25

Hr Meter:

Subcontractor: Shawn.

Description:

Hours

- noticed coolant leak changed hose clamp on hose to thermostat
- re-align and set hood on #36
- remove passenger seat replace with good used one
- build two brackets for back up lights on truck
- secure hose fill tube on rack
- install new hose tubes in pump box for heater vents
- install torch holder in pump box

NO.

QNTS.


Parts/Materials

1 light Ethos.

6 1/2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

WT-02
New Portable Water Trailer

Hr Meter:

No Meter

Date:

September 9 2024

Subcontractor:

CS Biegle

Description:

Hours

- Took hydraulic hose

off

- Fittings off

- Took brackets for
hydraulic line off

- Me / on tightened

up all fittings

- Added rubber under
brackets for no rattle

- Fastened all brackets

- All fitting back on

- Hydraulic hose back on

6 hrs

NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION