

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: HV-01

Date: May 13/25

Hr Meter:

Subcontractor: Dylan Baurassa

Description:

Hours

Changed Tractor

Protection Valve

- 1 hr

NO.

QNTS.

Parts/Materials

1

Tractor Protection Valve

TRAVEL:

WORK DESCRIPTION

Valve from SMR diesel,



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg Energy

Unit No: HV-01

Hr Meter: 25,801 hrs

[illegible]


Date: May 7/2025

Subcontractor: Dylan Borrassa

[illegible]

WORK DESCRIPTION

oil from GFA,	
filter from SMR diesel,	



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Mea

Unit No: # HV-01

Date: 17 March 19/25

Hr Meter:

Subcontractor:

Leah

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: HV-a1

Date: January 23/25

Mtr Meter: 659,523.6 Kms

Subcontractor: Dylan Bourns


Description:	Hours
Put Rear end on Jackstands	
Removed rear tires	
Change 3rd Rear axle	
Break pot on Left side	
changed 2nd Rear axle	
shocks	- 10 hrs
DID C-VIP	
Greased Rear end	
Put Rear wheels on	
took off Jackstands	
Filled all tires	
too 110 PSI	

NO.	QNTS.	Parts/Materials
	1	30/30 Break Pot
	2	shocks
	1	Grease tube
		TRAVEL:

WORK DESCRIPTION

Break Pot from shop supply, shocks from SMR diesel,
Grease from shop supply,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Date: Jan 23/25

Hr Meter:

Subcontractor: Shawn.

Description:

Hours

NO.

QNTS.

Parts/Materials

- top up transfer case with gear oil
- finish installing seal on blower drive shaft
- re-bolt flanges on blower shaft.
- remove U joint to transmission
- remove input seal and gasket
- install new ones (seals)
- new U joint clips
- check tranny and diff fluid levels
- finish installing light in workbench
- install paper towel rack, first aid


10 1/2 hrs

WORK DESCRIPTION

Kit, eye wash station

ordered new floor mats

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: # HV01

Hr Meter:

Date: Jan 22/25


Subcontractor: None

Description:	Hours
① Help Shawn troubleshoot and install blower input seals.	
	1/hr

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Date: Jan 22/25

Hr Meter:


Subcontractor: Shawn

Description:	Hours
- finish installing new rear transfer case seal and install drive shaft	
- torque down bolts	
- remove rear aluminum cover guard behind work cab to access blower drive shaft and seal.	
- remove yoke and seal.	
- install new seal but wrong one.	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Hr Meter:

Date: Jan 21/25

Subcontractor: Shawn P.

Description:

Hours

- wash under truck
- change out work cabinet heater with new one (passenger side)
- clean out drawers in work cabinet.
- remove drive shaft and change flange seal on front side transfer case
- re install drive line new bolts
- remove rear drive line from transfer case and remove seal and housing

NO.

QNTS.


Parts/Materials

- Sapphire (bolts) nts.) 24 each.
- SMR- new flange (in on 22 Jan Am)

8 1/2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HL 15/300w Blade HVO1

Date: Jan 27/25

Hr Meter:


Subcontractor: Shawn

Description:	Hours
- washed both rear compartments and all fittings	
- installed ear plug dispenser	
- stocked truck with face shields and hard hat straps	2 hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV01

Date: DEC 9/24

Hr Meter:

Subcontractor: Shaun

Description:

Hours

- change both plastic coolant lines to compress
- drain coolant
- fill coolant tank
- remove water fluid tank (install new one)
- open up rear hatch (full of frozen mud)
- clean passenger door access to pump
- winterize pump and hoses

NO.

QNTS.


Parts/Materials

SMR- Coolant lines plastic
3 of them.

4 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV01

Date: Nov 30/24

Hr Meter:

Subcontractor: Shawn.

Description:	Hours
- remove old broken harness for Webasto	
- install new harness	
and test Webasto heater	
2 runs - works great	
	2 hrs

NO.	QNTS.	Parts/Materials
		harness from shop stock

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: #HV-01

Hr Meter:

[illegible]

Date: June 6/24

Subcontractor: ICNL

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #HV-01

Date: May 22/24

Hr Meter:

Subcontractor: ZonL

Description:

Hours

① Troubleshoot water leak @ hose reel
↳ Packing seals are worn in swivel
fitting. Ordered new

② Troubleshoot erratic function of remote
control.

↳ Needs new rechargeable batteries
x4 "AA"s

1hr

NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: HV-01

Date: May 8 / 24

Hr Meter: 212598hrs

Subcontractor: Shaun P.

Description:	Hours
- help install boom bearing and boom	
- install new hoses to boom bearing cylinder	
- help change cut tire from old blue 33 to HV-01.	

5hrs.

NO.	QNTS.	Parts/Materials
		TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: [#] HV-01

Hr Meter: _____[illegible]

Date: Mon 8/2024


Subcontractor: Larl

[illegible]

WORK DESCRIPTION

[illegible]

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

HV-01

Date:

May 8 2024

Hr Meter:

21259.8

Subcontractor:

CS Biegler

Description:

Hours

- Took off 2 rear axle
wheels, switched
tires and rims

from old axle

- Put new tires
on, 8 of them

Torqued wheels.

- All done with

Dylan

6 hrs


NO.

QNTS.

Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Date: May 8/24


Hr Meter: 212598 hrs

Subcontractor: Dylan Bodrassy

Description:	Hours
removed rear	- 3 hrs
wheels on axle	
#2 and #3	
Put Tires on from	
old Blqe	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: 7

10: # HV 01

Date:

May 1/2024

Hr Meter:


Subcontractor:

Tan L

[illegible][illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: HV-01

Date: May 1 / 24

Hr Meter: 21,257.3 hrs

Subcontractor: Dylan Boarassa

Description:	Hours
changed oil	1 hr
changed oil filter	

NO.	QNTS.	Parts/Materials
	2	5W40 oil Pale's
	1	oil filter

WORK DESCRIPTION

filter from SMR diesel, oil from shop supply's



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Mea

Unit No:

#HV-01

Date:

Apr. 22/24

Hr Meter:

Subcontractor:

Thank

Description:

Hours

① Inspect boom turret. They said it was stuck. It moved freely now.

↳ Did notice/hear a grind noise in turret worm gear. No inspection cover to visually see inside.

↳ Al ordered parts and we will remove and repair.

2hrs

NO.


QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No. #11701

Hr Meter:

Date: April 6/2024


Subcontractor: Ionl

Description:	Hours
① Thread together couplers and unions for 8" pipe extensions. 1/2 inch longer than last time. Good will when new filling.	1hr
	1hr

NO.	QNTS.	Parts/Materials
	x 3	8" pipe extensions

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: #HV-01

Hr Meter:

Date: Feb 18/2024

Subcontractor: Ionl

Description:	Hours
① Replace heater assembly in pressure washer compartment. ↳ Had to remove coolant lines. Lost about 8 litres.	
② Top up anti-freeze to proper level.	

NO.	QNTS.	Parts/Materials
	x1	heater assembly
	x8	litres 50/50 antifreeze
		TRAVEL :

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meer

Unit No: _____

#HV-01

Hr Meter:

Date:

e: ~~F~~ 8/24

Subcontractor:

Tom

Description:	Hours
① Replace broken idler pulley	
② Install new alternator belt	
	1 1/2 hrs

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meg

Unit No:

HU-01 W. Star

Date:

Jan 23/24


Hr Meter:

Subcontractor:

Lon C

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: shop

Hr Meter: 20,689.4 hrs

Subcontractor: Dgln B04r9559

[illegible]

picked oil up at ufa, picked filter up at
Ethio's.



REPAIR REPORT

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site:

Unit No: 4V-01

Hr Meter: 20688ms


Date: December 28/23

Subcontractor: Shawn

Description:	Hours
Completely rebuild inside	
compartment drawers, new pop	
rivets, repaired stall shelves	
repaired lights	
cleaned up washing bay area	
and lubed up pump	5hrs

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: #HV-01 W.S for

Date: Dec 27/2023

Hr Meter:

Subcontractor: IanL

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Hr Meter: 20688.7 hrs

[illegible]

Date: Dec 27/23

Subcontractor: Dylan Bortness

[illegible]

WORK DESCRIPTION

Tire from ok tire



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mealy S/S

Unit No: # HV-01 Western Star

Date: Dec 18/2023

Hr Meter:

Subcontractor: Eal

Description:

Hours

① Replace #1 axle R/H tire

② Repair 3" ball valve on water tank

1 1/2 hrs

NO.

QNTS.

Parts/Materials

x/ 445/65R 22.5 tire (Ok Tire)

x/ 3" ball valve (Sapphire)

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Shop

Unit No: HV-01

Hr Meter: 246288.6 KMS

[illegible]

Date: oct 25/23


Subcontractor: Dylan Boetrassa

NO.	QNTS.	Parts/Materials
	1	Ball valve
		TRAVEL :

WORK DESCRIPTION

WORK DESCRIPTION	

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: #HV-01 Western Star

Date: Oct. 24/23

Hr Meter:

Subcontractor: Iarc

Description:

Hours

NO.

QNTS.

Parts/Materials


① Drain water from system once ice thawed.

② Perricle broken 3" ball valve @ fresh water tank that split open.

1 1/2 hrs

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiężny

Ph: (780) 623-2242

Cell: (780) 623-0346

Site:

Shop

Unit No:Hr Meter:

Description:

Hours

① Install new keyway on hyl pump drive sprocket to the pressure pump.

② Help Kyle with 2" ~~flex~~ valves for the main water feed line.

2 1/2 hrs

Date:Subcontractor:NO.

QNTS.


Parts/Materials

x

$\frac{3}{8}$ keystock (Sapphire)

TRAVEL:

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Shop

Hr Meter:

Subcontractor: Ian L

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: HV-01

Date: August 1, 2023

Hr Meter: 20217.7 hrs

Subcontractor:

Description:	Hours
Changed oil filter	5 hrs
drained old oil	
Filled with new oil	
Took out oil	
filters and cleaned	
Put Back in	
ordered AC switch	
from SMT	
Helped set up	
for test	
Made sign for	
when work is	
being done	

NO.	QNTS.	Parts/Materials
	1	filter
	2.5	15W40 Pales
		Supplies from C-CAN/
		Shop supplies.
		TRAVEL:

WORK DESCRIPTION

Picked up oil from ~~USA~~, filter from Saphire.
Drove to saphire, SMT, etiose to look for AC switch.