

# What Has Been Repaired / Fixed

## Mechanical Repairs

Boom cylinder repairs (multiple)

Lift ram removed, repaired, and refitted

Steering cylinder resealed (leak fixed)

Broken ladder repaired

Stairs rebuilt/replaced

Torque converter stand fabricated

Radio bracket repaired

Seat replaced (air seat leak diagnosed + new seat fitted)

## Hydraulic Repairs

Multiple **hydraulic hose replacements/repairs**, including:

Control valve hoses

Cooler hoses

Articulator hose (blown → repaired)

Steer hose

Hydraulic leaks repaired (several entries)

Grease lines repaired/replaced

Tilt cylinder hose safety lanyard installed

Water pump & thermostats replaced (overheating issue)

## **Engine & Powertrain Repairs**

Transmission faults:

Downshift fault repaired

Transmission inspected and repaired

Engine fault diagnosis and repair

Ignition power fault repaired

Oil pressure switch fitted

Coolant leak repaired

Overheating issues addressed (thermostat + cooling system work)

## **Electrical Repairs**

Electrical faults diagnosed and repaired

Gauge cluster frozen → repaired

Circuit breaker (start fault) repaired

Beacon repaired/reinstalled

Battery checked and replaced

UHF installed

## **Fluid & Leak Fixes**

Oil leaks repaired (multiple instances)

Hydraulic oil topped up regularly

Engine oil filled

AdBlue filled

Transmission oil changed

Coolant leaks fixed

## **General Repairs & Adjustments**

Cutting edges replaced/adjusted multiple times

Pins greased / dry pins addressed

Tyres:

Flat tyre repaired

Tyre inflation/relocation completed

Hose routing, transfers, and clean-ups completed

## **Major Services Completed**

Multiple **250hr services**

Multiple **500hr services**

Extensive **1000hr services**

**2000hr service + defects**

“Service & defects” completed repeatedly (indicates ongoing issue resolution)

## **Installations / Upgrades**

Bucket fitted

Bucket pin installed

Number boards & beacons installed

Safety lanyard installed

Fuel bowl fitted