


03770980

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Vehicle Standards and Inspect
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 

A767327

Date Inspection Started DAY: 21 MO: 02 YR: 2011	Station Number A31218	Station Name P. 15	City
Date Inspection Completed DAY: 21 MO: 03 YR: 2011	Mechanic Number M1916112	Mechanic Signature	Station Phone Number
Inspection Expiry Date DAY: 31 MO: 03 YR: 2011	Vehicle Owner M. 3316 or C. 3316		
Address		City	Province
		Postal Code	Phone
<input checked="" type="checkbox"/> Pass/Safe Vehicle	Licence Number TE154DB	Prov. MB	NSC #
<input checked="" type="checkbox"/> Fail/Unsafe Vehicle	Vehicle Identification Number 1F-L-1111111111111111	Make Ford	Model F150
<input type="checkbox"/> Fail/Hazardous	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle	Odometer Reading 16577	Odom. Type km

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>14</td> <td>13</td> <td>16.57</td> <td>16.42</td> <td>1.3</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>13</td> <td>13</td> <td>16.47</td> <td>16.34</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	14	13	16.57	16.42	1.3	1.5	2	13	13	16.47	16.34	1.5	1.5	3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	14	13	16.57	16.42	1.3	1.5																																																																		
2	13	13	16.47	16.34	1.5	1.5																																																																		
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X	X	Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>11</td> <td></td> <td></td> <td>122</td> <td>122</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>12</td> <td>11</td> <td></td> <td></td> <td>122</td> <td>122</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	12	11			122	122			2	12	11			122	122			3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	12	11			122	122																																																																		
2	12	11			122	122																																																																		
3																																																																								
4																																																																								
5																																																																								
		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.