



Commercial Vehicle Inspection Report

Decal Number: GH58632
Decal Expiry Date: 2026-May-31
Inspection Number: 21350842

Inspection Result:
PASS

FACILITY:		INSP. TYPE:	Complete	INSP. START:	2025-May-14 08:00 AM PDT
INSPECTOR:	Haverty, Kieran Albert / 108064	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-May-14 10:00 AM PDT
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	10285667	VIN:	1HTMMAAN5CH608031
PLATE #:	WN2067	UNIT/FLEET#:	03	OWNER/LESSEE NAME:	
PERMITTED GVW(kg):	14188	BODY STYLE:	Flat Deck	ADDRESS:	
VEHICLE YEAR:	2012	ODOMETER:	341084 KM		
MAKE:	INTERNATNA	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	30	35	11.9			11.1	✓
2	Clamp	30	Automatic	37	40	11.1	10.3	11.9	12.7	
Comment:				Comment:						

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	64	66	Lining (Shoe)		17	17	Drum		
2	88	83	Lining (Shoe)		17	17	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.				

Inspection Comments:	
Has this Vehicle been road tested?	No
Inspector:	Haverty, Kieran Albert
Road Test Date:	
Signature:	
Road Tester:	

Inspection Report was submitted to CVSE on 2025-May-14 11:22 AM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.