S04-2

Ontario DriveON

Annual Inspection Certificate
&
Safety Standards Certificate

VEHICLE INFORMATION			
Plate#:	Y9547R	Year:	2014
VIN:	2M5931614E1140583	Make:	MANAC
GVWR (kg):	54437	Model:	MANAC TRAILER
Odometer ():		Type:	Trailer

CERTIFICATE INFORMATION	
Annual Inspection Certificate	Expires at the end of: May 2027
Safety Standards Certificate	Expires at the end of: June 9, 2026
Vehicle Inspection Certificate Number	LS20AD41
Inspection Start Date	May 4, 2026 System Time: 08 : 09
Inspection End Date	May 4, 2026 System Time: 09 : 00

VEHICLE INSPECTION CENTRE	
Vehicle Inspection Centre #: 13563	Technician: PAUL DUBAY
LMB TRANSPORT INC.	
O/A LMB TRANSPORT INC.	
209 PUTMAN INDUSTRIAL RD	Technician Signature
BELLEVILLE, ON K8N4Z6	Technician ID: 317301
613-968-7541	STO ID/Account: 13800214
	Trade Code: 310T, 310S

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?

Call the Public Contact Centre 1-833-420-2103 or go to

https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program.

MINISTRY OF TRANSPORTATION
SAFETY INSPECTION REPORT

Ontario DriveON

Vehicle Inspection Certificate Number: LS20AD41
Start Date / Time: May 4, 2026, 8:09 AM
End Date / Time: May 4, 2026, 9:00 AM

VEHICLE/ENGINE INFORMATION	CHASSIS
Plate#: Y9547R	Year: 2014
VIN: 2M5931614E1140583	Make: MANAC
GVWR(kg): 54437	Model: MANAC TRAILER
Odometer:	Fleet ID: 18

SAFETY INSPECTION RESULT	PASS

SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection

MANDATORY ITEMS

Inspection Item	Result
Axle 1, Driver Side Tire	
Tire Tread Depth (mm)	13
Initial Tire Pressure (kPa)	828
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	10
Drum Inside Diameter (mm)	420.59
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 1, Passenger Side Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	828
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	8
Drum Inside Diameter (mm)	420.05
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 2, Driver Side, Inner Tire	
Tire Tread Depth (mm)	15
Initial Tire Pressure (kPa)	720
Axle 2, Driver Side, Outer Tire	
Tire Tread Depth (mm)	15
Initial Tire Pressure (kPa)	720
Drum Brakes	

Inspection Item	Result
Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	14
Initial Tire Pressure (kPa)	720
Axle 2, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	14
Initial Tire Pressure (kPa)	720
Drum Brakes	

Drum Inside Diameter (mm)	419.79
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Drum Inside Diameter (mm)	419.73
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	13
Drum Inside Diameter (mm)	418.77
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	720
Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	720
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	13
Drum Inside Diameter (mm)	419.78
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 4, Driver Side, Inner Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Axle 4, Driver Side, Outer Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	720
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	13
Drum Inside Diameter (mm)	419.46
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Inspection Item	Result
Axle 4, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	720
Axle 4, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	720
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	14
Drum Inside Diameter (mm)	420
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	1

Vehicle Inspection Centre #: 13563

LMB TRANSPORT INC.

290 PUTMAN INDUSTRIAL RD

Technician #: 317301

Name: PAUL DUBAY

Report Number: 218

613-968-7541

Software Version: 2025.06.18.1

STO ID/Account: 13800214

Trade Code: 310T, 310S

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program

Ontario DriveON

Annual Inspection Certificate
&
Safety Standards Certificate

VEHICLE INFORMATION			
Plate#:	Y9547R	Year:	2014
VIN:	2M5931614E1140583	Make:	MANAC
GVWR (kg):	54437	Model:	TRAILER
Odometer ():		Type:	Trailer

CERTIFICATE INFORMATION	
Annual Inspection Certificate	Expires at the end of: Jun 2026
Safety Standards Certificate	Expires at the end of: July 17, 2025
Vehicle Inspection Certificate Number	LS20AC24
Inspection Start Date	Jun 11, 2025 System Time: 8 : 53
Inspection End Date	Jun 11, 2025 System Time: 9 : 55

VEHICLE INSPECTION CENTRE	
Vehicle Inspection Centre #: 13563	Technician: RICHARD THOMPSON
LMB TRANSPORT INC.	
O/A LMB TRANSPORT INC.	
209 PUTMAN INDUSTRIAL RD	Technician Signature
BELLEVILLE, ON K8N4Z6	Technician ID: 191215
613-968-7541	STO ID/Account: 13171305
	Trade Code: 310T, 310S

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?
Call the Public Contact Centre 1-833-420-2103 or go to
https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program.

MTO Office use only: 93760B0R54494T2J6457

MINISTRY OF TRANSPORTATION
SAFETY INSPECTION REPORT

Ontario DriveON

Vehicle Inspection Certificate Number: LS20AC24
Start Date / Time: Jun 11, 2025, 8:53 AM
End Date / Time: Jun 11, 2025, 9:55 AM

VEHICLE/ENGINE INFORMATION	CHASSIS
Plate#: Y9547R	Year: 2014
VIN: 2M5931614E1140583	Make: MANAC
GVWR(kg): 54437	Model: TRAILER
Odometer:	Fleet ID: QD4018

SAFETY INSPECTION RESULT	PASS

SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection

MANDATORY ITEMS

Inspection Item	Result
Axle 1, Driver Side Tire	
Tire Tread Depth (mm)	13
Initial Tire Pressure (kPa)	720
Drum Brakes Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 1, Passenger Side Tire	
Tire Tread Depth (mm)	11
Initial Tire Pressure (kPa)	720
Drum Brakes Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 2, Driver Side, Inner Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Axle 2, Driver Side, Outer Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Drum Brakes Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15

Inspection Item	Result
Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Axle 2, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	720
Drum Brakes Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	Over 15

Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720
Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720
Drum Brakes **Bonded/riveted continuous strip**	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Drum Brakes **Bonded/riveted continuous strip**	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 4, Driver Side, Inner Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Axle 4, Driver Side, Outer Tire	
Tire Tread Depth (mm)	10
Initial Tire Pressure (kPa)	720
Drum Brakes **Bonded/riveted continuous strip**	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Inspection Item	Result
Axle 4, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Axle 4, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	9
Initial Tire Pressure (kPa)	720
Drum Brakes **Bonded/riveted continuous strip**	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	31

Vehicle Inspection Centre #: 13563	**Technician #:** 191215
LMB TRANSPORT INC.	**Name:** RICHARD THOMPSON
209 PUTMAN INDUSTRIAL RD	**Report Number:** 112
BELLEVILLE, ON K8N4Z6	**Tablet ID:** 2923

613-968-7541

Software Version: 2024.08.21.1

STO ID/Account: 13171305

Trade Code: 310T, 310S

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program

L.M.B. TRANSPORT INC

TRAILER SERVICE SHEET
STAPLE TO WORK ORDER

DATE June 11/25 UNIT # QD4018

NAME OF MECHANIC Rick / Paul SIGNATURE

- [x] 1) Check all lights and reflectors and/or reflective tape including rear bumper
- [x] 2) Check for major body damage
- [x] 3) DOCUMENT HOLDER- properly secure with proper cover, registration and annual safety up to date and signed.
- [x] 4) Tire wear and pressure (100-105 PSI)
- [x] 5) BOGIE – Complete Grease and inspection of bogie. Ensure all Grease fittings take grease.
- [x] 6) LANDING GEAR – Grease and inspect landing gear including cross b~~ar on all QD and TR series Mattac's~~
- [x] 7) WHEEL HUBS – Remove plug for physical inspection (oil levels – adjust if needed; clean and free of contamination)
- [x] 8) WHEELS – Clean away and rust/ ensure no cracks or breaks (including inner wheels). Ensure wheels are tight. Check re-torque board to ensure it doesn't need to be re-torqued.
- [x] 9) Check and adjust brakes if necessary
- [x] 10) Inspect jam nuts at brake clevis to ensure proper location
- [x] 11) Check U-bolts
- [x] 12) Check that all hoses are secured and no audible air leaks, check service side of brake system.
- [x] ~~13) Pry torque arms with bar to ensure they are secure~~
- [x] 14) DOORS- Check rear doors and door hold backs (in place and operational)
- [x] 15) AIR BOX DOORS- Operational. Rubber bung to hold the door shut.
- [x] 16) Aluminum Corners installed on quads and TR Series tridems.
- [x] 17) Rubber Dock Bumpers replace if needed
- [x] 18) Change Service date on front of trailer

L.M.B. TRANSPORT INC

TRAILER SERVICE SHEET
STAPLE TO WORK ORDER

DATE Nov 20/2025 UNIT # 4018

NAME OF MECHANIC Wesley Hinsley SIGNATURE Wesley

- [x] 1) Check all lights and reflectors and/or reflective tape including rear bumper
- [x] 2) Check for major body damage
- [x] 3) DOCUMENT HOLDER- properly secure with proper cover, registration and annual safety up to date and signed.
- [x] 4) Tire wear and pressure (100-105 PSI)
- [x] 5) BOGIE – Complete Grease and inspection of bogie. Ensure all Grease fittings take grease.
- [x] 6) LANDING GEAR – Grease and inspect landing gear including cross bar on all QD and TR series Manac's
- [x] 7) WHEEL HUBS – Remove plug for physical inspection (oil levels – adjust if needed; clean and free of contamination)
- [x] 8) WHEELS – Clean away and rust/ ensure no cracks or breaks (including inner wheels). Ensure wheels are tight. Check re-torque board to ensure it doesn't need to be re-torqued.
- [x] 9) Check and adjust brakes if necessary
- [x] 10) Inspect jam nuts at brake clevis to ensure proper location
- [x] 11) Check U-bolts ~~N/A~~
- [x] 12) Check that all hoses are secured and no audible air leaks, check service side of brake system.
- [ ] ~~13) Pry torque arms with bar to ensure they are secure.~~
- [x] 14) DOORS- Check rear doors and door hold backs (in place and operational)
- [x] 15) AIR BOX DOORS- Operational. Rubber bung to hold the door shut.
- [x] 16) Aluminum Corners installed on quads and TR Series tridems.
- [x] 17) Rubber Dock Bumpers replace if needed
- [x] 18) Change Service date on front of trailer

L.M.B. TRANSPORT INC.

P.O. BOX 8
CANNIFTON, ONTARIO K0K 1K0
TEL: (613) 968-7541 FAX: (613) 968-7541
HST NO: R129359477

36548

QUAN.	DESCRIPTION	AMOUNT
1	180.10630	
1	170.110257	
1	170.110700	
1	172.2002T	
2	TV12105U	
1	HD8000	
	TOTAL PARTS	
SUBLET		
	TOTAL SUBLET	

NAME	LMB GTD 4018	DATE 11/20/25	MAKE MANAC
ADDRESS		TYPE MODEL VSX	YR 2014
CITY #4018	PHONE	MILEAGE N/A	LIC Y7547R
		SERIAL NO. ON FILE	

INSTRUCTIONS	AMOUNT
-SERVICE	

NOTES:		
	LABOUR	
	PARTS	
	SUBLET	
	HST	
	TOTAL AMOUNT	

All estimates are for labour only. Material additional. This company does not assume any responsibility whatever for vehicle or equipment left for repairs, storage or other purposes, or for articles left in same. Vehicle driven by our employees at owner's risk.

IN — I hereby authorize the above work to be done along with necessary materials.

OUT — I hereby acknowledge my indebtedness in the amount of $ ______

DATE ______ SIGN ______