



Commercial Vehicle Inspection Report

Decal Number: GL38025
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21709854

Inspection Result:

PASS

FACILITY: UNITED SPRING & BRAKE / S0063 INSP. TYPE: Complete INSP. START: 2026-Mar-26 06:00 AM -07
INSPECTOR: POCOCK, LARRY HERBERT / 114138 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Mar-26 08:00 AM -07
WORK ORDER #: 50518 INSP. REASON: Annual

505-1

VEHICLE JUR: Alberta REGI: VIN: 2A9LB6049AN125093
PLATE #: UNIT/FLEET#: OWNER/LESSEE NAME: H.F. NODES CONSTRUCTION LT, NODES
LICENCED GVW(kg): 0 BODY STYLE: Trailer ADDRESS: PO BOX 373, PO BOX 373
VEHICLE YEAR: 2010 ODOMETER: Pouce Coupe, British Columbia
MAKE: Aspen HUB ODOMETER: V0C2C0, Canada
MODEL: LB60-16 BRAKE TYPE: Air
FUEL TYPE: Not Applicable

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Manual	32	32
2	Clamp	24	Manual	32	32
3	Clamp	24	Manual	32	32
4	Clamp	24	Manual	32	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14	14	9	9	
9	9	12	14	
12	12	15	15	
14	14	10	10	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSED014

3/26/2026 9:45:18 AM -07

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	82	61	Lining (Shoe)	14	16	Drum		
2	51	64	Lining (Shoe)	18	16	Drum		
3	63	70	Lining (Shoe)	16	16	Drum		
4	48	51	Lining (Shoe)	18	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

 Has this Vehicle been road tested? No
 Inspector: POCOCK, LARRY HERBERT

 Road Test Date:
 Signature:



Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-26 09:45 AM -07

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE014

3/26/2026 9:45:19 AM -07